





T20261014060445




BLK: 3,SNR1: 2.4186 ,SNR2: 9.1656




F20261014060448









BLK: 3,SNR1: 4.5896 ,SNR2: 10.728





0741-06 2026/10/13 21.11UT TOYOKAWA-FUJI










T20261014062205




BLK: 5, SNR1: 6.3568 ,SNR2: 16.390




F20261014062208









BLK: 5, SNR1: 4.9765 ,SNR2: 15.942





3C190 2026/10/13 21.40UT TOYOKAWA-FUJI









T20261014064540




BLK: 5, SNR1: 7.6783 ,SNR2: 20.042




F20261014064543









BLK: 5, SNR1: 7.3116 ,SNR2: 18.813





0821+394 2026/10/13 21.79UT TOYOKAWA-FUJI








T20261014070224





BLK: 7,SNR1: 10.862 ,SNR2: 19.185




Frequency (Hz)

F20261014070227







BLK: 7,SNR1: 0.17631 ,SNR2: 3.4338







Frequency (Hz)

0839-071 2026/10/13 22.07UT TOYOKAWA-FUJI













BLK: 2,SNR1: 4.5209 ,SNR2: 8.3406









BLK: 2,SNR1: 2.0165 ,SNR2: 7.6689





3C208 2026/10/13 22.25UT TOYOKAWA-FUJI









T20261014073008




BLK: 4,SNR1: 0.97102E-01,SNR2: 1.6739




F20261014073011









BLK: 4,SNR1: 10.605 ,SNR2: 25.461









3C216 2026/10/13 22.53UT TOYOKAWA-FUJI





















T20261014075641




BLK: 1,SNR1: 5.5009 ,SNR2: 19.072




F20261014075644









BLK: 1,SNR1: 2.6470 ,SNR2: 14.927





3C222 2026/10/13 22.97UT TOYOKAWA-FUJI









T20261014080341




BLK: 7, SNR1: 9.6546 , SNR2: 16.906




F20261014080344









BLK: 7, SNR1: 9.4870 , SNR2: 21.148







0941-08 2026/10/13 23.09UT TOYOKAWA-FUJI

















3C230 2026/10/13 23.23UT TOYOKAWA-FUJI









T20261014082804




BLK: 3, SNR1: 1.6284 , SNR2: 5.5760




F20261014082807









BLK: 3, SNR1: 0.89500 , SNR2: 4.0582





3C237 2026/10/13 23.50UT TOYOKAWA-FUJI










T20261014083420




BLK: 2, SNR1: 10.911 ,SNR2: 26.702




F20261014083423






BLK: 2, SNR1: 20.627 ,SNR2: 36.678





1011+110 2026/10/13 23.60UT TOYOKAWA-FUJI






F20261014083423





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1011+110 2026/10/13 23.60UT FUJI -KISO





T20261014084201




BLK: 4, SNR1: 2.6379 , SNR2: 6.9283




F20261014084204









BLK: 4, SNR1: 2.1475 , SNR2: 7.7364




3C241 2026/10/13 23.73UT TOYOKAWA-FUJI










T20261014090716




BLK: 1,SNR1: 16.162 ,SNR2: 28.599




F20261014090719









BLK: 1,SNR1: 0.58112 ,SNR2: 5.9591




1044-008 2026/10/14 0.15UT TOYOKAWA-FUJI













BLK: 1,SNR1: 12.720 ,SNR2: 22.963









BLK: 1,SNR1: 19.446 ,SNR2: 34.593





1055+01 2026/10/14 0.33UT TOYOKAWA-FUJI








T20261014092939





BLK: 3, SNR1: 6.4921 , SNR2: 16.166




Frequency (Hz)

F20261014092942







BLK: 3, SNR1: 10.598 , SNR2: 25.084






Frequency (Hz)


1107+109 2026/10/14 0.52UT TOYOKAWA-FUJI










T20261014093916




BLK: 1, SNR1: 9.5849 , SNR2: 19.976




F20261014093919









BLK: 1, SNR1: 11.582 , SNR2: 33.528




3C255 2026/10/14 0.68UT TOYOKAWA-FUJI









T20261014100314




BLK: 5, SNR1: 6.7731 ,SNR2: 12.397




F20261014100317









BLK: 5, SNR1: 5.1703 ,SNR2: 12.490





3C263.1 2026/10/14 1.08UT TOYOKAWA-FUJI








T20261014100941




BLK: 7,SNR1: 9.9945 ,SNR2: 30.838








3C267 2026/10/14 1.19UT TOYOKAWA-FUJI




F20261014100944




BLK: 7,SNR1: 0.45670E-01,SNR2: 1.0508









T20261014102855




BLK: 3,SNR1:-0.27125E-01,SNR2: 1.8723




F20261014102858









BLK: 3,SNR1: 7.2136 ,SNR2: 17.462





1206+439 2026/10/14 1.51UT TOYOKAWA-FUJI








T20261014104846





BLK:20,SNR1: 3.2108 ,SNR2: 9.7842








3C273 2026/10/14 1.84UT TOYOKAWA-FUJI




F20261014104849





BLK:20,SNR1: 9.5671 ,SNR2: 16.723










T20261014110157




BLK: 4, SNR1: 1.0208 , SNR2: 9.6399




F20261014110200









BLK: 4, SNR1: 0.98592 , SNR2: 3.9170







3C275 2026/10/14 2.06UT TOYOKAWA-FUJI


















3C279 2026/10/14 2.29UT TOYOKAWA-FUJI










T20261014113532




BLK: 8, SNR1: 12.663 , SNR2: 20.543




F20261014113535





BLK: 8, SNR1: 4.4598 , SNR2: 11.173







1313+453 2026/10/14 2.62UT TOYOKAWA-FUJI










1313+453 2026/10/14 2.62UT TOYOKAWA-KISO













1323+32 2026/10/14 2.79UT TOYOKAWA-FUJI







1323+32 2026/10/14 2.79UT TOYOKAWA-KISO







T20261014115029




BLK:13,SNR1: 4.6665 ,SNR2: 13.439




F20261014115032





BLK:13,SNR1: 11.513 ,SNR2: 31.158







3C286 2026/10/14 2.87UT TOYOKAWA-FUJI






3C286 2026/10/14 2.87UT TOYOKAWA-KISO







T20261014120656




BLK:18,SNR1: 4.5719 ,SNR2: 6.5381




F20261014120659









BLK:18,SNR1: 2.0001 ,SNR2: 5.1903





1345+12 2026/10/14 3.14UT TOYOKAWA-FUJI









T20261014121717




BLK:21,SNR1: 1.5617 ,SNR2: 6.1696




F20261014121720









BLK:21,SNR1: 0.37880 ,SNR2: 2.3356





1355+01 2026/10/14 3.32UT TOYOKAWA-FUJI









T20261014123828




BLK:25,SNR1: 6.5395 ,SNR2: 9.2421




F20261014123831









BLK:25,SNR1: 1.3686 ,SNR2: 4.8605




3C298 2026/10/14 3.67UT TOYOKAWA-FUJI









T20261014125011




BLK: 5,SNR1: 2.5440 ,SNR2: 17.392




F20261014125014









BLK: 5,SNR1: 0.15836 ,SNR2: 1.8650





1428-03 2026/10/14 3.86UT TOYOKAWA-FUJI








T20261014125614





BLK:11,SNR1: 173.79 ,SNR2: 221.88




Frequency (Hz)

F20261014125617







BLK:11,SNR1: 41.216 ,SNR2: 74.786






Frequency (Hz)


1434+03 2026/10/14 3.97UT TOYOKAWA-FUJI










T20261014133008




BLK: 1,SNR1: 3.9393 ,SNR2: 11.892




F20261014133011









BLK: 1,SNR1: 15.231 ,SNR2: 27.133





1508-05 2026/10/14 4.53UT TOYOKAWA-FUJI









T20261014133907




BLK: 1,SNR1: 8.6564 ,SNR2: 21.373




F20261014133910









BLK: 1,SNR1: 10.688 ,SNR2: 26.137




3C318 2026/10/14 4.68UT TOYOKAWA-FUJI










T20261014134455




BLK: 2,SNR1: 6.7067 ,SNR2: 17.834




F20261014134458









BLK: 2,SNR1: 7.1158 ,SNR2: 17.388





1523+03 2026/10/14 4.78UT TOYOKAWA-FUJI










T20261014135634




BLK: 6, SNR1: 3.9789 , SNR2: 11.577




F20261014135637









BLK: 6, SNR1: 9.0257 , SNR2: 22.020





1535+139 2026/10/14 4.97UT TOYOKAWA-FUJI









T20261014140940




BLK: 1,SNR1: 1.0159 ,SNR2: 5.0153




F20261014140943









BLK: 1,SNR1: 9.8499 ,SNR2: 31.519





1548+05 2026/10/14 5.19UT TOYOKAWA-FUJI








T20261014142801





No.Good Data




Frequency (Hz)

F20261014142804







No.Good Data






Frequency (Hz)


1607+26 2026/10/14 5.50UT TOYOKAWA-FUJI









T20261014145940




BLK: 1,SNR1: 9.5238 ,SNR2: 23.714




F20261014145943





BLK: 1,SNR1: 2.2271 ,SNR2: 12.645







1638-025 2026/10/14 6.02UT TOYOKAWA-FUJI








1638-025 2026/10/14 6.02UT TOYOKAWA-KISO









BLK: 1,SNR1: 2.3203 ,SNR2: 14.542









BLK: 1,SNR1: 2.0423 ,SNR2: 13.082







1650+004 2026/10/14 6.23UT TOYOKAWA-FUJI
















1656+053 2026/10/14 6.32UT TOYOKAWA-FUJI








1656+053 2026/10/14 6.32UT TOYOKAWA-KISO









BLK: 9,SNR1: 6.2401 ,SNR2: 15.739





BLK: 9,SNR1: 4.9741 ,SNR2: 12.984







1712-033 2026/10/14 6.59UT TOYOKAWA-FUJI










1712-033 2026/10/14 6.59UT TOYOKAWA-KISO














1748+031 2026/10/14 7.18UT TOYOKAWA-KISO








T20261014162016




BLK: 1,SNR1: 4.2573 ,SNR2: 9.2701




F20261014162019





BLK: 1,SNR1: 28.591 ,SNR2: 61.407



1759+13 2026/10/14 7.37UT TOYOKAWA-FUJI





1759+13 2026/10/14 7.37UT TOYOKAWA-KISO

