







TOYOKAWA 3043 2023/07/17(198)05:42:22-05:45:48JST





TOYOKAWA 0109+416 2023/07/17(198)05:24:49-05:28:15JST





TOYOKAWA 0017+565 2023/07/17(198)04:32:26-04:35:52JST





TOYOKAWA 3048 2023/07/17(198)05:50:06-05:53:32JST





TOYOKAWA 0116+31 2023/07/17(198)05:31:59-05:35:25JST





TOYOKAWA 0051+404 2023/07/17(198)05:06:56-05:10:22JST





TOYOKAWA 0139+287 2023/07/17(198)05:54:49-05:58:15JST




TOYOKAWA 0120+405 2023/07/17(198)05:35:54-05:39:20JST




TOYOKAWA 0103+422 2023/07/17(198)05:19:12-05:22:36JST




TOYOKAWA 0213+178 2023/07/17(198)06:28:48-06:32:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0157+217 2023/07/17(198)06:12:27-06:15:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0143+278 2023/07/17(198)05:58:46-06:02:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3067 2023/07/17(198)06:36:30-06:39:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0202+15 2023/07/17(198)06:16:58-06:20:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0148+274 2023/07/17(198)06:03:49-06:07:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3071 2023/07/17(198)06:54:46-06:58:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0207-018 2023/07/17(198)06:21:55-06:25:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)





TOYOKAWA 0152+435 2023/07/17(198)06:07:58-06:11:24JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)





TOYOKAWA 0355+50 2023/07/17(198)08:11:56-08:15:22JST





TOYOKAWA 0324+119 2023/07/17(198)07:39:26-07:42:52JST





TOYOKAWA 0258+350 2023/07/17(198)07:14:00-07:17:26JST





TOYOKAWA 0403-132 2023/07/17(198)08:17:19-08:20:45JST





TOYOKAWA 0333+32 2023/07/17(198)07:48:42-07:52:08JST





TOYOKAWA 0308+305 2023/07/17(198)07:23:49-07:27:15JST





TOYOKAWA 0411+05 2023/07/17(198)08:28:29-08:29:55JST





TOYOKAWA 0347+05 2023/07/17(198)08:01:44-08:05:10JST



TOYOKAWA 0320+05 2023/07/17(198)07:35:22-07:38:48JST





TOYOKAWA 3C147 2023/07/17(198)09:54:49-09:58:15JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

TOYOKAWA 0440-102 2023/07/17(198)08:54:07-08:57:33JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

TOYOKAWA 0418+236 2023/07/17(198)08:33:23-08:36:49JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

TOYOKAWA 0548+16 2023/07/17(198)10:03:02-10:06:28JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

TOYOKAWA 3C136 2023/07/17(198)09:32:58-09:36:24JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

TOYOKAWA 0422+178 2023/07/17(198)08:37:22-08:40:46JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

TOYOKAWA 0552+12 2023/07/17(198)10:07:13-10:10:39JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

TOYOKAWA 0531+194 2023/07/17(198)09:46:31-09:49:57JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

TOYOKAWA 3C119 2023/07/17(198)08:44:50-08:48:16JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)





