




T20230704061557





BLK:11,SNR1: 1.2252 ,SNR2: 5.2323




Frequency (Hz)

F20230704061559




BLK:11,SNR1: 0.29611 ,SNR2: 2.8117




Frequency (Hz)

0109+416 2023/07/03 21.29UT TOYOKAWA-FUJI



T20230704061557




No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0109+416 2023/07/03 21.29UT TOYOKAWA-KISO



F20230704061559




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0109+416 2023/07/03 21.29UT FUJI -KISO



T20230704062702





BLK: 7,SNR1: 0.56179 ,SNR2: 1.2820




Frequency (Hz)

F20230704062704




BLK: 7,SNR1: 0.22738 ,SNR2: 1.4855





Frequency (Hz)


0120+405 2023/07/03 21.48UT TOYOKAWA-FUJI



T20230704062702



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0120+405 2023/07/03 21.48UT TOYOKAWA-KISO



F20230704062704



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0120+405 2023/07/03 21.48UT FUJI -KISO



T20230704064115



BLK:20,SNR1: 0.88990 ,SNR2: 5.4507





Frequency (Hz)


3C48

2023/07/03 21.72UT TOYOKAWA-FUJI


F20230704064117




BLK:20,SNR1: 0.40177 ,SNR2: 2.9406




Frequency (Hz)




T20230704064115




No.Good Data




KISO



No.Good Data



3C48 2023/07/03 21.72UT TOYOKAWA-KISO





F20230704064117



No.Good Data



KISO




No.Good Data




3C48 2023/07/03 21.72UT FUJI -KISO



T20230704065458





BLK: 1,SNR1:-0.17478 ,SNR2: 0.0000




Frequency (Hz)

F20230704065500




BLK: 1,SNR1: 0.17599 ,SNR2: 0.97388



Frequency (Hz)


0148+274 2023/07/03 21.94UT TOYOKAWA-FUJI



T20230704065458



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0148+274 2023/07/03 21.94UT TOYOKAWA-KISO



F20230704065500




No.Good Data



KISO




No.Good Data




0148+274 2023/07/03 21.94UT FUJI -KISO




T20230704070807




No.Good Data




F20230704070809



No.Good Data




0202+15 2023/07/03 22.16UT TOYOKAWA-FUJI




T20230704070807




No.Good Data




KISO




No.Good Data



0202+15 2023/07/03 22.16UT TOYOKAWA-KISO




F20230704070809



No.Good Data




KISO




No.Good Data




0202+15 2023/07/03 22.16UT FUJI -KISO



T20230704071957




BLK: 2,SNR1:-0.11924 ,SNR2: 0.20019




Frequency (Hz)

F20230704071959




BLK: 2,SNR1: 0.48101 ,SNR2: 6.6011



Frequency (Hz)

0213+178 2023/07/03 22.36UT TOYOKAWA-FUJI






T20230704071957




No.Good Data




KISO





No.Good Data




0213+178 2023/07/03 22.36UT TOYOKAWA-KISO



F20230704071959



No.Good Data




KISO





No.Good Data




0213+178 2023/07/03 22.36UT FUJI -KISO



T20230704072739



BLK: 2,SNR1: 1.2684 ,SNR2: 8.4944





Frequency (Hz)


3C67

2023/07/03 22.49UT TOYOKAWA-FUJI


F20230704072741



BLK: 2,SNR1: 0.42572 ,SNR2: 2.0027



Frequency (Hz)



T20230704072739



No.Good Data



KISO



No.Good Data




3C67 2023/07/03 22.49UT TOYOKAWA-KISO



F20230704072741




No.Good Data



KISO





No.Good Data




3C67 2023/07/03 22.49UT FUJI -KISO





T20230704074555




No.Good Data




F20230704074557



No.Good Data



3C71 2023/07/03 22.79UT TOYOKAWA-FUJI



T20230704074555



No.Good Data





Frequency (Hz)


3C71

2023/07/03 22.79UT TOYOKAWA-KISO


KISO



No.Good Data




Frequency (Hz)



F20230704074557




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C71 2023/07/03 22.79UT FUJI -KISO






T20230704080509




BLK: 9,SNR1:-0.65645E-02,SNR2: 0.29450




Frequency (Hz)

F20230704080511




BLK: 9,SNR1: 1.1441 ,SNR2: 2.9261




Frequency (Hz)


0258+350 2023/07/03 23.11UT TOYOKAWA-FUJI



T20230704080509




No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0258+350 2023/07/03 23.11UT TOYOKAWA-KISO



F20230704080511





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0258+350 2023/07/03 23.11UT FUJI -KISO



T20230704081458





BLK: 3,SNR1: 0.94707E-01,SNR2: 0.63735




Frequency (Hz)

F20230704081500




BLK: 3,SNR1: 0.25544E-01,SNR2: 5.3360



Frequency (Hz)


0308+305 2023/07/03 23.28UT TOYOKAWA-FUJI



T20230704081458



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0308+305 2023/07/03 23.28UT TOYOKAWA-KISO





F20230704081500




No.Good Data




KISO





No.Good Data




0308+305 2023/07/03 23.28UT FUJI -KISO



T20230704082630





BLK: 3,SNR1: 0.25920 ,SNR2: 1.0229




Frequency (Hz)

F20230704082632




BLK: 3,SNR1: 0.24720 ,SNR2: 2.5103



Frequency (Hz)


0320+05 2023/07/03 23.47UT TOYOKAWA-FUJI





T20230704082630




No.Good Data




KISO



No.Good Data





0320+05 2023/07/03 23.47UT TOYOKAWA-KISO






F20230704082632





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0320+05 2023/07/03 23.47UT FUJI -KISO



T20230704083951




BLK: 1,SNR1: 0.16915 ,SNR2: 1.2627




Frequency (Hz)

F20230704083953




BLK: 1,SNR1: 0.95219 ,SNR2: 1.2796





Frequency (Hz)


0333+32 2023/07/03 23.69UT TOYOKAWA-FUJI



T20230704083951





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0333+32 2023/07/03 23.69UT TOYOKAWA-KISO





F20230704083953




No.Good Data




KISO




No.Good Data




0333+32 2023/07/03 23.69UT FUJI -KISO



T20230704085253




BLK: 4,SNR1: 0.23883 ,SNR2: 1.4128




Frequency (Hz)

F20230704085255




BLK: 4,SNR1: 0.80052 ,SNR2: 2.4033



Frequency (Hz)

0347+05 2023/07/03 23.91UT TOYOKAWA-FUJI



T20230704085253



No.Good Data




KISO





No.Good Data




0347+05 2023/07/03 23.91UT TOYOKAWA-KISO




F20230704085255




No.Good Data




KISO





No.Good Data




0347+05 2023/07/03 23.91UT FUJI -KISO




T20230704090828




BLK: 1,SNR1: 0.40826 ,SNR2: 1.4615




F20230704090830



BLK: 1,SNR1: 0.49842 ,SNR2: 4.2368





0403-132 2023/07/04 0.17UT TOYOKAWA-FUJI








T20230704090828




No. Good Data




KISO



No. Good Data



0403-132 2023/07/04 0.17UT TOYOKAWA-KISO



F20230704090830



No.Good Data



KISO





No.Good Data




0403-132 2023/07/04 0.17UT FUJI -KISO



T20230704091738





BLK: 6,SNR1: 0.31010 ,SNR2: 2.9615




Frequency (Hz)

F20230704091740




BLK: 6,SNR1: 1.1281 ,SNR2: 2.7777



Frequency (Hz)

0411+05 2023/07/04 0.32UT TOYOKAWA-FUJI





T20230704091738




No.Good Data




KISO



No.Good Data



0411+05 2023/07/04 0.32UT TOYOKAWA-KISO



F20230704091740



No.Good Data



KISO





No.Good Data




0411+05 2023/07/04 0.32UT FUJI -KISO



T20230704092432





BLK: 5,SNR1: 2.3210 ,SNR2: 19.754





0418+236 2023/07/04 0.44UT TOYOKAWA-FUJI

F20230704092434



BLK: 5,SNR1: 42.391 ,SNR2: 286.60



T20230704092432



No.Good Data



KISO





No.Good Data




0418+236 2023/07/04 0.44UT TOYOKAWA-KISO





F20230704092434




No.Good Data




KISO



No.Good Data




0418+236 2023/07/04 0.44UT FUJI -KISO






T20230704093558




BLK:11,SNR1: 0.86013 ,SNR2: 10.145




Frequency (Hz)

F20230704093600




BLK:11,SNR1: 0.57122 ,SNR2: 2.0073




Frequency (Hz)

3C119 2023/07/04 0.63UT TOYOKAWA-FUJI





T20230704093558




No.Good Data



KISO




No.Good Data



3C119 2023/07/04 0.63UT TOYOKAWA-KISO





F20230704093600




No.Good Data



KISO




No.Good Data




3C119 2023/07/04 0.63UT FUJI -KISO



T20230704102407




BLK:29,SNR1: 3.3147 ,SNR2: 9.4375




Frequency (Hz)

3C138 2023/07/04 1.43UT TOYOKAWA-FUJI


F20230704102409



BLK:29,SNR1: 0.20582 ,SNR2: 1.2103



Frequency (Hz)



T20230704102407



No. Good Data



KISO



No. Good Data



3C138 2023/07/04 1.43UT TOYOKAWA-KISO




F20230704102409




No. Good Data




KISO




No. Good Data




3C138 2023/07/04 1.43UT FUJI -KISO



T20230704103740





BLK:26,SNR1: 4.2590 ,SNR2: 25.344





0531+194 2023/07/04 1.66UT TOYOKAWA-FUJI


F20230704103742



BLK:26,SNR1: 0.54496 ,SNR2: 1.8446




T20230704103740



No. Good Data



KISO



No. Good Data





0531+194 2023/07/04 1.66UT TOYOKAWA-KISO






F20230704103742



No. Good Data




KISO




No. Good Data




0531+194 2023/07/04 1.66UT FUJI -KISO



T20230704104558




BLK:28,SNR1: 14.933 ,SNR2: 57.130





3C147 2023/07/04 1.79UT TOYOKAWA-FUJI

F20230704104600



BLK:28,SNR1: 0.40331 ,SNR2: 5.7517



T20230704104558




No. Good Data



KISO



No. Good Data



3C147 2023/07/04 1.79UT TOYOKAWA-KISO



F20230704104600



No. Good Data




KISO




No. Good Data




3C147 2023/07/04 1.79UT FUJI -KISO




T20230704105411




BLK:25,SNR1: 0.87700 ,SNR2: 6.6089




F20230704105413



BLK:25,SNR1: 0.37882 ,SNR2: 3.0646



0548+16 2023/07/04 1.93UT TOYOKAWA-FUJI




T20230704105411




No. Good Data



KISO




No. Good Data




0548+16 2023/07/04 1.93UT TOYOKAWA-KISO





F20230704105413




No. Good Data



KISO




No. Good Data




0548+16 2023/07/04 1.93UT FUJI -KISO



T20230704105822




BLK:12,SNR1: 5.2594 ,SNR2: 41.536





0552+12 2023/07/04 2.00UT TOYOKAWA-FUJI

F20230704105824



BLK:12,SNR1: 0.15703 ,SNR2: 1.4091





T20230704105822



No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


0552+12 2023/07/04 2.00UT TOYOKAWA-KISO





F20230704105824




No. Good Data




KISO





No. Good Data




0552+12 2023/07/04 2.00UT FUJI -KISO




T20230704110248




BLK:15,SNR1: 0.65353 ,SNR2: 5.9971




F20230704110250



BLK:15,SNR1: 0.10827 ,SNR2: 2.0333




0556+191 2023/07/04 2.07UT TOYOKAWA-FUJI



T20230704110248





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0556+191 2023/07/04 2.07UT TOYOKAWA-KISO



F20230704110250





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0556+191 2023/07/04 2.07UT FUJI -KISO



T20230704111035




BLK: 2,SNR1: 0.24354 ,SNR2: 2.6287





0605-08 2023/07/04 2.20UT TOYOKAWA-FUJI

F20230704111037




BLK: 2,SNR1: 0.25081 ,SNR2: 2.5917



T20230704111035



No. Good Data




Frequency (Hz)

KISO



No. Good Data




Frequency (Hz)


0605-08 2023/07/04 2.20UT TOYOKAWA-KISO



F20230704111037



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0605-08 2023/07/04 2.20UT FUJI -KISO






T20230704112943





BLK:11,SNR1: 1.1403 ,SNR2: 3.5128





3C161 2023/07/04 2.52UT TOYOKAWA-FUJI

F20230704112945



BLK:11,SNR1: 1.7709 ,SNR2: 4.1556



T20230704112943



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C161 2023/07/04 2.52UT TOYOKAWA-KISO



F20230704112945





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/07/04 2.52UT FUJI -KISO




T20230704115716




BLK: 9,SNR1: 0.91739E-01,SNR2: 0.85680




F20230704115718



BLK: 9,SNR1: 0.21343 ,SNR2: 3.0661



0652-130 2023/07/04 2.98UT TOYOKAWA-FUJI



T20230704115716



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0652-130 2023/07/04 2.98UT TOYOKAWA-KISO



F20230704115718




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0652-130 2023/07/04 2.98UT FUJI -KISO




T20230704120852




BLK: 3,SNR1: 0.26506 ,SNR2: 1.3207




F20230704120854



BLK: 3,SNR1: 0.41247E-01,SNR2: 0.64332



0703+138 2023/07/04 3.18UT TOYOKAWA-FUJI



T20230704120852





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0703+138 2023/07/04 3.18UT TOYOKAWA-KISO





F20230704120854



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0703+138 2023/07/04 3.18UT FUJI -KISO



T20230704121815





BLK: 6,SNR1: 0.35209 ,SNR2: 0.92971




Frequency (Hz)

F20230704121817




BLK: 6,SNR1:-0.13902 ,SNR2: 0.90504



Frequency (Hz)

0713-024 2023/07/04 3.33UT TOYOKAWA-FUJI



T20230704121815



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0713-024 2023/07/04 3.33UT TOYOKAWA-KISO



F20230704121817





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0713-024 2023/07/04 3.33UT FUJI -KISO





T20230704122826




BLK:18,SNR1: 0.53206 ,SNR2: 5.0103




F20230704122828



BLK:18,SNR1: 0.23711 ,SNR2: 0.70723



0723+10 2023/07/04 3.5OUT TOYOKAWA-FUJI



T20230704122826



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0723+10 2023/07/04 3.50UT TOYOKAWA-KISO





F20230704122828




No.Good Data




KISO





No.Good Data




0723+10 2023/07/04 3.50UT FUJI -KISO




T20230704123840




BLK:16,SNR1: 0.56081 ,SNR2: 2.4743




F20230704123842



BLK:16,SNR1: 0.30884 ,SNR2: 2.7553



0732+33 2023/07/04 3.67UT TOYOKAWA-FUJI





T20230704123840



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0732+33 2023/07/04 3.67UT TOYOKAWA-KISO





F20230704123842




No.Good Data




KISO





No.Good Data




0732+33 2023/07/04 3.67UT FUJI -KISO





T20230704124643




BLK: 9,SNR1: 0.65926 ,SNR2: 3.9577




F20230704124645



BLK: 9,SNR1: 0.17894 ,SNR2: 1.1252



0741-06 2023/07/04 3.81UT TOYOKAWA-FUJI



T20230704124643





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0741-06 2023/07/04 3.81UT TOYOKAWA-KISO



F20230704124645




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


0741-06 2023/07/04 3.81UT FUJI -KISO





T20230704130402




BLK:14,SNR1: 0.79533 ,SNR2: 3.4870




F20230704130404




BLK:14,SNR1: 0.71976 ,SNR2: 1.9788



3C190 2023/07/04 4.10UT TOYOKAWA-FUJI



T20230704130402




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C190 2023/07/04 4.10UT TOYOKAWA-KISO



F20230704130404





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C190 2023/07/04 4.10UT FUJI -KISO






T20230704131625




BLK:11,SNR1: 0.22528 ,SNR2: 1.3422





3C196 2023/07/04 4.30UT TOYOKAWA-FUJI

F20230704131627



BLK:11,SNR1: 0.86251 ,SNR2: 1.5539



T20230704131625



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C196 2023/07/04 4.30UT TOYOKAWA-KISO



F20230704131627



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C196 2023/07/04 4.30UT FUJI -KISO





T20230704132736




BLK:11,SNR1: 0.54774 ,SNR2: 6.5867




F20230704132738



BLK:11,SNR1:-0.35850 ,SNR2: 1.0537



0821+394 2023/07/04 4.49UT TOYOKAWA-FUJI



T20230704132736



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0821+394 2023/07/04 4.49UT TOYOKAWA-KISO



F20230704132738





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0821+394 2023/07/04 4.49UT FUJI -KISO



T20230704134422





BLK:10,SNR1: 3.5230 ,SNR2: 13.763




Frequency (Hz)

F20230704134424




BLK:10,SNR1: 0.45126 ,SNR2: 4.0577



Frequency (Hz)

0839-071 2023/07/04 4.77UT TOYOKAWA-FUJI



T20230704134422



No. Good Data



Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0839-071 2023/07/04 4.77UT TOYOKAWA-KISO





F20230704134424





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0839-071 2023/07/04 4.77UT FUJI -KISO




T20230704135523




BLK:28,SNR1: 0.21317 ,SNR2: 1.6295




F20230704135525



BLK:28,SNR1: 0.40344 ,SNR2: 1.4019



3C208 2023/07/04 4.95UT TOYOKAWA-FUJI



T20230704135523



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C208 2023/07/04 4.95UT TOYOKAWA-KISO



F20230704135525



No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


3C208 2023/07/04 4.95UT FUJI -KISO





T20230704141203




BLK:33,SNR1: 0.89287 ,SNR2: 1.3549




F20230704141205





BLK:33,SNR1: 5.6895 ,SNR2: 10.088



3C216 2023/07/04 5.23UT TOYOKAWA-FUJI



T20230704141203





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C216 2023/07/04 5.23UT TOYOKAWA-KISO



F20230704141205





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C216 2023/07/04 5.23UT FUJI -KISO





T20230704143055




BLK:17,SNR1: 73.009 ,SNR2: 135.94




F20230704143057



BLK:17,SNR1: 0.54900 ,SNR2: 1.5898





0926+117 2023/07/04 5.54UT TOYOKAWA-FUJI






T20230704143055





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

0926+117 2023/07/04 5.54UT TOYOKAWA-KISO





F20230704143057




No.Good Data




KISO




No.Good Data




0926+117 2023/07/04 5.54UT FUJI -KISO





T20230704143839




BLK:14,SNR1: 2.0847 ,SNR2: 11.680




F20230704143841



BLK:14,SNR1: 0.32452 ,SNR2: 1.2897



3C222 2023/07/04 5.67UT TOYOKAWA-FUJI



T20230704143839




No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

3C222 2023/07/04 5.67UT TOYOKAWA-KISO



F20230704143841




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C222 2023/07/04 5.67UT FUJI -KISO





T20230704144540




BLK:17,SNR1: 2.5994 ,SNR2: 8.9173




F20230704144542






BLK:17,SNR1: 0.91006E-01,SNR2: 0.96752






0941-08 2023/07/04 5.79UT TOYOKAWA-FUJI



T20230704144540





KISO




0941-08 2023/07/04 5.79UT TOYOKAWA-KISO



F20230704144542





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0941-08 2023/07/04 5.79UT FUJI -KISO






T20230704145401





BLK:24,SNR1: 0.22904 ,SNR2: 0.91037





3C230 2023/07/04 5.93UT TOYOKAWA-FUJI

F20230704145403



BLK:24,SNR1: 1.0047 ,SNR2: 4.4203



T20230704145401



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C230 2023/07/04 5.93UT TOYOKAWA-KISO



F20230704145403





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C230 2023/07/04 5.93UT FUJI -KISO





T20230704151002




BLK:24,SNR1: 0.55994 ,SNR2: 1.8025




F20230704151004





BLK:24,SNR1: 0.85737 ,SNR2: 2.9734



3C237 2023/07/04 6.20UT TOYOKAWA-FUJI



T20230704151002





No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C237 2023/07/04 6.20UT TOYOKAWA-KISO





F20230704151004




No.Good Data




KISO




No.Good Data




3C237 2023/07/04 6.20UT FUJI -KISO





T20230704151618




BLK:17,SNR1: 0.74406 ,SNR2: 1.8129




F20230704151620





BLK:17,SNR1: 0.69907 ,SNR2: 2.6959



1011+110 2023/07/04 6.30UT TOYOKAWA-FUJI



T20230704151618





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

1011+110 2023/07/04 6.30UT TOYOKAWA-KISO





F20230704151620





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1011+110 2023/07/04 6.30UT FUJI -KISO





T20230704152359




BLK:19,SNR1: 3.1558 ,SNR2: 4.2212




F20230704152401






BLK:19,SNR1: 0.40433 ,SNR2: 1.9203






3C241 2023/07/04 6.43UT TOYOKAWA-FUJI




T20230704152359





KISO



3C241 2023/07/04 6.43UT TOYOKAWA-KISO



F20230704152401





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C241 2023/07/04 6.43UT FUJI -KISO



T20230704153529





BLK:19,SNR1: 0.55612 ,SNR2: 3.1743




Frequency (Hz)

F20230704153531




BLK:19,SNR1: 0.80081 ,SNR2: 2.1786





Frequency (Hz)




1031-11 2023/07/04 6.62UT TOYOKAWA-FUJI




T20230704153529






KISO






1031-11 2023/07/04 6.62UT TOYOKAWA-KISO




F20230704153531




KISO




1031-11 2023/07/04 6.62UT FUJI -KISO




T20230704154002




BLK:23,SNR1: 7.3538 ,SNR2: 12.313




F20230704154004



BLK:23,SNR1: 0.64907 ,SNR2: 1.5541






1035-058 2023/07/04 6.70UT TOYOKAWA-FUJI








T20230704154002






KISO






1035-058 2023/07/04 6.70UT TOYOKAWA-KISO




F20230704154004




KISO




1035-058 2023/07/04 6.70UT FUJI -KISO





T20230704154915




BLK:25,SNR1: 1.8860 ,SNR2: 2.5637




F20230704154917




BLK:25,SNR1: 0.89826E-01,SNR2: 1.7927




1044-008 2023/07/04 6.85UT TOYOKAWA-FUJI




T20230704154915





KISO





1044-008 2023/07/04 6.85UT TOYOKAWA-KISO



F20230704154917





KISO




1044-008 2023/07/04 6.85UT FUJI -KISO



T20230704160019





BLK:27,SNR1: 0.67217 ,SNR2: 2.8375




Frequency (Hz)

F20230704160021




BLK:27,SNR1: 11.420 ,SNR2: 11.310




Frequency (Hz)

1055+01 2023/07/04 7.03UT TOYOKAWA-FUJI



T20230704160019




No.Good Data



Frequency (Hz)

KISO



No.Good Data






Frequency (Hz)




1055+01 2023/07/04 7.03UT TOYOKAWA-KISO




F20230704160021



KISO




1055+01 2023/07/04 7.03UT FUJI -KISO






T20230704161137




BLK:31,SNR1: 1.7643 ,SNR2: 2.2522




Frequency (Hz)

F20230704161139




BLK:31,SNR1: 2.9119 ,SNR2: 5.8085




Frequency (Hz)


1107+109 2023/07/04 7.22UT TOYOKAWA-FUJI



T20230704161137





KISO




1107+109 2023/07/04 7.22UT TOYOKAWA-KISO



F20230704161139





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1107+109 2023/07/04 7.22UT FUJI -KISO



T20230704162114





BLK:24,SNR1: 2.4496 ,SNR2: 3.1135




Frequency (Hz)

F20230704162116




BLK:24,SNR1: 7.3418 ,SNR2: 10.333






Frequency (Hz)




3C255 2023/07/04 7.38UT TOYOKAWA-FUJI




T20230704162114






KISO






3C255 2023/07/04 7.38UT TOYOKAWA-KISO




F20230704162116





KISO




3C255 2023/07/04 7.38UT FUJI -KISO



T20230704164512





BLK:34,SNR1: 0.77690E-01,SNR2: 1.0882




Frequency (Hz)

F20230704164514




BLK:34,SNR1: 1.2150 ,SNR2: 4.3724





Frequency (Hz)


3C263.1 2023/07/04 7.78UT TOYOKAWA-FUJI



T20230704164512





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)

3C263.1 2023/07/04 7.78UT TOYOKAWA-KISO









F20230704164514







KISO




3C263.1 2023/07/04 7.78UT FUJI -KISO











3C267 2023/07/04 7.89UT TOYOKAWA-FUJI




T20230704165139






KISO






3C267 2023/07/04 7.89UT TOYOKAWA-KISO




F20230704165141




KISO




3C267 2023/07/04 7.89UT FUJI -KISO



T20230704171053




BLK:33,SNR1: 3.6313 ,SNR2: 3.5208




Frequency (Hz)

F20230704171055




BLK:33,SNR1: 1.6289 ,SNR2: 2.3211






Frequency (Hz)




1206+439 2023/07/04 8.21UT TOYOKAWA-FUJI




T20230704171053





KISO



1206+439 2023/07/04 8.21UT TOYOKAWA-KISO






F20230704171055




No.Good Data

KISO




No.Good Data


1206+439 2023/07/04 8.21UT FUJI -KISO



T20230704174041





BLK:20,SNR1: 1.9518 ,SNR2: 3.2524




Frequency (Hz)

F20230704174043




BLK:20,SNR1: 1.5432 ,SNR2: 2.4473





Frequency (Hz)

1236+327 2023/07/04 8.71UT TOYOKAWA-FUJI









T20230704174041





KISO




1236+327 2023/07/04 8.71UT TOYOKAWA-KISO



F20230704174043





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1236+327 2023/07/04 8.71UT FUJI -KISO



T20230704181732





BLK:20,SNR1: 1.2506 ,SNR2: 3.3634




Frequency (Hz)

F20230704181734




BLK:20,SNR1: 2.2776 ,SNR2: 5.0112





Frequency (Hz)


1313+453 2023/07/04 9.32UT TOYOKAWA-FUJI



T20230704181732





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1313+453 2023/07/04 9.32UT TOYOKAWA-KISO



F20230704181734




No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1313+453 2023/07/04 9.32UT FUJI -KISO

