



T20230706060229




BLK: 9,SNR1: 10.563 ,SNR2: 66.813




Frequency (Hz)

F20230706060231




BLK: 9,SNR1: 0.46005 ,SNR2: 1.7331




Frequency (Hz)

0103+422 2023/07/05 21.07UT TOYOKAWA-FUJI



T20230706060229




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0103+422 2023/07/05 21.07UT TOYOKAWA-KISO



F20230706060231




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0103+422 2023/07/05 21.07UT FUJI -KISO




T20230706061516




BLK: 4,SNR1:-0.42253E-01,SNR2: 0.84121




F20230706061518



BLK: 4,SNR1: 0.97915E-01,SNR2: 2.5884




0116+31 2023/07/05 21.28UT TOYOKAWA-FUJI



T20230706061516



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0116+31 2023/07/05 21.28UT TOYOKAWA-KISO



F20230706061518



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0116+31 2023/07/05 21.28UT FUJI -KISO



T20230706063323



BLK:18,SNR1: 0.32846 ,SNR2: 2.8405





Frequency (Hz)


3C48

2023/07/05 21.58UT TOYOKAWA-FUJI


F20230706063325



BLK:18,SNR1: 0.20629 ,SNR2: 2.0988



Frequency (Hz)




T20230706063323



No.Good Data




KISO



No.Good Data



3C48 2023/07/05 21.58UT TOYOKAWA-KISO





F20230706063325



No.Good Data



KISO





No.Good Data




3C48 2023/07/05 21.58UT FUJI -KISO



T20230706064706





BLK: 5,SNR1:-0.12256E-01,SNR2: 0.77892




Frequency (Hz)

F20230706064708




BLK: 5,SNR1: 0.22219 ,SNR2: 1.3722



Frequency (Hz)


0148+274 2023/07/05 21.81UT TOYOKAWA-FUJI





T20230706064706




No.Good Data




KISO



No.Good Data




0148+274 2023/07/05 21.81UT TOYOKAWA-KISO



F20230706064708




No.Good Data



KISO





No.Good Data




0148+274 2023/07/05 21.81UT FUJI -KISO



T20230706070015





BLK: 6,SNR1: 0.58131 ,SNR2: 2.5133




Frequency (Hz)

F20230706070017




BLK: 6,SNR1: 0.35812 ,SNR2: 3.7329



Frequency (Hz)


0202+15 2023/07/05 22.03UT TOYOKAWA-FUJI



T20230706070015





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0202+15 2023/07/05 22.03UT TOYOKAWA-KISO



F20230706070017



No.Good Data




KISO





No.Good Data




0202+15 2023/07/05 22.03UT FUJI -KISO



T20230706071205





BLK: 1,SNR1:-0.77002E-01,SNR2: 0.0000




Frequency (Hz)

F20230706071207




BLK: 1,SNR1: 0.56107 ,SNR2: 6.0145



Frequency (Hz)

0213+178 2023/07/05 22.23UT TOYOKAWA-FUJI






T20230706071205




No.Good Data




KISO



No.Good Data



0213+178 2023/07/05 22.23UT TOYOKAWA-KISO



F20230706071207



No.Good Data



KISO





No.Good Data




0213+178 2023/07/05 22.23UT FUJI -KISO



T20230706071947





BLK: 5,SNR1: 0.46237 ,SNR2: 6.0423





3C67 2023/07/05 22.36UT TOYOKAWA-FUJI


F20230706071949



BLK: 5,SNR1: 0.66016 ,SNR2: 1.3799




T20230706071947



No.Good Data




KISO





No.Good Data




3C67 2023/07/05 22.36UT TOYOKAWA-KISO





F20230706071949




No.Good Data



KISO





No.Good Data




3C67 2023/07/05 22.36UT FUJI -KISO



T20230706073803



BLK: 6,SNR1: 0.68535E-01,SNR2: 0.36004





Frequency (Hz)


3C71

2023/07/05 22.66UT TOYOKAWA-FUJI


F20230706073805




BLK: 6,SNR1: 0.55285 ,SNR2: 4.3512




Frequency (Hz)





T20230706073803




No.Good Data




KISO




No.Good Data




3C71 2023/07/05 22.66UT TOYOKAWA-KISO



F20230706073805





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C71 2023/07/05 22.66UT FUJI -KISO






T20230706075717




BLK: 6,SNR1: 0.18450 ,SNR2: 1.1856




Frequency (Hz)

F20230706075719




BLK: 6,SNR1: 0.12157 ,SNR2: 2.6388



Frequency (Hz)

0258+350 2023/07/05 22.98UT TOYOKAWA-FUJI



T20230706075717



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


0258+350 2023/07/05 22.98UT TOYOKAWA-KISO





F20230706075719




No.Good Data




KISO





No.Good Data




0258+350 2023/07/05 22.98UT FUJI -KISO



T20230706080706





BLK: 5,SNR1: 0.84175E-01,SNR2: 0.54555




Frequency (Hz)

F20230706080708




BLK: 5,SNR1: 1.0284 ,SNR2: 4.4458




Frequency (Hz)

0308+305 2023/07/05 23.15UT TOYOKAWA-FUJI



T20230706080706




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0308+305 2023/07/05 23.15UT TOYOKAWA-KISO





F20230706080708




No.Good Data




KISO





No.Good Data




0308+305 2023/07/05 23.15UT FUJI -KISO



T20230706081838





BLK: 5,SNR1: 0.13830 ,SNR2: 0.83852




Frequency (Hz)

F20230706081840




BLK: 5,SNR1: 0.86648 ,SNR2: 5.5466



Frequency (Hz)


0320+05 2023/07/05 23.34UT TOYOKAWA-FUJI





T20230706081838




No.Good Data




KISO



No.Good Data





0320+05 2023/07/05 23.34UT TOYOKAWA-KISO








F20230706081840




No.Good Data




KISO





No.Good Data




0320+05 2023/07/05 23.34UT FUJI -KISO



T20230706083159





BLK: 3,SNR1: 0.75716E-01,SNR2: 0.98829




Frequency (Hz)

F20230706083201




BLK: 3,SNR1: 0.84040 ,SNR2: 5.9521





Frequency (Hz)


0333+32 2023/07/05 23.56UT TOYOKAWA-FUJI





T20230706083159




No.Good Data




KISO




No.Good Data




0333+32 2023/07/05 23.56UT TOYOKAWA-KISO





F20230706083201




No.Good Data




KISO





No.Good Data




0333+32 2023/07/05 23.56UT FUJI -KISO



T20230706084501





BLK: 1,SNR1:-0.20011E-01,SNR2: 0.61255




Frequency (Hz)

F20230706084503




BLK: 1,SNR1: 0.36409 ,SNR2: 2.4292





Frequency (Hz)


0347+05 2023/07/05 23.78UT TOYOKAWA-FUJI





T20230706084501




No.Good Data




KISO




No.Good Data




0347+05 2023/07/05 23.78UT TOYOKAWA-KISO





F20230706084503




No.Good Data




KISO





No.Good Data




0347+05 2023/07/05 23.78UT FUJI -KISO



T20230706090036





BLK: 5,SNR1: 0.25154 ,SNR2: 1.1907




Frequency (Hz)

F20230706090038




BLK: 5,SNR1: 0.45784 ,SNR2: 2.1359





Frequency (Hz)

0403-132 2023/07/06 0.04UT TOYOKAWA-FUJI








T20230706090036




No.Good Data



KISO



No.Good Data



0403-132 2023/07/06 0.04UT TOYOKAWA-KISO



F20230706090038




No.Good Data



KISO





No.Good Data




0403-132 2023/07/06 0.04UT FUJI -KISO



T20230706090946





BLK: 3,SNR1:-0.64751E-01,SNR2: 0.80317




Frequency (Hz)

F20230706090948




BLK: 3,SNR1: 0.71033 ,SNR2: 3.3830



Frequency (Hz)

0411+05 2023/07/06 0.19UT TOYOKAWA-FUJI



T20230706090946



No.Good Data



KISO



No.Good Data



0411+05 2023/07/06 0.19UT TOYOKAWA-KISO



F20230706090948



No.Good Data



KISO





No.Good Data




0411+05 2023/07/06 0.19UT FUJI -KISO




T20230706091640




BLK: 1,SNR1: 0.33766 ,SNR2: 0.68146




F20230706091642




BLK: 1,SNR1: 0.86958 ,SNR2: 13.119




0418+236 2023/07/06 0.31UT TOYOKAWA-FUJI




T20230706091640




No.Good Data



KISO





No.Good Data




0418+236 2023/07/06 0.31UT TOYOKAWA-KISO





F20230706091642




No.Good Data




KISO



No.Good Data




0418+236 2023/07/06 0.31UT FUJI -KISO







T20230706092807




BLK:14,SNR1: 2.2038 ,SNR2: 9.4601




F20230706092809



BLK:14,SNR1:-0.27605 ,SNR2: 2.6033



3C119 2023/07/06 0.50UT TOYOKAWA-FUJI



T20230706092807



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C119 2023/07/06 0.50UT TOYOKAWA-KISO



F20230706092809





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C119 2023/07/06 0.50UT FUJI -KISO



T20230706101615




BLK:29,SNR1: 8.3924 ,SNR2: 36.920





3C138 2023/07/06 1.30UT TOYOKAWA-FUJI


F20230706101617



BLK:29,SNR1: 0.18346 ,SNR2: 1.4170



T20230706101615





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C138 2023/07/06 1.30UT TOYOKAWA-KISO





F20230706101617




No.Good Data




KISO





No.Good Data




3C138 2023/07/06 1.30UT FUJI -KISO





T20230706102948




BLK:24,SNR1: 5.4328 ,SNR2: 22.965




F20230706102950



BLK:24,SNR1: 2.2019 ,SNR2: 5.7823



0531+194 2023/07/06 1.52UT TOYOKAWA-FUJI




T20230706102948



No. Good Data



KISO



No. Good Data




0531+194 2023/07/06 1.52UT TOYOKAWA-KISO







F20230706102950




No.Good Data



KISO




No.Good Data




0531+194 2023/07/06 1.52UT FUJI -KISO



T20230706103806




BLK:21,SNR1: 17.352 ,SNR2: 100.82





3C147 2023/07/06 1.66UT TOYOKAWA-FUJI

F20230706103808




BLK:21,SNR1: 0.18031 ,SNR2: 3.9381



T20230706103806



No. Good Data




Frequency (Hz)

KISO



No. Good Data



Frequency (Hz)

3C147 2023/07/06 1.66UT TOYOKAWA-KISO



F20230706103808



No. Good Data



KISO




No. Good Data




3C147 2023/07/06 1.66UT FUJI -KISO




T20230706104619




BLK:12,SNR1: 1.0887 ,SNR2: 11.352




F20230706104621



BLK:12,SNR1: 0.57880E-01,SNR2: 2.4289



0548+16 2023/07/06 1.80UT TOYOKAWA-FUJI



T20230706104619





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


0548+16 2023/07/06 1.80UT TOYOKAWA-KISO




F20230706104621




No.Good Data



KISO





No.Good Data




0548+16 2023/07/06 1.80UT FUJI -KISO





T20230706105030




BLK:12,SNR1: 11.546 ,SNR2: 111.79




F20230706105032



BLK:12,SNR1: 0.28396 ,SNR2: 1.0333



0552+12 2023/07/06 1.87UT TOYOKAWA-FUJI





T20230706105030



No. Good Data



Frequency (Hz)

KISO



No. Good Data



Frequency (Hz)

0552+12 2023/07/06 1.87UT TOYOKAWA-KISO



F20230706105032



No. Good Data




KISO





No. Good Data




0552+12 2023/07/06 1.87UT FUJI -KISO




T20230706105457




BLK: 6,SNR1: 0.43287 ,SNR2: 4.9001




F20230706105459



BLK: 6,SNR1: 0.43491 ,SNR2: 4.3411




0556+191 2023/07/06 1.94UT TOYOKAWA-FUJI



T20230706105457





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0556+191 2023/07/06 1.94UT TOYOKAWA-KISO



F20230706105459





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0556+191 2023/07/06 1.94UT FUJI -KISO



T20230706110243




BLK: 2,SNR1: 0.40184E-01,SNR2: 0.58493





0605-08 2023/07/06 2.07UT TOYOKAWA-FUJI

F20230706110245




BLK: 2,SNR1: 0.42896 ,SNR2: 1.3328



T20230706110243



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0605-08 2023/07/06 2.07UT TOYOKAWA-KISO



F20230706110245



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0605-08 2023/07/06 2.07UT FUJI -KISO






T20230706112151




BLK:19,SNR1: 1.4882 ,SNR2: 8.4771





3C161 2023/07/06 2.39UT TOYOKAWA-FUJI

F20230706112153



BLK:19,SNR1: 0.39409 ,SNR2: 2.4416



T20230706112151



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/07/06 2.39UT TOYOKAWA-KISO



F20230706112153





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/07/06 2.39UT FUJI -KISO



T20230706114924





BLK: 6,SNR1: 0.92559E-01,SNR2: 0.44983





0652-130 2023/07/06 2.85UT TOYOKAWA-FUJI

F20230706114926



BLK: 6,SNR1: 0.47770 ,SNR2: 3.1362



T20230706114924



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0652-130 2023/07/06 2.85UT TOYOKAWA-KISO



F20230706114926





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2023/07/06 2.85UT FUJI -KISO





T20230706120100




BLK: 6,SNR1: 0.72146E-01,SNR2: 2.0220




F20230706120102



BLK: 6,SNR1: 0.40071 ,SNR2: 2.6849



0703+138 2023/07/06 3.04UT TOYOKAWA-FUJI



T20230706120100





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0703+138 2023/07/06 3.04UT TOYOKAWA-KISO





F20230706120102





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0703+138 2023/07/06 3.04UT FUJI -KISO




T20230706121023




BLK: 6,SNR1: 0.27397 ,SNR2: 3.1620




F20230706121025



BLK: 6,SNR1: 0.28031 ,SNR2: 5.9578



0713-024 2023/07/06 3.20UT TOYOKAWA-FUJI



T20230706121023



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0713-024 2023/07/06 3.20UT TOYOKAWA-KISO



F20230706121025



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0713-024 2023/07/06 3.20UT FUJI -KISO





T20230706122034




BLK:18,SNR1: 1.0212 ,SNR2: 5.0256




F20230706122036



BLK:18,SNR1: 0.39477 ,SNR2: 2.5181



0723+10 2023/07/06 3.37UT TOYOKAWA-FUJI



T20230706122034



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0723+10 2023/07/06 3.37UT TOYOKAWA-KISO





F20230706122036




No.Good Data




KISO





No.Good Data




0723+10 2023/07/06 3.37UT FUJI -KISO




T20230706123048




BLK:25,SNR1: 0.66524 ,SNR2: 7.7095




F20230706123050



BLK:25,SNR1: 0.26435 ,SNR2: 2.2660





0732+33 2023/07/06 3.54UT TOYOKAWA-FUJI






T20230706123048





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0732+33 2023/07/06 3.54UT TOYOKAWA-KISO





F20230706123050




No.Good Data




KISO





No.Good Data




0732+33 2023/07/06 3.54UT FUJI -KISO




T20230706123851




BLK:14,SNR1: 1.0668 ,SNR2: 7.3297




F20230706123853




BLK:14,SNR1:-0.75882E-02,SNR2: 0.84979



0741-06 2023/07/06 3.68UT TOYOKAWA-FUJI



T20230706123851




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

0741-06 2023/07/06 3.68UT TOYOKAWA-KISO





F20230706123853




No.Good Data




KISO





No.Good Data




0741-06 2023/07/06 3.68UT FUJI -KISO



T20230706125610




BLK:14,SNR1: 0.47298 ,SNR2: 3.9605





3C190 2023/07/06 3.96UT TOYOKAWA-FUJI


F20230706125612



BLK:14,SNR1: 0.49809 ,SNR2: 1.2672



T20230706125610




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C190 2023/07/06 3.96UT TOYOKAWA-KISO



F20230706125612





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C190 2023/07/06 3.96UT FUJI -KISO







T20230706130834




BLK:18,SNR1: 0.44043 ,SNR2: 2.8883




F20230706130836



BLK:18,SNR1: 0.39725 ,SNR2: 4.6481



3C196 2023/07/06 4.17UT TOYOKAWA-FUJI



T20230706130834



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C196 2023/07/06 4.17UT TOYOKAWA-KISO



F20230706130836





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C196 2023/07/06 4.17UT FUJI -KISO





T20230706131944




BLK: 7,SNR1: 1.2649 ,SNR2: 9.7624




F20230706131946



BLK: 7,SNR1: 0.74890 ,SNR2: 5.3557



0821+394 2023/07/06 4.36UT TOYOKAWA-FUJI



T20230706131944



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0821+394 2023/07/06 4.36UT TOYOKAWA-KISO



F20230706131946





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0821+394 2023/07/06 4.36UT FUJI -KISO




T20230706133630




BLK: 4,SNR1: 0.39399 ,SNR2: 4.4733




F20230706133632



BLK: 4,SNR1: 0.41334 ,SNR2: 1.5357




0839-071 2023/07/06 4.64UT TOYOKAWA-FUJI



T20230706133630



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0839-071 2023/07/06 4.64UT TOYOKAWA-KISO





F20230706133632





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0839-071 2023/07/06 4.64UT FUJI -KISO



T20230706134731




BLK: 9,SNR1: 0.94475 ,SNR2: 3.7419




Frequency (Hz)

F20230706134733




BLK: 9,SNR1: 0.40612 ,SNR2: 1.2187





Frequency (Hz)


3C208 2023/07/06 4.82UT TOYOKAWA-FUJI



T20230706134731





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C208 2023/07/06 4.82UT TOYOKAWA-KISO



F20230706134733





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2023/07/06 4.82UT FUJI -KISO





T20230706140412




BLK: 6,SNR1: 0.67222E-01,SNR2: 0.59277




F20230706140414





BLK: 6,SNR1: 0.95221 ,SNR2: 6.0110




3C216 2023/07/06 5.10UT TOYOKAWA-FUJI





T20230706140412




No.Good Data




KISO





No.Good Data



3C216 2023/07/06 5.10UT TOYOKAWA-KISO



F20230706140414





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C216 2023/07/06 5.10UT FUJI -KISO





T20230706142303




BLK: 3,SNR1: 0.85753E-01,SNR2: 0.30808




F20230706142305



BLK: 3,SNR1: 0.11885 ,SNR2: 1.3090




0926+117 2023/07/06 5.41UT TOYOKAWA-FUJI





T20230706142303





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0926+117 2023/07/06 5.41UT TOYOKAWA-KISO



F20230706142305





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0926+117 2023/07/06 5.41UT FUJI -KISO




T20230706143048




BLK: 9,SNR1: 0.32395 ,SNR2: 2.2266




F20230706143050





BLK: 9,SNR1: 0.85520E-01,SNR2: 4.5394




3C222 2023/07/06 5.54UT TOYOKAWA-FUJI



T20230706143048





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C222 2023/07/06 5.54UT TOYOKAWA-KISO



F20230706143050



No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


3C222 2023/07/06 5.54UT FUJI -KISO





T20230706143748




BLK: 4,SNR1: 0.18863 ,SNR2: 1.6637




F20230706143750






BLK: 4,SNR1:-0.16269 ,SNR2: 0.48894






0941-08 2023/07/06 5.66UT TOYOKAWA-FUJI



T20230706143748




KISO



0941-08 2023/07/06 5.66UT TOYOKAWA-KISO



F20230706143750





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0941-08 2023/07/06 5.66UT FUJI -KISO







T20230706144610




BLK: 2,SNR1: 0.21074 ,SNR2: 1.1996




F20230706144612



BLK: 2,SNR1:-0.11124 ,SNR2: 0.87314



3C230 2023/07/06 5.80UT TOYOKAWA-FUJI



T20230706144610




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C230 2023/07/06 5.80UT TOYOKAWA-KISO



F20230706144612





No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C230 2023/07/06 5.80UT FUJI -KISO




T20230706150210




BLK:12,SNR1: 0.32648 ,SNR2: 1.9024




F20230706150212






BLK:12,SNR1: 2.7984 ,SNR2: 7.6709






3C237 2023/07/06 6.06UT TOYOKAWA-FUJI




T20230706150210





KISO



3C237 2023/07/06 6.06UT TOYOKAWA-KISO





F20230706150212




No.Good Data




KISO





No.Good Data




3C237 2023/07/06 6.06UT FUJI -KISO





T20230706150826




BLK: 7,SNR1: 0.49081E-01,SNR2: 0.70827




F20230706150828




BLK: 7,SNR1: 0.15217 ,SNR2: 0.81288



1011+110 2023/07/06 6.17UT TOYOKAWA-FUJI



T20230706150826




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1011+110 2023/07/06 6.17UT TOYOKAWA-KISO





F20230706150828





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1011+110 2023/07/06 6.17UT FUJI -KISO



T20230706151607





BLK:10,SNR1: 0.17458 ,SNR2: 2.0009




Frequency (Hz)

F20230706151609




BLK:10,SNR1: 0.48268 ,SNR2: 1.9185





Frequency (Hz)

3C241 2023/07/06 6.30UT TOYOKAWA-FUJI



T20230706151607





No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C241 2023/07/06 6.30UT TOYOKAWA-KISO



F20230706151609




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C241 2023/07/06 6.30UT FUJI -KISO




T20230706152737




BLK: 5,SNR1: 0.37574E-01,SNR2: 0.40890




F20230706152739





BLK: 5,SNR1: 0.36720 ,SNR2: 1.9592




1031-11 2023/07/06 6.49UT TOYOKAWA-FUJI



T20230706152737





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1031-11 2023/07/06 6.49UT TOYOKAWA-KISO



F20230706152739





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1031-11 2023/07/06 6.49UT FUJI -KISO




T20230706153210




BLK: 2,SNR1: 0.83085E-01,SNR2: 0.61306




F20230706153212



BLK: 2,SNR1: 2.1074 ,SNR2: 7.0865






1035-058 2023/07/06 6.56UT TOYOKAWA-FUJI









T20230706153210




KISO




1035-058 2023/07/06 6.56UT TOYOKAWA-KISO



F20230706153212




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/07/06 6.56UT FUJI -KISO




T20230706154123




BLK: 4,SNR1: 0.25488 ,SNR2: 0.56858




F20230706154125





BLK: 4,SNR1:-0.39943E-02,SNR2: 0.77906




1044-008 2023/07/06 6.72UT TOYOKAWA-FUJI



T20230706154123





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1044-008 2023/07/06 6.72UT TOYOKAWA-KISO



F20230706154125





KISO




1044-008 2023/07/06 6.72UT FUJI -KISO



T20230706155227





BLK: 4,SNR1: 0.26894 ,SNR2: 0.75738




Frequency (Hz)

F20230706155229




BLK: 4,SNR1: 3.2094 ,SNR2: 7.0413






Frequency (Hz)




1055+01 2023/07/06 6.90UT TOYOKAWA-FUJI




T20230706155227




KISO




1055+01 2023/07/06 6.90UT TOYOKAWA-KISO



F20230706155229




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1055+01 2023/07/06 6.90UT FUJI -KISO







T20230706160345




BLK: 4,SNR1: 0.75558E-01,SNR2: 0.43994




F20230706160347




BLK: 4,SNR1: 0.86671 ,SNR2: 2.2786




1107+109 2023/07/06 7.09UT TOYOKAWA-FUJI



T20230706160345





KISO




1107+109 2023/07/06 7.09UT TOYOKAWA-KISO



F20230706160347





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1107+109 2023/07/06 7.09UT FUJI -KISO





T20230706161322




BLK: 2,SNR1: 0.27555 ,SNR2: 0.96866




F20230706161324






BLK: 2,SNR1:-0.12558 ,SNR2: 0.92229






3C255 2023/07/06 7.25UT TOYOKAWA-FUJI




T20230706161322






KISO



3C255 2023/07/06 7.25UT TOYOKAWA-KISO






F20230706161324




No.Good Data

KISO





No.Good Data


3C255 2023/07/06 7.25UT FUJI -KISO



T20230706163720




BLK: 4,SNR1: 0.24535 ,SNR2: 1.7153




Frequency (Hz)

F20230706163722




BLK: 4,SNR1: 0.12434 ,SNR2: 1.4019






Frequency (Hz)

3C263.1 2023/07/06 7.65UT TOYOKAWA-FUJI






T20230706163720




No.Good Data

KISO






No.Good Data

3C263.1 2023/07/06 7.65UT TOYOKAWA-KISO








F20230706163722





KISO




3C263.1 2023/07/06 7.65UT FUJI -KISO





T20230706164347




BLK: 6,SNR1: 0.27249 ,SNR2: 0.81989




F20230706164349






BLK: 6,SNR1: 0.72853E-01,SNR2: 1.5993






3C267 2023/07/06 7.76UT TOYOKAWA-FUJI




T20230706164347





KISO




3C267 2023/07/06 7.76UT TOYOKAWA-KISO





F20230706164349




No.Good Data




KISO





No.Good Data




3C267 2023/07/06 7.76UT FUJI -KISO



T20230706170302




BLK: 2,SNR1: 0.17634 ,SNR2: 0.36589




Frequency (Hz)

F20230706170304




BLK: 2,SNR1: 0.57692 ,SNR2: 1.2796






Frequency (Hz)




1206+439 2023/07/06 8.08UT TOYOKAWA-FUJI




T20230706170302




KISO




1206+439 2023/07/06 8.08UT TOYOKAWA-KISO





F20230706170304




No.Good Data




KISO





No.Good Data




1206+439 2023/07/06 8.08UT FUJI -KISO



T20230706180940




BLK: 3,SNR1: 0.24127 ,SNR2: 0.97051




Frequency (Hz)

F20230706180942




BLK: 3,SNR1: 0.20149 ,SNR2: 0.63911





Frequency (Hz)

1313+453 2023/07/06 9.19UT TOYOKAWA-FUJI






T20230706180940





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1313+453 2023/07/06 9.19UT TOYOKAWA-KISO



F20230706180942



KISO



1313+453 2023/07/06 9.19UT FUJI -KISO

