




T20230707054407





BLK: 4,SNR1: 0.20292 ,SNR2: 0.44711




Frequency (Hz)

F20230707054409




BLK: 4,SNR1: 0.36049 ,SNR2: 4.3716





Frequency (Hz)


0049+379 2023/07/06 20.76UT TOYOKAWA-FUJI



T20230707054407



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0049+379 2023/07/06 20.76UT TOYOKAWA-KISO




F20230707054409



No.Good Data



KISO




No.Good Data




0049+379 2023/07/06 20.76UT FUJI -KISO



T20230707055833





BLK: 6,SNR1: 0.66295 ,SNR2: 4.5766




Frequency (Hz)

F20230707055835




BLK: 6,SNR1: 0.56455E-01,SNR2: 2.6123



Frequency (Hz)

0103+422 2023/07/06 21.00UT TOYOKAWA-FUJI




T20230707055833



No.Good Data




KISO



No.Good Data



0103+422 2023/07/06 21.00UT TOYOKAWA-KISO




F20230707055835



No.Good Data



KISO




No.Good Data




0103+422 2023/07/06 21.00T FUJI -KISO



T20230707061120





BLK:10,SNR1: 0.21317 ,SNR2: 3.4750




Frequency (Hz)

F20230707061122




BLK:10,SNR1: 0.78208 ,SNR2: 3.7796



Frequency (Hz)


0116+31 2023/07/06 21.22UT TOYOKAWA-FUJI



T20230707061120



No.Good Data




KISO



No.Good Data




0116+31 2023/07/06 21.22UT TOYOKAWA-KISO






F20230707061122



No.Good Data



KISO





No.Good Data




0116+31 2023/07/06 21.22UT FUJI -KISO



T20230707062927



BLK:16,SNR1: 0.66407 ,SNR2: 3.6885





Frequency (Hz)


3C48

2023/07/06 21.52UT TOYOKAWA-FUJI


F20230707062929




BLK:16,SNR1:-0.52069E-01,SNR2: 2.2765




Frequency (Hz)




T20230707062927




No.Good Data




KISO



No.Good Data



3C48 2023/07/06 21.52UT TOYOKAWA-KISO



F20230707062929




No.Good Data



KISO





No.Good Data




3C48 2023/07/06 21.52UT FUJI -KISO



T20230707064310




BLK: 1,SNR1: 0.26638E-02,SNR2: 0.41897




Frequency (Hz)

F20230707064312




BLK: 1,SNR1:-0.35726 ,SNR2: 0.15673




Frequency (Hz)


0148+274 2023/07/06 21.75UT TOYOKAWA-FUJI




T20230707064310




No.Good Data




KISO




No.Good Data



0148+274 2023/07/06 21.75UT TOYOKAWA-KISO




F20230707064312



No.Good Data



KISO





No.Good Data




0148+274 2023/07/06 21.75UT FUJI -KISO



T20230707065619




BLK: 2,SNR1: 0.13092E-01,SNR2: 0.40559




Frequency (Hz)

F20230707065621




BLK: 2,SNR1: 1.7837 ,SNR2: 7.2951




Frequency (Hz)

0202+15 2023/07/06 21.97UT TOYOKAWA-FUJI






T20230707065619





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0202+15 2023/07/06 21.97UT TOYOKAWA-KISO



F20230707065621



No.Good Data



KISO




No.Good Data




0202+15 2023/07/06 21.97UT FUJI -KISO



T20230707070809




BLK: 2,SNR1: 0.22340 ,SNR2: 0.67363




Frequency (Hz)

F20230707070811




BLK: 2,SNR1: 2.7620 ,SNR2: 7.7425





Frequency (Hz)


0213+178 2023/07/06 22.16UT TOYOKAWA-FUJI




T20230707070809




No.Good Data




KISO



No.Good Data



0213+178 2023/07/06 22.16UT TOYOKAWA-KISO



F202307070811



No.Good Data



KISO





No.Good Data




0213+178 2023/07/06 22.16UT FUJI -KISO



T20230707071551



BLK: 4,SNR1: 0.30194 ,SNR2: 1.2413





Frequency (Hz)


3C67

2023/07/06 22.29UT TOYOKAWA-FUJI


F20230707071553



BLK: 4,SNR1: 0.56734 ,SNR2: 1.6777



Frequency (Hz)



T20230707071551



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


3C67 2023/07/06 22.29UT TOYOKAWA-KISO



F20230707071553




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C67 2023/07/06 22.29UT FUJI -KISO






T20230707073407





BLK: 5,SNR1: 0.13942 ,SNR2: 1.5647




Frequency (Hz)

3C71 2023/07/06 22.60UT TOYOKAWA-FUJI


F20230707073409



BLK: 5,SNR1: 0.34467 ,SNR2: 2.0819



Frequency (Hz)



T20230707073407




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C71 2023/07/06 22.80UT TOYOKAWA-KISO



F20230707073409





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C71 2023/07/06 22.60UT FUJI -KISO



T20230707075321





BLK:12,SNR1: 0.48005 ,SNR2: 1.8627




Frequency (Hz)

F20230707075323




BLK:12,SNR1: 0.47769 ,SNR2: 1.9800



Frequency (Hz)

0258+350 2023/07/06 22.92UT TOYOKAWA-FUJI



T20230707075321



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0258+350 2023/07/06 22.92UT TOYOKAWA-KISO



F20230707075323




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0258+350 2023/07/06 22.92UT FUJI -KISO



T20230707080310





BLK: 5,SNR1:-0.29114E-03,SNR2: 1.0338




Frequency (Hz)

F20230707080312




BLK: 5,SNR1: 0.21206 ,SNR2: 1.6215



Frequency (Hz)


0308+305 2023/07/06 23.08UT TOYOKAWA-FUJI



T20230707080310



No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0308+305 2023/07/06 23.08UT TOYOKAWA-KISO






F20230707080312





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0308+305 2023/07/06 23.08UT FUJI -KISO



T20230707081443





BLK: 6,SNR1: 0.22041 ,SNR2: 2.2680




Frequency (Hz)

F20230707081445




BLK: 6,SNR1: 0.65686 ,SNR2: 3.6121



Frequency (Hz)

0320+05 2023/07/06 23.27UT TOYOKAWA-FUJI



T20230707081443



No.Good Data




KISO



No.Good Data




0320+05 2023/07/06 23.27UT TOYOKAWA-KISO





F20230707081445




No.Good Data




KISO





No.Good Data




0320+05 2023/07/06 23.27UT FUJI -KISO



T20230707082803





BLK: 6,SNR1: 0.15369 ,SNR2: 1.2916




Frequency (Hz)

F20230707082805




BLK: 6,SNR1: 0.48543 ,SNR2: 2.5966



Frequency (Hz)

0333+32 2023/07/06 23.50UT TOYOKAWA-FUJI



T20230707082803



No.Good Data




KISO



No.Good Data




0333+32 2023/07/06 23.50UT TOYOKAWA-KISO




F20230707082805




No.Good Data



KISO





No.Good Data




0333+32 2023/07/06 23.50UT FUJI -KISO



T20230707084105





BLK: 7,SNR1: 0.70639E-01,SNR2: 0.85730




Frequency (Hz)

F20230707084107




BLK: 7,SNR1: 0.31846 ,SNR2: 1.0271



Frequency (Hz)

0347+05 2023/07/06 23.71UT TOYOKAWA-FUJI





T20230707084105



No.Good Data



KISO



No.Good Data



0347+05 2023/07/06 23.71UT TOYOKAWA-KISO



F20230707084107



No.Good Data



KISO





No.Good Data




0347+05 2023/07/06 23.71UT FUJI -KISO



T20230707090550





BLK: 4,SNR1: 0.10874 ,SNR2: 1.0555




Frequency (Hz)

F20230707090552




BLK: 4,SNR1: 0.45123 ,SNR2: 1.6294



Frequency (Hz)

0411+05 2023/07/07 0.13UT TOYOKAWA-FUJI



T20230707090550



No.Good Data



KISO



No.Good Data



0411+05 2023/07/07 0.13UT TOYOKAWA-KISO





F20230707090552




No.Good Data



KISO





No.Good Data




0411+05 2023/07/07 0.13UT FUJI -KISO





T20230707091244




BLK: 7,SNR1: 0.72607E-01,SNR2: 1.0197




F20230707091246



BLK: 7,SNR1: 1.9579 ,SNR2: 5.6613



0418+236 2023/07/07 0.24UT TOYOKAWA-FUJI



T20230707091244



No.Good Data



KISO



No.Good Data



0418+236 2023/07/07 0.24UT TOYOKAWA-KISO



F20230707091246



No.Good Data



KISO



No.Good Data





0418+236 2023/07/07 0.24UT FUJI -KISO






T20230707092411





BLK:18,SNR1: 0.87477 ,SNR2: 3.2978




Frequency (Hz)

F20230707092413




BLK:18,SNR1: 0.19723 ,SNR2: 1.0615




Frequency (Hz)

3C119 2023/07/07 0.43UT TOYOKAWA-FUJI




T20230707092411




No.Good Data



KISO




No.Good Data



3C119 2023/07/07 0.43UT TOYOKAWA-KISO





F20230707092413




No. Good Data



KISO





No. Good Data




3C119 2023/07/07 0.43UT FUJI -KISO



T20230707101219





BLK:23,SNR1: 4.3016 ,SNR2: 19.150




Frequency (Hz)

F20230707101221




BLK:23,SNR1: 0.20668 ,SNR2: 0.98414



Frequency (Hz)

3C138 2023/07/07 1.23UT TOYOKAWA-FUJI



T20230707101219



No. Good Data



KISO





No. Good Data




3C138 2023/07/07 1.23UT TOYOKAWA-KISO




F20230707101221




No. Good Data




KISO





No. Good Data




3C138 2023/07/07 1.23UT FUJI -KISO



T20230707102552





BLK:24,SNR1: 24.939 ,SNR2: 65.088




Frequency (Hz)

F20230707102554




BLK:24,SNR1: 0.39573 ,SNR2: 2.6463



Frequency (Hz)

0531+194 2023/07/07 1.46UT TOYOKAWA-FUJI




T20230707102552



No. Good Data



KISO



No. Good Data





0531+194 2023/07/07 1.46UT TOYOKAWA-KISO







F20230707102554



No.Good Data




KISO




No.Good Data




0531+194 2023/07/07 1.46UT FUJI -KISO





T20230707103410




BLK:29,SNR1: 24.276 ,SNR2: 45.684




F20230707103412



BLK:29,SNR1: 87.139 ,SNR2: 91.671




3C147 2023/07/07 1.60UT TOYOKAWA-FUJI



T20230707103410



No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C147 2023/07/07 1.60UT TOYOKAWA-KISO



F20230707103412



No.Good Data




KISO




No.Good Data




3C147 2023/07/07 1.60UT FUJI -KISO




T20230707104223




BLK:15,SNR1: 0.67332 ,SNR2: 6.4613




F20230707104225



BLK:15,SNR1: 0.83807E-01,SNR2: 1.5154



0548+16 2023/07/07 1.73UT TOYOKAWA-FUJI





T20230707104223




No. Good Data



KISO




No. Good Data




0548+16 2023/07/07 1.73UT TOYOKAWA-KISO




F20230707104225




No. Good Data



KISO




No. Good Data




0548+16 2023/07/07 1.73UT FUJI -KISO





T20230707104634




BLK: 6,SNR1: 38.806 ,SNR2: 138.39




F20230707104636



BLK: 6,SNR1: 0.25047 ,SNR2: 3.9618



0552+12 2023/07/07 1.80UT TOYOKAWA-FUJI





T20230707104634



No. Good Data



Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0552+12 2023/07/07 1.80UT TOYOKAWA-KISO



F20230707104636





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0552+12 2023/07/07 1.80UT FUJI -KISO



T20230707105101





BLK: 9,SNR1: 0.17425 ,SNR2: 1.6165




Frequency (Hz)

F20230707105103




BLK: 9,SNR1: 0.68004 ,SNR2: 4.6563



Frequency (Hz)


0556+191 2023/07/07 1.88UT TOYOKAWA-FUJI



T20230707105101





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0556+191 2023/07/07 1.88UT TOYOKAWA-KISO



F20230707105103





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0556+191 2023/07/07 1.88UT FUJI -KISO



T20230707105847




BLK: 5,SNR1: 2.4446 ,SNR2: 21.929





0605-08 2023/07/07 2.01UT TOYOKAWA-FUJI

F20230707105849




BLK: 5,SNR1: 0.17508 ,SNR2: 2.1585



T20230707105847



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0605-08 2023/07/07 2.01UT TOYOKAWA-KISO





F20230707105849




No.Good Data




KISO



No.Good Data




0605-08 2023/07/07 2.01UT FUJI -KISO






T20230707111755





BLK:20,SNR1: 1.5507 ,SNR2: 13.315




Frequency (Hz)

3C161 2023/07/07 2.33UT TOYOKAWA-FUJI


F20230707111757



BLK:20,SNR1: 0.35494E-01,SNR2: 2.4780



Frequency (Hz)



T20230707111755



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/07/07 2.33UT TOYOKAWA-KISO



F20230707111757




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/07/07 2.33UT FUJI -KISO





T20230707114528




BLK: 5,SNR1: 0.16525 ,SNR2: 0.59834




F20230707114530



BLK: 5,SNR1: 0.29835 ,SNR2: 1.1227



0652-130 2023/07/07 2.79UT TOYOKAWA-FUJI



T20230707114528



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0652-130 2023/07/07 2.79UT TOYOKAWA-KISO





F20230707114530




No.Good Data




KISO





No.Good Data




0652-130 2023/07/07 2.79UT FUJI -KISO





T20230707115704




BLK: 9,SNR1: 0.23318 ,SNR2: 1.8350




F20230707115706



BLK: 9,SNR1: 1.9012 ,SNR2: 7.1872



0703+138 2023/07/07 2.98UT TOYOKAWA-FUJI



T20230707115704



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0703+138 2023/07/07 2.98UT TOYOKAWA-KISO





F20230707115706



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0703+138 2023/07/07 2.98UT FUJI -KISO



T20230707120627




BLK: 4,SNR1: 0.13161 ,SNR2: 1.7045




Frequency (Hz)

F20230707120629




BLK: 4,SNR1: 0.34300E-01,SNR2: 1.6210



Frequency (Hz)

0713-024 2023/07/07 3.14UT TOYOKAWA-FUJI



T20230707120627



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0713-024 2023/07/07 3.14UT TOYOKAWA-KISO



F20230707120629





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0713-024 2023/07/07 3.14UT FUJI -KISO





T20230707121639




BLK:13,SNR1: 0.74246 ,SNR2: 6.3719




F20230707121641



BLK:13,SNR1: 0.28743 ,SNR2: 1.7835



0723+10 2023/07/07 3.31UT TOYOKAWA-FUJI



T20230707121639



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0723+10 2023/07/07 3.31UT TOYOKAWA-KISO



F20230707121641



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0723+10 2023/07/07 3.31UT FUJI -KISO




T20230707122652




BLK:20,SNR1: 1.1163 ,SNR2: 5.7335




F20230707122654



BLK:20,SNR1: 0.84405 ,SNR2: 4.3571




0732+33 2023/07/07 3.48UT TOYOKAWA-FUJI





T20230707122652




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0732+33 2023/07/07 3.48UT TOYOKAWA-KISO





F20230707122654




No.Good Data




KISO




No.Good Data




0732+33 2023/07/07 3.48UT FUJI -KISO



T20230707123456




BLK: 7,SNR1: 0.64803 ,SNR2: 5.9211





0741-06 2023/07/07 3.61UT TOYOKAWA-FUJI



F20230707123458




BLK: 7,SNR1: 0.23186 ,SNR2: 2.3278



T20230707123456





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0741-06 2023/07/07 3.61UT TOYOKAWA-KISO



F20230707123458




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0741-06 2023/07/07 3.61UT FUJI -KISO




T20230707125214




BLK:11,SNR1: 0.49757 ,SNR2: 4.7505




F20230707125216




BLK:11,SNR1: 0.45954 ,SNR2: 2.8517



3C190 2023/07/07 3.90UT TOYOKAWA-FUJI



T20230707125214




No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


3C190 2023/07/07 3.90UT TOYOKAWA-KISO



F20230707125216





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C190 2023/07/07 3.90UT FUJI -KISO







T20230707130438




BLK:16,SNR1: 0.48201 ,SNR2: 2.2031




F20230707130440



BLK:16,SNR1: 0.47011E-01,SNR2: 2.3063



3C196 2023/07/07 4.11UT TOYOKAWA-FUJI



T20230707130438



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C196 2023/07/07 4.11UT TOYOKAWA-KISO



F20230707130440



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C196 2023/07/07 4.11UT FUJI -KISO




T20230707131548




BLK:10,SNR1: 0.81977E-01,SNR2: 0.48836




F20230707131550





BLK:10,SNR1: 22.192 ,SNR2: 55.145




0821+394 2023/07/07 4.29UT TOYOKAWA-FUJI



T20230707131548



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0821+394 2023/07/07 4.29UT TOYOKAWA-KISO



F20230707131550





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


0821+394 2023/07/07 4.29UT FUJI -KISO




T20230707133234




BLK: 6,SNR1: 1.2208 ,SNR2: 5.1499




F20230707133236



BLK: 6,SNR1:-0.27028E-01,SNR2: 2.1355



0839-071 2023/07/07 4.57UT TOYOKAWA-FUJI



T20230707133234



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0839-071 2023/07/07 4.57UT TOYOKAWA-KISO





F20230707133236





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0839-071 2023/07/07 4.57UT FUJI -KISO





T20230707134335




BLK: 4,SNR1: 0.25823 ,SNR2: 2.4322




F20230707134337



BLK: 4,SNR1:-0.96043E-01,SNR2: 0.41241



3C208 2023/07/07 4.75UT TOYOKAWA-FUJI



T20230707134335



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C208 2023/07/07 4.75UT TOYOKAWA-KISO



F20230707134337





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C208 2023/07/07 4.75UT FUJI -KISO




T20230707140016




BLK: 5,SNR1: 2.1201 ,SNR2: 6.4302




F20230707140018





BLK: 5,SNR1: 0.15494 ,SNR2: 2.3328




3C216 2023/07/07 5.03UT TOYOKAWA-FUJI



T20230707140016





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C216 2023/07/07 5.03UT TOYOKAWA-KISO



F20230707140018





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C216 2023/07/07 5.03UT FUJI -KISO





T20230707141907




BLK: 3,SNR1: 0.70626 ,SNR2: 16.134




F20230707141909



BLK: 3,SNR1:-0.12347 ,SNR2: 2.7174




0926+117 2023/07/07 5.35UT TOYOKAWA-FUJI





T20230707141907





No. Good Data



Frequency (Hz)

KISO




No. Good Data






Frequency (Hz)




0926+117 2023/07/07 5.35UT TOYOKAWA-KISO




F20230707141909





KISO




0926+117 2023/07/07 5.35UT FUJI -KISO





T20230707142652




BLK:15,SNR1: 5.0008 ,SNR2: 11.423




F20230707142654





BLK:15,SNR1: 0.73588 ,SNR2: 8.6237




3C222 2023/07/07 5.48UT TOYOKAWA-FUJI



T20230707142652





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C222 2023/07/07 5.48UT TOYOKAWA-KISO



F20230707142654





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C222 2023/07/07 5.48UT FUJI -KISO




T20230707143352




BLK: 1,SNR1: 0.52191 ,SNR2: 1.4281




F20230707143354






BLK: 1,SNR1: 0.80662 ,SNR2: 5.5950






0941-08 2023/07/07 5.59UT TOYOKAWA-FUJI




T20230707143352




KISO



0941-08 2023/07/07 5.59UT TOYOKAWA-KISO



F20230707143354





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0941-08 2023/07/07 5.59UT FUJI -KISO








T20230707144214




BLK: 2,SNR1: 0.21810E-01,SNR2: 1.6834




F20230707144216



BLK: 2,SNR1:-0.57196E-01,SNR2: 1.8185



3C230 2023/07/07 5.73UT TOYOKAWA-FUJI



T20230707144214



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C230 2023/07/07 5.73UT TOYOKAWA-KISO



F20230707144216





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C230 2023/07/07 5.73UT FUJI -KISO





T20230707145814




BLK:22,SNR1: 0.73286 ,SNR2: 10.186




F20230707145816





BLK:22,SNR1:-0.40991E-01,SNR2: 4.7496






3C237 2023/07/07 6.00UT TOYOKAWA-FUJI




T20230707145814



KISO



3C237 2023/07/07 6.00UT TOYOKAWA-KISO



F20230707145816



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C237 2023/07/07 6.00UT FUJI -KISO



T20230707150430





BLK: 3,SNR1: 2.9511 ,SNR2: 15.856




Frequency (Hz)

F20230707150432




BLK: 3,SNR1: 0.85386 ,SNR2: 2.0894




Frequency (Hz)

1011+110 2023/07/07 6.10UT TOYOKAWA-FUJI



T20230707150430




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

1011+110 2023/07/07 6.10UT TOYOKAWA-KISO





F20230707150432





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1011+110 2023/07/07 6.10UT FUJI -KISO





T20230707151211




BLK: 6,SNR1: 0.26327 ,SNR2: 1.9078




F20230707151213






BLK: 6,SNR1: 0.35430 ,SNR2: 3.8969






3C241 2023/07/07 6.23UT TOYOKAWA-FUJI




T20230707151211






KISO






3C241 2023/07/07 6.23UT TOYOKAWA-KISO




F20230707151213





KISO




3C241 2023/07/07 6.23UT FUJI -KISO




T20230707152341




BLK:12,SNR1: 0.22005 ,SNR2: 2.2475




F20230707152343





BLK:12,SNR1: 1.2319 ,SNR2: 5.9914






1031-11 2023/07/07 6.42UT TOYOKAWA-FUJI




T20230707152341





KISO




1031-11 2023/07/07 6.42UT TOYOKAWA-KISO



F20230707152343





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1031-11 2023/07/07 6.42UT FUJI -KISO



T20230707152814





BLK: 5,SNR1: 20.935 ,SNR2: 56.688




Frequency (Hz)

F20230707152816




BLK: 5,SNR1:-0.35655E-01,SNR2: 1.3438






Frequency (Hz)

1035-058 2023/07/07 6.50UT TOYOKAWA-FUJI









T20230707152814




KISO




1035-058 2023/07/07 6.50UT TOYOKAWA-KISO



F20230707152816




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/07/07 6.50UT FUJI -KISO



T20230707153727





BLK: 1,SNR1: 0.30285 ,SNR2: 1.0297




Frequency (Hz)

F20230707153729




BLK: 1,SNR1: 0.54012E-01,SNR2: 4.5924





Frequency (Hz)


1044-008 2023/07/07 6.65UT TOYOKAWA-FUJI



T20230707153727





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)



1044-008 2023/07/07 6.65UT TOYOKAWA-KISO



F20230707153729





KISO




1044-008 2023/07/07 6.65UT FUJI -KISO




T20230707154831




BLK: 5,SNR1:-0.53283E-03,SNR2: 1.7173




F20230707154833




BLK: 5,SNR1:-0.13631 ,SNR2: 1.0698



1055+01 2023/07/07 6.84UT TOYOKAWA-FUJI



T20230707154831




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1055+01 2023/07/07 6.84UT TOYOKAWA-KISO



F20230707154833




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

1055+01 2023/07/07 6.84UT FUJI -KISO








T20230707155949




BLK: 9,SNR1: 0.17185 ,SNR2: 1.1319




F20230707155951




BLK: 9,SNR1: 0.13669 ,SNR2: 1.2569




1107+109 2023/07/07 7.03UT TOYOKAWA-FUJI



T20230707155949




KISO




1107+109 2023/07/07 7.03UT TOYOKAWA-KISO



F20230707155951




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1107+109 2023/07/07 7.03UT FUJI -KISO



T20230707160926




BLK: 2,SNR1: 0.76121E-01,SNR2: 0.66665




Frequency (Hz)

F20230707160928




BLK: 2,SNR1: 0.22891 ,SNR2: 1.3857






Frequency (Hz)




3C255 2023/07/07 7.19UT TOYOKAWA-FUJI




T20230707160926






KISO






3C255 2023/07/07 7.19UT TOYOKAWA-KISO




F20230707160928





KISO




3C255 2023/07/07 7.19UT FUJI -KISO





T20230707163324




BLK: 9,SNR1: 0.37882 ,SNR2: 3.9514




F20230707163326






BLK: 9,SNR1: 0.43346 ,SNR2: 2.0750






3C263.1 2023/07/07 7.58UT TOYOKAWA-FUJI




T20230707163324



KISO






3C263.1 2023/07/07 7.58UT TOYOKAWA-KISO









F20230707163326




KISO




3C263.1 2023/07/07 7.58UT FUJI -KISO



T20230707163951




BLK: 4,SNR1: 0.86385 ,SNR2: 13.555




Frequency (Hz)

F20230707163953




BLK: 4,SNR1: 0.21806 ,SNR2: 2.5806






Frequency (Hz)




3C267 2023/07/07 7.69UT TOYOKAWA-FUJI



T20230707163951






KISO






3C267 2023/07/07 7.69UT TOYOKAWA-KISO




F20230707163953





KISO




3C267 2023/07/07 7.69UT FUJI -KISO



T20230707165906




BLK: 6,SNR1: 0.13407 ,SNR2: 0.99850




Frequency (Hz)

F20230707165908




BLK: 6,SNR1: 0.50928E-01,SNR2: 1.3929






Frequency (Hz)




1206+439 2023/07/07 8.01UT TOYOKAWA-FUJI




T20230707165906





KISO






1206+439 2023/07/07 8.01UT TOYOKAWA-KISO




F20230707165908




KISO




1206+439 2023/07/07 8.01UT FUJI -KISO




T20230707180544




BLK: 3,SNR1: 0.47012E-01,SNR2: 0.61841E-01




F20230707180546



BLK: 3,SNR1: 1.8956 ,SNR2: 8.9780





1313+453 2023/07/07 9.12UT TOYOKAWA-FUJI






T20230707180544





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1313+453 2023/07/07 9.12UT TOYOKAWA-KISO



F20230707180546



KISO



1313+453 2023/07/07 9.12UT FUJI -KISO

