




T20230708055437





BLK: 5,SNR1: 4.5010 ,SNR2: 52.190




Frequency (Hz)

F20230708055439




BLK: 5,SNR1: 0.50356 ,SNR2: 2.6999




Frequency (Hz)

0103+422 2023/07/07 20.94UT TOYOKAWA-FUJI



T20230708055437




No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0103+422 2023/07/07 20.94UT TOYOKAWA-KISO



F20230708055439



No.Good Data




KISO





No.Good Data




0103+422 2023/07/07 20.94UT FUJI -KISO



T20230708060724





BLK: 5,SNR1:-0.46292E-02,SNR2: 0.36806




Frequency (Hz)

F20230708060726




BLK: 5,SNR1: 0.59593 ,SNR2: 2.9254



Frequency (Hz)


0116+31 2023/07/07 21.15UT TOYOKAWA-FUJI




T20230708060724




No.Good Data




KISO




No.Good Data



0116+31 2023/07/07 21.15UT TOYOKAWA-KISO




F20230708060726



No.Good Data



KISO





No.Good Data




0116+31 2023/07/07 21.15UT FUJI -KISO



T20230708062531



BLK:18,SNR1: 0.75669 ,SNR2: 6.6686





Frequency (Hz)


3C48

2023/07/07 21.45UT TOYOKAWA-FUJI


F20230708062533



BLK:18,SNR1: 0.71313 ,SNR2: 2.1996




Frequency (Hz)



T20230708062531



No.Good Data




KISO



No.Good Data



3C48 2023/07/07 21.45UT TOYOKAWA-KISO





F20230708062533



No.Good Data



KISO





No.Good Data




3C48 2023/07/07 21.45UT FUJI -KISO



T20230708063914





BLK: 1,SNR1: 0.94863E-01,SNR2: 0.25338




Frequency (Hz)

F20230708063916




BLK: 1,SNR1: 0.10007 ,SNR2: 1.8167




Frequency (Hz)


0148+274 2023/07/07 21.68UT TOYOKAWA-FUJI





T20230708063914




No.Good Data




KISO



No.Good Data



0148+274 2023/07/07 21.68UT TOYOKAWA-KISO



F20230708063916




No.Good Data



KISO





No.Good Data




0148+274 2023/07/07 21.68UT FUJI -KISO



T20230708065223





BLK: 4,SNR1: 0.22127 ,SNR2: 0.28336




Frequency (Hz)

F20230708065225




BLK: 4,SNR1: 0.27780 ,SNR2: 5.9958




Frequency (Hz)


0202+15 2023/07/07 21.90UT TOYOKAWA-FUJI




T20230708065223




No.Good Data




KISO



No.Good Data



0202+15 2023/07/07 21.90UT TOYOKAWA-KISO



F20230708065225



No.Good Data




KISO





No.Good Data




0202+15 2023/07/07 21.90UT FUJI -KISO





T20230708070413




BLK: 4,SNR1:-0.18863E-02,SNR2: 0.13139




F20230708070415



BLK: 4,SNR1: 0.12535 ,SNR2: 1.7256



0213+178 2023/07/07 22.10UT TOYOKAWA-FUJI






T20230708070413




No.Good Data




KISO



No.Good Data



0213+178 2023/07/07 22.10UT TOYOKAWA-KISO



F20230708070415



No.Good Data



KISO





No.Good Data




0213+178 2023/07/07 22.10UT FUJI -KISO



T20230708071155



BLK: 5,SNR1: 0.14179 ,SNR2: 1.8564





Frequency (Hz)


3C67

2023/07/07 22.23UT TOYOKAWA-FUJI


F20230708071157



BLK: 5,SNR1: 0.59236 ,SNR2: 2.5715



Frequency (Hz)



T20230708071155



No.Good Data



KISO





No.Good Data




3C67 2023/07/07 22.23UT TOYOKAWA-KISO





F20230708071157




No.Good Data




KISO





No.Good Data




3C67 2023/07/07 22.23UT FUJI -KISO



T20230708073011



BLK: 5,SNR1: 0.15987E-01,SNR2: 0.81238





Frequency (Hz)


3C71

2023/07/07 22.53UT TOYOKAWA-FUJI


F20230708073013





BLK: 5,SNR1: 1.0064 ,SNR2: 4.1902




Frequency (Hz)



T20230708073011




No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C71 2023/07/07 22.53UT TOYOKAWA-KISO



F20230708073013



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C71 2023/07/07 22.53UT FUJI -KISO






T20230708074925





BLK: 6,SNR1: 0.12999E-01,SNR2: 0.60100




Frequency (Hz)

F20230708074927




BLK: 6,SNR1: 0.74016 ,SNR2: 4.6077




Frequency (Hz)


0258+350 2023/07/07 22.85UT TOYOKAWA-FUJI



T20230708074925




No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0258+350 2023/07/07 22.85UT TOYOKAWA-KISO




F20230708074927



No.Good Data




KISO




No.Good Data




0258+350 2023/07/07 22.85UT FUJI -KISO



T20230708075914




BLK: 6,SNR1: 0.41639E-01,SNR2: 0.94018




Frequency (Hz)

F20230708075916




BLK: 6,SNR1: 0.69125 ,SNR2: 5.0396



Frequency (Hz)


0308+305 2023/07/07 23.02UT TOYOKAWA-FUJI





T20230708075914




No.Good Data




KISO




No.Good Data



0308+305 2023/07/07 23.02UT TOYOKAWA-KISO



F20230708075916




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0308+305 2023/07/07 23.02UT FUJI -KISO



T20230708081047





BLK:12,SNR1: 0.15468 ,SNR2: 1.1016




Frequency (Hz)

F20230708081049




BLK:12,SNR1: 27.166 ,SNR2: 42.532



Frequency (Hz)


0320+05 2023/07/07 23.21UT TOYOKAWA-FUJI



T20230708081047



No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

0320+05 2023/07/07 23.21UT TOYOKAWA-KISO








F20230708081049




No.Good Data




KISO




No.Good Data




0320+05 2023/07/07 23.21UT FUJI -KISO



T20230708082407





BLK: 6,SNR1: 0.28956 ,SNR2: 1.5267




Frequency (Hz)

F20230708082409




BLK: 6,SNR1: 4.2240 ,SNR2: 14.690



Frequency (Hz)

0333+32 2023/07/07 23.43UT TOYOKAWA-FUJI



T20230708082407



No.Good Data




KISO



No.Good Data




0333+32 2023/07/07 23.43UT TOYOKAWA-KISO





F20230708082409




No.Good Data




KISO





No.Good Data




0333+32 2023/07/07 23.43UT FUJI -KISO



T20230708083709





BLK: 6,SNR1: 0.12214 ,SNR2: 1.3362




Frequency (Hz)

F20230708083711




BLK: 6,SNR1: 2.6625 ,SNR2: 6.8870



Frequency (Hz)

0347+05 2023/07/07 23.65UT TOYOKAWA-FUJI



T20230708083709



No. Good Data




KISO



No. Good Data




0347+05 2023/07/07 23.65UT TOYOKAWA-KISO




F20230708083711




No.Good Data



KISO





No.Good Data




0347+05 2023/07/07 23.65UT FUJI -KISO




T20230708085244




BLK: 9,SNR1: 0.10743 ,SNR2: 1.8708




F20230708085246



BLK: 9,SNR1: 1.2712 ,SNR2: 6.2151




0403-132 2023/07/07 23.91UT TOYOKAWA-FUJI








T20230708085244




No.Good Data




KISO



No.Good Data



0403-132 2023/07/07 23.91UT TOYOKAWA-KISO



F20230708085246



No.Good Data




KISO





No.Good Data




0403-132 2023/07/07 23.91UT FUJI -KISO



T20230708090154





BLK: 5,SNR1: 0.17336E-01,SNR2: 1.5648




Frequency (Hz)

F20230708090156




BLK: 5,SNR1: 0.27300 ,SNR2: 1.2747



Frequency (Hz)

0411+05 2023/07/08 0.06UT TOYOKAWA-FUJI



T20230708090154



No.Good Data




KISO





No.Good Data




0411+05 2023/07/08 0.06UT TOYOKAWA-KISO




F20230708090156




No.Good Data




KISO





No.Good Data




0411+05 2023/07/08 0.06UT FUJI -KISO





T20230708090848




BLK: 6,SNR1: 0.10033 ,SNR2: 0.98487




F20230708090850



BLK: 6,SNR1: 0.34070E-02,SNR2: 1.1072



0418+236 2023/07/08 0.17UT TOYOKAWA-FUJI



T20230708090848



No.Good Data



KISO




No.Good Data



0418+236 2023/07/08 0.17UT TOYOKAWA-KISO




F20230708090850




No.Good Data



KISO



No.Good Data




0418+236 2023/07/08 0.17UT FUJI -KISO








T20230708092015




BLK:18,SNR1: 1.5970 ,SNR2: 8.1992




F20230708092017



BLK:18,SNR1: 1.4716 ,SNR2: 4.0832



3C119 2023/07/08 0.37UT TOYOKAWA-FUJI




T20230708092015




No. Good Data



KISO



No. Good Data



3C119 2023/07/08 0.37UT TOYOKAWA-KISO




F20230708092017




No.Good Data



KISO




No.Good Data




3C119 2023/07/08 0.37UT FUJI -KISO




T20230708100823




BLK:18,SNR1: 2.3408 ,SNR2: 16.418




F20230708100825



BLK:18,SNR1: 0.36338 ,SNR2: 2.2990



3C138 2023/07/08 1.17UT TOYOKAWA-FUJI





T20230708100823




No. Good Data



KISO



No. Good Data



3C138 2023/07/08 1.17UT TOYOKAWA-KISO



F20230708100825





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C138 2023/07/08 1.17UT FUJI -KISO



T20230708102156





BLK:20,SNR1: 1.9263 ,SNR2: 19.240




Frequency (Hz)

F20230708102158




BLK:20,SNR1: 1.1278 ,SNR2: 5.3409



Frequency (Hz)

0531+194 2023/07/08 1.39UT TOYOKAWA-FUJI



T20230708102156



No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0531+194 2023/07/08 1.39UT TOYOKAWA-KISO






F20230708102158



No.Good Data




KISO




No.Good Data




0531+194 2023/07/08 1.39UT FUJI -KISO



T20230708103014





BLK:24,SNR1: 12.499 ,SNR2: 54.824





3C147 2023/07/08 1.53UT TOYOKAWA-FUJI


F20230708103016



BLK:24,SNR1: 0.75276 ,SNR2: 5.8986



T20230708103014




No. Good Data




Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


3C147 2023/07/08 1.53UT TOYOKAWA-KISO



F20230708103016





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C147 2023/07/08 1.53UT FUJI -KISO





T20230708103827




BLK:15,SNR1: 0.81538 ,SNR2: 3.7009




F20230708103829



BLK:15,SNR1: 0.11544 ,SNR2: 1.8205




0548+16 2023/07/08 1.67UT TOYOKAWA-FUJI



T20230708103827





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


0548+16 2023/07/08 1.67UT TOYOKAWA-KISO




F20230708103829




No. Good Data



KISO




No. Good Data




0548+16 2023/07/08 1.67UT FUJI -KISO



T20230708104238





BLK:14,SNR1: 5.5478 ,SNR2: 42.247





0552+12 2023/07/08 1.74UT TOYOKAWA-FUJI

F20230708104240



BLK:14,SNR1: 0.46788 ,SNR2: 1.2842





T20230708104238





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0552+12 2023/07/08 1.74UT TOYOKAWA-KISO





F20230708104240




No.Good Data




KISO





No.Good Data




0552+12 2023/07/08 1.74UT FUJI -KISO





T20230708104705




BLK:12,SNR1: 0.42673 ,SNR2: 1.6227




F20230708104707



BLK:12,SNR1: 7.8636 ,SNR2: 21.547



0556+191 2023/07/08 1.81UT TOYOKAWA-FUJI



T20230708104705





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0556+191 2023/07/08 1.81UT TOYOKAWA-KISO



F20230708104707





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0556+191 2023/07/08 1.81UT FUJI -KISO



T20230708105452





BLK: 5,SNR1: 0.16804 ,SNR2: 0.70992




Frequency (Hz)

F20230708105454




BLK: 5,SNR1: 0.71735 ,SNR2: 2.9212



Frequency (Hz)


0605-08 2023/07/08 1.94UT TOYOKAWA-FUJI



T20230708105452



No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


0605-08 2023/07/08 1.94UT TOYOKAWA-KISO



F20230708105454




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0605-08 2023/07/08 1.94UT FUJI -KISO






T20230708111359




BLK:18,SNR1: 2.5663 ,SNR2: 14.514





3C161 2023/07/08 2.26UT TOYOKAWA-FUJI



F20230708111401




BLK:18,SNR1: 0.67967E-01,SNR2: 1.4890



T20230708111359





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/07/08 2.26UT TOYOKAWA-KISO



F20230708111401




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/07/08 2.26UT FUJI -KISO





T20230708114132




BLK: 7,SNR1: 0.20682 ,SNR2: 0.96220




F20230708114134



BLK: 7,SNR1: 0.12979 ,SNR2: 2.7984



0652-130 2023/07/08 2.72UT TOYOKAWA-FUJI



T20230708114132



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0652-130 2023/07/08 2.72UT TOYOKAWA-KISO





F20230708114134




No. Good Data




KISO





No. Good Data




0652-130 2023/07/08 2.72UT FUJI -KISO



T20230708115308





BLK: 9,SNR1: 0.89396 ,SNR2: 10.391




Frequency (Hz)

F20230708115310




BLK: 9,SNR1: 7.8193 ,SNR2: 33.573




Frequency (Hz)

0703+138 2023/07/08 2.91UT TOYOKAWA-FUJI



T20230708115308





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0703+138 2023/07/08 2.91UT TOYOKAWA-KISO






F20230708115310





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0703+138 2023/07/08 2.91UT FUJI -KISO




T20230708120231




BLK: 8,SNR1: 1.0566 ,SNR2: 6.6323




F20230708120233



BLK: 8,SNR1:-0.15584 ,SNR2: 0.83057



0713-024 2023/07/08 3.07UT TOYOKAWA-FUJI



T20230708120231



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0713-024 2023/07/08 3.07UT TOYOKAWA-KISO



F20230708120233



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


0713-024 2023/07/08 3.07UT FUJI -KISO



T20230708121243





BLK:20,SNR1: 0.54966 ,SNR2: 5.0359





0723+10 2023/07/08 3.24UT TOYOKAWA-FUJI

F20230708121245



BLK:20,SNR1: 0.23160 ,SNR2: 1.1584



T20230708121243



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0723+10 2023/07/08 3.24UT TOYOKAWA-KISO



F20230708121245



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0723+10 2023/07/08 3.24UT FUJI -KISO




T20230708122257




BLK:25,SNR1: 0.87092 ,SNR2: 4.9714




F20230708122259



BLK:25,SNR1: 0.78550 ,SNR2: 2.1382



0732+33 2023/07/08 3.41UT TOYOKAWA-FUJI





T20230708122257





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0732+33 2023/07/08 3.41UT TOYOKAWA-KISO





F20230708122259




No.Good Data




KISO





No.Good Data




0732+33 2023/07/08 3.41UT FUJI -KISO





T20230708123100




BLK: 6,SNR1: 0.88468 ,SNR2: 2.1137




F20230708123102



BLK: 6,SNR1: 0.72051E-02,SNR2: 1.0645



0741-06 2023/07/08 3.54UT TOYOKAWA-FUJI



T20230708123100



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0741-06 2023/07/08 3.54UT TOYOKAWA-KISO



F20230708123102





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0741-06 2023/07/08 3.54UT FUJI -KISO



T20230708124818





BLK:19,SNR1: 0.65125 ,SNR2: 2.3187





3C190 2023/07/08 3.83UT TOYOKAWA-FUJI

F20230708124820



BLK:19,SNR1: 0.76058E-01,SNR2: 1.2418



T20230708124818



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C190 2023/07/08 3.83UT TOYOKAWA-KISO



F20230708124820





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C190 2023/07/08 3.83UT FUJI -KISO







T20230708130042




BLK:14,SNR1: 0.28986 ,SNR2: 5.1708




F20230708130044



BLK:14,SNR1: 0.58291 ,SNR2: 1.8407



3C196 2023/07/08 4.04UT TOYOKAWA-FUJI



T20230708130042





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)


3C196 2023/07/08 4.04UT TOYOKAWA-KISO



F20230708130044





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C196 2023/07/08 4.04UT FUJI -KISO



T20230708131152




BLK: 9,SNR1: 0.22204 ,SNR2: 2.1826




Frequency (Hz)

F20230708131154




BLK: 9,SNR1:-0.59023E-01,SNR2: 0.65276



Frequency (Hz)

0821+394 2023/07/08 4.23UT TOYOKAWA-FUJI



T20230708131152



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0821+394 2023/07/08 4.23UT TOYOKAWA-KISO





F20230708131154




No. Good Data




KISO





No. Good Data




0821+394 2023/07/08 4.23UT FUJI -KISO



T20230708132839





BLK: 2,SNR1: 5.1416 ,SNR2: 65.404





0839-071 2023/07/08 4.51UT TOYOKAWA-FUJI

F20230708132841



BLK: 2,SNR1: 0.25301 ,SNR2: 1.5034



T20230708132839



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0839-071 2023/07/08 4.51UT TOYOKAWA-KISO





F20230708132841





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0839-071 2023/07/08 4.51UT FUJI -KISO





T20230708133939




BLK: 8,SNR1: 0.11554 ,SNR2: 0.73690




F20230708133941



BLK: 8,SNR1: 1063.5 ,SNR2: 1392.9




3C208 2023/07/08 4.69UT TOYOKAWA-FUJI



T20230708133939



No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

3C208 2023/07/08 4.69UT TOYOKAWA-KISO



F20230708133941



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C208 2023/07/08 4.69UT FUJI -KISO





T20230708135620




BLK:10,SNR1: 0.23869 ,SNR2: 1.7921




F20230708135622





BLK:10,SNR1: 0.24831 ,SNR2: 1.2183



3C216 2023/07/08 4.97UT TOYOKAWA-FUJI



T20230708135620





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C216 2023/07/08 4.97UT TOYOKAWA-KISO



F20230708135622





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C216 2023/07/08 4.97UT FUJI -KISO





T20230708141511




BLK: 6,SNR1: 0.12898 ,SNR2: 1.3464




F20230708141513



BLK: 6,SNR1: 0.25820 ,SNR2: 1.2978





0926+117 2023/07/08 5.28UT TOYOKAWA-FUJI






T20230708141511





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0926+117 2023/07/08 5.28UT TOYOKAWA-KISO





F20230708141513




No. Good Data




KISO





No. Good Data




0926+117 2023/07/08 5.28UT FUJI -KISO




T20230708142256




BLK: 8,SNR1: 0.59270 ,SNR2: 2.5131




F20230708142258





BLK: 8,SNR1: 1.3297 ,SNR2: 4.2036




3C222 2023/07/08 5.41UT TOYOKAWA-FUJI



T20230708142256





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C222 2023/07/08 5.41UT TOYOKAWA-KISO



F20230708142258





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C222 2023/07/08 5.41UT FUJI -KISO




T20230708142956




BLK: 8,SNR1: 0.13193 ,SNR2: 1.6994




F20230708142958






BLK: 8,SNR1:-0.69129E-01,SNR2: 2.3121






0941-08 2023/07/08 5.53UT TOYOKAWA-FUJI



T20230708142956




KISO




0941-08 2023/07/08 5.53UT TOYOKAWA-KISO





F20230708142958




No.Good Data




KISO



No.Good Data





0941-08 2023/07/08 5.53UT FUJI -KISO






T20230708143818





BLK:14,SNR1: 0.32500 ,SNR2: 0.97409





3C230 2023/07/08 5.67UT TOYOKAWA-FUJI

F20230708143820



BLK:14,SNR1: 3.3083 ,SNR2: 15.331



T20230708143818




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C230 2023/07/08 5.67UT TOYOKAWA-KISO





F20230708143820




No.Good Data




KISO





No.Good Data




3C230 2023/07/08 5.67UT FUJI -KISO





T20230708145418




BLK:20,SNR1: 0.55911 ,SNR2: 5.5735




F20230708145420





BLK:20,SNR1: 0.31833 ,SNR2: 1.5386




3C237 2023/07/08 5.93UT TOYOKAWA-FUJI



T20230708145418





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C237 2023/07/08 5.93UT TOYOKAWA-KISO



F20230708145420




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C237 2023/07/08 5.93UT FUJI -KISO





T20230708150035




BLK: 6,SNR1:-0.27263E-01,SNR2: 0.49640




F20230708150037




BLK: 6,SNR1: 0.87569 ,SNR2: 3.1889



1011+110 2023/07/08 6.04UT TOYOKAWA-FUJI



T20230708150035




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

1011+110 2023/07/08 6.04UT TOYOKAWA-KISO





F20230708150037




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1011+110 2023/07/08 6.04UT FUJI -KISO



T20230708150815





BLK: 7,SNR1: 0.15049 ,SNR2: 0.66099




Frequency (Hz)

F20230708150817




BLK: 7,SNR1: 0.47009 ,SNR2: 3.3594





Frequency (Hz)

3C241 2023/07/08 6.17UT TOYOKAWA-FUJI



T20230708150815





No.Good Data



Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C241 2023/07/08 6.17UT TOYOKAWA-KISO




F20230708150817





KISO




3C241 2023/07/08 6.17UT FUJI -KISO




T20230708151945




BLK: 7,SNR1: 0.83498E-01,SNR2: 0.58668




F20230708151947






BLK: 7,SNR1: 0.94804 ,SNR2: 2.7354






1031-11 2023/07/08 6.36UT TOYOKAWA-FUJI




T20230708151945






KISO






1031-11 2023/07/08 6.36UT TOYOKAWA-KISO




F20230708151947





KISO




1031-11 2023/07/08 6.36UT FUJI -KISO



T20230708152419





BLK: 4,SNR1: 9.5110 ,SNR2: 86.150




Frequency (Hz)

F20230708152421




BLK: 4,SNR1: 0.42508 ,SNR2: 1.6299






Frequency (Hz)

1035-058 2023/07/08 6.43UT TOYOKAWA-FUJI









T20230708152419




KISO




1035-058 2023/07/08 6.43UT TOYOKAWA-KISO



F20230708152421




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1035-058 2023/07/08 6.43UT FUJI -KISO



T20230708153331





BLK: 4,SNR1: 0.22411 ,SNR2: 0.51347




Frequency (Hz)

F20230708153333




BLK: 4,SNR1: 0.26560 ,SNR2: 1.0641




Frequency (Hz)


1044-008 2023/07/08 6.59UT TOYOKAWA-FUJI



T20230708153331




KISO




1044-008 2023/07/08 6.59UT TOYOKAWA-KISO



F20230708153333





KISO




1044-008 2023/07/08 6.59UT FUJI -KISO




T20230708154436




BLK: 6,SNR1: 0.15805 ,SNR2: 0.67010




F20230708154438




BLK: 6,SNR1: 0.30922 ,SNR2: 1.7653



1055+01 2023/07/08 6.77UT TOYOKAWA-FUJI



T20230708154436




No.Good Data



Frequency (Hz)

KISO



No.Good Data






Frequency (Hz)




1055+01 2023/07/08 6.77UT TOYOKAWA-KISO




F20230708154438



KISO





1055+01 2023/07/08 6.77UT FUJI -KISO






T20230708155553





BLK: 4,SNR1: 0.96004E-01,SNR2: 0.71428




Frequency (Hz)

F20230708155555




BLK: 4,SNR1: 0.20603E-01,SNR2: 1.0994





Frequency (Hz)


1107+109 2023/07/08 6.96UT TOYOKAWA-FUJI



T20230708155553





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1107+109 2023/07/08 6.96UT TOYOKAWA-KISO



F20230708155555




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1107+109 2023/07/08 6.96UT FUJI -KISO



T20230708160530





BLK:12,SNR1: 4.1828 ,SNR2: 19.286




Frequency (Hz)

F20230708160532




BLK:12,SNR1: 0.10483E-01,SNR2: 1.0422





Frequency (Hz)


3C255 2023/07/08 7.12UT TOYOKAWA-FUJI



T20230708160530





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C255 2023/07/08 7.12UT TOYOKAWA-KISO




F20230708160532





KISO




3C255 2023/07/08 7.12UT FUJI -KISO





T20230708162928




BLK:11,SNR1: 0.34773E-01,SNR2: 1.2337




F20230708162930






BLK:11,SNR1: 1.0110 ,SNR2: 3.2035






3C263.1 2023/07/08 7.52UT TOYOKAWA-FUJI




T20230708162928



KISO






3C263.1 2023/07/08 7.52UT TOYOKAWA-KISO









F20230708162930





KISO




3C263.1 2023/07/08 7.52UT FUJI -KISO





T20230708163555




BLK: 2,SNR1: 0.83189 ,SNR2: 9.1443




F20230708163557






BLK: 2,SNR1: 0.45577E-01,SNR2: 0.67528






3C267 2023/07/08 7.63UT TOYOKAWA-FUJI



T20230708163555





KISO





3C267 2023/07/08 7.63UT TOYOKAWA-KISO




F20230708163557





KISO




3C267 2023/07/08 7.63UT FUJI -KISO




T20230708165510




BLK: 8,SNR1: 0.10379 ,SNR2: 0.56684




F20230708165512






BLK: 8,SNR1: 0.59660 ,SNR2: 5.7703






1206+439 2023/07/08 7.95UT TOYOKAWA-FUJI




T20230708165510





KISO






1206+439 2023/07/08 7.95UT TOYOKAWA-KISO




F20230708165512





KISO




1206+439 2023/07/08 7.95UT FUJI -KISO



T20230708180148





BLK: 8,SNR1: 0.13775 ,SNR2: 0.51260




Frequency (Hz)

F20230708180150




BLK: 8,SNR1: 0.97598 ,SNR2: 3.5628





Frequency (Hz)

1313+453 2023/07/08 9.06UT TOYOKAWA-FUJI






T20230708180148





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1313+453 2023/07/08 9.06UT TOYOKAWA-KISO




F20230708180150





KISO




1313+453 2023/07/08 9.06UT FUJI -KISO




T20230708182307




BLK: 6,SNR1: 2.0159 ,SNR2: 9.7580




F20230708182309




BLK: 6,SNR1: 0.32795 ,SNR2: 4.7390




1335+479 2023/07/08 9.41UT TOYOKAWA-FUJI



T20230708182307





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1335+479 2023/07/08 9.41UT TOYOKAWA-KISO



F20230708182309




No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1335+479 2023/07/08 9.41UT FUJI -KISO

