




T20230712142234





BLK:10,SNR1: 0.48174 ,SNR2: 2.1609




Frequency (Hz)

3C230 2023/07/12 5.40UT TOYOKAWA-FUJI


F20230712142236





BLK:10,SNR1:-0.13681 ,SNR2: 0.86733




Frequency (Hz)



T20230712142234




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C230 2023/07/12 5.40UT TOYOKAWA-KISO



F20230712142236




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C230 2023/07/12 5.40U FUJI -KISO



T20230712143835





BLK:17,SNR1: 1.2584 ,SNR2: 2.3489




Frequency (Hz)

F20230712143837




BLK:17,SNR1: 62.583 ,SNR2: 72.197





Frequency (Hz)


3C237 2023/07/12 5.67UT TOYOKAWA-FUJI




T20230712143835



No.Good Data




KISO





No.Good Data




3C237 2023/07/12 5.67UT TOYOKAWA-KISO



F20230712143837




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C237 2023/07/12 5.67UT FUJI -KISO



T20230712144451





BLK:10,SNR1: 0.49858 ,SNR2: 3.4535




Frequency (Hz)

F20230712144453




BLK:10,SNR1: 0.53834 ,SNR2: 1.7403



Frequency (Hz)


1011+110 2023/07/12 5.78UT TOYOKAWA-FUJI



T20230712144451





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1011+110 2023/07/12 5.78UT TOYOKAWA-KISO






F20230712144453




No.Good Data



KISO




No.Good Data




1011+110 2023/07/12 5.78UT FUJI -KISO



T20230712145232




BLK:16,SNR1: 1.0154 ,SNR2: 4.1217




Frequency (Hz)

3C241 2023/07/12 5.90UT TOYOKAWA-FUJI


F20230712145234




BLK:16,SNR1: 0.25629 ,SNR2: 3.7862




Frequency (Hz)





T20230712145232




No.Good Data




KISO



No.Good Data



3C241 2023/07/12 5.90UT TOYOKAWA-KISO



F20230712145234




No.Good Data



KISO





No.Good Data




3C241 2023/07/12 5.90UT FUJI -KISO



T20230712150401





BLK:10,SNR1: 0.99306 ,SNR2: 3.8487




Frequency (Hz)

F20230712150403




BLK:10,SNR1:-0.24336E-01,SNR2: 0.79001



Frequency (Hz)


1031-11 2023/07/12 6.10UT TOYOKAWA-FUJI



T20230712150401





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1031-11 2023/07/12 6.10UT TOYOKAWA-KISO



F20230712150403



No.Good Data




KISO




No.Good Data




1031-11 2023/07/12 6.10UT FUJI -KISO



T20230712150835





BLK:11,SNR1: 0.93043 ,SNR2: 3.8670




Frequency (Hz)

F20230712150837




BLK:11,SNR1:-0.40973E-01,SNR2: 1.7284



Frequency (Hz)

1035-058 2023/07/12 6.17UT TOYOKAWA-FUJI






T20230712150835




No.Good Data




KISO



No.Good Data



1035-058 2023/07/12 6.17UT TOYOKAWA-KISO



F20230712150837



No.Good Data




KISO






No.Good Data







1035-058 2023/07/12 6.17UT FUJI -KISO



T20230712151747



F20230712151749



T20230712151747



No.Good Data




KISO




No.Good Data



1044-008 2023/07/12 6.32UT TOYOKAWA-KISO



F20230712151749





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1044-008 2023/07/12 6.32UT FUJI -KISO



T20230712152852





BLK: 7,SNR1: 0.80187 ,SNR2: 1.9217




Frequency (Hz)

1055+01 2023/07/12 6.51UT TOYOKAWA-FUJI


F20230712152854



BLK: 7,SNR1:-0.14104 ,SNR2: 0.98487



Frequency (Hz)



T20230712152852



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1055+01 2023/07/12 6.51UT TOYOKAWA-KISO





F20230712152854




No.Good Data




KISO



No.Good Data





1055+01 2023/07/12 6.51UT FUJI -KISO






T20230712154009





BLK:16,SNR1: 0.21663 ,SNR2: 0.99014




Frequency (Hz)

1107+109 2023/07/12 6.70UT TOYOKAWA-FUJI


F20230712154011





BLK:16,SNR1: 0.40426 ,SNR2: 2.3896




Frequency (Hz)





T20230712154009




No.Good Data




KISO




No.Good Data




1107+109 2023/07/12 6.70UT TOYOKAWA-KISO




F20230712154011




No.Good Data




KISO




No.Good Data




1107+109 2023/07/12 6.70UT FUJI -KISO



T20230712154947




BLK:19,SNR1: 2.4427 ,SNR2: 7.4053




Frequency (Hz)

3C255 2023/07/12 6.86UT TOYOKAWA-FUJI


F20230712154949



BLK:19,SNR1: 1.7979 ,SNR2: 3.5612



Frequency (Hz)



T20230712154947



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C255 2023/07/12 6.86UT TOYOKAWA-KISO





F20230712154949




No.Good Data




KISO




No.Good Data




3C255 2023/07/12 6.86UT FUJI -KISO



T20230712161345




BLK:19,SNR1: 2.2665 ,SNR2: 4.2870




Frequency (Hz)

F20230712161347




BLK:19,SNR1: 0.83557 ,SNR2: 2.6076



Frequency (Hz)


3C263.1 2023/07/12 7.26UT TOYOKAWA-FUJI



T20230712161345



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C263.1 2023/07/12 7.26UT TOYOKAWA-KISO








F20230712161347




No.Good Data




KISO





No.Good Data




3C263.1 2023/07/12 7.26UT FUJI -KISO



T20230712162012





BLK:24,SNR1: 0.30823 ,SNR2: 2.5338




Frequency (Hz)

3C267 2023/07/12 7.36UT TOYOKAWA-FUJI


F20230712162014



BLK:24,SNR1: 0.99715 ,SNR2: 3.6887



Frequency (Hz)



T20230712162012



No.Good Data




KISO



No.Good Data



3C267 2023/07/12 7.36UT TOYOKAWA-KISO





F20230712162014




No.Good Data




KISO





No.Good Data




3C267 2023/07/12 7.36UT FUJI -KISO



T20230712163926





BLK:15,SNR1: 3.0275 ,SNR2: 4.5318




Frequency (Hz)

F20230712163928




BLK:15,SNR1: 0.15912 ,SNR2: 1.1699





Frequency (Hz)


1206+439 2023/07/12 7.69UT TOYOKAWA-FUJI





T20230712163926




No.Good Data




KISO



No.Good Data




1206+439 2023/07/12 7.69UT TOYOKAWA-KISO




F20230712163928




No. Good Data



KISO





No. Good Data




1206+439 2023/07/12 7.69UT FUJI -KISO



T20230712165917





BLK:18,SNR1: 3.4735 ,SNR2: 3.9240




Frequency (Hz)

F20230712165919




BLK:18,SNR1: 1.3840 ,SNR2: 3.4474



Frequency (Hz)

3C273 2023/07/12 8.02UT TOYOKAWA-FUJI







T20230712165917




No.Good Data



KISO



No.Good Data



3C273 2023/07/12 8.02UT TOYOKAWA-KISO



F20230712165919



No.Good Data



KISO



No.Good Data



3C273 2023/07/12 8.02UT FUJI -KISO

