




T20230715054348





BLK: 4,SNR1:-0.56532E-02,SNR2: 0.38722




Frequency (Hz)

F20230715054350




BLK: 4,SNR1: 0.48913 ,SNR2: 4.5061




Frequency (Hz)

0120+405 2023/07/14 20.76UT TOYOKAWA-FUJI



T20230715054348



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0120+405 2023/07/14 20.76UT TOYOKAWA-KISO



F20230715054350




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0120+405 2023/07/14 20.76UT FUJI -KISO



T20230715055800





BLK:19,SNR1: 0.85595 ,SNR2: 5.4804




Frequency (Hz)

3C48 2023/07/14 20.99UT TOYOKAWA-FUJI


F20230715055802





BLK:19,SNR1: 0.31058E-01,SNR2: 1.1111




Frequency (Hz)




T20230715055800



No.Good Data




KISO



No.Good Data



3C48 2023/07/14 20.99UT TOYOKAWA-KISO




F20230715055802



No.Good Data



KISO




No.Good Data




3C48 2023/07/14 20.99UT FUJI -KISO





T20230715061143




No.Good Data




F20230715061145




No.Good Data



0148+274 2023/07/14 21.22UT TOYOKAWA-FUJI



T20230715061143





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0148+274 2023/07/14 21.22UT TOYOKAWA-KISO





F20230715061145



No.Good Data



KISO





No.Good Data




0148+274 2023/07/14 21.22UT FUJI -KISO



T20230715062452





BLK: 5,SNR1: 0.27417E-02,SNR2: 0.21819




Frequency (Hz)

F20230715062454




BLK: 5,SNR1: 0.27941 ,SNR2: 3.3454




Frequency (Hz)


0202+15 2023/07/14 21.44UT TOYOKAWA-FUJI



T20230715062452



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0202+15 2023/07/14 21.44UT TOYOKAWA-KISO



F20230715062454




No.Good Data



KISO





No.Good Data




0202+15 2023/07/14 21.44UT FUJI -KISO



T20230715063642





BLK: 2,SNR1:-0.85941E-01,SNR2: 0.0000




Frequency (Hz)

F20230715063644




BLK: 2,SNR1: 1.6778 ,SNR2: 3.8143



Frequency (Hz)


0213+178 2023/07/14 21.64UT TOYOKAWA-FUJI



T20230715063642




No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0213+178 2023/07/14 21.64UT TOYOKAWA-KISO



F20230715063644




No.Good Data



KISO





No.Good Data




0213+178 2023/07/14 21.64UT FUJI -KISO



T20230715064424



BLK: 1,SNR1: 0.48925 ,SNR2: 0.68392




Frequency (Hz)


3C67

2023/07/14 21.77UT TOYOKAWA-FUJI


F20230715064426



BLK: 1,SNR1:-0.19482 ,SNR2: 0.45950



Frequency (Hz)






T20230715064424




No.Good Data




Frequency (Hz)

3C67 2023/07/14 21.77UT TOYOKAWA-KISO


KISO



No.Good Data



Frequency (Hz)



F20230715064426



No.Good Data



KISO





No.Good Data




3C67 2023/07/14 21.77UT FUJI -KISO



T20230715070240



BLK: 1,SNR1: 0.20634 ,SNR2: 2.2934





Frequency (Hz)


3C71

2023/07/14 22.07UT TOYOKAWA-FUJI


F20230715070242




BLK: 1,SNR1: 0.27735 ,SNR2: 3.5021




Frequency (Hz)




T20230715070240




No.Good Data



KISO



No.Good Data



3C71 2023/07/14 22.07UT TOYOKAWA-KISO



F20230715070242



No.Good Data



KISO




No.Good Data




3C71 2023/07/14 22.07UT FUJI -KISO



T20230715072154





BLK: 4,SNR1: 0.55971E-01,SNR2: 0.23793




Frequency (Hz)

F20230715072156




BLK: 4,SNR1: 0.74485 ,SNR2: 3.8803





Frequency (Hz)


0258+350 2023/07/14 22.39UT TOYOKAWA-FUJI



T20230715072154



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0258+350 2023/07/14 22.39UT TOYOKAWA-KISO



F20230715072156



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0258+350 2023/07/14 22.39UT FUJI -KISO






T20230715073143





BLK: 4,SNR1: 0.38569E-01,SNR2: 0.70188




Frequency (Hz)

F20230715073145




BLK: 4,SNR1: 0.60305 ,SNR2: 4.9165



Frequency (Hz)

0308+305 2023/07/14 22.56UT TOYOKAWA-FUJI



T20230715073143




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0308+305 2023/07/14 22.56UT TOYOKAWA-KISO



F20230715073145



No.Good Data




KISO





No.Good Data




0308+305 2023/07/14 22.56UT FUJI -KISO





T20230715074315




No.Good Data




F20230715074317



No.Good Data




0320+05 2023/07/14 22.75UT TOYOKAWA-FUJI





T20230715074315




No.Good Data




KISO





No.Good Data



0320+05 2023/07/14 22.75UT TOYOKAWA-KISO



F20230715074317





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0320+05 2023/07/14 22.75UT FUJI -KISO



T20230715075636





BLK:32,SNR1: 15.277 ,SNR2: 39.876




Frequency (Hz)

F20230715075638




BLK:32,SNR1: 1.3679 ,SNR2: 6.7661



Frequency (Hz)


0333+32 2023/07/14 22.97UT TOYOKAWA-FUJI



T20230715075636



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0333+32 2023/07/14 22.97UT TOYOKAWA-KISO








F20230715075638




No.Good Data




KISO





No.Good Data




0333+32 2023/07/14 22.97UT FUJI -KISO



T20230715080938





BLK: 3,SNR1: 0.67520E-02,SNR2: 0.73684





0347+05 2023/07/14 23.19UT TOYOKAWA-FUJI

F20230715080940



BLK: 3,SNR1: 0.31254 ,SNR2: 1.2121



T20230715080938



No.Good Data




KISO



No.Good Data




0347+05 2023/07/14 23.19UT TOYOKAWA-KISO





F20230715080940




No.Good Data




KISO





No.Good Data




0347+05 2023/07/14 23.19UT FUJI -KISO



T20230715082513




BLK: 3,SNR1: 0.32623 ,SNR2: 1.0220





0403-132 2023/07/14 23.45UT TOYOKAWA-FUJI



F20230715082515




BLK: 3,SNR1:-0.18572 ,SNR2: 0.15644E-01





T20230715082513




No.Good Data




KISO





No.Good Data




0403-132 2023/07/14 23.45UT TOYOKAWA-KISO




F20230715082515




No.Good Data




KISO





No.Good Data




0403-132 2023/07/14 23.45UT FUJI -KISO



T20230715083423




BLK: 4,SNR1: 0.10210 ,SNR2: 0.71155




Frequency (Hz)

F20230715083425




BLK: 4,SNR1: 0.62475 ,SNR2: 4.1970



Frequency (Hz)

0411+05 2023/07/14 23.60UT TOYOKAWA-FUJI





T20230715083423



No.Good Data



KISO



No.Good Data




0411+05 2023/07/14 23.60UT TOYOKAWA-KISO



F20230715083425




No.Good Data



KISO





No.Good Data




0411+05 2023/07/14 23.60UT FUJI -KISO



T20230715084117





BLK: 6,SNR1: 0.86553E-01,SNR2: 0.25033




Frequency (Hz)

F20230715084119




BLK: 6,SNR1: 0.66111 ,SNR2: 3.3755



Frequency (Hz)

0418+236 2023/07/14 23.72UT TOYOKAWA-FUJI



T20230715084117



No.Good Data




KISO



No.Good Data



0418+236 2023/07/14 23.72UT TOYOKAWA-KISO



F20230715084119



No.Good Data



KISO





No.Good Data




0418+236 2023/07/14 23.72UT FUJI -KISO



T20230715085243




BLK:12,SNR1: 0.69416 ,SNR2: 8.0282




Frequency (Hz)

3C119 2023/07/14 23.91UT TOYOKAWA-FUJI


F20230715085245



BLK:12,SNR1: 0.78417E-01,SNR2: 0.56378



Frequency (Hz)



T20230715085243



No.Good Data



KISO



No.Good Data



3C119 2023/07/14 23.91UT TOYOKAWA-KISO



F20230715085245



No.Good Data



KISO



No.Good Data





3C119 2023/07/14 23.91UT FUJI -KISO






T20230715094052





BLK:21,SNR1: 1.1009 ,SNR2: 12.741




Frequency (Hz)

F20230715094054




BLK:21,SNR1: 3.3162 ,SNR2: 4.8003



Frequency (Hz)

3C138 2023/07/15 0.71UT TOYOKAWA-FUJI




T20230715094052




No.Good Data



KISO




No.Good Data



3C138 2023/07/15 0.71UT TOYOKAWA-KISO





F20230715094054




No.Good Data



KISO




No.Good Data




3C138 2023/07/15 0.71UT FUJI -KISO





T20230715095425




BLK:17,SNR1: 1.2695 ,SNR2: 11.556




F20230715095427




BLK:17,SNR1: 8.7387 ,SNR2: 12.910




0531+194 2023/07/15 0.94UT TOYOKAWA-FUJI




T20230715095425




No. Good Data




KISO



No. Good Data



0531+194 2023/07/15 0.94UT TOYOKAWA-KISO




F20230715095427




No. Good Data




KISO




No. Good Data




0531+194 2023/07/15 0.94UT FUJI -KISO



T20230715100243




BLK:26,SNR1: 7.6932 ,SNR2: 30.727





3C147 2023/07/15 1.07UT TOYOKAWA-FUJI

F20230715100245



BLK:26,SNR1: 0.32410 ,SNR2: 2.6603



T20230715100243





No. Good Data




Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)

3C147 2023/07/15 1.07UT TOYOKAWA-KISO






F20230715100245





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C147 2023/07/15 1.07UT FUJI -KISO



T20230715101056





BLK:17,SNR1: 0.88267 ,SNR2: 6.2071




Frequency (Hz)

0548+16 2023/07/15 1.21UT TOYOKAWA-FUJI


F20230715101058



BLK:17,SNR1: 0.79496E-01,SNR2: 1.6744




Frequency (Hz)



T20230715101056



No. Good Data




Frequency (Hz)

KISO



No. Good Data



Frequency (Hz)


0548+16 2023/07/15 1.21UT TOYOKAWA-KISO



F20230715101058




No. Good Data




KISO




No. Good Data




0548+16 2023/07/15 1.21UT FUJI -KISO



T20230715101507





BLK: 8,SNR1: 24.764 ,SNR2: 39.881





0552+12 2023/07/15 1.28UT TOYOKAWA-FUJI

F20230715101509



BLK: 8,SNR1: 0.85227 ,SNR2: 2.1080



T20230715101507





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0552+12 2023/07/15 1.28UT TOYOKAWA-KISO





F20230715101509




No. Good Data



KISO





No. Good Data




0552+12 2023/07/15 1.28UT FUJI -KISO





T20230715101933




BLK:17,SNR1: 0.20924 ,SNR2: 1.7198




F20230715101935



BLK:17,SNR1: 2.1089 ,SNR2: 8.4210



0556+191 2023/07/15 1.35UT TOYOKAWA-FUJI





T20230715101933



No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


0556+191 2023/07/15 1.35UT TOYOKAWA-KISO





F20230715101935




No. Good Data




KISO





No. Good Data




0556+191 2023/07/15 1.35UT FUJI -KISO



T20230715102720




BLK: 6,SNR1: 0.11203 ,SNR2: 0.93259




Frequency (Hz)

F20230715102722




BLK: 6,SNR1:-0.47977E-01,SNR2: 1.2151



Frequency (Hz)

0605-08 2023/07/15 1.48UT TOYOKAWA-FUJI



T20230715102720





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0605-08 2023/07/15 1.48UT TOYOKAWA-KISO



F20230715102722





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


0605-08 2023/07/15 1.48UT FUJI -KISO



T20230715104628




BLK:24,SNR1: 1.9765 ,SNR2: 7.8524





3C161 2023/07/15 1.80UT TOYOKAWA-FUJI

F20230715104630




BLK:24,SNR1: 2.7544 ,SNR2: 11.688



T20230715104628



No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)


3C161 2023/07/15 1.80UT TOYOKAWA-KISO



F20230715104630



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C161 2023/07/15 1.80UT FUJI -KISO






T20230715111401





BLK: 4,SNR1:-0.60218E-01,SNR2: 1.1236





0652-130 2023/07/15 2.26UT TOYOKAWA-FUJI

F20230715111403



BLK: 4,SNR1:-0.31749E-01,SNR2: 0.84557



T20230715111401



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0652-130 2023/07/15 2.26UT TOYOKAWA-KISO





F20230715111403




No.Good Data




KISO




No.Good Data




0652-130 2023/07/15 2.26UT FUJI -KISO



T20230715112537




BLK:10,SNR1: 1.4908 ,SNR2: 12.998





0703+138 2023/07/15 2.46UT TOYOKAWA-FUJI

F20230715112539



BLK:10,SNR1: 0.28175 ,SNR2: 2.1713



T20230715112537



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


0703+138 2023/07/15 2.46UT TOYOKAWA-KISO



F20230715112539





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0703+138 2023/07/15 2.46UT FUJI -KISO




T20230715113500




BLK:18,SNR1: 7.8301 ,SNR2: 21.655




F20230715113502



BLK:18,SNR1: 0.70140 ,SNR2: 6.1496



0713-024 2023/07/15 2.61UT TOYOKAWA-FUJI



T20230715113500





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0713-024 2023/07/15 2.61UT TOYOKAWA-KISO






F20230715113502





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0713-024 2023/07/15 2.61UT FUJI -KISO




T20230715114511




BLK:17,SNR1: 1.8374 ,SNR2: 5.7160




F20230715114513



BLK:17,SNR1: 0.38042 ,SNR2: 1.2532



0723+10 2023/07/15 2.78UT TOYOKAWA-FUJI



T20230715114511



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0723+10 2023/07/15 2.78UT TOYOKAWA-KISO



F20230715114513



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


0723+10 2023/07/15 2.78UT FUJI -KISO




T20230715115525




BLK:29,SNR1: 61.113 ,SNR2: 71.297




F20230715115527



BLK:29,SNR1: 14.784 ,SNR2: 28.570



0732+33 2023/07/15 2.95UT TOYOKAWA-FUJI



T20230715115525



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0732+33 2023/07/15 2.95UT TOYOKAWA-KISO





F20230715115527




No.Good Data




KISO




No.Good Data




0732+33 2023/07/15 2.95UT FUJI -KISO



T20230715120328




BLK:21,SNR1: 3.9017 ,SNR2: 7.2811




0741-06 2023/07/15 3.09UT TOYOKAWA-FUJI


F20230715120330



BLK:21,SNR1:-0.56807E-01,SNR2: 1.3992



Frequency (Hz)





T20230715120328




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0741-06 2023/07/15 3.09UT TOYOKAWA-KISO





F20230715120330




No.Good Data




KISO





No.Good Data




0741-06 2023/07/15 3.09UT FUJI -KISO




T20230715122047




BLK:16,SNR1: 1.0935 ,SNR2: 6.3420




F20230715122049




BLK:16,SNR1: 0.54959 ,SNR2: 2.4153



3C190 2023/07/15 3.37UT TOYOKAWA-FUJI



T20230715122047




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C190 2023/07/15 3.37UT TOYOKAWA-KISO



F20230715122049





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C190 2023/07/15 3.37UT FUJI -KISO



T20230715123311





BLK:16,SNR1: 0.34108 ,SNR2: 1.8145




Frequency (Hz)

F20230715123313




BLK:16,SNR1: 0.19766 ,SNR2: 1.0760




Frequency (Hz)

3C196 2023/07/15 3.58UT TOYOKAWA-FUJI



T20230715123311




No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C196 2023/07/15 3.58UT TOYOKAWA-KISO



F20230715123313





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C196 2023/07/15 3.58UT FUJI -KISO







T20230715124421




BLK:11,SNR1: 0.23974 ,SNR2: 1.4645




F20230715124423



BLK:11,SNR1: 0.55879E-01,SNR2: 2.1056




0821+394 2023/07/15 3.77UT TOYOKAWA-FUJI



T20230715124421



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0821+394 2023/07/15 3.77UT TOYOKAWA-KISO



F20230715124423



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0821+394 2023/07/15 3.77UT FUJI -KISO



T20230715130107





BLK: 8,SNR1: 4.4746 ,SNR2: 28.471





0839-071 2023/07/15 4.05UT TOYOKAWA-FUJI

F20230715130109



BLK: 8,SNR1:-0.86250E-02,SNR2: 0.91195



T20230715130107



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0839-071 2023/07/15 4.05UT TOYOKAWA-KISO



F20230715130109



No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


0839-071 2023/07/15 4.05UT FUJI -KISO




T20230715131208




BLK:10,SNR1: 0.16312 ,SNR2: 3.3126




F20230715131210



BLK:10,SNR1:-0.12380 ,SNR2: 0.66953



3C208 2023/07/15 4.23UT TOYOKAWA-FUJI



T20230715131208



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C208 2023/07/15 4.23UT TOYOKAWA-KISO





F20230715131210





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C208 2023/07/15 4.23UT FUJI -KISO





T20230715132848




BLK: 9,SNR1: 0.24690E-01,SNR2: 1.7152




F20230715132850





BLK: 9,SNR1: 0.19806 ,SNR2: 1.8551




3C216 2023/07/15 4.51UT TOYOKAWA-FUJI



T20230715132848





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)

3C216 2023/07/15 4.51UT TOYOKAWA-KISO



F20230715132850





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C216 2023/07/15 4.51UT FUJI -KISO





T20230715134740




BLK: 3,SNR1: 0.18615 ,SNR2: 1.3502




F20230715134742





BLK: 3,SNR1:-0.38503E-01,SNR2: 0.39788




0926+117 2023/07/15 4.82UT TOYOKAWA-FUJI



T20230715134740




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0926+117 2023/07/15 4.82UT TOYOKAWA-KISO



F20230715134742





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0926+117 2023/07/15 4.82UT FUJI -KISO





T20230715135524




BLK: 8,SNR1: 0.78921E-01,SNR2: 1.9338




F20230715135526



BLK: 8,SNR1:-0.53756E-01,SNR2: 0.85394






3C222 2023/07/15 4.95UT TOYOKAWA-FUJI









T20230715135524






KISO






3C222 2023/07/15 4.95UT TOYOKAWA-KISO




F20230715135526





KISO




3C222 2023/07/15 4.95UT FUJI -KISO





T20230715140225




BLK: 5,SNR1: 0.16615 ,SNR2: 0.54593




F20230715140227



BLK: 5,SNR1: 0.90562E-01,SNR2: 3.2610



0941-08 2023/07/15 5.07UT TOYOKAWA-FUJI



T20230715140225




No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0941-08 2023/07/15 5.07UT TOYOKAWA-KISO



F20230715140227



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0941-08 2023/07/15 5.07UT FUJI -KISO




T20230715141046




BLK: 5,SNR1: 0.14938 ,SNR2: 0.53041




F20230715141048




BLK: 5,SNR1: 0.85215 ,SNR2: 2.0298






3C230 2023/07/15 5.21UT TOYOKAWA-FUJI




T20230715141046



KISO



3C230 2023/07/15 5.21UT TOYOKAWA-KISO



F20230715141048





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C230 2023/07/15 5.21UT FUJI -KISO








T20230715142647




BLK:21,SNR1: 0.89295 ,SNR2: 11.546




F20230715142649





BLK:21,SNR1: 0.18288 ,SNR2: 0.80433






3C237 2023/07/15 5.47UT TOYOKAWA-FUJI




T20230715142647



KISO



3C237 2023/07/15 5.47UT TOYOKAWA-KISO



F20230715142649





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C237 2023/07/15 5.47UT FUJI -KISO





T20230715143303




BLK: 3,SNR1:-0.46086E-01,SNR2: 0.17093




F20230715143305





BLK: 3,SNR1: 0.18171 ,SNR2: 1.0064



1011+110 2023/07/15 5.58UT TOYOKAWA-FUJI



T20230715143303





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1011+110 2023/07/15 5.58UT TOYOKAWA-KISO



F20230715143305





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1011+110 2023/07/15 5.58UT FUJI -KISO





T20230715144044




BLK: 5,SNR1: 0.32766E-01,SNR2: 1.6441




F20230715144046




BLK: 5,SNR1: 0.67659 ,SNR2: 1.8749



3C241 2023/07/15 5.71UT TOYOKAWA-FUJI



T20230715144044




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C241 2023/07/15 5.71UT TOYOKAWA-KISO







F20230715144046




No.Good Data




KISO





No.Good Data




3C241 2023/07/15 5.71UT FUJI -KISO





T20230715145214




BLK: 5,SNR1: 0.32942E-01,SNR2: 0.81157




F20230715145216




BLK: 5,SNR1: 0.17545 ,SNR2: 0.98105



1031-11 2023/07/15 5.90UT TOYOKAWA-FUJI



T20230715145214




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1031-11 2023/07/15 5.90UT TOYOKAWA-KISO



F20230715145216





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1031-11 2023/07/15 5.90UT FUJI -KISO



T20230715145647





BLK: 2,SNR1: 0.23639E-01,SNR2: 0.37116




Frequency (Hz)

F20230715145649




BLK: 2,SNR1:-0.22491 ,SNR2: 2.1882



Frequency (Hz)

1035-058 2023/07/15 5.97UT TOYOKAWA-FUJI



T20230715145647




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/07/15 5.97UT TOYOKAWA-KISO



F20230715145649





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/07/15 5.97UT FUJI -KISO



T20230715150600





No.Good Data




Frequency (Hz)

F20230715150602




No.Good Data






Frequency (Hz)

1044-008 2023/07/15 6.13UT TOYOKAWA-FUJI








T20230715150600




KISO




1044-008 2023/07/15 6.13UT TOYOKAWA-KISO



F20230715150602




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1044-008 2023/07/15 6.13UT FUJI -KISO




T20230715151704




BLK: 5,SNR1: 0.26174 ,SNR2: 1.4751




F20230715151706





BLK: 5,SNR1:-0.15775 ,SNR2: 0.98760




1055+01 2023/07/15 6.31UT TOYOKAWA-FUJI



T20230715151704





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1055+01 2023/07/15 6.31UT TOYOKAWA-KISO



F20230715151706





KISO




1055+01 2023/07/15 6.31UT FUJI -KISO





T20230715152822




BLK: 1,SNR1: 0.11339 ,SNR2: 0.56954




F20230715152824



BLK: 1,SNR1: 0.13898 ,SNR2: 0.95537




1107+109 2023/07/15 6.50UT TOYOKAWA-FUJI



T20230715152822




No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1107+109 2023/07/15 6.50UT TOYOKAWA-KISO



F20230715152824




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

1107+109 2023/07/15 6.50UT FUJI -KISO






T20230715153759





No.Good Data




Frequency (Hz)

F20230715153801




No.Good Data




Frequency (Hz)


3C255 2023/07/15 6.66UT TOYOKAWA-FUJI



T20230715153759





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C255 2023/07/15 6.66UT TOYOKAWA-KISO



F20230715153801





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C255 2023/07/15 6.66UT FUJI -KISO



T20230715160157





BLK: 7,SNR1: 0.90087E-01,SNR2: 1.1218




Frequency (Hz)

F20230715160159




BLK: 7,SNR1: 0.81094 ,SNR2: 4.0727






Frequency (Hz)

3C263.1 2023/07/15 7.06UT TOYOKAWA-FUJI






T20230715160157




No.Good Data

KISO






No.Good Data




3C263.1 2023/07/15 7.06UT TOYOKAWA-KISO




F20230715160159





KISO




3C263.1 2023/07/15 7.06UT FUJI -KISO





T20230715160824




BLK: 3,SNR1: 0.90563E-01,SNR2: 0.30868




F20230715160826






BLK: 3,SNR1: 0.11019 ,SNR2: 1.6332






3C267 2023/07/15 7.17UT TOYOKAWA-FUJI




T20230715160824



KISO






3C267 2023/07/15 7.17UT TOYOKAWA-KISO









F20230715160826





KISO




3C267 2023/07/15 7.17UT FUJI -KISO





T20230715162738




BLK:30,SNR1: 3.9552 ,SNR2: 27.679




F20230715162740






BLK:30,SNR1: 29.930 ,SNR2: 46.787






1206+439 2023/07/15 7.49UT TOYOKAWA-FUJI



T20230715162738





KISO





1206+439 2023/07/15 7.49UT TOYOKAWA-KISO




F20230715162740





KISO




1206+439 2023/07/15 7.49UT FUJI -KISO



T20230715164729





BLK:21,SNR1: 3.4133 ,SNR2: 5.1029




Frequency (Hz)

F20230715164731




BLK:21,SNR1: 16.386 ,SNR2: 29.772





Frequency (Hz)


3C273 2023/07/15 7.82UT TOYOKAWA-FUJI



T20230715164729





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C273 2023/07/15 7.82UT TOYOKAWA-KISO



F20230715164731





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C273 2023/07/15 7.82UT FUJI -KISO



T20230715173417





BLK:13,SNR1: 15.222 ,SNR2: 23.770




Frequency (Hz)

F20230715173419




BLK:13,SNR1: 3.3600 ,SNR2: 13.513





Frequency (Hz)

1313+453 2023/07/15 8.60UT TOYOKAWA-FUJI









T20230715173417






KISO






1313+453 2023/07/15 8.60UT TOYOKAWA-KISO




F20230715173419





KISO




1313+453 2023/07/15 8.60UT FUJI -KISO



T20230715174423





BLK:29,SNR1: 3.1066 ,SNR2: 12.643




Frequency (Hz)

F20230715174425




BLK:29,SNR1: 20.354 ,SNR2: 22.818




Frequency (Hz)


1323+32 2023/07/15 8.77UT TOYOKAWA-FUJI



T20230715174423





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1323+32 2023/07/15 8.77UT TOYOKAWA-KISO



F20230715174425





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2023/07/15 8.77UT FUJI -KISO



T20230715174913




BLK:25,SNR1: 0.42757 ,SNR2: 3.9574




Frequency (Hz)

F20230715174915




BLK:25,SNR1: 0.66713E-01,SNR2: 0.85268




Frequency (Hz)


3C286 2023/07/15 8.85UT TOYOKAWA-FUJI



T20230715174913




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C286 2023/07/15 8.85UT TOYOKAWA-KISO



F20230715174915




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C286 2023/07/15 8.85UT FUJI -KISO






T20230715175536





BLK:22,SNR1: 2.6733 ,SNR2: 11.147




Frequency (Hz)

1335+479 2023/07/15 8.95UT TOYOKAWA-FUJI


F20230715175538





BLK:22,SNR1: 2.8497 ,SNR2: 11.794




Frequency (Hz)



T20230715175536





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1335+479 2023/07/15 8.95UT TOYOKAWA-KISO




F20230715175538





KISO




1335+479 2023/07/15 8.95UT FUJI -KISO



T20230715175942





BLK: 3,SNR1: 0.31252 ,SNR2: 1.6863




Frequency (Hz)

F20230715175944




BLK: 3,SNR1:-0.63834E-01,SNR2: 1.1373





Frequency (Hz)


1339+472 2023/07/15 9.02UT TOYOKAWA-FUJI



T20230715175942





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1339+472 2023/07/15 9.02UT TOYOKAWA-KISO



F20230715175944





No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1339+472 2023/07/15 9.02UT FUJI -KISO

