




T20230717060800





BLK: 1,SNR1: 0.66325E-01,SNR2: 0.39515




Frequency (Hz)

F20230717060802




BLK: 1,SNR1: 0.96862 ,SNR2: 3.0904




Frequency (Hz)

0152+435 2023/07/16 21.16UT TOYOKAWA-FUJI



T20230717060800



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0152+435 2023/07/16 21.16UT TOYOKAWA-KISO



F20230717060802



No.Good Data



KISO





No.Good Data




0152+435 2023/07/16 21.16UT FUJI -KISO



T20230717062850




BLK: 4,SNR1: 0.70987E-01,SNR2: 0.76938




Frequency (Hz)

F20230717062852




BLK: 4,SNR1: 0.33303 ,SNR2: 1.4267



Frequency (Hz)

0213+178 2023/07/16 21.51UT TOYOKAWA-FUJI



T20230717062850



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0213+178 2023/07/16 21.51UT TOYOKAWA-KISO




F20230717062852



No.Good Data




KISO





No.Good Data




0213+178 2023/07/16 21.51UT FUJI -KISO



T20230717063632





BLK: 2,SNR1: 0.17698 ,SNR2: 1.0173




Frequency (Hz)

3067 2023/07/16 21.64UT TOYOKAWA-FUJI


F20230717063634




BLK: 2,SNR1:-0.17073E-01,SNR2: 1.1697



Frequency (Hz)



T20230717063632



No.Good Data




KISO



No.Good Data




3C67 2023/07/16 21.64UT TOYOKAWA-KISO







F20230717063634




No.Good Data



KISO





No.Good Data




3C67 2023/07/16 21.64UT FUJI -KISO



T20230717065448



BLK: 2,SNR1: 0.32037 ,SNR2: 1.1583





Frequency (Hz)


3C71

2023/07/16 21.94UT TOYOKAWA-FUJI


F20230717065450



BLK: 2,SNR1:-0.87212E-01,SNR2: 3.2671




Frequency (Hz)





T20230717065448




No.Good Data




KISO



No.Good Data



3C71 2023/07/16 21.94UT TOYOKAWA-KISO



F20230717065450




No.Good Data



KISO





No.Good Data




3C71 2023/07/16 21.94UT FUJI -KISO



T20230717071402





BLK: 2,SNR1:-0.37299E-01,SNR2: 0.54436




Frequency (Hz)

F20230717071404




BLK: 2,SNR1: 0.31866 ,SNR2: 1.9981




Frequency (Hz)


0258+350 2023/07/16 22.26UT TOYOKAWA-FUJI




T20230717071402




No.Good Data




KISO



No.Good Data



0258+350 2023/07/16 22.26UT TOYOKAWA-KISO



F20230717071404



No.Good Data



KISO




No.Good Data




0258+350 2023/07/16 22.26UT FUJI -KISO



T20230717072351





BLK: 3,SNR1: 0.15295 ,SNR2: 1.3190




Frequency (Hz)

F20230717072353




BLK: 3,SNR1: 0.16521 ,SNR2: 0.94229



Frequency (Hz)

0308+305 2023/07/16 22.43UT TOYOKAWA-FUJI






T20230717072351





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0308+305 2023/07/16 22.43UT TOYOKAWA-KISO



F20230717072353



No.Good Data



KISO





No.Good Data




0308+305 2023/07/16 22.43UT FUJI -KISO



T20230717073524





BLK: 4,SNR1: 0.12960 ,SNR2: 1.5048




Frequency (Hz)

0320+05 2023/07/16 22.62UT TOYOKAWA-FUJI


F20230717073526




BLK: 4,SNR1: 0.10898 ,SNR2: 2.0703




Frequency (Hz)




T20230717073524




No.Good Data



KISO




No.Good Data




0320+05 2023/07/16 22.62UT TOYOKAWA-KISO




F20230717073526




No.Good Data



KISO





No.Good Data




0320+05 2023/07/16 22.62UT FUJI -KISO



T20230717074844





BLK: 2,SNR1: 0.21402E-02,SNR2: 0.35347E-01




Frequency (Hz)

F20230717074846




BLK: 2,SNR1: 0.67684 ,SNR2: 2.0368




Frequency (Hz)


0333+32 2023/07/16 22.84UT TOYOKAWA-FUJI





T20230717074844




No.Good Data




KISO



No.Good Data



0333+32 2023/07/16 22.84UT TOYOKAWA-KISO



F20230717074846



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0333+32 2023/07/16 22.84UT FUJI -KISO






T20230717080146





BLK:12,SNR1: 0.34718 ,SNR2: 1.7918




Frequency (Hz)

F20230717080148




BLK:12,SNR1: 0.60604E-01,SNR2: 1.2298



Frequency (Hz)

0347+05 2023/07/16 23.06UT TOYOKAWA-FUJI



T20230717080146



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


0347+05 2023/07/16 23.08UT TOYOKAWA-KISO



F20230717080148





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0347+05 2023/07/16 23.06UT FUJI -KISO





T20230717081721




BLK: 1,SNR1: 0.99703E-01,SNR2: 0.77109




F20230717081723



BLK: 1,SNR1: 0.28691 ,SNR2: 1.6480




0403-132 2023/07/16 23.32UT TOYOKAWA-FUJI





T20230717081721




No.Good Data




KISO



No.Good Data



0403-132 2023/07/16 23.32UT TOYOKAWA-KISO



F20230717081723




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0403-132 2023/07/16 23.32UT FUJI -KISO



T20230717082631





BLK: 2,SNR1: 0.44211E-01,SNR2: 0.31234




Frequency (Hz)

F20230717082633




BLK: 2,SNR1:-0.15768 ,SNR2: 2.4309



Frequency (Hz)


0411+05 2023/07/16 23.47UT TOYOKAWA-FUJI



T20230717082631



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0411+05 2023/07/16 23.47UT TOYOKAWA-KISO








F20230717082633




No.Good Data




KISO





No.Good Data




0411+05 2023/07/16 23.47UT FWJ -KISO





T20230717083325




BLK: 3,SNR1:-0.33537E-01,SNR2: 0.60171




F20230717083327



BLK: 3,SNR1: 0.22610 ,SNR2: 1.7919



0418+236 2023/07/16 23.59UT TOYOKAWA-FUJI



T20230717083325



No.Good Data




KISO



No.Good Data



0418+236 2023/07/16 23.59UT TOYOKAWA-KISO





F20230717083327




No. Good Data




KISO





No. Good Data




0418+236 2023/07/16 23.59UT FUJI -KISO



T20230717084452





BLK: 5,SNR1: 0.61567 ,SNR2: 3.7025




Frequency (Hz)

F20230717084454




BLK: 5,SNR1: 0.16262 ,SNR2: 1.0712





Frequency (Hz)


3C119 2023/07/16 23.78UT TOYOKAWA-FUJI





T20230717084452




No. Good Data




KISO



No. Good Data




3C119 2023/07/16 23.78UT TOYOKAWA-KISO




F20230717084454




No.Good Data



KISO





No.Good Data




3C119 2023/07/16 23.78UT FUJI -KISO



T20230717085409





BLK: 2,SNR1: 0.19280 ,SNR2: 1.1221




Frequency (Hz)

F20230717085411




BLK: 2,SNR1: 0.19506 ,SNR2: 1.5145



Frequency (Hz)

0440-102 2023/07/16 23.93UT TOYOKAWA-FUJI





T20230717085409



No. Good Data




KISO



No. Good Data



0440-102 2023/07/16 23.93UT TOYOKAWA-KISO



F20230717085411




No. Good Data



KISO





No. Good Data




0440-102 2023/07/16 23.93UT FUJI -KISO



T20230717093300





BLK:23,SNR1: 1.1659 ,SNR2: 5.8334




Frequency (Hz)

3C138 2023/07/17 0.58UT TOYOKAWA-FUJI


F20230717093302



BLK:23,SNR1: 0.23834 ,SNR2: 0.89000



Frequency (Hz)



T20230717093300



No.Good Data



KISO




No.Good Data



3C138 2023/07/17 0.58UT TOYOKAWA-KISO




F20230717093302




No.Good Data



KISO




No.Good Data




3C138 2023/07/17 0.58UT FUJI -KISO



T20230717094633




BLK:27,SNR1: 2.4545 ,SNR2: 17.324




Frequency (Hz)

F20230717094635




BLK:27,SNR1: 0.25724 ,SNR2: 1.5204



Frequency (Hz)

0531+194 2023/07/17 0.80UT TOYOKAWA-FUJI



T20230717094633



No.Good Data



KISO



No.Good Data



0531+194 2023/07/17 0.80UT TOYOKAWA-KISO



F20230717094635



No.Good Data



KISO



No.Good Data





0531+194 2023/07/17 0.80UT FUJI -KISO








T20230717095451




BLK:27,SNR1: 6.0627 ,SNR2: 37.162




F20230717095453



BLK:27,SNR1: 0.21744 ,SNR2: 2.5288



3C147 2023/07/17 0.94UT TOYOKAWA-FUJI



T20230717095451



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C147 2023/07/17 0.94UT TOYOKAWA-KISO



F20230717095453





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C147 2023/07/17 0.94UT FUJI -KISO



T20230717100304




BLK:31,SNR1: 3.6628 ,SNR2: 15.267




Frequency (Hz)

F20230717100306




BLK:31,SNR1: 0.21434 ,SNR2: 1.8905



Frequency (Hz)

0548+16 2023/07/17 1.08UT TOYOKAWA-FUJI



T20230717100304



No. Good Data



KISO




No. Good Data



0548+16 2023/07/17 1.08UT TOYOKAWA-KISO




F20230717100306




No.Good Data




KISO




No.Good Data




0548+16 2023/07/17 1.08UT FUJI -KISO





T20230717100715




BLK:16,SNR1: 0.48434 ,SNR2: 5.2167




F20230717100717



BLK:16,SNR1: 0.55517E-01,SNR2: 0.16861



0552+12 2023/07/17 1.15UT TOYOKAWA-FUJI




T20230717100715



No. Good Data



KISO



No. Good Data



0552+12 2023/07/17 1.15UT TOYOKAWA-KISO








F20230717100717




No. Good Data



KISO




No. Good Data




0552+12 2023/07/17 1.15UT FUJI -KISO




T20230717101142




BLK:17,SNR1: 0.94959 ,SNR2: 4.4965




F20230717101144



BLK:17,SNR1: 0.48178 ,SNR2: 2.8136



0556+191 2023/07/17 1.22UT TOYOKAWA-FUJI



T20230717101142




No. Good Data



KISO



No. Good Data



0556+191 2023/07/17 1.22UT TOYOKAWA-KISO



F20230717101144



No. Good Data




KISO





No. Good Data




0556+191 2023/07/17 1.22UT FUJI -KISO





T20230717101928




BLK: 8,SNR1: 0.81486E-01,SNR2: 1.3625




F20230717101930



BLK: 8,SNR1: 0.47648 ,SNR2: 0.46369



0605-08 2023/07/17 1.35UT TOYOKAWA-FUJI




T20230717101928




No. Good Data




KISO



No. Good Data



0605-08 2023/07/17 1.35UT TOYOKAWA-KISO





F20230717101930




No.Good Data



KISO




No.Good Data




0605-08 2023/07/17 1.35UT FUJI -KISO



T20230717103836




BLK:29,SNR1: 13.965 ,SNR2: 98.227





3C161 2023/07/17 1.67UT TOYOKAWA-FUJI

F20230717103838



BLK:29,SNR1:-0.10186E-01,SNR2: 2.1750





T20230717103836



No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


3C161 2023/07/17 1.67UT TOYOKAWA-KISO





F20230717103838




No.Good Data




KISO





No.Good Data




3C161 2023/07/17 1.67UT FUJI -KISO



T20230717110609





BLK: 7,SNR1: 0.11387 ,SNR2: 1.0648




Frequency (Hz)

F20230717110611




BLK: 7,SNR1: 12.842 ,SNR2: 31.215



Frequency (Hz)


0652-130 2023/07/17 2.13UT TOYOKAWA-FUJI



T20230717110609





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0652-130 2023/07/17 2.13UT TOYOKAWA-KISO



F20230717110611





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2023/07/17 2.13UT FUJI -KISO



T20230717111745





BLK: 2,SNR1: 0.41037 ,SNR2: 0.86441




Frequency (Hz)

F20230717111747




BLK: 2,SNR1: 0.13533 ,SNR2: 2.5851



Frequency (Hz)


0703+138 2023/07/17 2.32UT TOYOKAWA-FUJI



T20230717111745



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


0703+138 2023/07/17 2.32UT TOYOKAWA-KISO





F20230717111747




No.Good Data




KISO



No.Good Data





0703+138 2023/07/17 2.32UT FUJI -KISO







T20230717112708




BLK: 8,SNR1: 0.19142 ,SNR2: 1.6319




F20230717112710



BLK: 8,SNR1:-0.12422 ,SNR2: 1.7439



0713-024 2023/07/17 2.48UT TOYOKAWA-FUJI



T20230717112708



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


0713-024 2023/07/17 2.48UT TOYOKAWA-KISO



F20230717112710




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0713-024 2023/07/17 2.48UT FUJI -KISO



T20230717113720




BLK:15,SNR1: 0.48128 ,SNR2: 3.5506





0723+10 2023/07/17 2.65UT TOYOKAWA-FUJI

F20230717113722



BLK:15,SNR1: 0.87544 ,SNR2: 2.4078



T20230717113720



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0723+10 2023/07/17 2.65UT TOYOKAWA-KISO



F20230717113722





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0723+10 2023/07/17 2.65UT FUJI -KISO





T20230717114734




BLK:20,SNR1: 0.81371 ,SNR2: 3.6916




F20230717114736



BLK:20,SNR1: 0.29263 ,SNR2: 3.0298



0732+33 2023/07/17 2.82UT TOYOKAWA-FUJI



T20230717114734





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0732+33 2023/07/17 2.82UT TOYOKAWA-KISO





F20230717114736





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0732+33 2023/07/17 2.82UT FUJI -KISO



T20230717115536




BLK:20,SNR1: 3.3574 ,SNR2: 11.571





0741-06 2023/07/17 2.95UT TOYOKAWA-FUJI

F20230717115538



BLK:20,SNR1: 3.3467 ,SNR2: 4.2918



T20230717115536





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0741-06 2023/07/17 2.95UT TOYOKAWA-KISO



F20230717115538





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0741-06 2023/07/17 2.95UT FUJI -KISO



T20230717121255




BLK: 9,SNR1: 0.83415 ,SNR2: 3.9412





3C190 2023/07/17 3.24UT TOYOKAWA-FUJI



F20230717121257




BLK: 9,SNR1: 0.33505 ,SNR2: 0.99908



T20230717121255





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C190 2023/07/17 3.24UT TOYOKAWA-KISO



F20230717121257





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C190 2023/07/17 3.24UT FUJI -KISO





T20230717122519




BLK:15,SNR1: 0.45267 ,SNR2: 2.1201




F20230717122521



BLK:15,SNR1: 0.53820E-01,SNR2: 1.2818



3C196 2023/07/17 3.45UT TOYOKAWA-FUJI





T20230717122519



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C196 2023/07/17 3.45UT TOYOKAWA-KISO



F20230717122521





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C196 2023/07/17 3.45UT FUJI -KISO



T20230717123629





BLK:15,SNR1: 0.47457 ,SNR2: 3.3321




Frequency (Hz)

F20230717123631




BLK:15,SNR1: 0.24071 ,SNR2: 0.61526




Frequency (Hz)

0821+394 2023/07/17 3.64UT TOYOKAWA-FUJI



T20230717123629




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0821+394 2023/07/17 3.64UT TOYOKAWA-KISO



F20230717123631





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0821+394 2023/07/17 3.64UT FUJI -KISO




T20230717125315




BLK: 5,SNR1: 0.25946 ,SNR2: 1.5018




F20230717125317



BLK: 5,SNR1: 0.78675E-01,SNR2: 3.1182



0839-071 2023/07/17 3.92UT TOYOKAWA-FUJI



T20230717125315



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0839-071 2023/07/17 3.92UT TOYOKAWA-KISO



F20230717125317





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0839-071 2023/07/17 3.92UT FUJI -KISO








T20230717130416




BLK:12,SNR1: 0.29082 ,SNR2: 3.4395




F20230717130418



BLK:12,SNR1: 1.2577 ,SNR2: 1.3710



3C208 2023/07/17 4.10UT TOYOKAWA-FUJI



T20230717130416



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C208 2023/07/17 4.10UT TOYOKAWA-KISO



F20230717130418





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2023/07/17 4.10UT FUJI -KISO



T20230717132057





BLK:12,SNR1: 0.81863 ,SNR2: 3.1948





3C216 2023/07/17 4.38UT TOYOKAWA-FUJI

F20230717132059



BLK:12,SNR1: 0.33645 ,SNR2: 1.1016



T20230717132057



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C216 2023/07/17 4.38UT TOYOKAWA-KISO



F20230717132059



No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C216 2023/07/17 4.38UT FUJI -KISO





T20230717133948




BLK: 6,SNR1: 0.10122 ,SNR2: 0.54717




F20230717133950



BLK: 6,SNR1: 0.37700E-01,SNR2: 1.8763




0926+117 2023/07/17 4.69UT TOYOKAWA-FUJI



T20230717133948



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0926+117 2023/07/17 4.69UT TOYOKAWA-KISO





F20230717133950





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0926+117 2023/07/17 4.69UT FUJI -KISO




T20230717134733




BLK: 9,SNR1: 0.30673 ,SNR2: 1.2107




F20230717134735





BLK: 9,SNR1: 0.20237 ,SNR2: 1.0888




3C222 2023/07/17 4.82UT TOYOKAWA-FUJI



T20230717134733





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C222 2023/07/17 4.82UT TOYOKAWA-KISO



F20230717134735





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C222 2023/07/17 4.82UT FUJI -KISO





T20230717135433




BLK: 8,SNR1:-0.37709E-02,SNR2: 0.22706




F20230717135435





BLK: 8,SNR1: 12.428 ,SNR2: 36.823



0941-08 2023/07/17 4.94UT TOYOKAWA-FUJI



T20230717135433





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

0941-08 2023/07/17 4.94UT TOYOKAWA-KISO



F20230717135435





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0941-08 2023/07/17 4.94UT FUJI -KISO




T20230717140255




BLK: 5,SNR1: 0.73140E-01,SNR2: 1.8737




F20230717140257



BLK: 5,SNR1: 0.19581 ,SNR2: 2.1243




3C230 2023/07/17 5.08UT TOYOKAWA-FUJI





T20230717140255





No.Good Data



Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C230 2023/07/17 5.08UT TOYOKAWA-KISO




F20230717140257





KISO




3C230 2023/07/17 5.08UT FUJI -KISO





T20230717141701




BLK:18,SNR1: 0.53471 ,SNR2: 5.9186




F20230717141703




BLK:18,SNR1: 0.27356 ,SNR2: 0.95034




3C236 2023/07/17 5.31UT TOYOKAWA-FUJI



T20230717141701




No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C236 2023/07/17 5.31UT TOYOKAWA-KISO



F20230717141703



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C236 2023/07/17 5.31UT FUJI -KISO





T20230717142511




BLK:13,SNR1: 0.52941 ,SNR2: 3.1946




F20230717142513




BLK:13,SNR1: 1.5710 ,SNR2: 6.3874




1011+110 2023/07/17 5.45UT TOYOKAWA-FUJI



T20230717142511





KISO




1011+110 2023/07/17 5.45UT TOYOKAWA-KISO



F20230717142513





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1011+110 2023/07/17 5.45UT FUJI -KISO







T20230717143252




BLK: 9,SNR1: 0.82480 ,SNR2: 3.2799




F20230717143254





BLK: 9,SNR1: 0.38687 ,SNR2: 1.8131




3C241 2023/07/17 5.58UT TOYOKAWA-FUJI



T20230717143252





No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C241 2023/07/17 5.58UT TOYOKAWA-KISO



F20230717143254





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C241 2023/07/17 5.58UT FUJI -KISO





T20230717144422




BLK: 6,SNR1: 0.28932 ,SNR2: 0.85418




F20230717144424





BLK: 6,SNR1: 0.39132 ,SNR2: 1.2880






1031-11 2023/07/17 5.77UT TOYOKAWA-FUJI




T20230717144422



KISO



1031-11 2023/07/17 5.77UT TOYOKAWA-KISO



F20230717144424



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1031-11 2023/07/17 5.77UT FUJI -KISO




T20230717144855




BLK: 6,SNR1: 0.55315E-01,SNR2: 1.0596




F20230717144857




BLK: 6,SNR1: 0.92560 ,SNR2: 3.0302



1035-058 2023/07/17 5.84UT TOYOKAWA-FUJI



T20230717144855




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1035-058 2023/07/17 5.84UT TOYOKAWA-KISO





F20230717144857




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1035-058 2023/07/17 5.84UT FUJI -KISO




T20230717145808




BLK: 1,SNR1:-0.20677E-01,SNR2: 1.2185




F20230717145810




BLK: 1,SNR1: 1.1027 ,SNR2: 4.8359



1044-008 2023/07/17 6.00UT TOYOKAWA-FUJI



T20230717145808




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1044-008 2023/07/17 6.00UT TOYOKAWA-KISO



F20230717145810





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1044-008 2023/07/17 6.00UT FUJI -KISO




T20230717150912




BLK: 8,SNR1: 0.94799 ,SNR2: 2.7945




F20230717150914




BLK: 8,SNR1:-0.10256 ,SNR2: 0.56132



1055+01 2023/07/17 6.18UT TOYOKAWA-FUJI



T20230717150912




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1055+01 2023/07/17 6.18UT TOYOKAWA-KISO



F20230717150914





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1055+01 2023/07/17 6.18UT FUJI -KISO





T20230717152030




BLK: 4,SNR1: 0.60756E-02,SNR2: 0.40369




F20230717152032



BLK: 4,SNR1: 0.11070 ,SNR2: 1.5051






1107+109 2023/07/17 6.37UT TOYOKAWA-FUJI








T20230717152030






KISO






1107+109 2023/07/17 6.37UT TOYOKAWA-KISO



F20230717152032




KISO




1107+109 2023/07/17 6.37UT FUJI -KISO




T20230717153007




BLK: 8,SNR1: 0.20443 ,SNR2: 2.2110




F20230717153009




BLK: 8,SNR1: 1.4480 ,SNR2: 6.0229




3C255 2023/07/17 6.53UT TOYOKAWA-FUJI



T20230717153007




KISO




3C255 2023/07/17 6.53UT TOYOKAWA-KISO



F20230717153009





KISO




3C255 2023/07/17 6.53UT FUJI -KISO





T20230717155405




BLK: 8,SNR1: 1.1597 ,SNR2: 3.4213




F20230717155407





BLK: 8,SNR1: 6.0234 ,SNR2: 12.491




3C263.1 2023/07/17 6.93UT TOYOKAWA-FUJI



T20230717155405





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C263.1 2023/07/17 6.93UT TOYOKAWA-KISO




F20230717155407



KISO





3C263.1 2023/07/17 6.93UT FUJI -KISO






T20230717160032





BLK: 8,SNR1: 0.25576 ,SNR2: 1.2617




Frequency (Hz)

F20230717160034




BLK: 8,SNR1: 2.2643 ,SNR2: 9.1243





Frequency (Hz)


3C267 2023/07/17 7.04UT TOYOKAWA-FUJI



T20230717160032





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C267 2023/07/17 7.04UT TOYOKAWA-KISO



F20230717160034



No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C267 2023/07/17 7.04UT FUJI -KISO





T20230717161947




BLK:29,SNR1: 3.2309 ,SNR2: 12.911




F20230717161949






BLK:29,SNR1: 6.8431 ,SNR2: 15.039






1206+439 2023/07/17 7.36UT TOYOKAWA-FUJI




T20230717161947






KISO






1206+439 2023/07/17 7.36UT TOYOKAWA-KISO




F20230717161949





KISO




1206+439 2023/07/17 7.36UT FUJI -KISO





T20230717163937




BLK:29,SNR1: 10.745 ,SNR2: 23.896




F20230717163939






BLK:29,SNR1: 3.2078 ,SNR2: 13.005






3C273 2023/07/17 7.69UT TOYOKAWA-FUJI




T20230717163937



KISO






3C273 2023/07/17 7.69UT TOYOKAWA-KISO









F20230717163939




KISO




3C273 2023/07/17 7.69UT FUJI -KISO




T20230717165248




BLK:37,SNR1: 11.473 ,SNR2: 24.542




F20230717165250






BLK:37,SNR1: 10.627 ,SNR2: 22.739






3C275 2023/07/17 7.91UT TOYOKAWA-FUJI



T20230717165248





KISO





3C275 2023/07/17 7.91UT TOYOKAWA-KISO




F20230717165250





KISO




3C275 2023/07/17 7.91UT FUJI -KISO




T20230717172625




BLK: 4,SNR1: 0.78300E-01,SNR2: 0.95064




F20230717172627





BLK: 4,SNR1: 0.13638 ,SNR2: 1.1577




1313+453 2023/07/17 8.47UT TOYOKAWA-FUJI



T20230717172625





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1313+453 2023/07/17 8.47UT TOYOKAWA-KISO






F20230717172627




No.Good Data

KISO





No.Good Data


1313+453 2023/07/17 8.47UT FUJI -KISO




T20230717173631




BLK:15,SNR1: 2.7730 ,SNR2: 10.806




F20230717173633



BLK:15,SNR1: 1.7840 ,SNR2: 7.5719





1323+32 2023/07/17 8.64UT TOYOKAWA-FUJI









T20230717173631





KISO




1323+32 2023/07/17 8.64UT TOYOKAWA-KISO



F20230717173633





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2023/07/17 8.64UT FUJI -KISO



T20230717174121




BLK:19,SNR1: 4.0702 ,SNR2: 9.0413




Frequency (Hz)

F20230717174123




BLK:19,SNR1: 13.041 ,SNR2: 15.861





Frequency (Hz)


3C286 2023/07/17 8.72UT TOYOKAWA-FUJI



T20230717174121





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C286 2023/07/17 8.72UT TOYOKAWA-KISO



F20230717174123




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C286 2023/07/17 8.72UT FUJI -KISO



T20230717174744




BLK:21,SNR1: 3.3936 ,SNR2: 12.704




Frequency (Hz)

1335+479 2023/07/17 8.82UT TOYOKAWA-FUJI


F20230717174746





BLK:21,SNR1: 1.8694 ,SNR2: 5.6694




Frequency (Hz)



T20230717174744




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1335+479 2023/07/17 8.82UT TOYOKAWA-KISO



F20230717174746





No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1335+479 2023/07/17 8.82UT FUJI -KISO

