






T20230719060008




BLK: 3,SNR1:-0.96741E-01,SNR2: 0.0000




F20230719060010




BLK: 3,SNR1:-0.18798 ,SNR2: 0.53984



0152+435 2023/07/18 21.03UT TOYOKAWA-FUJI



T20230719060008




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0152+435 2023/07/18 21.03UT TOYOKAWA-KISO



F20230719060010




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0152+435 2023/07/18 21.03UT FUJI -KISO



T20230719062058





BLK: 3,SNR1:-0.59555E-02,SNR2: 0.69531




Frequency (Hz)

F20230719062100




BLK: 3,SNR1: 1.3411 ,SNR2: 9.7005



Frequency (Hz)

0213+178 2023/07/18 21.38UT TOYOKAWA-FUJI



T20230719062058



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


0213+178 2023/07/18 21.38UT TOYOKAWA-KISO



F20230719062100




No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


0213+178 2023/07/18 21.38UT FUJI -KISO



T20230719062840



BLK: 1,SNR1: 0.16271 ,SNR2: 1.6005





Frequency (Hz)


3C67

2023/07/18 21.51UT TOYOKAWA-FUJI


F20230719062842



BLK: 1,SNR1: 0.45119E-01,SNR2: 1.7000




Frequency (Hz)




T20230719062840




No.Good Data




KISO



No.Good Data



3C67 2023/07/18 21.51UT TOYOKAWA-KISO





F20230719062842



No.Good Data



KISO





No.Good Data




3C67 2023/07/18 21.51UT FUJI -KISO



T20230719064656



BLK: 2,SNR1: 0.46055 ,SNR2: 1.6586





Frequency (Hz)


3C71

2023/07/18 21.81UT TOYOKAWA-FUJI


F20230719064658





BLK: 2,SNR1: 1.1303 ,SNR2: 2.9470




Frequency (Hz)




T20230719064656




No.Good Data




KISO



No.Good Data



3C71 2023/07/18 21.81UT TOYOKAWA-KISO



F20230719064658





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C71 2023/07/18 21.81UT FUJI -KISO



T20230719070610





BLK: 2,SNR1: 0.89867E-02,SNR2: 0.26945




Frequency (Hz)

F20230719070612




BLK: 2,SNR1: 0.26818 ,SNR2: 6.4479




Frequency (Hz)


0258+350 2023/07/18 22.13UT TOYOKAWA-FUJI




T20230719070610




No.Good Data




KISO



No.Good Data



0258+350 2023/07/18 22.13UT TOYOKAWA-KISO



F20230719070612



No.Good Data



KISO





No.Good Data




0258+350 2023/07/18 22.13UT FUJI -KISO



T20230719071559





BLK: 4,SNR1: 0.71980E-01,SNR2: 0.30000




Frequency (Hz)

F20230719071601




BLK: 4,SNR1:-0.31653 ,SNR2: 1.4804




Frequency (Hz)

0308+305 2023/07/18 22.29UT TOYOKAWA-FUJI







T20230719071559




No.Good Data




KISO



No.Good Data



0308+305 2023/07/18 22.29UT TOYOKAWA-KISO



F20230719071601



No.Good Data



KISO





No.Good Data




0308+305 2023/07/18 22.29UT FUJI -KISO



T20230719072732





BLK:10,SNR1: 0.68616E-01,SNR2: 0.66582




Frequency (Hz)

F20230719072734




BLK:10,SNR1: 68.724 ,SNR2: 134.26




Frequency (Hz)


0320+05 2023/07/18 22.49UT TOYOKAWA-FUJI




T20230719072732




No.Good Data



KISO



No.Good Data



0320+05 2023/07/18 22.49UT TOYOKAWA-KISO



F20230719072734



No.Good Data



KISO




No.Good Data




0320+05 2023/07/18 22.49UT FUJI -KISO



T20230719074052




BLK: 6,SNR1: 0.25744 ,SNR2: 1.0042




Frequency (Hz)

F20230719074054




BLK: 6,SNR1: 0.96375E-01,SNR2: 3.5801





Frequency (Hz)


0333+32 2023/07/18 22.71UT TOYOKAWA-FUJI



T20230719074052




No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0333+32 2023/07/18 22.71UT TOYOKAWA-KISO



F20230719074054



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0333+32 2023/07/18 22.71UT FUJI -KISO






T20230719075355





BLK: 3,SNR1: 0.10622 ,SNR2: 1.1568




Frequency (Hz)

F20230719075357




BLK: 3,SNR1: 0.98639E-01,SNR2: 0.83256




Frequency (Hz)


0347+05 2023/07/18 22.93UT TOYOKAWA-FUJI



T20230719075355




No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0347+05 2023/07/18 22.93UT TOYOKAWA-KISO



F20230719075357



No.Good Data




KISO





No.Good Data




0347+05 2023/07/18 22.93UT FUJI -KISO



T20230719080929





BLK: 4,SNR1: 0.12156 ,SNR2: 2.2960




Frequency (Hz)

F20230719080931




BLK: 4,SNR1: 1.2578 ,SNR2: 2.0833



Frequency (Hz)

0403-132 2023/07/18 23.19UT TOYOKAWA-FUJI



T20230719080929



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0403-132 2023/07/18 23.19UT TOYOKAWA-KISO



F20230719080931





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0403-132 2023/07/18 23.19UT FUJI -KISO





T20230719081840




BLK: 5,SNR1: 0.90697E-01,SNR2: 0.76690




F20230719081842



BLK: 5,SNR1: 0.53854 ,SNR2: 2.0448




0411+05 2023/07/18 23.34UT TOYOKAWA-FUJI





T20230719081840




No.Good Data




KISO



No.Good Data





0411+05 2023/07/18 23.34UT TOYOKAWA-KISO








F20230719081842




No.Good Data




KISO





No.Good Data




0411+05 2023/07/18 23.34UT FUJI -KISO



T20230719082533





BLK: 4,SNR1:-0.15342E-01,SNR2: 0.33267




Frequency (Hz)

F20230719082535




BLK: 4,SNR1: 1.2767 ,SNR2: 6.0050



Frequency (Hz)


0418+236 2023/07/18 23.45UT TOYOKAWA-FUJI



T20230719082533





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0418+236 2023/07/18 23.45UT TOYOKAWA-KISO





F20230719082535




No.Good Data




KISO




No.Good Data




0418+236 2023/07/18 23.45UT FUJI -KISO




T20230719083700




BLK:19,SNR1: 0.88993 ,SNR2: 2.8478




F20230719083702




BLK:19,SNR1:-0.22956 ,SNR2: 1.4977




3C119 2023/07/18 23.64UT TOYOKAWA-FUJI




T20230719083700




No.Good Data




KISO




No.Good Data




3C119 2023/07/18 23.64UT TOYOKAWA-KISO




F20230719083702




No.Good Data



KISO





No.Good Data




3C119 2023/07/18 23.64UT FUJI -KISO



T20230719085411




BLK: 9,SNR1: 0.15535 ,SNR2: 0.41371




Frequency (Hz)

F20230719085413




BLK: 9,SNR1: 0.67242 ,SNR2: 1.5596



Frequency (Hz)

0446+459 2023/07/18 23.93UT TOYOKAWA-FUJI





T20230719085411



No.Good Data



KISO



No.Good Data



0446+459 2023/07/18 23.93UT TOYOKAWA-KISO





F20230719085413




No.Good Data



KISO





No.Good Data




0446+459 2023/07/18 23.93UT FUJI -KISO



T20230719092508





BLK:16,SNR1: 111.12 ,SNR2: 181.93




Frequency (Hz)

3C138 2023/07/19 0.45UT TOYOKAWA-FUJI


F20230719092510



BLK:16,SNR1: 10.612 ,SNR2: 47.204



Frequency (Hz)



T20230719092508



No.Good Data



KISO




No.Good Data



3C138 2023/07/19 0.45UT TOYOKAWA-KISO




F20230719092510




No. Good Data



KISO




No. Good Data




3C138 2023/07/19 0.45UT FUJI -KISO




T20230719093841




BLK:25,SNR1: 2.7502 ,SNR2: 20.772




F20230719093843




BLK:25,SNR1: 0.53047 ,SNR2: 1.6343




0531+194 2023/07/19 0.67UT TOYOKAWA-FUJI




T20230719093841




No.Good Data



KISO



No.Good Data



0531+194 2023/07/19 0.67UT TOYOKAWA-KISO



F20230719093843



No.Good Data



KISO



No.Good Data




0531+194 2023/07/19 0.67UT FUJI -KISO






T20230719094700




BLK:19,SNR1: 13.568 ,SNR2: 41.770





3C147 2023/07/19 0.81UT TOYOKAWA-FUJI

F20230719094702



BLK:19,SNR1: 14.675 ,SNR2: 17.313




T20230719094700




No.Good Data



KISO




No.Good Data



3C147 2023/07/19 0.81UT TOYOKAWA-KISO





F20230719094702




No.Good Data



KISO




No.Good Data




3C147 2023/07/19 0.81UT FUJI -KISO



T20230719095512




BLK:14,SNR1: 0.25256 ,SNR2: 2.3728




Frequency (Hz)

F20230719095514




BLK:14,SNR1:-0.13775 ,SNR2: 0.85473




Frequency (Hz)


0548+16 2023/07/19 0.95UT TOYOKAWA-FUJI




T20230719095512




No. Good Data



KISO



No. Good Data



0548+16 2023/07/19 0.95UT TOYOKAWA-KISO




F20230719095514




No.Good Data




KISO





No.Good Data




0548+16 2023/07/19 0.95UT FUJI -KISO



T20230719095923





BLK: 8,SNR1: 1.0276 ,SNR2: 7.3204




Frequency (Hz)

F20230719095925




BLK: 8,SNR1: 0.18792E-01,SNR2: 0.35991



Frequency (Hz)

0552+12 2023/07/19 1.02UT TOYOKAWA-FUJI



T20230719095923



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0552+12 2023/07/19 1.02UT TOYOKAWA-KISO





F20230719095925



No.Good Data



KISO





No.Good Data




0552+12 2023/07/19 1.02UT FUJI -KISO



T20230719100350





BLK: 7,SNR1: 0.28483E-01,SNR2: 1.4909





0556+191 2023/07/19 1.09UT TOYOKAWA-FUJI

F20230719100352




BLK: 7,SNR1: 6.1666 ,SNR2: 10.567



T20230719100350



No. Good Data




Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


0556+191 2023/07/19 1.09UT TOYOKAWA-KISO



F20230719100352



No. Good Data




KISO





No. Good Data




0556+191 2023/07/19 1.09UT FUJI -KISO




T20230719101137




BLK: 5,SNR1: 0.89573E-01,SNR2: 0.31644




F20230719101139



BLK: 5,SNR1:-0.55162E-01,SNR2: 0.66536



0605-08 2023/07/19 1.22UT TOYOKAWA-FUJI




T20230719101137




No. Good Data



KISO



No. Good Data



0605-08 2023/07/19 1.22UT TOYOKAWA-KISO




F20230719101139




No.Good Data




KISO




No.Good Data




0605-08 2023/07/19 1.22UT FUJI -KISO




T20230719103044




BLK:24,SNR1: 5.4176 ,SNR2: 29.503




F20230719103046



BLK:24,SNR1:-0.14541 ,SNR2: 1.0355



3C161 2023/07/19 1.54UT TOYOKAWA-FUJI





T20230719103044



No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


3C161 2023/07/19 1.54UT TOYOKAWA-KISO



F20230719103046





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C161 2023/07/19 1.54UT FUJI -KISO




T20230719105818




BLK:12,SNR1: 116.76 ,SNR2: 119.71




F20230719105820



BLK:12,SNR1: 25.318 ,SNR2: 33.373




0652-130 2023/07/19 2.00UT TOYOKAWA-FUJI



T20230719105818





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0652-130 2023/07/19 2.00UT TOYOKAWA-KISO



F20230719105820





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2023/07/19 2.00UT FUJI -KISO



T20230719110953





BLK: 6,SNR1: 0.22147 ,SNR2: 2.4693





0703+138 2023/07/19 2.19UT TOYOKAWA-FUJI

F20230719110955




BLK: 6,SNR1: 9.7879 ,SNR2: 25.861



T20230719110953



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


0703+138 2023/07/19 2.19UT TOYOKAWA-KISO





F20230719110955




No.Good Data




KISO



No.Good Data




0703+138 2023/07/19 2.19UT FUJI -KISO






T20230719111916




BLK:17,SNR1: 2.6057 ,SNR2: 9.6531





0713-024 2023/07/19 2.35UT TOYOKAWA-FUJI

F20230719111918



BLK:17,SNR1: 0.67002 ,SNR2: 2.7339



T20230719111916



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


0713-024 2023/07/19 2.35UT TOYOKAWA-KISO



F20230719111918




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0713-024 2023/07/19 2.35UT FUJI -KISO





T20230719112928




BLK:20,SNR1: 4.2270 ,SNR2: 7.8063




F20230719112930



BLK:20,SNR1: 0.12095 ,SNR2: 1.0329



0723+10 2023/07/19 2.52UT TOYOKAWA-FUJI



T20230719112928



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0723+10 2023/07/19 2.52UT TOYOKAWA-KISO



F20230719112930




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0723+10 2023/07/19 2.52UT FUJI -KISO




T20230719113942




BLK: 7,SNR1: 1.8557 ,SNR2: 10.348




F20230719113944



BLK: 7,SNR1: 0.68801E-01,SNR2: 0.58947



0732+33 2023/07/19 2.69UT TOYOKAWA-FUJI



T20230719113942



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0732+33 2023/07/19 2.69UT TOYOKAWA-KISO







F20230719113944




No.Good Data




KISO




No.Good Data




0732+33 2023/07/19 2.69UT FUJI -KISO





T20230719114745




BLK:21,SNR1: 0.89732 ,SNR2: 5.8579




F20230719114747



BLK:21,SNR1: 0.11000E-01,SNR2: 1.3999



0741-06 2023/07/19 2.82UT TOYOKAWA-FUJI



T20230719114745



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0741-06 2023/07/19 2.82UT TOYOKAWA-KISO



F20230719114747



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0741-06 2023/07/19 2.82UT FUJI -KISO



T20230719120503




BLK:15,SNR1: 19.001 ,SNR2: 35.711





3C190 2023/07/19 3.11UT TOYOKAWA-FUJI

F20230719120505



BLK:15,SNR1: 0.70206 ,SNR2: 7.3344



T20230719120503



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C190 2023/07/19 3.11UT TOYOKAWA-KISO



F20230719120505





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C190 2023/07/19 3.11UT FUJI -KISO




T20230719121727




BLK:10,SNR1: 0.43222 ,SNR2: 7.0883




F20230719121729



BLK:10,SNR1: 0.67413E-01,SNR2: 2.0139




3C196 2023/07/19 3.32UT TOYOKAWA-FUJI





T20230719121727




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C196 2023/07/19 3.32UT TOYOKAWA-KISO



F20230719121729





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C196 2023/07/19 3.32UT FUJI -KISO




T20230719122837




BLK:12,SNR1: 0.40244 ,SNR2: 4.3214




F20230719122839



BLK:12,SNR1: 7.5787 ,SNR2: 19.624



0821+394 2023/07/19 3.51UT TOYOKAWA-FUJI



T20230719122837



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

0821+394 2023/07/19 3.51UT TOYOKAWA-KISO



F20230719122839




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0821+394 2023/07/19 3.51UT FUJI -KISO



T20230719124524





BLK:11,SNR1: 32.240 ,SNR2: 50.796





0839-071 2023/07/19 3.78UT TOYOKAWA-FUJI

F20230719124526



BLK:11,SNR1: 2.0137 ,SNR2: 11.519



T20230719124524



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0839-071 2023/07/19 3.78UT TOYOKAWA-KISO





F20230719124526




No.Good Data




KISO



No.Good Data





0839-071 2023/07/19 3.78UT FUJI -KISO







T20230719125624




BLK:13,SNR1: 0.26574 ,SNR2: 3.3151




F20230719125626



BLK:13,SNR1: 48.950 ,SNR2: 52.566



3C208 2023/07/19 3.97UT TOYOKAWA-FUJI



T20230719125624



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


3C208 2023/07/19 3.97UT TOYOKAWA-KISO



F20230719125626



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2023/07/19 3.97UT FUJI -KISO



T20230719131305





BLK:17,SNR1: 0.14457 ,SNR2: 2.2645





3C216 2023/07/19 4.25UT TOYOKAWA-FUJI



F20230719131307




BLK:17,SNR1: 2.6547 ,SNR2: 10.265



T20230719131305





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C216 2023/07/19 4.25UT TOYOKAWA-KISO



F20230719131307





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C216 2023/07/19 4.25UT FUJI -KISO




T20230719133156




BLK: 8,SNR1: 0.25502E-03,SNR2: 0.46112




F20230719133158



BLK: 8,SNR1: 54.583 ,SNR2: 54.857




0926+117 2023/07/19 4.56UT TOYOKAWA-FUJI



T20230719133156



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0926+117 2023/07/19 4.56UT TOYOKAWA-KISO





F20230719133158





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0926+117 2023/07/19 4.56UT FUJI -KISO





T20230719133941




BLK:10,SNR1: 0.34109 ,SNR2: 3.4077




F20230719133943





BLK:10,SNR1: 6.2057 ,SNR2: 35.619






3C222 2023/07/19 4.69UT TOYOKAWA-FUJI




T20230719133941




KISO




3C222 2023/07/19 4.69UT TOYOKAWA-KISO



F20230719133943





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C222 2023/07/19 4.69UT FUJI -KISO




T20230719134641




BLK: 4,SNR1: 0.23285 ,SNR2: 1.3094




F20230719134643





BLK: 4,SNR1: 0.68110 ,SNR2: 2.6058



0941-08 2023/07/19 4.81UT TOYOKAWA-FUJI



T20230719134641





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0941-08 2023/07/19 4.81UT TOYOKAWA-KISO



F20230719134643





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0941-08 2023/07/19 4.81UT FUJI -KISO





T20230719135503




BLK:16,SNR1: 0.16936 ,SNR2: 0.98278




F20230719135505



BLK:16,SNR1: 1.3849 ,SNR2: 9.8105




3C230 2023/07/19 4.95UT TOYOKAWA-FUJI





T20230719135503





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C230 2023/07/19 4.95UT TOYOKAWA-KISO



F20230719135505





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C230 2023/07/19 4.95UT FUJI -KISO





T20230719140909




BLK:12,SNR1: 0.33030 ,SNR2: 0.91731




F20230719140911




BLK:12,SNR1: 0.52045E-01,SNR2: 1.6995



3C236 2023/07/19 5.18UT TOYOKAWA-FUJI



T20230719140909




No.Good Data




Frequency (Hz)

KISO



No.Good Data






Frequency (Hz)




3C236 2023/07/19 5.18UT TOYOKAWA-KISO




F20230719140911





KISO




3C236 2023/07/19 5.18UT FUJI -KISO





T20230719141720




BLK: 3,SNR1: 0.52777E-01,SNR2: 0.42239




F20230719141722




BLK: 3,SNR1: 4.6296 ,SNR2: 12.385




1011+110 2023/07/19 5.32UT TOYOKAWA-FUJI



T20230719141720





KISO




1011+110 2023/07/19 5.32UT TOYOKAWA-KISO



F20230719141722





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1011+110 2023/07/19 5.32UT FUJI -KISO








T20230719142500




BLK: 5,SNR1: 0.16392 ,SNR2: 1.3104




F20230719142502



BLK: 5,SNR1: 0.29714E-02,SNR2: 1.0053



3C241 2023/07/19 5.44UT TOYOKAWA-FUJI



T20230719142500



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C241 2023/07/19 5.44UT TOYOKAWA-KISO





F20230719142502




No.Good Data




KISO





No.Good Data




3C241 2023/07/19 5.44UT FUJI -KISO



T20230719143630





BLK: 5,SNR1:-0.10613 ,SNR2: 0.91010




Frequency (Hz)

F20230719143632




BLK: 5,SNR1: 1.3369 ,SNR2: 3.3153





Frequency (Hz)

1031-11 2023/07/19 5.64UT TOYOKAWA-FUJI





T20230719143630




No.Good Data




KISO



No.Good Data



1031-11 2023/07/19 5.64UT TOYOKAWA-KISO



F20230719143632




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1031-11 2023/07/19 5.64UT FUJI -KISO



T20230719144104





BLK: 2,SNR1: 2.6174 ,SNR2: 10.228




Frequency (Hz)

F20230719144106




BLK: 2,SNR1: 0.26724 ,SNR2: 2.7658




Frequency (Hz)

1035-058 2023/07/19 5.71UT TOYOKAWA-FUJI



T20230719144104




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1035-058 2023/07/19 5.71UT TOYOKAWA-KISO





F20230719144106




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1035-058 2023/07/19 5.71UT FUJI -KISO




T20230719145016




BLK: 5,SNR1:-0.51403E-01,SNR2: 0.95587




F20230719145018





BLK: 5,SNR1: 3.5175 ,SNR2: 7.8400



1044-008 2023/07/19 5.87UT TOYOKAWA-FUJI



T20230719145016





No.Good Data



Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1044-008 2023/07/19 5.87UT TOYOKAWA-KISO




F20230719145018





KISO




1044-008 2023/07/19 5.87UT FUJI -KISO





T20230719150121




BLK: 4,SNR1: 0.98067E-01,SNR2: 0.90317




F20230719150123



BLK: 4,SNR1: 0.26314 ,SNR2: 3.7165



1055+01 2023/07/19 6.05UT TOYOKAWA-FUJI



T20230719150121




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1055+01 2023/07/19 6.05UT TOYOKAWA-KISO



F20230719150123





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1055+01 2023/07/19 6.05UT FUJI -KISO




T20230719151238




BLK: 2,SNR1: 0.21520E-01,SNR2: 0.34586




F20230719151240



BLK: 2,SNR1: 0.13287 ,SNR2: 0.97375






1107+109 2023/07/19 6.24UT TOYOKAWA-FUJI








T20230719151238






KISO






1107+109 2023/07/19 6.24UT TOYOKAWA-KISO




F20230719151240





KISO




1107+109 2023/07/19 6.24UT FUJI -KISO




T20230719152216




BLK: 9,SNR1: 0.28643 ,SNR2: 2.0226




F20230719152218




BLK: 9,SNR1: 6.1087 ,SNR2: 13.373




3C255 2023/07/19 6.40UT TOYOKAWA-FUJI



T20230719152216




KISO




3C255 2023/07/19 6.40UT TOYOKAWA-KISO



F20230719152218





KISO




3C255 2023/07/19 6.40UT FUJI -KISO





T20230719154614




BLK: 8,SNR1: 0.78074E-01,SNR2: 1.9033




F20230719154616



BLK: 8,SNR1: 0.28538 ,SNR2: 2.3186



3C263.1 2023/07/19 6.80UT TOYOKAWA-FUJI



T20230719154614




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


3C263.1 2023/07/19 6.80UT TOYOKAWA-KISO



F20230719154616




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C263.1 2023/07/19 6.80UT FUJI -KISO







T20230719155241




BLK:26,SNR1: 3.0988 ,SNR2: 12.605




F20230719155243




BLK:26,SNR1: 3.5422 ,SNR2: 13.955




3C267 2023/07/19 6.91UT TOYOKAWA-FUJI



T20230719155241




KISO




3C267 2023/07/19 6.91UT TOYOKAWA-KISO



F20230719155243



No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C267 2023/07/19 6.91UT FUJI -KISO





T20230719161155




BLK: 6,SNR1: 0.27294E-01,SNR2: 0.30077




F20230719161157






BLK: 6,SNR1: 10.290 ,SNR2: 16.057






1206+439 2023/07/19 7.23UT TOYOKAWA-FUJI




T20230719161155






KISO






1206+439 2023/07/19 7.23UT TOYOKAWA-KISO




F20230719161157





KISO




1206+439 2023/07/19 7.23UT FUJI -KISO




T20230719163146




BLK:19,SNR1: 158.66 ,SNR2: 200.07




F20230719163148






BLK:19,SNR1: 0.39225 ,SNR2: 4.4736






3C273 2023/07/19 7.56UT TOYOKAWA-FUJI




T20230719163146



KISO






3C273 2023/07/19 7.56UT TOYOKAWA-KISO








F20230719163148





KISO




3C273 2023/07/19 7.56UT FUJI -KISO





T20230719164456




BLK:17,SNR1: 96.458 ,SNR2: 120.86




F20230719164458






BLK:17,SNR1: 67.321 ,SNR2: 78.550






3C275 2023/07/19 7.78UT TOYOKAWA-FUJI




T20230719164456





KISO





3C275 2023/07/19 7.78UT TOYOKAWA-KISO




F20230719164458





KISO




3C275 2023/07/19 7.78UT FUJI -KISO



T20230719171833





BLK:16,SNR1: 1.3223 ,SNR2: 3.9522




Frequency (Hz)

F20230719171835




BLK:16,SNR1: 13.021 ,SNR2: 37.716






Frequency (Hz)




1313+453 2023/07/19 8.34UT TOYOKAWA-FUJI




T20230719171833





KISO






1313+453 2023/07/19 8.34UT TOYOKAWA-KISO




F20230719171835





KISO




1313+453 2023/07/19 8.34UT FUJI -KISO



T20230719172839




BLK: 5,SNR1: 0.50068E-01,SNR2: 0.69103




Frequency (Hz)

F20230719172841




BLK: 5,SNR1: 0.18484 ,SNR2: 2.5984





Frequency (Hz)

1323+32 2023/07/19 8.51UT TOYOKAWA-FUJI






T20230719172839





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2023/07/19 8.51UT TOYOKAWA-KISO



F20230719172841





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2023/07/19 8.51UT FUJI -KISO



T20230719173330





BLK:16,SNR1: 0.50229 ,SNR2: 1.9708




Frequency (Hz)

F20230719173332




BLK:16,SNR1: 2.1737 ,SNR2: 4.1704




Frequency (Hz)


3C286 2023/07/19 8.59UT TOYOKAWA-FUJI



T20230719173330





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C286 2023/07/19 8.59UT TOYOKAWA-KISO



F20230719173332





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C286 2023/07/19 8.59UT FUJI -KISO



T20230719173952




BLK: 7,SNR1: 0.16668 ,SNR2: 1.1310




Frequency (Hz)

F20230719173954




BLK: 7,SNR1: 0.44012 ,SNR2: 1.6628





Frequency (Hz)


1335+479 2023/07/19 8.69UT TOYOKAWA-FUJI



T20230719173952




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1335+479 2023/07/19 8.69UT TOYOKAWA-KISO



F20230719173954




No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1335+479 2023/07/19 8.69UT FUJI -KISO

