




T20230723054424





BLK: 1,SNR1: 0.20021E-01,SNR2: 0.47796




Frequency (Hz)

F20230723054426




BLK: 1,SNR1: 1.3031 ,SNR2: 2.8013





Frequency (Hz)


0152+435 2023/07/22 20.77UT TOYOKAWA-FUJI



T20230723054424




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0152+435 2023/07/22 20.77UT TOYOKAWA-KISO



F20230723054426



No.Good Data




KISO





No.Good Data




0152+435 2023/07/22 20.77UT FUJI -KISO



T20230723061257




BLK: 7,SNR1: 0.76196E-01,SNR2: 0.45094




Frequency (Hz)

3C67 2023/07/22 21.24UT TOYOKAWA-FUJI


F20230723061259



BLK: 7,SNR1: 0.10793 ,SNR2: 1.6153



Frequency (Hz)



T20230723061257



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C67 2023/07/22 21.24UT TOYOKAWA-KISO



F20230723061259



No.Good Data




KISO





No.Good Data




3C67 2023/07/22 21.24UT FUJI -KISO



T20230723065026




BLK: 4,SNR1: 0.38245E-01,SNR2: 0.64157




Frequency (Hz)

F20230723065028




BLK: 4,SNR1: 0.42763 ,SNR2: 5.6224



Frequency (Hz)

0258+350 2023/07/22 21.87UT TOYOKAWA-FUJI




T20230723065026



No.Good Data




KISO



No.Good Data



0258+350 2023/07/22 21.87UT TOYOKAWA-KISO





F20230723065028



No.Good Data



KISO





No.Good Data




0258+350 2023/07/22 21.87UT FUJI -KISO



T20230723070016




BLK: 4,SNR1: 0.14151 ,SNR2: 0.39868




Frequency (Hz)

F20230723070018




BLK: 4,SNR1: 2.0105 ,SNR2: 4.9727




Frequency (Hz)


0308+305 2023/07/22 22.03UT TOYOKAWA-FUJI



T20230723070016




No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0308+305 2023/07/22 22.03UT TOYOKAWA-KISO



F20230723070018




No.Good Data



KISO





No.Good Data




0308+305 2023/07/22 22.03UT FUJI -KISO



T20230723071148





BLK: 2,SNR1:-0.20061E-01,SNR2: 0.64100




Frequency (Hz)

F20230723071150




BLK: 2,SNR1: 0.31349 ,SNR2: 7.3091




Frequency (Hz)


0320+05 2023/07/22 22.22UT TOYOKAWA-FUJI



T20230723071148





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0320+05 2023/07/22 22.22UT TOYOKAWA-KISO





F20230723071150




No.Good Data



KISO





No.Good Data




0320+05 2023/07/22 22.22UT FUJI -KISO



T20230723072509




BLK: 1,SNR1: 0.61498E-01,SNR2: 1.4079




Frequency (Hz)

F20230723072511




BLK: 1,SNR1: 4.9967 ,SNR2: 20.912




Frequency (Hz)

0333+32 2023/07/22 22.45UT TOYOKAWA-FUJI






T20230723072509





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0333+32 2023/07/22 22.45UT TOYOKAWA-KISO



F20230723072511



No.Good Data



KISO





No.Good Data




0333+32 2023/07/22 22.45UT FUJI -KISO



T20230723073811





BLK: 3,SNR1: 0.27467 ,SNR2: 0.76941




Frequency (Hz)

F20230723073813




BLK: 3,SNR1: 1.2008 ,SNR2: 2.0433





Frequency (Hz)


0347+05 2023/07/22 22.66UT TOYOKAWA-FUJI




T20230723073811



No.Good Data




KISO



No.Good Data



0347+05 2023/07/22 22.66UT TOYOKAWA-KISO



F20230723073813





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0347+05 2023/07/22 22.66UT FUJI -KISO



T20230723075346





BLK: 4,SNR1:-0.53272E-01,SNR2: 0.19980




Frequency (Hz)

F20230723075348




BLK: 4,SNR1:-0.95201E-01,SNR2: 1.7823





Frequency (Hz)


0403-132 2023/07/22 22.92UT TOYOKAWA-FUJI



T20230723075346



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0403-132 2023/07/22 22.92UT TOYOKAWA-KISO



F20230723075348





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0403-132 2023/07/22 22.92UT FUJI -KISO






T20230723080256





BLK: 5,SNR1:-0.18622 ,SNR2: 0.32463




Frequency (Hz)

F20230723080258




BLK: 5,SNR1: 0.90485 ,SNR2: 2.4020



Frequency (Hz)


0411+05 2023/07/22 23.08UT TOYOKAWA-FUJI



T20230723080256



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0411+05 2023/07/22 23.08UT TOYOKAWA-KISO




F20230723080258



No.Good Data




KISO





No.Good Data




0411+05 2023/07/22 23.08UT FUJI -KISO



T20230723080950





BLK: 4,SNR1: 0.19581 ,SNR2: 1.2680




Frequency (Hz)

F20230723080952




BLK: 4,SNR1: 0.18482 ,SNR2: 0.97921





Frequency (Hz)


0418+236 2023/07/22 23.19UT TOYOKAWA-FUJI





T20230723080950




No.Good Data




KISO





No.Good Data



0418+236 2023/07/22 23.19UT TOYOKAWA-KISO



F20230723080952





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0418+236 2023/07/22 23.19UT FUJI -KISO



T20230723082116




BLK:10,SNR1: 0.50384 ,SNR2: 5.0407




Frequency (Hz)

3C119 2023/07/22 23.38UT TOYOKAWA-FUJI


F20230723082118



BLK:10,SNR1: 0.44158 ,SNR2: 4.1682




Frequency (Hz)





T20230723082116




No.Good Data




KISO



No.Good Data





3C119 2023/07/22 23.38UT TOYOKAWA-KISO






F20230723082118





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C119 2023/07/22 23.38UT FUJI -KISO



T20230723085337





BLK: 4,SNR1: 0.16688 ,SNR2: 0.37129




Frequency (Hz)

F20230723085339




BLK: 4,SNR1: 4.6010 ,SNR2: 10.194



Frequency (Hz)


0501+312 2023/07/22 23.92UT TOYOKAWA-FUJI



T20230723085337





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0501+312 2023/07/22 23.92UT TOYOKAWA-KISO





F20230723085339




No.Good Data




KISO





No.Good Data




0501+312 2023/07/22 23.92UT FUJI -KISO



T20230723090924





BLK:19,SNR1: 0.37765 ,SNR2: 1.9162




Frequency (Hz)

3C138 2023/07/23 0.18UT TOYOKAWA-FUJI


F20230723090926





BLK:19,SNR1: 0.27326 ,SNR2: 1.6748




Frequency (Hz)




T20230723090924




No. Good Data




KISO




No. Good Data




3C138 2023/07/23 0.18UT TOYOKAWA-KISO




F20230723090926




No.Good Data



KISO





No.Good Data




3C138 2023/07/23 0.18UT FUJI -KISO



T20230723092258





BLK:13,SNR1: 0.39778 ,SNR2: 5.4745




Frequency (Hz)

F20230723092300




BLK:13,SNR1: 0.67349 ,SNR2: 2.0945





Frequency (Hz)

0531+194 2023/07/23 0.41UT TOYOKAWA-FUJI








T20230723092258




No.Good Data



KISO





No.Good Data




0531+194 2023/07/23 0.41UT TOYOKAWA-KISO





F20230723092300




No.Good Data




KISO





No.Good Data




0531+194 2023/07/23 0.41UT FWJI -KISO



T20230723093116





BLK:21,SNR1: 6.2181 ,SNR2: 46.841




Frequency (Hz)

3C147 2023/07/23 0.55UT TOYOKAWA-FUJI


F20230723093116




BLK:21,SNR1: 0.16499 ,SNR2: 2.5632




Frequency (Hz)




T20230723093116




No. Good Data



KISO




No. Good Data



3C147 2023/07/23 0.55UT TOYOKAWA-KISO




F20230723093118




No.Good Data




KISO





No.Good Data




3C147 2023/07/23 0.55UT FUJI -KISO





T20230723093929




BLK: 6,SNR1: 0.19357 ,SNR2: 0.51766




F20230723093931



BLK: 6,SNR1: 0.39971 ,SNR2: 1.5897



0548+16 2023/07/23 0.69UT TOYOKAWA-FUJI



T20230723093929



No.Good Data



KISO




No.Good Data



0548+16 2023/07/23 0.69UT TOYOKAWA-KISO




F20230723093931




No.Good Data



KISO



No.Good Data





0548+16 2023/07/23 0.69UT FUJI -KISO







T20230723094340




BLK:10,SNR1: 2.5495 ,SNR2: 9.6159




F20230723094342




BLK:10,SNR1: 0.33587 ,SNR2: 1.4400



0552+12 2023/07/23 0.76UT TOYOKAWA-FUJI



T20230723094340




No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0552+12 2023/07/23 0.76UT TOYOKAWA-KISO





F20230723094342




No.Good Data



KISO




No.Good Data




0552+12 2023/07/23 0.76UT FUJI -KISO




T20230723094806




BLK: 2,SNR1: 0.24178 ,SNR2: 1.2262




F20230723094808




BLK: 2,SNR1: 1.0977 ,SNR2: 3.3285




0556+191 2023/07/23 0.83UT TOYOKAWA-FUJI




T20230723094806




No. Good Data



KISO



No. Good Data



0556+191 2023/07/23 0.83UT TOYOKAWA-KISO




F20230723094808




No. Good Data




KISO




No. Good Data




0556+191 2023/07/23 0.83UT FUJI -KISO




T20230723095553




BLK: 3,SNR1:-0.63917E-01,SNR2: 0.55873




F20230723095555



BLK: 3,SNR1:-0.11432E-01,SNR2: 1.0912



0605-08 2023/07/23 0.96UT TOYOKAWA-FUJI




T20230723095553



No. Good Data



KISO



No. Good Data



0605-08 2023/07/23 0.96UT TOYOKAWA-KISO





F20230723095555



No.Good Data



KISO




No.Good Data




0605-08 2023/07/23 0.96UT FUJI -KISO



T20230723101501





BLK:15,SNR1: 0.87421 ,SNR2: 11.390





3C161 2023/07/23 1.28UT TOYOKAWA-FUJI

F20230723101503




BLK:15,SNR1: 2.9365 ,SNR2: 11.623



T20230723101501



No. Good Data




Frequency (Hz)

KISO



No. Good Data



Frequency (Hz)

3C161 2023/07/23 1.28UT TOYOKAWA-KISO



F20230723101503





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/07/23 1.28UT FUJI -KISO





T20230723104234




BLK: 3,SNR1: 0.11830 ,SNR2: 3.6409




F20230723104236



BLK: 3,SNR1: 0.11323 ,SNR2: 1.8918



0652-130 2023/07/23 1.74UT TOYOKAWA-FUJI




T20230723104234




No.Good Data




KISO



No.Good Data



0652-130 2023/07/23 1.74UT TOYOKAWA-KISO





F20230723104236




No.Good Data



KISO




No.Good Data




0652-130 2023/07/23 1.74UT FUJI -KISO





T20230723105409




BLK: 8,SNR1: 4.9867 ,SNR2: 18.826




F20230723105411



BLK: 8,SNR1: 5.1024 ,SNR2: 31.201



0703+138 2023/07/23 1.93UT TOYOKAWA-FUJI





T20230723105409



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0703+138 2023/07/23 1.93UT TOYOKAWA-KISO



F20230723105411



No. Good Data




KISO





No. Good Data




0703+138 2023/07/23 1.93UT FUJI -KISO





T20230723110333




BLK: 7,SNR1: 0.24869 ,SNR2: 2.2325




F20230723110335



BLK: 7,SNR1: 0.23039E-01,SNR2: 1.4619




0713-024 2023/07/23 2.09UT TOYOKAWA-FUJI



T20230723110333





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0713-024 2023/07/23 2.09UT TOYOKAWA-KISO



F20230723110335





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0713-024 2023/07/23 2.09UT FUJI -KISO



T20230723111344




BLK:15,SNR1: 0.87528 ,SNR2: 7.2135





0723+10 2023/07/23 2.26UT TOYOKAWA-FUJI

F20230723111346




BLK:15,SNR1: 0.80900E-01,SNR2: 0.55809



T20230723111344





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0723+10 2023/07/23 2.26UT TOYOKAWA-KISO



F20230723111346



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0723+10 2023/07/23 2.26UT FUJI -KISO






T20230723112358




BLK:15,SNR1: 0.34337 ,SNR2: 4.5673




Frequency (Hz)

F20230723112400




BLK:15,SNR1: 0.79028E-01,SNR2: 1.1823



Frequency (Hz)

0732+33 2023/07/23 2.43UT TOYOKAWA-FUJI



T20230723112358



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0732+33 2023/07/23 2.43UT TOYOKAWA-KISO





F20230723112400




No.Good Data




KISO




No.Good Data




0732+33 2023/07/23 2.43UT FUJI -KISO



T20230723113201




BLK:20,SNR1: 1.6139 ,SNR2: 6.1229





0741-06 2023/07/23 2.56UT TOYOKAWA-FUJI


F20230723113203



BLK:20,SNR1:-0.72375E-01,SNR2: 1.8939



T20230723113201




No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0741-06 2023/07/23 2.56UT TOYOKAWA-KISO





F20230723113203




No.Good Data




KISO





No.Good Data




0741-06 2023/07/23 2.56UT FUJI -KISO




T20230723114920




BLK:17,SNR1: 8.2619 ,SNR2: 14.224




F20230723114922




BLK:17,SNR1: 0.40196 ,SNR2: 2.6676



3C190 2023/07/23 2.85UT TOYOKAWA-FUJI



T20230723114920





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C190 2023/07/23 2.85UT TOYOKAWA-KISO






F20230723114922





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C190 2023/07/23 2.85UT FUJI -KISO




T20230723120143




BLK:27,SNR1: 3.7163 ,SNR2: 9.5828




F20230723120145



BLK:27,SNR1: 0.24369 ,SNR2: 1.6756



3C196 2023/07/23 3.06UT TOYOKAWA-FUJI



T20230723120143



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C196 2023/07/23 3.06UT TOYOKAWA-KISO



F20230723120145



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C196 2023/07/23 3.06UT FUJI -KISO





T20230723121253




BLK:12,SNR1: 0.98460 ,SNR2: 2.9310




F20230723121255



BLK:12,SNR1: 0.76210 ,SNR2: 2.5246



0821+394 2023/07/23 3.24UT TOYOKAWA-FUJI



T20230723121253



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0821+394 2023/07/23 3.24UT TOYOKAWA-KISO





F20230723121255




No.Good Data




KISO




No.Good Data




0821+394 2023/07/23 3.24UT FUJI -KISO



T20230723122940




BLK: 6,SNR1: 3.5339 ,SNR2: 27.721




0839-071 2023/07/23 3.52UT TOYOKAWA-FUJI


F20230723122942



BLK: 6,SNR1: 1.0642 ,SNR2: 2.7854



Frequency (Hz)





T20230723122940




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0839-071 2023/07/23 3.52UT TOYOKAWA-KISO





F20230723122942




No.Good Data




KISO




No.Good Data




0839-071 2023/07/23 3.52UT FUJI -KISO




T20230723124041




BLK: 8,SNR1: 0.92524 ,SNR2: 5.2735




F20230723124043



BLK: 8,SNR1: 2.6082 ,SNR2: 26.515



3C208 2023/07/23 3.71UT TOYOKAWA-FUJI



T20230723124041



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C208 2023/07/23 3.71UT TOYOKAWA-KISO



F20230723124043





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C208 2023/07/23 3.71UT FUJI -KISO




T20230723125721




BLK:11,SNR1: 0.39730 ,SNR2: 5.6076




F20230723125723



BLK:11,SNR1: 0.11936 ,SNR2: 2.0221



3C216 2023/07/23 3.98UT TOYOKAWA-FUJI



T20230723125721



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C216 2023/07/23 3.98UT TOYOKAWA-KISO



F20230723125723





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C216 2023/07/23 3.98UT FUJI -KISO








T20230723131612




BLK:11,SNR1: 0.19714 ,SNR2: 0.91083




F20230723131614





BLK:11,SNR1: 0.53202 ,SNR2: 1.2360




0926+117 2023/07/23 4.30UT TOYOKAWA-FUJI



T20230723131612





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0926+117 2023/07/23 4.30UT TOYOKAWA-KISO



F20230723131614



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0926+117 2023/07/23 4.30UT FUJI -KISO





T20230723132357




BLK:14,SNR1: 0.43899 ,SNR2: 3.0652




F20230723132359





BLK:14,SNR1: 1.1191 ,SNR2: 5.1066




3C222 2023/07/23 4.43UT TOYOKAWA-FUJI



T20230723132357





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C222 2023/07/23 4.43UT TOYOKAWA-KISO



F20230723132359



No. Good Data




Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


3C222 2023/07/23 4.43UT FUJI -KISO



T20230723133058





BLK:10,SNR1: 0.69949 ,SNR2: 3.2211





0941-08 2023/07/23 4.54UT TOYOKAWA-FUJI

F20230723133100




BLK:10,SNR1: 2.0938 ,SNR2: 8.3907



T20230723133058



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0941-08 2023/07/23 4.54UT TOYOKAWA-KISO





F20230723133100





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


0941-08 2023/07/23 4.54UT FUJI -KISO




T20230723133919




BLK:21,SNR1: 5.1561 ,SNR2: 10.679




F20230723133921





BLK:21,SNR1: 0.53718 ,SNR2: 6.1805




3C230 2023/07/23 4.68UT TOYOKAWA-FUJI



T20230723133919





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C230 2023/07/23 4.68UT TOYOKAWA-KISO



F20230723133921





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C230 2023/07/23 4.68UT FUJI -KISO




T20230723135326




BLK:13,SNR1: 3.5964 ,SNR2: 13.359




F20230723135328





BLK:13,SNR1: 18.605 ,SNR2: 27.663




3C236 2023/07/23 4.92UT TOYOKAWA-FUJI



T20230723135326




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C236 2023/07/23 4.92UT TOYOKAWA-KISO



F20230723135328





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C236 2023/07/23 4.92UT FUJI -KISO



T20230723140136





BLK:32,SNR1: 11.873 ,SNR2: 26.881





1011+110 2023/07/23 5.05UT TOYOKAWA-FUJI

F20230723140138




BLK:32,SNR1: 3.5004 ,SNR2: 13.816





T20230723140136





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1011+110 2023/07/23 5.05UT TOYOKAWA-KISO



F20230723140138





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1011+110 2023/07/23 5.05UT FUJI -KISO





T20230723140917




BLK: 8,SNR1: 4.4460 ,SNR2: 8.9787




F20230723140919




BLK: 8,SNR1: 9.1059 ,SNR2: 19.901




3C241 2023/07/23 5.18UT TOYOKAWA-FUJI



T20230723140917




No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C241 2023/07/23 5.18UT TOYOKAWA-KISO



F20230723140919



No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


3C241 2023/07/23 5.18UT FUJI -KISO





T20230723142047




BLK:19,SNR1: 3.3562 ,SNR2: 13.518




F20230723142049




BLK:19,SNR1: 1.7426 ,SNR2: 7.2775




1031-11 2023/07/23 5.37UT TOYOKAWA-FUJI



T20230723142047



KISO



1031-11 2023/07/23 5.37UT TOYOKAWA-KISO



F20230723142049





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1031-11 2023/07/23 5.37UT FUJI -KISO








T20230723142520




BLK:29,SNR1: 11.671 ,SNR2: 18.116




F20230723142522





BLK:29,SNR1: 9.4220 ,SNR2: 14.708




1035-058 2023/07/23 5.45UT TOYOKAWA-FUJI



T20230723142520





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/07/23 5.45UT TOYOKAWA-KISO



F20230723142522





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1035-058 2023/07/23 5.45UT FUJI -KISO





T20230723143433




BLK:29,SNR1: 3.2235 ,SNR2: 13.057




F20230723143435





BLK:29,SNR1: 8.3528 ,SNR2: 18.354




1044-008 2023/07/23 5.60UT TOYOKAWA-FUJI



T20230723143433





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1044-008 2023/07/23 5.60UT TOYOKAWA-KISO



F20230723143435





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1044-008 2023/07/23 5.60UT FUJI -KISO





T20230723144537




BLK:37,SNR1: 27.903 ,SNR2: 44.084




F20230723144539






BLK:37,SNR1: 9.4523 ,SNR2: 20.100






1055+01 2023/07/23 5.79UT TOYOKAWA-FUJI




T20230723144537



KISO




1055+01 2023/07/23 5.79UT TOYOKAWA-KISO






F20230723144539




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1055+01 2023/07/23 5.79UT FUJI -KISO





T20230723145655




BLK:31,SNR1: 19.134 ,SNR2: 29.364




F20230723145657




BLK:31,SNR1: 11.851 ,SNR2: 26.848




1107+109 2023/07/23 5.98UT TOYOKAWA-FUJI



T20230723145655




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1107+109 2023/07/23 5.98UT TOYOKAWA-KISO



F20230723145657




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1107+109 2023/07/23 5.98UT FUJI -KISO





T20230723150632




BLK:18,SNR1: 4.6887 ,SNR2: 7.2111




F20230723150634



BLK:18,SNR1: 4.9274 ,SNR2: 9.9686



3C255 2023/07/23 6.14UT TOYOKAWA-FUJI



T20230723150632




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C255 2023/07/23 6.14UT TOYOKAWA-KISO



F20230723150634





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C255 2023/07/23 6.14UT FUJI -KISO



T20230723153030





BLK:14,SNR1: 0.54674 ,SNR2: 2.4629




Frequency (Hz)

F20230723153032




BLK:14,SNR1: 0.83834 ,SNR2: 3.6207




Frequency (Hz)

3C263.1 2023/07/23 6.54UT TOYOKAWA-FUJI






T20230723153030





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C263.1 2023/07/23 6.54UT TOYOKAWA-KISO



F20230723153032




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C263.1 2023/07/23 6.54UT FUJI -KISO





T20230723153657




BLK: 8,SNR1: 0.56429 ,SNR2: 2.0347




F20230723153659



BLK: 8,SNR1: 7.9324 ,SNR2: 16.838




3C267 2023/07/23 6.64UT TOYOKAWA-FUJI





T20230723153657




No.Good Data




KISO






No.Good Data






3C267 2023/07/23 6.64UT TOYOKAWA-KISO



F20230723153659





KISO




3C267 2023/07/23 6.64UT FUJI -KISO





T20230723155611




BLK:12,SNR1: 2.8984 ,SNR2: 11.284




F20230723155613




BLK:12,SNR1: 4.4051 ,SNR2: 9.0368



1206+439 2023/07/23 6.96UT TOYOKAWA-FUJI



T20230723155611




No.Good Data



Frequency (Hz)

KISO



No.Good Data






Frequency (Hz)




1206+439 2023/07/23 6.96UT TOYOKAWA-KISO




F20230723155613



KISO




1206+439 2023/07/23 6.96UT FUJI -KISO






T20230723161602




BLK:17,SNR1: 2.3600 ,SNR2: 9.1570




Frequency (Hz)

F20230723161604




BLK:17,SNR1: 0.45167 ,SNR2: 4.3696




Frequency (Hz)


3C273 2023/07/23 7.30UT TOYOKAWA-FUJI




T20230723161602






KISO






3C273 2023/07/23 7.30UT TOYOKAWA-KISO




F20230723161604





KISO




3C273 2023/07/23 7.30UT FUJI -KISO




T20230723162913




BLK:10,SNR1: 0.52278 ,SNR2: 1.1874




F20230723162915






BLK:10,SNR1: 1.1689 ,SNR2: 4.0159






3C275 2023/07/23 7.52UT TOYOKAWA-FUJI




T20230723162913






KISO






3C275 2023/07/23 7.52UT TOYOKAWA-KISO




F20230723162915




KISO




3C275 2023/07/23 7.52UT FUJI -KISO



T20230723164301




BLK: 7,SNR1: 1.3167 ,SNR2: 7.2600




Frequency (Hz)

F20230723164303




BLK: 7,SNR1: 0.53574E-01,SNR2: 1.8479






Frequency (Hz)




3C279 2023/07/23 7.75UT TOYOKAWA-FUJI




T20230723164301



KISO






3C279 2023/07/23 7.75UT TOYOKAWA-KISO








F20230723164303





KISO




3C279 2023/07/23 7.75UT FUJI -KISO





T20230723170250




BLK: 8,SNR1: 0.36926E-01,SNR2: 0.78898




F20230723170252






BLK: 8,SNR1: 13.641 ,SNR2: 21.373






1313+453 2023/07/23 8.08UT TOYOKAWA-FUJI



T20230723170250





KISO





1313+453 2023/07/23 8.08UT TOYOKAWA-KISO




F20230723170252





KISO




1313+453 2023/07/23 8.08UT FUJI -KISO




T20230723171256




BLK: 4,SNR1: 0.14950 ,SNR2: 0.79296




F20230723171258





BLK: 4,SNR1: 0.58552 ,SNR2: 3.5492




1323+32 2023/07/23 8.24UT TOYOKAWA-FUJI



T20230723171256





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1323+32 2023/07/23 8.24UT TOYOKAWA-KISO






F20230723171258




No.Good Data

KISO





No.Good Data


1323+32 2023/07/23 8.24UT FUJI -KISO





T20230723171746




BLK: 7,SNR1: 0.20840 ,SNR2: 2.6757




F20230723171748



BLK: 7,SNR1: 1.2216 ,SNR2: 4.1691






3C286 2023/07/23 8.32UT TOYOKAWA-FUJI








T20230723171746




No.Good Data

KISO





No.Good Data


3C286 2023/07/23 8.32UT TOYOKAWA-KISO





F20230723171748




No.Good Data



KISO



No.Good Data



3C286 2023/07/23 8.32UT FUJI -KISO

