






TOYOKAWA 0225+494 2023/08/07(219)05:18:43-05:22:09JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0232+411 2023/08/07(219)05:25:44-05:29:10JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0241+393 2023/08/07(219)05:34:18-05:37:44JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0246+428 2023/08/07(219)05:39:22-05:42:48JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0250+358 2023/08/07(219)05:43:10-05:46:36JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0258+350 2023/08/07(219)05:51:26-05:54:52JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0302+341 2023/08/07(219)05:55:22-05:58:48JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )









TOYOKAWA 0320+05 2023/08/07(219)06:12:48-06:16:14JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0324+119 2023/08/07(219)06:16:52-06:20:18JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0333+32 2023/08/07(219)06:26:08-06:29:34JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0347+05 2023/08/07(219)06:39:10-06:42:36JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0355+50 2023/08/07(219)06:49:22-06:52:48JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0403-132 2023/08/07(219)06:54:45-06:58:11JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0411+05 2023/08/07(219)07:03:55-07:07:21JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0418+236 2023/08/07(219)07:10:49-07:14:15JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0422+178 2023/08/07(219)07:14:48-07:18:14JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C119 2023/08/07(219)07:22:16-07:25:42JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C138 2023/08/07(219)08:10:24-08:13:50JST 175Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0531+194 2023/08/07(219)08:23:57-08:27:23JST 167Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C147 2023/08/07(219)08:32:16-08:35:42JST 172Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0548+16 2023/08/07(219)08:40:28-08:43:54JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0552+12 2023/08/07(219)08:44:39-08:48:05JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0556+191 2023/08/07(219)08:49:06-08:52:32JST 151Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C152 2023/08/07(219)08:53:38-08:57:04JST 148Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C158

2023/08/07(219)09:10:44-09:14:10JST 138Rs

6598+/- 639




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C161

2023/08/07(219)09:16:00-09:19:26JST 154Rs


6872+/- 53




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0652-130 2023/08/07(219)09:43:33-09:46:59JST 151Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0703+138 2023/08/07(219)09:55:09-09:58:35JST 105Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0713-024 2023/08/07(219)10:04:32-10:07:58JST 119Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0716+022 2023/08/07(219)10:08:12-10:11:38JST 108Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0723+10 2023/08/07(219)10:14:44-10:18:10JST 92Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0732+33 2023/08/07(219)10:24:58-10:28:24JST 95Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0741-06 2023/08/07(219)10:33:01-10:36:27JST 111Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0752-200 2023/08/07(219)10:42:45-10:46:11JST 142Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C190 2023/08/07(219)10:50:19-10:53:45JST 58Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0806-103 2023/08/07(219)10:57:25-11:00:51JST 110Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C196 2023/08/07(219)11:02:43-11:06:09JST 119Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0817+183 2023/08/07(219)11:09:28-11:12:54JST 41Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0821+394 2023/08/07(219)11:13:53-11:17:19JST 89Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0834-19 2023/08/07(219)11:25:34-11:29:00JST 131Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0839-071 2023/08/07(219)11:30:40-11:34:06JST 90Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C208 2023/08/07(219)11:41:40-11:45:06JST 15Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0857-191 2023/08/07(219)11:48:01-11:51:27JST 128Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C216 2023/08/07(219)11:58:21-12:01:47JST 96Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0912-132 2023/08/07(219)12:03:06-12:06:32JST 109Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0919-142 2023/08/07(219)12:10:33-12:13:59JST 113Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0926+117 2023/08/07(219)12:17:12-12:20:38JST 28Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C222 2023/08/07(219)12:24:57-12:28:23JST 53Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0941-08 2023/08/07(219)12:31:57-12:35:23JST 97Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C230 2023/08/07(219)12:40:19-12:43:45JST 74Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C236 2023/08/07(219)12:54:25-12:57:51JST 83Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1011+110 2023/08/07(219)13:02:36-13:06:02JST 65Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C241 2023/08/07(219)13:10:16-13:13:42JST 69Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1031-11 2023/08/07(219)13:21:46-13:25:12JST 127Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1035-058 2023/08/07(219)13:26:19-13:29:45JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1044-008 2023/08/07(219)13:35:32-13:38:58JST 110Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1055+01 2023/08/07(219)13:46:37-13:50:03JST 113Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1059-010 2023/08/07(219)13:50:13-13:53:39JST 120Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C255 2023/08/07(219)14:07:31-14:10:57JST 134Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1127-14 2023/08/07(219)14:18:09-14:21:35JST 160Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1136-13 2023/08/07(219)14:27:13-14:30:39JST 163Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C263.1 2023/08/07(219)14:31:29-14:34:55JST 132Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C267 2023/08/07(219)14:37:56-14:41:22JST 139Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1154+552 2023/08/07(219)14:45:21-14:48:47JST 167Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1206+439 2023/08/07(219)14:57:11-15:00:37JST 159Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1213-17 2023/08/07(219)15:03:44-15:07:10JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C273 2023/08/07(219)15:17:01-15:20:27JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C275 2023/08/07(219)15:30:12-15:33:38JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1245-19 2023/08/07(219)15:36:17-15:39:43JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 3C279


2023/08/07(219)15:44:01-15:47:27JST 190Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C283 2023/08/07(219)15:59:30-16:02:56JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1313+453 2023/08/07(219)16:03:49-16:07:15JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1323+32 2023/08/07(219)16:13:55-16:17:21JST 189Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C286 2023/08/07(219)16:18:45-16:22:11JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1334-17 2023/08/07(219)16:25:22-16:28:48JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1345+12 2023/08/07(219)16:35:12-16:38:38JST 201Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1355+01 2023/08/07(219)16:45:33-16:48:59JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 3C298


2023/08/07(219)17:06:44-17:10:10JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1428-03 2023/08/07(219)17:18:27-17:21:53JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1434+03 2023/08/07(219)17:24:29-17:27:55JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1452+16 2023/08/07(219)17:41:45-17:45:11JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1456+187 2023/08/07(219)17:45:57-17:49:23JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1504+323 2023/08/07(219)17:53:22-17:56:48JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1512+370 2023/08/07(219)18:01:54-18:05:20JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1522+546 2023/08/07(219)18:10:58-18:14:24JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1526+378 2023/08/07(219)18:15:35-18:19:01JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1536+574 2023/08/07(219)18:24:10-18:27:36JST 214Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1545+497 2023/08/07(219)18:34:13-18:37:39JST 216Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )

