




T20230817105123





BLK: 2,SNR1: 4.9848 ,SNR2: 22.691




Frequency (Hz)

0839-071 2023/08/17 1.88UT TOYOKAWA-FUJI


F20230817105127





BLK: 2,SNR1: 4.3951 ,SNR2: 10.755




Frequency (Hz)



T20230817105123




No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0839-071 2023/08/17 1.88UT TOYOKAWA-KISO



F20230817105127



No.Good Data



KISO





No.Good Data




0839-071 2023/08/17 1.88UT FUJI -KISO



T20230817110223




BLK:33,SNR1: 2.5776 ,SNR2: 8.5461




Frequency (Hz)

F20230817110223




BLK:33,SNR1: 12.995 ,SNR2: 29.267





Frequency (Hz)


3C208 2023/08/17 2.07UT TOYOKAWA-FUJI




T20230817110223



No.Good Data




KISO




No.Good Data



3C208 2023/08/17 2.07UT TOYOKAWA-KISO



F20230817110223




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2023/08/17 2.07UT FUJI -KISO



T20230817111904





BLK:10,SNR1: 3.2098 ,SNR2: 11.949




Frequency (Hz)

3C216 2023/08/17 2.35UT TOYOKAWA-FUJI


F20230817111905




BLK:10,SNR1: 0.59448E-01,SNR2: 0.77155



Frequency (Hz)



T20230817111904



No.Good Data




KISO



No.Good Data



3C216 2023/08/17 2.35UT TOYOKAWA-KISO





F20230817111905



No.Good Data



KISO





No.Good Data




3C216 2023/08/17 2.35UT FUJI -KISO



T20230817113755





BLK:37,SNR1: 111.13 ,SNR2: 188.02




Frequency (Hz)

F20230817113756




BLK:37,SNR1: 3.9371 ,SNR2: 15.312




Frequency (Hz)


0926+117 2023/08/17 2.66UT TOYOKAWA-FUJI



T20230817113755



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0926+117 2023/08/17 2.66UT TOYOKAWA-KISO



F20230817113756




No.Good Data



KISO





No.Good Data




0926+117 2023/08/17 2.66UT FUJI -KISO



T20230817114540





BLK:24,SNR1: 7.8800 ,SNR2: 15.216




Frequency (Hz)

3C222 2023/08/17 2.79UT TOYOKAWA-FUJI


F20230817114541




BLK:24,SNR1: 2.2448 ,SNR2: 6.9154




Frequency (Hz)




T20230817114540




No.Good Data




KISO




No.Good Data



3C222 2023/08/17 2.79UT TOYOKAWA-KISO




F20230817114541



No.Good Data



KISO




No.Good Data




3C222 2023/08/17 2.79UT FUJI -KISO



T20230817115240




BLK:34,SNR1: 18.127 ,SNR2: 25.128




Frequency (Hz)

F20230817115240




BLK:34,SNR1: 21.734 ,SNR2: 38.357



Frequency (Hz)

0941-08 2023/08/17 2.91UT TOYOKAWA-FUJI






T20230817115240




No.Good Data




KISO





No.Good Data




0941-08 2023/08/17 2.91UT TOYOKAWA-KISO



F20230817115240





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0941-08 2023/08/17 2.91UT FUJI -KISO



T20230817120102





BLK:29,SNR1: 9.1313 ,SNR2: 14.187




Frequency (Hz)

3C230 2023/08/17 3.05UT TOYOKAWA-FUJI


F20230817120103




BLK:29,SNR1: 5.4700 ,SNR2: 11.727




Frequency (Hz)




T20230817120102




No.Good Data




KISO





No.Good Data




3C230 2023/08/17 3.05UT TOYOKAWA-KISO





F20230817120103




No.Good Data



KISO





No.Good Data




3C230 2023/08/17 3.05UT FUJI -KISO



T20230817121508




BLK:14,SNR1: 0.50636 ,SNR2: 3.8056




Frequency (Hz)

3C236 2023/08/17 3.28UT TOYOKAWA-FUJI


F20230817121508



BLK:14,SNR1: 0.64633 ,SNR2: 1.3792



Frequency (Hz)



T20230817121508



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C236 2023/08/17 3.28UT TOYOKAWA-KISO





F20230817121508




No.Good Data



KISO



No.Good Data





3C236 2023/08/17 3.28UT FUJI -KISO






T20230817122318





BLK:33,SNR1: 3.2604 ,SNR2: 13.169




Frequency (Hz)

F20230817122318




BLK:33,SNR1: 3.5264 ,SNR2: 13.882





Frequency (Hz)


1011+110 2023/08/17 3.42UT TOYOKAWA-FUJI





T20230817122318




No.Good Data




KISO



No.Good Data



1011+110 2023/08/17 3.42UT TOYOKAWA-KISO



F20230817122318



No.Good Data




KISO





No.Good Data




1011+110 2023/08/17 3.42UT FUJI -KISO



T20230817123059





BLK:19,SNR1: 13.596 ,SNR2: 47.967




Frequency (Hz)

3C241 2023/08/17 3.54UT TOYOKAWA-FUJI


F20230817123059




BLK:19,SNR1: 1.0725 ,SNR2: 4.9496



Frequency (Hz)



T20230817123059




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C241 2023/08/17 3.54UT TOYOKAWA-KISO



F20230817123059





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C241 2023/08/17 3.54UT FUJI -KISO



T20230817124229





BLK:21,SNR1: 6.4717 ,SNR2: 12.759





1031-11 2023/08/17 3.74UT TOYOKAWA-FUJI

F20230817124229




BLK:21,SNR1: 2.1502 ,SNR2: 9.1696



T20230817124229



No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

1031-11 2023/08/17 3.74UT TOYOKAWA-KISO






F20230817124229





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1031-11 2023/08/17 3.74UT FUJI -KISO



T20230817124702





BLK:30,SNR1: 10.037 ,SNR2: 20.962





1035-058 2023/08/17 3.81UT TOYOKAWA-FUJI



F20230817124703




BLK:30,SNR1: 18.708 ,SNR2: 29.055





T20230817124702




No.Good Data




KISO




No.Good Data




1035-058 2023/08/17 3.81UT TOYOKAWA-KISO





F20230817124703




No.Good Data




KISO





No.Good Data




1035-058 2023/08/17 3.81UT FUJI -KISO



T20230817125615





BLK:31,SNR1: 3.2949 ,SNR2: 13.106




Frequency (Hz)

F20230817125616




BLK:31,SNR1: 14.361 ,SNR2: 16.012



Frequency (Hz)

1044-008 2023/08/17 3.97UT TOYOKAWA-FUJI



T20230817125615



No.Good Data




KISO



No.Good Data




1044-008 2023/08/17 3.97UT TOYOKAWA-KISO





F20230817125616




No.Good Data




KISO





No.Good Data




1044-008 2023/08/17 3.97UT FUJI -KISO



T20230817130713





BLK:30,SNR1: 2.4927 ,SNR2: 10.009




Frequency (Hz)

1055+20 2023/08/17 4.15UT TOYOKAWA-FUJI


F20230817130714



BLK:30,SNR1: 7.3954 ,SNR2: 16.127



Frequency (Hz)






T20230817130713





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1055+20 2023/08/17 4.15UT TOYOKAWA-KISO



F20230817130714



No.Good Data




KISO





No.Good Data




1055+20 2023/08/17 4.15UT FUJI -KISO



T20230817131837





BLK:28,SNR1: 3.6991 ,SNR2: 14.486




Frequency (Hz)

F20230817131838




BLK:28,SNR1: 3.7271 ,SNR2: 8.2376



Frequency (Hz)

1107+109 2023/08/17 4.34UT TOYOKAWA-FUJI



T20230817131837



No.Good Data



KISO




No.Good Data



1107+109 2023/08/17 4.34UT TOYOKAWA-KISO




F20230817131838




No.Good Data



KISO





No.Good Data




1107+109 2023/08/17 4.34UT FUJI -KISO





T20230817132814




BLK:15,SNR1: 3.2751 ,SNR2: 5.8406




F20230817132814




BLK:15,SNR1: 4.8780 ,SNR2: 11.007




3C255 2023/08/17 4.50UT TOYOKAWA-FUJI




T20230817132814




No.Good Data



KISO



No.Good Data



3C255 2023/08/17 4.50UT TOYOKAWA-KISO



F20230817132814



No.Good Data



KISO



No.Good Data





3C255 2023/08/17 4.50UT FUJI -KISO








T20230817135212




BLK:13,SNR1: 0.15649 ,SNR2: 0.74443




F20230817135212



BLK:13,SNR1: 0.30084 ,SNR2: 3.4954



3C263.1 2023/08/17 4.90UT TOYOKAWA-FUJI



T20230817135212



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C263.1 2023/08/17 4.90UT TOYOKAWA-KISO



F20230817135212





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C263.1 2023/08/17 4.90UT FUJI -KISO





T20230817135839




BLK:13,SNR1: 0.11072 ,SNR2: 0.44726




F20230817135840



BLK:13,SNR1: 8.6830 ,SNR2: 14.321



3C267 2023/08/17 5.01UT TOYOKAWA-FUJI





T20230817135839




No. Good Data




KISO





No. Good Data




3C267 2023/08/17 5.01UT TOYOKAWA-KISO





F20230817135840




No.Good Data




KISO




No.Good Data




3C267 2023/08/17 5.01UT FUJI -KISO



T20230817141754





BLK: 6,SNR1: 0.17775 ,SNR2: 1.1688





1206+439 2023/08/17 5.33UT TOYOKAWA-FUJI

F20230817141754



BLK: 6,SNR1: 3.1703 ,SNR2: 8.1677




T20230817141754



No. Good Data



KISO



No. Good Data



1206+439 2023/08/17 5.33UT TOYOKAWA-KISO





F20230817141754



No. Good Data



KISO




No. Good Data




1206+439 2023/08/17 5.33UT FUJI -KISO



T20230817143744




BLK:14,SNR1: 1.1500 ,SNR2: 5.6906




Frequency (Hz)

3C273 2023/08/17 5.66UT TOYOKAWA-FUJI


F20230817143744




BLK:14,SNR1: 1.2970 ,SNR2: 5.0337



Frequency (Hz)




T20230817143744




No. Good Data



KISO





No. Good Data




3C273 2023/08/17 5.66UT TOYOKAWA-KISO



F20230817143744



No. Good Data




KISO





No. Good Data




3C273 2023/08/17 5.66UT FUJI -KISO



T20230817145055





BLK: 6,SNR1: 0.66148E-03,SNR2: 0.89494




Frequency (Hz)

F20230817145055




BLK: 6,SNR1: 21.012 ,SNR2: 42.807




Frequency (Hz)


3C275 2023/08/17 5.88UT TOYOKAWA-FUJI




T20230817145055




No. Good Data



KISO



No. Good Data



3C275 2023/08/17 5.88UT TOYOKAWA-KISO




F20230817145055




No. Good Data



KISO





No. Good Data




3C275 2023/08/17 5.88UT FUJI -KISO



T20230817150444





BLK: 5,SNR1: 0.28036 ,SNR2: 0.45228




Frequency (Hz)

F20230817150444




BLK: 5,SNR1: 1.9547 ,SNR2: 10.406



Frequency (Hz)

3C279 2023/08/17 6.11UT TOYOKAWA-FUJI





T20230817150444



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C279 2023/08/17 6.11UT TOYOKAWA-KISO



F20230817150444



No. Good Data




KISO





No. Good Data




3C279 2023/08/17 6.11UT FUJI -KISO



T20230817152432





BLK: 8,SNR1: 0.71737E-01,SNR2: 1.8454




Frequency (Hz)

F20230817152432




BLK: 8,SNR1: 1.4698 ,SNR2: 6.1876



Frequency (Hz)


1313+453 2023/08/17 6.44UT TOYOKAWA-FUJI



T20230817152432





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

1313+453 2023/08/17 6.44UT TOYOKAWA-KISO



F20230817152432





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1313+453 2023/08/17 6.44UT FUJI -KISO



T20230817153438





BLK:15,SNR1: 0.99454E-01,SNR2: 0.68108




Frequency (Hz)

1323+32 2023/08/17 6.61UT TOYOKAWA-FUJI


F20230817153438



BLK:15,SNR1: 1.2763 ,SNR2: 5.5499




Frequency (Hz)



T20230817153438



No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1323+32 2023/08/17 6.61UT TOYOKAWA-KISO



F20230817153438



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1323+32 2023/08/17 6.61UT FUJI -KISO







T20230817153928




BLK: 7,SNR1: 1.0627 ,SNR2: 3.5440




F20230817153928



BLK: 7,SNR1: 1.7164 ,SNR2: 4.8636



3C286 2023/08/17 6.69UT TOYOKAWA-FUJI



T20230817153928



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C286 2023/08/17 6.69UT TOYOKAWA-KISO



F20230817153928



No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C286 2023/08/17 6.69UT FUJI -KISO



T20230817155555




BLK:12,SNR1: 1.9594 ,SNR2: 16.519





1345+12 2023/08/17 6.96UT TOYOKAWA-FUJI

F20230817155555



BLK:12,SNR1: 1.3941 ,SNR2: 3.9692



T20230817155555



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1345+12 2023/08/17 6.96UT TOYOKAWA-KISO





F2023081715555




No.Good Data




KISO




No.Good Data




1345+12 2023/08/17 6.96UT FUJI -KISO



T20230817160616





BLK: 8,SNR1: 0.99623E-01,SNR2: 0.89755





1355+01 2023/08/17 7.13UT TOYOKAWA-FUJI

F20230817160617



BLK: 8,SNR1: 1.3457 ,SNR2: 3.4872



T20230817160616



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1355+01 2023/08/17 7.13UT TOYOKAWA-KISO





F20230817160617



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


1355+01 2023/08/17 7.13UT FUJI -KISO



T20230817162726





BLK:11,SNR1: 0.96766 ,SNR2: 8.4056





3C298 2023/08/17 7.49UT TOYOKAWA-FUJI

F20230817162726



BLK:11,SNR1: 0.82898 ,SNR2: 2.8861



T20230817162726



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C298 2023/08/17 7.49UT TOYOKAWA-KISO



F20230817162726





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C298 2023/08/17 7.49UT FUJI -KISO





T20230817163910




No. Good Data




F20230817163911





No. Good Data




1428-03 2023/08/17 7.68UT TOYOKAWA-FUJI



T20230817163910





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1428-03 2023/08/17 7.68UT TOYOKAWA-KISO



F20230817163911



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1428-03 2023/08/17 7.68UT FUJI -KISO

