




T20230819062340





BLK: 7,SNR1: 1.1867 ,SNR2: 2.8076




Frequency (Hz)

F20230819062340




BLK: 7,SNR1: 2.7238 ,SNR2: 8.1862




Frequency (Hz)

0418+236 2023/08/18 21.42UT TOYOKAWA-FUJI



T20230819062340




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0418+236 2023/08/18 21.42UT TOYOKAWA-KISO




F20230819062340



No.Good Data



KISO





No.Good Data




0418+236 2023/08/18 21.42UT FUJI -KISO



T20230819063507





BLK:11,SNR1: 0.50763 ,SNR2: 2.5322




Frequency (Hz)

F20230819063508




BLK:11,SNR1: 0.87624E-01,SNR2: 1.0952




Frequency (Hz)


3C119 2023/08/18 21.61UT TOYOKAWA-FUJI





T20230819063507




No.Good Data




KISO





No.Good Data




3C119 2023/08/18 21.61UT TOYOKAWA-KISO




F20230819063508



No.Good Data




KISO




No.Good Data




3C119 2023/08/18 21.61UT FUJI -KISO



T20230819072315





BLK: 8,SNR1: 0.33960 ,SNR2: 2.9005




Frequency (Hz)

F20230819072315




BLK: 8,SNR1: 0.63103 ,SNR2: 4.3279




Frequency (Hz)


3C138 2023/08/18 22.42UT TOYOKAWA-FUJI



T20230819072315





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C138 2023/08/18 22.42UT TOYOKAWA-KISO







F20230819072315




No.Good Data



KISO





No.Good Data




3C138 2023/08/18 22.42UT FUJI -KISO



T20230819073648





BLK:13,SNR1: 0.29069 ,SNR2: 3.0471




Frequency (Hz)

F20230819073648




BLK:13,SNR1: 0.98504 ,SNR2: 2.7347



Frequency (Hz)


0531+194 2023/08/18 22.64UT TOYOKAWA-FUJI





T20230819073648




No.Good Data




KISO



No.Good Data



0531+194 2023/08/18 22.64UT TOYOKAWA-KISO



F20230819073648




No.Good Data



KISO





No.Good Data




0531+194 2023/08/18 22.64UT FUJI -KISO



T20230819074507





BLK:22,SNR1: 3.2550 ,SNR2: 12.521




Frequency (Hz)

F20230819074507




BLK:22,SNR1: 0.47000 ,SNR2: 2.4685




Frequency (Hz)


3C147 2023/08/18 22.78UT TOYOKAWA-FUJI



T20230819074507





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C147 2023/08/18 22.78UT TOYOKAWA-KISO



F20230819074507



No.Good Data




KISO




No.Good Data




3C147 2023/08/18 22.78UT FUJI -KISO




T20230819075320




BLK: 7,SNR1: 0.24018E-01,SNR2: 0.53162




F20230819075320



BLK: 7,SNR1: 0.69841 ,SNR2: 3.0651



0548+16 2023/08/18 22.92UT TOYOKAWA-FUJI






T20230819075320





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0548+16 2023/08/18 22.92UT TOYOKAWA-KISO



F20230819075320



No.Good Data



KISO





No.Good Data




0548+16 2023/08/18 22.92UT FUJI -KISO



T20230819075730





BLK:10,SNR1: 4.2206 ,SNR2: 49.409




Frequency (Hz)

F20230819075730




BLK:10,SNR1: 1.2357 ,SNR2: 3.6891




Frequency (Hz)


0552+12 2023/08/18 22.99UT TOYOKAWA-FUJI




T20230819075730




No.Good Data



KISO



No.Good Data



0552+12 2023/08/18 22.99UT TOYOKAWA-KISO



F20230819075730



No.Good Data



KISO





No.Good Data




0552+12 2023/08/18 22.99UT FUJI -KISO



T20230819080157





BLK: 9,SNR1: 2.3032 ,SNR2: 8.4476




Frequency (Hz)

F20230819080157




BLK: 9,SNR1: 1.1212 ,SNR2: 7.6768





Frequency (Hz)


0556+191 2023/08/18 23.06UT TOYOKAWA-FUJI



T20230819080157




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0556+191 2023/08/18 23.06UT TOYOKAWA-KISO



F20230819080157




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0556+191 2023/08/18 23.06UT FUJI -KISO






T20230819080630




BLK: 4,SNR1: 0.12638 ,SNR2: 0.69536




Frequency (Hz)

F20230819080630




BLK: 4,SNR1: 1.2259 ,SNR2: 4.9456



Frequency (Hz)


3C152 2023/08/18 23.14UT TOYOKAWA-FUJI





T20230819080630




No.Good Data




KISO




No.Good Data




3C152 2023/08/18 23.14UT TOYOKAWA-KISO





F20230819080630




No.Good Data




KISO




No.Good Data




3C152 2023/08/18 23.14UT FUJI -KISO



T20230819082851




BLK:10,SNR1: 0.75104 ,SNR2: 4.8080




Frequency (Hz)

3C161 2023/08/18 23.51UT TOYOKAWA-FUJI


F20230819082851



BLK:10,SNR1:-0.70598E-01,SNR2: 1.4444




Frequency (Hz)





T20230819082851




No.Good Data




KISO



No.Good Data




3C161 2023/08/18 23.51UT TOYOKAWA-KISO





F20230819082851




No.Good Data




KISO





No.Good Data




3C161 2023/08/18 23.51UT FUJI -KISO



T20230819085337




BLK: 4,SNR1:-0.17190E-01,SNR2: 0.77117





0648+263 2023/08/18 23.92UT TOYOKAWA-FUJI


F20230819085337




BLK: 4,SNR1: 9.6418 ,SNR2: 18.355





T20230819085337




No.Good Data




KISO



No.Good Data




0648+263 2023/08/18 23.92UT TOYOKAWA-KISO








F20230819085337




No.Good Data




KISO





No.Good Data




0648+263 2023/08/18 23.92UT FUJI -KISO



T20230819090800





BLK:27,SNR1: 1.8583 ,SNR2: 14.392




Frequency (Hz)

F20230819090800




BLK:27,SNR1: 263.23 ,SNR2: 636.22




Frequency (Hz)


0703+138 2023/08/19 0.16UT TOYOKAWA-FUJI





T20230819090800




No.Good Data




KISO



No.Good Data




0703+138 2023/08/19 0.16UT TOYOKAWA-KISO





F20230819090800




No.Good Data




KISO





No.Good Data




0703+138 2023/08/19 0.16UT FUJI -KISO





T20230819091723




BLK: 7,SNR1: 1.4459 ,SNR2: 9.5910




F20230819091723





BLK: 7,SNR1: 33.895 ,SNR2: 113.05




0713-024 2023/08/19 0.32UT TOYOKAWA-FUJI




T20230819091723




No.Good Data




KISO





No.Good Data




0713-024 2023/08/19 0.32UT TOYOKAWA-KISO




F20230819091723




No. Good Data




KISO





No. Good Data




0713-024 2023/08/19 0.32UT FUJI -KISO



T20230819092735





BLK: 9,SNR1: 0.11400 ,SNR2: 1.6487




Frequency (Hz)

F20230819092735




BLK: 9,SNR1: 1.5746 ,SNR2: 2.5368



Frequency (Hz)

0723+10 2023/08/19 0.49UT TOYOKAWA-FUJI





T20230819092735



No.Good Data




KISO



No.Good Data



0723+10 2023/08/19 0.49UT TOYOKAWA-KISO



F20230819092735




No.Good Data



KISO





No.Good Data




0723+10 2023/08/19 0.49UT FUJI -KISO



T20230819093749





BLK:12,SNR1: 0.66851 ,SNR2: 3.2956





0732+33 2023/08/19 0.66UT TOYOKAWA-FUJI


F20230819093749




BLK:12,SNR1: 0.68278 ,SNR2: 2.4534




T20230819093749




No.Good Data




KISO




No.Good Data



0732+33 2023/08/19 0.66UT TOYOKAWA-KISO




F20230819093749




No. Good Data



KISO





No. Good Data




0732+33 2023/08/19 0.66UT FUJI -KISO



T20230819094552




BLK: 9,SNR1: 0.37032 ,SNR2: 6.1737





0741-06 2023/08/19 0.79UT TOYOKAWA-FUJI


F20230819094552




BLK: 9,SNR1: 0.44974E-01,SNR2: 1.4048




T20230819094552




No.Good Data



KISO



No.Good Data



0741-06 2023/08/19 0.79UT TOYOKAWA-KISO



F20230819094552



No.Good Data



KISO



No.Good Data





0741-06 2023/08/19 0.79UT FUJI -KISO






T20230819100311





BLK:11,SNR1: 0.36291 ,SNR2: 1.8757




Frequency (Hz)

F20230819100311




BLK:11,SNR1: 3.3343 ,SNR2: 10.315



Frequency (Hz)

3C190 2023/08/19 1.08UT TOYOKAWA-FUJI



T20230819100311



No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C190 2023/08/19 1.08UT TOYOKAWA-KISO



F20230819100311





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C190 2023/08/19 1.08UT FUJI -KISO




T20230819101534




BLK:14,SNR1: 0.24030 ,SNR2: 1.5502




F20230819101534



BLK:14,SNR1: 0.46861 ,SNR2: 1.9764



3C196 2023/08/19 1.29UT TOYOKAWA-FUJI



T20230819101534



No. Good Data



KISO





No. Good Data




3C196 2023/08/19 1.29UT TOYOKAWA-KISO




F20230819101534




No. Good Data




KISO





No. Good Data




3C196 2023/08/19 1.29UT FUJI -KISO




T20230819102644




BLK:12,SNR1: 0.69688 ,SNR2: 3.1408




F20230819102644



BLK:12,SNR1: 1.0128 ,SNR2: 2.9491



0821+394 2023/08/19 1.47UT TOYOKAWA-FUJI




T20230819102644



No. Good Data



KISO



No. Good Data



0821+394 2023/08/19 1.47UT TOYOKAWA-KISO





F20230819102644



No. Good Data



KISO





No. Good Data




0821+394 2023/08/19 1.47UT FUJI -KISO



T20230819104331





BLK:12,SNR1: 0.20256 ,SNR2: 1.7729




Frequency (Hz)

F20230819104331




BLK:12,SNR1: 0.88295 ,SNR2: 2.3355



Frequency (Hz)


0839-071 2023/08/19 1.75UT TOYOKAWA-FUJI



T20230819104331



No. Good Data




Frequency (Hz)

KISO



No. Good Data



Frequency (Hz)

0839-071 2023/08/19 1.75UT TOYOKAWA-KISO



F20230819104331



No. Good Data



KISO




No. Good Data




0839-071 2023/08/19 1.75UT FUJI -KISO





T20230819105431




BLK:16,SNR1: 0.96441 ,SNR2: 2.9690




F20230819105431



BLK:16,SNR1: 5.7288 ,SNR2: 8.9341



3C208 2023/08/19 1.94UT TOYOKAWA-FUJI



T20230819105431





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C208 2023/08/19 1.94UT TOYOKAWA-KISO




F20230819105431




No. Good Data



KISO





No. Good Data




3C208 2023/08/19 1.94UT FUJI -KISO



T20230819111112





BLK:28,SNR1: 9.0974 ,SNR2: 19.782




Frequency (Hz)

F20230819111112




BLK:28,SNR1: 10.314 ,SNR2: 22.584



Frequency (Hz)

3C216 2023/08/19 2.21UT TOYOKAWA-FUJI





T20230819111112



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


3C216 2023/08/19 2.21UT TOYOKAWA-KISO



F20230819111112





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C216 2023/08/19 2.21UT FUJI -KISO



T20230819113003




BLK:26,SNR1: 14.002 ,SNR2: 21.870





0926+117 2023/08/19 2.53UT TOYOKAWA-FUJI

F20230819113003



BLK:26,SNR1: 8.5176 ,SNR2: 18.575



T20230819113003





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0926+117 2023/08/19 2.53UT TOYOKAWA-KISO



F20230819113003





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0926+117 2023/08/19 2.53UT FUJI -KISO




T20230819113748




BLK:18,SNR1: 1.0619 ,SNR2: 4.8995




F20230819113748



BLK:18,SNR1: 0.93774E-01,SNR2: 2.0910




3C222 2023/08/19 2.66UT TOYOKAWA-FUJI



T20230819113748



No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C222 2023/08/19 2.66UT TOYOKAWA-KISO





F20230819113748




No.Good Data




KISO



No.Good Data





3C222 2023/08/19 2.66UT FUJI -KISO






T20230819114448





BLK:26,SNR1: 12.724 ,SNR2: 20.586




0941-08 2023/08/19 2.77UT TOYOKAWA-FUJI


F20230819114448



BLK:26,SNR1: 12.592 ,SNR2: 20.372



Frequency (Hz)



T20230819114448



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0941-08 2023/08/19 2.77UT TOYOKAWA-KISO



F20230819114448



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0941-08 2023/08/19 2.77UT FUJI -KISO




T20230819115310




BLK:24,SNR1: 11.284 ,SNR2: 17.561




F20230819115310



BLK:24,SNR1: 2.0325 ,SNR2: 4.3423



3C230 2023/08/19 2.91UT TOYOKAWA-FUJI



T20230819115310



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C230 2023/08/19 2.91UT TOYOKAWA-KISO



F20230819115310





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C230 2023/08/19 2.91UT FUJI -KISO



T20230819120910




BLK:16,SNR1: 7.6847 ,SNR2: 31.202





3C237 2023/08/19 3.18UT TOYOKAWA-FUJI

F20230819120910



BLK:16,SNR1: 1.0275 ,SNR2: 3.2458



T20230819120910





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C237 2023/08/19 3.18UT TOYOKAWA-KISO






F20230819120910





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C237 2023/08/19 3.18UT FUJI -KISO



T20230819121527




BLK:13,SNR1: 9.7220 ,SNR2: 15.687





1011+110 2023/08/19 3.29UT TOYOKAWA-FUJI

F20230819121528



BLK:13,SNR1: 9.2258 ,SNR2: 20.151



T20230819121527



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1011+110 2023/08/19 3.29UT TOYOKAWA-KISO



F20230819121528



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


1011+110 2023/08/19 3.29UT FUJI -KISO




T20230819122308




BLK:20,SNR1: 1.6240 ,SNR2: 11.672




F20230819122308



BLK:20,SNR1: 1.4973 ,SNR2: 4.1771



3C241 2023/08/19 3.41UT TOYOKAWA-FUJI



T20230819122308



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C241 2023/08/19 3.41UT TOYOKAWA-KISO



F20230819122308



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C241 2023/08/19 3.41UT FUJI -KISO



T20230819123437





BLK: 6,SNR1: 0.15017 ,SNR2: 0.67259





1031-11 2023/08/19 3.61UT TOYOKAWA-FUJI

F20230819123437



BLK: 6,SNR1: 5.4752 ,SNR2: 5.0898





T20230819123437



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1031-11 2023/08/19 3.61UT TOYOKAWA-KISO





F20230819123437




No.Good Data




KISO





No.Good Data




1031-11 2023/08/19 3.61UT FUJI -KISO





T20230819123911




BLK:17,SNR1: 6.7818 ,SNR2: 13.153




F20230819123911



BLK:17,SNR1: 7.3409 ,SNR2: 8.9361



1035-058 2023/08/19 3.68UT TOYOKAWA-FUJI



T20230819123911



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

1035-058 2023/08/19 3.68UT TOYOKAWA-KISO



F20230819123911





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/08/19 3.68UT FUJI -KISO





T20230819124823




BLK:10,SNR1: 1.0058 ,SNR2: 4.2628




F20230819124823



BLK:10,SNR1: 0.21908 ,SNR2: 1.9192



1044-008 2023/08/19 3.83UT TOYOKAWA-FUJI



T20230819124823



No. Good Data



Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

1044-008 2023/08/19 3.83UT TOYOKAWA-KISO



F20230819124823





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1044-008 2023/08/19 3.83UT FUJI -KISO






T20230819125922





BLK: 9,SNR1: 9.6516 ,SNR2: 24.733




1055+20 2023/08/19 4.02UT TOYOKAWA-FUJI


F20230819125922



BLK: 9,SNR1: 0.33442 ,SNR2: 0.91130



Frequency (Hz)



T20230819125922



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1055+20 2023/08/19 4.02UT TOYOKAWA-KISO



F20230819125922



No. Good Data



Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1055+20 2023/08/19 4.02UT FUJI -KISO



T20230819131045





BLK:12,SNR1: 38.280 ,SNR2: 67.171





1107+109 2023/08/19 4.21UT TOYOKAWA-FUJI

F20230819131045



BLK:12,SNR1: 0.29182 ,SNR2: 3.0535



T20230819131045



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1107+109 2023/08/19 4.21UT TOYOKAWA-KISO



F20230819131045





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1107+109 2023/08/19 4.21UT FUJI -KISO




T20230819132023




BLK:11,SNR1: 0.70565 ,SNR2: 3.7272




F20230819132023



BLK:11,SNR1: 1.9126 ,SNR2: 5.0958




3C255 2023/08/19 4.37UT TOYOKAWA-FUJI



T20230819132023





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

3C255 2023/08/19 4.37UT TOYOKAWA-KISO





F20230819132023





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C255 2023/08/19 4.37UT FUJI -KISO





T20230819134421




BLK:10,SNR1: 0.16396 ,SNR2: 0.55641




F20230819134421





BLK:10,SNR1: 1.8158 ,SNR2: 4.1919




3C263.1 2023/08/19 4.77UT TOYOKAWA-FUJI



T20230819134421





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


3C263.1 2023/08/19 4.77UT TOYOKAWA-KISO



F20230819134421




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C263.1 2023/08/19 4.77UT FUJI -KISO





T20230819135048




BLK:16,SNR1: 6.4410 ,SNR2: 18.051




F20230819135049





BLK:16,SNR1: 120.04 ,SNR2: 117.73



3C267 2023/08/19 4.87UT TOYOKAWA-FUJI



T20230819135048





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

3C267 2023/08/19 4.87UT TOYOKAWA-KISO



F20230819135049





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2023/08/19 4.87UT FUJI -KISO





T20230819141002




BLK:11,SNR1: 0.54852E-01,SNR2: 0.28118




F20230819141002



BLK:11,SNR1: 0.41456 ,SNR2: 1.6520




1206+439 2023/08/19 5.20UT TOYOKAWA-FUJI





T20230819141002





No.Good Data



Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1206+439 2023/08/19 5.20UT TOYOKAWA-KISO




F20230819141002




KISO




1206+439 2023/08/19 5.20UT FUJI -KISO




T20230819142953




BLK:16,SNR1: 0.89867 ,SNR2: 4.5095




F20230819142953





BLK:16,SNR1: 1.9525 ,SNR2: 2.1276




3C273 2023/08/19 5.53UT TOYOKAWA-FUJI



T20230819142953





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C273 2023/08/19 5.53UT TOYOKAWA-KISO



F20230819142953





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C273 2023/08/19 5.53UT FUJI -KISO





T20230819144303




BLK:10,SNR1: 0.16160 ,SNR2: 1.4663




F20230819144303





BLK:10,SNR1: 0.30938 ,SNR2: 1.2941




3C275 2023/08/19 5.75UT TOYOKAWA-FUJI



T20230819144303





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C275 2023/08/19 5.75UT TOYOKAWA-KISO



F20230819144303





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C275 2023/08/19 5.75UT FUJI -KISO








T20230819145652




BLK: 5,SNR1: 0.13314 ,SNR2: 2.3958




F20230819145653



BLK: 5,SNR1: 0.65502 ,SNR2: 2.2582



3C279 2023/08/19 5.98UT TOYOKAWA-FUJI



T20230819145652



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C279 2023/08/19 5.98UT TOYOKAWA-KISO



F20230819145653





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C279 2023/08/19 5.98UT FUJI -KISO





T20230819151640




BLK: 5,SNR1: 0.93064E-01,SNR2: 0.68682




F20230819151640





BLK: 5,SNR1: 69.005 ,SNR2: 110.39






1313+453 2023/08/19 6.31UT TOYOKAWA-FUJI




T20230819151640





KISO



1313+453 2023/08/19 6.31UT TOYOKAWA-KISO





F20230819151640




No.Good Data




KISO





No.Good Data




1313+453 2023/08/19 6.31UT FUJI -KISO




T20230819152646




BLK:14,SNR1: 0.12326 ,SNR2: 0.71429




F20230819152646




BLK:14,SNR1: 94.734 ,SNR2: 109.28



1323+32 2023/08/19 6.47UT TOYOKAWA-FUJI



T20230819152646




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

1323+32 2023/08/19 6.47UT TOYOKAWA-KISO





F20230819152646




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


1323+32 2023/08/19 6.47UT FUJI -KISO





T20230819153137




BLK:15,SNR1: 0.55089 ,SNR2: 2.5738




F20230819153137




BLK:15,SNR1: 75.007 ,SNR2: 78.486



3C286 2023/08/19 6.56UT TOYOKAWA-FUJI



T20230819153137




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C286 2023/08/19 6.56UT TOYOKAWA-KISO



F20230819153137




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C286 2023/08/19 6.56UT FUJI -KISO





T20230819154804




BLK:13,SNR1: 0.23992 ,SNR2: 1.3275




F20230819154804





BLK:13,SNR1: 16.418 ,SNR2: 24.147



1345+12 2023/08/19 6.83UT TOYOKAWA-FUJI



T20230819154804





No.Good Data



Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1345+12 2023/08/19 6.83UT TOYOKAWA-KISO




F20230819154804




KISO




1345+12 2023/08/19 6.83UT FUJI -KISO





T20230819155824




BLK:12,SNR1: 0.20762 ,SNR2: 1.8018




F20230819155824



BLK:12,SNR1: 2.4179 ,SNR2: 6.8993






1355+01 2023/08/19 7.00UT TOYOKAWA-FUJI









T20230819155824




KISO




1355+01 2023/08/19 7.00UT TOYOKAWA-KISO



F20230819155824




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1355+01 2023/08/19 7.00UT FUJI -KISO



T20230819161935





BLK:18,SNR1: 0.42199 ,SNR2: 2.2984




Frequency (Hz)

F20230819161936




BLK:18,SNR1: 0.15153 ,SNR2: 1.1338





Frequency (Hz)


3C298 2023/08/19 7.35UT TOYOKAWA-FUJI



T20230819161935





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)



3C298 2023/08/19 7.35UT TOYOKAWA-KISO



F20230819161936





KISO




3C298 2023/08/19 7.35UT FUJI -KISO



T20230819163118





BLK:17,SNR1: 0.63913 ,SNR2: 1.4003




Frequency (Hz)

F20230819163118




BLK:17,SNR1: 0.84884 ,SNR2: 3.5498




Frequency (Hz)

1428-03 2023/08/19 7.55UT TOYOKAWA-FUJI



T20230819163118




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1428-03 2023/08/19 7.55UT TOYOKAWA-KISO



F20230819163118




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

1428-03 2023/08/19 7.55UT FUJI -KISO






T20230819165622





BLK:15,SNR1: 0.57088 ,SNR2: 2.2635




Frequency (Hz)

F20230819165623




BLK:15,SNR1: 1.2600 ,SNR2: 1.4715




Frequency (Hz)


1453-10 2023/08/19 7.97UT TOYOKAWA-FUJI



T20230819165622






KISO






1453-10 2023/08/19 7.97UT TOYOKAWA-KISO




F20230819165623




KISO




1453-10 2023/08/19 7.97UT FUJI -KISO





T20230819172015




BLK:12,SNR1: 1.5355 ,SNR2: 3.0550




F20230819172016






BLK:12,SNR1: 18.626 ,SNR2: 45.537






3C318 2023/08/19 8.37UT TOYOKAWA-FUJI




T20230819172015






KISO



3C318 2023/08/19 8.37UT TOYOKAWA-KISO






F20230819172016



No.Good Data

KISO



No.Good Data

3C318 2023/08/19 8.37UT FUJI -KISO

