






T20230829061319




No. Good Data




F20230829061319




No. Good Data




0446+449 2023/08/28 21.25UT TOYOKAWA-FUJI



T20230829061319




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0446+449 2023/08/28 21.25UT TOYOKAWA-KISO




F20230829061319



No.Good Data




KISO





No.Good Data




0446+449 2023/08/28 21.25UT FUJI -KISO



T20230829061748





No.Good Data




Frequency (Hz)

F20230829061748




No.Good Data





Frequency (Hz)

0451+421 2023/08/28 21.32UT TOYOKAWA-FUJI








T20230829061748




No.Good Data




KISO




No.Good Data



0451+421 2023/08/28 21.32UT TOYOKAWA-KISO



F20230829061748




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0451+421 2023/08/28 21.32UT FUJI -KISO



T20230829062551





No.Good Data




Frequency (Hz)

F20230829062550




No.Good Data




Frequency (Hz)


0459+237 2023/08/28 21.46UT TOYOKAWA-FUJI





T20230829062551




No.Good Data




KISO



No.Good Data




0459+237 2023/08/28 21.46UT TOYOKAWA-KISO



F20230829062550




No.Good Data



KISO





No.Good Data




0459+237 2023/08/28 21.46UT FUJI -KISO



T20230829063335





No.Good Data




Frequency (Hz)

F20230829063335




No.Good Data





Frequency (Hz)


0507+290 2023/08/28 21.59UT TOYOKAWA-FUJI





T20230829063335




No.Good Data




KISO



No.Good Data




0507+290 2023/08/28 21.59UT TOYOKAWA-KISO





F20230829063335




No.Good Data



KISO



No.Good Data





0507+290 2023/08/28 21.59UT FUJI -KISO








T20230829064357




No.Good Data




F20230829064356





No.Good Data




3C138 2023/08/28 21.76UT TOYOKAWA-FUJI




T20230829064357




No.Good Data




KISO




No.Good Data




3C138 2023/08/28 21.76UT TOYOKAWA-KISO




F20230829064356




No.Good Data



KISO





No.Good Data




3C138 2023/08/28 21.76UT FUJI -KISO





T20230829064859




No.Good Data




F20230829064859




No.Good Data




0523+116 2023/08/28 21.84UT TOYOKAWA-FUJI



T20230829064859





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0523+116 2023/08/28 21.84UT TOYOKAWA-KISO





F20230829064859




No.Good Data




KISO





No.Good Data




0523+116 2023/08/28 21.84UT FUJI -KISO



T20230829065730




No.Good Data




Frequency (Hz)

F20230829065730




No.Good Data





Frequency (Hz)


0531+194 2023/08/28 21.99UT TOYOKAWA-FUJI



T20230829065730





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0531+194 2023/08/28 21.99UT TOYOKAWA-KISO







F20230829065730




No.Good Data



KISO





No.Good Data




0531+194 2023/08/28 21.99UT FUJI -KISO





T20230829070549




No.Good Data




F20230829070548





No.Good Data




3C147 2023/08/28 22.12UT TOYOKAWA-FUJI





T20230829070549




No.Good Data




KISO





No.Good Data




3C147 2023/08/28 22.12UT TOYOKAWA-KISO





F20230829070548




No.Good Data




KISO





No.Good Data




3C147 2023/08/28 22.12UT FUJI -KISO



T20230829071402





No.Good Data




Frequency (Hz)

F20230829071401




No.Good Data





Frequency (Hz)


0548+16 2023/08/28 22.26UT TOYOKAWA-FUJI



T20230829071402





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0548+16 2023/08/28 22.28UT TOYOKAWA-KISO





F20230829071401




No.Good Data




KISO





No.Good Data




0548+16 2023/08/28 22.26UT FUJI -KISO



T20230829071812





No.Good Data




Frequency (Hz)

F20230829071812




No.Good Data




Frequency (Hz)

0552+12 2023/08/28 22.33UT TOYOKAWA-FUJI






T20230829071812





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0552+12 2023/08/28 22.33UT TOYOKAWA-KISO



F20230829071812





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0552+12 2023/08/28 22.33UT FUJI -KISO



T20230829072239





No.Good Data




Frequency (Hz)

F20230829072239




No.Good Data





Frequency (Hz)


0556+191 2023/08/28 22.41UT TOYOKAWA-FUJI



T20230829072239





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0556+191 2023/08/28 22.41UT TOYOKAWA-KISO



F20230829072239





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0556+191 2023/08/28 22.41UT FUJI -KISO





T20230829072712




No.Good Data




F20230829072712





No.Good Data




3C152 2023/08/28 22.48UT TOYOKAWA-FUJI





T20230829072712




No.Good Data




KISO





No.Good Data




3C152 2023/08/28 22.48UT TOYOKAWA-KISO





F20230829072712




No.Good Data




KISO



No.Good Data





3C152 2023/08/28 22.48UT FUJI -KISO








T20230829074933




No.Good Data




F20230829074933





No.Good Data




3C161 2023/08/28 22.85UT TOYOKAWA-FUJI





T20230829074933




No.Good Data




KISO



No.Good Data




3C161 2023/08/28 22.85UT TOYOKAWA-KISO





F20230829074933




No.Good Data




KISO





No.Good Data




3C161 2023/08/28 22.85UT FUJI -KISO





T20230829081707




No.Good Data




F20230829081706





No.Good Data




0652-130 2023/08/28 23.31UT TOYOKAWA-FUJI





T20230829081707




No.Good Data




KISO



No.Good Data



0652-130 2023/08/28 23.31UT TOYOKAWA-KISO





F20230829081706




No.Good Data



KISO





No.Good Data




0652-130 2023/08/28 23.31UT FUJI -KISO





T20230829082842




No.Good Data




F20230829082841




No.Good Data




0703+138 2023/08/28 23.51UT TOYOKAWA-FUJI




T20230829082842




No.Good Data




KISO



No.Good Data



0703+138 2023/08/28 23.51UT TOYOKAWA-KISO








F20230829082841




No.Good Data




KISO





No.Good Data



0703+138 2023/08/28 23.51UT FUJI -KISO





T20230829083805




No. Good Data




F20230829083804




No. Good Data




0713-024 2023/08/28 23.66UT TOYOKAWA-FUJI




T20230829083805




No.Good Data



KISO



No.Good Data



0713-024 2023/08/28 23.66UT TOYOKAWA-KISO



F20230829083804





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0713-024 2023/08/28 23.66UT FUJI -KISO





T20230829084817




No. Good Data



F20230829084817




No. Good Data




0723+10 2023/08/28 23.83UT TOYOKAWA-FUJI





T20230829084817




No. Good Data



KISO



No. Good Data



0723+10 2023/08/28 23.83UT TOYOKAWA-KISO





F20230829084817




No.Good Data




KISO





No.Good Data




0723+10 2023/08/28 23.83UT FUJI -KISO





T20230829090634




No. Good Data




F20230829090634



No. Good Data




0741-06 2023/08/29 0.14UT TOYOKAWA-FUJI







T20230829090634




No. Good Data




KISO




No. Good Data




0741-06 2023/08/29 0.14UT TOYOKAWA-KISO





F20230829090634




No.Good Data




KISO





No.Good Data



0741-06 2023/08/29 0.14UT FUJI -KISO



T20230829092353




No. Good Data




Frequency (Hz)

3C190 2023/08/29 0.43UT TOYOKAWA-FUJI


F20230829092352



No. Good Data




Frequency (Hz)





T20230829092353




No. Good Data




KISO




No. Good Data




3C190 2023/08/29 0.43UT TOYOKAWA-KISO



F20230829092352




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C190 2023/08/29 0.43UT FUJI -KISO





T20230829093616




No. Good Data




F20230829093615



No. Good Data




3C196 2023/08/29 0.63UT TOYOKAWA-FUJI



T20230829093616





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

3C196 2023/08/29 0.63UT TOYOKAWA-KISO



F20230829093615



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C196 2023/08/29 0.63UT FUJI -KISO








T20230829094726




No. Good Data




F20230829094726



No. Good Data



0821+394 2023/08/29 0.82UT TOYOKAWA-FUJI





T20230829094726




No. Good Data




KISO



No. Good Data



0821+394 2023/08/29 0.82UT TOYOKAWA-KISO





F20230829094726




No. Good Data




KISO





No. Good Data




0821+394 2023/08/29 0.82UT FUJI -KISO





T20230829100413




No. Good Data




F20230829100412



No. Good Data



0839-071 2023/08/29 1.10UT TOYOKAWA-FUJI



T20230829100413





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0839-071 2023/08/29 1.10UT TOYOKAWA-KISO





F20230829100412




No. Good Data




KISO





No. Good Data




0839-071 2023/08/29 1.10UT FUJI -KISO





T20230829101513




No. Good Data




F20230829101512





No. Good Data




3C208 2023/08/29 1.28UT TOYOKAWA-FUJI



T20230829101513





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

3C208 2023/08/29 1.28UT TOYOKAWA-KISO






F20230829101512





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2023/08/29 1.28UT FUJI -KISO





T20230829103154




No. Good Data




F20230829103153





No. Good Data




3C216 2023/08/29 1.56UT TOYOKAWA-FUJI



T20230829103154





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C216 2023/08/29 1.56UT TOYOKAWA-KISO



F20230829103153





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C216 2023/08/29 1.56UT FUJI -KISO





T20230829105045




No. Good Data




F20230829105044





No. Good Data




0926+117 2023/08/29 1.87UT TOYOKAWA-FUJI



T20230829105045





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0926+117 2023/08/29 1.87UT TOYOKAWA-KISO



F20230829105044





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0926+117 2023/08/29 1.87UT FUJI -KISO



T20230829105830





No. Good Data




Frequency (Hz)

F20230829105829




No. Good Data



Frequency (Hz)

3C222 2023/08/29 2.00UT TOYOKAWA-FUJI






T20230829105830



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C222 2023/08/29 2.00UT TOYOKAWA-KISO



F20230829105829





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C222 2023/08/29 2.00UT FUJI -KISO





T20230829110530




No. Good Data




F20230829110530



No. Good Data



0941-08 2023/08/29 2.12UT TOYOKAWA-FUJI



T20230829110530





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0941-08 2023/08/29 2.12UT TOYOKAWA-KISO



F20230829110530





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0941-08 2023/08/29 2.12UT FUJI -KISO



T20230829111352





No.Good Data




Frequency (Hz)

F20230829111351




No.Good Data



Frequency (Hz)

3C230 2023/08/29 2.26UT TOYOKAWA-FUJI



T20230829111352





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C230 2023/08/29 2.26UT TOYOKAWA-KISO



F20230829111351



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C230 2023/08/29 2.26UT FUJI -KISO





T20230829112952





No.Good Data



Frequency (Hz)

F20230829112952




No.Good Data



Frequency (Hz)

3C237 2023/08/29 2.53UT TOYOKAWA-FUJI



T20230829112952



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

3C237 2023/08/29 2.53UT TOYOKAWA-KISO



F20230829112952



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C237 2023/08/29 2.53UT FUJI -KISO



T20230829113609





No. Good Data




Frequency (Hz)

F20230829113608




No. Good Data





Frequency (Hz)


1011+110 2023/08/29 2.63UT TOYOKAWA-FUJI



T20230829113609





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1011+110 2023/08/29 2.63UT TOYOKAWA-KISO





F20230829113608




No.Good Data




KISO





No.Good Data




1011+110 2023/08/29 2.63UT FUJI -KISO



T20230829114350




No. Good Data




Frequency (Hz)

F20230829114349




No. Good Data




Frequency (Hz)

3C241 2023/08/29 2.76UT TOYOKAWA-FUJI



T20230829114350




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C241 2023/08/29 2.76UT TOYOKAWA-KISO






F20230829114349





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C241 2023/08/29 2.76UT FUJI -KISO



T20230829115519





No. Good Data




Frequency (Hz)

F20230829115518




No. Good Data




Frequency (Hz)

1031-11 2023/08/29 2.95UT TOYOKAWA-FUJI



T20230829115519




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1031-11 2023/08/29 2.95UT TOYOKAWA-KISO





F20230829115518




No.Good Data




KISO




No.Good Data




1031-11 2023/08/29 2.95UT FUJI -KISO





T20230829115953




No. Good Data




F20230829115952



No. Good Data




1035-058 2023/08/29 3.03UT TOYOKAWA-FUJI



T20230829115953





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1035-058 2023/08/29 3.03UT TOYOKAWA-KISO



F20230829115952





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/08/29 3.03UT FUJI -KISO





T20230829120905




No. Good Data




F20230829120905



No. Good Data



1044-008 2023/08/29 3.18UT TOYOKAWA-FUJI






T20230829120905





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


1044-008 2023/08/29 3.18UT TOYOKAWA-KISO



F20230829120905





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1044-008 2023/08/29 3.18UT FUJI -KISO




T20230829122004




No. Good Data




F20230829122003



No. Good Data




1055+20 2023/08/29 3.36UT TOYOKAWA-FUJI



T20230829122004



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


1055+20 2023/08/29 3.36UT TOYOKAWA-KISO



F20230829122003





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1055+20 2023/08/29 3.36UT FUJI -KISO




T20230829123127




No. Good Data




F20230829123126






No. Good Data






1107+109 2023/08/29 3.55UT TOYOKAWA-FUJI




T20230829123127



KISO




1107+109 2023/08/29 3.55UT TOYOKAWA-KISO



F20230829123126





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1107+109 2023/08/29 3.55UT FUJI -KISO






T20230829124210





No. Good Data




Frequency (Hz)

F20230829124209




No. Good Data





Frequency (Hz)


1117+14 2023/08/29 3.73UT TOYOKAWA-FUJI



T20230829124210





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1117+14 2023/08/29 3.73UT TOYOKAWA-KISO



F20230829124209





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1117+14 2023/08/29 3.73UT FUJI -KISO




T20230829130503




No.Good Data




F20230829130503





No.Good Data




3C263.1 2023/08/29 4.11UT TOYOKAWA-FUJI



T20230829130503





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C263.1 2023/08/29 4.11UT TOYOKAWA-KISO



F20230829130503





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C263.1 2023/08/29 4.11UT FUJI -KISO





T20230829131130




No.Good Data




F20230829131129





No.Good Data




3C267 2023/08/29 4.22UT TOYOKAWA-FUJI



T20230829131130





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C267 2023/08/29 4.22UT TOYOKAWA-KISO






F20230829131129





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2023/08/29 4.22UT FUJI -KISO




T20230829133044




No.Good Data




F20230829133043





No.Good Data




1206+439 2023/08/29 4.54UT TOYOKAWA-FUJI



T20230829133044





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1206+439 2023/08/29 4.54UT TOYOKAWA-KISO




F20230829133043





KISO




1206+439 2023/08/29 4.54UT FUJI -KISO





T20230829135035




No.Good Data




F20230829135034





No.Good Data




3C273 2023/08/29 4.87UT TOYOKAWA-FUJI



T20230829135035





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C273 2023/08/29 4.87UT TOYOKAWA-KISO



F20230829135034





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C273 2023/08/29 4.87UT FUJI -KISO





T20230829140345




No.Good Data




F20230829140344



No.Good Data






3C275 2023/08/29 5.09UT TOYOKAWA-FUJI









T20230829140345




KISO



3C275 2023/08/29 5.09UT TOYOKAWA-KISO



F20230829140344




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C275 2023/08/29 5.09UT FUJI -KISO





T20230829141734




No.Good Data




F20230829141733




No.Good Data




3C279 2023/08/29 5.32UT TOYOKAWA-FUJI



T20230829141734




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C279 2023/08/29 5.32UT TOYOKAWA-KISO



F20230829141733





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)




3C279 2023/08/29 5.32UT FUJI -KISO




T20230829143722





F20230829143721




1313+453 2023/08/29 5.65UT TOYOKAWA-FUJI



T20230829143722





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1313+453 2023/08/29 5.65UT TOYOKAWA-KISO




F20230829143721



KISO





1313+453 2023/08/29 5.65UT FUJI -KISO








T20230829144728




No.Good Data




F20230829144728





No.Good Data




1323+32 2023/08/29 5.82UT TOYOKAWA-FUJI



T20230829144728




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2023/08/29 5.82UT TOYOKAWA-KISO



F20230829144728




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2023/08/29 5.82UT FUJI -KISO





T20230829145219




No.Good Data




F20230829145218






No.Good Data






3C286 2023/08/29 5.90UT TOYOKAWA-FUJI




T20230829145219




KISO




3C286 2023/08/29 5.90UT TOYOKAWA-KISO



F20230829145218





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C286 2023/08/29 5.90UT FUJI -KISO





T20230829150846




No.Good Data




F20230829150846






No.Good Data






1345+12 2023/08/29 6.17UT TOYOKAWA-FUJI




T20230829150846



KISO






1345+12 2023/08/29 6.17UT TOYOKAWA-KISO








F20230829150846






KISO





1345+12 2023/08/29 6.17UT FUJI -KISO




T20230829151906




F20230829151905




1355+01 2023/08/29 6.35UT TOYOKAWA-FUJI



T20230829151906





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1355+01 2023/08/29 6.35UT TOYOKAWA-KISO



F20230829151905





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1355+01 2023/08/29 6.35UT FUJI -KISO




T20230829154017






F20230829154017






3C298 2023/08/29 6.70UT TOYOKAWA-FUJI




T20230829154017






KISO






3C298 2023/08/29 6.70UT TOYOKAWA-KISO




F20230829154017






KISO






3C298 2023/08/29 6.70UT FUJI -KISO




T20230829155200



F20230829155159






1428-03 2023/08/29 6.89UT TOYOKAWA-FUJI









T20230829155200






KISO






1428-03 2023/08/29 6.89UT TOYOKAWA-KISO




F20230829155159






KISO






1428-03 2023/08/29 6.89UT FUJI -KISO




T20230829160041





FUJI




1436-16 2023/08/29 7.04UT TOYOKAWA-FUJI



T20230829160041





No.Good Data




Frequency (Hz)

K20230829160023




No.Good Data





Frequency (Hz)


1436-16 2023/08/29 7.04UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20230829160023




No.Good Data





Frequency (Hz)




1436-16 2023/08/29 7.04UT FUJI -KISO




T20230829161704






F20230829161703






1453-10 2023/08/29 7.31UT TOYOKAWA-FUJI




T20230829161704






KISO






1453-10 2023/08/29 7.31UT TOYOKAWA-KISO




F20230829161703



KISO





1453-10 2023/08/29 7.31UT FUJI -KISO








T20230829163157






F20230829163156






1508-05 2023/08/29 7.56UT TOYOKAWA-FUJI




T20230829163157






KISO






1508-05 2023/08/29 7.56UT TOYOKAWA-KISO




F20230829163156





KISO





1508-05 2023/08/29 7.56UT FUJI -KISO




T20230829164057






F20230829164056






3C318 2023/08/29 7.71UT TOYOKAWA-FUJI




T20230829164057






KISO






3C318 2023/08/29 7.71UT TOYOKAWA-KISO




F20230829164056





KISO




3C318 2023/08/29 7.71UT FUJI -KISO





T20230829164644




No.Good Data




F20230829164643





No.Good Data




1523+03 2023/08/29 7.81UT TOYOKAWA-FUJI





T20230829164644




No.Good Data




KISO



No.Good Data




1523+03 2023/08/29 7.81UT TOYOKAWA-KISO






F20230829164643





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1523+03 2023/08/29 7.81UT FUJI -KISO




T20230829165824




No.Good Data




F20230829165823




No.Good Data




1535+139 2023/08/29 8.00UT TOYOKAWA-FUJI



T20230829165824




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1535+139 2023/08/29 8.00UT TOYOKAWA-KISO



F20230829165823





No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1535+139 2023/08/29 8.00UT FUJI -KISO

