






T20230901062148




No.Good Data




F20230901062147




No.Good Data




0507+290 2023/08/31 21.39UT TOYOKAWA-FUJI



T20230901062148




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0507+290 2023/08/31 21.39UT TOYOKAWA-KISO



F20230901062147




No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0507+290 2023/08/31 21.39UT FUJI -KISO



T20230901063209





No.Good Data




Frequency (Hz)

F20230901063208




No.Good Data





Frequency (Hz)

3C138 2023/08/31 21.56UT TOYOKAWA-FUJI








T20230901063209




No.Good Data




KISO



No.Good Data



3C138 2023/08/31 21.56UT TOYOKAWA-KISO




F20230901063208




No.Good Data




KISO





No.Good Data




3C138 2023/08/31 21.56UT FUJI -KISO



T20230901063712





No.Good Data




Frequency (Hz)

F20230901063712




No.Good Data




Frequency (Hz)


0523+116 2023/08/31 21.65UT TOYOKAWA-FUJI





T20230901063712




No.Good Data




KISO



No.Good Data



0523+116 2023/08/31 21.65UT TOYOKAWA-KISO



F20230901063712




No.Good Data



KISO





No.Good Data




0523+116 2023/08/31 21.65UT FUJI -KISO



T20230901064543





No.Good Data




Frequency (Hz)

F20230901064543




No.Good Data





Frequency (Hz)


0531+194 2023/08/31 21.79UT TOYOKAWA-FUJI




T20230901064543




No.Good Data




KISO



No.Good Data



0531+194 2023/08/31 21.79UT TOYOKAWA-KISO





F20230901064543




No.Good Data



KISO



No.Good Data





0531+194 2023/08/31 21.79UT FUJI -KISO








T20230901065401




No. Good Data




F20230901065401





No. Good Data




3C147 2023/08/31 21.93UT TOYOKAWA-FUJI




T20230901065401




No.Good Data




KISO




No.Good Data



3C147 2023/08/31 21.93UT TOYOKAWA-KISO




F20230901065401



No.Good Data




KISO





No.Good Data




3C147 2023/08/31 21.93UT FUJI -KISO



T20230901070214





No.Good Data




Frequency (Hz)

F20230901070214




No.Good Data





Frequency (Hz)


0548+16 2023/08/31 22.07UT TOYOKAWA-FUJI



T20230901070214





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0548+16 2023/08/31 22.07UT TOYOKAWA-KISO





F20230901070214




No.Good Data




KISO





No.Good Data




0548+16 2023/08/31 22.07UT FUJI -KISO



T20230901070625




No.Good Data




Frequency (Hz)

F20230901070625




No.Good Data





Frequency (Hz)


0552+12 2023/08/31 22.13UT TOYOKAWA-FUJI





T20230901070625




No.Good Data




KISO



No.Good Data




0552+12 2023/08/31 22.13UT TOYOKAWA-KISO







F20230901070625




No.Good Data



KISO





No.Good Data




0552+12 2023/08/31 22.13UT FUJI -KISO




T20230901071051




No.Good Data



F20230901071050





No.Good Data




0556+191 2023/08/31 22.21UT TOYOKAWA-FUJI



T20230901071051





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0556+191 2023/08/31 22.21UT TOYOKAWA-KISO





F20230901071050




No.Good Data




KISO





No.Good Data




0556+191 2023/08/31 22.21UT FUJI -KISO



T20230901071524





No.Good Data




Frequency (Hz)

F20230901071524




No.Good Data





Frequency (Hz)


3C152 2023/08/31 22.28UT TOYOKAWA-FUJI



T20230901071524





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C152 2023/08/31 22.28UT TOYOKAWA-KISO





F20230901071524




No.Good Data




KISO





No.Good Data




3C152 2023/08/31 22.28UT FUJI -KISO





T20230901073746




No. Good Data




F20230901073746



No. Good Data




3C161 2023/08/31 22.66UT TOYOKAWA-FUJI






T20230901073746





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/08/31 22.66UT TOYOKAWA-KISO





F20230901073746




No.Good Data




KISO





No.Good Data




3C161 2023/08/31 22.66UT FUJI -KISO



T20230901080519





No.Good Data




Frequency (Hz)

F20230901080518




No.Good Data





Frequency (Hz)


0652-130 2023/08/31 23.12UT TOYOKAWA-FUJI



T20230901080519





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2023/08/31 23.12UT TOYOKAWA-KISO





F20230901080518




No.Good Data




KISO





No.Good Data




0652-130 2023/08/31 23.12UT FUJI -KISO





T20230901081654




No.Good Data




F20230901081654





No.Good Data




0703+138 2023/08/31 23.31UT TOYOKAWA-FUJI





T20230901081654




No.Good Data




KISO





No.Good Data




0703+138 2023/08/31 23.31UT TOYOKAWA-KISO





F20230901081654




No.Good Data




KISO



No.Good Data





0703+138 2023/08/31 23.31UT FUJI -KISO






T20230901082618





No.Good Data




Frequency (Hz)

F20230901082618




No.Good Data





Frequency (Hz)


0713-024 2023/08/31 23.47UT TOYOKAWA-FUJI





T20230901082618




No.Good Data




KISO




No.Good Data




0713-024 2023/08/31 23.47UT TOYOKAWA-KISO





F20230901082618




No.Good Data




KISO





No.Good Data




0713-024 2023/08/31 23.47UT FUJI -KISO



T20230901083629





No. Good Data




Frequency (Hz)

0723+10 2023/08/31 23.64UT TOYOKAWA-FUJI


F20230901083628





No. Good Data




Frequency (Hz)





T20230901083629




No.Good Data




KISO



No.Good Data



0723+10 2023/08/31 23.64UT TOYOKAWA-KISO




F20230901083628




No.Good Data



KISO





No.Good Data




0723+10 2023/08/31 23.64UT FUJI -KISO



T20230901084643





No.Good Data




Frequency (Hz)

F20230901084642




No.Good Data




Frequency (Hz)


0732+33 2023/08/31 23.81UT TOYOKAWA-FUJI




T20230901084643




No.Good Data




KISO



No.Good Data



0732+33 2023/08/31 23.81UT TOYOKAWA-KISO







F20230901084642




No.Good Data




KISO





No.Good Data




0732+33 2023/08/31 23.81UT FUJI -KISO





T20230901085308




No. Good Data




F20230901085307




No. Good Data




0739+052 2023/08/31 23.91UT TOYOKAWA-FUJI




T20230901085308




No.Good Data



KISO



No.Good Data




0739+052 2023/08/31 23.91UT TOYOKAWA-KISO



F20230901085307




No.Good Data



KISO





No.Good Data



0739+052 2023/08/31 23.91UT FUJI -KISO





T20230901091205




No. Good Data



F20230901091204




No. Good Data




3C190 2023/09/01 0.23UT TOYOKAWA-FUJI



T20230901091205





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C190 2023/09/01 0.23UT TOYOKAWA-KISO





F20230901091204




No.Good Data




KISO





No.Good Data




3C190 2023/09/01 0.23UT FUJI -KISO



T20230901092429





No. Good Data




Frequency (Hz)

F20230901092428




No. Good Data




Frequency (Hz)

3C196 2023/09/01 0.44UT TOYOKAWA-FUJI








T20230901092429




No. Good Data




KISO




No. Good Data




3C196 2023/09/01 0.44UT TOYOKAWA-KISO





F20230901092428




No.Good Data




KISO





No.Good Data



3C196 2023/09/01 0.44UT FUJI -KISO





T20230901093539




No. Good Data




F20230901093538



No. Good Data




0821+394 2023/09/01 0.62UT TOYOKAWA-FUJI





T20230901093539




No.Good Data




KISO





No.Good Data




0821+394 2023/09/01 0.62UT TOYOKAWA-KISO





F20230901093538




No.Good Data




KISO





No.Good Data




0821+394 2023/09/01 0.62UT FUJI -KISO



T20230901095225





No. Good Data




Frequency (Hz)

F20230901095224




No. Good Data



Frequency (Hz)


0839-071 2023/09/01 0.90UT TOYOKAWA-FUJI



T20230901095225





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0839-071 2023/09/01 0.90UT TOYOKAWA-KISO





F20230901095224




No. Good Data




KISO



No. Good Data





0839-071 2023/09/01 0.90UT FUJI -KISO








T20230901100326




No. Good Data




F20230901100325




No. Good Data




3C208 2023/09/01 1.09UT TOYOKAWA-FUJI





T20230901100326




No. Good Data




KISO



No. Good Data



3C208 2023/09/01 1.09UT TOYOKAWA-KISO





F20230901100325




No. Good Data




KISO





No. Good Data



3C208 2023/09/01 1.09UT FUJI -KISO





T20230901102006




No. Good Data




F20230901102005



No. Good Data



3C216 2023/09/01 1.36UT TOYOKAWA-FUJI



T20230901102006





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C216 2023/09/01 1.36UT TOYOKAWA-KISO





F20230901102005




No. Good Data




KISO





No. Good Data




3C216 2023/09/01 1.36UT FUJI -KISO



T20230901103857





No. Good Data




Frequency (Hz)

F20230901103856




No. Good Data





Frequency (Hz)


0926+117 2023/09/01 1.68UT TOYOKAWA-FUJI



T20230901103857





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

0926+117 2023/09/01 1.68UT TOYOKAWA-KISO






F20230901103856





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0926+117 2023/09/01 1.68UT FUJI -KISO



T20230901104642





No. Good Data




Frequency (Hz)

F20230901104641




No. Good Data






Frequency (Hz)




3C222 2023/09/01 1.81UT TOYOKAWA-FUJI




T20230901104642





KISO




3C222 2023/09/01 1.81UT TOYOKAWA-KISO



F20230901104641



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C222 2023/09/01 1.81UT FUJI -KISO



T20230901105342





No. Good Data




Frequency (Hz)

0941-08 2023/09/01 1.92UT TOYOKAWA-FUJI


F20230901105341



No. Good Data




Frequency (Hz)



T20230901105342



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0941-08 2023/09/01 1.92UT TOYOKAWA-KISO



F20230901105341





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0941-08 2023/09/01 1.92UT FUJI -KISO



T20230901110204





No. Good Data




Frequency (Hz)

F20230901110203




No. Good Data



Frequency (Hz)

3C230 2023/09/01 2.06UT TOYOKAWA-FUJI






T20230901110204



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)




3C230 2023/09/01 2.06UT TOYOKAWA-KISO




F20230901110203





KISO




3C230 2023/09/01 2.06UT FUJI -KISO



T20230901111611





No. Good Data




Frequency (Hz)

F20230901111610




No. Good Data



Frequency (Hz)

3C236 2023/09/01 2.30UT TOYOKAWA-FUJI



T20230901111611





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C236 2023/09/01 2.30UT TOYOKAWA-KISO





F20230901111610




No.Good Data




KISO





No.Good Data




3C236 2023/09/01 2.30UT FUJI -KISO





T20230901112421




No. Good Data




F20230901112421



No. Good Data



1011+110 2023/09/01 2.43UT TOYOKAWA-FUJI



T20230901112421





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1011+110 2023/09/01 2.43UT TOYOKAWA-KISO



F20230901112421



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1011+110 2023/09/01 2.43UT FUJI -KISO





T20230901113202





No.Good Data




Frequency (Hz)

F20230901113201




No.Good Data



Frequency (Hz)

3C241 2023/09/01 2.56UT TOYOKAWA-FUJI



T20230901113202



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C241 2023/09/01 2.56UT TOYOKAWA-KISO



F20230901113201





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C241 2023/09/01 2.56UT FUJI -KISO



T20230901114332





No.Good Data




Frequency (Hz)

F20230901114331




No.Good Data





Frequency (Hz)


1031-11 2023/09/01 2.75UT TOYOKAWA-FUJI



T20230901114332





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1031-11 2023/09/01 2.75UT TOYOKAWA-KISO





F20230901114331




No.Good Data




KISO





No.Good Data



1031-11 2023/09/01 2.75UT FUJI -KISO





T20230901114805




No. Good Data




F20230901114805





No. Good Data




1035-058 2023/09/01 2.83UT TOYOKAWA-FUJI



T20230901114805





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

1035-058 2023/09/01 2.83UT TOYOKAWA-KISO






F20230901114805





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


1035-058 2023/09/01 2.83UT FUJI -KISO





T20230901115718




No. Good Data




F20230901115717




No. Good Data



1044-008 2023/09/01 2.98UT TOYOKAWA-FUJI



T20230901115718




No. Good Data



Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

1044-008 2023/09/01 2.98UT TOYOKAWA-KISO



F20230901115717





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1044-008 2023/09/01 2.98UT FUJI -KISO




T20230901120822




BLK: 6,SNR1: 61.946 ,SNR2: 69.853




F20230901120822



BLK: 6,SNR1: 0.59618 ,SNR2: 3.0351



1055+01 2023/09/01 3.17UT TOYOKAWA-FUJI



T20230901120822





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


1055+01 2023/09/01 3.17UT TOYOKAWA-KISO



F20230901120822





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1055+01 2023/09/01 3.17UT FUJI -KISO




T20230901123022




BLK: 4,SNR1: 1.9095 ,SNR2: 7.7630




F20230901123021



BLK: 4,SNR1: 0.26355 ,SNR2: 2.0193



1117+14 2023/09/01 3.53UT TOYOKAWA-FUJI






T20230901123022





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


1117+14 2023/09/01 3.53UT TOYOKAWA-KISO



F20230901123021





No. Good Data




Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


1117+14 2023/09/01 3.53UT FUJI -KISO




T20230901150718




BLK:10,SNR1: 22.515 ,SNR2: 38.532




F20230901150718



BLK:10,SNR1: 8.0299 ,SNR2: 31.087




1355+01 2023/09/01 6.15UT TOYOKAWA-FUJI



T20230901150718



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


1355+01 2023/09/01 6.15UT TOYOKAWA-KISO



F20230901150718





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1355+01 2023/09/01 6.15UT FUJI -KISO





T20230901152829




BLK: 3,SNR1: 0.14711 ,SNR2: 1.3704




F20230901152828





BLK: 3,SNR1: 1.1194 ,SNR2: 2.5890




3C298 2023/09/01 6.50UT TOYOKAWA-FUJI



T20230901152829



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C298 2023/09/01 6.50UT TOYOKAWA-KISO



F20230901152828





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C298 2023/09/01 6.50UT FUJI -KISO







T20230901154012




BLK: 3,SNR1: 0.11801 ,SNR2: 1.3976




F20230901154011





BLK: 3,SNR1: 0.19919 ,SNR2: 3.3595




1428-03 2023/09/01 6.70UT TOYOKAWA-FUJI



T20230901154012





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1428-03 2023/09/01 6.70UT TOYOKAWA-KISO



F20230901154011





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1428-03 2023/09/01 6.70UT FUJI -KISO





T20230901160517




BLK: 3,SNR1:-0.24891E-01,SNR2: 2.9098




F20230901160516





BLK: 3,SNR1:-0.10153 ,SNR2: 1.2185




1453-10 2023/09/01 7.12UT TOYOKAWA-FUJI



T20230901160517





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1453-10 2023/09/01 7.12UT TOYOKAWA-KISO



F20230901160516





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1453-10 2023/09/01 7.12UT FUJI -KISO





T20230901162009




BLK: 4,SNR1: 0.35486E-01,SNR2: 2.5549




F20230901162008




BLK: 4,SNR1: 3.5638 ,SNR2: 8.7033




1508-05 2023/09/01 7.36UT TOYOKAWA-FUJI



T20230901162009





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1508-05 2023/09/01 7.36UT TOYOKAWA-KISO






F20230901162008





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1508-05 2023/09/01 7.36UT FUJI -KISO





T20230901162910




BLK: 4,SNR1: 0.21512E-01,SNR2: 1.5741




F20230901162910





BLK: 4,SNR1: 0.64292 ,SNR2: 3.7323




3C318 2023/09/01 7.51UT TOYOKAWA-FUJI



T20230901162910





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C318 2023/09/01 7.51UT TOYOKAWA-KISO



F20230901162910





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C318 2023/09/01 7.51UT FUJI -KISO





T20230901163456




BLK: 4,SNR1: 0.87970E-02,SNR2: 0.58312




F20230901163456





BLK: 4,SNR1: 1.7091 ,SNR2: 10.393




1523+03 2023/09/01 7.61UT TOYOKAWA-FUJI



T20230901163456





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1523+03 2023/09/01 7.61UT TOYOKAWA-KISO



F20230901163456





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1523+03 2023/09/01 7.61UT FUJI -KISO





T20230901164636




BLK: 3,SNR1: 0.69340E-01,SNR2: 1.3768




F20230901164635



BLK: 3,SNR1:-0.42672E-01,SNR2: 0.22404





1535+139 2023/09/01 7.80UT TOYOKAWA-FUJI






T20230901164636





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1535+139 2023/09/01 7.80UT TOYOKAWA-KISO



F20230901164635




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1535+139 2023/09/01 7.80UT FUJI -KISO




T20230901165700




BLK: 1,SNR1: 0.63514 ,SNR2: 2.1049




F20230901165700



BLK: 1,SNR1:-0.16352 ,SNR2: 0.76002E-01




1545-12 2023/09/01 7.98UT TOYOKAWA-FUJI



T20230901165700





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1545-12 2023/09/01 7.98UT TOYOKAWA-KISO



F20230901165700





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1545-12 2023/09/01 7.98UT FUJI -KISO





T20230901171804




BLK: 1,SNR1: 0.38742 ,SNR2: 1.3185




F20230901171804





BLK: 1,SNR1: 0.53626 ,SNR2: 5.5202




1607+26 2023/09/01 8.33UT TOYOKAWA-FUJI



T20230901171804





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1607+26 2023/09/01 8.33UT TOYOKAWA-KISO



F20230901171804



KISO



1607+26 2023/09/01 8.33UT FUJI -KISO

