




T20230902062814




BLK:15,SNR1: 1.8575 ,SNR2: 3.9086




Frequency (Hz)

3C138 2023/09/01 21.50UT TOYOKAWA-FUJI


F20230902062814




BLK:15,SNR1: 0.39700 ,SNR2: 3.2368




Frequency (Hz)





T20230902062814




No.Good Data




KISO



No.Good Data



3C138 2023/09/01 21.50UT TOYOKAWA-KISO




F20230902062814



No.Good Data




KISO





No.Good Data




3C138 2023/09/01 21.50UT FUJI -KISO



T20230902063316





BLK:21,SNR1: 2.1641 ,SNR2: 8.8970




Frequency (Hz)

F20230902063316




BLK:21,SNR1: 3.1281 ,SNR2: 6.3336





Frequency (Hz)

0523+116 2023/09/01 21.58UT TOYOKAWA-FUJI






T20230902063316





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0523+116 2023/09/01 21.58UT TOYOKAWA-KISO




F20230902063316




No.Good Data




KISO





No.Good Data




0523+116 2023/09/01 21.58UT FUJI -KISO



T20230902064147





BLK: 5,SNR1: 0.17389 ,SNR2: 0.63783




Frequency (Hz)

F20230902064146




BLK: 5,SNR1: 1.3873 ,SNR2: 6.1020




Frequency (Hz)


0531+194 2023/09/01 21.72UT TOYOKAWA-FUJI



T20230902064147





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0531+194 2023/09/01 21.72UT TOYOKAWA-KISO



F20230902064146




No.Good Data



KISO





No.Good Data




0531+194 2023/09/01 21.72UT FUJI -KISO



T20230902065005





BLK:29,SNR1: 2.5411 ,SNR2: 5.8571




Frequency (Hz)

3C147 2023/09/01 21.86UT TOYOKAWA-FUJI


F20230902065005




BLK:29,SNR1: 0.71497 ,SNR2: 3.4376




Frequency (Hz)





T20230902065005




No.Good Data




KISO




No.Good Data




3C147 2023/09/01 21.86UT TOYOKAWA-KISO





F20230902065005




No.Good Data




KISO



No.Good Data





3C147 2023/09/01 21.86UT FUJI -KISO






T20230902065818





BLK:30,SNR1: 20.610 ,SNR2: 33.137




Frequency (Hz)

F20230902065818




BLK:30,SNR1: 11.006 ,SNR2: 23.574





Frequency (Hz)


0548+16 2023/09/01 22.00UT TOYOKAWA-FUJI



T20230902065818




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0548+16 2023/09/01 22.00UT TOYOKAWA-KISO



F20230902065818





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0548+16 2023/09/01 22.00UT FUJI -KISO



T20230902070229





BLK: 9,SNR1: 0.53807 ,SNR2: 5.0018




Frequency (Hz)

F20230902070228




BLK: 9,SNR1: 0.42037 ,SNR2: 2.6436





Frequency (Hz)


0552+12 2023/09/01 22.07UT TOYOKAWA-FUJI



T20230902070229





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0552+12 2023/09/01 22.07UT TOYOKAWA-KISO





F20230902070228




No.Good Data




KISO




No.Good Data




0552+12 2023/09/01 22.07UT FUJI -KISO



T20230902070655




BLK: 3,SNR1: 0.34364E-01,SNR2: 0.12034




Frequency (Hz)

F20230902070654




BLK: 3,SNR1: 0.76520 ,SNR2: 4.0465





Frequency (Hz)


0556+191 2023/09/01 22.14UT TOYOKAWA-FUJI





T20230902070655




No.Good Data




KISO



No.Good Data




0556+191 2023/09/01 22.14UT TOYOKAWA-KISO







F20230902070654




No.Good Data



KISO




No.Good Data




0556+191 2023/09/01 22.14UT FUJI -KISO



T20230902071128





BLK: 3,SNR1:-0.47667E-01,SNR2: 0.20076E-01





3C152 2023/09/01 22.22UT TOYOKAWA-FUJI



F20230902071127




BLK: 3,SNR1: 0.87266 ,SNR2: 2.1678



T20230902071128





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C152 2023/09/01 22.22UT TOYOKAWA-KISO





F20230902071127




No.Good Data




KISO




No.Good Data




3C152 2023/09/01 22.22UT FUJI -KISO



T20230902073350




BLK:12,SNR1: 0.59005 ,SNR2: 4.7876




Frequency (Hz)

3C161 2023/09/01 22.59UT TOYOKAWA-FUJI


F20230902073349





BLK:12,SNR1: 6.4446 ,SNR2: 12.615




Frequency (Hz)



T20230902073350





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C161 2023/09/01 22.59UT TOYOKAWA-KISO





F20230902073349




No.Good Data




KISO





No.Good Data




3C161 2023/09/01 22.59UT FUJI -KISO



T20230902080123




BLK: 5,SNR1: 0.13104 ,SNR2: 1.5583




Frequency (Hz)

F20230902080122




BLK: 5,SNR1: 0.17228 ,SNR2: 2.5791




Frequency (Hz)

0652-130 2023/09/01 23.05UT TOYOKAWA-FUJI






T20230902080123





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2023/09/01 23.05UT TOYOKAWA-KISO



F20230902080122





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2023/09/01 23.05UT FUJI -KISO



T20230902081259





BLK: 6,SNR1: 0.47972 ,SNR2: 1.7092




Frequency (Hz)

F20230902081259




BLK: 6,SNR1:-0.50378E-01,SNR2: 0.72694





Frequency (Hz)


0703+138 2023/09/01 23.24UT TOYOKAWA-FUJI



T20230902081259





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0703+138 2023/09/01 23.24UT TOYOKAWA-KISO





F20230902081259




No.Good Data




KISO





No.Good Data




0703+138 2023/09/01 23.24UT FUJI -KISO



T20230902082222





BLK: 4,SNR1: 0.22580 ,SNR2: 3.4556




Frequency (Hz)

0713-024 2023/09/01 23.40UT TOYOKAWA-FUJI


F20230902082222





BLK: 4,SNR1: 6.7335 ,SNR2: 16.263




Frequency (Hz)



T20230902082222





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0713-024 2023/09/01 23.40UT TOYOKAWA-KISO



F20230902082222





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0713-024 2023/09/01 23.40UT FUJI -KISO






T20230902083233





BLK: 7,SNR1:-0.28009E-02,SNR2: 0.52284




Frequency (Hz)

F20230902083232




BLK: 7,SNR1: 0.59575 ,SNR2: 4.1287





Frequency (Hz)


0723+10 2023/09/01 23.57UT TOYOKAWA-FUJI





T20230902083233




No.Good Data




KISO




No.Good Data




0723+10 2023/09/01 23.57UT TOYOKAWA-KISO





F20230902083232




No.Good Data




KISO





No.Good Data




0723+10 2023/09/01 23.57UT FUJI -KISO



T20230902084247




BLK: 3,SNR1: 0.12951 ,SNR2: 0.87815




Frequency (Hz)

F20230902084247




BLK: 3,SNR1: 0.13993E-01,SNR2: 0.73092





Frequency (Hz)


0732+33 2023/09/01 23.74UT TOYOKAWA-FUJI





T20230902084247




No. Good Data




KISO




No. Good Data



0732+33 2023/09/01 23.74UT TOYOKAWA-KISO




F20230902084247




No.Good Data



KISO




No.Good Data




0732+33 2023/09/01 23.74UT FUJI -KISO



T20230902085050





BLK: 4,SNR1: 0.29673 ,SNR2: 3.0649




Frequency (Hz)

F20230902085049




BLK: 4,SNR1: 0.56789 ,SNR2: 2.4812




Frequency (Hz)


0741-06 2023/09/01 23.88UT TOYOKAWA-FUJI





T20230902085050




No.Good Data




KISO



No.Good Data



0741-06 2023/09/01 23.88UT TOYOKAWA-KISO








F20230902085049




No.Good Data




KISO





No.Good Data




0741-06 2023/09/01 23.88UT FUJI -KISO



T20230902090809





BLK: 4,SNR1: 0.10816 ,SNR2: 1.5493




Frequency (Hz)

3C190 2023/09/02 0.16UT TOYOKAWA-FUJI


F20230902090809




BLK: 4,SNR1: 0.15721 ,SNR2: 0.45449




Frequency (Hz)



T20230902090809





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C190 2023/09/02 0.16UT TOYOKAWA-KISO




F20230902090809




No.Good Data



KISO





No.Good Data




3C190 2023/09/02 0.16UT FUJI -KISO





T20230902092033




BLK:10,SNR1: 0.23126 ,SNR2: 1.3109




F20230902092032




BLK:10,SNR1: 0.51221 ,SNR2: 2.8119




3C196 2023/09/02 0.37UT TOYOKAWA-FUJI





T20230902092033




No.Good Data



KISO



No.Good Data




3C196 2023/09/02 0.37UT TOYOKAWA-KISO



F20230902092032





No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C196 2023/09/02 0.37UT FUJI -KISO




T20230902093143




BLK: 4,SNR1: 0.18240 ,SNR2: 0.43114




F20230902093142



BLK: 4,SNR1: 0.48120 ,SNR2: 4.6395




0821+394 2023/09/02 0.56UT TOYOKAWA-FUJI







T20230902093143




No. Good Data




KISO



No. Good Data




0821+394 2023/09/02 0.56UT TOYOKAWA-KISO





F20230902093142




No.Good Data




KISO




No.Good Data




0821+394 2023/09/02 0.56UT FUJI -KISO



T20230902094829




BLK: 5,SNR1: 1.5862 ,SNR2: 13.974





0839-071 2023/09/02 0.84UT TOYOKAWA-FUJI


F20230902094828




BLK: 5,SNR1: 0.88647E-01,SNR2: 1.1735



T20230902094829





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0839-071 2023/09/02 0.84UT TOYOKAWA-KISO





F20230902094828




No. Good Data




KISO




No. Good Data




0839-071 2023/09/02 0.84UT FUJI -KISO



T20230902095930




BLK:12,SNR1: 1.2846 ,SNR2: 12.753





3C208 2023/09/02 1.02UT TOYOKAWA-FUJI


F20230902095930




BLK:12,SNR1: 0.94747 ,SNR2: 8.2578



T20230902095930





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C208 2023/09/02 1.02UT TOYOKAWA-KISO



F20230902095930





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C208 2023/09/02 1.02UT FUJI -KISO






T20230902101610





BLK: 8,SNR1: 0.52887 ,SNR2: 5.4084




Frequency (Hz)

3C216 2023/09/02 1.30UT TOYOKAWA-FUJI


F20230902101609



BLK: 8,SNR1:-0.11145E-01,SNR2: 1.9225



Frequency (Hz)



T20230902101610





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

3C216 2023/09/02 1.30UT TOYOKAWA-KISO





F20230902101609




No.Good Data




KISO





No.Good Data




3C216 2023/09/02 1.30UT FUJI -KISO



T20230902103502





BLK: 5,SNR1: 0.34079 ,SNR2: 5.0003




Frequency (Hz)

0926+117 2023/09/02 1.61UT TOYOKAWA-FUJI


F20230902103501



BLK: 5,SNR1: 0.21100 ,SNR2: 1.4352



Frequency (Hz)





T20230902103502




No. Good Data




KISO





No. Good Data




0926+117 2023/09/02 1.61UT TOYOKAWA-KISO



F20230902103501





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0926+117 2023/09/02 1.61UT FUJI -KISO



T20230902104246




BLK:18,SNR1: 1.5312 ,SNR2: 10.315





3C222 2023/09/02 1.74UT TOYOKAWA-FUJI



F20230902104245




BLK:18,SNR1: 0.12899 ,SNR2: 2.2930



T20230902104246





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

3C222 2023/09/02 1.74UT TOYOKAWA-KISO






F20230902104245





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C222 2023/09/02 1.74UT FUJI -KISO



T20230902104947




BLK: 6,SNR1: 0.31687 ,SNR2: 2.8318




0941-08 2023/09/02 1.86UT TOYOKAWA-FUJI


F20230902104946





BLK: 6,SNR1:-0.13208 ,SNR2: 1.0812




Frequency (Hz)



T20230902104947





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0941-08 2023/09/02 1.86UT TOYOKAWA-KISO



F20230902104946





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0941-08 2023/09/02 1.86UT FUJI -KISO




T20230902105808




BLK:22,SNR1: 2.5551 ,SNR2: 10.851




F20230902105808



BLK:22,SNR1:-0.10723 ,SNR2: 1.8704




3C230 2023/09/02 2.00UT TOYOKAWA-FUJI



T20230902105808



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C230 2023/09/02 2.00UT TOYOKAWA-KISO



F20230902105808





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C230 2023/09/02 2.00UT FUJI -KISO



T20230902111215




BLK: 8,SNR1: 0.29883 ,SNR2: 2.1186




Frequency (Hz)

F20230902111215




BLK: 8,SNR1: 0.89200 ,SNR2: 4.3072



Frequency (Hz)

3C236 2023/09/02 2.23UT TOYOKAWA-FUJI






T20230902111215





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C236 2023/09/02 2.23UT TOYOKAWA-KISO



F20230902111215





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C236 2023/09/02 2.23UT FUJI -KISO





T20230902112025




BLK:10,SNR1: 0.39529 ,SNR2: 1.9734




F20230902112024



BLK:10,SNR1: 0.67604 ,SNR2: 6.1112



1011+110 2023/09/02 2.37UT TOYOKAWA-FUJI



T20230902112025





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1011+110 2023/09/02 2.37UT TOYOKAWA-KISO



F20230902112024





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1011+110 2023/09/02 2.37UT FUJI -KISO



T20230902112806




BLK:14,SNR1: 0.53533 ,SNR2: 5.8433





3C241 2023/09/02 2.50UT TOYOKAWA-FUJI

F20230902112805



BLK:14,SNR1: 0.60977E-01,SNR2: 1.1123



T20230902112806





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C241 2023/09/02 2.50UT TOYOKAWA-KISO





F20230902112805




No.Good Data




KISO



No.Good Data




3C241 2023/09/02 2.50UT FUJI -KISO






T20230902113936




BLK: 3,SNR1: 0.29334 ,SNR2: 1.6508





1031-11 2023/09/02 2.69UT TOYOKAWA-FUJI

F20230902113935



BLK: 3,SNR1: 0.37078 ,SNR2: 7.0635



T20230902113936



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1031-11 2023/09/02 2.69UT TOYOKAWA-KISO



F20230902113935





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1031-11 2023/09/02 2.69UT FUJI -KISO



T20230902114409




BLK: 6,SNR1: 1.1510 ,SNR2: 10.890




Frequency (Hz)

F20230902114408




BLK: 6,SNR1: 0.12272 ,SNR2: 3.0271





Frequency (Hz)


1035-058 2023/09/02 2.76UT TOYOKAWA-FUJI



T20230902114409





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/09/02 2.76UT TOYOKAWA-KISO





F20230902114408




No.Good Data




KISO





No.Good Data




1035-058 2023/09/02 2.76UT FUJI -KISO




T20230902115322




BLK: 9,SNR1: 0.10818 ,SNR2: 0.35656




F20230902115322




BLK: 9,SNR1: 2.8724 ,SNR2: 9.5232



1044-008 2023/09/02 2.92UT TOYOKAWA-FUJI



T20230902115322




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

1044-008 2023/09/02 2.92UT TOYOKAWA-KISO






F20230902115322





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


1044-008 2023/09/02 2.92UT FUJI -KISO




T20230902120426




BLK: 7,SNR1: 1.2269 ,SNR2: 5.1012




F20230902120425




BLK: 7,SNR1:-0.10012 ,SNR2: 2.0062



1055+01 2023/09/02 3.10UT TOYOKAWA-FUJI



T20230902120426




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1055+01 2023/09/02 3.10UT TOYOKAWA-KISO



F20230902120425





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1055+01 2023/09/02 3.10UT FUJI -KISO




T20230902121544




BLK:19,SNR1: 0.99074 ,SNR2: 2.2591




F20230902121543



BLK:19,SNR1: 0.28950 ,SNR2: 2.5662



1107+109 2023/09/02 3.29UT TOYOKAWA-FUJI



T20230902121544





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1107+109 2023/09/02 3.29UT TOYOKAWA-KISO



F20230902121543





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1107+109 2023/09/02 3.29UT FUJI -KISO





T20230902122626




BLK:11,SNR1: 1.7690 ,SNR2: 8.1733




F20230902122625



BLK:11,SNR1: 0.39010 ,SNR2: 4.5475



1117+14 2023/09/02 3.47UT TOYOKAWA-FUJI






T20230902122626





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1117+14 2023/09/02 3.47UT TOYOKAWA-KISO



F20230902122625





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1117+14 2023/09/02 3.47UT FUJI -KISO



T20230902124919





BLK: 9,SNR1: 0.32037 ,SNR2: 1.5044





3C263.1 2023/09/02 3.85UT TOYOKAWA-FUJI

F20230902124918




BLK: 9,SNR1: 0.35902 ,SNR2: 0.87802



T20230902124919



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C263.1 2023/09/02 3.85UT TOYOKAWA-KISO



F20230902124918





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C263.1 2023/09/02 3.85UT FUJI -KISO



T20230902125546




BLK: 9,SNR1: 0.27578 ,SNR2: 1.3365




Frequency (Hz)

F20230902125545




BLK: 9,SNR1: 0.82752E-01,SNR2: 0.85704





Frequency (Hz)


3C267 2023/09/02 3.96UT TOYOKAWA-FUJI



T20230902125546



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2023/09/02 3.96UT TOYOKAWA-KISO



F20230902125545





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C267 2023/09/02 3.96UT FUJI -KISO







T20230902131500




BLK:10,SNR1: 12.225 ,SNR2: 36.956




F20230902131459





BLK:10,SNR1: 0.49901 ,SNR2: 1.3346




1206+439 2023/09/02 4.28UT TOYOKAWA-FUJI



T20230902131500





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1206+439 2023/09/02 4.28UT TOYOKAWA-KISO



F20230902131459





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1206+439 2023/09/02 4.28UT FUJI -KISO




T20230902133451




BLK:16,SNR1: 2.6252 ,SNR2: 18.532




F20230902133451





BLK:16,SNR1:-0.66456E-01,SNR2: 1.2815




3C273 2023/09/02 4.61UT TOYOKAWA-FUJI



T20230902133451





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C273 2023/09/02 4.61UT TOYOKAWA-KISO



F20230902133451





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C273 2023/09/02 4.61UT FUJI -KISO




T20230902134802




BLK: 4,SNR1: 0.40511 ,SNR2: 4.0274




F20230902134801




BLK: 4,SNR1: 0.27243 ,SNR2: 4.6059




3C275 2023/09/02 4.83UT TOYOKAWA-FUJI



T20230902134802





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C275 2023/09/02 4.83UT TOYOKAWA-KISO








F20230902134801




No.Good Data




KISO





No.Good Data




3C275 2023/09/02 4.83UT FUJI -KISO




T20230902140150




BLK: 3,SNR1: 0.24415 ,SNR2: 2.5370




F20230902140149






BLK: 3,SNR1: 0.33719 ,SNR2: 1.2215






3C279 2023/09/02 5.06UT TOYOKAWA-FUJI




T20230902140150





KISO




3C279 2023/09/02 5.06UT TOYOKAWA-KISO





F20230902140149




No.Good Data




KISO





No.Good Data




3C279 2023/09/02 5.06UT FUJI -KISO




T20230902142139




BLK: 2,SNR1: 0.21906 ,SNR2: 0.45452




F20230902142138





BLK: 2,SNR1:-0.83267E-02,SNR2: 0.47102




1313+453 2023/09/02 5.39UT TOYOKAWA-FUJI



T20230902142139





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1313+453 2023/09/02 5.39UT TOYOKAWA-KISO



F20230902142138





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1313+453 2023/09/02 5.39UT FUJI -KISO




T20230902143145




BLK: 4,SNR1: 0.17020 ,SNR2: 1.3609




F20230902143144



BLK: 4,SNR1: 1.3331 ,SNR2: 4.8940





1323+32 2023/09/02 5.56UT TOYOKAWA-FUJI






T20230902143145




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1323+32 2023/09/02 5.56UT TOYOKAWA-KISO



F20230902143144




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1323+32 2023/09/02 5.56UT FUJI -KISO





T20230902143635




BLK:20,SNR1: 0.88837 ,SNR2: 7.6563




F20230902143634



BLK:20,SNR1: 0.25476 ,SNR2: 1.7350




3C286 2023/09/02 5.64UT TOYOKAWA-FUJI



T20230902143635





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C286 2023/09/02 5.64UT TOYOKAWA-KISO



F20230902143634





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C286 2023/09/02 5.64UT FUJI -KISO




T20230902145302




BLK:10,SNR1: 0.20902 ,SNR2: 2.2447




F20230902145301





BLK:10,SNR1: 1.3846 ,SNR2: 3.5640




1345+12 2023/09/02 5.91UT TOYOKAWA-FUJI



T20230902145302





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1345+12 2023/09/02 5.91UT TOYOKAWA-KISO



F20230902145301





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1345+12 2023/09/02 5.91UT FUJI -KISO








T20230902150322




BLK:11,SNR1: 0.23036 ,SNR2: 0.93767




F20230902150321





BLK:11,SNR1: 1.8054 ,SNR2: 6.8183




1355+01 2023/09/02 6.08UT TOYOKAWA-FUJI



T20230902150322




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1355+01 2023/09/02 6.08UT TOYOKAWA-KISO



F20230902150321




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1355+01 2023/09/02 6.08UT FUJI -KISO





T20230902152433




BLK:13,SNR1: 0.35685 ,SNR2: 2.0861




F20230902152432






BLK:13,SNR1: 0.18034 ,SNR2: 0.74889






3C298 2023/09/02 6.44UT TOYOKAWA-FUJI




T20230902152433




KISO




3C298 2023/09/02 6.44UT TOYOKAWA-KISO



F20230902152432





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C298 2023/09/02 6.44UT FUJI -KISO



T20230902153616





BLK: 3,SNR1: 0.97055E-01,SNR2: 1.3095




Frequency (Hz)

F20230902153616




BLK: 3,SNR1: 2.4054 ,SNR2: 8.6617






Frequency (Hz)




1428-03 2023/09/02 6.63UT TOYOKAWA-FUJI




T20230902153616



KISO






1428-03 2023/09/02 6.63UT TOYOKAWA-KISO








F20230902153616





KISO




1428-03 2023/09/02 6.63UT FUJI -KISO





T20230902160121




BLK: 1,SNR1: 0.40021E-01,SNR2: 0.58433




F20230902160120





BLK: 1,SNR1:-0.31205 ,SNR2: 0.84891




1453-10 2023/09/02 7.05UT TOYOKAWA-FUJI



T20230902160121





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1453-10 2023/09/02 7.05UT TOYOKAWA-KISO




F20230902160120





KISO




1453-10 2023/09/02 7.05UT FUJI -KISO



T20230902161613




BLK: 3,SNR1: 0.28413E-01,SNR2: 0.70699




Frequency (Hz)

F20230902161612




BLK: 3,SNR1: 0.10801 ,SNR2: 1.2159






Frequency (Hz)




1508-05 2023/09/02 7.30UT TOYOKAWA-FUJI




T20230902161613





KISO




1508-05 2023/09/02 7.30UT TOYOKAWA-KISO



F20230902161612





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1508-05 2023/09/02 7.30UT FUJI -KISO




T20230902162514




BLK: 2,SNR1:-0.83018E-02,SNR2: 0.37934




F20230902162513



BLK: 2,SNR1: 0.71997 ,SNR2: 2.8262






3C318 2023/09/02 7.45UT TOYOKAWA-FUJI









T20230902162514






KISO






3C318 2023/09/02 7.45UT TOYOKAWA-KISO




F20230902162513





KISO




3C318 2023/09/02 7.45UT FUJI -KISO



T20230902163100





BLK: 1,SNR1: 0.26671 ,SNR2: 1.2266




Frequency (Hz)

F20230902163059




BLK: 1,SNR1: 0.27401 ,SNR2: 1.2446






Frequency (Hz)




1523+03 2023/09/02 7.54UT TOYOKAWA-FUJI




T20230902163100






KISO






1523+03 2023/09/02 7.54UT TOYOKAWA-KISO




F20230902163059





KISO




1523+03 2023/09/02 7.54UT FUJI -KISO



T20230902164240





BLK: 2,SNR1:-0.23134 ,SNR2: 0.42468




Frequency (Hz)

F20230902164239




BLK: 2,SNR1:-0.51861E-01,SNR2: 3.0774






Frequency (Hz)




1535+139 2023/09/02 7.74UT TOYOKAWA-FUJI




T20230902164240






KISO






1535+139 2023/09/02 7.74UT TOYOKAWA-KISO




F20230902164239



KISO





1535+139 2023/09/02 7.74UT FUJI -KISO








T20230902165304




BLK:13,SNR1: 36.016 ,SNR2: 70.337




F20230902165303





BLK:13,SNR1: 34.873 ,SNR2: 68.678




1545-12 2023/09/02 7.91UT TOYOKAWA-FUJI



T20230902165304





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1545-12 2023/09/02 7.91UT TOYOKAWA-KISO




F20230902165303




KISO




1545-12 2023/09/02 7.91UT FUJI -KISO



T20230902171408




BLK:10,SNR1: 21.211 ,SNR2: 28.336




Frequency (Hz)

F20230902171407




BLK:10,SNR1: 121.17 ,SNR2: 143.82




Frequency (Hz)


1607+26 2023/09/02 8.26UT TOYOKAWA-FUJI



T20230902171408





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1607+26 2023/09/02 8.26UT TOYOKAWA-KISO





F20230902171407




No.Good Data



KISO



No.Good Data



1607+26 2023/09/02 8.26UT FUJI -KISO

