




T20230906062603





BLK: 5,SNR1: 5.9637 ,SNR2: 46.156




Frequency (Hz)

F20230906062602




BLK: 5,SNR1:-0.19176E-01,SNR2: 0.84089





Frequency (Hz)


0531+194 2023/09/05 21.46UT TOYOKAWA-FUJI



T20230906062603





BLK: 7,SNR1: 7.4156 ,SNR2: 45.384




Frequency (Hz)

K20230906062600




BLK: 7,SNR1: 7.3072 ,SNR2: 13.907




Frequency (Hz)

0531+194 2023/09/05 21.46UT TOYOKAWA-KISO






F20230906062602





BLK: 5,SNR1:-0.25343E-01,SNR2: 1.0149




Frequency (Hz)

K20230906062600




BLK: 5,SNR1: 0.75859 ,SNR2: 2.5877





Frequency (Hz)


0531+194 2023/09/05 21.46UT FUJI -KISO



T20230906063422





BLK:23,SNR1: 0.91991 ,SNR2: 6.4325




Frequency (Hz)

F20230906063422




BLK:23,SNR1: 0.22010 ,SNR2: 1.3304





Frequency (Hz)


3C147 2023/09/05 21.60UT TOYOKAWA-FUJI



T20230906063422





BLK:29,SNR1: 0.87227 ,SNR2: 5.4554




Frequency (Hz)

K20230906063419




BLK:29,SNR1: 0.42917 ,SNR2: 1.9269





Frequency (Hz)


3C147 2023/09/05 21.60UT TOYOKAWA-KISO



F20230906063422





BLK:23,SNR1: 0.20798 ,SNR2: 1.2967




Frequency (Hz)

K20230906063419




BLK:23,SNR1: 0.61410 ,SNR2: 2.7186





Frequency (Hz)


3C147 2023/09/05 21.60UT FUJI -KISO



T20230906064234




BLK: 5,SNR1: 4.6640 ,SNR2: 56.041




Frequency (Hz)

F20230906064234




BLK: 5,SNR1: 0.43238 ,SNR2: 0.91997





Frequency (Hz)


0548+16 2023/09/05 21.74UT TOYOKAWA-FUJI



T20230906064234





BLK: 6,SNR1: 2.5875 ,SNR2: 31.531




Frequency (Hz)

K20230906064231




BLK: 6,SNR1: 1.0911 ,SNR2: 3.5276





Frequency (Hz)


0548+16 2023/09/05 21.74UT TOYOKAWA-KISO



F20230906064234





BLK: 2,SNR1: 0.10416 ,SNR2: 1.4644




Frequency (Hz)

K20230906064231




BLK: 2,SNR1: 0.30308E-01,SNR2: 1.2298





Frequency (Hz)


0548+16 2023/09/05 21.74UT FUJI -KISO



T20230906064645





BLK: 8,SNR1: 7.4282 ,SNR2: 49.295




Frequency (Hz)

F20230906064645




BLK: 8,SNR1:-0.22366E-01,SNR2: 1.1549





Frequency (Hz)

0552+12 2023/09/05 21.81UT TOYOKAWA-FUJI






T20230906064645





BLK: 9,SNR1: 12.015 ,SNR2: 81.605




Frequency (Hz)

K20230906064642




BLK: 9,SNR1: 0.54051 ,SNR2: 2.1055





Frequency (Hz)


0552+12 2023/09/05 21.81UT TOYOKAWA-KISO



F20230906064645





BLK: 4,SNR1: 0.35543E-02,SNR2: 2.9473




Frequency (Hz)

K20230906064642




BLK: 4,SNR1: 1.0300 ,SNR2: 3.9466





Frequency (Hz)


0552+12 2023/09/05 21.81UT FUJI -KISO



T20230906065112




BLK: 2,SNR1: 0.15051 ,SNR2: 0.95828




Frequency (Hz)

F20230906065112




BLK: 2,SNR1: 2.6928 ,SNR2: 16.751




Frequency (Hz)


0556+191 2023/09/05 21.88UT TOYOKAWA-FUJI



T20230906065112




BLK: 7,SNR1: 0.49753E-01,SNR2: 0.60217




Frequency (Hz)

K20230906065109




BLK: 7,SNR1: 0.78226 ,SNR2: 3.3592




Frequency (Hz)


0556+191 2023/09/05 21.88UT TOYOKAWA-KISO



F20230906065112





BLK: 5,SNR1: 5.3375 ,SNR2: 8.3470




Frequency (Hz)

K20230906065109




BLK: 5,SNR1: 0.38998 ,SNR2: 1.5353





Frequency (Hz)


0556+191 2023/09/05 21.88UT FUJI -KISO



T20230906065544





BLK: 5,SNR1: 0.29080 ,SNR2: 0.85477




Frequency (Hz)

F20230906065544




BLK: 5,SNR1: 0.31817 ,SNR2: 1.6859





Frequency (Hz)


3C152 2023/09/05 21.96UT TOYOKAWA-FUJI



T20230906065544





BLK: 3,SNR1: 0.36590 ,SNR2: 3.0256




Frequency (Hz)

K20230906065541




BLK: 3,SNR1: 1.6671 ,SNR2: 6.3025





Frequency (Hz)


3C152 2023/09/05 21.96UT TOYOKAWA-KISO



F20230906065544





BLK: 5,SNR1:-0.10774 ,SNR2: 0.85078




Frequency (Hz)

3C152 2023/09/05 21.96UT FUJI -KISO


K20230906065541



BLK: 5,SNR1: 0.53897 ,SNR2: 2.3148





Frequency (Hz)






T20230906071806





BLK:13,SNR1: 0.24101 ,SNR2: 2.5770




Frequency (Hz)

3C161 2023/09/05 22.33UT TOYOKAWA-FUJI


F20230906071806





BLK:13,SNR1:-0.16032 ,SNR2: 0.50191




Frequency (Hz)



T20230906071806





BLK:15,SNR1: 0.29191 ,SNR2: 3.0192




Frequency (Hz)

3C161 2023/09/05 22.33UT TOYOKAWA-KISO


K20230906071803




BLK:15,SNR1: 0.42804 ,SNR2: 3.0569




Frequency (Hz)





F20230906071806




BLK: 7,SNR1:-0.62994E-01,SNR2: 0.77680




K20230906071803





BLK: 7,SNR1: 0.49356 ,SNR2: 2.6845




3C161 2023/09/05 22.33UT FUJI -KISO



T20230906074539




BLK: 2,SNR1: 0.14333 ,SNR2: 0.78870




Frequency (Hz)

F20230906074539




BLK: 2,SNR1:-0.20040 ,SNR2: 0.50061





Frequency (Hz)


0652-130 2023/09/05 22.79UT TOYOKAWA-FUJI



T20230906074539





BLK: 4,SNR1: 0.30096E-01,SNR2: 0.93214





0652-130 2023/09/05 22.79UT TOYOKAWA-KISO



K20230906074536




BLK: 4,SNR1: 0.27780 ,SNR2: 3.6744



F20230906074539





BLK: 2,SNR1:-0.31690 ,SNR2: 0.26700




Frequency (Hz)

K20230906074536




BLK: 2,SNR1: 0.14034 ,SNR2: 1.1018





Frequency (Hz)


0652-130 2023/09/05 22.79UT FUJI -KISO



T20230906075715





BLK: 4,SNR1: 0.19421E-01,SNR2: 0.61188




Frequency (Hz)

F20230906075714




BLK: 4,SNR1: 0.42545E-01,SNR2: 1.2613





Frequency (Hz)


0703+138 2023/09/05 22.98UT TOYOKAWA-FUJI



T20230906075715





BLK: 3,SNR1:-0.11863E-01,SNR2: 0.46424




Frequency (Hz)

K20230906075712




BLK: 3,SNR1: 0.81521 ,SNR2: 2.8942




Frequency (Hz)

0703+138 2023/09/05 22.98UT TOYOKAWA-KISO








F20230906075714




BLK: 1,SNR1:-0.10857 ,SNR2: 0.48150




K20230906075712





BLK: 1,SNR1: 0.20278 ,SNR2: 3.7907




0703+138 2023/09/05 22.98UT FUJI -KISO



T20230906080638




BLK: 3,SNR1: 0.75189E-01,SNR2: 0.64149




Frequency (Hz)

F20230906080637




BLK: 3,SNR1:-0.20486E-01,SNR2: 0.64042





Frequency (Hz)


0713-024 2023/09/05 23.14UT TOYOKAWA-FUJI





T20230906080638




BLK: 4,SNR1: 0.14296E-01,SNR2: 0.59738




K20230906080635





BLK: 4,SNR1: 0.95879 ,SNR2: 7.0062




0713-024 2023/09/05 23.14UT TOYOKAWA-KISO



F20230906080637





BLK: 1,SNR1: 0.42392 ,SNR2: 3.6095




Frequency (Hz)

K20230906080635




BLK: 1,SNR1: 0.30917 ,SNR2: 2.5424





Frequency (Hz)


0713-024 2023/09/05 23.14UT FUJI -KISO



T20230906081650





BLK: 3,SNR1: 0.80186E-02,SNR2: 0.35941




Frequency (Hz)

F20230906081650




BLK: 3,SNR1: 1.1944 ,SNR2: 4.5746





Frequency (Hz)


0723+10 2023/09/05 23.31UT TOYOKAWA-FUJI



T20230906081650





BLK: 3,SNR1: 0.13611 ,SNR2: 1.1082





0723+10 2023/09/05 23.31UT TOYOKAWA-KISO



K20230906081647




BLK: 3,SNR1: 0.19013 ,SNR2: 0.50740



F20230906081650




BLK: 7,SNR1: 0.30736 ,SNR2: 1.3493




Frequency (Hz)

K20230906081647




BLK: 7,SNR1: 0.19288 ,SNR2: 2.2722





Frequency (Hz)


0723+10 2023/09/05 23.31UT FWJ -KISO



T20230906082704





BLK: 3,SNR1: 0.13785 ,SNR2: 0.43225




Frequency (Hz)

F20230906082703




BLK: 3,SNR1: 1.3309 ,SNR2: 6.8637





Frequency (Hz)

0732+33 2023/09/05 23.48UT TOYOKAWA-FUJI








T20230906082704




BLK: 2,SNR1: 0.58752E-01,SNR2: 0.21600




K20230906082701





BLK: 2,SNR1:-0.36944E-01,SNR2: 0.78711




0732+33 2023/09/05 23.48UT TOYOKAWA-KISO



F20230906082703





BLK: 4,SNR1:-0.17903E-01,SNR2: 0.75959




Frequency (Hz)

K20230906082701




BLK: 4,SNR1: 0.96333E-01,SNR2: 0.94075





Frequency (Hz)


0732+33 2023/09/05 23.48UT FUJI -KISO



T20230906083507





BLK:10,SNR1: 0.27363 ,SNR2: 2.0095




Frequency (Hz)

F20230906083507




BLK:10,SNR1:-0.14533 ,SNR2: 0.73706




Frequency (Hz)


0741-06 2023/09/05 23.61UT TOYOKAWA-FUJI



T20230906083507





BLK:13,SNR1: 0.64487 ,SNR2: 3.9160





0741-06 2023/09/05 23.61UT TOYOKAWA-KISO


K20230906083504




BLK:13,SNR1: 0.77834E-01,SNR2: 1.9625



F20230906083507




BLK: 3,SNR1: 1.4217 ,SNR2: 3.2351




Frequency (Hz)

K20230906083504




BLK: 3,SNR1: 0.54352E-01,SNR2: 0.12108





Frequency (Hz)


0741-06 2023/09/05 23.61UT FUJI -KISO





T20230906084451




No.Good Data




FUJI




No.Good Data




0752-200 2023/09/05 23.78UT TOYOKAWA-FUJI



T20230906084451




BLK: 3,SNR1: 0.13631 ,SNR2: 2.1376





0752-200 2023/09/05 23.78UT TOYOKAWA-KISO



K20230906084448




BLK: 3,SNR1: 0.32336 ,SNR2: 1.7073



FUJI





No.Good Data




Frequency (Hz)

K20230906084448




No.Good Data





Frequency (Hz)

0752-200 2023/09/05 23.78UT FUJI -KISO








T20230906085225




BLK: 2, SNR1: 0.31725 , SNR2: 1.3096




F20230906085224





BLK: 2, SNR1: 4.4348 , SNR2: 23.682




3C190 2023/09/05 23.90UT TOYOKAWA-FUJI



T20230906085225





BLK: 2,SNR1: 0.14790 ,SNR2: 2.1761




Frequency (Hz)

K20230906085222




BLK: 2,SNR1: 1.1113 ,SNR2: 8.9561





Frequency (Hz)


3C190 2023/09/05 23.90UT TOYOKAWA-KISO





F20230906085224




BLK: 6,SNR1: 0.49257 ,SNR2: 3.9727




K20230906085222





BLK: 6,SNR1: 0.10095 ,SNR2: 1.4572




3C190 2023/09/05 23.90UT FUJI -KISO



T20230906090449





BLK: 9,SNR1: 2.2234 ,SNR2: 6.6140





3C196 2023/09/06 0.11UT TOYOKAWA-FUJI



F20230906090449




BLK: 9,SNR1: 0.13952 ,SNR2: 1.0379





T20230906090449




BLK: 3,SNR1: 0.82727 ,SNR2: 2.5169




K20230906090446




BLK: 3,SNR1: 1.0389 ,SNR2: 3.9618




3C196 2023/09/06 0.11UT TOYOKAWA-KISO





F20230906090449




BLK: 2,SNR1: 0.30870E-01,SNR2: 1.0850




K20230906090446




BLK: 2,SNR1: 1.8847 ,SNR2: 5.7526




3C196 2023/09/06 0.11UT FUJI -KISO




T20230906091559




BLK: 2,SNR1:-0.21790E-01,SNR2: 0.71688




F20230906091558




BLK: 2,SNR1: 0.57824 ,SNR2: 2.9501




0821+394 2023/09/06 0.29UT TOYOKAWA-FUJI





T20230906091559




BLK: 4,SNR1:-0.12014E-01,SNR2: 0.75623




K20230906091556



BLK: 4,SNR1: 0.33041 ,SNR2: 2.1233





0821+394 2023/09/06 0.29UT TOYOKAWA-KISO








F20230906091558




BLK: 4,SNR1: 0.65838 ,SNR2: 2.9535




K20230906091556




BLK: 4,SNR1: 0.29950 ,SNR2: 2.6187




0821+394 2023/09/06 0.29UT FUJI -KISO





T20230906092740




No.Good Data




FUJI





No.Good Data




0834-19 2023/09/06 0.49UT TOYOKAWA-FUJI



T20230906092740





BLK: 7,SNR1: 0.25887E-01,SNR2: 1.4532




Frequency (Hz)

K20230906092737




BLK: 7,SNR1: 0.38676 ,SNR2: 2.5872





Frequency (Hz)


0834-19 2023/09/06 0.49UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20230906092737




No. Good Data





Frequency (Hz)


0834-19 2023/09/06 0.49UT FUJI -KISO




T20230906093246




BLK: 6,SNR1: 17.815 ,SNR2: 28.274




F20230906093245




BLK: 6,SNR1:-0.91010E-02,SNR2: 0.65289




0839-071 2023/09/06 0.57UT TOYOKAWA-FUJI





T20230906093246




BLK: 9,SNR1: 24.095 ,SNR2: 57.502




K20230906093243




BLK: 9,SNR1: 0.74375 ,SNR2: 3.6672




0839-071 2023/09/06 0.57UT TOYOKAWA-KISO





F20230906093245




BLK: 2,SNR1:-0.19043 ,SNR2: 0.56653




K20230906093243




BLK: 2,SNR1: 1.1544 ,SNR2: 4.0679




0839-071 2023/09/06 0.57UT FUJI -KISO



T20230906094346




BLK: 2,SNR1: 1.7051 ,SNR2: 3.8388




Frequency (Hz)

F20230906094346




BLK: 2,SNR1: 0.43612 ,SNR2: 2.4940




Frequency (Hz)

3C208 2023/09/06 0.76UT TOYOKAWA-FUJI








T20230906094346




BLK: 7,SNR1: 1.3919 ,SNR2: 3.0292




K20230906094343




BLK: 7,SNR1: 0.22403 ,SNR2: 2.0099




3C208 2023/09/06 0.76UT TOYOKAWA-KISO





F20230906094346




BLK: 3,SNR1: 0.37699 ,SNR2: 1.2840




K20230906094343





BLK: 3,SNR1: 0.73579E-01,SNR2: 0.88816




3C208 2023/09/06 0.76UT FUJI -KISO





T20230906100027




BLK: 5,SNR1: 0.11814 ,SNR2: 2.3337




F20230906100026





BLK: 5,SNR1: 0.21720 ,SNR2: 1.0999




3C216 2023/09/06 1.04UT TOYOKAWA-FUJI



T20230906100027





BLK: 6,SNR1: 0.19057 ,SNR2: 2.0152





3C216 2023/09/06 1.04UT TOYOKAWA-KISO


K20230906100024




BLK: 6,SNR1: 0.17774 ,SNR2: 3.8570





F20230906100026




BLK: 2,SNR1:-0.72309E-01,SNR2: 1.6650




K20230906100024





BLK: 2,SNR1: 0.29204 ,SNR2: 7.6212




3C216 2023/09/06 1.04UT FUJI -KISO



T20230906101239





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0919-142 2023/09/06 1.24UT TOYOKAWA-FUJI



T20230906101239




BLK: 7,SNR1: 0.34315 ,SNR2: 0.88021





0919-142 2023/09/06 1.24UT TOYOKAWA-KISO



K20230906101236




BLK: 7,SNR1: 3.6606 ,SNR2: 15.869



FUJI





No. Good Data




Frequency (Hz)

K20230906101236




No. Good Data





Frequency (Hz)

0919-142 2023/09/06 1.24UT FUJI -KISO








T20230906101918




BLK:10,SNR1: 0.11008 ,SNR2: 1.3629




F20230906101918





BLK:10,SNR1: 0.45315 ,SNR2: 0.78781




0926+117 2023/09/06 1.35UT TOYOKAWA-FUJI



T20230906101918





BLK: 5,SNR1: 1.6051 ,SNR2: 7.6073





0926+117 2023/09/06 1.35UT TOYOKAWA-KISO



K20230906101915




BLK: 5,SNR1: 0.97726 ,SNR2: 4.2392



F20230906101918





BLK: 6,SNR1: 0.27707 ,SNR2: 1.7554




Frequency (Hz)

K20230906101915




BLK: 6,SNR1:-0.15280 ,SNR2: 0.0000






Frequency (Hz)




0926+117 2023/09/06 1.35UT FUJI -KISO




T20230906102703




F20230906102702




3C222 2023/09/06 1.48UT TOYOKAWA-FUJI



T20230906102703





BLK:18,SNR1: 25.434 ,SNR2: 40.966





3C222 2023/09/06 1.48UT TOYOKAWA-KISO



K20230906102700




BLK:18,SNR1: 0.15589 ,SNR2: 1.1749



F20230906102702





BLK: 9,SNR1: 0.81944E-01,SNR2: 3.3556




Frequency (Hz)

K20230906102700




BLK: 9,SNR1: 0.92352E-02,SNR2: 0.49313





Frequency (Hz)


3C222 2023/09/06 1.48UT FUJI -KISO



T20230906103403




BLK:14,SNR1: 1.4651 ,SNR2: 11.153




0941-08 2023/09/06 1.60UT TOYOKAWA-FUJI


F20230906103403





BLK:14,SNR1:-0.10927 ,SNR2: 0.91653




Frequency (Hz)



T20230906103403




BLK:15,SNR1: 174.47 ,SNR2: 254.79




0941-08 2023/09/06 1.60UT TOYOKAWA-KISO


K20230906103400



BLK:15,SNR1: 0.42831 ,SNR2: 1.6337




Frequency (Hz)







F20230906103403




BLK: 3,SNR1: 0.33597E-01,SNR2: 0.70995




K20230906103400




BLK: 3,SNR1: 0.81374E-01,SNR2: 2.8564




0941-08 2023/09/06 1.60UT FUJI -KISO





T20230906104225




BLK:19,SNR1: 2.4749 ,SNR2: 17.626




F20230906104224




BLK:19,SNR1:-0.16446 ,SNR2: 0.76973




3C230 2023/09/06 1.73UT TOYOKAWA-FUJI





T20230906104225




BLK:34,SNR1: 1.5445 ,SNR2: 12.186




K20230906104222




BLK:34,SNR1: 0.40902 ,SNR2: 3.2763




3C230 2023/09/06 1.73UT TOYOKAWA-KISO





F20230906104224




BLK:15,SNR1: 0.19508 ,SNR2: 1.4267




K20230906104222




BLK:15,SNR1: 0.54282 ,SNR2: 3.3831




3C230 2023/09/06 1.73UT FUJI -KISO




T20230906105631




BLK: 8, SNR1: 0.25537 , SNR2: 3.5660




F20230906105631




BLK: 8, SNR1: 0.36075 , SNR2: 2.8055




3C236 2023/09/06 1.97UT TOYOKAWA-FUJI



T20230906105631




BLK:11,SNR1: 3.7671 ,SNR2: 7.4070





3C236 2023/09/06 1.97UT TOYOKAWA-KISO



K20230906105628




BLK:11,SNR1: 0.19349 ,SNR2: 1.4586




F20230906105631




BLK: 4,SNR1: 0.12247E-01,SNR2: 1.4413




K20230906105628





BLK: 4,SNR1: 0.32138 ,SNR2: 3.5229




3C236 2023/09/06 1.97UT FUJI -KISO




T20230906110441




BLK: 4,SNR1: 0.25732 ,SNR2: 1.0311




F20230906110440



BLK: 4,SNR1:-0.49196E-01,SNR2: 1.9849





1011+110 2023/09/06 2.11UT TOYOKAWA-FUJI






T20230906110441





BLK: 3,SNR1: 0.48196E-01,SNR2: 0.50627





1011+110 2023/09/06 2.11UT TOYOKAWA-KISO


K20230906110439




BLK: 3,SNR1: 3.7395 ,SNR2: 14.800





F20230906110440




BLK: 3,SNR1: 0.21677E-01,SNR2: 1.9535




K20230906110439




BLK: 3,SNR1: 0.36592 ,SNR2: 6.3350




1011+110 2023/09/06 2.11UT FUJI -KISO




T20230906111222




BLK:21,SNR1: 2.6078 ,SNR2: 6.9383




F20230906111222




BLK:21,SNR1: 0.19199 ,SNR2: 1.5305




3C241 2023/09/06 2.23UT TOYOKAWA-FUJI





T20230906111222




BLK:29,SNR1: 2.8717 ,SNR2: 4.4311




K20230906111220




BLK:29,SNR1: 0.61833 ,SNR2: 2.1857




3C241 2023/09/06 2.23UT TOYOKAWA-KISO





F20230906111222




BLK:22,SNR1: 0.18314 ,SNR2: 1.5777




K20230906111220





BLK:22,SNR1: 0.68033 ,SNR2: 2.6879




3C241 2023/09/06 2.23UT FUJI -KISO




T20230906112352




BLK: 5,SNR1: 0.21566 ,SNR2: 1.7210




F20230906112351





BLK: 5,SNR1:-0.10724 ,SNR2: 1.7471




1031-11 2023/09/06 2.43UT TOYOKAWA-FUJI





T20230906112352




BLK:13,SNR1: 0.26844 ,SNR2: 2.2094




K20230906112350




BLK:13,SNR1: 0.20834 ,SNR2: 0.81976




1031-11 2023/09/06 2.43UT TOYOKAWA-KISO



F20230906112351





BLK: 1,SNR1:-0.13453 ,SNR2: 0.79194




Frequency (Hz)

K20230906112350




BLK: 1,SNR1: 0.24583 ,SNR2: 1.4718




Frequency (Hz)

1031-11 2023/09/06 2.43UT FUJI -KISO






T20230906112825




BLK:12,SNR1: 8.4419 ,SNR2: 34.094




1035-058 2023/09/06 2.50UT TOYOKAWA-FUJI


F20230906112824




BLK:12,SNR1: 0.11392 ,SNR2: 2.5913




Frequency (Hz)



T20230906112825





BLK: 4,SNR1: 10.708 ,SNR2: 145.96





1035-058 2023/09/06 2.50UT TOYOKAWA-KISO


K20230906112823




BLK: 4,SNR1: 0.81922 ,SNR2: 3.9932



F20230906112824





BLK: 3,SNR1: 0.44415E-01,SNR2: 0.52965





1035-058 2023/09/06 2.50UT FUJI -KISO



K20230906112823




BLK: 3,SNR1: 0.21026 ,SNR2: 2.6544




T20230906113738




BLK: 7,SNR1: 30.308 ,SNR2: 66.044




F20230906113738





BLK: 7,SNR1:-0.32343E-01,SNR2: 0.67443




1044-008 2023/09/06 2.66UT TOYOKAWA-FUJI





T20230906113738




BLK: 5,SNR1: 72.094 ,SNR2: 152.84




K20230906113736





BLK: 5,SNR1: -0.90311E-01,SNR2: 0.43761




1044-008 2023/09/06 2.66UT TOYOKAWA-KISO





F20230906113738




BLK: 6,SNR1: 0.69234E-01,SNR2: 2.1606




K20230906113736




BLK: 6,SNR1: 0.16865 ,SNR2: 1.2288




1044-008 2023/09/06 2.66UT FUJI -KISO



T20230906114842




BLK:20,SNR1:-0.62420E-01,SNR2: 1.0520




1055+01 2023/09/06 2.84UT TOYOKAWA-FUJI


F20230906114842




BLK:20,SNR1: 9.8969 ,SNR2: 28.987




Frequency (Hz)




T20230906114842




BLK: 7,SNR1: 0.38835E-03,SNR2: 1.2947




K20230906114840



BLK: 7,SNR1: 22.571 ,SNR2: 36.056





1055+01 2023/09/06 2.84UT TOYOKAWA-KISO







F20230906114842




BLK: 8,SNR1: 7.0123 ,SNR2: 18.202




K20230906114840





BLK: 8,SNR1: 7.0893 ,SNR2: 26.104




1055+01 2023/09/06 2.84UT FUJI -KISO




T20230906120000




BLK: 5,SNR1: 0.39706 ,SNR2: 1.2853




F20230906115959





BLK: 5,SNR1: 0.11507 ,SNR2: 0.45507




1107+109 2023/09/06 3.03UT TOYOKAWA-FUJI




T20230906120000




BLK: 4,SNR1:-0.41538E-01,SNR2: 1.1208




K20230906115958




BLK: 4,SNR1: 0.66649E-01,SNR2: 0.75218




1107+109 2023/09/06 3.03UT TOYOKAWA-KISO





F20230906115959




BLK: 4,SNR1: 0.41285 ,SNR2: 0.89381




K20230906115958




BLK: 4,SNR1: 0.78653E-01,SNR2: 2.0284




1107+109 2023/09/06 3.03UT FUJI -KISO




T20230906120937




BLK:13,SNR1: 4.1399 ,SNR2: 11.479




F20230906120937




BLK:13,SNR1: 0.24078 ,SNR2: 4.6338




3C255 2023/09/06 3.19UT TOYOKAWA-FUJI




T20230906120937




BLK:26,SNR1: 2.9108 ,SNR2: 17.086




K20230906120935




BLK:26,SNR1: 0.64016 ,SNR2: 2.4055




3C255 2023/09/06 3.19UT TOYOKAWA-KISO



F20230906120937




BLK:20,SNR1: 0.24454 ,SNR2: 3.5347





3C255 2023/09/06 3.19UT FUJI -KISO



K20230906120935




BLK:20,SNR1: 0.62599 ,SNR2: 4.1730



T20230906122015





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

1127-14 2023/09/06 3.37UT TOYOKAWA-FUJI








T20230906122015




BLK:22,SNR1: 69.098 ,SNR2: 98.086




K20230906122013





BLK:22,SNR1: 0.45070 ,SNR2: 1.5398




1127-14 2023/09/06 3.37UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20230906122013




No.Good Data




Frequency (Hz)


1127-14 2023/09/06 3.37UT FUJI -KISO




T20230906123335




BLK:12,SNR1: 5.3012 ,SNR2: 19.684




F20230906123334





BLK:12,SNR1: 0.57529E-01,SNR2: 1.4769




3C263.1 2023/09/06 3.59UT TOYOKAWA-FUJI





T20230906123335




BLK:13,SNR1: 2.3934 ,SNR2: 17.813




K20230906123333




BLK:13,SNR1: 0.21625 ,SNR2: 1.1027




3C263.1 2023/09/06 3.59UT TOYOKAWA-KISO



F20230906123334





BLK: 5,SNR1: 0.52269E-01,SNR2: 1.2988





3C263.1 2023/09/06 3.59UT FUJI -KISO



K20230906123333




BLK: 5,SNR1: 0.84161 ,SNR2: 2.8296





T20230906124002




BLK: 8,SNR1: 0.69359 ,SNR2: 3.1609




F20230906124001




BLK: 8,SNR1: 0.17045 ,SNR2: 1.1038




3C267 2023/09/06 3.70UT TOYOKAWA-FUJI





T20230906124002




BLK:13,SNR1: 0.89658 ,SNR2: 8.7182




K20230906124000





BLK:13,SNR1: 0.43421 ,SNR2: 1.3848




3C267 2023/09/06 3.70UT TOYOKAWA-KISO



F20230906124001





BLK: 6,SNR1: 0.21486 ,SNR2: 3.7200





3C267 2023/09/06 3.70UT FUJI -KISO

K20230906124000





BLK: 6,SNR1: 0.28303 ,SNR2: 2.3865








T20230906125917




BLK: 1,SNR1: 0.18895 ,SNR2: 5.9744




F20230906125917






BLK: 1,SNR1:-0.19698E-01,SNR2: 0.53509






1206+439 2023/09/06 4.02UT TOYOKAWA-FUJI




T20230906125917





KISO




1206+439 2023/09/06 4.02UT TOYOKAWA-KISO



F20230906125917





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1206+439 2023/09/06 4.02UT FUJI -KISO



T20230906130550





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1213-17 2023/09/06 4.13UT TOYOKAWA-FUJI





T20230906130550




BLK: 5,SNR1:-0.51652E-02,SNR2: 3.5343




K20230906130548




BLK: 5,SNR1:-0.39716E-01,SNR2: 0.91317




1213-17 2023/09/06 4.13UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20230906130548




No.Good Data





Frequency (Hz)


1213-17 2023/09/06 4.13UT FUJI -KISO




T20230906131907




BLK:25,SNR1: 3.6888 ,SNR2: 25.598




F20230906131906




BLK:25,SNR1:-0.38420E-01,SNR2: 1.4451




3C273 2023/09/06 4.35UT TOYOKAWA-FUJI





T20230906131907




BLK:29,SNR1: 3.6219 ,SNR2: 25.917




K20230906131905



BLK:29,SNR1: 0.90092 ,SNR2: 8.3270





3C273 2023/09/06 4.35UT TOYOKAWA-KISO






F20230906131906





BLK:22,SNR1:-0.53578E-01,SNR2: 1.3387





3C273 2023/09/06 4.35UT FUJI -KISO



K20230906131905




BLK:22,SNR1: 1.0796 ,SNR2: 5.8314





T20230906133218




BLK:12,SNR1: 0.27704 ,SNR2: 1.6176




F20230906133217





BLK:12,SNR1: 0.27929 ,SNR2: 1.4829




3C275 2023/09/06 4.57UT TOYOKAWA-FUJI



T20230906133218





BLK: 7,SNR1: 0.12747 ,SNR2: 3.0870




Frequency (Hz)

K20230906133216




BLK: 7,SNR1: 0.16297 ,SNR2: 1.0863




Frequency (Hz)


3C275 2023/09/06 4.57UT TOYOKAWA-KISO



F20230906133217





BLK: 1,SNR1: 1.8910 ,SNR2: 3.6124




Frequency (Hz)

3C275 2023/09/06 4.57UT FUJI -KISO


K20230906133216





BLK: 1,SNR1: 0.26971 ,SNR2: 1.2155




Frequency (Hz)



T20230906133823





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1245-19 2023/09/06 4.67UT TOYOKAWA-FUJI





T20230906133823




BLK:21,SNR1: 0.28957 ,SNR2: 1.3748




K20230906133821





BLK:21,SNR1: 0.19304 ,SNR2: 0.80043




1245-19 2023/09/06 4.67UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20230906133821




No.Good Data




Frequency (Hz)


1245-19 2023/09/06 4.67UT FUJI -KISO




T20230906134607




BLK:13,SNR1: 0.73174 ,SNR2: 6.5595




F20230906134606



BLK:13,SNR1: 0.19545 ,SNR2: 2.5613





3C279 2023/09/06 4.80UT TOYOKAWA-FUJI








T20230906134607




BLK: 8,SNR1: 0.87503 ,SNR2: 4.5886




K20230906134605





BLK: 8,SNR1: 0.10774 ,SNR2: 1.2735




3C279 2023/09/06 4.80UT TOYOKAWA-KISO





F20230906134606




BLK: 5,SNR1: 3.3301 ,SNR2: 21.382




K20230906134605





BLK: 5,SNR1: 0.17039 ,SNR2: 2.2643




3C279 2023/09/06 4.80UT FUJI -KISO



T20230906140136





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C283 2023/09/06 5.05UT TOYOKAWA-FUJI





T20230906140136




BLK:33,SNR1: 0.31350 ,SNR2: 2.9418




K20230906140134





BLK:33,SNR1: 0.34143 ,SNR2: 1.5232




3C283 2023/09/06 5.05UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20230906140134




No.Good Data





Frequency (Hz)


3C283 2023/09/06 5.05UT FUJI -KISO



T20230906140555





BLK: 4,SNR1: 24.169 ,SNR2: 196.40




Frequency (Hz)

F20230906140554




BLK: 4,SNR1: 0.33133 ,SNR2: 2.7819






Frequency (Hz)




1313+453 2023/09/06 5.13UT TOYOKAWA-FUJI




T20230906140555






KISO






1313+453 2023/09/06 5.13UT TOYOKAWA-KISO




F20230906140554



KISO




1313+453 2023/09/06 5.13UT FUJI -KISO








T20230906141601




BLK:16,SNR1: 0.70487 ,SNR2: 5.1250




F20230906141601





BLK:16,SNR1: 0.19524 ,SNR2: 1.8064




1323+32 2023/09/06 5.29UT TOYOKAWA-FUJI



T20230906141601





BLK:10,SNR1: 0.58510 ,SNR2: 5.3914




Frequency (Hz)

K20230906141559




BLK:10,SNR1: 2.3035 ,SNR2: 8.8899





Frequency (Hz)


1323+32 2023/09/06 5.29UT TOYOKAWA-KISO



F20230906141601





BLK: 4,SNR1:-0.21425E-01,SNR2: 0.91358




Frequency (Hz)

K20230906141559




BLK: 4,SNR1: 1.5590 ,SNR2: 10.201





Frequency (Hz)


1323+32 2023/09/06 5.29UT FUJI -KISO





T20230906142051




BLK:26,SNR1: 4.3560 ,SNR2: 11.483




F20230906142050





BLK:26,SNR1: 0.40769 ,SNR2: 2.5621




3C286 2023/09/06 5.38UT TOYOKAWA-FUJI





T20230906142051




BLK:10,SNR1: 3.8270 ,SNR2: 25.720




K20230906142053





BLK:10,SNR1: 0.33651 ,SNR2: 2.1179




3C286 2023/09/06 5.38UT TOYOKAWA-KISO





F20230906142050




BLK:11,SNR1: 0.61607 ,SNR2: 2.9249




K20230906142053




BLK:11,SNR1: 0.91245 ,SNR2: 4.7603




3C286 2023/09/06 5.38UT FUJI -KISO





T20230906143718




BLK: 7,SNR1: 0.36656 ,SNR2: 2.8923




F20230906143718




BLK: 7,SNR1: 0.23465 ,SNR2: 1.4960




1345+12 2023/09/06 5.65UT TOYOKAWA-FUJI



T20230906143718





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1345+12 2023/09/06 5.65UT TOYOKAWA-KISO






F20230906143718





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1345+12 2023/09/06 5.65UT FUJI -KISO




T20230906144739




BLK: 5,SNR1:-0.52242E-01,SNR2: 1.0534




F20230906144738





BLK: 5,SNR1: 0.95769 ,SNR2: 2.5189




1355+01 2023/09/06 5.82UT TOYOKAWA-FUJI



T20230906144739





BLK: 5,SNR1: 0.23362 ,SNR2: 1.1575




Frequency (Hz)

K20230906144738




BLK: 5,SNR1: 0.76229 ,SNR2: 4.3817





Frequency (Hz)


1355+01 2023/09/06 5.82UT TOYOKAWA-KISO



F20230906144738





BLK: 1,SNR1: 0.16194 ,SNR2: 0.47625




Frequency (Hz)

K20230906144738




BLK: 1,SNR1: 0.12214 ,SNR2: 2.3106




Frequency (Hz)


1355+01 2023/09/06 5.82UT FUJI -KISO




T20230906150849




BLK:18,SNR1: 0.65165 ,SNR2: 4.5266




F20230906150849




BLK:18,SNR1: 0.18432 ,SNR2: 0.87323




3C298 2023/09/06 6.17UT TOYOKAWA-FUJI




T20230906150849




BLK:23,SNR1: 0.53854 ,SNR2: 4.3064




K20230906150848




BLK:23,SNR1: 0.36916 ,SNR2: 2.3909




3C298 2023/09/06 6.17UT TOYOKAWA-KISO



F20230906150849





BLK:12,SNR1: 0.10310 ,SNR2: 1.0886




Frequency (Hz)

K20230906150848




BLK:12,SNR1: 0.18649 ,SNR2: 2.4294





Frequency (Hz)


3C298 2023/09/06 6.17UT FUJI -KISO



T20230906152033





BLK: 3,SNR1: 0.20085 ,SNR2: 1.4595




Frequency (Hz)

F20230906152032




BLK: 3,SNR1: 1.9776 ,SNR2: 7.3187





Frequency (Hz)

1428-03 2023/09/06 6.37UT TOYOKAWA-FUJI






T20230906152033





BLK: 2,SNR1: 0.13438 ,SNR2: 0.57132




Frequency (Hz)

K20230906152032




BLK: 2,SNR1: 0.10806 ,SNR2: 1.8720




Frequency (Hz)


1428-03 2023/09/06 6.37UT TOYOKAWA-KISO





F20230906152032




BLK: 3,SNR1: 4.6965 ,SNR2: 16.529




K20230906152032





BLK: 3,SNR1: 0.40771E-01,SNR2: 1.0704




1428-03 2023/09/06 6.37UT FUJI -KISO



T20230906152914





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1436-16 2023/09/06 6.52UT TOYOKAWA-FUJI



T20230906152914





BLK: 3,SNR1: 0.18298 ,SNR2: 1.2602




Frequency (Hz)

K20230906152913




BLK: 3,SNR1: 0.47357 ,SNR2: 2.0774






Frequency (Hz)




1436-16 2023/09/06 6.52UT TOYOKAWA-KISO




FUJI





K20230906152913




1436-16 2023/09/06 6.52UT FUJI -KISO




T20230906154537




BLK: 5,SNR1: 0.30302 ,SNR2: 1.7611




F20230906154537





BLK: 5,SNR1:-0.11972 ,SNR2: 1.7594




1453-10 2023/09/06 6.79UT TOYOKAWA-FUJI



T20230906154537





BLK: 5,SNR1: 0.50420 ,SNR2: 1.8756




Frequency (Hz)

K20230906154536




BLK: 5,SNR1: 0.20617 ,SNR2: 1.5418





Frequency (Hz)


1453-10 2023/09/06 6.79UT TOYOKAWA-KISO





F20230906154537




BLK: 4,SNR1: 12.402 ,SNR2: 23.073




K20230906154536



BLK: 4,SNR1: 0.28693E-01,SNR2: 0.73340





1453-10 2023/09/06 6.79UT FUJI -KISO






T20230906160030





BLK: 6,SNR1: 0.72827E-01,SNR2: 1.2592




Frequency (Hz)

F20230906160029




BLK: 6,SNR1: 0.13731 ,SNR2: 1.1152





Frequency (Hz)


1508-05 2023/09/06 7.04UT TOYOKAWA-FUJI





T20230906160030




BLK: 3,SNR1: 0.10305 ,SNR2: 0.49497




K20230906160029




BLK: 3,SNR1: 0.80683E-01,SNR2: 1.0706




1508-05 2023/09/06 7.04UT TOYOKAWA-KISO



F20230906160029





BLK: 2,SNR1: 0.92282 ,SNR2: 3.1710




Frequency (Hz)

K20230906160029




BLK: 2,SNR1:-0.15667 ,SNR2: 0.20073




Frequency (Hz)


1508-05 2023/09/06 7.04UT FUJI -KISO



T20230906160930




BLK: 4,SNR1: 0.13751 ,SNR2: 0.73240




Frequency (Hz)

F20230906160930




BLK: 4,SNR1:-0.10240 ,SNR2: 2.0734





Frequency (Hz)


3C318 2023/09/06 7.19UT TOYOKAWA-FUJI



T20230906160930




BLK: 8,SNR1: 0.13606 ,SNR2: 0.56462




Frequency (Hz)

K20230906160929




BLK: 8,SNR1: 0.13984 ,SNR2: 2.3426





Frequency (Hz)


3C318 2023/09/06 7.19UT TOYOKAWA-KISO



F20230906160930





BLK: 3,SNR1: 0.20527E-01,SNR2: 1.6611




Frequency (Hz)

K20230906160929




BLK: 3,SNR1: 0.86721E-01,SNR2: 0.48446





Frequency (Hz)


3C318 2023/09/06 7.19UT FUJI -KISO



T20230906161517




BLK: 6,SNR1: 0.41028 ,SNR2: 3.3200




Frequency (Hz)

F20230906161516




BLK: 6,SNR1: 0.25921E-01,SNR2: 1.0975





Frequency (Hz)


1523+03 2023/09/06 7.28UT TOYOKAWA-FUJI





T20230906161517




BLK: 6,SNR1: 0.60295 ,SNR2: 6.9322




K20230906161516



BLK: 6,SNR1: 0.10054 ,SNR2: 2.4744





1523+03 2023/09/06 7.28UT TOYOKAWA-KISO






F20230906161516





BLK: 1,SNR1: 0.87542E-01,SNR2: 0.0000




Frequency (Hz)

K20230906161516




BLK: 1,SNR1: 0.58368 ,SNR2: 2.7381





Frequency (Hz)


1523+03 2023/09/06 7.28UT FUJI -KISO



T20230906162656




BLK: 2,SNR1: 0.59785E-01,SNR2: 1.3343




Frequency (Hz)

F20230906162656




BLK: 2,SNR1: 0.48747 ,SNR2: 2.1616





Frequency (Hz)


1535+139 2023/09/06 7.48UT TOYOKAWA-FUJI



T20230906162656





BLK: 2,SNR1: 0.89369E-01,SNR2: 1.1776




Frequency (Hz)

K20230906162655




BLK: 2,SNR1: 0.98559E-01,SNR2: 1.1291




Frequency (Hz)


1535+139 2023/09/06 7.48UT TOYOKAWA-KISO



F20230906162656





BLK: 3,SNR1: 0.62347 ,SNR2: 3.9380




Frequency (Hz)

K20230906162655




BLK: 3,SNR1: 0.24396 ,SNR2: 0.84126





Frequency (Hz)


1535+139 2023/09/06 7.48UT FUJI -KISO



T20230906163720





BLK: 3,SNR1:-0.27910E-01,SNR2: 0.52539




Frequency (Hz)

F20230906163719




BLK: 3,SNR1:-0.15665,SNR2: 1.3860





Frequency (Hz)


1545-12 2023/09/06 7.65UT TOYOKAWA-FUJI



T20230906163720





BLK: 3,SNR1:-0.10736 ,SNR2: 0.18635




Frequency (Hz)

K20230906163719




BLK: 3,SNR1: 1.0702 ,SNR2: 4.4102





Frequency (Hz)


1545-12 2023/09/06 7.65UT TOYOKAWA-KISO



F20230906163719





BLK: 2,SNR1:-0.40199E-01,SNR2: 1.7636




Frequency (Hz)

K20230906163719




BLK: 2,SNR1: 0.23100E-01,SNR2: 1.1919





Frequency (Hz)


1545-12 2023/09/06 7.65UT FUJI -KISO



T20230906165824




BLK: 4,SNR1:-0.35889E-01,SNR2: 2.8786




Frequency (Hz)

F20230906165824




BLK: 4,SNR1: 0.12362 ,SNR2: 0.86490




Frequency (Hz)

1607+26 2023/09/06 8.00UT TOYOKAWA-FUJI






T20230906165824





BLK: 3,SNR1: 0.47424E-01,SNR2: 1.5566




Frequency (Hz)

K20230906165823




BLK: 3,SNR1: 0.45358 ,SNR2: 5.6206




Frequency (Hz)


1607+26 2023/09/06 8.00UT TOYOKAWA-KISO



F20230906165824




BLK: 4,SNR1: 0.15700 ,SNR2: 1.0178




Frequency (Hz)

K20230906165823



BLK: 4,SNR1:-0.59905E-01,SNR2: 0.98151



Frequency (Hz)

1607+26 2023/09/06 8.00UT FUJI -KISO

