




T20230907062207





BLK: 5,SNR1:-0.58196E-02,SNR2: 0.85951




Frequency (Hz)

F20230907062207




BLK: 5,SNR1: 0.82496 ,SNR2: 3.4947





Frequency (Hz)


0531+194 2023/09/06 21.40UT TOYOKAWA-FUJI



T20230907062207





BLK: 1,SNR1: 0.53255E-01,SNR2: 2.2766





0531+194 2023/09/06 21.40UT TOYOKAWA-KISO


K20230907062207






BLK: 1,SNR1: 0.36381 ,SNR2: 1.6622









BLK: 3,SNR1: 5.2658 ,SNR2: 7.1907





BLK: 3,SNR1: 0.14628 ,SNR2: 0.64560




0531+194 2023/09/06 21.40UT FUJI -KISO



T20230907063026





BLK:18,SNR1: 1.1216 ,SNR2: 5.6253




Frequency (Hz)

3C147 2023/09/06 21.54UT TOYOKAWA-FUJI


F20230907063026





BLK:18,SNR1: 0.25768 ,SNR2: 1.0925




Frequency (Hz)



T20230907063026





BLK:32,SNR1: 1.0971 ,SNR2: 5.2556




Frequency (Hz)

K20230907063026




BLK:32,SNR1: 0.54337E-01,SNR2: 1.5600





Frequency (Hz)


3C147 2023/09/06 21.54UT TOYOKAWA-KISO



F20230907063026





BLK:10,SNR1: 0.73543E-01,SNR2: 0.80260




Frequency (Hz)

K20230907063026




BLK:10,SNR1: 0.26678 ,SNR2: 1.6048





Frequency (Hz)


3C147 2023/09/06 21.54UT FUJI -KISO



T20230907063838





BLK: 9,SNR1: 5.2333 ,SNR2: 43.042




Frequency (Hz)

F20230907063838




BLK: 9,SNR1: 0.82654 ,SNR2: 6.4021





Frequency (Hz)


0548+16 2023/09/06 21.67UT TOYOKAWA-FUJI



T20230907063838





BLK: 5,SNR1: 1.7082 ,SNR2: 19.575




Frequency (Hz)

K20230907063838




BLK: 5,SNR1: 0.63519 ,SNR2: 3.0216





Frequency (Hz)


0548+16 2023/09/06 21.67UT TOYOKAWA-KISO



F20230907063838




BLK: 2,SNR1:-0.10806 ,SNR2: 2.6932




Frequency (Hz)

K20230907063838




BLK: 2,SNR1: 0.29300 ,SNR2: 1.6581





Frequency (Hz)


0548+16 2023/09/06 21.67UT FUJI -KISO



T20230907064249





BLK: 2,SNR1: 13.436 ,SNR2: 124.10




Frequency (Hz)

F20230907064248




BLK: 2,SNR1:-0.10831E-01,SNR2: 0.42952





Frequency (Hz)

0552+12 2023/09/06 21.74UT TOYOKAWA-FUJI






T20230907064249





BLK: 4,SNR1: 68.851 ,SNR2: 499.20




Frequency (Hz)

K20230907064249




BLK: 4,SNR1: 0.38915 ,SNR2: 1.2665





Frequency (Hz)


0552+12 2023/09/06 21.74UT TOYOKAWA-KISO



F20230907064248





BLK: 2,SNR1: 0.66467 ,SNR2: 2.7553




Frequency (Hz)

K20230907064249




BLK: 2,SNR1: 0.28558 ,SNR2: 4.9113




Frequency (Hz)

0552+12 2023/09/06 21.74UT FUJI -KISO




T20230907064716



Time (sec)




BLK: 4,SNR1: 0.70305E-01,SNR2: 1.2862



Frequency (Hz)


F20230907064716



Time (sec)




BLK: 4,SNR1: 0.69767 ,SNR2: 1.8368





Frequency (Hz)


0556+191 2023/09/06 21.82UT TOYOKAWA-FUJI



T20230907064716





BLK: 2,SNR1: 1.3697 ,SNR2: 3.0533




Frequency (Hz)

K20230907064716




BLK: 2,SNR1: 0.21004 ,SNR2: 3.5092




Frequency (Hz)


0556+191 2023/09/06 21.82UT TOYOKAWA-KISO



F20230907064716





BLK: 4,SNR1: 0.43630 ,SNR2: 5.4092




Frequency (Hz)

K20230907064716




BLK: 4,SNR1: 0.60727 ,SNR2: 4.8427





Frequency (Hz)


0556+191 2023/09/06 21.82UT FUJI -KISO



T20230907065148





BLK: 4,SNR1: 0.13590 ,SNR2: 0.64451




Frequency (Hz)

F20230907065148




BLK: 4,SNR1: 0.54915 ,SNR2: 7.1562





Frequency (Hz)


3C152 2023/09/06 21.89UT TOYOKAWA-FUJI



T20230907065148




BLK: 2,SNR1:-0.31792E-01,SNR2: 0.33724




Frequency (Hz)

3C152 2023/09/06 21.89UT TOYOKAWA-KISO


K20230907065148





BLK: 2,SNR1: 1.1744 ,SNR2: 5.0945




Frequency (Hz)





F20230907065148




BLK: 1,SNR1: 0.36212 ,SNR2: 0.43477




K20230907065148



BLK: 1,SNR1:-0.95840E-01,SNR2: 0.55395





3C152 2023/09/06 21.89UT FUJI -KISO






T20230907071410





BLK: 5,SNR1: 0.17766 ,SNR2: 1.5333




Frequency (Hz)

3C161 2023/09/06 22.28UT TOYOKAWA-FUJI


F20230907071410





BLK: 5,SNR1:-0.16766 ,SNR2: 1.1248




Frequency (Hz)



T20230907071410





BLK: 8,SNR1: 0.11958 ,SNR2: 3.6840




Frequency (Hz)

K20230907071410




BLK: 8,SNR1: 0.10651 ,SNR2: 2.0594





Frequency (Hz)


3C161 2023/09/06 22.26UT TOYOKAWA-KISO



F20230907071410




BLK: 4,SNR1:-0.10783 ,SNR2: 0.14446




Frequency (Hz)

K20230907071410




BLK: 4,SNR1: 0.82850E-01,SNR2: 0.65231





Frequency (Hz)


3C161 2023/09/06 22.26UT FUJI -KISO



T20230907074143





BLK: 8,SNR1: 8.0099 ,SNR2: 19.331




Frequency (Hz)

F20230907074142




BLK: 8,SNR1: 61.271 ,SNR2: 99.506




Frequency (Hz)


0652-130 2023/09/06 22.72UT TOYOKAWA-FUJI





T20230907074143




BLK: 8,SNR1: 8.0099 ,SNR2: 19.331




K20230907074143





BLK: 8,SNR1: 2.1644 ,SNR2: 9.7503




0652-130 2023/09/06 22.72UT TOYOKAWA-KISO



F20230907074142





BLK: 9,SNR1: 54.213 ,SNR2: 88.762




Frequency (Hz)

K20230907074143




BLK: 9,SNR1: 1.9362 ,SNR2: 7.6371





Frequency (Hz)


0652-130 2023/09/06 22.72UT FUJI -KISO



T20230907075319




BLK: 3,SNR1:-0.20890 ,SNR2: 0.48038E-01




Frequency (Hz)

F20230907075319




BLK: 3,SNR1: 0.24866 ,SNR2: 4.3622





Frequency (Hz)


0703+138 2023/09/06 22.92UT TOYOKAWA-FUJI





T20230907075319




No.Good Data




K20230907075319



No.Good Data





0703+138 2023/09/06 22.92UT TOYOKAWA-KISO






F20230907075319





BLK: 4,SNR1: 1.1846 ,SNR2: 6.7401




Frequency (Hz)

K20230907075319




BLK: 4,SNR1: 0.34407 ,SNR2: 1.5259





Frequency (Hz)


0703+138 2023/09/06 22.92UT FUJI -KISO





T20230907080242




BLK: 3,SNR1: 0.22597E-01,SNR2: 0.73374




F20230907080241





BLK: 3,SNR1: 0.19416 ,SNR2: 1.3520




0713-024 2023/09/06 23.07UT TOYOKAWA-FUJI



T20230907080242





BLK: 1,SNR1: 0.27063 ,SNR2: 0.74700




Frequency (Hz)

K20230907080242




BLK: 1,SNR1: 0.88454 ,SNR2: 4.7145




Frequency (Hz)


0713-024 2023/09/06 23.07UT TOYOKAWA-KISO



F20230907080241




BLK: 2,SNR1:-0.68710E-01,SNR2: 0.59587




Frequency (Hz)

K20230907080242




BLK: 2,SNR1: 0.27860 ,SNR2: 1.4192





Frequency (Hz)


0713-024 2023/09/06 23.07UT FUJI -KISO



T20230907081254





BLK: 4,SNR1: 0.21953 ,SNR2: 1.2850




Frequency (Hz)

F20230907081254




BLK: 4,SNR1: 0.12573 ,SNR2: 1.0560




Frequency (Hz)


0723+10 2023/09/06 23.24UT TOYOKAWA-FUJI



T20230907081254




BLK:10,SNR1: 0.17170E-01,SNR2: 1.6654




Frequency (Hz)

K20230907081254




BLK:10,SNR1: 0.32310 ,SNR2: 1.5040





Frequency (Hz)


0723+10 2023/09/06 23.24UT TOYOKAWA-KISO



F20230907081254





BLK: 4,SNR1: 0.36651 ,SNR2: 2.7550




Frequency (Hz)

K20230907081254




BLK: 4,SNR1: 0.11843 ,SNR2: 0.36322




Frequency (Hz)


0723+10 2023/09/06 23.24UT FUJI -KISO




T20230907082308




BLK: 3,SNR1:-0.13278 ,SNR2: 0.77339




F20230907082307



BLK: 3,SNR1: 0.78121 ,SNR2: 5.2409





0732+33 2023/09/06 23.41UT TOYOKAWA-FUJI






T20230907082308




BLK: 3,SNR1: 0.12533 ,SNR2: 0.44279




Frequency (Hz)

K20230907082308




BLK: 3,SNR1: 0.31594 ,SNR2: 2.3434





Frequency (Hz)


0732+33 2023/09/06 23.41UT TOYOKAWA-KISO



F20230907082307





BLK: 1,SNR1: 0.91434E-01,SNR2: 6.5390




Frequency (Hz)

K20230907082308





BLK: 1,SNR1: 0.24691 ,SNR2: 0.57703





Frequency (Hz)

0732+33 2023/09/06 23.41UT FUJI -KISO







BLK: 7,SNR1: 0.75101 ,SNR2: 4.9938




BLK: 7,SNR1:-0.15259 ,SNR2: 0.84570





0741-06 2023/09/06 23.55UT TOYOKAWA-FUJI







BLK:11,SNR1: 0.17500 ,SNR2: 2.6396




BLK:11,SNR1: 0.18117 ,SNR2: 0.58119




0741-06 2023/09/06 23.55UT TOYOKAWA-KISO





F20230907083110




BLK: 5,SNR1: 0.68095 ,SNR2: 1.2894




K20230907083111





BLK: 5,SNR1: 0.56147 ,SNR2: 3.9304




0741-06 2023/09/06 23.55UT FUJI -KISO



T20230907084829





BLK: 8,SNR1: 9.9442 ,SNR2: 17.235





3C190 2023/09/06 23.84UT TOYOKAWA-FUJI


F20230907084828




BLK: 8,SNR1: 0.11703 ,SNR2: 1.6638





T20230907084829




BLK: 4,SNR1: 0.22240 ,SNR2: 2.1224




K20230907084829





BLK: 4,SNR1: 1.7322 ,SNR2: 5.5611




3C190 2023/09/06 23.84UT TOYOKAWA-KISO





F20230907084828




BLK: 3,SNR1: 0.66633 ,SNR2: 6.3035




K20230907084829



BLK: 3,SNR1: 0.99538E-01,SNR2: 0.42752





3C190 2023/09/06 23.84UT FUJI -KISO






T20230907090053




BLK: 9,SNR1: 0.68005 ,SNR2: 4.1423





3C196 2023/09/07 0.04UT TOYOKAWA-FUJI



F20230907090052




BLK: 9,SNR1: 0.10527 ,SNR2: 1.7261



T20230907090053





BLK:11,SNR1: 0.23327 ,SNR2: 2.1865




Frequency (Hz)

K20230907090053




BLK:11,SNR1: 0.20447 ,SNR2: 0.88165





Frequency (Hz)


3C196 2023/09/07 0.04UT TOYOKAWA-KISO



F20230907090052





BLK: 3,SNR1:-0.26287E-01,SNR2: 1.7419





3C196 2023/09/07 0.04UT FUJI -KISO


K20230907090053




BLK: 3,SNR1:-0.11245E-02,SNR2: 0.17898



T20230907091203




BLK: 8,SNR1: 4.2128 ,SNR2: 12.286





0821+394 2023/09/07 0.23UT TOYOKAWA-FUJI


F20230907091202




BLK: 8,SNR1: 0.28607 ,SNR2: 2.4828



T20230907091203




BLK: 4,SNR1:-0.25595 ,SNR2: 1.3859




Frequency (Hz)

K20230907091203




BLK: 4,SNR1: 0.13653 ,SNR2: 0.62749





Frequency (Hz)


0821+394 2023/09/07 0.23UT TOYOKAWA-KISO



F20230907091202





BLK: 4,SNR1: 0.46221 ,SNR2: 2.6143




Frequency (Hz)

K20230907091203




BLK: 4,SNR1: 0.81838 ,SNR2: 2.9845





Frequency (Hz)


0821+394 2023/09/07 0.23UT FUJI -KISO



T20230907092850





BLK: 4, SNR1: 3.7033 ,SNR2: 13.659




Frequency (Hz)

F20230907092850




BLK: 4, SNR1: 0.30515 ,SNR2: 1.3940





Frequency (Hz)


0839-071 2023/09/07 0.51UT TOYOKAWA-FUJI



T20230907092850





BLK: 5,SNR1: 3.4042 ,SNR2: 10.786




Frequency (Hz)

K20230907092850




BLK: 5,SNR1: 0.37924 ,SNR2: 3.3257





Frequency (Hz)

0839-071 2023/09/07 0.51UT TOYOKAWA-KISO






F20230907092850





BLK: 4,SNR1: 0.17403 ,SNR2: 0.88726




Frequency (Hz)

K20230907092850




BLK: 4,SNR1: 1.3856 ,SNR2: 4.3784





Frequency (Hz)


0839-071 2023/09/07 0.51UT FUJI -KISO



T20230907093950





BLK: 3,SNR1: 1.0151 ,SNR2: 5.8191





3C208 2023/09/07 0.69UT TOYOKAWA-FUJI



F20230907093949




BLK: 3,SNR1:-0.12767 ,SNR2: 0.39729





T20230907093950




BLK: 6,SNR1: 0.47920 ,SNR2: 3.3136




K20230907093950




BLK: 6,SNR1: 0.33418 ,SNR2: 2.5669




3C208 2023/09/07 0.69UT TOYOKAWA-KISO





F20230907093949




BLK: 4,SNR1: 0.69040E-01,SNR2: 2.5578




K20230907093950




BLK: 4,SNR1: 0.12665 ,SNR2: 1.6649




3C208 2023/09/07 0.69UT FUJI -KISO



T20230907095631




BLK: 7,SNR1: 5.8748 ,SNR2: 13.624





3C216 2023/09/07 0.97UT TOYOKAWA-FUJI


F20230907095630




BLK: 7,SNR1: 0.69478 ,SNR2: 4.4584



T20230907095631




BLK: 9,SNR1: 4.6063 ,SNR2: 15.812





3C216 2023/09/07 0.97UT TOYOKAWA-KISO



K20230907095631




BLK: 9,SNR1: 0.32151 ,SNR2: 1.3345



F20230907095630





BLK: 6,SNR1: 0.27831 ,SNR2: 3.8593




Frequency (Hz)

3C216 2023/09/07 0.97UT FUJI -KISO


K20230907095631





BLK: 6,SNR1: 0.86676 ,SNR2: 3.6767




Frequency (Hz)



T20230907101522





BLK: 2,SNR1: 0.18833 ,SNR2: 2.1865




Frequency (Hz)

F20230907101521




BLK: 2,SNR1: 0.58168E-01,SNR2: 0.33966




Frequency (Hz)

0926+117 2023/09/07 1.28UT TOYOKAWA-FUJI






T20230907101522





BLK: 4, SNR1: 0.50681 , SNR2: 6.4646




Frequency (Hz)

0926+117 2023/09/07 1.28UT TOYOKAWA-KISO


K20230907101522





BLK: 4, SNR1: 0.39699 , SNR2: 1.6308




Frequency (Hz)



F20230907101521




BLK: 3,SNR1: 0.11412 ,SNR2: 0.97320




Frequency (Hz)

K20230907101522




BLK: 3,SNR1: 0.17116 ,SNR2: 0.63114





Frequency (Hz)


0926+117 2023/09/07 1.28UT FUJI -KISO





T20230907102307




BLK:15,SNR1: 1.1919 ,SNR2: 12.562




F20230907102306




BLK:15,SNR1: 0.26977 ,SNR2: 5.3035




3C222 2023/09/07 1.41UT TOYOKAWA-FUJI





T20230907102307




BLK:18,SNR1: 1.0843 ,SNR2: 10.482




K20230907102307




BLK:18,SNR1: 0.39835 ,SNR2: 1.8214




3C222 2023/09/07 1.41UT TOYOKAWA-KISO





F20230907102306




BLK: 7,SNR1: 0.28925 ,SNR2: 2.3906




K20230907102307





BLK: 7,SNR1: 0.62046 ,SNR2: 2.9274




3C222 2023/09/07 1.41UT FUJI -KISO



T20230907103007





BLK:14,SNR1: 0.93386 ,SNR2: 4.5610




Frequency (Hz)

0941-08 2023/09/07 1.53UT TOYOKAWA-FUJI


F20230907103006





BLK:14,SNR1: 0.66495E-01,SNR2: 0.98283




Frequency (Hz)



T20230907103007





BLK:18,SNR1: 0.83037 ,SNR2: 7.0034




0941-08 2023/09/07 1.53UT TOYOKAWA-KISO


K20230907103007




BLK:18,SNR1: 0.34566 ,SNR2: 0.85112




Frequency (Hz)



F20230907103006




BLK: 5,SNR1: 0.63034E-01,SNR2: 2.2827





0941-08 2023/09/07 1.53UT FUJI -KISO

K20230907103007




BLK: 5,SNR1: 0.38442 ,SNR2: 1.6499






T20230907103829





BLK:20,SNR1: 1.9104 ,SNR2: 18.810




Frequency (Hz)

3C230 2023/09/07 1.67UT TOYOKAWA-FUJI


F20230907103829




BLK:20,SNR1:-0.65092E-01,SNR2: 0.76014




Frequency (Hz)




T20230907103829




BLK:34,SNR1: 2.0156 ,SNR2: 18.840




K20230907103829





BLK:34,SNR1: 0.48771 ,SNR2: 1.2920




3C230 2023/09/07 1.67UT TOYOKAWA-KISO



F20230907103829





BLK:13,SNR1:-0.11646 ,SNR2: 1.3858




Frequency (Hz)

3C230 2023/09/07 1.67UT FUJI -KISO


K20230907103829





BLK:13,SNR1: 0.63140 ,SNR2: 1.9222




Frequency (Hz)



T20230907105235





BLK: 5,SNR1: 0.14551 ,SNR2: 1.5463




Frequency (Hz)

F20230907105234




BLK: 5,SNR1: 0.86649 ,SNR2: 6.6909





Frequency (Hz)


3C236 2023/09/07 1.90UT TOYOKAWA-FUJI





T20230907105235




BLK: 9,SNR1: 0.16815 ,SNR2: 2.5157




K20230907105235





BLK: 9,SNR1: 0.56276 ,SNR2: 4.2161




3C236 2023/09/07 1.90UT TOYOKAWA-KISO



F20230907105234





BLK: 5,SNR1: 1.5774 ,SNR2: 6.0249




Frequency (Hz)

3C236 2023/09/07 1.90UT FUJI -KISO


K20230907105235





BLK: 5,SNR1: 0.67051 ,SNR2: 5.3734




Frequency (Hz)





T20230907110046




BLK: 2,SNR1: 0.35906E-01,SNR2: 0.34794




F20230907110045





BLK: 2,SNR1: 0.18196 ,SNR2: 2.1518




1011+110 2023/09/07 2.04UT TOYOKAWA-FUJI





T20230907110046




BLK: 5,SNR1: 0.41447 ,SNR2: 1.6651




K20230907110046



BLK: 5,SNR1: 0.67872 ,SNR2: 3.4000




1011+110 2023/09/07 2.04UT TOYOKAWA-KISO






F20230907110045




BLK: 4,SNR1: 0.70138E-01,SNR2: 1.2505





1011+110 2023/09/07 2.04UT FUJI -KISO



K20230907110046




BLK: 4,SNR1: 0.18702 ,SNR2: 2.1797




T20230907110826




BLK:20,SNR1: 2.3521 ,SNR2: 13.044




F20230907110826




BLK:20,SNR1: 0.49240E-01,SNR2: 3.0143




3C241 2023/09/07 2.17UT TOYOKAWA-FUJI




T20230907110826




BLK:29,SNR1: 1.9331 ,SNR2: 15.854




K20230907110826




BLK:29,SNR1: 0.32311 ,SNR2: 1.3354




3C241 2023/09/07 2.17UT TOYOKAWA-KISO





F20230907110826




BLK:20,SNR1: 0.20867 ,SNR2: 1.1574




K20230907110826




BLK:20,SNR1: 0.53178 ,SNR2: 2.7606




3C241 2023/09/07 2.17UT FUJI -KISO



T20230907111956





BLK: 7,SNR1: 0.27795 ,SNR2: 1.5934





1031-11 2023/09/07 2.36UT TOYOKAWA-FUJI



F20230907111955




BLK: 7,SNR1: 0.90701 ,SNR2: 4.1417



T20230907111956





BLK: 8,SNR1: 0.15047 ,SNR2: 2.8245




Frequency (Hz)

1031-11 2023/09/07 2.36UT TOYOKAWA-KISO


K20230907111956




BLK: 8,SNR1: 0.71070 ,SNR2: 5.4436




Frequency (Hz)




F20230907111955




BLK: 5,SNR1:-0.52455E-01,SNR2: 1.2787




K20230907111956




BLK: 5,SNR1: 0.78568 ,SNR2: 3.0494




1031-11 2023/09/07 2.36UT FUJI -KISO



T20230907112430




BLK:13,SNR1: 1.0433 ,SNR2: 7.7446





1035-058 2023/09/07 2.44UT TOYOKAWA-FUJI

F20230907112430




BLK:13,SNR1:-0.13630 ,SNR2: 1.2125






T20230907112430





BLK: 6,SNR1: 0.17250 ,SNR2: 1.0076





1035-058 2023/09/07 2.44UT TOYOKAWA-KISO


K20230907112430




BLK: 6,SNR1: 0.90431E-01,SNR2: 1.1306





F20230907112430




BLK: 7,SNR1: 0.33528E-01,SNR2: 1.3110




K20230907112430





BLK: 7,SNR1: 0.94391 ,SNR2: 4.1833




1035-058 2023/09/07 2.44UT FUJI -KISO




T20230907113342




BLK: 3,SNR1: 2.3279 ,SNR2: 8.7580




F20230907113341





BLK: 3,SNR1:-0.22796E-01,SNR2: 0.0000




1044-008 2023/09/07 2.59UT TOYOKAWA-FUJI





T20230907113342




BLK:16,SNR1: 0.87259 ,SNR2: 3.6099




K20230907113342





BLK:16,SNR1: 0.35635 ,SNR2: 0.81931




1044-008 2023/09/07 2.59UT TOYOKAWA-KISO





F20230907113341




BLK: 1,SNR1: 0.89098E-01,SNR2: 0.78593




K20230907113342





BLK: 1,SNR1: 0.42142 ,SNR2: 1.9168




1044-008 2023/09/07 2.59UT FUJI -KISO



T20230907114447





BLK:17,SNR1: 19.978 ,SNR2: 34.976





1055+01 2023/09/07 2.77UT TOYOKAWA-FUJI


F20230907114447




BLK:17,SNR1: 6.1227 ,SNR2: 18.341



T20230907114447




BLK:15,SNR1: 21.423 ,SNR2: 49.464




1055+01 2023/09/07 2.77UT TOYOKAWA-KISO


K20230907114447





BLK:15,SNR1: 14.644 ,SNR2: 20.084




Frequency (Hz)



F20230907114447




BLK:14,SNR1: 9.4633 ,SNR2: 16.590





1055+01 2023/09/07 2.77UT FUJI -KISO

K20230907114447




BLK:14,SNR1: 14.395 ,SNR2: 17.940








T20230907115604




BLK:15,SNR1: 4.6850 ,SNR2: 10.133




F20230907115603




BLK:15,SNR1: 0.21175 ,SNR2: 1.0696




1107+109 2023/09/07 2.96UT TOYOKAWA-FUJI





T20230907115604




BLK:17,SNR1: 4.6747 ,SNR2: 9.0340




K20230907115604





BLK:17,SNR1: 0.58192 ,SNR2: 2.4438




1107+109 2023/09/07 2.96UT TOYOKAWA-KISO





F20230907115603




BLK:16,SNR1: 0.29691 ,SNR2: 1.5181




K20230907115604





BLK:16,SNR1: 0.58250 ,SNR2: 1.7450




1107+109 2023/09/07 2.96UT FUJI -KISO





T20230907120541




BLK:11,SNR1: 4.3275 ,SNR2: 24.878




F20230907120540




BLK:11,SNR1: 0.31964E-01,SNR2: 2.3407




3C255 2023/09/07 3.12UT TOYOKAWA-FUJI





T20230907120541




BLK:23,SNR1: 3.8073 ,SNR2: 9.8445




K20230907120541




BLK:23,SNR1: 1.6207 ,SNR2: 6.3933




3C255 2023/09/07 3.12UT TOYOKAWA-KISO



F20230907120540





BLK:16,SNR1: 0.12248 ,SNR2: 1.6789





3C255 2023/09/07 3.12UT FUJI -KISO


K20230907120541




BLK:16,SNR1: 1.7052 ,SNR2: 6.6408



T20230907122939




BLK: 6,SNR1: 4.3537 ,SNR2: 49.333





3C263.1 2023/09/07 3.52UT TOYOKAWA-FUJI


F20230907122938




BLK: 6,SNR1: 0.16045 ,SNR2: 0.62925




T20230907122939




BLK:15,SNR1: 5.0892 ,SNR2: 25.699




K20230907122939



BLK:15,SNR1: 0.38756 ,SNR2: 1.8968




3C263.1 2023/09/07 3.52UT TOYOKAWA-KISO






F20230907122938




BLK: 3,SNR1: 0.13660E-01,SNR2: 2.1699





3C263.1 2023/09/07 3.52UT FUJI -KISO


K20230907122939




BLK: 3,SNR1: 0.78601E-02,SNR2: 0.89430





T20230907123606




BLK: 9,SNR1: 1.8856 ,SNR2: 22.753




F20230907123605




BLK: 9,SNR1:-0.16364 ,SNR2: 0.23766




3C267 2023/09/07 3.63UT TOYOKAWA-FUJI



T20230907123606





BLK:12,SNR1: 1.8222 ,SNR2: 13.040





3C267 2023/09/07 3.63UT TOYOKAWA-KISO



K20230907123606




BLK:12,SNR1: 0.32882 ,SNR2: 1.3881



F20230907123605





BLK: 6,SNR1: 0.31497 ,SNR2: 1.1706





3C267 2023/09/07 3.63UT FUJI -KISO


K20230907123606




BLK: 6,SNR1: 1.4640 ,SNR2: 6.4150




T20230907125521




BLK: 3,SNR1: 0.24117 ,SNR2: 1.2774




F20230907125520





BLK: 3,SNR1:-0.23251 ,SNR2: 0.74698




1206+439 2023/09/07 3.95UT TOYOKAWA-FUJI



T20230907125521





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1206+439 2023/09/07 3.95UT TOYOKAWA-KISO



F20230907125520





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1206+439 2023/09/07 3.95UT FUJI -KISO




T20230907131512




BLK:29,SNR1: 8.2587 ,SNR2: 31.157




F20230907131511



BLK:29,SNR1:-0.12897E-01,SNR2: 2.0015





3C273 2023/09/07 4.28UT TOYOKAWA-FUJI








T20230907131512




BLK:34,SNR1: 7.9560 ,SNR2: 30.038




K20230907131512





BLK:34,SNR1: 1.2977 ,SNR2: 3.6525




3C273 2023/09/07 4.28UT TOYOKAWA-KISO



F20230907131511





BLK:30,SNR1:-0.73830E-01,SNR2: 1.7380





3C273 2023/09/07 4.28UT FUJI -KISO



K20230907131512




BLK:30,SNR1: 1.4768 ,SNR2: 9.2155





T20230907132822




BLK: 2,SNR1: 0.23834 ,SNR2: 3.7003




F20230907132822





BLK: 2,SNR1:-0.85876E-01,SNR2: 0.21290




3C275 2023/09/07 4.50UT TOYOKAWA-FUJI





T20230907132822




BLK: 6,SNR1: 0.37362E-01,SNR2: 1.2791




K20230907132822




BLK: 6,SNR1: 0.49162 ,SNR2: 1.6980




3C275 2023/09/07 4.50UT TOYOKAWA-KISO




F20230907132822




BLK: 6,SNR1:-0.27212E-01,SNR2: 0.76444




K20230907132822





BLK: 6,SNR1: 0.42442 ,SNR2: 4.6729




3C275 2023/09/07 4.50UT FUJI -KISO



T20230907134211





BLK:10,SNR1: 0.38701 ,SNR2: 2.9384





3C279 2023/09/07 4.73UT TOYOKAWA-FUJI



F20230907134210




BLK:10,SNR1: 9.0655 ,SNR2: 12.689





T20230907134211




BLK: 8,SNR1: 0.38543 ,SNR2: 2.5741




K20230907134211




BLK: 8,SNR1: 0.43822 ,SNR2: 3.0087




3C279 2023/09/07 4.73UT TOYOKAWA-KISO



F20230907134210




BLK: 2,SNR1: 3.9302 ,SNR2: 16.465





3C279 2023/09/07 4.73UT FUJI -KISO

K20230907134211





BLK: 2,SNR1: 0.26740 ,SNR2: 1.2147








T20230907140159




BLK: 4,SNR1: 5.3700 ,SNR2: 13.703




F20230907140158





BLK: 4,SNR1: 0.17703 ,SNR2: 1.8032




1313+453 2023/09/07 5.06UT TOYOKAWA-FUJI



T20230907140159





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1313+453 2023/09/07 5.06UT TOYOKAWA-KISO



F20230907140158





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


1313+453 2023/09/07 5.06UT FUJI -KISO





T20230907141205




BLK:12,SNR1: 0.38749 ,SNR2: 2.3865




F20230907141204




BLK:12,SNR1: 8.1663 ,SNR2: 9.0191




1323+32 2023/09/07 5.23UT TOYOKAWA-FUJI





T20230907141205




BLK: 9,SNR1: 0.36131 ,SNR2: 2.3009




K20230907141205





BLK: 9,SNR1: 13.646 ,SNR2: 26.665




1323+32 2023/09/07 5.23UT TOYOKAWA-KISO



F20230907141204





BLK:30,SNR1: 9.2338 ,SNR2: 10.031





1323+32 2023/09/07 5.23UT FUJI -KISO



K20230907141205




BLK:30,SNR1: 22.408 ,SNR2: 30.993





T20230907141655




BLK:29,SNR1: 10.452 ,SNR2: 13.275




F20230907141654





BLK:29,SNR1: 3.0677 ,SNR2: 3.9845




3C286 2023/09/07 5.31UT TOYOKAWA-FUJI





T20230907141655




BLK:16,SNR1: 7.0619 ,SNR2: 13.564




K20230907141655



BLK:16,SNR1: 14.204 ,SNR2: 19.220





3C286 2023/09/07 5.31UT TOYOKAWA-KISO








F20230907141654




BLK:19,SNR1: 4.0960 ,SNR2: 6.6372




K20230907141655





BLK:19,SNR1: 14.340 ,SNR2: 26.885




3C286 2023/09/07 5.31UT FUJI -KISO





T20230907143322




BLK: 6,SNR1: 0.16596 ,SNR2: 1.0461




F20230907143321





BLK: 6,SNR1: 0.67574E-01,SNR2: 1.1308




1345+12 2023/09/07 5.58UT TOYOKAWA-FUJI





T20230907143322




BLK: 4,SNR1: 0.33850 ,SNR2: 4.3199




K20230907143322





BLK: 4,SNR1:-0.63864E-01,SNR2: 0.25937




1345+12 2023/09/07 5.58UT TOYOKAWA-KISO



F20230907143321





BLK: 2,SNR1: 0.37391 ,SNR2: 1.4142




Frequency (Hz)

K20230907143322




BLK: 2,SNR1: 1.9207 ,SNR2: 9.2139





Frequency (Hz)


1345+12 2023/09/07 5.58UT FUJI -KISO





T20230907144343




BLK: 6,SNR1: 0.16214 ,SNR2: 1.4872




F20230907144343





BLK: 6,SNR1: 0.94449 ,SNR2: 2.1593




1355+01 2023/09/07 5.76UT TOYOKAWA-FUJI





T20230907144343




BLK: 6,SNR1: 0.17422 ,SNR2: 2.7055




K20230907144343





BLK: 6,SNR1: 0.19776 ,SNR2: 1.4523




1355+01 2023/09/07 5.76UT TOYOKAWA-KISO



F20230907144343





No.Good Data




Frequency (Hz)

K20230907144343




No.Good Data





Frequency (Hz)


1355+01 2023/09/07 5.76UT FUJI -KISO



T20230907150454





BLK:12,SNR1: 0.35589 ,SNR2: 4.2863




Frequency (Hz)

F20230907150453




BLK:12,SNR1: 0.56705E-01,SNR2: 1.5952





Frequency (Hz)

3C298 2023/09/07 6.11UT TOYOKAWA-FUJI






T20230907150454





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C298 2023/09/07 6.11UT TOYOKAWA-KISO



F20230907150453





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C298 2023/09/07 6.11UT FUJI -KISO



T20230907151637





BLK: 3,SNR1: 0.16794 ,SNR2: 2.3750




Frequency (Hz)

F20230907151637




BLK: 3,SNR1:-0.13494 ,SNR2: 0.76665





Frequency (Hz)


1428-03 2023/09/07 6.30UT TOYOKAWA-FUJI



T20230907151637




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1428-03 2023/09/07 6.30UT TOYOKAWA-KISO



F20230907151637





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1428-03 2023/09/07 6.30UT FUJI -KISO



T20230907154141





BLK: 1,SNR1: 0.55128 ,SNR2: 1.6580




Frequency (Hz)

F20230907154140




BLK: 1,SNR1:-0.18324 ,SNR2: 0.43077E-01






Frequency (Hz)




1453-10 2023/09/07 6.72UT TOYOKAWA-FUJI




T20230907154141





KISO




1453-10 2023/09/07 6.72UT TOYOKAWA-KISO



F20230907154140





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1453-10 2023/09/07 6.72UT FUJI -KISO






T20230907155634





No.Good Data




Frequency (Hz)

F20230907155633




No.Good Data




Frequency (Hz)


1508-05 2023/09/07 6.97UT TOYOKAWA-FUJI



T20230907155634





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1508-05 2023/09/07 6.97UT TOYOKAWA-KISO




F20230907155633




KISO




1508-05 2023/09/07 6.97UT FUJI -KISO



T20230907160534





BLK: 3,SNR1: 0.10513 ,SNR2: 1.2154




Frequency (Hz)

F20230907160533




BLK: 3,SNR1: 0.27829 ,SNR2: 1.2399





Frequency (Hz)


3C318 2023/09/07 7.12UT TOYOKAWA-FUJI



T20230907160534





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C318 2023/09/07 7.12UT TOYOKAWA-KISO



F20230907160533





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C318 2023/09/07 7.12UT FUJI -KISO





T20230907161121




BLK: 7,SNR1: 1.1843 ,SNR2: 17.263




F20230907161120





BLK: 7,SNR1:-0.15295 ,SNR2: 1.5477




1523+03 2023/09/07 7.22UT TOYOKAWA-FUJI



T20230907161121





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)

1523+03 2023/09/07 7.22UT TOYOKAWA-KISO









F20230907161120





KISO




1523+03 2023/09/07 7.22UT FUJI -KISO



T20230907162301




BLK: 6,SNR1: 0.88758 ,SNR2: 13.405




Frequency (Hz)

F20230907162301




BLK: 6,SNR1: 2.5441 ,SNR2: 6.2661






Frequency (Hz)




1535+139 2023/09/07 7.41UT TOYOKAWA-FUJI




T20230907162301






KISO






1535+139 2023/09/07 7.41UT TOYOKAWA-KISO




F20230907162301





KISO




1535+139 2023/09/07 7.41UT FUJI -KISO




T20230907163324




BLK: 5,SNR1: 0.26141 ,SNR2: 0.79217




F20230907163323






BLK: 5,SNR1: 0.42959 ,SNR2: 1.2118






1545-12 2023/09/07 7.58UT TOYOKAWA-FUJI




T20230907163324






KISO






1545-12 2023/09/07 7.58UT TOYOKAWA-KISO




F20230907163323





KISO




1545-12 2023/09/07 7.58UT FUJI -KISO





T20230907165428




BLK: 3,SNR1:-0.10298 ,SNR2: 1.0322




F20230907165427



BLK: 3,SNR1:-0.74175E-01,SNR2: 1.1140






1607+26 2023/09/07 7.94UT TOYOKAWA-FUJI









T20230907165428





KISO




1607+26 2023/09/07 7.94UT TOYOKAWA-KISO





F20230907165427




No.Good Data



KISO



No.Good Data



1607+26 2023/09/07 7.94UT FUJI -KISO

