




T20230908062630





BLK:17,SNR1: 0.49807 ,SNR2: 5.3162




Frequency (Hz)

F20230908062630




BLK:17,SNR1:-0.32868E-01,SNR2: 1.1844




Frequency (Hz)


3C147 2023/09/07 21.47UT TOYOKAWA-FUJI



T20230908062630




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C147 2023/09/07 21.47UT TOYOKAWA-KISO




F20230908062630



No.Good Data




KISO




No.Good Data




3C147 2023/09/07 21.47UT FUJI -KISO



T20230908063443





BLK:10,SNR1: 5.2395 ,SNR2: 46.002




Frequency (Hz)

F20230908063443




BLK:10,SNR1: 2.7261 ,SNR2: 13.618





Frequency (Hz)

0548+16 2023/09/07 21.61UT TOYOKAWA-FUJI







T20230908063443




No.Good Data




KISO




No.Good Data



0548+16 2023/09/07 21.61UT TOYOKAWA-KISO





F20230908063443




No.Good Data




KISO





No.Good Data




0548+16 2023/09/07 21.61UT FUJI -KISO



T20230908063853





BLK: 5,SNR1: 0.55659 ,SNR2: 5.0429




Frequency (Hz)

F20230908063853




BLK: 5,SNR1: 2.5239 ,SNR2: 9.4744





Frequency (Hz)


0552+12 2023/09/07 21.68UT TOYOKAWA-FUJI





T20230908063853




No.Good Data




KISO



No.Good Data




0552+12 2023/09/07 21.68UT TOYOKAWA-KISO



F20230908063853




No.Good Data



KISO





No.Good Data




0552+12 2023/09/07 21.68UT FUJI -KISO



T20230908064320





BLK: 4,SNR1: 0.40676 ,SNR2: 1.1631




Frequency (Hz)

F20230908064320




BLK: 4,SNR1: 3.7106 ,SNR2: 9.8717




Frequency (Hz)


0556+191 2023/09/07 21.75UT TOYOKAWA-FUJI





T20230908064320




No.Good Data




KISO



No.Good Data




0556+191 2023/09/07 21.75UT TOYOKAWA-KISO





F20230908064320




No.Good Data



KISO



No.Good Data





0556+191 2023/09/07 21.75UT FUJI -KISO






T20230908064753





BLK: 7,SNR1:-0.59067E-01,SNR2: 0.18285




Frequency (Hz)

3C152 2023/09/07 21.83UT TOYOKAWA-FUJI


F20230908064753





BLK: 7,SNR1: 1.3445 ,SNR2: 4.2914




Frequency (Hz)




T20230908064753




No.Good Data




KISO




No.Good Data




3C152 2023/09/07 21.83UT TOYOKAWA-KISO




F20230908064753



No.Good Data




KISO




No.Good Data




3C152 2023/09/07 21.83UT FUJI -KISO



T20230908071014




BLK: 7,SNR1: 0.20258 ,SNR2: 2.2130




Frequency (Hz)

3C161 2023/09/07 22.20UT TOYOKAWA-FUJI


F20230908071013





BLK: 7,SNR1: 0.24996 ,SNR2: 1.3473




Frequency (Hz)



T20230908071014





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2023/09/07 22.20UT TOYOKAWA-KISO





F20230908071013




No.Good Data




KISO





No.Good Data




3C161 2023/09/07 22.20UT FUJI -KISO



T20230908073748





BLK: 3,SNR1:-0.49758E-01,SNR2: 0.43034




Frequency (Hz)

F20230908073748




BLK: 3,SNR1:-0.39180E-01,SNR2: 0.41772





Frequency (Hz)


0652-130 2023/09/07 22.66UT TOYOKAWA-FUJI





T20230908073748




No.Good Data




KISO



No.Good Data





0652-130 2023/09/07 22.66UT TOYOKAWA-KISO







F20230908073748




No.Good Data




KISO




No.Good Data




0652-130 2023/09/07 22.66UT FUJI -KISO



T20230908074923




BLK: 3,SNR1:-0.45092E-01,SNR2: 0.17994




Frequency (Hz)

F20230908074923




BLK: 3,SNR1: 0.79521 ,SNR2: 7.1602





Frequency (Hz)


0703+138 2023/09/07 22.85UT TOYOKAWA-FUJI



T20230908074923





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0703+138 2023/09/07 22.85UT TOYOKAWA-KISO



F20230908074923





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0703+138 2023/09/07 22.85UT FUJI -KISO



T20230908075846





BLK: 1,SNR1: 0.90447E-01,SNR2: 0.53933




Frequency (Hz)

F20230908075846




BLK: 1,SNR1:-0.16040E-01,SNR2: 1.3128





Frequency (Hz)


0713-024 2023/09/07 23.01UT TOYOKAWA-FUJI



T20230908075846





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0713-024 2023/09/07 23.01UT TOYOKAWA-KISO



F20230908075846





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0713-024 2023/09/07 23.01UT FUJI -KISO



T20230908080858





BLK: 5,SNR1: 0.81538E-01,SNR2: 2.3297




Frequency (Hz)

F20230908080858




BLK: 5,SNR1:-0.18291E-01,SNR2: 2.1054





Frequency (Hz)

0723+10 2023/09/07 23.18UT TOYOKAWA-FUJI








T20230908080858




No.Good Data




KISO





No.Good Data




0723+10 2023/09/07 23.18UT TOYOKAWA-KISO



F20230908080858





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0723+10 2023/09/07 23.18UT FUJI -KISO



T20230908081912





BLK: 1,SNR1:-0.24136 ,SNR2: 0.51567




Frequency (Hz)

F20230908081912




BLK: 1,SNR1: 0.30655 ,SNR2: 0.89035





Frequency (Hz)


0732+33 2023/09/07 23.35UT TOYOKAWA-FUJI





T20230908081912




No.Good Data




KISO





No.Good Data




0732+33 2023/09/07 23.35UT TOYOKAWA-KISO





F20230908081912




No.Good Data




KISO





No.Good Data




0732+33 2023/09/07 23.35UT FUJI -KISO



T20230908082715





BLK:12,SNR1: 0.26576 ,SNR2: 2.5888




Frequency (Hz)

F20230908082715




BLK:12,SNR1:-0.14807 ,SNR2: 1.4843





Frequency (Hz)


0741-06 2023/09/07 23.48UT TOYOKAWA-FUJI



T20230908082715





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0741-06 2023/09/07 23.48UT TOYOKAWA-KISO





F20230908082715




No.Good Data




KISO



No.Good Data




0741-06 2023/09/07 23.48UT FUJI -KISO








T20230908084434




BLK: 9,SNR1: 58.294 ,SNR2: 107.59




F20230908084434





BLK: 9,SNR1: 0.11623 ,SNR2: 2.2446




3C190 2023/09/07 23.77UT TOYOKAWA-FUJI





T20230908084434




No.Good Data




KISO



No.Good Data




3C190 2023/09/07 23.77UT TOYOKAWA-KISO





F20230908084434




No.Good Data




KISO





No.Good Data




3C190 2023/09/07 23.77UT FUJI -KISO



T20230908085139





BLK: 7,SNR1: 0.93949E-01,SNR2: 1.5010




Frequency (Hz)

F20230908085139




BLK: 7,SNR1: 1.5961 ,SNR2: 6.2491





Frequency (Hz)


0806-103 2023/09/07 23.89UT TOYOKAWA-FUJI



T20230908085139





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0806-103 2023/09/07 23.89UT TOYOKAWA-KISO




F20230908085139




No.Good Data



KISO





No.Good Data




0806-103 2023/09/07 23.89UT FUJI -KISO



T20230908090807





BLK: 8,SNR1: 0.19591 ,SNR2: 1.4947




Frequency (Hz)

0821+394 2023/09/08 0.16UT TOYOKAWA-FUJI


F20230908090807




BLK: 8,SNR1: 0.45889 ,SNR2: 3.3794




Frequency (Hz)




T20230908090807




No.Good Data




KISO



No.Good Data



0821+394 2023/09/08 0.16UT TOYOKAWA-KISO








F20230908090807




No.Good Data




KISO





No.Good Data




0821+394 2023/09/08 0.16UT FUJI -KISO



T20230908092454





BLK: 7,SNR1: 1.3514 ,SNR2: 18.867





0839-071 2023/09/08 0.44UT TOYOKAWA-FUJI


F20230908092453




BLK: 7,SNR1:-0.95545E-01,SNR2: 1.2909




T20230908092454




No.Good Data



KISO



No.Good Data




0839-071 2023/09/08 0.44UT TOYOKAWA-KISO



F20230908092453




No.Good Data



KISO




No.Good Data




0839-071 2023/09/08 0.44UT FUJI -KISO



T20230908093554





BLK: 4,SNR1: 0.12266 ,SNR2: 0.36160




Frequency (Hz)

F20230908093554




BLK: 4,SNR1: 0.37052 ,SNR2: 1.4800




Frequency (Hz)


3C208 2023/09/08 0.63UT TOYOKAWA-FUJI





T20230908093554




No. Good Data



KISO





No. Good Data




3C208 2023/09/08 0.63UT TOYOKAWA-KISO





F20230908093554




No.Good Data




KISO





No.Good Data




3C208 2023/09/08 0.63UT FUJI -KISO





T20230908095235




BLK: 8,SNR1: 0.14168 ,SNR2: 1.0711




F20230908095235



BLK: 8,SNR1: 0.17875 ,SNR2: 2.1551




3C216 2023/09/08 0.90UT TOYOKAWA-FUJI







T20230908095235




No. Good Data




KISO



No. Good Data




3C216 2023/09/08 0.90UT TOYOKAWA-KISO





F20230908095235




No.Good Data




KISO




No.Good Data




3C216 2023/09/08 0.90UT FUJI -KISO



T20230908101126





BLK: 6,SNR1: 0.88460 ,SNR2: 10.735





0926+117 2023/09/08 1.22UT TOYOKAWA-FUJI

F20230908101126




BLK: 6,SNR1: 1.2174 ,SNR2: 3.0801



T20230908101126





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0926+117 2023/09/08 1.22UT TOYOKAWA-KISO





F20230908101126




No. Good Data




KISO




No. Good Data




0926+117 2023/09/08 1.22UT FUJI -KISO





T20230908101911




BLK:16,SNR1: 0.78453 ,SNR2: 6.5327




F20230908101911



BLK:16,SNR1: 0.19826 ,SNR2: 2.0290




3C222 2023/09/08 1.35UT TOYOKAWA-FUJI





T20230908101911




No. Good Data




KISO



No. Good Data



3C222 2023/09/08 1.35UT TOYOKAWA-KISO



F20230908101911





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C222 2023/09/08 1.35UT FUJI -KISO







T20230908102611




BLK: 9,SNR1: 0.60628 ,SNR2: 1.7473




F20230908102610




BLK: 9,SNR1: 0.10958E-01,SNR2: 0.82554




0941-08 2023/09/08 1.46UT TOYOKAWA-FUJI





T20230908102611




No. Good Data




KISO



No. Good Data



0941-08 2023/09/08 1.46UT TOYOKAWA-KISO





F20230908102610




No. Good Data




KISO




No. Good Data




0941-08 2023/09/08 1.46UT FUJI -KISO



T20230908103433




BLK:14,SNR1: 0.81704 ,SNR2: 8.1635





3C230 2023/09/08 1.60UT TOYOKAWA-FUJI

F20230908103433



BLK:14,SNR1:-0.62484E-01,SNR2: 2.3452



T20230908103433





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C230 2023/09/08 1.60UT TOYOKAWA-KISO



F20230908103433





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C230 2023/09/08 1.60UT FUJI -KISO





T20230908104840




BLK: 8,SNR1: 0.13766 ,SNR2: 2.2576




F20230908104840





BLK: 8,SNR1: 0.26582 ,SNR2: 1.9176




3C236 2023/09/08 1.84UT TOYOKAWA-FUJI



T20230908104840





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

3C236 2023/09/08 1.84UT TOYOKAWA-KISO






F20230908104840





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C236 2023/09/08 1.84UT FUJI -KISO





T20230908105650




BLK: 3,SNR1: 0.17407 ,SNR2: 2.2451




F20230908105650





BLK: 3,SNR1: 0.50357 ,SNR2: 5.2398




1011+110 2023/09/08 1.98UT TOYOKAWA-FUJI



T20230908105650





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1011+110 2023/09/08 1.98UT TOYOKAWA-KISO



F20230908105650



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1011+110 2023/09/08 1.98UT FUJI -KISO



T20230908110431





BLK:12,SNR1: 0.99422 ,SNR2: 7.0418




Frequency (Hz)

F20230908110430




BLK:12,SNR1: 0.82969E-01,SNR2: 1.0166



Frequency (Hz)


3C241 2023/09/08 2.10UT TOYOKAWA-FUJI



T20230908110431



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C241 2023/09/08 2.10UT TOYOKAWA-KISO



F20230908110430





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C241 2023/09/08 2.10UT FUJI -KISO



T20230908111600




BLK: 4,SNR1: 0.16959 ,SNR2: 1.1802




Frequency (Hz)

F20230908111600




BLK: 4,SNR1: 0.29638 ,SNR2: 1.4120



Frequency (Hz)

1031-11 2023/09/08 2.29UT TOYOKAWA-FUJI






T20230908111600



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1031-11 2023/09/08 2.29UT TOYOKAWA-KISO





F20230908111600




No.Good Data




KISO




No.Good Data




1031-11 2023/09/08 2.29UT FUJI -KISO



T20230908112034





BLK:11,SNR1: 4.9431 ,SNR2: 20.807





1035-058 2023/09/08 2.37UT TOYOKAWA-FUJI

F20230908112033



BLK:11,SNR1: 1.0404 ,SNR2: 2.1185



T20230908112034





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1035-058 2023/09/08 2.37UT TOYOKAWA-KISO



F20230908112033





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/09/08 2.37UT FUJI -KISO




T20230908112946




BLK: 6,SNR1: 0.17619 ,SNR2: 1.1404




F20230908112946



BLK: 6,SNR1:-0.22257 ,SNR2: 1.4209




1044-008 2023/09/08 2.52UT TOYOKAWA-FUJI



T20230908112946





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1044-008 2023/09/08 2.52UT TOYOKAWA-KISO



F20230908112946



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1044-008 2023/09/08 2.52UT FUJI -KISO







T20230908114051




BLK:15,SNR1: 0.19724E-01,SNR2: 0.57525




F20230908114050



BLK:15,SNR1: 4.9004 ,SNR2: 34.205



1055+01 2023/09/08 2.71UT TOYOKAWA-FUJI



T20230908114051



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

1055+01 2023/09/08 2.71UT TOYOKAWA-KISO





F20230908114050




No.Good Data




KISO




No.Good Data




1055+01 2023/09/08 2.71UT FUJI -KISO




T20230908115208




BLK: 9,SNR1: 0.92634E-01,SNR2: 0.55968




F20230908115208





BLK: 9,SNR1: 6.2797 ,SNR2: 16.358




1107+109 2023/09/08 2.90UT TOYOKAWA-FUJI



T20230908115208





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1107+109 2023/09/08 2.90UT TOYOKAWA-KISO





F20230908115208




No.Good Data




KISO





No.Good Data




1107+109 2023/09/08 2.90UT FUJI -KISO





T20230908120146




BLK: 9,SNR1: 3.8103 ,SNR2: 15.291




F20230908120145




BLK: 9,SNR1:-0.82237E-01,SNR2: 0.90492



3C255 2023/09/08 3.06UT TOYOKAWA-FUJI



T20230908120146




No. Good Data



Frequency (Hz)

KISO



No. Good Data




Frequency (Hz)

3C255 2023/09/08 3.06UT TOYOKAWA-KISO






F20230908120145





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C255 2023/09/08 3.06UT FUJI -KISO




T20230908122544




BLK:12,SNR1: 2.1980 ,SNR2: 14.265




F20230908122544




BLK:12,SNR1: 0.15646 ,SNR2: 1.6830



3C263.1 2023/09/08 3.46UT TOYOKAWA-FUJI



T20230908122544




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C263.1 2023/09/08 3.46UT TOYOKAWA-KISO



F20230908122544





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C263.1 2023/09/08 3.46UT FUJI -KISO





T20230908123211




BLK:14,SNR1: 0.41215 ,SNR2: 2.4402




F20230908123210



BLK:14,SNR1: 1.9383 ,SNR2: 6.0232



3C267 2023/09/08 3.56UT TOYOKAWA-FUJI



T20230908123211





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2023/09/08 3.56UT TOYOKAWA-KISO



F20230908123210





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2023/09/08 3.56UT FUJI -KISO





T20230908125125




BLK:12,SNR1: 0.17771 ,SNR2: 0.97840




F20230908125124



BLK:12,SNR1: 1.4782 ,SNR2: 2.9721



1206+439 2023/09/08 3.88UT TOYOKAWA-FUJI






T20230908125125





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

1206+439 2023/09/08 3.88UT TOYOKAWA-KISO



F20230908125124





No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


1206+439 2023/09/08 3.88UT FUJI -KISO




T20230908131116




BLK:21,SNR1: 11.166 ,SNR2: 40.089




F20230908131116



BLK:21,SNR1:-0.64022E-01,SNR2: 2.1294




3C273 2023/09/08 4.22UT TOYOKAWA-FUJI



T20230908131116



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C273 2023/09/08 4.22UT TOYOKAWA-KISO



F20230908131116





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C273 2023/09/08 4.22UT FUJI -KISO




T20230908132426




BLK: 9,SNR1: 0.28560 ,SNR2: 1.4553




F20230908132425





BLK: 9,SNR1:-0.31230E-01,SNR2: 0.89092




3C275 2023/09/08 4.44UT TOYOKAWA-FUJI



T20230908132426



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C275 2023/09/08 4.44UT TOYOKAWA-KISO



F20230908132425





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C275 2023/09/08 4.44UT FUJI -KISO







T20230908133815




BLK: 7,SNR1: 0.37002 ,SNR2: 3.2069




F20230908133814





BLK: 7,SNR1:-0.13575 ,SNR2: 0.84540




3C279 2023/09/08 4.67UT TOYOKAWA-FUJI



T20230908133815




No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C279 2023/09/08 4.67UT TOYOKAWA-KISO



F20230908133814





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C279 2023/09/08 4.67UT FUJI -KISO





T20230908135803




BLK: 2,SNR1: 8.9278 ,SNR2: 40.989




F20230908135802





BLK: 2,SNR1:-0.72071E-01,SNR2: 0.91373




1313+453 2023/09/08 5.00UT TOYOKAWA-FUJI



T20230908135803





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1313+453 2023/09/08 5.00UT TOYOKAWA-KISO



F20230908135802





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1313+453 2023/09/08 5.00UT FUJI -KISO




T20230908140809




BLK:12,SNR1: 0.73390 ,SNR2: 1.7893




F20230908140808




BLK:12,SNR1:-0.42230E-01,SNR2: 0.58422




1323+32 2023/09/08 5.16UT TOYOKAWA-FUJI



T20230908140809





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)

1323+32 2023/09/08 5.16UT TOYOKAWA-KISO






F20230908140808





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1323+32 2023/09/08 5.16UT FUJI -KISO





T20230908141300




BLK:31,SNR1: 3.4276 ,SNR2: 20.553




F20230908141300






BLK:31,SNR1: 0.30636 ,SNR2: 1.2137






3C286 2023/09/08 5.24UT TOYOKAWA-FUJI




T20230908141300





KISO




3C286 2023/09/08 5.24UT TOYOKAWA-KISO





F20230908141300




No.Good Data




KISO





No.Good Data




3C286 2023/09/08 5.24UT FUJI -KISO





T20230908142927




BLK:12,SNR1: 0.22422 ,SNR2: 1.0507




F20230908142926





BLK:12,SNR1: 0.27190 ,SNR2: 1.3933




1345+12 2023/09/08 5.52UT TOYOKAWA-FUJI



T20230908142927





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1345+12 2023/09/08 5.52UT TOYOKAWA-KISO



F20230908142926





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1345+12 2023/09/08 5.52UT FUJI -KISO




T20230908143947




BLK: 4,SNR1: 0.15406E-01,SNR2: 1.6941




F20230908143946



BLK: 4,SNR1:-0.92812E-01,SNR2: 1.0602






1355+01 2023/09/08 5.69UT TOYOKAWA-FUJI









T20230908143947




KISO



1355+01 2023/09/08 5.69UT TOYOKAWA-KISO



F20230908143946




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1355+01 2023/09/08 5.69UT FUJI -KISO





T20230908150058




BLK: 9,SNR1: 0.80112 ,SNR2: 6.3537




F20230908150057




BLK: 9,SNR1: 0.80923 ,SNR2: 6.1950




3C298 2023/09/08 6.04UT TOYOKAWA-FUJI



T20230908150058





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C298 2023/09/08 6.04UT TOYOKAWA-KISO



F20230908150057





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C298 2023/09/08 6.04UT FUJI -KISO





T20230908151241




BLK: 7,SNR1: 0.50385 ,SNR2: 4.5593




F20230908151241





BLK: 7,SNR1:-0.72913E-01,SNR2: 1.2326




1428-03 2023/09/08 6.24UT TOYOKAWA-FUJI



T20230908151241





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1428-03 2023/09/08 6.24UT TOYOKAWA-KISO



F20230908151241





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1428-03 2023/09/08 6.24UT FUJI -KISO






T20230908153745





BLK: 4,SNR1: 0.21516 ,SNR2: 1.1154




Frequency (Hz)

F20230908153745




BLK: 4,SNR1: 0.19088 ,SNR2: 0.99647






Frequency (Hz)




1453-10 2023/09/08 6.66UT TOYOKAWA-FUJI




T20230908153745






KISO






1453-10 2023/09/08 6.66UT TOYOKAWA-KISO




F20230908153745





KISO




1453-10 2023/09/08 6.66UT FUJI -KISO




T20230908155238




BLK: 4,SNR1: 0.12829 ,SNR2: 0.88332




F20230908155238




BLK: 4,SNR1: 0.43768 ,SNR2: 4.0641




1508-05 2023/09/08 6.91UT TOYOKAWA-FUJI



T20230908155238





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1508-05 2023/09/08 6.91UT TOYOKAWA-KISO



F20230908155238





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1508-05 2023/09/08 6.91UT FUJI -KISO





T20230908160138




BLK: 7,SNR1: 29.272 ,SNR2: 49.541




F20230908160137






BLK: 7,SNR1:-0.13207E-01,SNR2: 2.6799






3C318 2023/09/08 7.06UT TOYOKAWA-FUJI




T20230908160138



KISO






3C318 2023/09/08 7.06UT TOYOKAWA-KISO









F20230908160137





KISO




3C318 2023/09/08 7.06UT FUJI -KISO




T20230908160725




BLK: 7,SNR1: 1.3197 ,SNR2: 4.5568




F20230908160724






BLK: 7,SNR1: 0.17471 ,SNR2: 0.99622






1523+03 2023/09/08 7.15UT TOYOKAWA-FUJI




T20230908160725






KISO






1523+03 2023/09/08 7.15UT TOYOKAWA-KISO




F20230908160724





KISO




1523+03 2023/09/08 7.15UT FUJI -KISO



T20230908161905





BLK: 4,SNR1:-0.48095E-01,SNR2: 0.17385




Frequency (Hz)

F20230908161905




BLK: 4,SNR1: 25.510 ,SNR2: 73.704






Frequency (Hz)




1535+139 2023/09/08 7.35UT TOYOKAWA-FUJI




T20230908161905





KISO




1535+139 2023/09/08 7.35UT TOYOKAWA-KISO



F20230908161905





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1535+139 2023/09/08 7.35UT FUJI -KISO





T20230908162928




BLK: 1,SNR1: 0.32325E-01,SNR2: 1.8687




F20230908162928



BLK: 1,SNR1: 0.21210 ,SNR2: 1.7629






1545-12 2023/09/08 7.52UT TOYOKAWA-FUJI









T20230908162928






KISO






1545-12 2023/09/08 7.52UT TOYOKAWA-KISO




F20230908162928





KISO




1545-12 2023/09/08 7.52UT FUJI -KISO





T20230908165032




BLK: 5,SNR1: 0.71714E-01,SNR2: 0.77884




F20230908165032






BLK: 5,SNR1: 0.97852 ,SNR2: 5.1455



1607+26 2023/09/08 7.87UT TOYOKAWA-FUJI






T20230908165032




No.Good Data

KISO






No.Good Data




1607+26 2023/09/08 7.87UT TOYOKAWA-KISO



F20230908165032



KISO



1607+26 2023/09/08 7.87UT FUJI -KISO

