






T20230912062310




No. Good Data




F20230912062309





No. Good Data




0552+12 2023/09/11 21.41UT TOYOKAWA-FUJI





T20230912062310




No.Good Data




K20230912062306



No.Good Data




0552+12 2023/09/11 21.41UT TOYOKAWA-KISO






F20230912062309





BLK: 5,SNR1:-0.52393E-01,SNR2: 0.62013




Frequency (Hz)

0552+12 2023/09/11 21.41UT FUJI -KISO


K20230912062306





BLK: 5,SNR1: 0.36117 ,SNR2: 1.8763




Frequency (Hz)



T20230912062736





No.Good Data




Frequency (Hz)

F20230912062736




No.Good Data





Frequency (Hz)


0556+191 2023/09/11 21.49UT TOYOKAWA-FUJI



T20230912062736




No.Good Data




Frequency (Hz)

K20230912062732




No.Good Data




Frequency (Hz)


0556+191 2023/09/11 21.49UT TOYOKAWA-KISO



F20230912062736





BLK: 6,SNR1: 0.90378 ,SNR2: 4.2510




Frequency (Hz)

K20230912062732




BLK: 6,SNR1:-0.85894E-01,SNR2: 0.63297





Frequency (Hz)


0556+191 2023/09/11 21.49UT FUJI -KISO



T20230912063209




No.Good Data




Frequency (Hz)

F20230912063209




No.Good Data





Frequency (Hz)


3C152 2023/09/11 21.56UT TOYOKAWA-FUJI



T20230912063209





No.Good Data




Frequency (Hz)

3C152 2023/09/11 21.56UT TOYOKAWA-KISO


K20230912063205





No.Good Data




Frequency (Hz)



F20230912063209




BLK: 3,SNR1: 0.48830 ,SNR2: 1.1678




Frequency (Hz)

3C152 2023/09/11 21.56UT FUJI -KISO


K20230912063205





BLK: 3,SNR1: 0.21257 ,SNR2: 1.0690




Frequency (Hz)



T20230912065431





No.Good Data




Frequency (Hz)

3C161 2023/09/11 21.94UT TOYOKAWA-FUJI


F20230912065431



No.Good Data





Frequency (Hz)






T20230912065431





No.Good Data




Frequency (Hz)

3C161 2023/09/11 21.94UT TOYOKAWA-KISO


K20230912065428




No.Good Data




Frequency (Hz)



F20230912065431




BLK: 9,SNR1: 1.5304 ,SNR2: 5.3815




Frequency (Hz)

3C161 2023/09/11 21.94UT FUJI -KISO


K20230912065428





BLK: 9,SNR1: 0.73724 ,SNR2: 2.9703




Frequency (Hz)



T20230912072204





No.Good Data




Frequency (Hz)

F20230912072203




No.Good Data





Frequency (Hz)


0652-130 2023/09/11 22.40UT TOYOKAWA-FUJI



T20230912072204





No. Good Data




Frequency (Hz)

K20230912072200




No. Good Data





Frequency (Hz)


0652-130 2023/09/11 22.40UT TOYOKAWA-KISO





F20230912072203




No.Good Data




K20230912072200





No.Good Data




0652-130 2023/09/11 22.40UT FUJI -KISO



T20230912073340




No.Good Data




Frequency (Hz)

F20230912073339




No.Good Data





Frequency (Hz)


0703+138 2023/09/11 22.59UT TOYOKAWA-FUJI



T20230912073340




No.Good Data




Frequency (Hz)

K20230912073336




No.Good Data





Frequency (Hz)


0703+138 2023/09/11 22.59UT TOYOKAWA-KISO



F20230912073339




BLK: 1,SNR1: 0.20698 ,SNR2: 0.74749




Frequency (Hz)

K20230912073336




BLK: 1,SNR1: 0.44204 ,SNR2: 1.1414





Frequency (Hz)

0703+138 2023/09/11 22.59UT FUJI -KISO








T20230912074303




No.Good Data




F20230912074302





No.Good Data




0713-024 2023/09/11 22.75UT TOYOKAWA-FUJI



T20230912074303





No.Good Data




Frequency (Hz)

K20230912074259




No.Good Data




Frequency (Hz)


0713-024 2023/09/11 22.75UT TOYOKAWA-KISO



F20230912074302




BLK: 4,SNR1: 0.30861 ,SNR2: 2.1355




Frequency (Hz)

K20230912074259




BLK: 4,SNR1: 0.12206 ,SNR2: 2.9251





Frequency (Hz)


0713-024 2023/09/11 22.75UT FUJI -KISO





T20230912075314




No.Good Data




F20230912075313





No.Good Data




0723+10 2023/09/11 22.92UT TOYOKAWA-FUJI



T20230912075314





No.Good Data




Frequency (Hz)

K20230912075310




No.Good Data




Frequency (Hz)


0723+10 2023/09/11 22.92UT TOYOKAWA-KISO



F20230912075313





BLK: 7,SNR1: 0.46442 ,SNR2: 1.7512




Frequency (Hz)

K20230912075310




BLK: 7,SNR1: 0.56229 ,SNR2: 2.2846





Frequency (Hz)


0723+10 2023/09/11 22.92UT FUJI -KISO



T20230912080328




No.Good Data




Frequency (Hz)

F20230912080328




No.Good Data





Frequency (Hz)


0732+33 2023/09/11 23.09UT TOYOKAWA-FUJI




T20230912080328




No.Good Data




K20230912080324



No.Good Data





0732+33 2023/09/11 23.09UT TOYOKAWA-KISO






F20230912080328





BLK: 4,SNR1:-0.73312E-01,SNR2: 1.2550




Frequency (Hz)

K20230912080324




BLK: 4,SNR1: 0.61016 ,SNR2: 2.0864





Frequency (Hz)


0732+33 2023/09/11 23.09UT FUJI -KISO



T20230912081131





No.Good Data




Frequency (Hz)

F20230912081130




No.Good Data





Frequency (Hz)


0741-06 2023/09/11 23.22UT TOYOKAWA-FUJI




T20230912081131




No.Good Data




K20230912081127




No.Good Data




0741-06 2023/09/11 23.22UT TOYOKAWA-KISO



F20230912081130




BLK: 3,SNR1:-0.50164E-02,SNR2: 0.81844




Frequency (Hz)

K20230912081127




BLK: 3,SNR1: 0.33784 ,SNR2: 0.86556





Frequency (Hz)


0741-06 2023/09/11 23.22UT FUJI -KISO




T20230912082850




No.Good Data




F20230912082850





No.Good Data




3C190 2023/09/11 23.51UT TOYOKAWA-FUJI




T20230912082850




No.Good Data




K20230912082847





No.Good Data




3C190 2023/09/11 23.51UT TOYOKAWA-KISO



F20230912082850





BLK: 7,SNR1: 9.7622 ,SNR2: 9.2771




Frequency (Hz)

K20230912082847




BLK: 7,SNR1: 0.17604 ,SNR2: 2.4131





Frequency (Hz)


3C190 2023/09/11 23.51UT FUJI -KISO





T20230912084114




No.Good Data




F20230912084113



No.Good Data





3C196 2023/09/11 23.72UT TOYOKAWA-FUJI








T20230912084114




No.Good Data




K20230912084110




No.Good Data




3C196 2023/09/11 23.72UT TOYOKAWA-KISO



F20230912084113




BLK:10,SNR1: 0.70380 ,SNR2: 2.8390




Frequency (Hz)

3C196 2023/09/11 23.72UT FUJI -KISO


K20230912084110





BLK:10,SNR1: 0.23079E-01,SNR2: 0.58700




Frequency (Hz)



T20230912085224




No.Good Data




Frequency (Hz)

F20230912085223




No.Good Data





Frequency (Hz)


0821+394 2023/09/11 23.90UT TOYOKAWA-FUJI




T20230912085224




No. Good Data




K20230912085220





No. Good Data




0821+394 2023/09/11 23.90UT TOYOKAWA-KISO



F20230912085223





BLK: 6,SNR1: 1.5394 ,SNR2: 3.8933




Frequency (Hz)

K20230912085220




BLK: 6,SNR1: 0.14917 ,SNR2: 0.24540





Frequency (Hz)


0821+394 2023/09/11 23.90UT FUJI -KISO





T20230912090910




No. Good Data




F20230912090910





No. Good Data




0839-071 2023/09/12 0.18UT TOYOKAWA-FUJI




T20230912090910




No.Good Data




K20230912090906




No.Good Data




0839-071 2023/09/12 0.18UT TOYOKAWA-KISO




F20230912090910




BLK: 2,SNR1: 0.33687E-01,SNR2: 1.7830




K20230912090906



BLK: 2,SNR1: 0.21255 ,SNR2: 4.2241





0839-071 2023/09/12 0.18UT FUJI -KISO








T20230912092011




No.Good Data




F20230912092010





No.Good Data




3C208 2023/09/12 0.36UT TOYOKAWA-FUJI



T20230912092011




No.Good Data




Frequency (Hz)

K20230912092007




No.Good Data





Frequency (Hz)


3C208 2023/09/12 0.36UT TOYOKAWA-KISO



F20230912092010




BLK: 4,SNR1: 0.15079 ,SNR2: 3.1927




Frequency (Hz)

3C208 2023/09/12 0.36UT FUJI -KISO


K20230912092007





BLK: 4,SNR1: 0.27665 ,SNR2: 1.4954




Frequency (Hz)





T20230912093651




No. Good Data




F20230912093651





No. Good Data




3C216 2023/09/12 0.64UT TOYOKAWA-FUJI




T20230912093651




No. Good Data




K20230912093647




No. Good Data




3C216 2023/09/12 0.64UT TOYOKAWA-KISO



F20230912093651




BLK: 7,SNR1: 1.2065 ,SNR2: 3.7753





3C216 2023/09/12 0.64UT FUJI -KISO



K20230912093647




BLK: 7,SNR1: 0.20791 ,SNR2: 0.67556




T20230912095543




No. Good Data




F20230912095543





No. Good Data




0926+117 2023/09/12 0.96UT TOYOKAWA-FUJI





T20230912095543




No. Good Data




K20230912095539



No. Good Data





0926+117 2023/09/12 0.96UT TOYOKAWA-KISO







F20230912095543




BLK: 7,SNR1: 0.76238 ,SNR2: 3.4622




K20230912095539





BLK: 7,SNR1: 0.33341 ,SNR2: 1.1007




0926+117 2023/09/12 0.96UT FUJI -KISO



T20230912100327





No. Good Data




Frequency (Hz)

3C222 2023/09/12 1.09UT TOYOKAWA-FUJI


F20230912100326





No. Good Data




Frequency (Hz)




T20230912100327




No. Good Data




K20230912100324





No. Good Data




3C222 2023/09/12 1.09UT TOYOKAWA-KISO



F20230912100326





BLK:17,SNR1: 3.2372 ,SNR2: 4.9511




Frequency (Hz)

3C222 2023/09/12 1.09UT FUJI -KISO


K20230912100324





BLK:17,SNR1: 4.6902 ,SNR2: 19.866




Frequency (Hz)





T20230912101028




No. Good Data




F20230912101027





No. Good Data




0941-08 2023/09/12 1.20UT TOYOKAWA-FUJI





T20230912101028




No. Good Data




K20230912101024




No. Good Data




0941-08 2023/09/12 1.20UT TOYOKAWA-KISO




F20230912101027




BLK:10,SNR1: 0.42224 ,SNR2: 1.6955




K20230912101024





BLK:10,SNR1: 0.44668 ,SNR2: 3.7015




0941-08 2023/09/12 1.20UT FUJI -KISO





T20230912101849




No. Good Data




F20230912101848



No. Good Data





3C230 2023/09/12 1.34UT TOYOKAWA-FUJI








T20230912101849




No. Good Data




K20230912101845




No. Good Data




3C230 2023/09/12 1.34UT TOYOKAWA-KISO





F20230912101848




BLK: 7,SNR1:-0.52808E-01,SNR2: 2.2255




K20230912101845





BLK: 7,SNR1: 0.16143 ,SNR2: 1.3416




3C230 2023/09/12 1.34UT FUJI -KISO





T20230912103256




No. Good Data




F20230912103255





No. Good Data




3C236 2023/09/12 1.58UT TOYOKAWA-FUJI



T20230912103256





No. Good Data




Frequency (Hz)

K20230912103252




No. Good Data




Frequency (Hz)


3C236 2023/09/12 1.58UT TOYOKAWA-KISO




F20230912103255




BLK: 7,SNR1: 0.13008 ,SNR2: 2.1957




K20230912103252





BLK: 7,SNR1: 0.18240 ,SNR2: 3.9653




3C236 2023/09/12 1.58UT FUJI -KISO





T20230912104106




No. Good Data




F20230912104105





No. Good Data




1011+110 2023/09/12 1.71UT TOYOKAWA-FUJI





T20230912104106




No. Good Data




K20230912104102





No. Good Data




1011+110 2023/09/12 1.71UT TOYOKAWA-KISO





F20230912104105




BLK: 4,SNR1: 0.27560 ,SNR2: 1.6797




K20230912104102



BLK: 4,SNR1: 0.39420 ,SNR2: 3.8318





1011+110 2023/09/12 1.71UT FUJI -KISO








T20230912104847




No. Good Data




F20230912104846




No. Good Data




3C241 2023/09/12 1.84UT TOYOKAWA-FUJI




T20230912104847




No. Good Data




K20230912104843




No. Good Data




3C241 2023/09/12 1.84UT TOYOKAWA-KISO




F20230912104846




BLK:23,SNR1: 0.20942 ,SNR2: 2.2476




K20230912104843





BLK:23,SNR1: 0.43169 ,SNR2: 4.3083




3C241 2023/09/12 1.84UT FUJI -KISO



T20230912110017





No. Good Data




Frequency (Hz)

F20230912110016




No. Good Data





Frequency (Hz)


1031-11 2023/09/12 2.03UT TOYOKAWA-FUJI





T20230912110017




No. Good Data




K20230912110013




No. Good Data




1031-11 2023/09/12 2.03UT TOYOKAWA-KISO



F20230912110016





BLK: 5,SNR1: 0.31538 ,SNR2: 1.4647





1031-11 2023/09/12 2.03UT FUJI -KISO



K20230912110013




BLK: 5,SNR1: 0.50190E-01,SNR2: 1.6128



T20230912110450





No. Good Data




Frequency (Hz)

F20230912110449




No. Good Data





Frequency (Hz)


1035-058 2023/09/12 2.11UT TOYOKAWA-FUJI



T20230912110450





No. Good Data




Frequency (Hz)

K20230912110446




No. Good Data




Frequency (Hz)

1035-058 2023/09/12 2.11UT TOYOKAWA-KISO








F20230912110449




BLK: 7,SNR1:-0.74742E-01,SNR2: 1.0005




K20230912110446





BLK: 7,SNR1: 0.98460 ,SNR2: 4.5057




1035-058 2023/09/12 2.11UT FUJI -KISO



T20230912111403





No. Good Data




Frequency (Hz)

F20230912111402




No. Good Data





Frequency (Hz)


1044-008 2023/09/12 2.26UT TOYOKAWA-FUJI



T20230912111403





No. Good Data




Frequency (Hz)

K20230912111359




No. Good Data




Frequency (Hz)


1044-008 2023/09/12 2.26UT TOYOKAWA-KISO



F20230912111402




BLK: 9,SNR1: 0.16561 ,SNR2: 2.6340





1044-008 2023/09/12 2.26UT FUJI -KISO



K20230912111359




BLK: 9,SNR1: 69.802 ,SNR2: 78.726



T20230912112507




No. Good Data




Frequency (Hz)

F20230912112506




No. Good Data





Frequency (Hz)


1055+01 2023/09/12 2.45UT TOYOKAWA-FUJI



T20230912112507





No. Good Data




Frequency (Hz)

K20230912112503




No. Good Data




Frequency (Hz)


1055+01 2023/09/12 2.45UT TOYOKAWA-KISO



F20230912112506




BLK: 9,SNR1: 20.063 ,SNR2: 27.339





1055+01 2023/09/12 2.45UT FUJI -KISO



K20230912112503




BLK: 9,SNR1: 0.54836 ,SNR2: 1.9558




T20230912113625




No. Good Data




F20230912113624



No. Good Data





1107+109 2023/09/12 2.63UT TOYOKAWA-FUJI








T20230912113625




No. Good Data




K20230912113621





No. Good Data




1107+109 2023/09/12 2.63UT TOYOKAWA-KISO



F20230912113624





BLK: 5,SNR1:-0.90061E-03,SNR2: 1.0259




Frequency (Hz)

K20230912113621




BLK: 5,SNR1: 0.82515 ,SNR2: 2.8376





Frequency (Hz)


1107+109 2023/09/12 2.63UT FUJI -KISO



T20230912114602





No. Good Data




Frequency (Hz)

F20230912114601




No. Good Data





Frequency (Hz)


3C255 2023/09/12 2.80UT TOYOKAWA-FUJI



T20230912114602





No.Good Data




Frequency (Hz)

K20230912114558




No.Good Data





Frequency (Hz)


3C255 2023/09/12 2.80UT TOYOKAWA-KISO



F20230912114601





BLK:12,SNR1: 0.69559 ,SNR2: 7.6600





3C255 2023/09/12 2.80UT FUJI -KISO



K20230912114558




BLK:12,SNR1: 5.0684 ,SNR2: 16.169



T20230912121000





No. Good Data




Frequency (Hz)

F20230912120959




No. Good Data





Frequency (Hz)


3C263.1 2023/09/12 3.19UT TOYOKAWA-FUJI





T20230912121000




No.Good Data




K20230912120956




No.Good Data




3C263.1 2023/09/12 3.19UT TOYOKAWA-KISO




F20230912120959




BLK: 9,SNR1: 0.65881E-01,SNR2: 2.4163




K20230912120956



BLK: 9,SNR1: 0.25787 ,SNR2: 2.7236





3C263.1 2023/09/12 3.19UT FUJI -KISO






T20230912121627





No. Good Data




Frequency (Hz)

F20230912121626




No. Good Data





Frequency (Hz)


3C267 2023/09/12 3.30UT TOYOKAWA-FUJI




T20230912121627




No. Good Data




K20230912121623




No. Good Data




3C267 2023/09/12 3.30UT TOYOKAWA-KISO





F20230912121626




BLK: 8,SNR1: 0.18624 ,SNR2: 1.8029




K20230912121623





BLK: 8,SNR1: 0.29320 ,SNR2: 3.1910




3C267 2023/09/12 3.30UT FUJI -KISO



T20230912123541




No. Good Data




Frequency (Hz)

F20230912123540




No. Good Data




Frequency (Hz)


1206+439 2023/09/12 3.62UT TOYOKAWA-FUJI




T20230912123541




No.Good Data




K20230912123537




No.Good Data




1206+439 2023/09/12 3.62UT TOYOKAWA-KISO




F20230912123540




BLK: 6,SNR1: 0.45981 ,SNR2: 1.8933




K20230912123537




BLK: 6,SNR1: 0.24486 ,SNR2: 0.83283




1206+439 2023/09/12 3.62UT FUJI -KISO




T20230912125532




No.Good Data




F20230912125531





No.Good Data




3C273 2023/09/12 3.95UT TOYOKAWA-FUJI





T20230912125532




No. Good Data




K20230912125528



No. Good Data




3C273 2023/09/12 3.95UT TOYOKAWA-KISO






F20230912125531





BLK:32,SNR1: 0.22132 ,SNR2: 3.4331





3C273 2023/09/12 3.95UT FUJI -KISO



K20230912125528




BLK:32,SNR1: 6.3549 ,SNR2: 19.134



T20230912130843





No. Good Data




Frequency (Hz)

F20230912130843




No. Good Data





Frequency (Hz)


3C275 2023/09/12 4.17UT TOYOKAWA-FUJI




T20230912130843




No. Good Data




K20230912130839




No. Good Data




3C275 2023/09/12 4.17UT TOYOKAWA-KISO



F20230912130843





BLK: 7,SNR1:-0.99439E-01,SNR2: 1.1720





3C275 2023/09/12 4.17UT FUJI -KISO



K20230912130839




BLK: 7,SNR1: 0.10996 ,SNR2: 0.42200



T20230912132231





No. Good Data




Frequency (Hz)

F20230912132230




No. Good Data





Frequency (Hz)


3C279 2023/09/12 4.40UT TOYOKAWA-FUJI



T20230912132231





No.Good Data




Frequency (Hz)

K20230912132227




No.Good Data




Frequency (Hz)


3C279 2023/09/12 4.40UT TOYOKAWA-KISO





F20230912132230




BLK: 8,SNR1: 0.97380 ,SNR2: 7.3375




K20230912132227





BLK: 8,SNR1:-0.20998E-01,SNR2: 1.2665




3C279 2023/09/12 4.40UT FUJI -KISO




T20230912134220




No.Good Data




F20230912134220



No.Good Data





1313+453 2023/09/12 4.73UT TOYOKAWA-FUJI






T20230912134220





No. Good Data




Frequency (Hz)

K20230912134216




No. Good Data





Frequency (Hz)


1313+453 2023/09/12 4.73UT TOYOKAWA-KISO





F20230912134220




BLK: 3,SNR1: 0.55649 ,SNR2: 1.9847




K20230912134216





BLK: 3,SNR1:-0.24364E-01,SNR2: 0.97955




1313+453 2023/09/12 4.73UT FUJI -KISO





T20230912135226




No.Good Data




F20230912135225





No.Good Data




1323+32 2023/09/12 4.90UT TOYOKAWA-FUJI





T20230912135226




No. Good Data




K20230912135222




No. Good Data




1323+32 2023/09/12 4.90UT TOYOKAWA-KISO





F20230912135225




BLK: 8,SNR1: 0.59697 ,SNR2: 2.9180




K20230912135222





BLK: 8,SNR1: 0.54187 ,SNR2: 1.8221




1323+32 2023/09/12 4.90UT FUJI -KISO




T20230912135716




No. Good Data




F20230912135715





No. Good Data




3C286 2023/09/12 4.98UT TOYOKAWA-FUJI





T20230912135716




No.Good Data




K20230912135712





No.Good Data




3C286 2023/09/12 4.98UT TOYOKAWA-KISO



F20230912135715





BLK:16,SNR1: 0.15781 ,SNR2: 2.2933





3C286 2023/09/12 4.98UT FUJI -KISO

K20230912135712





BLK:16,SNR1: 0.51321 ,SNR2: 2.2601







T20230912141343




No.Good Data




F20230912141342





No.Good Data




1345+12 2023/09/12 5.26UT TOYOKAWA-FUJI




T20230912141343




No. Good Data




K20230912141339





No. Good Data




1345+12 2023/09/12 5.26UT TOYOKAWA-KISO





F20230912141342




BLK: 7,SNR1: 0.30143 ,SNR2: 1.5918




K20230912141339





BLK: 7,SNR1: 0.22261 ,SNR2: 2.4258




1345+12 2023/09/12 5.26UT FUJI -KISO





T20230912142403




BLK: 9,SNR1: 3.7700 ,SNR2: 17.750




F20230912142402





BLK: 9,SNR1:-0.22603 ,SNR2: 0.93481




1355+01 2023/09/12 5.43UT TOYOKAWA-FUJI



T20230912142403





BLK:10,SNR1: 3.8452 ,SNR2: 13.594





1355+01 2023/09/12 5.43UT TOYOKAWA-KISO


K20230912142359




BLK:10,SNR1: 0.21484 ,SNR2: 1.4392





F20230912142402




BLK: 3,SNR1: 0.44474E-01,SNR2: 2.6269




K20230912142359





BLK: 3,SNR1: 0.18176 ,SNR2: 1.0934




1355+01 2023/09/12 5.43UT FUJI -KISO




T20230912144514




BLK:16,SNR1: 2.9498 ,SNR2: 20.090




F20230912144513





BLK:16,SNR1: 1.3696 ,SNR2: 2.1199




3C298 2023/09/12 5.78UT TOYOKAWA-FUJI



T20230912144514





BLK:10,SNR1: 2.8017 ,SNR2: 10.214




Frequency (Hz)

3C298 2023/09/12 5.78UT TOYOKAWA-KISO


K20230912144510



BLK:10,SNR1: 24.195 ,SNR2: 46.836





Frequency (Hz)






F20230912144513





BLK:26,SNR1: 0.45162 ,SNR2: 5.2656





3C298 2023/09/12 5.78UT FUJI -KISO



K20230912144510




BLK:26,SNR1: 15.597 ,SNR2: 63.720




T20230912145657




BLK: 5,SNR1: 3.1012 ,SNR2: 4.4100




F20230912145657





BLK: 5,SNR1: 0.80673 ,SNR2: 2.7893




1428-03 2023/09/12 5.98UT TOYOKAWA-FUJI





T20230912145657




BLK:10,SNR1: 3.4300 ,SNR2: 6.3322




K20230912145653





BLK:10,SNR1: 0.19974 ,SNR2: 0.46132




1428-03 2023/09/12 5.98UT TOYOKAWA-KISO



F20230912145657





BLK: 7,SNR1: 0.55808 ,SNR2: 1.7775




Frequency (Hz)

K20230912145653




BLK: 7,SNR1: 0.21319 ,SNR2: 0.64889





Frequency (Hz)


1428-03 2023/09/12 5.98UT FUJI -KISO





T20230912152202




BLK: 7,SNR1: 1.0202 ,SNR2: 5.9877




F20230912152201





BLK: 7,SNR1: 1.1487 ,SNR2: 9.6173




1453-10 2023/09/12 6.40UT TOYOKAWA-FUJI





T20230912152202




BLK:12,SNR1: 0.69286 ,SNR2: 2.6775




K20230912152158





BLK:12,SNR1: 0.32391 ,SNR2: 3.2604




1453-10 2023/09/12 6.40UT TOYOKAWA-KISO



F20230912152201





BLK: 1,SNR1:-0.29785 ,SNR2: 0.82810E-01





1453-10 2023/09/12 6.40UT FUJI -KISO



K20230912152158




BLK: 1,SNR1: 0.22072 ,SNR2: 0.55354



T20230912153654





BLK:10,SNR1: 0.18531 ,SNR2: 1.6148




Frequency (Hz)

F20230912153653




BLK:10,SNR1:-0.29391E-01,SNR2: 1.7342





Frequency (Hz)

1508-05 2023/09/12 6.64UT TOYOKAWA-FUJI








T20230912153654




BLK: 9,SNR1: 0.78131E-01,SNR2: 1.3834




K20230912153650





BLK: 9,SNR1: 0.20972 ,SNR2: 2.1108




1508-05 2023/09/12 6.64UT TOYOKAWA-KISO



F20230912153653





BLK: 6,SNR1:-0.11065 ,SNR2: 0.73715




Frequency (Hz)

K20230912153650




BLK: 6,SNR1: 0.40613 ,SNR2: 2.2513




Frequency (Hz)


1508-05 2023/09/12 6.64UT FUJI -KISO





T20230912154555




BLK: 8,SNR1: 2.0326 ,SNR2: 8.7436




F20230912154554





BLK: 8,SNR1: 0.37770 ,SNR2: 1.1257




3C318 2023/09/12 6.79UT TOYOKAWA-FUJI





T20230912154555




BLK:12,SNR1: 1.8750 ,SNR2: 9.7731




K20230912154551





BLK:12,SNR1: 0.46838 ,SNR2: 3.8668




3C318 2023/09/12 6.79UT TOYOKAWA-KISO





F20230912154554




BLK: 4,SNR1:-0.66611E-01,SNR2: 3.3583




K20230912154551





BLK: 4,SNR1: 0.17806 ,SNR2: 1.5759




3C318 2023/09/12 6.79UT FUJI -KISO



T20230912155141





BLK: 9,SNR1: 3.4607 ,SNR2: 17.072





1523+03 2023/09/12 6.89UT TOYOKAWA-FUJI



F20230912155140




BLK: 9,SNR1: 2.6034 ,SNR2: 11.136



T20230912155141





BLK: 5,SNR1: 3.7718 ,SNR2: 14.883




Frequency (Hz)

K20230912155138




BLK: 5,SNR1: 0.12941 ,SNR2: 0.53495





Frequency (Hz)


1523+03 2023/09/12 6.89UT TOYOKAWA-KISO




F20230912155140




BLK:10,SNR1: 2.8232 ,SNR2: 6.1659




K20230912155138



BLK:10,SNR1: 0.77135E-01,SNR2: 0.96639





1523+03 2023/09/12 6.89UT FUJI -KISO








T20230912160321




BLK: 8,SNR1: 4.0044 ,SNR2: 34.517




F20230912160320





BLK: 8,SNR1: 0.32841 ,SNR2: 1.8860




1535+139 2023/09/12 7.08UT TOYOKAWA-FUJI





T20230912160321




BLK:12,SNR1: 3.3083 ,SNR2: 8.0208




K20230912160317





BLK:12,SNR1: 0.35634 ,SNR2: 2.9773




1535+139 2023/09/12 7.08UT TOYOKAWA-KISO



F20230912160320





BLK: 4,SNR1: 0.35278 ,SNR2: 1.7193




Frequency (Hz)

K20230912160317




BLK: 4,SNR1: 0.45340 ,SNR2: 1.5508





Frequency (Hz)


1535+139 2023/09/12 7.08UT FUJI -KISO



T20230912161345





BLK: 5,SNR1: 1.4121 ,SNR2: 8.9969




Frequency (Hz)

F20230912161345




BLK: 5,SNR1:-0.27548 ,SNR2: 0.49511





Frequency (Hz)


1545-12 2023/09/12 7.26UT TOYOKAWA-FUJI





T20230912161345




BLK:14,SNR1: 1.2597 ,SNR2: 8.2749




K20230912161341





BLK:14,SNR1: 0.31420 ,SNR2: 1.1364




1545-12 2023/09/12 7.26UT TOYOKAWA-KISO



F20230912161345





BLK: 2,SNR1: 0.56538E-01,SNR2: 0.25850




Frequency (Hz)

K20230912161341




BLK: 2,SNR1: 0.22113 ,SNR2: 2.3337





Frequency (Hz)


1545-12 2023/09/12 7.26UT FUJI -KISO





T20230912163449




BLK: 6,SNR1: 0.40171 ,SNR2: 4.1917




F20230912163448





BLK: 6,SNR1: 0.22187 ,SNR2: 3.7487




1607+26 2023/09/12 7.61UT TOYOKAWA-FUJI



T20230912163449





BLK:11,SNR1: 0.55027 ,SNR2: 2.9687




Frequency (Hz)

K20230912163445




BLK:11,SNR1: 0.24408 ,SNR2: 1.6382





Frequency (Hz)

1607+26 2023/09/12 7.61UT TOYOKAWA-KISO






F20230912163448





BLK: 2,SNR1: 0.96048E-01,SNR2: 0.95821




Frequency (Hz)

K20230912163445



BLK: 2,SNR1: 0.57113 ,SNR2: 7.4756



Frequency (Hz)

1607+26 2023/09/12 7.61UT FUJI -KISO

