




T20230915064243





BLK:14,SNR1: 1.9595 ,SNR2: 13.431




Frequency (Hz)

3C161 2023/09/14 21.74UT TOYOKAWA-FUJI


F20230915064243





BLK:14,SNR1: 2.9048 ,SNR2: 17.595




Frequency (Hz)



T20230915064243





BLK:20,SNR1: 1.2499 ,SNR2: 9.0628




Frequency (Hz)

3C161 2023/09/14 21.74UT TOYOKAWA-KISO


K20230915064239



BLK:20,SNR1: 3.4357 ,SNR2: 10.418





Frequency (Hz)






F20230915064243





BLK:10,SNR1: 7.1961 ,SNR2: 15.450




Frequency (Hz)

3C161 2023/09/14 21.74UT FUJI -KISO


K20230915064239




BLK:10,SNR1: 6.2024 ,SNR2: 24.099




Frequency (Hz)



T20230915071016





BLK:22,SNR1: 0.78531 ,SNR2: 4.9261




Frequency (Hz)

F20230915071015




BLK:22,SNR1:-0.56692E-01,SNR2: 1.6652





Frequency (Hz)


0652-130 2023/09/14 22.20UT TOYOKAWA-FUJI



T20230915071016





BLK:25,SNR1: 0.67187 ,SNR2: 1.9925




Frequency (Hz)

K20230915071012




BLK:25,SNR1: 0.42259 ,SNR2: 1.7380





Frequency (Hz)


0652-130 2023/09/14 22.20UT TOYOKAWA-KISO



F20230915071015





BLK:13,SNR1:-0.35614E-01,SNR2: 1.9572




Frequency (Hz)

K20230915071012




BLK:13,SNR1: 0.25358 ,SNR2: 1.1259





Frequency (Hz)


0652-130 2023/09/14 22.20UT FUJI -KISO



T20230915072152





BLK: 8,SNR1: 0.46306 ,SNR2: 6.8286




Frequency (Hz)

F20230915072151




BLK: 8,SNR1: 0.41517 ,SNR2: 2.8363





Frequency (Hz)


0703+138 2023/09/14 22.39UT TOYOKAWA-FUJI



T20230915072152





BLK:16,SNR1: 0.23360 ,SNR2: 1.6079




Frequency (Hz)

K20230915072149




BLK:16,SNR1: 2.0517 ,SNR2: 6.7762





Frequency (Hz)


0703+138 2023/09/14 22.39UT TOYOKAWA-KISO



F20230915072151





BLK:17,SNR1: 0.28979 ,SNR2: 1.2748




Frequency (Hz)

K20230915072149




BLK:17,SNR1: 2.2662 ,SNR2: 9.2548





Frequency (Hz)


0703+138 2023/09/14 22.39UT FUJI -KISO



T20230915073115





BLK: 5,SNR1: 0.42261 ,SNR2: 1.7923




Frequency (Hz)

F20230915073115




BLK: 5,SNR1:-0.73315E-02,SNR2: 1.6417





Frequency (Hz)

0713-024 2023/09/14 22.55UT TOYOKAWA-FUJI






T20230915073115





BLK: 7,SNR1: 0.35715 ,SNR2: 2.4080




Frequency (Hz)

K20230915073111




BLK: 7,SNR1: 0.20521 ,SNR2: 1.1185





Frequency (Hz)


0713-024 2023/09/14 22.55UT TOYOKAWA-KISO



F20230915073115





BLK: 5,SNR1: 1.3282 ,SNR2: 2.7474




Frequency (Hz)

K20230915073111




BLK: 5,SNR1: 0.14375 ,SNR2: 1.4367





Frequency (Hz)


0713-024 2023/09/14 22.55UT FUJI -KISO



T20230915074127





BLK:19,SNR1: 0.30916 ,SNR2: 0.95789




Frequency (Hz)

F20230915074126




BLK:19,SNR1: 1.2189 ,SNR2: 2.9550





Frequency (Hz)


0723+10 2023/09/14 22.72UT TOYOKAWA-FUJI



T20230915074127





BLK:11,SNR1: 0.33516 ,SNR2: 2.8163




Frequency (Hz)

K20230915074123




BLK:11,SNR1: 0.26858 ,SNR2: 3.3133




Frequency (Hz)


0723+10 2023/09/14 22.72UT TOYOKAWA-KISO



F20230915074126





BLK:15,SNR1: 1.3450 ,SNR2: 8.1585




Frequency (Hz)

K20230915074123




BLK:15,SNR1: 0.14840 ,SNR2: 1.7133





Frequency (Hz)


0723+10 2023/09/14 22.72UT FUJI -KISO



T20230915075141





BLK:25,SNR1: 0.58754 ,SNR2: 3.6526




Frequency (Hz)

F20230915075140




BLK:25,SNR1: 0.83454 ,SNR2: 5.8949





Frequency (Hz)


0732+33 2023/09/14 22.89UT TOYOKAWA-FUJI



T20230915075141





BLK:24,SNR1: 0.59342 ,SNR2: 3.7866




Frequency (Hz)

K20230915075137




BLK:24,SNR1: 1.5651 ,SNR2: 5.9791





Frequency (Hz)


0732+33 2023/09/14 22.89UT TOYOKAWA-KISO



F20230915075140





BLK:26,SNR1: 0.63241 ,SNR2: 6.3297




Frequency (Hz)

K20230915075137




BLK:26,SNR1: 1.3607 ,SNR2: 5.1434





Frequency (Hz)

0732+33 2023/09/14 22.89UT FUJI -KISO






T20230915075943





BLK: 6,SNR1: 0.44901 ,SNR2: 1.9984




Frequency (Hz)

0741-06 2023/09/14 23.02UT TOYOKAWA-FUJI


F20230915075942





BLK: 6,SNR1: 0.67085 ,SNR2: 1.9660




Frequency (Hz)



T20230915075943





BLK:11,SNR1: 0.24788 ,SNR2: 1.2376




Frequency (Hz)

K20230915075940




BLK:11,SNR1:-0.48897E-02,SNR2: 0.31720





Frequency (Hz)


0741-06 2023/09/14 23.02UT TOYOKAWA-KISO



F20230915075942





BLK: 6,SNR1: 0.19295 ,SNR2: 1.0326




Frequency (Hz)

K20230915075940




BLK: 6,SNR1:-0.30544E-01,SNR2: 0.60207





Frequency (Hz)


0741-06 2023/09/14 23.02UT FUJI -KISO



T20230915081702




BLK:26,SNR1: 2.3452 ,SNR2: 11.197




Frequency (Hz)

3C190 2023/09/14 23.31UT TOYOKAWA-FUJI


F20230915081701





BLK:26,SNR1: 0.41289 ,SNR2: 1.8175




Frequency (Hz)



T20230915081702





BLK:26,SNR1: 2.2472 ,SNR2: 11.126




Frequency (Hz)

3C190 2023/09/14 23.31UT TOYOKAWA-KISO


K20230915081658




BLK:26,SNR1: 0.51016 ,SNR2: 2.3993




Frequency (Hz)



F20230915081701





BLK:15,SNR1: 0.45119 ,SNR2: 4.1783




Frequency (Hz)

3C190 2023/09/14 23.31UT FUJI -KISO


K20230915081658





BLK:15,SNR1: 0.44274 ,SNR2: 2.1100




Frequency (Hz)



T20230915082926





BLK: 9,SNR1: 0.11025 ,SNR2: 1.9320




Frequency (Hz)

F20230915082925




BLK: 9,SNR1: 6.0361 ,SNR2: 10.643





Frequency (Hz)


3C196 2023/09/14 23.52UT TOYOKAWA-FUJI



T20230915082926





BLK: 7,SNR1: 0.17139 ,SNR2: 1.6188




Frequency (Hz)

3C196 2023/09/14 23.52UT TOYOKAWA-KISO


K20230915082922



BLK: 7,SNR1: 0.39496 ,SNR2: 1.5083





Frequency (Hz)






F20230915082925





BLK: 4,SNR1: 2.0346 ,SNR2: 9.8678




Frequency (Hz)

3C196 2023/09/14 23.52UT FUJI -KISO


K20230915082922




BLK: 4,SNR1: 0.74880E-01,SNR2: 0.35152




Frequency (Hz)




T20230915084036




No.Good Data




F20230915084036





No.Good Data




0821+394 2023/09/14 23.70UT TOYOKAWA-FUJI





T20230915084036




BLK: 6,SNR1: 0.19150E-01,SNR2: 0.32283




K20230915084032





BLK: 6,SNR1: 0.10513 ,SNR2: 0.67489




0821+394 2023/09/14 23.70UT TOYOKAWA-KISO



F20230915084036





BLK: 4,SNR1: 1.8007 ,SNR2: 4.4577




Frequency (Hz)

K20230915084032




BLK: 4,SNR1: 0.81867E-01,SNR2: 0.60996





Frequency (Hz)


0821+394 2023/09/14 23.70UT FUJI -KISO



T20230915090823




BLK: 5,SNR1: 3.2225 ,SNR2: 8.5498




Frequency (Hz)

3C208 2023/09/15 0.17UT TOYOKAWA-FUJI


F20230915090823





BLK: 5,SNR1:-0.19168E-01,SNR2: 1.5026




Frequency (Hz)



T20230915090823





BLK: 8,SNR1: 1.1511 ,SNR2: 9.3992




Frequency (Hz)

K20230915090819




BLK: 8,SNR1: 0.51443 ,SNR2: 4.5336




Frequency (Hz)


3C208 2023/09/15 0.17UT TOYOKAWA-KISO




F20230915090823




BLK: 1,SNR1:-0.65867E-01,SNR2: 1.5828




K20230915090819





BLK: 1,SNR1: 0.59167 ,SNR2: 1.4619




3C208 2023/09/15 0.17UT FUJI -KISO



T20230915092504




BLK: 5,SNR1: 0.68001E-01,SNR2: 1.1214




Frequency (Hz)

3C216 2023/09/15 0.45UT TOYOKAWA-FUJI


F20230915092504



BLK: 5,SNR1: 0.16593 ,SNR2: 3.3504





Frequency (Hz)








T20230915092504




BLK: 9,SNR1: 0.21039 ,SNR2: 1.3994




K20230915092500





BLK: 9,SNR1: 0.40959 ,SNR2: 2.0755




3C216 2023/09/15 0.45UT TOYOKAWA-KISO



F20230915092504





BLK: 7,SNR1: 0.51456 ,SNR2: 5.3257




Frequency (Hz)

3C216 2023/09/15 0.45UT FUJI -KISO


K20230915092500





BLK: 7,SNR1: 0.24824 ,SNR2: 1.5429




Frequency (Hz)



T20230915094355





BLK: 6,SNR1: 0.13174E-01,SNR2: 0.52441





0926+117 2023/09/15 0.76UT TOYOKAWA-FUJI



F20230915094354




BLK: 6,SNR1: 5.7653 ,SNR2: 17.042



T20230915094355





BLK: 3,SNR1: 0.15649 ,SNR2: 0.77036




Frequency (Hz)

0926+117 2023/09/15 0.76UT TOYOKAWA-KISO


K20230915094351





BLK: 3,SNR1: 2.3895 ,SNR2: 7.4343




Frequency (Hz)



F20230915094354





BLK: 4,SNR1: 0.55130 ,SNR2: 2.5916




Frequency (Hz)

K20230915094351




BLK: 4,SNR1: 0.26905 ,SNR2: 0.36207





Frequency (Hz)


0926+117 2023/09/15 0.76UT FUJI -KISO



T20230915095140





BLK:15,SNR1: 0.34838 ,SNR2: 4.4412




Frequency (Hz)

F20230915095139




BLK:15,SNR1: 0.66141 ,SNR2: 6.1800





Frequency (Hz)


3C222 2023/09/15 0.89UT TOYOKAWA-FUJI



T20230915095140





BLK:17,SNR1: 0.35048 ,SNR2: 3.2818




Frequency (Hz)

K20230915095136




BLK:17,SNR1: 3.0996 ,SNR2: 12.475





Frequency (Hz)


3C222 2023/09/15 0.89UT TOYOKAWA-KISO



F20230915095139




BLK:18,SNR1: 1.0462 ,SNR2: 4.3302




Frequency (Hz)

3C222 2023/09/15 0.89UT FUJI -KISO


K20230915095136



BLK:18,SNR1: 3.9985 ,SNR2: 7.9941




Frequency (Hz)






T20230915095840




BLK: 6,SNR1: 0.49719 ,SNR2: 2.5702





0941-08 2023/09/15 1.01UT TOYOKAWA-FUJI



F20230915095839




BLK: 6,SNR1: 0.48595 ,SNR2: 1.9468



T20230915095840





BLK: 7,SNR1: 0.37134 ,SNR2: 1.4493





0941-08 2023/09/15 1.01UT TOYOKAWA-KISO


K20230915095836




BLK: 7,SNR1: 0.52578 ,SNR2: 2.2111





F20230915095839




BLK: 7,SNR1: 0.48979 ,SNR2: 1.8806




K20230915095836





BLK: 7,SNR1: 0.27133 ,SNR2: 2.0878




0941-08 2023/09/15 1.01UT FUJI -KISO





T20230915100702




BLK: 6,SNR1: 0.41896 ,SNR2: 3.1498




F20230915100702





BLK: 6,SNR1: 0.43694 ,SNR2: 3.5883




3C230 2023/09/15 1.15UT TOYOKAWA-FUJI



T20230915100702





BLK:19,SNR1: 0.40891 ,SNR2: 2.5364





3C230 2023/09/15 1.15UT TOYOKAWA-KISO


K20230915100658




BLK:19,SNR1: 0.64727 ,SNR2: 1.8989



F20230915100702





BLK:10,SNR1: 0.22612 ,SNR2: 2.8342





3C230 2023/09/15 1.15UT FUJI -KISO



K20230915100658




BLK:10,SNR1: 0.21742 ,SNR2: 1.3993





T20230915102108




BLK:13,SNR1: 0.81080 ,SNR2: 6.6164




F20230915102107





BLK:13,SNR1: 2.5306 ,SNR2: 7.5842




3C236 2023/09/15 1.38UT TOYOKAWA-FUJI



T20230915102108





BLK:11,SNR1: 1.0091 ,SNR2: 6.6785




Frequency (Hz)

3C236 2023/09/15 1.38UT TOYOKAWA-KISO


K20230915102104



BLK:11,SNR1: 0.21295 ,SNR2: 0.56450





Frequency (Hz)






F20230915102107





BLK:11,SNR1: 2.3285 ,SNR2: 5.5031




Frequency (Hz)

K20230915102104




BLK:11,SNR1: 0.34416 ,SNR2: 1.0702





Frequency (Hz)


3C236 2023/09/15 1.38UT FUJI -KISO



T20230915102918




BLK: 4,SNR1: 2.6476 ,SNR2: 14.826





1011+110 2023/09/15 1.52UT TOYOKAWA-FUJI



F20230915102918




BLK: 4,SNR1: 0.10085 ,SNR2: 1.4886



T20230915102918




BLK:10,SNR1: 1.1252 ,SNR2: 6.6490





1011+110 2023/09/15 1.52UT TOYOKAWA-KISO


K20230915102914




BLK:10,SNR1: 1.0381 ,SNR2: 3.6463





F20230915102918




BLK: 5,SNR1: 0.85989 ,SNR2: 1.4667




K20230915102914





BLK: 5,SNR1: 0.14731 ,SNR2: 1.2491




1011+110 2023/09/15 1.52UT FUJI -KISO





T20230915103659




BLK:19,SNR1: 0.84624 ,SNR2: 3.8754




F20230915103659





BLK:19,SNR1: 0.67561 ,SNR2: 3.8612




3C241 2023/09/15 1.64UT TOYOKAWA-FUJI





T20230915103659




BLK:24,SNR1: 0.98940 ,SNR2: 9.1191




K20230915103655





BLK:24,SNR1: 0.25944 ,SNR2: 3.0252




3C241 2023/09/15 1.64UT TOYOKAWA-KISO



F20230915103659





BLK:13,SNR1: 1.4353 ,SNR2: 8.1558





3C241 2023/09/15 1.64UT FUJI -KISO


K20230915103655




BLK:13,SNR1: 0.18550 ,SNR2: 2.8831





T20230915104829




BLK: 8,SNR1: 0.18626 ,SNR2: 1.3746




F20230915104828



BLK: 8,SNR1:-0.97896E-01,SNR2: 1.3931




1031-11 2023/09/15 1.84UT TOYOKAWA-FUJI






T20230915104829





BLK:10,SNR1: 0.16221 ,SNR2: 3.2145





1031-11 2023/09/15 1.84UT TOYOKAWA-KISO


K20230915104825




BLK:10,SNR1: 1.0694 ,SNR2: 3.8577





F20230915104828




BLK: 5,SNR1:-0.17572 ,SNR2: 1.4762




K20230915104825




BLK: 5,SNR1: 0.13584 ,SNR2: 0.45025




1031-11 2023/09/15 1.84UT FUJI -KISO




T20230915105302




BLK:11,SNR1: 0.89199E-01,SNR2: 0.77839




F20230915105301




BLK:11,SNR1: 1.4082 ,SNR2: 7.0052




1035-058 2023/09/15 1.91UT TOYOKAWA-FUJI



T20230915105302





BLK: 8,SNR1: 0.25019 ,SNR2: 3.0192





1035-058 2023/09/15 1.91UT TOYOKAWA-KISO


K20230915105258




BLK: 8,SNR1: 0.23886 ,SNR2: 0.81319





F20230915105301




BLK: 6,SNR1: 2.2204 ,SNR2: 10.185




K20230915105258





BLK: 6,SNR1: 0.34465 ,SNR2: 0.47314




1035-058 2023/09/15 1.91UT FUJI -KISO



T20230915110215





BLK: 5,SNR1: 226.85 ,SNR2: 222.47




Frequency (Hz)

F20230915110215




BLK: 5,SNR1: 0.19155 ,SNR2: 4.4627





Frequency (Hz)


1044-008 2023/09/15 2.07UT TOYOKAWA-FUJI





T20230915110215




No.Good Data




KISO





No.Good Data




1044-008 2023/09/15 2.07UT TOYOKAWA-KISO





F20230915110215




No. Good Data




KISO



No. Good Data




1044-008 2023/09/15 2.07UT FUJI -KISO






T20230915111319




BLK:16,SNR1: 14.115 ,SNR2: 24.997





1055+01 2023/09/15 2.25UT TOYOKAWA-FUJI



F20230915111318




BLK:16,SNR1: 0.51137 ,SNR2: 4.7478



T20230915111319





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1055+01 2023/09/15 2.25UT TOYOKAWA-KISO



F20230915111318





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


1055+01 2023/09/15 2.25UT FUJI -KISO




T20230915112437




BLK:12,SNR1: 0.56318 ,SNR2: 2.3127




F20230915112436




BLK:12,SNR1: 4.5309 ,SNR2: 14.383




1107+109 2023/09/15 2.44UT TOYOKAWA-FUJI



T20230915112437




BLK:12,SNR1: 0.82871 ,SNR2: 2.6502





1107+109 2023/09/15 2.44UT TOYOKAWA-KISO



K20230915112433




BLK:12,SNR1: 0.72540 ,SNR2: 5.8996



F20230915112436





BLK: 6,SNR1: 0.58776 ,SNR2: 1.7780




Frequency (Hz)

K20230915112433




BLK: 6,SNR1: 0.27381 ,SNR2: 5.2405




Frequency (Hz)


1107+109 2023/09/15 2.44UT FUJI -KISO




T20230915113414




BLK:14,SNR1: 1.4912 ,SNR2: 8.3175




F20230915113413





BLK:14,SNR1:-0.14278 ,SNR2: 1.7970




3C255 2023/09/15 2.60UT TOYOKAWA-FUJI



T20230915113414




BLK:20,SNR1: 1.7280 ,SNR2: 4.5522




Frequency (Hz)

K20230915113410




BLK:20,SNR1: 0.26541 ,SNR2: 2.7372




Frequency (Hz)

3C255 2023/09/15 2.60UT TOYOKAWA-KISO






F20230915113413





BLK: 9,SNR1:-0.25216 ,SNR2: 1.3214




Frequency (Hz)

3C255 2023/09/15 2.60UT FUJI -KISO


K20230915113410




BLK: 9,SNR1: 0.51389 ,SNR2: 3.9582




Frequency (Hz)



T20230915115812





BLK:13,SNR1: 1.2753 ,SNR2: 5.5565




Frequency (Hz)

F20230915115811




BLK:13,SNR1: 0.32131 ,SNR2: 1.8769




Frequency (Hz)


3C263.1 2023/09/15 3.00UT TOYOKAWA-FUJI



T20230915115812





BLK:18,SNR1: 2.3336 ,SNR2: 9.6790




Frequency (Hz)

K20230915115808




BLK:18,SNR1: 0.77001 ,SNR2: 2.4154




Frequency (Hz)


3C263.1 2023/09/15 3.00UT TOYOKAWA-KISO



F20230915115811





BLK: 7,SNR1: 0.48855 ,SNR2: 1.9245





3C263.1 2023/09/15 3.00UT FUJI -KISO



K20230915115808




BLK: 7,SNR1: 0.64100E-01,SNR2: 1.5431



T20230915120439





BLK:17,SNR1: 0.83165 ,SNR2: 3.6482





3C267 2023/09/15 3.11UT TOYOKAWA-FUJI



F20230915120438




BLK:17,SNR1: 0.25353 ,SNR2: 0.90938





T20230915120439




BLK:17,SNR1: 0.80298 ,SNR2: 3.2245




K20230915120435





BLK:17,SNR1: 0.11481 ,SNR2: 1.2823




3C267 2023/09/15 3.11UT TOYOKAWA-KISO




F20230915120438




BLK: 8,SNR1: 0.29500 ,SNR2: 1.4534




K20230915120435





BLK: 8,SNR1: 0.44151 ,SNR2: 1.5521




3C267 2023/09/15 3.11UT FUJI -KISO



T20230915122354





BLK: 3,SNR1:-0.98089E-01,SNR2: 0.84390





1206+439 2023/09/15 3.43UT TOYOKAWA-FUJI

F20230915122353





BLK: 3,SNR1: 0.38265E-01,SNR2: 0.57225








T20230915122354




BLK: 2,SNR1: 0.11129 ,SNR2: 0.30224




K20230915122350





BLK: 2,SNR1: 0.45227 ,SNR2: 5.3590




1206+439 2023/09/15 3.43UT TOYOKAWA-KISO




F20230915122353




BLK: 4,SNR1:-0.38914E-01,SNR2: 0.75883




K20230915122350




BLK: 4,SNR1: 0.38686 ,SNR2: 3.3997




1206+439 2023/09/15 3.43UT FUJI -KISO




T20230915124344




BLK:25,SNR1: 18.866 ,SNR2: 89.349




F20230915124343




BLK:25,SNR1: 1.3817 ,SNR2: 5.6202




3C273 2023/09/15 3.76UT TOYOKAWA-FUJI



T20230915124344





BLK:28,SNR1: 19.972 ,SNR2: 92.378





3C273 2023/09/15 3.76UT TOYOKAWA-KISO


K20230915124340




BLK:28,SNR1: 1.7325 ,SNR2: 8.5224



F20230915124343





BLK:24,SNR1: 1.6536 ,SNR2: 6.5136





3C273 2023/09/15 3.76UT FUJI -KISO



K20230915124340




BLK:24,SNR1: 3.3329 ,SNR2: 14.726



T20230915125655





BLK: 8,SNR1: 0.87583 ,SNR2: 7.1813




Frequency (Hz)

F20230915125654




BLK: 8,SNR1:-0.26383 ,SNR2: 0.78330




Frequency (Hz)


3C275 2023/09/15 3.98UT TOYOKAWA-FUJI



T20230915125655




BLK:11,SNR1: 0.66854 ,SNR2: 5.8982





3C275 2023/09/15 3.98UT TOYOKAWA-KISO


K20230915125651




BLK:11,SNR1: 0.10626 ,SNR2: 1.0629





F20230915125654




BLK: 5,SNR1: 0.44620E-01,SNR2: 1.0652




K20230915125651



BLK: 5,SNR1: 0.31660 ,SNR2: 1.7878




3C275 2023/09/15 3.98UT FUJI -KISO







T20230915131044




BLK:13,SNR1: 1.1545 ,SNR2: 5.5929




F20230915131044




BLK:13,SNR1:-0.88157E-01,SNR2: 2.1202




3C279 2023/09/15 4.21UT TOYOKAWA-FUJI



T20230915131044





BLK:28,SNR1: 0.79370 ,SNR2: 5.4024





3C279 2023/09/15 4.21UT TOYOKAWA-KISO


K20230915131041




BLK:28,SNR1: 0.53045 ,SNR2: 4.0643





F20230915131044




BLK:11,SNR1: 0.13048E-01,SNR2: 3.0141




K20230915131041





BLK:11,SNR1: 0.37942 ,SNR2: 2.3998




3C279 2023/09/15 4.21UT FUJI -KISO





T20230915133032




BLK:12,SNR1: 0.19424 ,SNR2: 1.6987




F20230915133031





BLK:12,SNR1: 8.0486 ,SNR2: 10.080




1313+453 2023/09/15 4.54UT TOYOKAWA-FUJI





T20230915133032




BLK:11,SNR1: 0.15227 ,SNR2: 0.96739




K20230915133028





BLK:11,SNR1: 7.3308 ,SNR2: 20.416




1313+453 2023/09/15 4.54UT TOYOKAWA-KISO





F20230915133031




BLK:16,SNR1: 14.594 ,SNR2: 18.298




K20230915133028




BLK:16,SNR1: 6.7752 ,SNR2: 19.287




1313+453 2023/09/15 4.54UT FUJI -KISO





T20230915134038




BLK: 4,SNR1: 0.30128 ,SNR2: 1.8242




F20230915134038





BLK: 4,SNR1:-0.25791E-01,SNR2: 1.1610




1323+32 2023/09/15 4.71UT TOYOKAWA-FUJI





T20230915134038




BLK: 2,SNR1: 0.68028 ,SNR2: 1.9284




K20230915134034



BLK: 2,SNR1: 0.29340 ,SNR2: 0.78712




1323+32 2023/09/15 4.71UT TOYOKAWA-KISO








F20230915134038




BLK: 5,SNR1: 0.25769 ,SNR2: 4.8911




K20230915134034





BLK: 5,SNR1: 0.18064 ,SNR2: 1.3352




1323+32 2023/09/15 4.71UT FUJI -KISO




T20230915134528




BLK:31,SNR1: 1.5377 ,SNR2: 9.7237




F20230915134528





BLK:31,SNR1: 0.21320 ,SNR2: 1.7057




3C286 2023/09/15 4.79UT TOYOKAWA-FUJI




T20230915134528




BLK:27,SNR1: 1.6932 ,SNR2: 10.080




K20230915134524




BLK:27,SNR1: 0.30569 ,SNR2: 1.4624




3C286 2023/09/15 4.79UT TOYOKAWA-KISO




F20230915134528




BLK:21,SNR1: 0.24616 ,SNR2: 2.6968




K20230915134524





BLK:21,SNR1: 0.57405 ,SNR2: 3.4344




3C286 2023/09/15 4.79UT FUJI -KISO





T20230915140155




BLK:18,SNR1: 0.65229 ,SNR2: 5.0883




F20230915140154





BLK:18,SNR1: 0.57865 ,SNR2: 4.1960




1345+12 2023/09/15 5.06UT TOYOKAWA-FUJI





T20230915140155




BLK:23,SNR1: 0.68210 ,SNR2: 5.1785




K20230915140151




BLK:23,SNR1: 0.61180 ,SNR2: 2.4757




1345+12 2023/09/15 5.06UT TOYOKAWA-KISO





F20230915140154




BLK:13,SNR1: 0.24079 ,SNR2: 2.3719




K20230915140151





BLK:13,SNR1: 0.19467 ,SNR2: 1.1559




1345+12 2023/09/15 5.06UT FUJI -KISO




T20230915141216




BLK:10,SNR1: 0.16754 ,SNR2: 1.9779




F20230915141215



BLK:10,SNR1: 0.94466 ,SNR2: 10.987





1355+01 2023/09/15 5.23UT TOYOKAWA-FUJI







T20230915141216




BLK: 9,SNR1: 0.12069 ,SNR2: 1.9082




K20230915141212




BLK: 9,SNR1: 0.74015 ,SNR2: 4.7310




1355+01 2023/09/15 5.23UT TOYOKAWA-KISO



F20230915141215





BLK:11,SNR1: 0.28587 ,SNR2: 4.1087





1355+01 2023/09/15 5.23UT FUJI -KISO



K20230915141212




BLK:11,SNR1: 6.1877 ,SNR2: 26.609





T20230915143326




BLK:17,SNR1: 1.0297 ,SNR2: 8.0204




F20230915143325




BLK:17,SNR1: 0.10268 ,SNR2: 0.75834




3C298 2023/09/15 5.59UT TOYOKAWA-FUJI





T20230915143326




BLK:24,SNR1: 0.83624 ,SNR2: 4.4914




K20230915143322





BLK:24,SNR1: 0.79724 ,SNR2: 3.5170




3C298 2023/09/15 5.59UT TOYOKAWA-KISO



F20230915143325





BLK:14,SNR1: 0.37814 ,SNR2: 1.4458





3C298 2023/09/15 5.59UT FUJI -KISO



K20230915143322




BLK:14,SNR1: 3.4295 ,SNR2: 12.057




T20230915144510




BLK: 3,SNR1: 0.45912E-01,SNR2: 2.4554




F20230915144510





BLK: 3,SNR1: 1.0976 ,SNR2: 2.8650




1428-03 2023/09/15 5.78UT TOYOKAWA-FUJI





T20230915144510




BLK: 9,SNR1: 0.53889E-01,SNR2: 1.4936




K20230915144506





BLK: 9,SNR1: 0.83945 ,SNR2: 2.6694




1428-03 2023/09/15 5.78UT TOYOKAWA-KISO



F20230915144510





BLK: 1,SNR1:-0.13531 ,SNR2: 0.57072




Frequency (Hz)

K20230915144506




BLK: 1,SNR1: 0.21476 ,SNR2: 0.70221





Frequency (Hz)

1428-03 2023/09/15 5.78UT FUJI -KISO








T20230915151014




BLK: 3,SNR1: 0.18981 ,SNR2: 2.4452




F20230915151014





BLK: 3,SNR1: 0.49759 ,SNR2: 2.2012




1453-10 2023/09/15 6.20UT TOYOKAWA-FUJI





T20230915151014




BLK: 1,SNR1: 0.20745 ,SNR2: 2.1268




K20230915151010





BLK: 1,SNR1: 7.0902 ,SNR2: 20.094




1453-10 2023/09/15 6.20UT TOYOKAWA-KISO



F20230915151014





BLK: 4,SNR1: 1.0917 ,SNR2: 4.2329




Frequency (Hz)

K20230915151010




BLK: 4,SNR1: 2.3106 ,SNR2: 9.9045




Frequency (Hz)


1453-10 2023/09/15 6.20UT FUJI -KISO





T20230915152506




BLK:10,SNR1: 0.33085E-01,SNR2: 0.44669




F20230915152505





BLK:10,SNR1: 9.0867 ,SNR2: 8.5614




1508-05 2023/09/15 6.45UT TOYOKAWA-FUJI





T20230915152506




BLK: 4,SNR1: 1.1641 ,SNR2: 2.0024




K20230915152502




BLK: 4,SNR1:-0.60734E-01,SNR2: 0.29687




1508-05 2023/09/15 6.45UT TOYOKAWA-KISO





F20230915152505




BLK: 5,SNR1: 0.24077E-01,SNR2: 1.4504




K20230915152502





BLK: 5,SNR1: 1.8766 ,SNR2: 8.5132




1508-05 2023/09/15 6.45UT FUJI -KISO





T20230915153407




BLK:15,SNR1: 30.512 ,SNR2: 39.210




F20230915153406




BLK:15,SNR1: 3.1951 ,SNR2: 4.6165




3C318 2023/09/15 6.60UT TOYOKAWA-FUJI





T20230915153407




BLK: 7,SNR1: 3.4897 ,SNR2: 10.034




K20230915153403



BLK: 7,SNR1: 0.33363 ,SNR2: 3.3161





3C318 2023/09/15 6.60UT TOYOKAWA-KISO






F20230915153406





BLK: 5,SNR1: 8.1932 ,SNR2: 12.229





3C318 2023/09/15 6.60UT FUJI -KISO



K20230915153403




BLK: 5,SNR1: 0.38210 ,SNR2: 2.1908





T20230915153954




BLK:10,SNR1:-0.14410 ,SNR2: 0.31894




F20230915153954





BLK:10,SNR1: 1.6405 ,SNR2: 2.8933




1523+03 2023/09/15 6.69UT TOYOKAWA-FUJI





T20230915153954




BLK: 3,SNR1:-0.24735 ,SNR2: 0.22334




K20230915153950





BLK: 3,SNR1: 0.86225E-01,SNR2: 0.44573




1523+03 2023/09/15 6.69UT TOYOKAWA-KISO





F20230915153954




BLK:10,SNR1: 0.80532 ,SNR2: 1.1853




K20230915153950





BLK:10,SNR1: 0.59906 ,SNR2: 3.8280




1523+03 2023/09/15 6.69UT FUJI -KISO




T20230915155133




BLK:19,SNR1: 0.90953E-01,SNR2: 0.65441




F20230915155132





BLK:19,SNR1: 4.6555 ,SNR2: 4.4915




1535+139 2023/09/15 6.89UT TOYOKAWA-FUJI





T20230915155133




BLK: 8,SNR1: 0.52437E-01,SNR2: 0.64058




K20230915155129




BLK: 8,SNR1: 0.82383E-01,SNR2: 0.35941




1535+139 2023/09/15 6.89UT TOYOKAWA-KISO





F20230915155132




BLK:12,SNR1: 6.0707 ,SNR2: 5.8802




K20230915155129




BLK:12,SNR1: 0.99206E-01,SNR2: 0.46922




1535+139 2023/09/15 6.89UT FUJI -KISO




T20230915160157




BLK:17,SNR1: 0.22667 ,SNR2: 1.1211




F20230915160157



BLK:17,SNR1: 0.36132E-01,SNR2: 0.58416





1545-12 2023/09/15 7.06UT TOYOKAWA-FUJI








T20230915160157




BLK: 9,SNR1: 0.44911 ,SNR2: 2.0984




K20230915160153




BLK: 9,SNR1: 0.19619 ,SNR2: 0.84091




1545-12 2023/09/15 7.06UT TOYOKAWA-KISO





F20230915160157




BLK: 9,SNR1: 0.10412 ,SNR2: 0.61113




K20230915160153





BLK: 9,SNR1: 0.31530 ,SNR2: 1.9612




1545-12 2023/09/15 7.06UT FUJI -KISO




T20230915162301




BLK:17,SNR1: 0.12613 ,SNR2: 0.85491




F20230915162301





BLK:17,SNR1: 0.50435 ,SNR2: 2.1193




1607+26 2023/09/15 7.41UT TOYOKAWA-FUJI





T20230915162301




BLK: 4,SNR1: 0.12423 ,SNR2: 0.95792




K20230915162257





BLK: 4,SNR1: 0.11750 ,SNR2: 0.78923




1607+26 2023/09/15 7.41UT TOYOKAWA-KISO



F20230915162301





BLK:10,SNR1: 0.83807 ,SNR2: 2.8046





1607+26 2023/09/15 7.41UT FUJI -KISO



K20230915162257




BLK:10,SNR1: 0.34209 ,SNR2: 1.2366





T20230915165438




BLK: 7,SNR1: 2.4689 ,SNR2: 4.2277




F20230915165438





BLK: 7,SNR1: 2.4940 ,SNR2: 2.9456




1638-025 2023/09/15 7.94UT TOYOKAWA-FUJI





T20230915165438




BLK: 9,SNR1: 2.7788 ,SNR2: 5.3110




K20230915165434





BLK: 9,SNR1: 0.50430 ,SNR2: 2.5821




1638-025 2023/09/15 7.94UT TOYOKAWA-KISO





F20230915165438




BLK: 4,SNR1:-0.52403E-01,SNR2: 0.96555




K20230915165434



BLK: 4,SNR1: 0.10651 ,SNR2: 1.1800





1638-025 2023/09/15 7.94UT FUJI -KISO








T20230915170132




BLK: 8,SNR1: 0.83950E-01,SNR2: 0.61868




F20230915170132





BLK: 8,SNR1: 0.47374 ,SNR2: 3.1608




1644-106 2023/09/15 8.05UT TOYOKAWA-FUJI




T20230915170132




BLK: 6,SNR1: 0.96757E-02,SNR2: 0.34447




K20230915170128





BLK: 6,SNR1: 1.6632 ,SNR2: 5.1250




1644-106 2023/09/15 8.05UT TOYOKAWA-KISO



F20230915170132





BLK: 3,SNR1: 0.89995 ,SNR2: 3.3883




Frequency (Hz)

K20230915170128



BLK: 3,SNR1: 0.23558 ,SNR2: 6.5191



Frequency (Hz)

1644-106 2023/09/15 8.05UT FUJI -KISO

