



T20230919105729





BLK: 3,SNR1: 0.28210 ,SNR2: 2.4794




Frequency (Hz)

F20230919105729




BLK: 3,SNR1: 0.65218 ,SNR2: 3.3219




Frequency (Hz)


1055+20 2023/09/19 1.99UT TOYOKAWA-FUJI



T20230919105729





BLK:11,SNR1: 0.32326E-01,SNR2: 1.4239




Frequency (Hz)

K20230919105726




BLK:11,SNR1: 22.260 ,SNR2: 30.158




Frequency (Hz)


1055+20 2023/09/19 1.99UT TOYOKAWA-KISO



F20230919105729




BLK: 4,SNR1: 0.25808 ,SNR2: 2.6112




Frequency (Hz)

K20230919105726




BLK: 4,SNR1: 19.143 ,SNR2: 40.204





Frequency (Hz)


1055+20 2023/09/19 1.99UT FUJI -KISO



T20230919110852





BLK:12,SNR1: 2.0519 ,SNR2: 8.9877




Frequency (Hz)

F20230919110852




BLK:12,SNR1: 0.38755E-01,SNR2: 1.1477





Frequency (Hz)

1107+109 2023/09/19 2.18UT TOYOKAWA-FUJI






T20230919110852





BLK:15,SNR1: 1.0642 ,SNR2: 2.6835




Frequency (Hz)

K20230919110849




BLK:15,SNR1: 3.6235 ,SNR2: 14.155





Frequency (Hz)


1107+109 2023/09/19 2.18UT TOYOKAWA-KISO



F20230919110852





BLK: 3,SNR1: 0.23724 ,SNR2: 0.65787




Frequency (Hz)

K20230919110849




BLK: 3,SNR1: 0.31502 ,SNR2: 1.1540





Frequency (Hz)


1107+109 2023/09/19 2.18UT FUJI -KISO



T20230919111830





BLK:15,SNR1: 2.9724 ,SNR2: 8.0588




Frequency (Hz)

3C255 2023/09/19 2.34UT TOYOKAWA-FUJI


F20230919111831





BLK:15,SNR1:-0.12127 ,SNR2: 1.5269




Frequency (Hz)



T20230919111830





BLK:26,SNR1: 3.3545 ,SNR2: 8.9385




Frequency (Hz)

K20230919111827




BLK:26,SNR1: 0.57832 ,SNR2: 2.2913





Frequency (Hz)


3C255 2023/09/19 2.34UT TOYOKAWA-KISO



F20230919111831





BLK:11,SNR1: 0.76686 ,SNR2: 2.0743




Frequency (Hz)

3C255 2023/09/19 2.34UT FUJI -KISO


K20230919111827





BLK:11,SNR1: 0.39848 ,SNR2: 2.6166




Frequency (Hz)



T20230919114228





BLK:30,SNR1: 4.6502 ,SNR2: 13.039




Frequency (Hz)

F20230919114228




BLK:30,SNR1: 7.9148 ,SNR2: 20.861





Frequency (Hz)


3C263.1 2023/09/19 2.74UT TOYOKAWA-FUJI



T20230919114228





BLK:33,SNR1: 4.6397 ,SNR2: 12.827




Frequency (Hz)

K20230919114226




BLK:33,SNR1: 8.6314 ,SNR2: 16.390





Frequency (Hz)


3C263.1 2023/09/19 2.74UT TOYOKAWA-KISO



F20230919114228




BLK:37,SNR1: 8.3067 ,SNR2: 12.009




Frequency (Hz)

K20230919114226




BLK:37,SNR1: 8.4439 ,SNR2: 12.626





Frequency (Hz)

3C263.1 2023/09/19 2.74UT FUJI -KISO






T20230919114855





BLK:19,SNR1: 1.1793 ,SNR2: 5.1279




Frequency (Hz)

3C267 2023/09/19 2.84UT TOYOKAWA-FUJI


F20230919114855





BLK:19,SNR1: 0.28457 ,SNR2: 0.73225




Frequency (Hz)



T20230919114855





BLK:15,SNR1: 1.5016 ,SNR2: 6.7977




Frequency (Hz)

K20230919114852




BLK:15,SNR1: 0.37574 ,SNR2: 2.1640





Frequency (Hz)


3C267 2023/09/19 2.84UT TOYOKAWA-KISO



F20230919114855





BLK: 5,SNR1: 0.20665 ,SNR2: 4.7970




Frequency (Hz)

K20230919114852




BLK: 5,SNR1: 0.62705 ,SNR2: 5.9636





Frequency (Hz)


3C267 2023/09/19 2.84UT FUJI -KISO



T20230919120809





BLK: 4,SNR1: 0.10916 ,SNR2: 1.0694




Frequency (Hz)

F20230919120809




BLK: 4,SNR1: 0.11835 ,SNR2: 2.7684





Frequency (Hz)


1206+439 2023/09/19 3.16UT TOYOKAWA-FUJI



T20230919120809





BLK: 9,SNR1: 0.15232 ,SNR2: 0.66870




Frequency (Hz)

K20230919120806




BLK: 9,SNR1: 0.99638E-01,SNR2: 1.4632




Frequency (Hz)


1206+439 2023/09/19 3.16UT TOYOKAWA-KISO



F20230919120809





BLK: 1,SNR1: 0.64663 ,SNR2: 2.4166




Frequency (Hz)

K20230919120806




BLK: 1,SNR1: 0.65800E-02,SNR2: 0.49613





Frequency (Hz)


1206+439 2023/09/19 3.16UT FUJI -KISO



T20230919122800





BLK:30,SNR1: 28.601 ,SNR2: 54.750




Frequency (Hz)

3C273 2023/09/19 3.49UT TOYOKAWA-FUJI


F20230919122800




BLK:30,SNR1: 0.82343 ,SNR2: 5.0633




Frequency (Hz)



T20230919122800





BLK:22,SNR1: 23.738 ,SNR2: 45.487




Frequency (Hz)

3C273 2023/09/19 3.49UT TOYOKAWA-KISO


K20230919122757



BLK:22,SNR1: 16.445 ,SNR2: 30.673





Frequency (Hz)






F20230919122800





BLK:23,SNR1: 0.92851 ,SNR2: 3.5925




Frequency (Hz)

3C273 2023/09/19 3.49UT FUJI -KISO


K20230919122757





BLK:23,SNR1: 52.746 ,SNR2: 72.380




Frequency (Hz)



T20230919124110





BLK: 7,SNR1: 188.34 ,SNR2: 183.82




Frequency (Hz)

3C275 2023/09/19 3.71UT TOYOKAWA-FUJI


F20230919124110





BLK: 7,SNR1: 11.241 ,SNR2: 26.908




Frequency (Hz)



T20230919124110





BLK:12,SNR1: 521.58 ,SNR2: 509.06




Frequency (Hz)

3C275 2023/09/19 3.71UT TOYOKAWA-KISO


K20230919124107




BLK:12,SNR1: 51.324 ,SNR2: 64.332




Frequency (Hz)



F20230919124110




BLK: 9,SNR1: 6.4272 ,SNR2: 25.557




Frequency (Hz)

3C275 2023/09/19 3.71UT FUJI -KISO


K20230919124107




BLK: 9,SNR1: 20.267 ,SNR2: 55.657




Frequency (Hz)



T20230919125459




BLK: 8,SNR1: 0.97238 ,SNR2: 9.1289




Frequency (Hz)

3C279 2023/09/19 3.94UT TOYOKAWA-FUJI


F20230919125459




BLK: 8,SNR1: 0.48162E-01,SNR2: 1.0315




Frequency (Hz)



T20230919125459




BLK:20,SNR1: 0.87918 ,SNR2: 7.4763




Frequency (Hz)

3C279 2023/09/19 3.94UT TOYOKAWA-KISO


K20230919125456




BLK:20,SNR1: 0.36588 ,SNR2: 4.3279




Frequency (Hz)



F20230919125459




BLK: 8,SNR1: 0.10187 ,SNR2: 1.0885




Frequency (Hz)

3C279 2023/09/19 3.94UT FUJI -KISO


K20230919125456




BLK: 8,SNR1: 0.23858 ,SNR2: 1.2342




Frequency (Hz)



T20230919131447




BLK: 8,SNR1: 0.93112 ,SNR2: 3.1235




Frequency (Hz)

F20230919131447




BLK: 8,SNR1:-0.16965 ,SNR2: 1.0795




Frequency (Hz)

1313+453 2023/09/19 4.27UT TOYOKAWA-FUJI







T20230919131447




BLK: 5,SNR1: 0.70595 ,SNR2: 2.7063




K20230919131444




BLK: 5,SNR1: 0.47035 ,SNR2: 1.5861




1313+453 2023/09/19 4.27UT TOYOKAWA-KISO




F20230919131447




BLK: 4,SNR1: 0.75840 ,SNR2: 1.9027




K20230919131444





BLK: 4,SNR1: 0.17382 ,SNR2: 2.3988




1313+453 2023/09/19 4.27UT FUJI -KISO



T20230919132453





BLK:21,SNR1: 0.65429 ,SNR2: 4.6923




Frequency (Hz)

F20230919132453




BLK:21,SNR1:-0.26276E-02,SNR2: 1.7691




Frequency (Hz)


1323+32 2023/09/19 4.44UT TOYOKAWA-FUJI



T20230919132453





BLK:22,SNR1: 0.65600 ,SNR2: 3.8418





1323+32 2023/09/19 4.44UT TOYOKAWA-KISO


K20230919132450




BLK:22,SNR1: 0.23168 ,SNR2: 3.0288



F20230919132453





BLK: 9,SNR1:-0.24711E-01,SNR2: 1.7278




Frequency (Hz)

K20230919132450




BLK: 9,SNR1: 0.48221 ,SNR2: 1.7922





Frequency (Hz)


1323+32 2023/09/19 4.44UT FUJI -KISO



T20230919132944





BLK:36,SNR1: 8.2919 ,SNR2: 34.471




Frequency (Hz)

F20230919132944




BLK:36,SNR1: 0.55007 ,SNR2: 1.7788





Frequency (Hz)


3C286 2023/09/19 4.52UT TOYOKAWA-FUJI



T20230919132944





BLK:29,SNR1: 8.2955 ,SNR2: 39.343




Frequency (Hz)

3C286 2023/09/19 4.52UT TOYOKAWA-KISO


K20230919132941




BLK:29,SNR1: 0.80315 ,SNR2: 3.9646




Frequency (Hz)





F20230919132944




BLK:19,SNR1: 0.61479 ,SNR2: 1.9454




K20230919132941



BLK:19,SNR1: 0.94847 ,SNR2: 4.6256





3C286 2023/09/19 4.52UT FUJI -KISO






T20230919134611





BLK:19,SNR1: 1.2071 ,SNR2: 5.5723




Frequency (Hz)

F20230919134611




BLK:19,SNR1: 0.11539 ,SNR2: 1.1608





Frequency (Hz)


1345+12 2023/09/19 4.80UT TOYOKAWA-FUJI



T20230919134611





BLK:18,SNR1: 1.1505 ,SNR2: 4.9294




Frequency (Hz)

K20230919134608




BLK:18,SNR1: 0.14777 ,SNR2: 0.86568





Frequency (Hz)


1345+12 2023/09/19 4.80UT TOYOKAWA-KISO



F20230919134611




BLK: 9,SNR1: 0.20197 ,SNR2: 1.8402




Frequency (Hz)

K20230919134608




BLK: 9,SNR1: 0.89723 ,SNR2: 4.1188





Frequency (Hz)


1345+12 2023/09/19 4.80UT FUJI -KISO



T20230919135631





BLK: 7,SNR1: 3.9242 ,SNR2: 14.410




Frequency (Hz)

1355+01 2023/09/19 4.97UT TOYOKAWA-FUJI


F20230919135632





BLK: 7,SNR1: 0.52584E-01,SNR2: 4.7062




Frequency (Hz)



T20230919135631





BLK: 8,SNR1: 2.0093 ,SNR2: 7.5196




Frequency (Hz)

K20230919135628




BLK: 8,SNR1: 1.6695 ,SNR2: 10.218





Frequency (Hz)


1355+01 2023/09/19 4.97UT TOYOKAWA-KISO





F20230919135632




BLK: 6,SNR1: 1.2046 ,SNR2: 3.4843




K20230919135628




BLK: 6,SNR1: 1.1947 ,SNR2: 5.8435




1355+01 2023/09/19 4.97UT FUJI -KISO



T20230919141742





BLK:16,SNR1: 2.8578 ,SNR2: 10.812




Frequency (Hz)

3C298 2023/09/19 5.32UT TOYOKAWA-FUJI


F20230919141742




BLK:16,SNR1: 0.26841 ,SNR2: 0.88675



Frequency (Hz)




T20230919141742



Time (sec)




BLK:16,SNR1: 2.6668 ,SNR2: 10.613




Frequency (Hz)


K20230919141739



Time (sec)




BLK:16,SNR1: 0.14936 ,SNR2: 1.3477




Frequency (Hz)

3C298 2023/09/19 5.32UT TOYOKAWA-KISO








F20230919141742




BLK: 6,SNR1: 0.71536E-01,SNR2: 1.3836




K20230919141739





BLK: 6,SNR1: 0.62672 ,SNR2: 1.9230




3C298 2023/09/19 5.32UT FUJI -KISO





T20230919142925




BLK: 5,SNR1: 0.30130E-01,SNR2: 1.5982




F20230919142925




BLK: 5,SNR1: 10.396 ,SNR2: 20.275




1428-03 2023/09/19 5.52UT TOYOKAWA-FUJI



T20230919142925




BLK: 7,SNR1: 4.1494 ,SNR2: 18.298





1428-03 2023/09/19 5.52UT TOYOKAWA-KISO


K20230919142922




BLK: 7,SNR1: 0.91250 ,SNR2: 6.4654




F20230919142925




BLK: 5,SNR1: 3.4643 ,SNR2: 9.7075




K20230919142922




BLK: 5,SNR1: 0.59904E-01,SNR2: 1.6584




1428-03 2023/09/19 5.52UT FUJI -KISO




T20230919145429




BLK: 6,SNR1: 0.94543E-01,SNR2: 2.1357




F20230919145430





BLK: 6,SNR1: 0.30507 ,SNR2: 0.96528




1453-10 2023/09/19 5.94UT TOYOKAWA-FUJI



T20230919145429





BLK: 7,SNR1: 0.39062E-01,SNR2: 1.5214




Frequency (Hz)

K20230919145426




BLK: 7,SNR1: 0.47902 ,SNR2: 3.9231




Frequency (Hz)


1453-10 2023/09/19 5.94UT TOYOKAWA-KISO




F20230919145430




BLK: 4,SNR1:-0.19584 ,SNR2: 0.63077




K20230919145426





BLK: 4,SNR1: 0.75450 ,SNR2: 4.6915




1453-10 2023/09/19 5.94UT FUJI -KISO



T20230919150922





BLK: 4,SNR1:-0.64045E-01,SNR2: 1.1097




Frequency (Hz)

1508-05 2023/09/19 6.18UT TOYOKAWA-FUJI


F20230919150922



BLK: 4,SNR1: 0.29440 ,SNR2: 1.3532





Frequency (Hz)






T20230919150922





BLK: 3,SNR1: 0.34722E-01,SNR2: 1.2487





1508-05 2023/09/19 6.18UT TOYOKAWA-KISO



K20230919150919




BLK: 3,SNR1: 1.1797 ,SNR2: 5.6128



F20230919150922





BLK: 1,SNR1:-0.30331 ,SNR2: 0.70856




Frequency (Hz)

K20230919150919




BLK: 1,SNR1: 8.0867 ,SNR2: 13.472





Frequency (Hz)


1508-05 2023/09/19 6.18UT FUJI -KISO




T20230919151822




BLK: 6,SNR1: 0.10370 ,SNR2: 1.5398




F20230919151822




BLK: 6,SNR1:-0.36164E-01,SNR2: 1.5029




3C318 2023/09/19 6.33UT TOYOKAWA-FUJI



T20230919151822




BLK: 2,SNR1: 0.28593 ,SNR2: 1.7490





3C318 2023/09/19 6.33UT TOYOKAWA-KISO


K20230919151820




BLK: 2,SNR1: 0.25735 ,SNR2: 1.0350





F20230919151822




BLK: 4,SNR1:-0.78879E-01,SNR2: 1.8976




K20230919151820





BLK: 4,SNR1: 0.11001 ,SNR2: 1.7972




3C318 2023/09/19 6.33UT FUJI -KISO



T20230919152409




BLK: 6,SNR1: 3.4600 ,SNR2: 12.960





1523+03 2023/09/19 6.43UT TOYOKAWA-FUJI



F20230919152410




BLK: 6,SNR1: 0.80492E-01,SNR2: 2.0298



T20230919152409




BLK: 5,SNR1: 1.4586 ,SNR2: 5.6863




Frequency (Hz)

1523+03 2023/09/19 6.43UT TOYOKAWA-KISO


K20230919152407




BLK: 5,SNR1: 0.12576 ,SNR2: 1.1673




Frequency (Hz)





F20230919152410




BLK: 2,SNR1:-0.46715E-01,SNR2: 1.6524




K20230919152407



BLK: 2,SNR1: 0.15418 ,SNR2: 0.48584




1523+03 2023/09/19 6.43UT FUJI -KISO







T20230919153549




BLK:11,SNR1: 2.1484 ,SNR2: 8.5153




F20230919153549




BLK:11,SNR1: 0.80556 ,SNR2: 2.0713




1535+139 2023/09/19 6.63UT TOYOKAWA-FUJI



T20230919153549





BLK: 2,SNR1:-0.78698E-01,SNR2: 0.60140





1535+139 2023/09/19 6.63UT TOYOKAWA-KISO


K20230919153546




BLK: 2,SNR1: 0.23422 ,SNR2: 5.6707





F20230919153549




BLK: 3,SNR1:-0.11880 ,SNR2: 0.51786




K20230919153546




BLK: 3,SNR1: 0.94667E-01,SNR2: 2.1842




1535+139 2023/09/19 6.63UT FUJI -KISO



T20230919154612





BLK:25,SNR1: 2.8993 ,SNR2: 5.4834




Frequency (Hz)

F20230919154613




BLK:25,SNR1: 10.189 ,SNR2: 18.417




Frequency (Hz)


1545-12 2023/09/19 6.80UT TOYOKAWA-FUJI



T20230919154612




BLK:13,SNR1: 4.9843 ,SNR2: 9.4664





1545-12 2023/09/19 6.80UT TOYOKAWA-KISO



K20230919154609




BLK:13,SNR1: 41.896 ,SNR2: 78.047





F20230919154613




BLK: 9,SNR1: 1.1766 ,SNR2: 3.8164




K20230919154609




BLK: 9,SNR1: 14.074 ,SNR2: 26.366




1545-12 2023/09/19 6.80UT FUJI -KISO



T20230919160716





BLK:14,SNR1: 3.2536 ,SNR2: 12.620





1607+26 2023/09/19 7.15UT TOYOKAWA-FUJI


F20230919160717




BLK:14,SNR1: 0.50816E-01,SNR2: 1.3517



T20230919160716





BLK: 8,SNR1: 3.3496 ,SNR2: 12.985





1607+26 2023/09/19 7.15UT TOYOKAWA-KISO

K20230919160713




BLK: 8,SNR1: 3.2980 ,SNR2: 12.512








F20230919160717




BLK: 4,SNR1: 0.17375 ,SNR2: 1.9044




K20230919160713




BLK: 4,SNR1: 3.6615 ,SNR2: 13.892




1607+26 2023/09/19 7.15UT FUJI -KISO




T20230919163853




BLK:10,SNR1: 0.12082 ,SNR2: 1.5341




F20230919163854




BLK:10,SNR1: 0.70594 ,SNR2: 1.5176




1638-025 2023/09/19 7.68UT TOYOKAWA-FUJI





T20230919163853




BLK: 3, SNR1: 0.42800 , SNR2: 4.0233




K20230919163850




BLK: 3, SNR1: 1.8513 , SNR2: 9.9323




1638-025 2023/09/19 7.68UT TOYOKAWA-KISO



F20230919163854




BLK: 4,SNR1: 2.7040 ,SNR2: 3.4789





1638-025 2023/09/19 7.68UT FUJI -KISO


K20230919163850




BLK: 4,SNR1: 0.41738 ,SNR2: 2.6273



T20230919164548





BLK:25,SNR1: 6.6669 ,SNR2: 15.359





1644-106 2023/09/19 7.79UT TOYOKAWA-FUJI


F20230919164548




BLK:25,SNR1: 15.348 ,SNR2: 24.795



T20230919164548




BLK:12,SNR1: 8.0028 ,SNR2: 18.605





1644-106 2023/09/19 7.79UT TOYOKAWA-KISO


K20230919164545




BLK:12,SNR1: 1.3135 ,SNR2: 4.3220



F20230919164548





BLK:13,SNR1: 3.2715 ,SNR2: 13.003





1644-106 2023/09/19 7.79UT FUJI -KISO


K20230919164545




BLK:13,SNR1: 0.80806 ,SNR2: 2.8827



T20230919165108




BLK: 9,SNR1: 3.4393 ,SNR2: 13.265





1650+004 2023/09/19 7.88UT TOYOKAWA-FUJI

F20230919165108




BLK: 9,SNR1: 2.2095 ,SNR2: 5.4098






T20230919165108




BLK: 7,SNR1: 9.5665 ,SNR2: 15.771





1650+004 2023/09/19 7.88UT TOYOKAWA-KISO



K20230919165105




BLK: 7,SNR1: 0.13717 ,SNR2: 0.47567



F20230919165108





BLK: 5,SNR1: 2.1491 ,SNR2: 6.9370




Frequency (Hz)

1650+004 2023/09/19 7.88UT FUJI -KISO


K20230919165105





BLK: 5,SNR1: 0.34280 ,SNR2: 1.9296




Frequency (Hz)



T20230919165640




BLK:30,SNR1: 11.994 ,SNR2: 19.401





1656+053 2023/09/19 7.97UT TOYOKAWA-FUJI



F20230919165640




BLK:30,SNR1: 9.5519 ,SNR2: 20.934



T20230919165640





BLK:22,SNR1: 11.997 ,SNR2: 19.406





1656+053 2023/09/19 7.97UT TOYOKAWA-KISO


K20230919165637




BLK:22,SNR1: 1.4971 ,SNR2: 3.0763



F20230919165640




BLK:23,SNR1: 9.6161 ,SNR2: 21.072



1656+053 2023/09/19 7.97UT FUJI -KISO

K20230919165637



BLK:23,SNR1: 1.4966 ,SNR2: 2.8756

