



T20230920062303





BLK: 4,SNR1: 0.68593E-01,SNR2: 1.9043




Frequency (Hz)

3C161 2023/09/19 21.41UT TOYOKAWA-FUJI


F20230920062304





BLK: 4,SNR1: 0.74145E-01,SNR2: 6.3828




Frequency (Hz)



T20230920062303




No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C161 2023/09/19 21.41UT TOYOKAWA-KISO




F20230920062304




No.Good Data




KISO





No.Good Data




3C161 2023/09/19 21.41UT FUJI -KISO



T20230920065036




BLK: 1,SNR1:-0.52012E-01,SNR2: 1.8085




Frequency (Hz)

F20230920065036




BLK: 1,SNR1: 0.20633 ,SNR2: 1.3321





Frequency (Hz)

0652-130 2023/09/19 21.87UT TOYOKAWA-FUJI






T20230920065036





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0652-130 2023/09/19 21.87UT TOYOKAWA-KISO





F20230920065036




No.Good Data




KISO




No.Good Data




0652-130 2023/09/19 21.87UT FUJI -KISO



T20230920070211





BLK: 3,SNR1:-0.17684 ,SNR2: 0.12253




Frequency (Hz)

F20230920070211




BLK: 3,SNR1: 0.99601E-01,SNR2: 0.53476





Frequency (Hz)


0703+138 2023/09/19 22.06UT TOYOKAWA-FUJI





T20230920070211




No.Good Data




KISO



No.Good Data




0703+138 2023/09/19 22.06UT TOYOKAWA-KISO



F20230920070211




No.Good Data



KISO





No.Good Data




0703+138 2023/09/19 22.06UT FUJI -KISO



T20230920071135





BLK: 3,SNR1: 0.25628E-01,SNR2: 0.83281




Frequency (Hz)

F20230920071136




BLK: 3,SNR1:-0.78516E-01,SNR2: 0.43818




Frequency (Hz)


0713-024 2023/09/19 22.22UT TOYOKAWA-FUJI



T20230920071135





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0713-024 2023/09/19 22.22UT TOYOKAWA-KISO



F20230920071136




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0713-024 2023/09/19 22.22UT FUJI -KISO






T20230920072146




BLK: 3,SNR1:-0.10608 ,SNR2: 0.17341




Frequency (Hz)

F20230920072146




BLK: 3,SNR1: 0.41616 ,SNR2: 1.9664




Frequency (Hz)


0723+10 2023/09/19 22.39UT TOYOKAWA-FUJI



T20230920072146





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0723+10 2023/09/19 22.39UT TOYOKAWA-KISO




F20230920072146



No.Good Data




KISO





No.Good Data




0723+10 2023/09/19 22.39UT FUJI -KISO



T20230920073200




BLK: 8,SNR1: 0.49225 ,SNR2: 5.8630




Frequency (Hz)

F20230920073200




BLK: 8,SNR1: 0.59426 ,SNR2: 1.3860





Frequency (Hz)


0732+33 2023/09/19 22.56UT TOYOKAWA-FUJI





T20230920073200




No.Good Data




KISO




No.Good Data



0732+33 2023/09/19 22.56UT TOYOKAWA-KISO





F20230920073200




No.Good Data




KISO




No.Good Data




0732+33 2023/09/19 22.56UT FUJI -KISO



T20230920074003




BLK: 8,SNR1: 0.31138 ,SNR2: 2.5047




Frequency (Hz)

0741-06 2023/09/19 22.70UT TOYOKAWA-FUJI


F20230920074003





BLK: 8,SNR1: 0.34550 ,SNR2: 1.7785




Frequency (Hz)





T20230920074003




No.Good Data




KISO



No.Good Data




0741-06 2023/09/19 22.70UT TOYOKAWA-KISO







F20230920074003




No.Good Data



KISO




No.Good Data




0741-06 2023/09/19 22.70UT FUJI -KISO



T20230920075722




BLK: 4,SNR1: 0.10241E-01,SNR2: 1.6081




Frequency (Hz)

3C190 2023/09/19 22.98UT TOYOKAWA-FUJI


F20230920075723





BLK: 4,SNR1: 0.17467 ,SNR2: 0.84910




Frequency (Hz)



T20230920075722





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C190 2023/09/19 22.98UT TOYOKAWA-KISO





F20230920075723




No.Good Data




KISO





No.Good Data




3C190 2023/09/19 22.98UT FUJI -KISO



T20230920080945




BLK: 7,SNR1: 0.12804 ,SNR2: 1.4909




Frequency (Hz)

F20230920080945




BLK: 7,SNR1: 0.31305 ,SNR2: 1.8303





Frequency (Hz)


3C196 2023/09/19 23.19UT TOYOKAWA-FUJI





T20230920080945




No.Good Data




KISO




No.Good Data




3C196 2023/09/19 23.19UT TOYOKAWA-KISO





F20230920080945




No.Good Data




KISO





No.Good Data




3C196 2023/09/19 23.19UT FUJI -KISO



T20230920082055





BLK: 4,SNR1: 0.28688 ,SNR2: 2.7511




Frequency (Hz)

F20230920082055




BLK: 4,SNR1: 0.67271 ,SNR2: 4.0444




Frequency (Hz)

0821+394 2023/09/19 23.38UT TOYOKAWA-FUJI






T20230920082055





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0821+394 2023/09/19 23.38UT TOYOKAWA-KISO



F20230920082055





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0821+394 2023/09/19 23.38UT FUJI -KISO



T20230920083742





BLK: 5,SNR1: 7.3066 ,SNR2: 53.063




Frequency (Hz)

0839-071 2023/09/19 23.66UT TOYOKAWA-FUJI


F20230920083742





BLK: 5,SNR1: 0.79215 ,SNR2: 1.7690




Frequency (Hz)



T20230920083742





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0839-071 2023/09/19 23.66UT TOYOKAWA-KISO





F20230920083742




No.Good Data




KISO





No.Good Data




0839-071 2023/09/19 23.66UT FUJI -KISO



T20230920084842





BLK: 6,SNR1: 0.16499 ,SNR2: 1.7875




Frequency (Hz)

3C208 2023/09/19 23.84UT TOYOKAWA-FUJI


F20230920084843





BLK: 6,SNR1:-0.21918E-01,SNR2: 2.0526




Frequency (Hz)





T20230920084842




No.Good Data




KISO





No.Good Data




3C208 2023/09/19 23.84UT TOYOKAWA-KISO





F20230920084843




No.Good Data




KISO



No.Good Data




3C208 2023/09/19 23.84UT FUJI -KISO







T20230920085420




No. Good Data




F20230920085420





No. Good Data




0855+143 2023/09/19 23.93UT TOYOKAWA-FUJI





T20230920085420




No.Good Data




KISO



No.Good Data




0855+143 2023/09/19 23.93UT TOYOKAWA-KISO





F20230920085420




No.Good Data




KISO





No.Good Data




0855+143 2023/09/19 23.93UT FUJI -KISO



T20230920090523




BLK: 1,SNR1: 0.30793 ,SNR2: 2.9012




Frequency (Hz)

3C216 2023/09/20 0.12UT TOYOKAWA-FUJI


F20230920090523





BLK: 1,SNR1: 0.41127 ,SNR2: 5.4658




Frequency (Hz)





T20230920090523




No.Good Data




KISO



No.Good Data



3C216 2023/09/20 0.12UT TOYOKAWA-KISO





F20230920090523




No. Good Data



KISO





No. Good Data




3C216 2023/09/20 0.12UT FUJI -KISO



T20230920092414





BLK: 6,SNR1: 2.2107 ,SNR2: 13.095




Frequency (Hz)

F20230920092414




BLK: 6,SNR1: 0.32507 ,SNR2: 1.4168




Frequency (Hz)


0926+117 2023/09/20 0.43UT TOYOKAWA-FUJI




T20230920092414




No.Good Data




KISO



No.Good Data



0926+117 2023/09/20 0.43UT TOYOKAWA-KISO








F20230920092414




No.Good Data




KISO





No.Good Data




0926+117 2023/09/20 0.43UT FUJI -KISO



T20230920093159





BLK: 9,SNR1: 0.20952 ,SNR2: 2.4237




Frequency (Hz)

3C222 2023/09/20 0.56UT TOYOKAWA-FUJI


F20230920093159




BLK: 9,SNR1: 0.28212 ,SNR2: 1.5463




Frequency (Hz)




T20230920093159




No.Good Data



KISO



No.Good Data




3C222 2023/09/20 0.56UT TOYOKAWA-KISO



F20230920093159




No.Good Data



KISO





No.Good Data




3C222 2023/09/20 0.56UT FUJI -KISO



T20230920093859





BLK: 3,SNR1: 0.23857 ,SNR2: 1.5610




Frequency (Hz)

F20230920093859




BLK: 3,SNR1: 0.31546 ,SNR2: 1.6716




Frequency (Hz)


0941-08 2023/09/20 0.68UT TOYOKAWA-FUJI





T20230920093859




No. Good Data



KISO



No. Good Data



0941-08 2023/09/20 0.68UT TOYOKAWA-KISO





F20230920093859




No.Good Data




KISO





No.Good Data




0941-08 2023/09/20 0.68UT FUJI -KISO



T20230920094721





BLK:10,SNR1: 0.24558 ,SNR2: 4.5625




Frequency (Hz)

F20230920094721




BLK:10,SNR1: 0.57436 ,SNR2: 2.8571




Frequency (Hz)

3C230 2023/09/20 0.82UT TOYOKAWA-FUJI







T20230920094721




No. Good Data




KISO




No. Good Data




3C230 2023/09/20 0.82UT TOYOKAWA-KISO





F20230920094721




No.Good Data




KISO





No.Good Data




3C230 2023/09/20 0.82UT FUJI -KISO



T20230920100322





BLK:24,SNR1: 1.9692 ,SNR2: 17.568




Frequency (Hz)

F20230920100322




BLK:24,SNR1: 0.44523 ,SNR2: 2.7683



Frequency (Hz)


3C237 2023/09/20 1.08UT TOYOKAWA-FUJI



T20230920100322





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C237 2023/09/20 1.08UT TOYOKAWA-KISO



F20230920100322





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C237 2023/09/20 1.08UT FUJI -KISO





T20230920100938




BLK: 4,SNR1: 0.10999 ,SNR2: 0.78524




F20230920100938



BLK: 4,SNR1: 0.56864 ,SNR2: 1.7108




1011+110 2023/09/20 1.19UT TOYOKAWA-FUJI





T20230920100938




No. Good Data




KISO



No. Good Data



1011+110 2023/09/20 1.19UT TOYOKAWA-KISO





F20230920100938




No.Good Data




KISO



No.Good Data





1011+110 2023/09/20 1.19UT FUJI -KISO






T20230920101719





BLK: 9,SNR1: 0.58882 ,SNR2: 1.6866




Frequency (Hz)

F20230920101719




BLK: 9,SNR1: 0.31601E-01,SNR2: 2.6207



Frequency (Hz)

3C241 2023/09/20 1.32UT TOYOKAWA-FUJI



T20230920101719





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C241 2023/09/20 1.32UT TOYOKAWA-KISO





F20230920101719




No. Good Data




KISO




No. Good Data




3C241 2023/09/20 1.32UT FUJI -KISO



T20230920102848




BLK: 7, SNR1: 0.22383 , SNR2: 0.91289




Frequency (Hz)

1031-11 2023/09/20 1.51UT TOYOKAWA-FUJI


F20230920102848



BLK: 7, SNR1: 13.209 , SNR2: 28.795



Frequency (Hz)



T20230920102848





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1031-11 2023/09/20 1.51UT TOYOKAWA-KISO





F20230920102848




No. Good Data




KISO





No. Good Data




1031-11 2023/09/20 1.51UT FUJI -KISO





T20230920103322




BLK: 7,SNR1: 1.2730 ,SNR2: 3.4920




F20230920103322





BLK: 7,SNR1:-0.15876 ,SNR2: 1.0650




1035-058 2023/09/20 1.58UT TOYOKAWA-FUJI



T20230920103322





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

1035-058 2023/09/20 1.58UT TOYOKAWA-KISO






F20230920103322



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2023/09/20 1.58UT FUJI -KISO




T20230920104234




BLK: 6, SNR1: 174.76 , SNR2: 279.54




F20230920104234





BLK: 6, SNR1: 0.12659 , SNR2: 2.3910




1044-008 2023/09/20 1.74UT TOYOKAWA-FUJI



T20230920104234





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1044-008 2023/09/20 1.74UT TOYOKAWA-KISO



F20230920104234





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1044-008 2023/09/20 1.74UT FUJI -KISO



T20230920105333





BLK: 7,SNR1: 0.18045 ,SNR2: 0.41455




1055+20 2023/09/20 1.92UT TOYOKAWA-FUJI


F20230920105333



BLK: 7,SNR1: 0.64272 ,SNR2: 4.9674




Frequency (Hz)



T20230920105333



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


1055+20 2023/09/20 1.92UT TOYOKAWA-KISO



F20230920105333





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1055+20 2023/09/20 1.92UT FUJI -KISO



T20230920110456





BLK:10,SNR1: 0.60789 ,SNR2: 2.6684





1107+109 2023/09/20 2.11UT TOYOKAWA-FUJI

F20230920110456



BLK:10,SNR1: 0.26816 ,SNR2: 1.4984






T20230920110456



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1107+109 2023/09/20 2.11UT TOYOKAWA-KISO



F20230920110456





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1107+109 2023/09/20 2.11UT FUJI -KISO



T20230920111434




BLK:22,SNR1: 4.4815 ,SNR2: 23.104





3C255 2023/09/20 2.27UT TOYOKAWA-FUJI

F20230920111434



BLK:22,SNR1: 0.15789 ,SNR2: 2.7583



T20230920111434





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C255 2023/09/20 2.27UT TOYOKAWA-KISO



F20230920111434





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C255 2023/09/20 2.27UT FUJI -KISO




T20230920113832




BLK:27,SNR1: 16.191 ,SNR2: 31.269




F20230920113832



BLK:27,SNR1: 0.14586 ,SNR2: 1.5750



3C263.1 2023/09/20 2.67UT TOYOKAWA-FUJI



T20230920113832





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C263.1 2023/09/20 2.67UT TOYOKAWA-KISO



F20230920113832





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C263.1 2023/09/20 2.67UT FUJI -KISO







T20230920114459




BLK:19,SNR1: 5.6663 ,SNR2: 15.081




F20230920114459





BLK:19,SNR1: 1.1960 ,SNR2: 3.1310




3C267 2023/09/20 2.78UT TOYOKAWA-FUJI



T20230920114459





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2023/09/20 2.78UT TOYOKAWA-KISO



F20230920114459





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2023/09/20 2.78UT FUJI -KISO





T20230920120413




BLK: 4,SNR1: 0.13978 ,SNR2: 1.5161




F20230920120413





BLK: 4,SNR1: 0.38277E-01,SNR2: 1.1640




1206+439 2023/09/20 3.10UT TOYOKAWA-FUJI



T20230920120413





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1206+439 2023/09/20 3.10UT TOYOKAWA-KISO





F20230920120413




No.Good Data




KISO




No.Good Data




1206+439 2023/09/20 3.10UT FUJI -KISO



T20230920122404




BLK:23,SNR1: 23.108 ,SNR2: 43.806





3C273 2023/09/20 3.43UT TOYOKAWA-FUJI


F20230920122404



BLK:23,SNR1: 1.0173 ,SNR2: 8.1024



T20230920122404




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C273 2023/09/20 3.43UT TOYOKAWA-KISO






F20230920122404





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C273 2023/09/20 3.43UT FUJI -KISO



T20230920123715





BLK:20,SNR1: 0.36653 ,SNR2: 2.8760




Frequency (Hz)

F20230920123715




BLK:20,SNR1: 0.23056 ,SNR2: 1.4535




Frequency (Hz)

3C275 2023/09/20 3.65UT TOYOKAWA-FUJI



T20230920123715




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C275 2023/09/20 3.65UT TOYOKAWA-KISO



F20230920123715





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C275 2023/09/20 3.65UT FUJI -KISO




T20230920125103




BLK:12,SNR1: 1.8151 ,SNR2: 10.015




F20230920125103



BLK:12,SNR1: 0.37731 ,SNR2: 5.6614




3C279 2023/09/20 3.88UT TOYOKAWA-FUJI



T20230920125103





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C279 2023/09/20 3.88UT TOYOKAWA-KISO



F20230920125103





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C279 2023/09/20 3.88UT FUJI -KISO





T20230920131052




BLK: 7,SNR1: 24.950 ,SNR2: 194.86




F20230920131052



BLK: 7,SNR1: 5.7964 ,SNR2: 17.935



1313+453 2023/09/20 4.21UT TOYOKAWA-FUJI






T20230920131052





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1313+453 2023/09/20 4.21UT TOYOKAWA-KISO



F20230920131052





No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


1313+453 2023/09/20 4.21UT FUJI -KISO




T20230920132057




BLK: 7,SNR1: 0.39224 ,SNR2: 3.6581




F20230920132057



BLK: 7,SNR1: 0.76862 ,SNR2: 2.4845




1323+32 2023/09/20 4.38UT TOYOKAWA-FUJI



T20230920132057



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


1323+32 2023/09/20 4.38UT TOYOKAWA-KISO



F20230920132057





No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


1323+32 2023/09/20 4.38UT FUJI -KISO





T20230920132548




BLK:29,SNR1: 3.4397 ,SNR2: 13.161




F20230920132548





BLK:29,SNR1: 0.27976 ,SNR2: 2.3542




3C286 2023/09/20 4.46UT TOYOKAWA-FUJI



T20230920132548



No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C286 2023/09/20 4.46UT TOYOKAWA-KISO



F20230920132548





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C286 2023/09/20 4.46UT FUJI -KISO








T20230920134215




BLK:14,SNR1: 0.59452 ,SNR2: 5.4916




F20230920134215





BLK:14,SNR1: 0.92499E-01,SNR2: 2.5332




1345+12 2023/09/20 4.73UT TOYOKAWA-FUJI



T20230920134215





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1345+12 2023/09/20 4.73UT TOYOKAWA-KISO



F20230920134215





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1345+12 2023/09/20 4.73UT FUJI -KISO




T20230920135235




BLK:12,SNR1: 0.20501 ,SNR2: 1.4633




F20230920135235






BLK:12,SNR1: 0.91942 ,SNR2: 5.9731






1355+01 2023/09/20 4.90UT TOYOKAWA-FUJI




T20230920135235





KISO






1355+01 2023/09/20 4.90UT TOYOKAWA-KISO




F20230920135235




KISO




1355+01 2023/09/20 4.90UT FUJI -KISO





T20230920141346




BLK:16,SNR1: 1.8136 ,SNR2: 7.1433




F20230920141346





BLK:16,SNR1: 0.26942 ,SNR2: 2.1060




3C298 2023/09/20 5.26UT TOYOKAWA-FUJI



T20230920141346





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C298 2023/09/20 5.26UT TOYOKAWA-KISO






F20230920141346





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C298 2023/09/20 5.26UT FUJI -KISO




T20230920142529




BLK: 8,SNR1: 0.11796 ,SNR2: 1.0509




F20230920142530





BLK: 8,SNR1: 1.3800 ,SNR2: 2.9050




1428-03 2023/09/20 5.45UT TOYOKAWA-FUJI



T20230920142529





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1428-03 2023/09/20 5.45UT TOYOKAWA-KISO



F20230920142530





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1428-03 2023/09/20 5.45UT FUJI -KISO




T20230920145034




BLK: 5,SNR1: 0.18152 ,SNR2: 2.1878




F20230920145034





BLK: 5,SNR1: 2.5279 ,SNR2: 5.2320




1453-10 2023/09/20 5.87UT TOYOKAWA-FUJI



T20230920145034





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1453-10 2023/09/20 5.87UT TOYOKAWA-KISO



F20230920145034





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1453-10 2023/09/20 5.87UT FUJI -KISO





T20230920150526




BLK: 6,SNR1: 181.08 ,SNR2: 282.92




F20230920150526



BLK: 6,SNR1: 0.24663 ,SNR2: 1.7121






1508-05 2023/09/20 6.12UT TOYOKAWA-FUJI









T20230920150526




KISO



1508-05 2023/09/20 6.12UT TOYOKAWA-KISO



F20230920150526




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1508-05 2023/09/20 6.12UT FUJI -KISO





T20230920151426




BLK:14,SNR1: 0.40109 ,SNR2: 2.5003




F20230920151426




BLK:14,SNR1: 0.73861 ,SNR2: 2.5488




3C318 2023/09/20 6.27UT TOYOKAWA-FUJI



T20230920151426




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C318 2023/09/20 6.27UT TOYOKAWA-KISO



F20230920151426





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C318 2023/09/20 6.27UT FUJI -KISO




T20230920152013




BLK: 7,SNR1: 0.32124 ,SNR2: 1.1708




F20230920152013





BLK: 7,SNR1:-0.22679E-01,SNR2: 1.1507




1523+03 2023/09/20 6.37UT TOYOKAWA-FUJI



T20230920152013





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1523+03 2023/09/20 6.37UT TOYOKAWA-KISO




F20230920152013



KISO





1523+03 2023/09/20 6.37UT FUJI -KISO








T20230920153153




BLK:11,SNR1: 0.43876 ,SNR2: 1.6329




F20230920153153





BLK:11,SNR1: 0.16680 ,SNR2: 2.4675




1535+139 2023/09/20 6.56UT TOYOKAWA-FUJI



T20230920153153




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1535+139 2023/09/20 6.56UT TOYOKAWA-KISO



F20230920153153




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1535+139 2023/09/20 6.56UT FUJI -KISO



T20230920154216




BLK: 6,SNR1: 1.0082 ,SNR2: 4.2909




Frequency (Hz)

F20230920154216




BLK: 6,SNR1: 0.15228 ,SNR2: 2.0111






Frequency (Hz)




1545-12 2023/09/20 6.73UT TOYOKAWA-FUJI




T20230920154216






KISO






1545-12 2023/09/20 6.73UT TOYOKAWA-KISO




F20230920154216





KISO




1545-12 2023/09/20 6.73UT FUJI -KISO





T20230920160320




BLK:24,SNR1: 5.2364 ,SNR2: 11.538




F20230920160320






BLK:24,SNR1: 13.640 ,SNR2: 21.261






1607+26 2023/09/20 7.08UT TOYOKAWA-FUJI




T20230920160320



KISO






1607+26 2023/09/20 7.08UT TOYOKAWA-KISO









F20230920160320





KISO




1607+26 2023/09/20 7.08UT FUJI -KISO




T20230920163457




BLK:26,SNR1: 3.8198 ,SNR2: 8.8124




F20230920163458




BLK:26,SNR1: 11.982 ,SNR2: 18.715




1638-025 2023/09/20 7.61UT TOYOKAWA-FUJI



T20230920163457





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1638-025 2023/09/20 7.61UT TOYOKAWA-KISO




F20230920163458





KISO




1638-025 2023/09/20 7.61UT FUJI -KISO



T20230920164152




BLK: 4,SNR1: 2.3673 ,SNR2: 6.8717




Frequency (Hz)

F20230920164152




BLK: 4,SNR1:-0.17441 ,SNR2: 1.3882






Frequency (Hz)




1644-106 2023/09/20 7.73UT TOYOKAWA-FUJI




T20230920164152






KISO






1644-106 2023/09/20 7.73UT TOYOKAWA-KISO




F20230920164152




KISO




1644-106 2023/09/20 7.73UT FUJI -KISO




T20230920164712




BLK:18,SNR1: 6.6499 ,SNR2: 14.685




F20230920164712



BLK:18,SNR1: 3.6150 ,SNR2: 14.203






1650+004 2023/09/20 7.81UT TOYOKAWA-FUJI









T20230920164712






KISO






1650+004 2023/09/20 7.81UT TOYOKAWA-KISO




F20230920164712




KISO




1650+004 2023/09/20 7.81UT FUJI -KISO





T20230920165244




BLK: 4,SNR1: 0.43949 ,SNR2: 1.6467




F20230920165244






BLK: 4,SNR1: 0.26392 ,SNR2: 1.9114






1656+053 2023/09/20 7.91UT TOYOKAWA-FUJI




T20230920165244






KISO






1656+053 2023/09/20 7.91UT TOYOKAWA-KISO



F20230920165244



KISO



1656+053 2023/09/20 7.91UT FUJI -KISO

