




T20230924063452





No.Good Data




Frequency (Hz)

F20230924063452




No.Good Data




Frequency (Hz)


0652-130 2023/09/23 21.61UT TOYOKAWA-FUJI



T20230924063452




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0652-130 2023/09/23 21.61UT TOYOKAWA-KISO




F20230924063452



No.Good Data




KISO





No.Good Data




0652-130 2023/09/23 21.61UT FUJI -KISO



T20230924064628





No.Good Data




Frequency (Hz)

F20230924064629




No.Good Data





Frequency (Hz)

0703+138 2023/09/23 21.80UT TOYOKAWA-FUJI






T20230924064628





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0703+138 2023/09/23 21.80UT TOYOKAWA-KISO




F20230924064629




No.Good Data




KISO





No.Good Data




0703+138 2023/09/23 21.80UT FUJI -KISO





T20230924065551




No.Good Data




F20230924065551




No.Good Data




0713-024 2023/09/23 21.96UT TOYOKAWA-FUJI



T20230924065551




No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0713-024 2023/09/23 21.96UT TOYOKAWA-KISO



F20230924065551




No.Good Data



KISO





No.Good Data




0713-024 2023/09/23 21.96UT FUJI -KISO



T20230924070602





No.Good Data




Frequency (Hz)

F20230924070603




No.Good Data





Frequency (Hz)


0723+10 2023/09/23 22.13UT TOYOKAWA-FUJI



T20230924070602





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0723+10 2023/09/23 22.13UT TOYOKAWA-KISO





F20230924070603




No.Good Data



KISO



No.Good Data





0723+10 2023/09/23 22.13UT FUJI -KISO






T20230924071616





No.Good Data




Frequency (Hz)

F20230924071617




No.Good Data





Frequency (Hz)


0732+33 2023/09/23 22.30UT TOYOKAWA-FUJI



T20230924071616





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0732+33 2023/09/23 22.30UT TOYOKAWA-KISO




F20230924071617



No.Good Data



KISO





No.Good Data




0732+33 2023/09/23 22.30UT FUJI -KISO



T20230924072419





No.Good Data




Frequency (Hz)

F20230924072420




No.Good Data




Frequency (Hz)


0741-06 2023/09/23 22.43UT TOYOKAWA-FUJI



T20230924072419





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0741-06 2023/09/23 22.43UT TOYOKAWA-KISO





F20230924072420




No.Good Data




KISO





No.Good Data




0741-06 2023/09/23 22.43UT FUJI -KISO



T20230924074138





No.Good Data




Frequency (Hz)

3C190 2023/09/23 22.72UT TOYOKAWA-FUJI


F20230924074139





No.Good Data




Frequency (Hz)



T20230924074138





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C190 2023/09/23 22.72UT TOYOKAWA-KISO







F20230924074139




No.Good Data



KISO





No.Good Data




3C190 2023/09/23 22.72UT FUJI -KISO



T20230924075402





No.Good Data




3C196 2023/09/23 22.93UT TOYOKAWA-FUJI



F20230924075402




No.Good Data



T20230924075402





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C196 2023/09/23 22.93UT TOYOKAWA-KISO





F20230924075402




No.Good Data




KISO





No.Good Data




3C196 2023/09/23 22.93UT FUJI -KISO



T20230924080512





No.Good Data




Frequency (Hz)

F20230924080513




No.Good Data





Frequency (Hz)


0821+394 2023/09/23 23.11UT TOYOKAWA-FUJI



T20230924080512





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0821+394 2023/09/23 23.11UT TOYOKAWA-KISO



F20230924080513





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0821+394 2023/09/23 23.11UT FUJI -KISO





T20230924082158




No.Good Data




F20230924082158



No.Good Data




0839-071 2023/09/23 23.39UT TOYOKAWA-FUJI






T20230924082158





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0839-071 2023/09/23 23.39UT TOYOKAWA-KISO



F20230924082158





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0839-071 2023/09/23 23.39UT FUJI -KISO





T20230924083259




No.Good Data




F20230924083300





No.Good Data




3C208 2023/09/23 23.58UT TOYOKAWA-FUJI



T20230924083259





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2023/09/23 23.58UT TOYOKAWA-KISO



F20230924083300





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2023/09/23 23.58UT FUJI -KISO





T20230924084940




No. Good Data




F20230924084940





No. Good Data




3C216 2023/09/23 23.86UT TOYOKAWA-FUJI





T20230924084940




No.Good Data




KISO





No.Good Data




3C216 2023/09/23 23.86UT TOYOKAWA-KISO





F20230924084940




No.Good Data




KISO



No.Good Data





3C216 2023/09/23 23.86UT FUJI -KISO






T20230924090831





No.Good Data




Frequency (Hz)

F20230924090832




No.Good Data





Frequency (Hz)


0926+117 2023/09/24 0.17UT TOYOKAWA-FUJI





T20230924090831




No. Good Data




KISO




No. Good Data




0926+117 2023/09/24 0.17UT TOYOKAWA-KISO





F20230924090832




No.Good Data




KISO





No.Good Data




0926+117 2023/09/24 0.17UT FUJI -KISO



T20230924091615





No.Good Data




Frequency (Hz)

F20230924091616




No.Good Data





Frequency (Hz)


3C222 2023/09/24 0.30UT TOYOKAWA-FUJI





T20230924091615




No. Good Data




KISO



No. Good Data



3C222 2023/09/24 0.30UT TOYOKAWA-KISO




F20230924091616




No.Good Data



KISO





No.Good Data




3C222 2023/09/24 0.30UT FUJI -KISO





T20230924092316




No. Good Data




F20230924092316




No. Good Data




0941-08 2023/09/24 0.42UT TOYOKAWA-FUJI




T20230924092316




No.Good Data




KISO



No.Good Data



0941-08 2023/09/24 0.42UT TOYOKAWA-KISO







F20230924092316




No.Good Data




KISO




No.Good Data



0941-08 2023/09/24 0.42UT FUJI -KISO



T20230924093137





No.Good Data




Frequency (Hz)

F20230924093137




No.Good Data




Frequency (Hz)


3C230 2023/09/24 0.56UT TOYOKAWA-FUJI





T20230924093137




No. Good Data




KISO



No. Good Data




3C230 2023/09/24 0.56UT TOYOKAWA-KISO



F20230924093137




No.Good Data




KISO





No.Good Data




3C230 2023/09/24 0.56UT FUJI -KISO




T20230924094738




No. Good Data




F20230924094739




No. Good Data




3C237 2023/09/24 0.82UT TOYOKAWA-FUJI





T20230924094738




No.Good Data



KISO




No.Good Data




3C237 2023/09/24 0.82UT TOYOKAWA-KISO





F20230924094739




No.Good Data




KISO





No.Good Data



3C237 2023/09/24 0.82UT FUJI -KISO





T20230924095354



No. Good Data




F20230924095355



No. Good Data




1011+110 2023/09/24 0.93UT TOYOKAWA-FUJI







T20230924095354




No.Good Data




KISO



No.Good Data




1011+110 2023/09/24 0.93UT TOYOKAWA-KISO





F20230924095355




No.Good Data




KISO





No.Good Data




1011+110 2023/09/24 0.93UT FUJI -KISO





T20230924100135




No. Good Data




F20230924100136



No. Good Data




3C241 2023/09/24 1.05UT TOYOKAWA-FUJI





T20230924100135




No. Good Data




KISO





No. Good Data




3C241 2023/09/24 1.05UT TOYOKAWA-KISO





F20230924100136




No. Good Data




KISO





No. Good Data



3C241 2023/09/24 1.05UT FUJI -KISO





T20230924101305



No. Good Data



F20230924101305



No. Good Data




1031-11 2023/09/24 1.25UT TOYOKAWA-FUJI



T20230924101305





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

1031-11 2023/09/24 1.25UT TOYOKAWA-KISO





F20230924101305




No.Good Data




KISO



No.Good Data





1031-11 2023/09/24 1.25UT FUJI -KISO








T20230924101738




No. Good Data




F20230924101739



No. Good Data



1035-058 2023/09/24 1.32UT TOYOKAWA-FUJI



T20230924101738





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

1035-058 2023/09/24 1.32UT TOYOKAWA-KISO





F20230924101739




No. Good Data




KISO





No. Good Data




1035-058 2023/09/24 1.32UT FUJI -KISO




T20230924102651




No. Good Data



F20230924102652



No. Good Data




1044-008 2023/09/24 1.48UT TOYOKAWA-FUJI



T20230924102651





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1044-008 2023/09/24 1.48UT TOYOKAWA-KISO





F20230924102652




No. Good Data




KISO





No. Good Data



1044-008 2023/09/24 1.48UT FUJI -KISO





T20230924103755




No. Good Data




F20230924103756





No. Good Data




1055+01 2023/09/24 1.66UT TOYOKAWA-FUJI



T20230924103755





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1055+01 2023/09/24 1.66UT TOYOKAWA-KISO






F20230924103756



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1055+01 2023/09/24 1.66UT FUJI -KISO



T20230924104913





No. Good Data




Frequency (Hz)

F20230924104913




No. Good Data





Frequency (Hz)


1107+109 2023/09/24 1.85UT TOYOKAWA-FUJI



T20230924104913





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1107+109 2023/09/24 1.85UT TOYOKAWA-KISO



F20230924104913



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1107+109 2023/09/24 1.85UT FUJI -KISO



T20230924105850





No. Good Data




Frequency (Hz)

F20230924105850




No. Good Data



Frequency (Hz)


3C255 2023/09/24 2.01UT TOYOKAWA-FUJI



T20230924105850



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C255 2023/09/24 2.01UT TOYOKAWA-KISO





F20230924105850




No.Good Data




KISO





No.Good Data




3C255 2023/09/24 2.01UT FUJI -KISO





T20230924112248




No. Good Data




F20230924112249



No. Good Data



3C263.1 2023/09/24 2.41UT TOYOKAWA-FUJI






T20230924112248



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C263.1 2023/09/24 2.41UT TOYOKAWA-KISO





F20230924112249




No.Good Data




KISO





No.Good Data




3C263.1 2023/09/24 2.41UT FUJI -KISO



T20230924112915





No. Good Data




Frequency (Hz)

F20230924112915




No. Good Data



Frequency (Hz)

3C267 2023/09/24 2.52UT TOYOKAWA-FUJI





T20230924112915




No.Good Data




KISO



No.Good Data



3C267 2023/09/24 2.52UT TOYOKAWA-KISO



F20230924112915





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2023/09/24 2.52UT FUJI -KISO





T20230924114829




No. Good Data




F20230924114830




No. Good Data



1206+439 2023/09/24 2.84UT TOYOKAWA-FUJI



T20230924114829





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1206+439 2023/09/24 2.84UT TOYOKAWA-KISO



F20230924114830





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1206+439 2023/09/24 2.84UT FUJI -KISO





T20230924120820





No. Good Data




Frequency (Hz)

F20230924120821




No. Good Data



Frequency (Hz)

3C273 2023/09/24 3.17UT TOYOKAWA-FUJI



T20230924120820



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C273 2023/09/24 3.17UT TOYOKAWA-KISO



F20230924120821





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C273 2023/09/24 3.17UT FUJI -KISO



T20230924122131





No. Good Data




Frequency (Hz)

F20230924122131




No. Good Data





Frequency (Hz)


3C275 2023/09/24 3.39UT TOYOKAWA-FUJI



T20230924122131





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C275 2023/09/24 3.39UT TOYOKAWA-KISO



F20230924122131





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C275 2023/09/24 3.39UT FUJI -KISO



T20230924123520




No. Good Data




Frequency (Hz)

3C279 2023/09/24 3.62UT TOYOKAWA-FUJI


F20230924123520




No. Good Data



Frequency (Hz)



T20230924123520




No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)

3C279 2023/09/24 3.62UT TOYOKAWA-KISO






F20230924123520





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C279 2023/09/24 3.62UT FUJI -KISO




T20230924125508




No. Good Data




F20230924125508




No. Good Data




1313+453 2023/09/24 3.95UT TOYOKAWA-FUJI



T20230924125508





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1313+453 2023/09/24 3.95UT TOYOKAWA-KISO



F20230924125508





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1313+453 2023/09/24 3.95UT FUJI -KISO





T20230924130514




No. Good Data




F20230924130515



No. Good Data




1323+32 2023/09/24 4.12UT TOYOKAWA-FUJI



T20230924130514





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1323+32 2023/09/24 4.12UT TOYOKAWA-KISO



F20230924130515





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2023/09/24 4.12UT FUJI -KISO



T20230924131004





No. Good Data




Frequency (Hz)

F20230924131004




No. Good Data



Frequency (Hz)

3C286 2023/09/24 4.20UT TOYOKAWA-FUJI






T20230924131004





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C286 2023/09/24 4.20UT TOYOKAWA-KISO



F20230924131004





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C286 2023/09/24 4.20UT FUJI -KISO




T20230924132631




No. Good Data




F20230924132631



No. Good Data




1345+12 2023/09/24 4.47UT TOYOKAWA-FUJI



T20230924132631



No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

1345+12 2023/09/24 4.47UT TOYOKAWA-KISO



F20230924132631





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1345+12 2023/09/24 4.47UT FUJI -KISO





T20230924133651




No. Good Data




F20230924133652





No. Good Data




1355+01 2023/09/24 4.64UT TOYOKAWA-FUJI



T20230924133651



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1355+01 2023/09/24 4.64UT TOYOKAWA-KISO



F20230924133652





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

1355+01 2023/09/24 4.64UT FUJI -KISO









T20230924135802





F20230924135803




3C298 2023/09/24 5.00UT TOYOKAWA-FUJI



T20230924135802





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C298 2023/09/24 5.00UT TOYOKAWA-KISO



F20230924135803





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)




3C298 2023/09/24 5.00UT FUJI -KISO




T20230924140945





F20230924140945




1428-03 2023/09/24 5.19UT TOYOKAWA-FUJI



T20230924140945





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)




1428-03 2023/09/24 5.19UT TOYOKAWA-KISO




F20230924140945





KISO




1428-03 2023/09/24 5.19UT FUJI -KISO




T20230924143450




No.Good Data




F20230924143450





No.Good Data




1453-10 2023/09/24 5.61UT TOYOKAWA-FUJI



T20230924143450





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1453-10 2023/09/24 5.61UT TOYOKAWA-KISO






F20230924143450





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1453-10 2023/09/24 5.61UT FUJI -KISO





T20230924144942




No.Good Data




F20230924144942






No.Good Data






1508-05 2023/09/24 5.86UT TOYOKAWA-FUJI




T20230924144942





KISO




1508-05 2023/09/24 5.86UT TOYOKAWA-KISO



F20230924144942





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)



1508-05 2023/09/24 5.86UT FUJI -KISO




T20230924145843






F20230924145844






3C318 2023/09/24 6.01UT TOYOKAWA-FUJI




T20230924145843





KISO




3C318 2023/09/24 6.01UT TOYOKAWA-KISO



F20230924145844





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C318 2023/09/24 6.01UT FUJI -KISO




T20230924150429



F20230924150430





1523+03 2023/09/24 6.10UT TOYOKAWA-FUJI






T20230924150429





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1523+03 2023/09/24 6.10UT TOYOKAWA-KISO



F20230924150430





No.Good Data



Frequency (Hz)

KISO



No.Good Data






Frequency (Hz)




1523+03 2023/09/24 6.10UT FUJI -KISO




T20230924151609





F20230924151609






1535+139 2023/09/24 6.30UT TOYOKAWA-FUJI




T20230924151609





KISO



1535+139 2023/09/24 6.30UT TOYOKAWA-KISO



F20230924151609





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)




1535+139 2023/09/24 6.30UT FUJI -KISO




T20230924152633





F20230924152634




1545-12 2023/09/24 6.47UT TOYOKAWA-FUJI



T20230924152633





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1545-12 2023/09/24 6.47UT TOYOKAWA-KISO



F20230924152634





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1545-12 2023/09/24 6.47UT FUJI -KISO









T20230924154737





F20230924154737




1607+26 2023/09/24 6.82UT TOYOKAWA-FUJI



T20230924154737




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1607+26 2023/09/24 6.82UT TOYOKAWA-KISO





F20230924154737




No.Good Data




KISO





No.Good Data





1607+26 2023/09/24 6.82UT FUJI -KISO




T20230924161914





F20230924161915




1638-025 2023/09/24 7.35UT TOYOKAWA-FUJI



T20230924161914





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1638-025 2023/09/24 7.35UT TOYOKAWA-KISO



F20230924161915




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1638-025 2023/09/24 7.35UT FUJI -KISO



T20230924162608





No.Good Data




Frequency (Hz)

F20230924162609




No.Good Data






Frequency (Hz)




1644-106 2023/09/24 7.46UT TOYOKAWA-FUJI




T20230924162608



KISO






1644-106 2023/09/24 7.46UT TOYOKAWA-KISO









F20230924162609




KISO




1644-106 2023/09/24 7.46UT FUJI -KISO




T20230924163129




No.Good Data




F20230924163129




No.Good Data




1650+004 2023/09/24 7.55UT TOYOKAWA-FUJI



T20230924163129





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




1650+004 2023/09/24 7.55UT TOYOKAWA-KISO




F20230924163129






KISO






1650+004 2023/09/24 7.55UT FUJI -KISO




T20230924163701






F20230924163702






1656+053 2023/09/24 7.65UT TOYOKAWA-FUJI




T20230924163701






KISO






1656+053 2023/09/24 7.65UT TOYOKAWA-KISO




F20230924163702




KISO




1656+053 2023/09/24 7.65UT FUJI -KISO





T20230924165330




No.Good Data




F20230924165330



No.Good Data






1712-033 2023/09/24 7.92UT TOYOKAWA-FUJI









T20230924165330






KISO






1712-033 2023/09/24 7.92UT TOYOKAWA-KISO



F20230924165330



KISO



1712-033 2023/09/24 7.92UT FUJI -KISO

