






T20230928061908




No. Good Data




F20230928061908




No. Good Data




0652-130 2023/09/27 21.35UT TOYOKAWA-FUJI



T20230928061908




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0652-130 2023/09/27 21.35UT TOYOKAWA-KISO




F20230928061908



No.Good Data




KISO





No.Good Data




0652-130 2023/09/27 21.35UT FUJI -KISO





T20230928064007




No.Good Data




F20230928064008



No.Good Data





0713-024 2023/09/27 21.70UT TOYOKAWA-FUJI






T20230928064007





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0713-024 2023/09/27 21.70UT TOYOKAWA-KISO




F20230928064008




No.Good Data




KISO





No.Good Data




0713-024 2023/09/27 21.70UT FUJI -KISO



T20230928065019




No.Good Data




Frequency (Hz)

F20230928065019




No.Good Data





Frequency (Hz)


0723+10 2023/09/27 21.87UT TOYOKAWA-FUJI



T20230928065019





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0723+10 2023/09/27 21.87UT TOYOKAWA-KISO



F20230928065019




No.Good Data




KISO





No.Good Data




0723+10 2023/09/27 21.87UT FUJI -KISO



T20230928070033





No.Good Data




Frequency (Hz)

F20230928070034




No.Good Data





Frequency (Hz)


0732+33 2023/09/27 22.04UT TOYOKAWA-FUJI



T20230928070033





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0732+33 2023/09/27 22.04UT TOYOKAWA-KISO





F20230928070034




No.Good Data



KISO



No.Good Data





0732+33 2023/09/27 22.04UT FUJI -KISO








T20230928070836




No.Good Data




F20230928070836





No.Good Data




0741-06 2023/09/27 22.17UT TOYOKAWA-FUJI



T20230928070836





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0741-06 2023/09/27 22.17UT TOYOKAWA-KISO




F20230928070836



No.Good Data




KISO





No.Good Data




0741-06 2023/09/27 22.17UT FUJI -KISO



T20230928072555




No.Good Data




Frequency (Hz)

3C190 2023/09/27 22.46UT TOYOKAWA-FUJI


F20230928072556





No.Good Data




Frequency (Hz)





T20230928072555




No.Good Data




KISO



No.Good Data



3C190 2023/09/27 22.46UT TOYOKAWA-KISO





F20230928072556




No.Good Data




KISO





No.Good Data




3C190 2023/09/27 22.46UT FUJI -KISO



T20230928073818





No.Good Data




Frequency (Hz)

F20230928073818




No.Good Data





Frequency (Hz)


3C196 2023/09/27 22.67UT TOYOKAWA-FUJI



T20230928073818





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C196 2023/09/27 22.67UT TOYOKAWA-KISO







F20230928073818




No.Good Data



KISO





No.Good Data




3C196 2023/09/27 22.67UT FUJI -KISO



T20230928074928





No.Good Data




Frequency (Hz)

F20230928074929




No.Good Data





Frequency (Hz)


0821+394 2023/09/27 22.85UT TOYOKAWA-FUJI



T20230928074928





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0821+394 2023/09/27 22.85UT TOYOKAWA-KISO



F20230928074929





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0821+394 2023/09/27 22.85UT FUJI -KISO





T20230928080615




No.Good Data




F20230928080616





No.Good Data




0839-071 2023/09/27 23.13UT TOYOKAWA-FUJI



T20230928080615





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0839-071 2023/09/27 23.13UT TOYOKAWA-KISO





F20230928080616




No.Good Data




KISO





No.Good Data




0839-071 2023/09/27 23.13UT FUJI -KISO



T20230928081715





No.Good Data




Frequency (Hz)

F20230928081715




No.Good Data




Frequency (Hz)

3C208 2023/09/27 23.32UT TOYOKAWA-FUJI






T20230928081715





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2023/09/27 23.32UT TOYOKAWA-KISO



F20230928081715





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2023/09/27 23.32UT FUJI -KISO



T20230928083356





No.Good Data




Frequency (Hz)

F20230928083356




No.Good Data





Frequency (Hz)


3C216 2023/09/27 23.59UT TOYOKAWA-FUJI



T20230928083356





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C216 2023/09/27 23.59UT TOYOKAWA-KISO



F20230928083356





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C216 2023/09/27 23.59UT FUJI -KISO



T20230928085247




No.Good Data




Frequency (Hz)

F20230928085247




No.Good Data





Frequency (Hz)


0926+117 2023/09/27 23.91UT TOYOKAWA-FUJI



T20230928085247





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0926+117 2023/09/27 23.91UT TOYOKAWA-KISO





F20230928085247




No.Good Data




KISO



No.Good Data





0926+117 2023/09/27 23.91UT FUJI -KISO








T20230928090032




No.Good Data




F20230928090032





No.Good Data




3C222 2023/09/28 0.04UT TOYOKAWA-FUJI





T20230928090032




No.Good Data




KISO



No.Good Data




3C222 2023/09/28 0.04UT TOYOKAWA-KISO





F20230928090032




No.Good Data




KISO





No.Good Data




3C222 2023/09/28 00.4UT FUJI -KISO



T20230928090732





No.Good Data




Frequency (Hz)

0941-08 2023/09/28 0.15UT TOYOKAWA-FUJI


F20230928090733





No.Good Data




Frequency (Hz)





T20230928090732




No.Good Data




KISO



No.Good Data




0941-08 2023/09/28 0.15UT TOYOKAWA-KISO




F20230928090733




No.Good Data



KISO





No.Good Data




0941-08 2023/09/28 0.15UT FUJI -KISO





T20230928091554




No.Good Data




F20230928091555




No.Good Data




3C230 2023/09/28 0.29UT TOYOKAWA-FUJI




T20230928091554




No.Good Data




KISO



No.Good Data



3C230 2023/09/28 0.29UT TOYOKAWA-KISO








F20230928091555




No.Good Data




KISO





No.Good Data




3C230 2023/09/28 0.29UT FUJI -KISO





T20230928093154




No. Good Data




F20230928093154




No. Good Data




3C237 2023/09/28 0.56UT TOYOKAWA-FUJI




T20230928093154




No.Good Data



KISO



No.Good Data




3C237 2023/09/28 0.56UT TOYOKAWA-KISO



F20230928093154





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C237 2023/09/28 0.56UT FUJI -KISO





T20230928093811




No. Good Data




F20230928093812




No. Good Data




1011+110 2023/09/28 0.66UT TOYOKAWA-FUJI





T20230928093811




No. Good Data



KISO



No. Good Data



1011+110 2023/09/28 0.66UT TOYOKAWA-KISO





F20230928093812




No.Good Data




KISO





No.Good Data




1011+110 2023/09/28 0.66UT FUJI -KISO





T20230928094552




No. Good Data




F20230928094552



No. Good Data




3C241 2023/09/28 0.79UT TOYOKAWA-FUJI








T20230928094552




No. Good Data




KISO



No. Good Data




3C241 2023/09/28 0.79UT TOYOKAWA-KISO



F20230928094552



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C241 2023/09/28 0.79UT FUJI -KISO



T20230928095721





No. Good Data




Frequency (Hz)

F20230928095722




No. Good Data



Frequency (Hz)


1031-11 2023/09/28 0.98UT TOYOKAWA-FUJI





T20230928095721




No. Good Data




KISO





No. Good Data




1031-11 2023/09/28 0.98UT TOYOKAWA-KISO





F20230928095722




No.Good Data




KISO





No.Good Data




1031-11 2023/09/28 0.98UT FUJI -KISO



T20230928100155





No.Good Data




Frequency (Hz)

F20230928100155




No.Good Data



Frequency (Hz)


1035-058 2023/09/28 1.06UT TOYOKAWA-FUJI



T20230928100155





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

1035-058 2023/09/28 1.06UT TOYOKAWA-KISO





F20230928100155




No. Good Data




KISO



No. Good Data





1035-058 2023/09/28 1.06UT FUJI -KISO








T20230928101107




No. Good Data




F20230928101107



No. Good Data




1044-008 2023/09/28 1.21UT TOYOKAWA-FUJI



T20230928101107





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1044-008 2023/09/28 1.21UT TOYOKAWA-KISO





F20230928101107




No.Good Data




KISO





No.Good Data




1044-008 2023/09/28 1.21UT FUJI -KISO



T20230928102212





No. Good Data




Frequency (Hz)

F20230928102212




No. Good Data



Frequency (Hz)

1055+01 2023/09/28 1.4OUT TOYOKAWA-FUJI



T20230928102212





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1055+01 2023/09/28 1.40UT TOYOKAWA-KISO





F20230928102212




No.Good Data




KISO





No.Good Data




1055+01 2023/09/28 1.40UT FUJI -KISO




T20230928103329




No. Good Data




F20230928103329





No. Good Data




1107+109 2023/09/28 1.59UT TOYOKAWA-FUJI



T20230928103329





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1107+109 2023/09/28 1.59UT TOYOKAWA-KISO






F20230928103329





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1107+109 2023/09/28 1.59UT FUJI -KISO



T20230928104307





No. Good Data




Frequency (Hz)

F20230928104307




No. Good Data





Frequency (Hz)


3C255 2023/09/28 1.75UT TOYOKAWA-FUJI



T20230928104307





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C255 2023/09/28 1.75UT TOYOKAWA-KISO



F20230928104307



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C255 2023/09/28 1.75UT FUJI -KISO



T20230928110705





No. Good Data




Frequency (Hz)

F20230928110705




No. Good Data



Frequency (Hz)


3C263.1 2023/09/28 2.15UT TOYOKAWA-FUJI



T20230928110705



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C263.1 2023/09/28 2.15UT TOYOKAWA-KISO



F20230928110705





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C263.1 2023/09/28 2.15UT FUJI -KISO





T20230928111332




No. Good Data




F20230928111332



No. Good Data



3C267 2023/09/28 2.25UT TOYOKAWA-FUJI






T20230928111332



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C267 2023/09/28 2.25UT TOYOKAWA-KISO



F20230928111332





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C267 2023/09/28 2.25UT FUJI -KISO



T20230928113246





No. Good Data




Frequency (Hz)

F20230928113247




No. Good Data



Frequency (Hz)

1206+439 2023/09/28 2.57UT TOYOKAWA-FUJI



T20230928113246





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1206+439 2023/09/28 2.57UT TOYOKAWA-KISO





F20230928113247




No.Good Data




KISO





No.Good Data



1206+439 2023/09/28 2.57UT FUJI -KISO





T20230928115237




No. Good Data




F20230928115237



No. Good Data



3C273 2023/09/28 2.91UT TOYOKAWA-FUJI



T20230928115237





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C273 2023/09/28 2.91UT TOYOKAWA-KISO





F20230928115237




No.Good Data




KISO



No.Good Data





3C273 2023/09/28 2.91UT FUJI -KISO






T20230928120547





No.Good Data




Frequency (Hz)

F20230928120547




No.Good Data



Frequency (Hz)

3C275 2023/09/28 3.12UT TOYOKAWA-FUJI



T20230928120547



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

3C275 2023/09/28 3.12UT TOYOKAWA-KISO



F20230928120547



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C275 2023/09/28 3.12UT FUJI -KISO



T20230928121936





No. Good Data




Frequency (Hz)

F20230928121936




No. Good Data





Frequency (Hz)


3C279 2023/09/28 3.35UT TOYOKAWA-FUJI



T20230928121936





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C279 2023/09/28 3.35UT TOYOKAWA-KISO



F20230928121936





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C279 2023/09/28 3.35UT FUJI -KISO



T20230928123924




No. Good Data




Frequency (Hz)

F20230928123924




No. Good Data




Frequency (Hz)

1313+453 2023/09/28 3.68UT TOYOKAWA-FUJI



T20230928123924




No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)

1313+453 2023/09/28 3.68UT TOYOKAWA-KISO






F20230928123924




No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1313+453 2023/09/28 3.68UT FUJI -KISO



T20230928124930





No.Good Data




Frequency (Hz)

F20230928124930




No.Good Data




Frequency (Hz)

1323+32 2023/09/28 3.85UT TOYOKAWA-FUJI



T20230928124930




No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


1323+32 2023/09/28 3.85UT TOYOKAWA-KISO



F20230928124930





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2023/09/28 3.85UT FUJI -KISO



T20230928125421




No. Good Data




Frequency (Hz)

F20230928125421




No. Good Data



Frequency (Hz)

3C286 2023/09/28 3.93UT TOYOKAWA-FUJI



T20230928125421





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C286 2023/09/28 3.93UT TOYOKAWA-KISO



F20230928125421





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C286 2023/09/28 3.93UT FUJI -KISO



T20230928131048





No. Good Data




Frequency (Hz)

F20230928131048




No. Good Data



Frequency (Hz)

1345+12 2023/09/28 4.21UT TOYOKAWA-FUJI






T20230928131048





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1345+12 2023/09/28 4.21UT TOYOKAWA-KISO



F20230928131048





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1345+12 2023/09/28 4.21UT FUJI -KISO





T20230928132108




No.Good Data




F20230928132108



No.Good Data




1355+01 2023/09/28 4.38UT TOYOKAWA-FUJI



T20230928132108



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1355+01 2023/09/28 4.38UT TOYOKAWA-KISO





F20230928132108




No. Good Data




KISO





No. Good Data




1355+01 2023/09/28 4.38UT FUJI -KISO





T20230928134219




No.Good Data




F20230928134219





No.Good Data




3C298 2023/09/28 4.73UT TOYOKAWA-FUJI



T20230928134219



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


3C298 2023/09/28 4.73UT TOYOKAWA-KISO



F20230928134219





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C298 2023/09/28 4.73UT FUJI -KISO







T20230928135402




No.Good Data




F20230928135403





No.Good Data




1428-03 2023/09/28 4.93UT TOYOKAWA-FUJI



T20230928135402





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1428-03 2023/09/28 4.93UT TOYOKAWA-KISO





F20230928135403




No.Good Data




KISO





No.Good Data




1428-03 2023/09/28 4.93UT FUJI -KISO





T20230928140004




No.Good Data




F20230928140004





No.Good Data




1434+03 2023/09/28 5.03UT TOYOKAWA-FUJI



T20230928140004





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1434+03 2023/09/28 5.03UT TOYOKAWA-KISO





F20230928140004




No.Good Data




KISO





No.Good Data




1434+03 2023/09/28 5.03UT FUJI -KISO





T20230928141906




No.Good Data




F20230928141906




No.Good Data




1453-10 2023/09/28 5.35UT TOYOKAWA-FUJI



T20230928141906




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1453-10 2023/09/28 5.35UT TOYOKAWA-KISO






F20230928141906





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1453-10 2023/09/28 5.35UT FUJI -KISO





T20230928143359




No.Good Data




F20230928143400






No.Good Data






1508-05 2023/09/28 5.59UT TOYOKAWA-FUJI




T20230928143359




KISO




1508-05 2023/09/28 5.59UT TOYOKAWA-KISO



F20230928143400





No. Good Data




Frequency (Hz)

KISO




No. Good Data






Frequency (Hz)




1508-05 2023/09/28 5.59UT FUJI -KISO




T20230928144259





F20230928144259




3C318 2023/09/28 5.74UT TOYOKAWA-FUJI



T20230928144259





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C318 2023/09/28 5.74UT TOYOKAWA-KISO



F20230928144259





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C318 2023/09/28 5.74UT FUJI -KISO





T20230928144846




No.Good Data




F20230928144846



No.Good Data





1523+03 2023/09/28 5.84UT TOYOKAWA-FUJI






T20230928144846




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1523+03 2023/09/28 5.84UT TOYOKAWA-KISO



F20230928144846




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)




1523+03 2023/09/28 5.84UT FUJI -KISO




T20230928150026





F20230928150026




1535+139 2023/09/28 6.04UT TOYOKAWA-FUJI



T20230928150026





No.Good Data




Frequency (Hz)

K20230928150023




No.Good Data




Frequency (Hz)


1535+139 2023/09/28 6.04UT TOYOKAWA-KISO





F20230928150026




BLK: 4,SNR1: 0.19499 ,SNR2: 0.60614




K20230928150023





BLK: 4,SNR1: 0.76998 ,SNR2: 3.5956




1535+139 2023/09/28 6.04UT FUJI -KISO





T20230928151049




No. Good Data




F20230928151049





No. Good Data






1545-12 2023/09/28 6.21UT TOYOKAWA-FUJI




T20230928151049




K20230928151046




1545-12 2023/09/28 6.21UT TOYOKAWA-KISO





F20230928151049




BLK: 4,SNR1: 1.0321 ,SNR2: 8.4621




K20230928151046



BLK: 4,SNR1: 1.4624 ,SNR2: 5.9155





1545-12 2023/09/28 6.21UT FUJI -KISO









T20230928153153





F20230928153153




1607+26 2023/09/28 6.56UT TOYOKAWA-FUJI





T20230928153153




No.Good Data




K20230928153150





No.Good Data




1607+26 2023/09/28 6.56UT TOYOKAWA-KISO





F20230928153153




BLK:12,SNR1: 6.9351 ,SNR2: 9.3685




K20230928153150





BLK:12,SNR1: 0.57876 ,SNR2: 3.0797




1607+26 2023/09/28 6.56UT FUJI -KISO





T20230928160330




No.Good Data




F20230928160330






No.Good Data






1638-025 2023/09/28 7.09UT TOYOKAWA-FUJI




T20230928160330





KISO




1638-025 2023/09/28 7.09UT TOYOKAWA-KISO



F20230928160330





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)




1638-025 2023/09/28 7.09UT FUJI -KISO




T20230928161024






F20230928161024






1644-106 2023/09/28 7.20UT TOYOKAWA-FUJI




T20230928161024



KISO






1644-106 2023/09/28 7.20UT TOYOKAWA-KISO








F20230928161024





KISO





1644-106 2023/09/28 7.20UT FUJI -KISO




T20230928161545






F20230928161545






1650+004 2023/09/28 7.29UT TOYOKAWA-FUJI




T20230928161545





KISO




1650+004 2023/09/28 7.29UT TOYOKAWA-KISO



F20230928161545





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1650+004 2023/09/28 7.29UT FUJI -KISO





T20230928162117




No.Good Data




F20230928162117





No.Good Data




1656+053 2023/09/28 7.38UT TOYOKAWA-FUJI





T20230928162117




No.Good Data




K20230928162117





No.Good Data




1656+053 2023/09/28 7.38UT TOYOKAWA-KISO



F20230928162117





BLK: 3,SNR1: 10.023 ,SNR2: 20.235




Frequency (Hz)

K20230928162117




BLK: 3,SNR1: 0.34225E-01,SNR2: 0.37225






Frequency (Hz)




1656+053 2023/09/28 7.38UT FUJI -KISO




T20230928163747



F20230928163748






1712-033 2023/09/28 7.66UT TOYOKAWA-FUJI









T20230928163747







K20230928163745




1712-033 2023/09/28 7.66UT TOYOKAWA-KISO








1712-033 2023/09/28 7.66UT FUJI -KISO





T20230928165549




No.Good Data




F20230928165550





No.Good Data






1730-13 2023/09/28 7.96UT TOYOKAWA-FUJI




T20230928165549




K20230928165546




1730-13 2023/09/28 7.96UT TOYOKAWA-KISO





F20230928165550




BLK:17,SNR1: 7.4945 ,SNR2: 14.806



K20230928165546



BLK:17,SNR1: 44.617 ,SNR2: 74.395



1730-13 2023/09/28 7.96UT FUJI -KISO

