




TOYOKAWA 0713-192 2023/10/11(284)05:48:41-05:52:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0718-154 2023/10/11(284)05:54:17-05:57:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723-008 2023/10/11(284)05:59:02-06:02:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0727-115 2023/10/11(284)06:03:24-06:06:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0731+021 2023/10/11(284)06:07:06-06:10:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0735+076 2023/10/11(284)06:10:56-06:14:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0746+162 2023/10/11(284)06:22:14-06:25:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0752-200 2023/10/11(284)06:27:12-06:30:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0755+029 2023/10/11(284)06:30:49-06:34:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C190


2023/10/11(284)06:34:46-06:38:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0806-103 2023/10/11(284)06:41:52-06:45:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C196


2023/10/11(284)06:47:10-06:50:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0817+183 2023/10/11(284)06:53:55-06:57:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2023/10/11(284)06:58:20-07:01:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0834-19 2023/10/11(284)07:10:01-07:13:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0839-071 2023/10/11(284)07:15:06-07:18:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0857-191 2023/10/11(284)07:32:27-07:35:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216

2023/10/11(284)07:42:47-07:46:13JST


11365+/- 35




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0912-132 2023/10/11(284)07:47:33-07:50:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0919-142 2023/10/11(284)07:55:00-07:58:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0923+392 2023/10/11(284)08:00:10-08:03:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C222 2023/10/11(284)08:09:23-08:12:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0941-08 2023/10/11(284)08:16:23-08:19:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C230

2023/10/11(284)08:24:45-08:28:11JST

11611+/- 53




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C237 2023/10/11(284)08:40:46-08:44:12JST


10736+/- 193




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1011+110 2023/10/11(284)08:47:02-08:50:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1017+318 2023/10/11(284)08:53:30-08:56:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1031-11 2023/10/11(284)09:06:12-09:09:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1035-058 2023/10/11(284)09:10:46-09:14:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1044-008 2023/10/11(284)09:19:58-09:23:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1055+01 2023/10/11(284)09:31:03-09:34:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1107+109 2023/10/11(284)09:42:20-09:45:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C255 2023/10/11(284)09:51:58-09:55:24JST


9604+/- 247




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1127-14 2023/10/11(284)10:02:36-10:06:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1136-13 2023/10/11(284)10:11:39-10:15:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C263.1 2023/10/11(284)10:15:56-10:19:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C267 2023/10/11(284)10:22:23-10:25:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1154+552 2023/10/11(284)10:29:48-10:33:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1206+439 2023/10/11(284)10:41:37-10:45:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1213-17 2023/10/11(284)10:48:11-10:51:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C273 2023/10/11(284)11:01:28-11:04:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C275 2023/10/11(284)11:14:39-11:18:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1245-19 2023/10/11(284)11:20:44-11:24:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C283 2023/10/11(284)11:43:57-11:47:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1313+453 2023/10/11(284)11:48:16-11:51:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1323+32 2023/10/11(284)11:58:22-12:01:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C286 2023/10/11(284)12:03:12-12:06:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1334-17 2023/10/11(284)12:09:48-12:13:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1345+12 2023/10/11(284)12:19:39-12:23:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1355+01 2023/10/11(284)12:29:59-12:33:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C298 2023/10/11(284)12:51:10-12:54:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1428-03 2023/10/11(284)13:02:53-13:06:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1434+03 2023/10/11(284)13:08:56-13:12:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1453-10 2023/10/11(284)13:27:58-13:31:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1508-05 2023/10/11(284)13:42:50-13:46:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C318 2023/10/11(284)13:51:50-13:55:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1523+03 2023/10/11(284)13:57:37-14:01:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1535+139 2023/10/11(284)14:09:17-14:12:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1607+26 2023/10/11(284)14:40:44-14:44:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1623-228 2023/10/11(284)14:58:14-15:01:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1631-222 2023/10/11(284)15:06:44-15:10:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1638-025 2023/10/11(284)15:12:21-15:15:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1644-106 2023/10/11(284)15:19:16-15:22:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1650+004 2023/10/11(284)15:24:37-15:28:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1656+053 2023/10/11(284)15:30:08-15:33:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1712-033 2023/10/11(284)15:46:38-15:50:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1730-13 2023/10/11(284)16:04:40-16:08:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1759+13 2023/10/11(284)16:32:59-16:36:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1819-096 2023/10/11(284)16:53:58-16:57:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1830-210 2023/10/11(284)17:05:13-17:08:39JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1848-245 2023/10/11(284)17:22:58-17:26:24JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

