




T20231003062028




BLK: 5,SNR1: 0.48411 ,SNR2: 2.3032




Frequency (Hz)

F20231003062029




BLK: 5,SNR1:-0.26052E-01,SNR2: 2.1657





Frequency (Hz)


0713-024 2023/10/02 21.37UT TOYOKAWA-FUJI



T20231003062028





BLK: 5,SNR1: 0.22499 ,SNR2: 1.9547




Frequency (Hz)

K20231003062025




BLK: 5,SNR1: 2.7762 ,SNR2: 7.1159





Frequency (Hz)


0713-024 2023/10/02 21.37UT TOYOKAWA-KISO





F20231003062029




No.Good Data




K20231003062025




No.Good Data





0713-024 2023/10/02 21.37UT FUJI -KISO







BLK: 4,SNR1: 0.41925 ,SNR2: 1.2513





BLK: 4,SNR1:-0.34339E-01,SNR2: 1.3537




0723+10 2023/10/02 21.54UT TOYOKAWA-FUJI



T20231003063039





BLK: 1,SNR1: 0.84715E-01,SNR2: 0.56889




Frequency (Hz)

K20231003063037




BLK: 1,SNR1: 1.9144 ,SNR2: 13.864




Frequency (Hz)


0723+10 2023/10/02 21.54UT TOYOKAWA-KISO



F20231003063040





BLK: 9,SNR1: 1.2991 ,SNR2: 1.8169




Frequency (Hz)

K20231003063037




BLK: 9,SNR1: 1.0432 ,SNR2: 3.0472





Frequency (Hz)


0723+10 2023/10/02 21.54UT FUJI -KISO



T20231003064053





BLK: 5,SNR1:-0.23321E-01,SNR2: 0.35770




Frequency (Hz)

F20231003064054




BLK: 5,SNR1: 7.9018 ,SNR2: 15.765




Frequency (Hz)


0732+33 2023/10/02 21.71UT TOYOKAWA-FUJI



T20231003064053





BLK: 6,SNR1: 0.87862E-01,SNR2: 0.57856




Frequency (Hz)

K20231003064050




BLK: 6,SNR1: 2.6228 ,SNR2: 9.4249





Frequency (Hz)

0732+33 2023/10/02 21.71UT TOYOKAWA-KISO






F20231003064054





BLK: 9,SNR1: 4.1901 ,SNR2: 11.753




Frequency (Hz)

K20231003064050




BLK: 9,SNR1: 0.29598 ,SNR2: 4.7263





Frequency (Hz)


0732+33 2023/10/02 21.71UT FUJI -KISO



T20231003064856




BLK: 4,SNR1: 0.67743E-01,SNR2: 0.83038




Frequency (Hz)

0741-06 2023/10/02 21.84UT TOYOKAWA-FUJI


F20231003064857





BLK: 4,SNR1:-0.97162E-02,SNR2: 3.4486




Frequency (Hz)



T20231003064856





BLK: 4,SNR1: 0.16336 ,SNR2: 1.1702




Frequency (Hz)

0741-06 2023/10/02 21.84UT TOYOKAWA-KISO


K20231003064853





BLK: 4,SNR1: 1.0569 ,SNR2: 10.389





Frequency (Hz)







0741-06 2023/10/02 21.84UT FUJI -KISO







BLK: 6,SNR1: 0.28425 ,SNR2: 1.0584





BLK: 6,SNR1: 0.78068E-01,SNR2: 0.93998




3C190 2023/10/02 22.13UT TOYOKAWA-FUJI



T20231003070615




BLK: 9,SNR1: 0.22969 ,SNR2: 0.70716




Frequency (Hz)

3C190 2023/10/02 22.13UT TOYOKAWA-KISO


K20231003070613





BLK: 9,SNR1: 1.4427 ,SNR2: 5.5172




Frequency (Hz)



F20231003070616





BLK: 8,SNR1:-0.64849E-02,SNR2: 0.81688




Frequency (Hz)

K20231003070613




BLK: 8,SNR1: 1.3780 ,SNR2: 8.9124





Frequency (Hz)


3C190 2023/10/02 22.13UT FUJI -KISO



T20231003071839





BLK:18,SNR1: 1.9582 ,SNR2: 10.147




Frequency (Hz)

F20231003071840




BLK:18,SNR1: 1.1600 ,SNR2: 8.6979









Frequency (Hz)


3C196 2023/10/02 22.34UT TOYOKAWA-FUJI










3C196 2023/10/02 22.34UT TOYOKAWA-KISO



F20231003071840





BLK:15,SNR1: 0.93270 ,SNR2: 7.3715




Frequency (Hz)

3C196 2023/10/02 22.34UT FUJI -KISO


K20231003071836





BLK:15,SNR1: 8.3345 ,SNR2: 61.242




Frequency (Hz)



T20231003072949




BLK: 8,SNR1: 0.65090 ,SNR2: 3.1555




Frequency (Hz)

F20231003072950




BLK: 8,SNR1: 3.8879 ,SNR2: 15.861




Frequency (Hz)


0821+394 2023/10/02 22.53UT TOYOKAWA-FUJI



T20231003072949





BLK: 7,SNR1: 0.10120 ,SNR2: 0.41412




Frequency (Hz)

K20231003072946




BLK: 7,SNR1: 2.7715 ,SNR2: 10.040





Frequency (Hz)


0821+394 2023/10/02 22.53UT TOYOKAWA-KISO



F20231003072950





BLK: 7,SNR1: 3.1531 ,SNR2: 14.363




Frequency (Hz)

K20231003072946




BLK: 7,SNR1:-0.13989E-01,SNR2: 0.32390






Frequency (Hz)




0821+394 2023/10/02 22.53UT FUJI -KISO




T20231003074635





F20231003074636




0839-071 2023/10/02 22.80UT TOYOKAWA-FUJI



T20231003074635




BLK: 7,SNR1: 8.6887 ,SNR2: 37.627




Frequency (Hz)

K20231003074633




BLK: 7,SNR1: 0.81220 ,SNR2: 4.1478





Frequency (Hz)


0839-071 2023/10/02 22.80UT TOYOKAWA-KISO





F20231003074636




BLK: 9,SNR1: 0.21215 ,SNR2: 3.1184




K20231003074633



BLK: 9,SNR1: 0.46901 ,SNR2: 1.8847




0839-071 2023/10/02 22.80UT FUJI -KISO






T20231003075736




BLK: 7,SNR1: 0.42555 ,SNR2: 2.1533




Frequency (Hz)

F20231003075737




BLK: 7,SNR1:-0.12992 ,SNR2: 0.48425




Frequency (Hz)


3C208 2023/10/02 22.99UT TOYOKAWA-FUJI



T20231003075736





BLK: 9,SNR1: 1.0300 ,SNR2: 2.9365




Frequency (Hz)

3C208 2023/10/02 22.99UT TOYOKAWA-KISO


K20231003075733





BLK: 9,SNR1: 1.1340 ,SNR2: 6.5343




Frequency (Hz)



F20231003075737





BLK: 4,SNR1:-0.68763E-01,SNR2: 0.73993




Frequency (Hz)

3C208 2023/10/02 22.99UT FUJI -KISO


K20231003075733





BLK: 4,SNR1: 1.1782 ,SNR2: 7.4822




Frequency (Hz)



T20231003081417





BLK: 7,SNR1: 0.32284E-01,SNR2: 0.16855




Frequency (Hz)

3C216 2023/10/02 23.27UT TOYOKAWA-FUJI


F20231003081418




BLK: 7,SNR1: 1.1200 ,SNR2: 7.8966




Frequency (Hz)



T20231003081417





BLK: 4,SNR1:-0.28899E-01,SNR2: 0.18596




Frequency (Hz)

K20231003081415




BLK: 4,SNR1: 1.7150 ,SNR2: 8.4208





Frequency (Hz)


3C216 2023/10/02 23.27UT TOYOKAWA-KISO



F20231003081418





BLK: 6,SNR1: 2.8347 ,SNR2: 12.972




Frequency (Hz)

3C216 2023/10/02 23.27UT FUJI -KISO


K20231003081415




BLK: 6,SNR1: 0.48574 ,SNR2: 3.2918





Frequency (Hz)







BLK:13,SNR1: 0.12005 ,SNR2: 1.1348







BLK:13,SNR1: 0.14772 ,SNR2: 0.94006




0926+117 2023/10/02 23.58UT TOYOKAWA-FUJI







0926+117 2023/10/02 23.58UT TOYOKAWA-KISO






F20231003083308





BLK:12,SNR1: 0.91278 ,SNR2: 1.6933




Frequency (Hz)

K20231003083305




BLK:12,SNR1: 0.79555 ,SNR2: 5.8868





Frequency (Hz)


0926+117 2023/10/02 23.58UT FUJI -KISO



T20231003084052





BLK:10,SNR1: 0.78263 ,SNR2: 2.1727




Frequency (Hz)

F20231003084053




BLK:10,SNR1: 0.84159 ,SNR2: 3.3005





Frequency (Hz)


3C222 2023/10/02 23.71UT TOYOKAWA-FUJI



T20231003084052




BLK:13,SNR1: 1.3884 ,SNR2: 3.6543





3C222 2023/10/02 23.71UT TOYOKAWA-KISO


K20231003084050




BLK:13,SNR1: 0.36494 ,SNR2: 3.1321





F20231003084053




BLK: 8,SNR1: 1.4380 ,SNR2: 8.4739




K20231003084050





BLK: 8,SNR1: 1.5543 ,SNR2: 5.2800




3C222 2023/10/02 23.71UT FUJI -KISO




T20231003084753




BLK:10,SNR1: 0.67228E-01,SNR2: 0.91723




F20231003084754





BLK:10,SNR1: 2.1792 ,SNR2: 7.5267




0941-08 2023/10/02 23.83UT TOYOKAWA-FUJI



T20231003084753




BLK: 6,SNR1: 0.78479E-01,SNR2: 1.5593





0941-08 2023/10/02 23.83UT TOYOKAWA-KISO


K20231003084751




BLK: 6,SNR1: 1.5533 ,SNR2: 5.0161



F20231003084754




BLK:19,SNR1: 2.3612 ,SNR2: 8.2203




Frequency (Hz)

0941-08 2023/10/02 23.83UT FUJI -KISO


K20231003084751





BLK:19,SNR1: 0.28765 ,SNR2: 1.2375




Frequency (Hz)





T20231003091215




BLK:20,SNR1:-0.14602E-01,SNR2: 0.68275E-01




F20231003091216



BLK:20,SNR1:-0.97309E-02,SNR2: 0.35029E-01





3C237 2023/10/03 0.23UT TOYOKAWA-FUJI







T20231003091215




BLK:20,SNR1:-0.14563E-01,SNR2: 0.71359E-01




K20231003091212





BLK:20,SNR1: 1.5714 ,SNR2: 2.3800




3C237 2023/10/03 0.23UT TOYOKAWA-KISO




F20231003091216




BLK:26,SNR1:-0.96956E-02,SNR2: 0.35651E-01




K20231003091212





BLK:26,SNR1: 1.5694 ,SNR2: 2.3582




3C237 2023/10/03 0.23UT FUJI -KISO



T20231003091831





BLK: 7,SNR1:-0.45737E-02,SNR2: 0.34094E-01




Frequency (Hz)

F20231003091832




BLK: 7,SNR1: 0.34822 ,SNR2: 1.9146





Frequency (Hz)


1011+110 2023/10/03 0.34UT TOYOKAWA-FUJI



T20231003091831





BLK:10,SNR1:-0.74732E-02,SNR2: 0.34941E-01




Frequency (Hz)

K20231003091828




BLK:10,SNR1:-0.62909E-02,SNR2: 0.26043E-01





Frequency (Hz)


1011+110 2023/10/03 0.34UT TOYOKAWA-KISO





F20231003091832




BLK:10,SNR1: 0.12982 ,SNR2: 1.3987




K20231003091828





BLK:10,SNR1:-0.60637E-02,SNR2: 0.26830E-01




1011+110 2023/10/03 0.34UT FUJI -KISO



T20231003092612





BLK: 5,SNR1:-0.14661E-01,SNR2: 0.25769E-01




Frequency (Hz)

3C241 2023/10/03 0.46UT TOYOKAWA-FUJI


F20231003092613





BLK: 5,SNR1: 0.64401 ,SNR2: 7.4299




Frequency (Hz)



T20231003092612





BLK:11,SNR1:-0.10907E-01,SNR2: 0.26401E-01




Frequency (Hz)

K20231003092609




BLK:11,SNR1: 0.17178E-01,SNR2: 1.3912






Frequency (Hz)




3C241 2023/10/03 0.46UT TOYOKAWA-KISO




F20231003092613



K20231003092609





3C241 2023/10/03 0.46UT FUJI -KISO







T20231003093742




BLK: 5,SNR1:-0.10315E-01,SNR2: 0.25882E-01




F20231003093742





BLK: 5,SNR1: 0.13354 ,SNR2: 4.0299




1031-11 2023/10/03 0.66UT TOYOKAWA-FUJI



T20231003093742





BLK: 4,SNR1:-0.10038E-01,SNR2: 0.27671E-01




Frequency (Hz)

K20231003093740




BLK: 4,SNR1: 0.12133 ,SNR2: 2.4695




Frequency (Hz)


1031-11 2023/10/03 0.66UT TOYOKAWA-KISO




F20231003093742




BLK: 4,SNR1: 0.57422 ,SNR2: 1.7170




K20231003093740





BLK: 4,SNR1: 0.70600 ,SNR2: 6.9453




1031-11 2023/10/03 0.66UT FUJI -KISO





T20231003094215




BLK: 9,SNR1:-0.20436E-04,SNR2: 0.20641E-01




F20231003094215





BLK: 9,SNR1: 0.62906 ,SNR2: 2.9063




1035-058 2023/10/03 0.73UT TOYOKAWA-FUJI




T20231003094215




BLK:14,SNR1:-0.61463E-02,SNR2: 0.79057E-01




K20231003094212




BLK:14,SNR1: 0.88287E-01,SNR2: 1.0755




1035-058 2023/10/03 0.73UT TOYOKAWA-KISO





F20231003094215




BLK:16,SNR1: 0.13461 ,SNR2: 2.2877




K20231003094212




BLK:16,SNR1: 0.53356E-01,SNR2: 0.31053




1035-058 2023/10/03 0.73UT FUJI -KISO





T20231003095128




BLK:12,SNR1:-0.20869E-01,SNR2: 0.17771E-01




F20231003095129





BLK:12,SNR1:-0.20739E-02,SNR2: 0.17282E-01




1044-008 2023/10/03 0.89UT TOYOKAWA-FUJI





T20231003095128




BLK: 3, SNR1: 0.14632 , SNR2: 1.4396




K20231003095125



BLK: 3, SNR1: 0.14261 , SNR2: 1.1075





1044-008 2023/10/03 0.89UT TOYOKAWA-KISO






F20231003095129





BLK: 4,SNR1: 1.9060 ,SNR2: 3.5475




Frequency (Hz)

K20231003095125




BLK: 4,SNR1: 0.26714 ,SNR2: 3.5809




Frequency (Hz)


1044-008 2023/10/03 0.89UT FUJI -KISO




T20231003100232




BLK: 7,SNR1: 0.39109 ,SNR2: 2.7850




F20231003100233





BLK: 7,SNR1: 0.26311 ,SNR2: 4.6018




1055+01 2023/10/03 1.07UT TOYOKAWA-FUJI



T20231003100232





BLK:18,SNR1: 0.34878 ,SNR2: 3.1239




1055+01 2023/10/03 1.07UT TOYOKAWA-KISO


K20231003100229




BLK:18,SNR1: 0.69082 ,SNR2: 2.6605




Frequency (Hz)



F20231003100233





BLK: 5,SNR1: 0.58591 ,SNR2: 7.9757





1055+01 2023/10/03 1.07UT FUJI -KISO


K20231003100229




BLK: 5,SNR1: 0.26579E-01,SNR2: 0.84018





T20231003101350




BLK: 8,SNR1: 0.19384 ,SNR2: 1.0578




F20231003101351





BLK: 8,SNR1: 0.65037 ,SNR2: 5.8976




1107+109 2023/10/03 1.26UT TOYOKAWA-FUJI





T20231003101350




BLK: 5,SNR1: 0.21494 ,SNR2: 2.6070




K20231003101347





BLK: 5,SNR1: 0.28939 ,SNR2: 1.9289




1107+109 2023/10/03 1.26UT TOYOKAWA-KISO





F20231003101351




BLK: 9,SNR1: 0.79864 ,SNR2: 3.7523




K20231003101347




BLK: 9,SNR1: 0.66210 ,SNR2: 2.5301




1107+109 2023/10/03 1.26UT FUJI -KISO



T20231003102327




BLK:16,SNR1: 1.7500 ,SNR2: 7.9109




Frequency (Hz)

3C255 2023/10/03 1.42UT TOYOKAWA-FUJI


F20231003102328



BLK:16,SNR1: 0.68363 ,SNR2: 7.5568




Frequency (Hz)






T20231003102327





BLK:19,SNR1: 1.6992 ,SNR2: 11.374





3C255 2023/10/03 1.42UT TOYOKAWA-KISO



K20231003102324




BLK:19,SNR1: 7.3675 ,SNR2: 18.326



F20231003102328





BLK:11,SNR1: 1.5506 ,SNR2: 7.5531




Frequency (Hz)

3C255 2023/10/03 1.42UT FUJI -KISO


K20231003102324





BLK:11,SNR1: 3.4837 ,SNR2: 14.438




Frequency (Hz)



T20231003104725





BLK:11,SNR1: 1.2160 ,SNR2: 7.7364




Frequency (Hz)

3C263.1 2023/10/03 1.82UT TOYOKAWA-FUJI


F20231003104726





BLK:11,SNR1: 0.24350 ,SNR2: 1.3210




Frequency (Hz)



T20231003104725





BLK:12,SNR1: 1.7596 ,SNR2: 6.5520





3C263.1 2023/10/03 1.82UT TOYOKAWA-KISO


K20231003104722




BLK:12,SNR1: 0.31355 ,SNR2: 1.4102




F20231003104726




BLK: 9,SNR1: 0.49905 ,SNR2: 1.8079




K20231003104722





BLK: 9,SNR1: 0.50002 ,SNR2: 1.8848




3C263.1 2023/10/03 1.82UT FUJI -KISO




T20231003105352




BLK: 9,SNR1: 0.10849 ,SNR2: 2.9928




F20231003105352





BLK: 9,SNR1:-0.68142E-02,SNR2: 0.82348




3C267 2023/10/03 1.93UT TOYOKAWA-FUJI



T20231003105352





BLK: 7,SNR1: 1.4664 ,SNR2: 19.649





3C267 2023/10/03 1.93UT TOYOKAWA-KISO


K20231003105349




BLK: 7,SNR1: 0.70111 ,SNR2: 3.7292



F20231003105352





BLK: 6,SNR1: 0.34048E-01,SNR2: 0.81420





3C267 2023/10/03 1.93UT FUJI -KISO

K20231003105349





BLK: 6,SNR1: 0.69036E-01,SNR2: 1.0159






T20231003111306





BLK: 4,SNR1: 0.15391 ,SNR2: 0.19803




Frequency (Hz)

F20231003111306




BLK: 4,SNR1:-0.16610 ,SNR2: 0.49817




Frequency (Hz)


1206+439 2023/10/03 2.25UT TOYOKAWA-FUJI





T20231003111306




BLK: 3,SNR1: 0.73556E-01,SNR2: 0.58225




K20231003111304




BLK: 3,SNR1: 0.90746 ,SNR2: 3.9932




1206+439 2023/10/03 2.25UT TOYOKAWA-KISO





F20231003111306




BLK: 4,SNR1: 2.0579 ,SNR2: 3.2919




K20231003111304




BLK: 4,SNR1: 0.38437 ,SNR2: 2.0492




1206+439 2023/10/03 2.25UT FUJI -KISO





T20231003113257




BLK:15,SNR1: 3.0203 ,SNR2: 12.179




F20231003113257




BLK:15,SNR1: 12.505 ,SNR2: 20.235




3C273 2023/10/03 2.58UT TOYOKAWA-FUJI



T20231003113257




BLK:17,SNR1: 2.9416 ,SNR2: 12.110





3C273 2023/10/03 2.58UT TOYOKAWA-KISO


K20231003113254




BLK:17,SNR1: 4.0530 ,SNR2: 7.7952




F20231003113257




BLK:15,SNR1: 10.299 ,SNR2: 21.880




K20231003113254




BLK:15,SNR1: 7.4123 ,SNR2: 11.802




3C273 2023/10/03 2.58UT FUJI -KISO




T20231003115956




BLK:32,SNR1: 68.662 ,SNR2: 127.88




F20231003115957




BLK:32,SNR1: 61.280 ,SNR2: 148.26




3C279 2023/10/03 3.03UT TOYOKAWA-FUJI




T20231003115956




BLK:25,SNR1: 89.367 ,SNR2: 166.42




K20231003115954



BLK:25,SNR1: 0.59701 ,SNR2: 7.1756





3C279 2023/10/03 3.03UT TOYOKAWA-KISO







F20231003115957




BLK:22,SNR1: 91.357 ,SNR2: 185.54




K20231003115954





BLK:22,SNR1: 0.62772 ,SNR2: 3.9297




3C279 2023/10/03 3.03UT FUJI -KISO



T20231003121945





BLK: 9,SNR1: 9.1167 ,SNR2: 42.157




Frequency (Hz)

F20231003121946




BLK: 9,SNR1: 7.4365 ,SNR2: 11.567




Frequency (Hz)


1313+453 2023/10/03 3.36UT TOYOKAWA-FUJI



T20231003121945




BLK: 6,SNR1: 13.731 ,SNR2: 60.755





1313+453 2023/10/03 3.36UT TOYOKAWA-KISO


K20231003121942




BLK: 6,SNR1: 0.42889 ,SNR2: 2.4659




F20231003121946




BLK: 9,SNR1: 1.6800 ,SNR2: 4.0559




K20231003121942





BLK: 9,SNR1: 0.40248 ,SNR2: 2.4874




1313+453 2023/10/03 3.36UT FUJI -KISO



T20231003122951




BLK: 5,SNR1: 0.26856 ,SNR2: 1.0187




Frequency (Hz)

1323+32 2023/10/03 3.53UT TOYOKAWA-FUJI


F20231003122951





BLK: 5,SNR1: 0.52693E-01,SNR2: 1.5559




Frequency (Hz)




T20231003122951




BLK: 9,SNR1: 0.87617E-01,SNR2: 0.47038




K20231003122948




BLK: 9,SNR1: 0.19359 ,SNR2: 0.69079




1323+32 2023/10/03 3.53UT TOYOKAWA-KISO



F20231003122951




BLK: 4,SNR1:-0.94593E-02,SNR2: 3.6271





1323+32 2023/10/03 3.53UT FUJI -KISO



K20231003122948




BLK: 4,SNR1: 0.91445 ,SNR2: 3.6969





T20231003123441




BLK:21,SNR1: 44.672 ,SNR2: 83.405




F20231003123441



BLK:21,SNR1: 83.144 ,SNR2: 100.46





3C286 2023/10/03 3.61UT TOYOKAWA-FUJI








T20231003123441




BLK:30,SNR1: 43.482 ,SNR2: 81.183




K20231003123438





BLK:30,SNR1: 8.6909 ,SNR2: 21.395




3C286 2023/10/03 3.61UT TOYOKAWA-KISO



F20231003123441





BLK:13,SNR1: 85.187 ,SNR2: 102.93





3C286 2023/10/03 3.61UT FUJI -KISO



K20231003123438




BLK:13,SNR1: 10.977 ,SNR2: 27.010



T20231003125108




BLK:14,SNR1: 0.42178 ,SNR2: 4.1323





1345+12 2023/10/03 3.88UT TOYOKAWA-FUJI


F20231003125108




BLK:14,SNR1: 7.1603 ,SNR2: 11.317



T20231003125108




BLK:26,SNR1: 0.62545 ,SNR2: 5.0937









1345+12 2023/10/03 3.88UT TOYOKAWA-KISO

K20231003125105




BLK:26,SNR1: 0.32471 ,SNR2: 2.5173







1345+12 2023/10/03 3.88UT FUJI -KISO




T20231003130128




BLK:10,SNR1: 0.63660 ,SNR2: 6.7384




F20231003130129




BLK:10,SNR1: 1.7375 ,SNR2: 3.5347




1355+01 2023/10/03 4.05UT TOYOKAWA-FUJI




T20231003130128




BLK:22,SNR1: 0.69204 ,SNR2: 7.3399




K20231003130125




BLK:22,SNR1: 0.64273 ,SNR2: 1.2951




1355+01 2023/10/03 4.05UT TOYOKAWA-KISO



F20231003130129




BLK:11,SNR1:-0.59902E-01,SNR2: 1.8742





1355+01 2023/10/03 4.05UT FUJI -KISO

K20231003130125




BLK:11,SNR1: 0.40511 ,SNR2: 1.9178







T20231003132239




BLK:24,SNR1: 1.1080 ,SNR2: 3.3428




F20231003132240




BLK:24,SNR1: 0.36910 ,SNR2: 2.2041




3C298 2023/10/03 4.41UT TOYOKAWA-FUJI



T20231003132239





BLK:28,SNR1: 0.80452 ,SNR2: 6.2681





3C298 2023/10/03 4.41UT TOYOKAWA-KISO



K20231003132236




BLK:28,SNR1: 0.43176 ,SNR2: 2.3904



F20231003132240





BLK:17,SNR1: 0.58923 ,SNR2: 3.0243





3C298 2023/10/03 4.41UT FUJI -KISO



K20231003132236




BLK:17,SNR1: 0.55067 ,SNR2: 4.8453




T20231003133422




BLK: 7,SNR1: 0.12248 ,SNR2: 0.38039




F20231003133423




BLK: 7,SNR1: 0.44869 ,SNR2: 3.8248




1428-03 2023/10/03 4.60UT TOYOKAWA-FUJI





T20231003133422




BLK: 7,SNR1: 0.44974E-01,SNR2: 0.46001




K20231003133419




BLK: 7,SNR1: 11.414 ,SNR2: 29.155




1428-03 2023/10/03 4.60UT TOYOKAWA-KISO



F20231003133423





BLK:22,SNR1: 0.65130 ,SNR2: 4.3190





1428-03 2023/10/03 4.60UT FUJI -KISO



K20231003133419




BLK:22,SNR1: 9.7959 ,SNR2: 15.470





T20231003134025




BLK: 7,SNR1: 0.54785 ,SNR2: 1.6032




F20231003134025




BLK: 7,SNR1: 0.45899E-01,SNR2: 1.9987




1434+03 2023/10/03 4.70UT TOYOKAWA-FUJI




T20231003134025




BLK: 5,SNR1: 0.54174 ,SNR2: 2.5538




K20231003134022



BLK: 5,SNR1: 0.25803E-01,SNR2: 0.37158





1434+03 2023/10/03 4.70UT TOYOKAWA-KISO








F20231003134025




BLK: 3,SNR1:-0.34071E-01,SNR2: 2.4366




K20231003134022





BLK: 3,SNR1: 0.58330 ,SNR2: 2.1574




1434+03 2023/10/03 4.70UT FUJI -KISO





T20231003135927




BLK: 4,SNR1: 0.79835E-01,SNR2: 0.27648




F20231003135928





BLK: 4,SNR1: 4.2954 ,SNR2: 4.8244




1453-10 2023/10/03 5.02UT TOYOKAWA-FUJI





T20231003135927




BLK: 4,SNR1: 0.44719E-01,SNR2: 1.0120




K20231003135924





BLK: 4,SNR1: 0.55043 ,SNR2: 4.6600




1453-10 2023/10/03 5.02UT TOYOKAWA-KISO



F20231003135928





BLK: 8,SNR1: 1.2279 ,SNR2: 3.0819





1453-10 2023/10/03 5.02UT FUJI -KISO



K20231003135924




BLK: 8,SNR1: 0.47476 ,SNR2: 1.3349





T20231003141419




BLK: 2,SNR1: 0.28887 ,SNR2: 1.0527




F20231003141420





BLK: 2,SNR1: 0.83782 ,SNR2: 2.5618




1508-05 2023/10/03 5.27UT TOYOKAWA-FUJI





T20231003141419




BLK:10,SNR1: 0.70233 ,SNR2: 2.0285




K20231003141416





BLK:10,SNR1: 1.0420 ,SNR2: 2.3073




1508-05 2023/10/03 5.27UT TOYOKAWA-KISO



F20231003141420





BLK:11,SNR1:-0.10788 ,SNR2: 1.7936





1508-05 2023/10/03 5.27UT FUJI -KISO



K20231003141416




BLK:11,SNR1: 1.5355 ,SNR2: 3.2934





T20231003142320




BLK: 8,SNR1:-0.51879E-01,SNR2: 1.1081




F20231003142320



BLK: 8,SNR1: 5.9809 ,SNR2: 12.413





3C318 2023/10/03 5.42UT TOYOKAWA-FUJI








T20231003142320




BLK: 4,SNR1: 0.59644E-01,SNR2: 1.3164




K20231003142317





BLK: 4,SNR1: 0.35973 ,SNR2: 3.7716




3C318 2023/10/03 5.42UT TOYOKAWA-KISO



F20231003142320





BLK: 7,SNR1: 4.0664 ,SNR2: 12.006





3C318 2023/10/03 5.42UT FUJI -KISO


K20231003142317




BLK: 7,SNR1: 0.77459 ,SNR2: 2.5673




T20231003142906




BLK: 3,SNR1:-0.10577E-01,SNR2: 0.69879




F20231003142907





BLK: 3,SNR1: 0.78178 ,SNR2: 2.5051




1523+03 2023/10/03 5.51UT TOYOKAWA-FUJI





T20231003142906




BLK: 5,SNR1: 0.18717 ,SNR2: 1.3399




K20231003142903







BLK: 5,SNR1: 0.57389E-01,SNR2: 3.1232




1523+03 2023/10/03 5.51UT TOYOKAWA-KISO








1523+03 2023/10/03 5.51UT FUJI -KISO




T20231003144046




BLK: 2,SNR1:-0.49620E-01,SNR2: 0.21603




F20231003144046





BLK: 2,SNR1:-0.33634 ,SNR2: 0.41250




1535+139 2023/10/03 5.71UT TOYOKAWA-FUJI





T20231003144046




BLK: 3,SNR1:-0.89746E-01,SNR2: 0.33770




K20231003144044




BLK: 3,SNR1: 0.33726 ,SNR2: 1.3422




1535+139 2023/10/03 5.71UT TOYOKAWA-KISO





F20231003144046




BLK: 4,SNR1:-0.27990 ,SNR2: 0.17517




K20231003144044



BLK: 4,SNR1: 0.51510 ,SNR2: 3.3062





1535+139 2023/10/03 5.71UT FUJI -KISO







T20231003145110




BLK: 4,SNR1:-0.42089E-01,SNR2: 0.64735




F20231003145111





BLK: 4,SNR1: 3.0313 ,SNR2: 10.356




1545-12 2023/10/03 5.88UT TOYOKAWA-FUJI





T20231003145110




BLK: 2,SNR1: 4.2488 ,SNR2: 12.951




K20231003145107




BLK: 2,SNR1: 0.25927 ,SNR2: 3.7288




1545-12 2023/10/03 5.88UT TOYOKAWA-KISO



F20231003145111





BLK: 5,SNR1: 3.0881 ,SNR2: 10.565





1545-12 2023/10/03 5.88UT FUJI -KISO



K20231003145107




BLK: 5,SNR1: 0.87921E-01,SNR2: 1.6166





T20231003151214




BLK: 6,SNR1: 1.1455 ,SNR2: 5.1912




F20231003151214




BLK: 6,SNR1: 1.4103 ,SNR2: 6.0166




1607+26 2023/10/03 6.23UT TOYOKAWA-FUJI





T20231003151214




BLK: 1,SNR1:-0.42314E-01,SNR2: 1.8598




K20231003151211







BLK: 1,SNR1: 0.33123E-01,SNR2: 0.71987




1607+26 2023/10/03 6.23UT TOYOKAWA-KISO








1607+26 2023/10/03 6.23UT FUJI -KISO




T20231003154351




BLK: 5,SNR1: 6.1964 ,SNR2: 46.749




F20231003154352





BLK: 5,SNR1: 6.1497 ,SNR2: 14.154




1638-025 2023/10/03 6.76UT TOYOKAWA-FUJI





T20231003154351




BLK: 6,SNR1: 15.600 ,SNR2: 83.245




K20231003154349



BLK: 6,SNR1: 0.88628 ,SNR2: 4.7594




1638-025 2023/10/03 6.76UT TOYOKAWA-KISO








F20231003154352




BLK: 6,SNR1: 6.1154 ,SNR2: 13.570




K20231003154349






BLK: 6,SNR1: 0.24864 ,SNR2: 1.9900






1638-025 2023/10/03 6.76UT FUJI -KISO




T20231003155045





F20231003155045




1644-106 2023/10/03 6.87UT TOYOKAWA-FUJI





T20231003155045




BLK: 2,SNR1: 0.20509 ,SNR2: 0.99194




K20231003155043









BLK: 2,SNR1: -0.17113 ,SNR2: 1.1433




1644-106 2023/10/03 6.87UT TOYOKAWA-KISO








1644-106 2023/10/03 6.87UT FUJI -KISO




T20231003155606




BLK: 7,SNR1: 0.14334 ,SNR2: 0.41791




F20231003155607




BLK: 7,SNR1: 101.40 ,SNR2: 190.65




1650+004 2023/10/03 6.96UT TOYOKAWA-FUJI





T20231003155606




BLK: 1,SNR1: 0.52784 ,SNR2: 2.3663




K20231003155604




BLK: 1,SNR1: 0.97163E-01,SNR2: 0.60923




1650+004 2023/10/03 6.96UT TOYOKAWA-KISO





F20231003155607




BLK: 5,SNR1:-0.29642 ,SNR2: 1.0745




K20231003155604





BLK: 5,SNR1: 1.3878 ,SNR2: 8.4398




1650+004 2023/10/03 6.96UT FUJI -KISO




T20231003160138




BLK: 1,SNR1: 0.66834 ,SNR2: 1.7152




F20231003160139





BLK: 1,SNR1: 0.45876E-01,SNR2: 0.28642




1656+053 2023/10/03 7.06UT TOYOKAWA-FUJI













1656+053 2023/10/03 7.06UT TOYOKAWA-KISO



F20231003160139





K20231003160135




1656+053 2023/10/03 7.06UT FUJI -KISO




T20231003161807




BLK: 3,SNR1:-0.18670E-01,SNR2: 0.37113




F20231003161807







BLK: 3,SNR1: 1.2427 ,SNR2: 2.5344




1712-033 2023/10/03 7.33UT TOYOKAWA-FUJI








1712-033 2023/10/03 7.33UT TOYOKAWA-KISO





F20231003161807




BLK: 4,SNR1: 5.1608 ,SNR2: 26.482




K20231003161804





BLK: 4,SNR1:-0.96542E-01,SNR2: 0.24520




1712-033 2023/10/03 7.33UT FUJI -KISO



T20231003163609




BLK: 3,SNR1: 0.56946E-01,SNR2: 0.45818




Frequency (Hz)

F20231003163609




BLK: 3,SNR1: 0.75750 ,SNR2: 3.0691





Frequency (Hz)


1730-13 2023/10/03 7.63UT TOYOKAWA-FUJI



T20231003163609





BLK: 2,SNR1:-0.11652 ,SNR2: 0.34330




Frequency (Hz)

K20231003163606




BLK: 2,SNR1: 0.16926E-01,SNR2: 0.52697





Frequency (Hz)


1730-13 2023/10/03 7.63UT TOYOKAWA-KISO





F20231003163609




BLK: 4,SNR1: 0.47179 ,SNR2: 2.3781




K20231003163606



BLK: 4,SNR1: 0.10520E-01,SNR2: 0.67892





1730-13 2023/10/03 7.63UT FUJI -KISO








T20231003165334




BLK:11,SNR1: 0.11178 ,SNR2: 0.35746




F20231003165334





BLK:11,SNR1: 546.99 ,SNR2: 2095.5




1748+031 2023/10/03 7.92UT TOYOKAWA-FUJI





T20231003165334




BLK: 2,SNR1: 0.85937 ,SNR2: 2.2609




K20231003165331




BLK: 2,SNR1:-0.13445 ,SNR2: 0.27492





1748+031 2023/10/03 7.92UT TOYOKAWA-KISO






BLK:11,SNR1: 679.47 ,SNR2: 1916.0



BLK:11,SNR1: 0.53083 ,SNR2: 4.1689



1748+031 2023/10/03 7.92UT FUJI -KISO

