



T20231024060105




BLK:10,SNR1: 1.5746 ,SNR2: 17.159




Frequency (Hz)

F20231024060106




BLK:10,SNR1: 1.7164 ,SNR2: 5.5662




Frequency (Hz)


0816-108 2023/10/23 21.05UT TOYOKAWA-FUJI



T20231024060105




BLK: 5, SNR1: 3.7920 ,SNR2: 20.042




Frequency (Hz)

K20231024060102




BLK: 5, SNR1: 2.1887 ,SNR2: 6.2778




Frequency (Hz)


0816-108 2023/10/23 21.05UT TOYOKAWA-KISO



F20231024060106





BLK:10,SNR1: 2.6266 ,SNR2: 8.1591




Frequency (Hz)

K20231024060102





BLK:10,SNR1: 2.2157 ,SNR2: 8.6143





Frequency (Hz)

0816-108 2023/10/23 21.05UT FUJI -KISO







BLK: 5, SNR1: 0.14302 ,SNR2: 3.1254





BLK: 5, SNR1: 0.46453 ,SNR2: 1.2432






0822-096 2023/10/23 21.13UT TOYOKAWA-FUJI







BLK: 7,SNR1: 0.89296E-01,SNR2: 0.53990




BLK: 7,SNR1: 4.9290 ,SNR2: 14.207




0822-096 2023/10/23 21.13UT TOYOKAWA-KISO



F20231024060621





BLK: 2,SNR1: 0.28285E-01,SNR2: 0.41929E-01




Frequency (Hz)

K20231024060617




BLK: 2,SNR1: 2.6492 ,SNR2: 12.877





Frequency (Hz)


0822-096 2023/10/23 21.13UT FUJI -KISO



T20231024061418





BLK: 7, SNR1: 2.5272 ,SNR2: 16.452




Frequency (Hz)

F20231024061419




BLK: 7, SNR1: 1.8482 ,SNR2: 7.4531





Frequency (Hz)


0830-118 2023/10/23 21.27UT TOYOKAWA-FUJI



T20231024061418





BLK: 7,SNR1: 7.6402 ,SNR2: 36.589




Frequency (Hz)

K20231024061415




BLK: 7,SNR1: 2.2746 ,SNR2: 6.1723





Frequency (Hz)

0830-118 2023/10/23 21.27UT TOYOKAWA-KISO






F20231024061419





BLK: 5,SNR1: 4.8869 ,SNR2: 11.997




Frequency (Hz)

K20231024061415




BLK: 5,SNR1: 1.7923 ,SNR2: 5.7274





Frequency (Hz)


0830-118 2023/10/23 21.27UT FUJI -KISO



T20231024062401





BLK: 6,SNR1: 0.21822 ,SNR2: 1.6863




Frequency (Hz)

F20231024062402




BLK: 6,SNR1: 0.10294E-01,SNR2: 2.1886





Frequency (Hz)


0839-071 2023/10/23 21.43UT TOYOKAWA-FUJI



T20231024062401





BLK: 6,SNR1: 0.19623 ,SNR2: 2.4529




Frequency (Hz)

K20231024062358




BLK: 6,SNR1: 3.0073 ,SNR2: 13.058




Frequency (Hz)


0839-071 2023/10/23 21.43UT TOYOKAWA-KISO



F20231024062402





BLK: 4,SNR1: 1.1955 ,SNR2: 2.5432




Frequency (Hz)

K20231024062358




BLK: 4,SNR1: 0.66745 ,SNR2: 2.4523




Frequency (Hz)


0839-071 2023/10/23 21.43UT FUJI -KISO



T20231024063502





BLK: 1, SNR1: 0.15243 , SNR2: 0.72771




Frequency (Hz)

3C208 2023/10/23 21.61UT TOYOKAWA-FUJI


F20231024063503




BLK: 1, SNR1: 1.3315 , SNR2: 10.455




Frequency (Hz)



T20231024063502





BLK: 1, SNR1: 0.32007 ,SNR2: 0.11342




Frequency (Hz)

3C208 2023/10/23 21.61UT TOYOKAWA-KISO


K20231024063459





BLK: 1, SNR1: 0.80897 ,SNR2: 6.8311




Frequency (Hz)



F20231024063503




BLK: 8,SNR1: 1.7099 ,SNR2: 5.2622




Frequency (Hz)

3C208 2023/10/23 21.61UT FUJI -KISO


K20231024063459





BLK: 8,SNR1: 1.0180 ,SNR2: 3.2611




Frequency (Hz)



T20231024065628




BLK: 8,SNR1: 0.19732 ,SNR2: 1.2615




Frequency (Hz)

0912-132 2023/10/23 21.97UT TOYOKAWA-FUJI


F20231024065629



BLK: 8,SNR1: 0.96282E-01,SNR2: 4.4458




Frequency (Hz)






T20231024065628




BLK: 4,SNR1: 0.33813 ,SNR2: 1.9882





0912-132 2023/10/23 21.97UT TOYOKAWA-KISO


K20231024065625




BLK: 4,SNR1: 3.9794 ,SNR2: 12.140



F20231024065629





BLK: 7,SNR1: 0.86796 ,SNR2: 2.9736





0912-132 2023/10/23 21.97UT FUJI -KISO



K20231024065625




BLK: 7,SNR1: 1.1823 ,SNR2: 5.5711



T20231024070905





BLK: 5,SNR1: 16.872 ,SNR2: 83.571




Frequency (Hz)

F20231024070906




BLK: 5,SNR1: 1.0607 ,SNR2: 8.7616





Frequency (Hz)


0923+392 2023/10/23 22.18UT TOYOKAWA-FUJI



T20231024070905





BLK: 2,SNR1: 0.23045 ,SNR2: 0.90257




Frequency (Hz)

K20231024070902




BLK: 2,SNR1: 1.7076 ,SNR2: 7.9979





Frequency (Hz)


0923+392 2023/10/23 22.18UT TOYOKAWA-KISO



F20231024070906





BLK: 1,SNR1: 1.9476 ,SNR2: 8.5891




Frequency (Hz)

K20231024070902




BLK: 1,SNR1: 0.68213E-02,SNR2: 0.38970





Frequency (Hz)


0923+392 2023/10/23 22.18UT FUJI -KISO



T20231024071818





BLK: 3,SNR1: 0.28793 ,SNR2: 0.86666




Frequency (Hz)

F20231024071818




BLK: 3,SNR1: 0.65472 ,SNR2: 6.4764




Frequency (Hz)


3C222 2023/10/23 22.33UT TOYOKAWA-FUJI



T20231024071818





BLK: 4,SNR1: 0.70939E-01,SNR2: 1.0736




Frequency (Hz)

K20231024071815




BLK: 4,SNR1: 4.1336 ,SNR2: 8.7595





Frequency (Hz)


3C222 2023/10/23 22.33UT TOYOKAWA-KISO



F20231024071818





BLK: 5,SNR1: 0.38616 ,SNR2: 4.8135




Frequency (Hz)

K20231024071815




BLK: 5,SNR1: 1.1141 ,SNR2: 3.1043





Frequency (Hz)

3C222 2023/10/23 22.33UT FUJI -KISO






T20231024072519





BLK: 2,SNR1: 0.29239 ,SNR2: 0.92276




Frequency (Hz)

F20231024072520




BLK: 2,SNR1: 0.73371E-01,SNR2: 4.2917




Frequency (Hz)


0941-08 2023/10/23 22.45UT TOYOKAWA-FUJI



T20231024072519





BLK: 2,SNR1:-0.60414E-01,SNR2: 0.42163E-01





0941-08 2023/10/23 22.45UT TOYOKAWA-KISO


K20231024072516




BLK: 2,SNR1: 2.7903 ,SNR2: 9.4574



F20231024072520





BLK: 4,SNR1: 0.69172 ,SNR2: 1.8991




Frequency (Hz)

K20231024072516




BLK: 4,SNR1: 2.5545 ,SNR2: 6.5968





Frequency (Hz)


0941-08 2023/10/23 22.45UT FUJI -KISO



T20231024073340





BLK: 3,SNR1: 0.67969E-01,SNR2: 1.5049




Frequency (Hz)

F20231024073341




BLK: 3,SNR1: 3.4392 ,SNR2: 10.663





Frequency (Hz)


3C230 2023/10/23 22.59UT TOYOKAWA-FUJI



T20231024073340





BLK: 4,SNR1: 0.18117 ,SNR2: 1.1453




Frequency (Hz)

K20231024073337




BLK: 4,SNR1: 0.14679 ,SNR2: 0.75024





Frequency (Hz)


3C230 2023/10/23 22.59UT TOYOKAWA-KISO



F20231024073341





BLK: 4,SNR1: 3.2849 ,SNR2: 8.2244




Frequency (Hz)

3C230 2023/10/23 22.59UT FUJI -KISO


K20231024073337





BLK: 4,SNR1: 0.44774 ,SNR2: 1.3186




Frequency (Hz)



T20231024074941





BLK: 9,SNR1: 0.19211 ,SNR2: 3.1852




Frequency (Hz)

3C237 2023/10/23 22.86UT TOYOKAWA-FUJI


F20231024074942





BLK: 9,SNR1: 0.24404 ,SNR2: 1.3369




Frequency (Hz)



T20231024074941





BLK: 9,SNR1: 0.55312 ,SNR2: 2.2758




Frequency (Hz)

3C237 2023/10/23 22.86UT TOYOKAWA-KISO


K20231024074938



BLK: 9,SNR1: 0.45581E-01,SNR2: 1.8069





Frequency (Hz)






F20231024074942





BLK: 4, SNR1: 0.19556 , SNR2: 1.2484




Frequency (Hz)

3C237 2023/10/23 22.86UT FUJI -KISO


K20231024074938




BLK: 4, SNR1: 0.19584 , SNR2: 1.1682




Frequency (Hz)




T20231024075557




BLK: 3,SNR1:-0.34467E-02,SNR2: 1.0499




F20231024075558




BLK: 3,SNR1: 1.9765 ,SNR2: 4.5452




1011+110 2023/10/23 22.96UT TOYOKAWA-FUJI



T20231024075557




BLK: 2,SNR1: 0.35872 ,SNR2: 1.1209





1011+110 2023/10/23 22.96UT TOYOKAWA-KISO



K20231024075554




BLK: 2,SNR1: 0.24089 ,SNR2: 1.0675





F20231024075558




BLK: 4,SNR1: 3.9749 ,SNR2: 8.9419




K20231024075554





BLK: 4,SNR1: 1.0008 ,SNR2: 7.8044




1011+110 2023/10/23 22.96UT FUJI -KISO



T20231024080338





BLK: 4,SNR1:-0.67768E-01,SNR2: 0.22348




Frequency (Hz)

F20231024080339




BLK: 4,SNR1: 0.13461 ,SNR2: 1.5145




Frequency (Hz)


3C241 2023/10/23 23.09UT TOYOKAWA-FUJI





T20231024080338




BLK: 5,SNR1: 0.70133E-01,SNR2: 0.21671




K20231024080335





BLK: 5,SNR1: 3.8447 ,SNR2: 7.1224




3C241 2023/10/23 23.09UT TOYOKAWA-KISO





F20231024080339




BLK: 5,SNR1: 1.0851 ,SNR2: 4.7587




K20231024080335




BLK: 5,SNR1: 0.11738E-01,SNR2: 0.33234




3C241 2023/10/23 23.09UT FUJI -KISO



T20231024081508




BLK: 5, SNR1: 0.25981 , SNR2: 1.1263




Frequency (Hz)

F20231024081509




BLK: 5, SNR1: 1.0193 , SNR2: 8.2146




Frequency (Hz)

1031-11 2023/10/23 23.28UT TOYOKAWA-FUJI






T20231024081508




BLK: 4,SNR1: 0.14675 ,SNR2: 0.61259




Frequency (Hz)

K20231024081505




BLK: 4,SNR1: 0.43156 ,SNR2: 2.2433




Frequency (Hz)


1031-11 2023/10/23 23.28UT TOYOKAWA-KISO




F20231024081509




BLK: 9,SNR1: 1.3071 ,SNR2: 9.3023




K20231024081505




BLK: 9,SNR1: 1.0401 ,SNR2: 7.2210




1031-11 2023/10/23 23.28UT FUJI -KISO



T20231024081941




BLK: 8,SNR1: 4.8474 ,SNR2: 35.065





1035-058 2023/10/23 23.36UT TOYOKAWA-FUJI


F20231024081942




BLK: 8,SNR1: 0.21321 ,SNR2: 1.4156



T20231024081941





BLK: 5,SNR1: 2.8523 ,SNR2: 21.571





1035-058 2023/10/23 23.36UT TOYOKAWA-KISO



K20231024081938




BLK: 5,SNR1: 0.10122 ,SNR2: 0.81930





F20231024081942




BLK: 2,SNR1: 0.81881 ,SNR2: 2.7257




K20231024081938





BLK: 2,SNR1: 0.17221E-01,SNR2: 2.2300




1035-058 2023/10/23 23.36UT FUJI -KISO





T20231024082854




BLK: 3,SNR1: 0.43168 ,SNR2: 1.8137




F20231024082855





BLK: 3,SNR1: 0.54518E-01,SNR2: 2.6165




1044-008 2023/10/23 23.51UT TOYOKAWA-FUJI




T20231024082854




BLK: 2,SNR1: 0.20288 ,SNR2: 0.49680




K20231024082852




BLK: 2,SNR1:-0.45793E-01,SNR2: 1.0913




1044-008 2023/10/23 23.51UT TOYOKAWA-KISO



F20231024082855




BLK: 4,SNR1: 1.4554 ,SNR2: 2.9053




Frequency (Hz)

K20231024082852




BLK: 4,SNR1: 0.85122 ,SNR2: 6.1330




Frequency (Hz)



1044-008 2023/10/23 23.51UT FUJI -KISO









BLK: 3, SNR1: 0.27075 , SNR2: 0.51598




BLK: 3, SNR1: 0.89256 , SNR2: 4.3488




1055+01 2023/10/23 23.69UT TOYOKAWA-FUJI





T20231024083958




BLK: 3,SNR1:-0.10782E-01,SNR2: 0.49630




K20231024083956




BLK: 3,SNR1: 2.2801 ,SNR2: 12.697




1055+01 2023/10/23 23.69UT TOYOKAWA-KISO





F20231024083959




BLK: 3,SNR1: 0.24904 ,SNR2: 3.0751




K20231024083956





BLK: 3,SNR1: 0.21928 ,SNR2: 2.7180




1055+01 2023/10/23 23.69UT FUJI -KISO




T20231024085116




BLK: 7,SNR1: 0.53050E-01,SNR2: 1.5691




F20231024085117





BLK: 7,SNR1: 2.6966 ,SNR2: 6.7678




1107+109 2023/10/23 23.88UT TOYOKAWA-FUJI





T20231024085116




BLK: 4,SNR1:-0.63094E-01,SNR2: 0.34075




K20231024085113




BLK: 4,SNR1: 0.18497 ,SNR2: 1.4666




1107+109 2023/10/23 23.88UT TOYOKAWA-KISO





F20231024085117




BLK: 7, SNR1: 1.1277 ,SNR2: 8.3055




K20231024085113





BLK: 7, SNR1: 0.13852 ,SNR2: 0.71471




1107+109 2023/10/23 23.88UT FUJI -KISO




T20231024090053




BLK: 8,SNR1: 0.28574 ,SNR2: 2.7489




F20231024090054





BLK: 8,SNR1:-0.47983E-01,SNR2: 1.3346




3C255 2023/10/24 0.04UT TOYOKAWA-FUJI





T20231024090053




BLK: 6, SNR1: 0.42958 , SNR2: 1.9052




K20231024090050



BLK: 6, SNR1: 0.50471 , SNR2: 4.6654




3C255 2023/10/24 0.04UT TOYOKAWA-KISO








F20231024090054




BLK: 6,SNR1:-0.74392E-01,SNR2: 1.2287




K20231024090050





BLK: 6,SNR1: 0.38137 ,SNR2: 5.4018




3C255 2023/10/24 0.04UT FUJI -KISO



T20231024092451




BLK: 5,SNR1: 0.10629 ,SNR2: 0.77731





3C263.1 2023/10/24 0.44UT TOYOKAWA-FUJI


F20231024092452




BLK: 5,SNR1: 1.7980 ,SNR2: 5.4842



T20231024092451




BLK: 6,SNR1: 0.45782E-01,SNR2: 1.5161




3C263.1 2023/10/24 0.44UT TOYOKAWA-KISO


K20231024092448




BLK: 6,SNR1: 3.2531 ,SNR2: 12.628




Frequency (Hz)



F20231024092452




BLK:11,SNR1: 3.5067 ,SNR2: 13.069





3C263.1 2023/10/24 0.44UT FUJI -KISO


K20231024092448




BLK:11,SNR1: 3.0393 ,SNR2: 11.806



T20231024093118




BLK: 5,SNR1: 0.97185 ,SNR2: 6.8655





3C267 2023/10/24 0.55UT TOYOKAWA-FUJI


F20231024093119




BLK: 5,SNR1: 1.8311 ,SNR2: 6.4348





T20231024093118




BLK: 6,SNR1: 0.24665 ,SNR2: 5.6949




K20231024093115




BLK: 6,SNR1: 0.76318 ,SNR2: 7.3902




3C267 2023/10/24 0.55UT TOYOKAWA-KISO



F20231024093119





BLK: 7,SNR1: 0.25653 ,SNR2: 2.5897





3C267 2023/10/24 0.55UT FUJI -KISO


K20231024093115




BLK: 7,SNR1: 68.115 ,SNR2: 99.489



T20231024095032




BLK: 5, SNR1: 0.13212 , SNR2: 0.77225





1206+439 2023/10/24 0.87UT TOYOKAWA-FUJI

F20231024095033





BLK: 5, SNR1: 1.1483 , SNR2: 4.8158







T20231024095032




BLK: 4, SNR1: 0.62957E-01, SNR2: 0.77856




K20231024095029




BLK: 4, SNR1: 1.4514, SNR2: 7.1306




1206+439 2023/10/24 0.87UT TOYOKAWA-KISO





F20231024095033




BLK: 4,SNR1: 0.17538 ,SNR2: 1.8438




K20231024095029




BLK: 4,SNR1: 0.25345 ,SNR2: 1.4561




1206+439 2023/10/24 0.87UT FUJI -KISO




T20231024101023




BLK:19,SNR1: 4.1587 ,SNR2: 24.075




F20231024101024





BLK:19,SNR1: 2.4675 ,SNR2: 10.131




3C273 2023/10/24 1.20UT TOYOKAWA-FUJI



T20231024101023





BLK:31,SNR1: 3.3635 ,SNR2: 20.121





3C273 2023/10/24 1.20UT TOYOKAWA-KISO



K20231024101020






BLK:31,SNR1: 1.7772 ,SNR2: 7.0232




F20231024101024




K20231024101020



T20231024102334





BLK:13,SNR1: 0.22533 ,SNR2: 5.1780





3C275 2023/10/24 1.42UT TOYOKAWA-FUJI


F20231024102335




BLK:13,SNR1: 11.173 ,SNR2: 26.168





T20231024102334




BLK:17,SNR1: 0.32040 ,SNR2: 5.7258




K20231024102331





BLK:17,SNR1: 1.4734 ,SNR2: 2.9319




3C275 2023/10/24 1.42UT TOYOKAWA-KISO



F20231024102335





BLK:18,SNR1: 3.3252 ,SNR2: 13.393




Frequency (Hz)

3C275 2023/10/24 1.42UT FUJI -KISO


K20231024102331



BLK:18,SNR1: 0.99103 ,SNR2: 2.0767




Frequency (Hz)






T20231024103723





BLK: 9, SNR1: 1.6361 , SNR2: 10.297





3C279 2023/10/24 1.65UT TOYOKAWA-FUJI


F20231024103724




BLK: 9, SNR1: 0.45092 , SNR2: 5.3882





T20231024103723




BLK:19,SNR1: 1.0496 ,SNR2: 7.0626




K20231024103720





BLK:19,SNR1: 0.49324 ,SNR2: 3.0579





3C279 2023/10/24 1.65UT TOYOKAWA-KISO




F20231024103724





K20231024103720




3C279 2023/10/24 1.65UT FUJI -KISO



T20231024105711




BLK:10,SNR1:-0.27423E-02,SNR2: 4.5312





1313+453 2023/10/24 1.98UT TOYOKAWA-FUJI



F20231024105712




BLK:10,SNR1: 12.459 ,SNR2: 24.095





T20231024105711




BLK: 9,SNR1: 11.461 ,SNR2: 20.013




K20231024105708




BLK: 9,SNR1:-0.39853 ,SNR2: 0.85449




1313+453 2023/10/24 1.98UT TOYOKAWA-KISO



F20231024105712





BLK:12,SNR1: 15.929 ,SNR2: 26.243





1313+453 2023/10/24 1.98UT FUJI -KISO



K20231024105708




BLK:12,SNR1: 12.037 ,SNR2: 19.373



T20231024110717




BLK:12,SNR1: 9.7280 ,SNR2: 14.938





1323+32 2023/10/24 2.15UT TOYOKAWA-FUJI



F20231024110718




BLK:12,SNR1: 17.362 ,SNR2: 25.467



T20231024110717





BLK:15,SNR1: 8.5654 ,SNR2: 17.881




1323+32 2023/10/24 2.15UT TOYOKAWA-KISO


K20231024110714



BLK:15,SNR1: 8.2104 ,SNR2: 17.958





Frequency (Hz)






F20231024110718





BLK:22,SNR1: 10.989 ,SNR2: 17.197




Frequency (Hz)

K20231024110714








BLK:22,SNR1: 13.268 ,SNR2: 19.054




Frequency (Hz)





1323+32 2023/10/24 2.15UT FUJI -KISO






3C286 2023/10/24 2.23UT TOYOKAWA-FUJI








3C286 2023/10/24 2.23UT TOYOKAWA-KISO



F20231024111208





BLK:20,SNR1: 0.56912 ,SNR2: 3.2750




Frequency (Hz)

3C286 2023/10/24 2.23UT FUJI -KISO


K20231024111204




BLK:20,SNR1: 0.43481 ,SNR2: 2.1056




Frequency (Hz)



T20231024112834





BLK:15,SNR1: 0.81752 ,SNR2: 2.6608





1345+12 2023/10/24 2.50UT TOYOKAWA-FUJI



F20231024112835




BLK:15,SNR1: 0.31046E-01,SNR2: 3.9985



T20231024112834





BLK:27,SNR1: 0.55737 ,SNR2: 2.2152




1345+12 2023/10/24 2.50UT TOYOKAWA-KISO


K20231024112831





BLK:27,SNR1: 0.19193 ,SNR2: 2.0365




Frequency (Hz)



F20231024112835





BLK:19,SNR1: 18.458 ,SNR2: 28.569





1345+12 2023/10/24 2.50UT FUJI -KISO


K20231024112831




BLK:19,SNR1: 17.215 ,SNR2: 30.326



T20231024113854





BLK:15,SNR1: 1.2414 ,SNR2: 4.8083





1355+01 2023/10/24 2.68UT TOYOKAWA-FUJI

F20231024113855





BLK:15,SNR1: 9.0485 ,SNR2: 15.811






T20231024113854





BLK:26,SNR1: 1.0637 ,SNR2: 8.4970





1355+01 2023/10/24 2.68UT TOYOKAWA-KISO



K20231024113851




BLK:26,SNR1: 6.7241 ,SNR2: 12.851





F20231024113855




BLK: 8,SNR1: 26.243 ,SNR2: 39.421




K20231024113851







BLK: 8,SNR1: 0.48931 ,SNR2: 4.6212








1355+01 2023/10/24 2.68UT FUJI -KISO






3C298 2023/10/24 3.03UT TOYOKAWA-FUJI








3C298 2023/10/24 3.03UT TOYOKAWA-KISO



F20231024120006





BLK:32,SNR1: 0.47710 ,SNR2: 1.7155





3C298 2023/10/24 3.03UT FUJI -KISO


K20231024120002




BLK:32,SNR1: 1.0116 ,SNR2: 3.5180




T20231024121148




BLK: 5,SNR1: 0.31857 ,SNR2: 1.7907




F20231024121149





BLK: 5,SNR1: 0.17455E-01,SNR2: 0.86744




1428-03 2023/10/24 3.22UT TOYOKAWA-FUJI





T20231024121148




BLK:12,SNR1: 0.20251 ,SNR2: 1.2749




K20231024121145




BLK:12,SNR1: 0.50648 ,SNR2: 5.3783




1428-03 2023/10/24 3.22UT TOYOKAWA-KISO



F20231024121149





BLK: 2,SNR1: 6.9317 ,SNR2: 11.301





1428-03 2023/10/24 3.22UT FUJI -KISO

K20231024121145





BLK: 2,SNR1: 0.67860 ,SNR2: 3.1439







T20231024121751




BLK: 6,SNR1: 0.10720 ,SNR2: 1.2333




F20231024121752





BLK: 6,SNR1: 0.49466E-01,SNR2: 1.5797




1434+03 2023/10/24 3.33UT TOYOKAWA-FUJI



T20231024121751




BLK: 8,SNR1: 0.32340E-01,SNR2: 1.3901





1434+03 2023/10/24 3.33UT TOYOKAWA-KISO


K20231024121748




BLK: 8,SNR1: 0.24020 ,SNR2: 1.7337





F20231024121752




BLK: 7,SNR1: 0.44881E-01,SNR2: 1.5846




K20231024121748





BLK: 7,SNR1: 0.43340 ,SNR2: 1.7857




1434+03 2023/10/24 3.33UT FUJI -KISO




T20231024123653




BLK:11,SNR1: 0.26770 ,SNR2: 0.80232




F20231024123654




BLK:11,SNR1: 0.72519E-01,SNR2: 1.7663




1453-10 2023/10/24 3.64UT TOYOKAWA-FUJI



T20231024123653




BLK:13,SNR1: 0.17522 ,SNR2: 1.4221




Frequency (Hz)

1453-10 2023/10/24 3.64UT TOYOKAWA-KISO


K20231024123650




BLK:13,SNR1: 4.3720 ,SNR2: 10.177




Frequency (Hz)



F20231024123654




BLK: 9,SNR1: 0.48691 ,SNR2: 0.94434




1453-10 2023/10/24 3.64UT FUJI -KISO


K20231024123650





BLK: 9,SNR1: 5.5023 ,SNR2: 10.288




1453-10 2023/10/24 3.64UT FUJI -KISO



T20231024125145




BLK: 4,SNR1: 0.19914 ,SNR2: 1.1751





1508-05 2023/10/24 3.89UT TOYOKAWA-FUJI



F20231024125146




BLK: 4,SNR1: 1.7354 ,SNR2: 11.771





T20231024125145




BLK: 1,SNR1: 0.20015E-01,SNR2: 2.9323




K20231024125142



BLK: 1,SNR1:-0.12146 ,SNR2: 0.41891




1508-05 2023/10/24 3.89UT TOYOKAWA-KISO






F20231024125146





BLK: 2,SNR1: 3.0843 ,SNR2: 17.604





1508-05 2023/10/24 3.89UT FUJI -KISO



K20231024125142




BLK: 2,SNR1: 0.22040 ,SNR2: 0.68915




T20231024130046




BLK: 3,SNR1:-0.90564E-01,SNR2: 0.17085




F20231024130047





BLK: 3,SNR1:-0.19300 ,SNR2: 0.76748




3C318 2023/10/24 4.04UT TOYOKAWA-FUJI



T20231024130046





BLK: 2,SNR1:-0.20135E-01,SNR2: 0.31228





3C318 2023/10/24 4.04UT TOYOKAWA-KISO


K20231024130043




BLK: 2,SNR1: 1.1689 ,SNR2: 3.3030



F20231024130047





BLK: 4,SNR1: 0.16399 ,SNR2: 0.94205





3C318 2023/10/24 4.04UT FUJI -KISO



K20231024130043




BLK: 4,SNR1: 0.23123 ,SNR2: 0.55674




T20231024130632




BLK: 6,SNR1: 0.22710 ,SNR2: 2.7519




F20231024130633





BLK: 6,SNR1:-0.80926E-01,SNR2: 0.78561




1523+03 2023/10/24 4.14UT TOYOKAWA-FUJI





T20231024130632




BLK: 7,SNR1: 0.15882 ,SNR2: 1.7334




K20231024130629





BLK: 7,SNR1: 0.13334 ,SNR2: 2.6423




1523+03 2023/10/24 4.14UT TOYOKAWA-KISO



F20231024130633





BLK: 5,SNR1: 0.16156E-01,SNR2: 1.1357





1523+03 2023/10/24 4.14UT FUJI -KISO



K20231024130629




BLK: 5,SNR1: 1.4763 ,SNR2: 4.1257





T20231024131812




No.Good Data




F20231024131813



No.Good Data





1535+139 2023/10/24 4.33UT TOYOKAWA-FUJI








T20231024131812




BLK: 1,SNR1:-0.20752E-01,SNR2: 0.84105E-01




K20231024131809




BLK: 1,SNR1: 0.11420 ,SNR2: 0.57055




1535+139 2023/10/24 4.33UT TOYOKAWA-KISO





F20231024131813




BLK: 1,SNR1: 0.83395E-01,SNR2: 6.0451




K20231024131809





BLK: 1,SNR1: 0.33901E-01,SNR2: 1.3212




1535+139 2023/10/24 4.33UT FUJI -KISO





T20231024133118




BLK: 5,SNR1: 0.60369E-01,SNR2: 0.18723




F20231024133119





BLK: 5,SNR1: 0.17845 ,SNR2: 1.1084




1548+05 2023/10/24 4.55UT TOYOKAWA-FUJI





T20231024133118




BLK: 3,SNR1:-0.38211E-01,SNR2: 0.27214




K20231024133116





BLK: 3,SNR1: 1.3060 ,SNR2: 6.7454




1548+05 2023/10/24 4.55UT TOYOKAWA-KISO





F20231024133119




BLK: 4,SNR1: 0.18699 ,SNR2: 1.4639




K20231024133116





BLK: 4,SNR1: 1.0839 ,SNR2: 8.2162




1548+05 2023/10/24 4.55UT FUJI -KISO




T20231024134940




BLK: 3,SNR1: 0.21301 ,SNR2: 0.56948




F20231024134941





BLK: 3,SNR1: 0.17047 ,SNR2: 1.7195




1607+26 2023/10/24 4.86UT TOYOKAWA-FUJI





T20231024134940




BLK: 1,SNR1: 0.49551 ,SNR2: 1.0967




K20231024134937




BLK: 1,SNR1: 0.20758 ,SNR2: 3.7110




1607+26 2023/10/24 4.86UT TOYOKAWA-KISO





F20231024134941




BLK: 1,SNR1: 0.64807 ,SNR2: 3.9279




K20231024134937



BLK: 1,SNR1: 0.38064 ,SNR2: 0.74000






1607+26 2023/10/24 4.86UT FUJI -KISO









T20231024142117






F20231024142118






1638-025 2023/10/24 5.38UT TOYOKAWA-FUJI




T20231024142117





K20231024142114





1638-025 2023/10/24 5.38UT TOYOKAWA-KISO




F20231024142118







K20231024142114





1638-025 2023/10/24 5.38UT FUJI -KISO







1644-106 2023/10/24 5.50UT TOYOKAWA-FUJI







BLK: 5,SNR1: 0.15429 ,SNR2: 0.80534




BLK: 5,SNR1: 1.8389 ,SNR2: 11.250




1644-106 2023/10/24 5.50UT TOYOKAWA-KISO





F20231024142812




BLK: 2,SNR1: 0.17695 ,SNR2: 2.0391




K20231024142808





BLK: 2,SNR1: 0.39520 ,SNR2: 2.3941




1644-106 2023/10/24 5.50UT FUJI -KISO





T20231024143332




BLK: 5,SNR1: 0.17125E-01,SNR2: 1.0069




F20231024143333





BLK: 5,SNR1: 0.66351E-01,SNR2: 1.3619




1650+004 2023/10/24 5.59UT TOYOKAWA-FUJI





T20231024143332




BLK: 5,SNR1: 0.85454E-01,SNR2: 0.22022




K20231024143329



BLK: 5,SNR1: 1.0104 ,SNR2: 5.9434




1650+004 2023/10/24 5.59UT TOYOKAWA-KISO






F20231024143333





BLK: 3, SNR1: 1.3174 , SNR2: 4.8433




Frequency (Hz)

K20231024143329




BLK: 3, SNR1: 1.9827 , SNR2: 6.4268





Frequency (Hz)


1650+004 2023/10/24 5.59UT FUJI -KISO





T20231024143904




BLK: 3,SNR1: 0.16706E-01,SNR2: 0.30527




F20231024143904





BLK: 3,SNR1: 0.22228 ,SNR2: 3.2386




1656+053 2023/10/24 5.68UT TOYOKAWA-FUJI





T20231024143904




BLK: 7,SNR1: 0.35044E-01,SNR2: 0.59331




K20231024143902





BLK: 7,SNR1: 1.3050 ,SNR2: 3.7043




1656+053 2023/10/24 5.68UT TOYOKAWA-KISO




F20231024143904




BLK: 3,SNR1: 0.34162 ,SNR2: 2.5243




K20231024143902





BLK: 3,SNR1: 0.11910 ,SNR2: 1.8813




1656+053 2023/10/24 5.68UT FUJI -KISO




T20231024145533




BLK: 3,SNR1:-0.92421E-02,SNR2: 0.55891




F20231024145534




BLK: 3,SNR1:-0.11198E-01,SNR2: 2.0295




1712-033 2023/10/24 5.95UT TOYOKAWA-FUJI





T20231024145533




BLK: 7,SNR1: 0.15679E-01,SNR2: 0.27407




K20231024145530




BLK: 7,SNR1: 0.22475 ,SNR2: 2.5531




1712-033 2023/10/24 5.95UT TOYOKAWA-KISO





F20231024145534




BLK: 2,SNR1:-0.30054 ,SNR2: 0.39749




K20231024145530





BLK: 2,SNR1: 0.59536 ,SNR2: 3.8072




1712-033 2023/10/24 5.95UT FUJI -KISO




T20231024151336




BLK: 3,SNR1: 0.11609 ,SNR2: 0.47019




F20231024151337



BLK: 3,SNR1: 0.75691 ,SNR2: 2.1929





1730-13 2023/10/24 6.25UT TOYOKAWA-FUJI








T20231024151336




BLK: 2,SNR1: 0.40862 ,SNR2: 0.38952




K20231024151334




BLK: 2,SNR1: 0.82382 ,SNR2: 6.1540




1730-13 2023/10/24 6.25UT TOYOKAWA-KISO




F20231024151337




BLK: 2,SNR1: 0.41787 ,SNR2: 1.7949




K20231024151334




BLK: 2,SNR1: 0.18027 ,SNR2: 1.1312




1730-13 2023/10/24 6.25UT FUJI -KISO




T20231024153100




BLK: 1,SNR1: 0.15194 ,SNR2: 0.71177




F20231024153101





BLK: 1,SNR1:-0.27620 ,SNR2: 0.0000




1748+031 2023/10/24 6.55UT TOYOKAWA-FUJI



T20231024153100





BLK: 1,SNR1:-0.24204 ,SNR2: 0.19247




Frequency (Hz)

K20231024153057




BLK: 1,SNR1: 0.49315 ,SNR2: 3.0307





Frequency (Hz)


1748+031 2023/10/24 6.55UT TOYOKAWA-KISO





F20231024153101




BLK: 2,SNR1: 0.12177 ,SNR2: 5.3396




K20231024153057





BLK: 2,SNR1: 0.21247 ,SNR2: 1.2965




1748+031 2023/10/24 6.55UT FUJI -KISO





T20231024154154




BLK: 4,SNR1: 9.7794 ,SNR2: 19.712




F20231024154155





BLK: 4,SNR1: 0.24657 ,SNR2: 3.2042




1759+13 2023/10/24 6.73UT TOYOKAWA-FUJI



T20231024154154





BLK: 3,SNR1: 0.65509 ,SNR2: 3.8729




Frequency (Hz)

K20231024154151




BLK: 3,SNR1: 0.16113 ,SNR2: 2.7921





Frequency (Hz)


1759+13 2023/10/24 6.73UT TOYOKAWA-KISO



F20231024154155





BLK: 4,SNR1: 0.45667 ,SNR2: 1.4618




Frequency (Hz)

K20231024154151




BLK: 4,SNR1: 2.3702 ,SNR2: 9.0649





Frequency (Hz)

1759+13 2023/10/24 6.73UT FUJI -KISO







T20231024160253




BLK: 2,SNR1: 0.13736E-01,SNR2: 1.7656




F20231024160254





BLK: 2,SNR1:-0.78400E-01,SNR2: 0.45895




1819-096 2023/10/24 7.08UT TOYOKAWA-FUJI





T20231024160253




BLK: 3,SNR1:-0.62932E-01,SNR2: 0.21906




K20231024160250




BLK: 3,SNR1: 0.80391 ,SNR2: 4.2742




1819-096 2023/10/24 7.08UT TOYOKAWA-KISO





F20231024160254




BLK: 1,SNR1:-0.98797E-01,SNR2: 0.0000




K20231024160250





BLK: 1,SNR1:-0.51269E-01,SNR2: 0.73513




1819-096 2023/10/24 7.08UT FUJI -KISO




T20231024164034




BLK: 4,SNR1:-0.85296E-01,SNR2: 0.20694




F20231024164035





BLK: 4,SNR1:-0.25299E-01,SNR2: 2.0471




1858+171 2023/10/24 7.70UT TOYOKAWA-FUJI



T20231024164034





BLK: 1,SNR1: 0.16795 ,SNR2: 0.27206




Frequency (Hz)

K20231024164031








BLK: 1,SNR1: 0.92621 ,SNR2: 8.1058




Frequency (Hz)

1858+171 2023/10/24 7.70UT TOYOKAWA-KISO








1858+171 2023/10/24 7.70UT FUJI -KISO




T20231024165809




BLK: 5,SNR1: 0.20694 ,SNR2: 0.90041




F20231024165810





BLK: 5,SNR1: 0.14379 ,SNR2: 1.7900




1915-121 2023/10/24 8.00UT TOYOKAWA-FUJI





T20231024165809




BLK: 1,SNR1: 0.70301E-01,SNR2: 0.60461




K20231024165807




BLK: 1,SNR1: 0.18534 ,SNR2: 2.7310






1915-121 2023/10/24 8.00UT TOYOKAWA-KISO









BLK: 4,SNR1: 0.42955E-01,SNR2: 1.5623





BLK: 4,SNR1:-0.10399 ,SNR2: 1.3265




1915-121 2023/10/24 8.00UT FUJI -KISO




T20231024171150




BLK: 4,SNR1: 2.5074 ,SNR2: 9.4025




F20231024171151





BLK: 4,SNR1: -0.45419E-01,SNR2: 0.94221




1928-142 2023/10/24 8.23UT TOYOKAWA-FUJI



T20231024171150





BLK: 3,SNR1: 3.6372 ,SNR2: 12.639




Frequency (Hz)

K20231024171147





BLK: 3,SNR1: 0.82318 ,SNR2: 5.9879





Frequency (Hz)

1928-142 2023/10/24 8.23UT TOYOKAWA-KISO






BLK: 5, SNR1: 0.72381E-01, SNR2: 3.7955



BLK: 5, SNR1: 0.60923, SNR2: 2.5663



1928-142 2023/10/24 8.23UT FUJI -KISO

