



T20231105060016




BLK: 7,SNR1: 0.71585 ,SNR2: 13.182




Frequency (Hz)

F20231105060017




BLK: 7,SNR1: 0.57095 ,SNR2: 2.3646





Frequency (Hz)


0903-041 2023/11/04 21.03UT TOYOKAWA-FUJI



T20231105060016





BLK: 5,SNR1: 0.11512 ,SNR2: 2.0092




Frequency (Hz)

K20231105060014




BLK: 5,SNR1: 0.34471 ,SNR2: 6.4143





Frequency (Hz)

0903-041 2023/11/04 21.03UT TOYOKAWA-KISO






F20231105060017





BLK: 7,SNR1:-0.31828E-01,SNR2: 1.3118




Frequency (Hz)

K20231105060014




BLK: 7,SNR1: 0.50711 ,SNR2: 1.7187





Frequency (Hz)


0903-041 2023/11/04 21.03UT FUJI -KISO





T20231105060917




BLK:15,SNR1: 0.86734E-01,SNR2: 0.30312




F20231105060918





BLK:15,SNR1: 11.887 ,SNR2: 25.860




0912-132 2023/11/04 21.18UT TOYOKAWA-FUJI



T20231105060917





BLK: 3,SNR1:-0.16851E-01,SNR2: 0.65570




Frequency (Hz)

K20231105060915




BLK: 3,SNR1: 77.109 ,SNR2: 74.897




Frequency (Hz)


0912-132 2023/11/04 21.18UT TOYOKAWA-KISO



F20231105060918





BLK: 4,SNR1: 12.028 ,SNR2: 26.160





0912-132 2023/11/04 21.18UT FUJI -KISO



K20231105060915




BLK: 4,SNR1: 0.24364 ,SNR2: 2.6829




T20231105062323




BLK: 9, SNR1: 1.9197 ,SNR2: 7.2198




F20231105062324




BLK: 9, SNR1: 1.9772 ,SNR2: 4.5873




0926+117 2023/11/04 21.42UT TOYOKAWA-FUJI





T20231105062323




BLK: 4,SNR1: 2.9143 ,SNR2: 10.919




K20231105062321





BLK: 4,SNR1: 26.253 ,SNR2: 63.724




0926+117 2023/11/04 21.42UT TOYOKAWA-KISO



F20231105062324





BLK: 5,SNR1: 2.7373 ,SNR2: 5.9231




Frequency (Hz)

K20231105062321




BLK: 5,SNR1: 0.92749 ,SNR2: 4.1134





Frequency (Hz)


0926+117 2023/11/04 21.42UT FUJI -KISO



T20231105063108





BLK:17,SNR1: 2.3803 ,SNR2: 9.8445




Frequency (Hz)

3C222 2023/11/04 21.55UT TOYOKAWA-FUJI


F20231105063109



BLK:17,SNR1: 3.0345 ,SNR2: 12.171





Frequency (Hz)






T20231105063108





BLK:12,SNR1: 2.5074 ,SNR2: 10.385




Frequency (Hz)

3C222 2023/11/04 21.55UT TOYOKAWA-KISO


K20231105063106





BLK:12,SNR1: 78.481 ,SNR2: 75.508




Frequency (Hz)



F20231105063109





BLK:22,SNR1: 9.8005 ,SNR2: 26.538




Frequency (Hz)

3C222 2023/11/04 21.55UT FUJI -KISO


K20231105063106





BLK:22,SNR1: 10.186 ,SNR2: 27.542




Frequency (Hz)



T20231105063808





BLK: 2,SNR1: 0.40117E-01,SNR2: 0.63703




Frequency (Hz)

F20231105063809




BLK: 2,SNR1: 4.5650 ,SNR2: 8.8116




Frequency (Hz)


0941-08 2023/11/04 21.66UT TOYOKAWA-FUJI





T20231105063808




BLK: 2,SNR1: 0.44187E-01,SNR2: 0.18435




K20231105063806




BLK: 2,SNR1: 0.64068E-01,SNR2: 0.91387




0941-08 2023/11/04 21.66UT TOYOKAWA-KISO



F20231105063809





BLK: 7, SNR1: 4.3843 ,SNR2: 8.4586




Frequency (Hz)

K20231105063806






BLK: 7, SNR1: 80.306 ,SNR2: 76.181





Frequency (Hz)

0941-08 2023/11/04 21.66UT FUJI -KISO







BLK: 2,SNR1: 0.19145E-01,SNR2: 0.64413





BLK: 2,SNR1: 0.32910 ,SNR2: 1.6515




3C230 2023/11/04 21.80UT TOYOKAWA-FUJI



T20231105064630





BLK: 1, SNR1: 0.20887 , SNR2: 0.38561




Frequency (Hz)

K20231105064628




BLK: 1, SNR1: 41.303 , SNR2: 86.417





Frequency (Hz)


3C230 2023/11/04 21.80UT TOYOKAWA-KISO



F20231105064631





BLK: 3,SNR1: 0.19709E-01,SNR2: 0.79383




Frequency (Hz)

K20231105064628




BLK: 3,SNR1: 77.721 ,SNR2: 75.854





Frequency (Hz)

3C230 2023/11/04 21.80UT FUJI -KISO






T20231105070230





BLK:10,SNR1: 0.18621 ,SNR2: 0.80903




Frequency (Hz)

3C237 2023/11/04 22.07UT TOYOKAWA-FUJI


F20231105070231





BLK:10,SNR1: 12.729 ,SNR2: 23.324




Frequency (Hz)



T20231105070230





BLK: 5,SNR1: 0.42903E-01,SNR2: 0.76631




Frequency (Hz)

3C237 2023/11/04 22.07UT TOYOKAWA-KISO


K20231105070228





BLK: 5,SNR1: 0.36170 ,SNR2: 2.4623




Frequency (Hz)



F20231105070231





BLK:13,SNR1: 22.547 ,SNR2: 31.347




Frequency (Hz)

3C237 2023/11/04 22.07UT FUJI -KISO


K20231105070228





BLK:13,SNR1: 1.5981 ,SNR2: 7.8065




Frequency (Hz)



T20231105070846




BLK: 2,SNR1:-0.22388E-01,SNR2: 0.32549




Frequency (Hz)

F20231105070847




BLK: 2,SNR1: 0.50531 ,SNR2: 5.9681





Frequency (Hz)


1011+110 2023/11/04 22.17UT TOYOKAWA-FUJI



T20231105070846





BLK: 1,SNR1: 0.54939E-01,SNR2: 0.54282E-01




Frequency (Hz)

K20231105070844




BLK: 1,SNR1: 0.53886 ,SNR2: 1.0630




Frequency (Hz)


1011+110 2023/11/04 22.17UT TOYOKAWA-KISO





F20231105070847




BLK: 4,SNR1: 0.23229 ,SNR2: 1.2202




K20231105070844




BLK: 4,SNR1: 0.37848 ,SNR2: 2.4954




1011+110 2023/11/04 22.17UT FUJI -KISO




T20231105071627




BLK: 4,SNR1: 0.45578E-01,SNR2: 0.32615




F20231105071628




BLK: 4,SNR1: 0.41674 ,SNR2: 2.9740




3C241 2023/11/04 22.30UT TOYOKAWA-FUJI



T20231105071627




BLK: 5,SNR1: 0.15200 ,SNR2: 0.83477




Frequency (Hz)

3C241 2023/11/04 22.30UT TOYOKAWA-KISO


K20231105071625



BLK: 5,SNR1: 1.2593 ,SNR2: 4.9888





Frequency (Hz)






F20231105071628





BLK:10,SNR1: 2.0272 ,SNR2: 5.1535




Frequency (Hz)

K20231105071625




BLK:10,SNR1: 7.5693 ,SNR2: 9.4990





Frequency (Hz)


3C241 2023/11/04 22.30UT FUJI -KISO



T20231105072757





BLK: 4,SNR1:-0.99448E-02,SNR2: 0.17597




Frequency (Hz)

F20231105072758




BLK: 4,SNR1: 0.93957E-01,SNR2: 4.6940




Frequency (Hz)


1031-11 2023/11/04 22.49UT TOYOKAWA-FUJI



T20231105072757




BLK: 4,SNR1:-0.74400E-01,SNR2: 0.29621




Frequency (Hz)

K20231105072754




BLK: 4,SNR1: 0.98673 ,SNR2: 9.5137





Frequency (Hz)


1031-11 2023/11/04 22.49UT TOYOKAWA-KISO





F20231105072758




BLK: 9,SNR1: 0.88448E-01,SNR2: 4.6555




K20231105072754





BLK: 9,SNR1: 0.83695 ,SNR2: 8.4207




1031-11 2023/11/04 22.49UT FUJI -KISO



T20231105073230





BLK: 6,SNR1: 7.3536 ,SNR2: 43.327




Frequency (Hz)

F20231105073231




BLK: 6,SNR1: 0.16204E-01,SNR2: 1.5436





Frequency (Hz)


1035-058 2023/11/04 22.57UT TOYOKAWA-FUJI



T20231105073230





BLK: 5, SNR1: 4.0684 , SNR2: 27.068




Frequency (Hz)

K20231105073227




BLK: 5, SNR1: 0.61716 , SNR2: 1.8584





Frequency (Hz)


1035-058 2023/11/04 22.57UT TOYOKAWA-KISO



F20231105073231





BLK: 2,SNR1:-0.10064 ,SNR2: 3.7917




Frequency (Hz)

K20231105073227




BLK: 2,SNR1: 0.58581 ,SNR2: 6.4109





Frequency (Hz)


1035-058 2023/11/04 22.57UT FUJI -KISO





T20231105074143




BLK: 2,SNR1:-0.59284E-01,SNR2: 0.60575




F20231105074144



BLK: 2,SNR1: 0.18523 ,SNR2: 1.2960





1044-008 2023/11/04 22.72UT TOYOKAWA-FUJI






T20231105074143




BLK: 2,SNR1:-0.73913E-01,SNR2: 0.92950E-01





1044-008 2023/11/04 22.72UT TOYOKAWA-KISO



K20231105074140




BLK: 2,SNR1: 0.28883 ,SNR2: 2.0422





F20231105074144




BLK: 2,SNR1: 0.40678 ,SNR2: 2.1182




K20231105074140




BLK: 2,SNR1: 1.1418 ,SNR2: 2.2059




1044-008 2023/11/04 22.72UT FUJI -KISO



T20231105075247




BLK: 3,SNR1: 0.33509 ,SNR2: 1.8113





1055+01 2023/11/04 22.91UT TOYOKAWA-FUJI


F20231105075248




BLK: 3,SNR1: 3.6141 ,SNR2: 12.360



T20231105075247




BLK: 6,SNR1: 0.16241 ,SNR2: 1.0946





1055+01 2023/11/04 22.91UT TOYOKAWA-KISO


K20231105075244




BLK: 6,SNR1: 0.87100E-01,SNR2: 0.75247




F20231105075248




BLK: 3,SNR1: 0.52692E-02,SNR2: 3.3523




K20231105075244




BLK: 3,SNR1: 0.28535 ,SNR2: 3.9472




1055+01 2023/11/04 22.91UT FUJI -KISO



T20231105080405




BLK: 1,SNR1: 0.11110 ,SNR2: 0.65421




Frequency (Hz)

F20231105080406




BLK: 1,SNR1: 0.84929 ,SNR2: 4.1567




Frequency (Hz)


1107+109 2023/11/04 23.10UT TOYOKAWA-FUJI





T20231105080405




BLK: 5,SNR1:-0.32537E-01,SNR2: 0.77458




K20231105080403





BLK: 5,SNR1: 1.1031 ,SNR2: 3.4394




1107+109 2023/11/04 23.10UT TOYOKAWA-KISO




F20231105080406




BLK: 2,SNR1: 0.51941 ,SNR2: 4.9604




K20231105080403



BLK: 2,SNR1: 3.3655 ,SNR2: 14.802





1107+109 2023/11/04 23.10UT FUJI -KISO






T20231105081342




BLK: 5, SNR1: 0.38467 , SNR2: 1.2987





3C255 2023/11/04 23.26UT TOYOKAWA-FUJI



F20231105081343




BLK: 5, SNR1: -0.21764 , SNR2: 0.71432



T20231105081342




BLK:15,SNR1: 0.34047 ,SNR2: 1.8447





3C255 2023/11/04 23.26UT TOYOKAWA-KISO


K20231105081340




BLK:15,SNR1: 0.49978 ,SNR2: 2.0067



F20231105081343





BLK: 4,SNR1:-0.17182 ,SNR2: 1.2240





3C255 2023/11/04 23.26UT FUJI -KISO


K20231105081340



BLK: 4,SNR1: 0.61591 ,SNR2: 2.6350




T20231105083740



Time (sec)




BLK: 5,SNR1: 3.3033 ,SNR2: 12.663



Frequency (Hz)


F20231105083741



Time (sec)




BLK: 5,SNR1: 0.54030 ,SNR2: 4.8673





Frequency (Hz)


3C263.1 2023/11/04 23.66UT TOYOKAWA-FUJI



T20231105083740





BLK: 4,SNR1: 0.64516E-01,SNR2: 2.0015




Frequency (Hz)

K20231105083737




BLK: 4,SNR1: 0.36730 ,SNR2: 4.2367




Frequency (Hz)


3C263.1 2023/11/04 23.66UT TOYOKAWA-KISO





F20231105083741




BLK: 7,SNR1: 0.63312E-01,SNR2: 3.6586




K20231105083737





BLK: 7,SNR1: 0.96302E-03,SNR2: 1.1637




3C263.1 2023/11/04 23.66UT FUJI -KISO



T20231105084407





BLK: 5, SNR1: 1.2240 ,SNR2: 26.425





3C267 2023/11/04 23.76UT TOYOKAWA-FUJI



F20231105084408




BLK: 5, SNR1: 0.20286 ,SNR2: 0.90867



T20231105084407





BLK: 3,SNR1: 0.21597 ,SNR2: 3.2939




Frequency (Hz)

K20231105084405




BLK: 3,SNR1: 0.57971 ,SNR2: 4.0324




Frequency (Hz)

3C267 2023/11/04 23.76UT TOYOKAWA-KISO






F20231105084408





BLK: 1,SNR1: 0.38578 ,SNR2: 2.9292





3C267 2023/11/04 23.76UT FUJI -KISO



K20231105084405




BLK: 1,SNR1: 3.6052 ,SNR2: 15.341




T20231105090322




BLK: 4,SNR1: 0.50996 ,SNR2: 1.3924




F20231105090323





BLK: 4,SNR1:-0.11609 ,SNR2: 0.26738




1206+439 2023/11/05 0.08UT TOYOKAWA-FUJI





T20231105090322




BLK: 2, SNR1: 0.13411 , SNR2: 1.0955




K20231105090319





BLK: 2, SNR1: 11.007 , SNR2: 16.092




1206+439 2023/11/05 0.08UT TOYOKAWA-KISO





F20231105090323




BLK: 6, SNR1: 0.47024 ,SNR2: 2.4874




K20231105090319




BLK: 6, SNR1: 2.9105 ,SNR2: 10.611




1206+439 2023/11/05 0.08UT FUJI -KISO



T20231105092312




BLK:14,SNR1: 2.2279 ,SNR2: 6.1315






3C273 2023/11/05 0.41UT TOYOKAWA-FUJI

F20231105092313





BLK:14,SNR1:-0.16011 ,SNR2: 2.0951







BLK:27,SNR1: 2.3400 ,SNR2: 8.5363




BLK:27,SNR1: 0.88500 ,SNR2: 2.9017




3C273 2023/11/05 0.41UT TOYOKAWA-KISO




F20231105092313




BLK:12,SNR1: 0.11836 ,SNR2: 2.7981




K20231105092310




BLK:12,SNR1: 0.21270 ,SNR2: 2.6450




3C273 2023/11/05 0.41UT FUJI -KISO





T20231105093623




BLK: 4,SNR1: 0.77656E-01,SNR2: 2.8354




F20231105093623



BLK: 4,SNR1:-0.15281 ,SNR2: 0.18690E-01




3C275 2023/11/05 0.63UT TOYOKAWA-FUJI






T20231105093623





BLK: 8,SNR1: 0.22335 ,SNR2: 1.6569









3C275 2023/11/05 0.63UT TOYOKAWA-KISO

K20231105093620








BLK: 8,SNR1: 0.24524 ,SNR2: 1.2466










3C275 2023/11/05 0.63UT FUJI -KISO






3C279 2023/11/05 0.86UT TOYOKAWA-FUJI








3C279 2023/11/05 0.86UT TOYOKAWA-KISO





F20231105095013




BLK: 8,SNR1: 0.75675 ,SNR2: 3.1472




K20231105095009




BLK: 8,SNR1: 764.10 ,SNR2: 816.37




3C279 2023/11/05 0.86UT FUJI -KISO



T20231105101000




BLK: 3, SNR1: 10.622 , SNR2: 143.69





1313+453 2023/11/05 1.19UT TOYOKAWA-FUJI


F20231105101001




BLK: 3, SNR1: 0.15569 , SNR2: 2.4197



T20231105101000





BLK:12,SNR1: 11.046 ,SNR2: 97.646





1313+453 2023/11/05 1.19UT TOYOKAWA-KISO


K20231105100958




BLK:12,SNR1: 21.891 ,SNR2: 50.051





F20231105101001




BLK: 6,SNR1: 0.43699 ,SNR2: 1.5258




K20231105100958



BLK: 6,SNR1: 4.9949 ,SNR2: 12.138





1313+453 2023/11/05 1.19UT FUJI -KISO






T20231105102006




BLK: 4,SNR1: 0.25537 ,SNR2: 1.9393





1323+32 2023/11/05 1.36UT TOYOKAWA-FUJI



F20231105102007




BLK: 4,SNR1: 0.86320 ,SNR2: 4.9137





T20231105102006




BLK: 4, SNR1: 0.13212 , SNR2: 1.3492




K20231105102004




BLK: 4, SNR1: 1.2329 , SNR2: 3.8626




1323+32 2023/11/05 1.36UT TOYOKAWA-KISO





F20231105102007




BLK: 3, SNR1: 0.44954 , SNR2: 2.1644




K20231105102004




BLK: 3, SNR1: 4.0936 , SNR2: 17.288




1323+32 2023/11/05 1.36UT FUJI -KISO





T20231105102456




BLK: 7,SNR1: 0.63849 ,SNR2: 3.8681




F20231105102457




BLK: 7,SNR1: -0.21866E-01,SNR2: 1.4244




3C286 2023/11/05 1.44UT TOYOKAWA-FUJI




T20231105102456




BLK:17,SNR1: 0.71836 ,SNR2: 3.9298




K20231105102453




BLK:17,SNR1: 0.17402 ,SNR2: 0.70900




3C286 2023/11/05 1.44UT TOYOKAWA-KISO




F20231105102457




BLK: 8,SNR1: 0.43103 ,SNR2: 1.9290




K20231105102453





BLK: 8,SNR1: 0.30929 ,SNR2: 1.0832




3C286 2023/11/05 1.44UT FUJI -KISO



T20231105104123





BLK:11,SNR1: 3.1547 ,SNR2: 5.6988




Frequency (Hz)

F20231105104124




BLK:11,SNR1: 0.23230 ,SNR2: 0.79551




Frequency (Hz)


1345+12 2023/11/05 1.72UT TOYOKAWA-FUJI



T20231105104123





BLK:26,SNR1: 2.2484 ,SNR2: 4.3337




1345+12 2023/11/05 1.72UT TOYOKAWA-KISO


K20231105104121



BLK:26,SNR1: 1.9650 ,SNR2: 9.1027




Frequency (Hz)








F20231105104124




BLK:11,SNR1: 0.35399 ,SNR2: 0.97568




K20231105104121




BLK:11,SNR1: 1.6565 ,SNR2: 6.9781




1345+12 2023/11/05 1.72UT FUJI -KISO



T20231105105144





BLK:10,SNR1: 2.5624 ,SNR2: 18.083




Frequency (Hz)

1355+01 2023/11/05 1.89UT TOYOKAWA-FUJI


F20231105105145




BLK:10,SNR1: 0.78678 ,SNR2: 4.6962




Frequency (Hz)



T20231105105144




BLK:18,SNR1: 1.7333 ,SNR2: 14.908




1355+01 2023/11/05 1.89UT TOYOKAWA-KISO


K20231105105142




BLK:18,SNR1: 0.23175 ,SNR2: 1.0053




Frequency (Hz)



F20231105105145





BLK: 3,SNR1: 1.0117 ,SNR2: 3.3305




Frequency (Hz)

1355+01 2023/11/05 1.89UT FUJI -KISO


K20231105105142




BLK: 3,SNR1: 0.10210 ,SNR2: 1.4342




Frequency (Hz)





T20231105111254




BLK:19,SNR1: 3.5086 ,SNR2: 20.193




F20231105111255




BLK:19,SNR1: 0.24706 ,SNR2: 1.0318




3C298 2023/11/05 2.24UT TOYOKAWA-FUJI





T20231105111254




BLK:33,SNR1: 2.7984 ,SNR2: 20.429




K20231105111252





BLK:33,SNR1: 0.50119 ,SNR2: 5.7710






3C298 2023/11/05 2.24UT TOYOKAWA-KISO




F20231105111255





K20231105111252




3C298 2023/11/05 2.24UT FUJI -KISO



T20231105112438





BLK:10,SNR1: 0.31499 ,SNR2: 1.8249




1428-03 2023/11/05 2.44UT TOYOKAWA-FUJI


F20231105112439



BLK:10,SNR1: 0.86788 ,SNR2: 3.7219




Frequency (Hz)







T20231105112438




BLK:14,SNR1: 0.33622 ,SNR2: 1.5257




K20231105112436





BLK:14,SNR1: 0.53518 ,SNR2: 2.7046




1428-03 2023/11/05 2.44UT TOYOKAWA-KISO





F20231105112439




BLK: 4, SNR1: 1.6903 , SNR2: 6.5735




K20231105112436




BLK: 4, SNR1: 0.28305 , SNR2: 4.7839




1428-03 2023/11/05 2.44UT FUJI -KISO



T20231105113040




BLK: 7,SNR1: 0.27377 ,SNR2: 1.8809





1434+03 2023/11/05 2.54UT TOYOKAWA-FUJI


F20231105113041




BLK: 7,SNR1: 2.6651 ,SNR2: 8.0299




T20231105113040




BLK:17,SNR1: 0.19801 ,SNR2: 1.3184




K20231105113038




BLK:17,SNR1: 14.255 ,SNR2: 23.962




1434+03 2023/11/05 2.54UT TOYOKAWA-KISO




F20231105113041




BLK:11,SNR1: 1.2378 ,SNR2: 8.2480




K20231105113038





BLK:11,SNR1: 9.7045 ,SNR2: 16.375




1434+03 2023/11/05 2.54UT FUJI -KISO



T20231105114942




BLK: 3,SNR1:-0.55357E-01,SNR2: 0.59710




Frequency (Hz)

F20231105114943




BLK: 3,SNR1: 0.84716 ,SNR2: 2.9607





Frequency (Hz)


1453-10 2023/11/05 2.86UT TOYOKAWA-FUJI



T20231105114942




BLK: 2,SNR1: -0.11779 ,SNR2: 0.72878





1453-10 2023/11/05 2.86UT TOYOKAWA-KISO


K20231105114940




BLK: 2,SNR1: 4.7931 ,SNR2: 17.382




F20231105114943




BLK: 2,SNR1: 0.47877E-01,SNR2: 0.74496




K20231105114940



BLK: 2,SNR1: 0.46718E-01,SNR2: 0.99641





1453-10 2023/11/05 2.86UT FUJI -KISO






T20231105120435




BLK: 6,SNR1: 0.36664 ,SNR2: 2.2098





1508-05 2023/11/05 3.10UT TOYOKAWA-FUJI


F20231105120435




BLK: 6,SNR1: 0.20339 ,SNR2: 1.1604




T20231105120435




BLK:13,SNR1: 0.20748 ,SNR2: 2.0387




K20231105120433





BLK:13,SNR1: 0.57159 ,SNR2: 2.5046




1508-05 2023/11/05 3.10UT TOYOKAWA-KISO





F20231105120435




BLK: 2,SNR1: 0.92883E-02,SNR2: 0.30856




K20231105120433




BLK: 2,SNR1: 0.59581 ,SNR2: 6.0022




1508-05 2023/11/05 3.10UT FUJI -KISO




T20231105121335




BLK: 9,SNR1: 0.31063 ,SNR2: 2.9437




F20231105121336




BLK: 9,SNR1: 0.81071E-02,SNR2: 1.4074




3C318 2023/11/05 3.25UT TOYOKAWA-FUJI



T20231105121335





BLK:13,SNR1: 0.14389 ,SNR2: 0.99772





3C318 2023/11/05 3.25UT TOYOKAWA-KISO


K20231105121333




BLK:13,SNR1: 0.45122E-02,SNR2: 0.78045



F20231105121336





BLK: 3,SNR1: 0.37942 ,SNR2: 2.1690





3C318 2023/11/05 3.25UT FUJI -KISO



K20231105121333




BLK: 3,SNR1: 0.13089E-01,SNR2: 0.49562



T20231105121922




BLK: 7,SNR1: 0.46532 ,SNR2: 1.9205





1523+03 2023/11/05 3.35UT TOYOKAWA-FUJI



F20231105121922




BLK: 7,SNR1:-0.18916 ,SNR2: 0.86601




T20231105121922




BLK:14,SNR1: 1.0896 ,SNR2: 7.2094




K20231105121920



BLK:14,SNR1: 0.59742 ,SNR2: 2.6588





1523+03 2023/11/05 3.35UT TOYOKAWA-KISO









F20231105121922




K20231105121920




1523+03 2023/11/05 3.35UT FUJI -KISO




T20231105123101




BLK: 2,SNR1:-0.11793 ,SNR2: 0.48411




F20231105123102




BLK: 2,SNR1: 0.13043E-01,SNR2: 1.0343




1535+139 2023/11/05 3.55UT TOYOKAWA-FUJI





T20231105123101




BLK: 4,SNR1: 0.96416E-01,SNR2: 0.60116




K20231105123058




BLK: 4,SNR1: 0.38772 ,SNR2: 2.1717




1535+139 2023/11/05 3.55UT TOYOKAWA-KISO





F20231105123102




BLK: 6,SNR1: 0.10646 ,SNR2: 0.74648




K20231105123058







BLK: 6,SNR1: 0.69645 ,SNR2: 3.3136





1535+139 2023/11/05 3.55UT FUJI -KISO







1545-12 2023/11/05 3.72UT TOYOKAWA-FUJI







BLK:17,SNR1: 0.27921 ,SNR2: 3.1200




BLK:17,SNR1: 0.31363 ,SNR2: 1.8399




1545-12 2023/11/05 3.72UT TOYOKAWA-KISO





F20231105124126




BLK: 3,SNR1: 0.22311 ,SNR2: 1.7832




K20231105124122





BLK: 3,SNR1: 0.48655 ,SNR2: 3.4500




1545-12 2023/11/05 3.72UT FUJI -KISO




T20231105130229




BLK: 8,SNR1: 1.4230 ,SNR2: 4.6082




F20231105130230



BLK: 8,SNR1: 0.77329E-01,SNR2: 0.99037





1607+26 2023/11/05 4.07UT TOYOKAWA-FUJI








T20231105130229




BLK: 4,SNR1: 2.4629 ,SNR2: 18.858




K20231105130226





BLK: 4,SNR1: 0.39196E-01,SNR2: 1.7989




1607+26 2023/11/05 4.07UT TOYOKAWA-KISO




F20231105130230




BLK: 7,SNR1: 0.12445 ,SNR2: 1.0847




K20231105130226





BLK: 7,SNR1: 0.51052E-01,SNR2: 2.6793




1607+26 2023/11/05 4.07UT FUJI -KISO





T20231105133406




BLK: 4,SNR1: 0.98593E-01,SNR2: 0.78288




F20231105133407





BLK: 4,SNR1:-0.12340 ,SNR2: 1.9929




1638-025 2023/11/05 4.60UT TOYOKAWA-FUJI





T20231105133406




BLK: 7,SNR1: 1.9848 ,SNR2: 17.560




K20231105133403




BLK: 7,SNR1: 0.43977 ,SNR2: 1.6002




1638-025 2023/11/05 4.60UT TOYOKAWA-KISO



F20231105133407





BLK: 1,SNR1:-0.69638E-01,SNR2: 0.44789




Frequency (Hz)

K20231105133403




BLK: 1,SNR1: 0.73978 ,SNR2: 3.5484





Frequency (Hz)


1638-025 2023/11/05 4.60UT FUJI -KISO





T20231105134100




BLK: 3,SNR1: 0.21371 ,SNR2: 3.0268




F20231105134101







BLK: 3,SNR1:-0.18155 ,SNR2: 1.5879




1644-106 2023/11/05 4.71UT TOYOKAWA-FUJI







1644-106 2023/11/05 4.71UT TOYOKAWA-KISO




F20231105134101




BLK: 5,SNR1:-0.13777 ,SNR2: 1.8498




K20231105134057



BLK: 5,SNR1: 0.42653 ,SNR2: 2.3141





1644-106 2023/11/05 4.71UT FUJI -KISO








T20231105134621




BLK: 4,SNR1: 0.20544 ,SNR2: 2.5767




F20231105134621





BLK: 4,SNR1:-0.17174 ,SNR2: 1.4027




1650+004 2023/11/05 4.80UT TOYOKAWA-FUJI





T20231105134621




BLK: 9,SNR1: 0.93693E-01,SNR2: 1.1042




K20231105134618





BLK: 9,SNR1: 0.70700 ,SNR2: 2.0574




1650+004 2023/11/05 4.80UT TOYOKAWA-KISO





F20231105134621




BLK: 3,SNR1:-0.33303 ,SNR2: 0.13529




K20231105134618





BLK: 3,SNR1: 0.11888 ,SNR2: 0.50770




1650+004 2023/11/05 4.80UT FUJI -KISO





T20231105135153




BLK: 3,SNR1: 0.16989 ,SNR2: 1.4095




F20231105135154




BLK: 3,SNR1: 0.50400 ,SNR2: 5.5763




1656+053 2023/11/05 4.89UT TOYOKAWA-FUJI





T20231105135153




BLK: 2,SNR1: 0.13833 ,SNR2: 0.53749




K20231105135150




BLK: 2,SNR1: 0.11478 ,SNR2: 0.56411




1656+053 2023/11/05 4.89UT TOYOKAWA-KISO




F20231105135154




BLK: 5,SNR1:-0.20905 ,SNR2: 0.89939




K20231105135150





BLK: 5,SNR1: 0.35490 ,SNR2: 3.6709




1656+053 2023/11/05 4.89UT FUJI -KISO




T20231105140823




BLK: 4,SNR1: 0.50594E-01,SNR2: 1.6546




F20231105140824





BLK: 4,SNR1:-0.16552 ,SNR2: 0.72778




1712-033 2023/11/05 5.17UT TOYOKAWA-FUJI





T20231105140823




BLK: 5,SNR1: 0.79439E-01,SNR2: 0.71469




K20231105140820







BLK: 5,SNR1: 0.29145 ,SNR2: 1.4494




1712-033 2023/11/05 5.17UT TOYOKAWA-KISO










1712-033 2023/11/05 5.17UT FUJI -KISO





T20231105142625




BLK: 3,SNR1: 0.56700E-01,SNR2: 0.74606




F20231105142625





BLK: 3,SNR1:-0.14471 ,SNR2: 0.53268




1730-13 2023/11/05 5.47UT TOYOKAWA-FUJI




T20231105142625




BLK: 3,SNR1: 0.16956E-01,SNR2: 1.1056




K20231105142622





BLK: 3,SNR1: 0.54873E-01,SNR2: 0.57927




1730-13 2023/11/05 5.47UT TOYOKAWA-KISO





F20231105142625




BLK: 4,SNR1: 0.34368E-01,SNR2: 0.67382




K20231105142622





BLK: 4,SNR1: 0.12580 ,SNR2: 0.72995




1730-13 2023/11/05 5.47UT FUJI -KISO





T20231105144350




BLK: 5,SNR1: 0.17893 ,SNR2: 0.69741




F20231105144351





BLK: 5,SNR1:-0.21850 ,SNR2: 1.7970




1748+031 2023/11/05 5.76UT TOYOKAWA-FUJI





T20231105144350




BLK: 2,SNR1: 0.23903 ,SNR2: 1.1777




K20231105144347





BLK: 2,SNR1: 2.6794 ,SNR2: 13.602




1748+031 2023/11/05 5.76UT TOYOKAWA-KISO





F20231105144351




BLK: 3,SNR1:-0.15141 ,SNR2: 1.9804




K20231105144347





BLK: 3,SNR1: 0.73873 ,SNR2: 3.4246




1748+031 2023/11/05 5.76UT FUJI -KISO





T20231105145443




BLK:12,SNR1: 0.35613 ,SNR2: 2.9425




F20231105145444



BLK:12,SNR1:-0.10396E-01,SNR2: 0.91057






1759+13 2023/11/05 5.94UT TOYOKAWA-FUJI











T20231105145443




K20231105145440





F20231105145444




BLK: 4,SNR1:-0.20266E-01,SNR2: 1.6966




K20231105145440





BLK: 4,SNR1: 0.19723 ,SNR2: 0.82973




1759+13 2023/11/05 5.94UT FUJI -KISO





T20231105151543




BLK: 2,SNR1: 0.59092 ,SNR2: 1.2790




F20231105151543





BLK: 2,SNR1: -0.15982 ,SNR2: 1.5307




1819-096 2023/11/05 6.29UT TOYOKAWA-FUJI





T20231105151543




BLK: 3,SNR1:-0.28248E-01,SNR2: 0.34928




K20231105151540





BLK: 3,SNR1: 1.4462 ,SNR2: 2.4373




1819-096 2023/11/05 6.29UT TOYOKAWA-KISO



F20231105151543





BLK: 6,SNR1: 0.68342 ,SNR2: 3.1228




Frequency (Hz)

K20231105151540




BLK: 6,SNR1: 0.37833 ,SNR2: 1.6823





Frequency (Hz)


1819-096 2023/11/05 6.29UT FUJI -KISO





T20231105155323




BLK: 1,SNR1:-0.10437 ,SNR2: 0.0000




F20231105155324





BLK: 1,SNR1: 1.3966 ,SNR2: 4.0697




1858+171 2023/11/05 6.92UT TOYOKAWA-FUJI





T20231105155323




BLK: 2,SNR1: 0.17728 ,SNR2: 0.82495




K20231105155320





BLK: 2,SNR1: 3.5236 ,SNR2: 14.789




1858+171 2023/11/05 6.92UT TOYOKAWA-KISO





F20231105155324




BLK: 2,SNR1:-0.14643 ,SNR2: 0.33505




K20231105155320





BLK: 2,SNR1: 0.40048 ,SNR2: 1.9062




1858+171 2023/11/05 6.92UT FUJI -KISO










1915-121 2023/11/05 7.21UT TOYOKAWA-FUJI








1915-121 2023/11/05 7.21UT TOYOKAWA-KISO





F20231105161058




BLK: 3,SNR1: 0.75741E-01,SNR2: 2.9579




K20231105161055





BLK: 3,SNR1: 0.67020 ,SNR2: 4.3757






1915-121 2023/11/05 7.21UT FUJI -KISO






1928-142 2023/11/05 7.44UT TOYOKAWA-FUJI







1928-142 2023/11/05 7.44UT TOYOKAWA-KISO





F20231105162440




BLK: 3,SNR1: 0.37175 ,SNR2: 1.5695




K20231105162437





BLK: 3,SNR1:-0.50315E-02,SNR2: 0.22569




1928-142 2023/11/05 7.44UT FUJI -KISO



T20231105164907




BLK: 4,SNR1: 0.45166 ,SNR2: 3.4112




Frequency (Hz)

F20231105164908




BLK: 4,SNR1: 0.90882 ,SNR2: 2.2309





Frequency (Hz)


1953-077 2023/11/05 7.85UT TOYOKAWA-FUJI





T20231105164907




BLK: 5,SNR1: 0.13170 ,SNR2: 3.4892




K20231105164905







BLK: 5,SNR1: 0.42264 ,SNR2: 2.8625



1953-077 2023/11/05 7.85UT TOYOKAWA-KISO







1953-077 2023/11/05 7.85UT FUJI -KISO

