




T20231106060521




BLK: 4,SNR1: 0.64156E-01,SNR2: 0.67695




Frequency (Hz)

F20231106060522






BLK: 4,SNR1: 3.6526 ,SNR2: 10.061






Frequency (Hz)

0912-132 2023/11/05 21.12UT TOYOKAWA-FUJI







BLK: 3, SNR1:  $-0.44990E-01$ , SNR2: 0.81809



BLK: 3, SNR1: 0.71074 ,SNR2: 8.4780





0912-132 2023/11/05 21.12UT TOYOKAWA-KISO






F20231106060522





BLK: 7,SNR1: 0.99248 ,SNR2: 5.0954




Frequency (Hz)

K20231106060518




BLK: 7,SNR1: 0.10965 ,SNR2: 0.51746





Frequency (Hz)


0912-132 2023/11/05 21.12UT FUJI -KISO



T20231106061927





BLK: 8,SNR1: 0.73390 ,SNR2: 2.1352




Frequency (Hz)

F20231106061928




BLK: 8,SNR1: 3.0213 ,SNR2: 12.359





Frequency (Hz)


0926+117 2023/11/05 21.35UT TOYOKAWA-FUJI



T20231106061927





BLK: 4,SNR1: 0.32850E-01,SNR2: 0.41883




Frequency (Hz)

K20231106061924




BLK: 4,SNR1: 78.636 ,SNR2: 75.656




Frequency (Hz)


0926+117 2023/11/05 21.35UT TOYOKAWA-KISO



F20231106061928





BLK:14,SNR1: 3.0403 ,SNR2: 12.418




Frequency (Hz)

0926+117 2023/11/05 21.35UT FUJI -KISO


K20231106061924






BLK:14,SNR1: 74.799 ,SNR2: 69.337






Frequency (Hz)




T20231106062712





F20231106062712




3C222 2023/11/05 21.48UT TOYOKAWA-FUJI





T20231106062712




BLK: 6,SNR1: 0.75980 ,SNR2: 5.4774




K20231106062709





BLK: 6,SNR1: 83.788 ,SNR2: 80.997




3C222 2023/11/05 21.48UT TOYOKAWA-KISO



F20231106062712





BLK: 4,SNR1: 0.76507 ,SNR2: 1.9172





3C222 2023/11/05 21.48UT FUJI -KISO



K20231106062709




BLK: 4,SNR1: 79.123 ,SNR2: 76.487



T20231106063412





BLK:18,SNR1: 8.9735 ,SNR2: 19.558




Frequency (Hz)

0941-08 2023/11/05 21.60UT TOYOKAWA-FUJI


F20231106063413



BLK:18,SNR1: 3.2940 ,SNR2: 13.285





Frequency (Hz)






T20231106063412




BLK: 4,SNR1: 8.6924 ,SNR2: 23.897




Frequency (Hz)

K20231106063409




BLK: 4,SNR1: 3.3427 ,SNR2: 13.268





Frequency (Hz)


0941-08 2023/11/05 21.60UT TOYOKAWA-KISO



F20231106063413





BLK:10,SNR1: 8.7557 ,SNR2: 19.235




Frequency (Hz)

K20231106063409




BLK:10,SNR1: 3.3399 ,SNR2: 13.256





Frequency (Hz)


0941-08 2023/11/05 21.60UT FUJI -KISO



T20231106064234





BLK:10,SNR1: 0.32646 ,SNR2: 1.1278




Frequency (Hz)

F20231106064235




BLK:10,SNR1: 7.8931 ,SNR2: 17.381




Frequency (Hz)


3C230 2023/11/05 21.74UT TOYOKAWA-FUJI



T20231106064234





BLK:10,SNR1: 0.16525 ,SNR2: 1.7218




Frequency (Hz)

K20231106064231




BLK:10,SNR1: 14.770 ,SNR2: 15.152





Frequency (Hz)


3C230 2023/11/05 21.74UT TOYOKAWA-KISO



F20231106064235




BLK:14,SNR1: 8.0001 ,SNR2: 17.634




Frequency (Hz)

3C230 2023/11/05 21.74UT FUJI -KISO


K20231106064231





BLK:14,SNR1: 1.7005 ,SNR2: 6.2047




Frequency (Hz)





T20231106065834




BLK: 5,SNR1: 0.22833 ,SNR2: 1.2188




F20231106065835





BLK: 5,SNR1: 0.18727 ,SNR2: 1.4054




3C237 2023/11/05 22.00UT TOYOKAWA-FUJI



T20231106065834





BLK: 6,SNR1: 0.18638 ,SNR2: 0.88952




Frequency (Hz)

3C237 2023/11/05 22.00UT TOYOKAWA-KISO


K20231106065831





BLK: 6,SNR1: 4.7540 ,SNR2: 16.678




Frequency (Hz)



F20231106065835




BLK: 6,SNR1: 0.12257 ,SNR2: 1.4724




Frequency (Hz)

3C237 2023/11/05 22.00UT FUJI -KISO


K20231106065831



BLK: 6,SNR1: 6.6485 ,SNR2: 22.103





Frequency (Hz)






T20231106070451




BLK: 6,SNR1:-0.33708E-01,SNR2: 0.11137




Frequency (Hz)

F20231106070452




BLK: 6,SNR1: 6.4652 ,SNR2: 14.250





Frequency (Hz)


1011+110 2023/11/05 22.11UT TOYOKAWA-FUJI



T20231106070451




BLK: 3,SNR1:-0.52991E-01,SNR2: 0.19357




Frequency (Hz)

K20231106070448




BLK: 3,SNR1: 3.7380 ,SNR2: 15.109




Frequency (Hz)


1011+110 2023/11/05 22.11UT TOYOKAWA-KISO



F20231106070452





BLK: 8,SNR1: 0.81185 ,SNR2: 5.9029




Frequency (Hz)

K20231106070448




BLK: 8,SNR1: 8.6588 ,SNR2: 32.468





Frequency (Hz)


1011+110 2023/11/05 22.11UT FUJI -KISO



T20231106071231




BLK: 1,SNR1: 0.14395 ,SNR2: 0.59909




Frequency (Hz)

3C241 2023/11/05 22.24UT TOYOKAWA-FUJI


F20231106071232





BLK: 1,SNR1: 0.41745 ,SNR2: 5.6111




Frequency (Hz)



T20231106071231




BLK: 8,SNR1: 0.10581 ,SNR2: 1.1673




Frequency (Hz)

3C241 2023/11/05 22.24UT TOYOKAWA-KISO


K20231106071229




BLK: 8,SNR1: 14.237 ,SNR2: 27.155




Frequency (Hz)



F20231106071232




BLK: 9,SNR1:-0.15485 ,SNR2: 0.94316




Frequency (Hz)

3C241 2023/11/05 22.24UT FUJI -KISO


K20231106071229





BLK: 9,SNR1: 14.744 ,SNR2: 18.481




Frequency (Hz)



T20231106072401




BLK: 4,SNR1: 0.99570E-01,SNR2: 0.70485




Frequency (Hz)

F20231106072401




BLK: 4,SNR1: 2.4451 ,SNR2: 7.4513





Frequency (Hz)


1031-11 2023/11/05 22.43UT TOYOKAWA-FUJI



T20231106072401




BLK: 2,SNR1:-0.10329 ,SNR2: 0.20905




Frequency (Hz)

K20231106072359




BLK: 2,SNR1: 0.82390 ,SNR2: 5.6602




Frequency (Hz)

1031-11 2023/11/05 22.43UT TOYOKAWA-KISO






F20231106072401




BLK: 4,SNR1: 2.8030 ,SNR2: 8.3579




Frequency (Hz)

K20231106072359




BLK: 4,SNR1: 0.91758 ,SNR2: 5.7433





Frequency (Hz)


1031-11 2023/11/05 22.43UT FUJI -KISO





T20231106072834




BLK: 4,SNR1: 26.808 ,SNR2: 181.39




F20231106072834




BLK: 4,SNR1:-0.13705 ,SNR2: 0.56951




1035-058 2023/11/05 22.50UT TOYOKAWA-FUJI



T20231106072834





BLK:12,SNR1: 9.7630 ,SNR2: 37.403




Frequency (Hz)

1035-058 2023/11/05 22.50UT TOYOKAWA-KISO


K20231106072832





BLK:12,SNR1: 8.4972 ,SNR2: 34.871




Frequency (Hz)




F20231106072834




No.Good Data




K20231106072832





No.Good Data




1035-058 2023/11/05 22.50UT FUJI -KISO



T20231106073747




BLK: 3,SNR1: 0.45101E-01,SNR2: 0.35777




Frequency (Hz)

F20231106073748




BLK: 3,SNR1:-0.10147 ,SNR2: 0.86401





Frequency (Hz)


1044-008 2023/11/05 22.66UT TOYOKAWA-FUJI




T20231106073747




BLK: 5,SNR1: 0.46681E-01,SNR2: 0.48335




K20231106073744




BLK: 5,SNR1: 3.1647 ,SNR2: 13.352




1044-008 2023/11/05 22.66UT TOYOKAWA-KISO




F20231106073748




BLK: 2,SNR1:-0.13546 ,SNR2: 1.6062




K20231106073744





BLK: 2,SNR1: 13.354 ,SNR2: 45.455




1044-008 2023/11/05 22.66UT FUJI -KISO



T20231106074852




BLK: 4,SNR1: 0.13833 ,SNR2: 1.3617




Frequency (Hz)

F20231106074853




BLK: 4,SNR1:-0.66831E-01,SNR2: 0.49001





Frequency (Hz)

1055+01 2023/11/05 22.84UT TOYOKAWA-FUJI






T20231106074852





BLK: 3,SNR1: 0.44460 ,SNR2: 3.0895





1055+01 2023/11/05 22.84UT TOYOKAWA-KISO



K20231106074850




BLK: 3,SNR1: 23.266 ,SNR2: 39.437



F20231106074853





BLK: 5, SNR1: 0.84674 , SNR2: 2.6328




Frequency (Hz)

K20231106074850




BLK: 5, SNR1: 87.416 , SNR2: 84.104




Frequency (Hz)


1055+01 2023/11/05 22.84UT FUJI -KISO




T20231106080009




BLK: 8,SNR1: 0.32916E-01,SNR2: 0.23979




F20231106080010





BLK: 8,SNR1:-0.49825E-01,SNR2: 1.3688




1107+109 2023/11/05 23.03UT TOYOKAWA-FUJI



T20231106080009





BLK: 5,SNR1: 0.12568 ,SNR2: 0.32810




Frequency (Hz)

K20231106080006




BLK: 5,SNR1: 2.2033 ,SNR2: 7.8890





Frequency (Hz)


1107+109 2023/11/05 23.03UT TOYOKAWA-KISO



F20231106080010





BLK: 2,SNR1:-0.25918 ,SNR2: 0.67661




Frequency (Hz)

K20231106080006




BLK: 2,SNR1: 3.8073 ,SNR2: 12.166




Frequency (Hz)


1107+109 2023/11/05 23.03UT FUJI -KISO




T20231106080946




BLK: 4,SNR1: 0.16114 ,SNR2: 1.1746




F20231106080947





BLK: 4,SNR1:-0.26868 ,SNR2: 0.63607




3C255 2023/11/05 23.19UT TOYOKAWA-FUJI



T20231106080946





BLK: 4, SNR1: 0.20584 , SNR2: 0.70556




Frequency (Hz)

3C255 2023/11/05 23.19UT TOYOKAWA-KISO


K20231106080943




BLK: 4, SNR1: 16.397 , SNR2: 56.248




Frequency (Hz)



F20231106080947





BLK: 3,SNR1: 0.97814E-01,SNR2: 1.3581





3C255 2023/11/05 23.19UT FUJI -KISO

K20231106080943




BLK: 3,SNR1: 31.972 ,SNR2: 154.99






T20231106083344




BLK: 5,SNR1: 0.39991 ,SNR2: 1.1730




Frequency (Hz)

F20231106083345




BLK: 5,SNR1: 0.45953 ,SNR2: 4.5465





Frequency (Hz)


3C263.1 2023/11/05 23.59UT TOYOKAWA-FUJI





T20231106083344




BLK: 4,SNR1: 0.26105 ,SNR2: 1.1074




K20231106083341




BLK: 4,SNR1: 0.72789 ,SNR2: 5.7912




3C263.1 2023/11/05 23.59UT TOYOKAWA-KISO



F20231106083345




BLK: 5,SNR1: 0.24985 ,SNR2: 1.4469





3C263.1 2023/11/05 23.59UT FUJI -KISO


K20231106083341




BLK: 5,SNR1: 7.7502 ,SNR2: 36.724



T20231106084011




BLK: 3,SNR1: 0.10381 ,SNR2: 0.61907




Frequency (Hz)

3C267 2023/11/05 23.70UT TOYOKAWA-FUJI


F20231106084011





BLK: 3,SNR1: 0.33939 ,SNR2: 1.2077




Frequency (Hz)



T20231106084011





BLK: 3,SNR1: 0.22257 ,SNR2: 0.75225





3C267 2023/11/05 23.70UT TOYOKAWA-KISO


K20231106084008




BLK: 3,SNR1: 7.4170 ,SNR2: 25.322





F20231106084011




BLK:10,SNR1: 0.13777 ,SNR2: 0.85603




K20231106084008




BLK:10,SNR1: 2.5556 ,SNR2: 9.2562




3C267 2023/11/05 23.70UT FUJI -KISO



T20231106091916





BLK:21,SNR1: 3.1091 ,SNR2: 17.516




Frequency (Hz)

3C273 2023/11/06 0.35UT TOYOKAWA-FUJI


F20231106091916





BLK:21,SNR1:-0.18211 ,SNR2: 1.1775




Frequency (Hz)



T20231106091916





BLK:32,SNR1: 3.0192 ,SNR2: 16.588




Frequency (Hz)

3C273 2023/11/06 0.35UT TOYOKAWA-KISO


K20231106091913



BLK:32,SNR1: 2.5060 ,SNR2: 4.5387




Frequency (Hz)






F20231106091916





BLK:18,SNR1:-0.16312 ,SNR2: 1.4806





3C273 2023/11/06 0.35UT FUJI -KISO


K20231106091913




BLK:18,SNR1: 0.57267 ,SNR2: 3.1681



T20231106093227




BLK:11,SNR1: 0.12542 ,SNR2: 1.5034





3C275 2023/11/06 0.57UT TOYOKAWA-FUJI


F20231106093228




BLK:11,SNR1: 2.5203 ,SNR2: 12.485



T20231106093227




BLK:13,SNR1: 0.25243 ,SNR2: 1.8988





3C275 2023/11/06 0.57UT TOYOKAWA-KISO


K20231106093224




BLK:13,SNR1: 0.27691 ,SNR2: 2.2344



F20231106093228




BLK: 2, SNR1: 8.4524 ,SNR2: 23.170





3C275 2023/11/06 0.57UT FUJI -KISO


K20231106093224




BLK: 2, SNR1: 0.20110 ,SNR2: 0.40873



T20231106094616




BLK: 6,SNR1: 0.49642 ,SNR2: 3.3435





3C279 2023/11/06 0.80UT TOYOKAWA-FUJI


F20231106094617




BLK: 6,SNR1:-0.25832 ,SNR2: 0.79904



T20231106094616





BLK:25,SNR1: 0.59772 ,SNR2: 5.0458





3C279 2023/11/06 0.80UT TOYOKAWA-KISO


K20231106094613




BLK:25,SNR1: 0.37519 ,SNR2: 1.1618



F20231106094617





BLK: 3,SNR1: 0.82058E-01,SNR2: 2.7202









3C279 2023/11/06 0.80UT FUJI -KISO

K20231106094613




BLK: 3,SNR1: 1.2179 ,SNR2: 5.6911










1313+453 2023/11/06 1.13UT TOYOKAWA-FUJI









1313+453 2023/11/06 1.13UT TOYOKAWA-KISO




F20231106100605




BLK: 6,SNR1: 0.33495 ,SNR2: 3.8933




K20231106100601




BLK: 6,SNR1: 0.15943 ,SNR2: 0.56277





1313+453 2023/11/06 1.13UT FUJI -KISO







BLK: 7,SNR1: 0.76972E-01,SNR2: 0.29256





BLK: 7,SNR1: 0.32503 ,SNR2: 1.4846




1323+32 2023/11/06 1.30UT TOYOKAWA-FUJI



T20231106101610





BLK: 4,SNR1: 0.14693 ,SNR2: 0.53153




Frequency (Hz)

K20231106101607




BLK: 4,SNR1: 1.0015 ,SNR2: 5.3415




Frequency (Hz)


1323+32 2023/11/06 1.30UT TOYOKAWA-KISO




F20231106101610




BLK: 7, SNR1: -0.63219E-01, SNR2: 2.2298




K20231106101607




BLK: 7, SNR1: 0.13677, SNR2: 1.4642




1323+32 2023/11/06 1.30UT FUJI -KISO



T20231106102100




BLK:14,SNR1: 0.42686 ,SNR2: 2.3874





3C286 2023/11/06 1.38UT TOYOKAWA-FUJI


F20231106102101




BLK:14,SNR1: 0.27036 ,SNR2: 1.7797




T20231106102100




BLK:12,SNR1: 0.40692 ,SNR2: 2.9915




K20231106102057




BLK:12,SNR1: 0.22200 ,SNR2: 1.9356




3C286 2023/11/06 1.38UT TOYOKAWA-KISO



F20231106102101




BLK: 7,SNR1: 0.22889 ,SNR2: 2.8275





3C286 2023/11/06 1.38UT FUJI -KISO

K20231106102057




BLK: 7,SNR1: 0.35568 ,SNR2: 1.6311






T20231106103727





BLK:11,SNR1: 1.1026 ,SNR2: 6.6362





1345+12 2023/11/06 1.65UT TOYOKAWA-FUJI


F20231106103727




BLK:11,SNR1: 0.62084 ,SNR2: 2.6777




T20231106103727




BLK:24,SNR1: 1.0215 ,SNR2: 3.2646




K20231106103724





BLK:24,SNR1: 0.23844 ,SNR2: 1.3957




1345+12 2023/11/06 1.65UT TOYOKAWA-KISO




F20231106103727




BLK:19,SNR1: 4.0855 ,SNR2: 16.674




K20231106103724







BLK:19,SNR1: 3.0211 ,SNR2: 12.669








1345+12 2023/11/06 1.65UT FUJI -KISO






1355+01 2023/11/06 1.82UT TOYOKAWA-FUJI








1355+01 2023/11/06 1.82UT TOYOKAWA-KISO



F20231106104749





BLK: 4,SNR1:-0.18334 ,SNR2: 0.49668E-01




Frequency (Hz)

1355+01 2023/11/06 1.82UT FUJI -KISO


K20231106104745




BLK: 4,SNR1: 0.31771 ,SNR2: 2.8428




Frequency (Hz)





T20231106110858




BLK:26,SNR1: 2.4768 ,SNR2: 11.889




F20231106110859





BLK:26,SNR1: 0.17303 ,SNR2: 1.0877




3C298 2023/11/06 2.18UT TOYOKAWA-FUJI



T20231106110858





BLK:35,SNR1: 2.5447 ,SNR2: 19.373




3C298 2023/11/06 2.18UT TOYOKAWA-KISO


K20231106110855



BLK:35,SNR1: 0.47518 ,SNR2: 2.9681




Frequency (Hz)






F20231106110859




BLK:28,SNR1: 0.15411 ,SNR2: 0.98938





3C298 2023/11/06 2.18UT FUJI -KISO


K20231106110855




BLK:28,SNR1: 0.50200 ,SNR2: 3.2799



T20231106112042




BLK: 9,SNR1: 0.15854 ,SNR2: 1.2480





1428-03 2023/11/06 2.37UT TOYOKAWA-FUJI


F20231106112043




BLK: 9,SNR1: 0.11072 ,SNR2: 5.5446





T20231106112042




BLK:10,SNR1: 0.12873 ,SNR2: 1.9204




K20231106112039





BLK:10,SNR1: 0.32452 ,SNR2: 1.3343




1428-03 2023/11/06 2.37UT TOYOKAWA-KISO



F20231106112043





BLK: 3,SNR1: 1.1079 ,SNR2: 6.8743





1428-03 2023/11/06 2.37UT FUJI -KISO


K20231106112039




BLK: 3,SNR1: 0.19486 ,SNR2: 0.95043




T20231106112644




BLK: 7,SNR1: 0.26817 ,SNR2: 2.1485




F20231106112645





BLK: 7,SNR1: 0.19268 ,SNR2: 1.5333




1434+03 2023/11/06 2.47UT TOYOKAWA-FUJI



T20231106112644





BLK:13,SNR1: 0.80335 ,SNR2: 6.9027









1434+03 2023/11/06 2.47UT TOYOKAWA-KISO

K20231106112641




BLK:13,SNR1: 0.70009 ,SNR2: 5.5021








1434+03 2023/11/06 2.47UT FUJI -KISO




T20231106114546




BLK: 7,SNR1: 0.22973E-01,SNR2: 0.70196




F20231106114547



BLK: 7,SNR1: 0.65821 ,SNR2: 1.9165




1453-10 2023/11/06 2.79UT TOYOKAWA-FUJI






T20231106114546




BLK:10,SNR1: 0.78238E-01,SNR2: 0.43594





1453-10 2023/11/06 2.79UT TOYOKAWA-KISO



K20231106114543




BLK:10,SNR1: 0.70945 ,SNR2: 2.5363





F20231106114547




BLK: 7,SNR1: 0.53524E-01,SNR2: 1.2084




K20231106114543





BLK: 7,SNR1: 1.0297 ,SNR2: 7.4733




1453-10 2023/11/06 2.79UT FUJI -KISO



T20231106120039




BLK:11,SNR1: 0.12957 ,SNR2: 1.7911





1508-05 2023/11/06 3.04UT TOYOKAWA-FUJI



F20231106120040




BLK:11,SNR1: 1.0077 ,SNR2: 5.0137





T20231106120039




BLK:15,SNR1: 0.20694 ,SNR2: 2.8628




K20231106120037




BLK:15,SNR1: 0.31892 ,SNR2: 3.3953




1508-05 2023/11/06 3.04UT TOYOKAWA-KISO



F20231106120040





BLK: 6,SNR1: 3.1689 ,SNR2: 14.109





1508-05 2023/11/06 3.04UT FUJI -KISO



K20231106120037




BLK: 6,SNR1: 1.4823 ,SNR2: 6.1289




T20231106120939




BLK: 8,SNR1: 0.46353 ,SNR2: 5.1242




F20231106120940




BLK: 8,SNR1: 0.26673E-01,SNR2: 1.6638




3C318 2023/11/06 3.19UT TOYOKAWA-FUJI



T20231106120939





BLK:16,SNR1: 0.41481 ,SNR2: 3.5865





3C318 2023/11/06 3.19UT TOYOKAWA-KISO


K20231106120936




BLK:16,SNR1: 0.34204 ,SNR2: 1.3557





F20231106120940




BLK: 6,SNR1:-0.83614E-01,SNR2: 1.8163




K20231106120936



BLK: 6,SNR1: 0.98608E-01,SNR2: 1.4434




30318 2023/11/06 3.19UT FUJI -KISO






T20231106121526




BLK: 8,SNR1: 0.59056 ,SNR2: 3.2810




1523+03 2023/11/06 3.29UT TOYOKAWA-FUJI


F20231106121527




BLK: 8,SNR1:-0.28381 ,SNR2: 1.1245




Frequency (Hz)





T20231106121526




BLK:13,SNR1: 0.48878 ,SNR2: 3.0695




K20231106121523




BLK:13,SNR1: 0.24950 ,SNR2: 2.4043




1523+03 2023/11/06 3.29UT TOYOKAWA-KISO



F20231106121527





BLK: 3,SNR1:-0.11937 ,SNR2: 2.3815





1523+03 2023/11/06 3.29UT FUJI -KISO


K20231106121523




BLK: 3,SNR1: 0.51120 ,SNR2: 1.6847




T20231106122705




BLK: 4,SNR1:-0.40708E-01,SNR2: 0.43124




F20231106122706





BLK: 4,SNR1:-0.31655E-01,SNR2: 1.0186




1535+139 2023/11/06 3.48UT TOYOKAWA-FUJI





T20231106122705




BLK: 4,SNR1:-0.17708E-01,SNR2: 0.47255




K20231106122702





BLK: 4,SNR1: 0.83871E-01,SNR2: 0.84771




1535+139 2023/11/06 3.48UT TOYOKAWA-KISO



F20231106122706





BLK: 7,SNR1: 3.9581 ,SNR2: 16.623





1535+139 2023/11/06 3.48UT FUJI -KISO



K20231106122702




BLK: 7,SNR1: 0.17687 ,SNR2: 1.0277




T20231106123729




BLK: 8,SNR1: 0.16233 ,SNR2: 1.8165




F20231106123730





BLK: 8,SNR1: -0.22902E-01,SNR2: 1.3715




1545-12 2023/11/06 3.65UT TOYOKAWA-FUJI




T20231106123729




BLK:16,SNR1: 0.21472 ,SNR2: 3.2963




K20231106123726



BLK:16,SNR1: 0.73446 ,SNR2: 3.8724




1545-12 2023/11/06 3.65UT TOYOKAWA-KISO








F20231106123730




BLK: 7,SNR1:-0.13152 ,SNR2: 1.2223




K20231106123726





BLK: 7,SNR1: 0.32746 ,SNR2: 1.1836




1545-12 2023/11/06 3.65UT FUJI -KISO




T20231106125833




BLK: 3,SNR1:-0.22449E-01,SNR2: 0.28390




F20231106125833




BLK: 3,SNR1: 0.41464 ,SNR2: 7.2412




1607+26 2023/11/06 4.00UT TOYOKAWA-FUJI




T20231106125833




BLK: 3,SNR1: 0.12931 ,SNR2: 0.37342




K20231106125830




BLK: 3,SNR1: 0.58115E-01,SNR2: 1.0031





1607+26 2023/11/06 4.00UT TOYOKAWA-KISO







BLK: 4,SNR1: 0.82809E-01,SNR2: 3.1585





BLK: 4,SNR1: 0.17833 ,SNR2: 1.0858




1607+26 2023/11/06 4.00UT FUJI -KISO





T20231106133010




BLK: 1,SNR1: 0.22056 ,SNR2: 1.4364




F20231106133011





BLK: 1,SNR1: 0.16337 ,SNR2: 2.5141




1638-025 2023/11/06 4.53UT TOYOKAWA-FUJI





T20231106133010




BLK: 4,SNR1: 0.61939 ,SNR2: 4.2663




K20231106133007




BLK: 4,SNR1: 0.22189 ,SNR2: 3.6462




1638-025 2023/11/06 4.53UT TOYOKAWA-KISO




F20231106133011




BLK: 1,SNR1: 1.9410 ,SNR2: 5.6807




K20231106133007





BLK: 1,SNR1: 0.28218 ,SNR2: 0.88145




1638-025 2023/11/06 4.53UT FUJI -KISO




T20231106133704




BLK: 1,SNR1: 0.26361 ,SNR2: 1.6478




F20231106133704



BLK: 1,SNR1:-0.13306 ,SNR2: 0.84621




1644-106 2023/11/06 4.65UT TOYOKAWA-FUJI








T20231106133704




BLK: 5,SNR1: 0.13878 ,SNR2: 1.0221




K20231106133701





BLK: 5,SNR1: 1.5136 ,SNR2: 6.4494




1644-106 2023/11/06 4.65UT TOYOKAWA-KISO





F20231106133704




BLK: 6,SNR1:-0.53161E-01,SNR2: 2.7695




K20231106133701







BLK: 6,SNR1: 0.59805 ,SNR2: 2.1697




1644-106 2023/11/06 4.65UT FUJI -KISO








1650+004 2023/11/06 4.74UT TOYOKAWA-FUJI




T20231106134225




BLK: 3,SNR1: 0.24137 ,SNR2: 0.61382




K20231106134222





BLK: 3,SNR1: 0.81765E-01,SNR2: 2.0589




1650+004 2023/11/06 4.74UT TOYOKAWA-KISO





F20231106134225




BLK: 2,SNR1:-0.21980 ,SNR2: 0.0000




K20231106134222





BLK: 2,SNR1: 0.66795 ,SNR2: 8.5509




1650+004 2023/11/06 4.74UT FUJI -KISO





T20231106134757




BLK: 2,SNR1:-0.39338E-02,SNR2: 0.35637




F20231106134758




BLK: 2,SNR1: 0.33492 ,SNR2: 1.2316




1656+053 2023/11/06 4.83UT TOYOKAWA-FUJI





T20231106134757




BLK: 4,SNR1: 0.39565E-01,SNR2: 0.47164




K20231106134754





BLK: 4,SNR1: 0.15464 ,SNR2: 1.1206




1656+053 2023/11/06 4.83UT TOYOKAWA-KISO





F20231106134758




BLK: 6,SNR1: 3.9390 ,SNR2: 16.561




K20231106134754



BLK: 6,SNR1: 0.39284 ,SNR2: 2.4323





1656+053 2023/11/06 4.83UT FUJI -KISO







T20231106140427




BLK: 4,SNR1: 0.92785E-01,SNR2: 0.61391




F20231106140428




BLK: 4,SNR1:-0.40971E-01,SNR2: 1.8709




1712-033 2023/11/06 5.10UT TOYOKAWA-FUJI





T20231106140427




BLK: 7,SNR1: 0.14281 ,SNR2: 0.57218




K20231106140424





BLK: 7,SNR1: 1.2059 ,SNR2: 5.3674




1712-033 2023/11/06 5.10UT TOYOKAWA-KISO





F20231106140428




BLK: 2,SNR1:-0.62839E-01,SNR2: 0.83806




K20231106140424





BLK: 2,SNR1: 0.50595 ,SNR2: 2.4822




1712-033 2023/11/06 5.10UT FUJI -KISO




T20231106142229




BLK: 5,SNR1: 7.9253 ,SNR2: 23.841




F20231106142230





BLK: 5,SNR1: 0.83906 ,SNR2: 5.3015




1730-13 2023/11/06 5.40UT TOYOKAWA-FUJI





T20231106142229




BLK: 5,SNR1: 0.18187 ,SNR2: 1.2415




K20231106142226




BLK: 5,SNR1: 1.4767 ,SNR2: 6.3618




1730-13 2023/11/06 5.40UT TOYOKAWA-KISO





F20231106142230




BLK: 2,SNR1: 0.12445 ,SNR2: 4.5992




K20231106142226





BLK: 2,SNR1: 0.79015 ,SNR2: 9.3608




1730-13 2023/11/06 5.40UT FUJI -KISO




T20231106143954




BLK: 2,SNR1: 0.32604E-01,SNR2: 0.46605




F20231106143955





BLK: 2,SNR1:-0.56688E-02,SNR2: 3.0572




1748+031 2023/11/06 5.69UT TOYOKAWA-FUJI





T20231106143954




BLK: 3,SNR1:-0.86985E-01,SNR2: 0.13967




K20231106143951



BLK: 3,SNR1: 0.84169 ,SNR2: 2.9254




1748+031 2023/11/06 5.69UT TOYOKAWA-KISO








F20231106143955




BLK: 4,SNR1:-0.17998 ,SNR2: 1.6801




K20231106143951





BLK: 4,SNR1: 0.33843 ,SNR2: 1.3162




1748+031 2023/11/06 5.69UT FUJI -KISO




T20231106145047




BLK: 7,SNR1: 0.89378E-01,SNR2: 0.52407




F20231106145048





BLK: 7,SNR1: 0.24315 ,SNR2: 1.9072




1759+13 2023/11/06 5.87UT TOYOKAWA-FUJI





T20231106145047




BLK: 9,SNR1: 0.13920 ,SNR2: 0.55914




K20231106145044




BLK: 9,SNR1: 0.12607 ,SNR2: 0.83099




1759+13 2023/11/06 5.87UT TOYOKAWA-KISO





F20231106145048




BLK: 4,SNR1: 0.22957 ,SNR2: 1.6755




K20231106145044





BLK: 4,SNR1: 0.45220 ,SNR2: 1.7238




1759+13 2023/11/06 5.87UT FUJI -KISO




T20231106151147




BLK: 1,SNR1: 0.69648E-01,SNR2: 0.48144




F20231106151148





BLK: 1,SNR1: 1.0698 ,SNR2: 5.4102




1819-096 2023/11/06 6.22UT TOYOKAWA-FUJI







1819-096 2023/11/06 6.22UT TOYOKAWA-KISO





F20231106151148




BLK: 7,SNR1: 2.1867 ,SNR2: 9.7221




K20231106151145





BLK: 7,SNR1: 0.79517 ,SNR2: 3.8362




1819-096 2023/11/06 6.22UT FUJI -KISO





T20231106154927




BLK: 5,SNR1: 36.160 ,SNR2: 114.14




F20231106154928



BLK: 5,SNR1: 0.17149 ,SNR2: 1.0406





1858+171 2023/11/06 6.85UT TOYOKAWA-FUJI







T20231106154927




BLK: 2,SNR1: 107.33 ,SNR2: 169.07




K20231106154924







BLK: 2,SNR1: 0.36910 ,SNR2: 1.4835




1858+171 2023/11/06 6.85UT TOYOKAWA-KISO








1858+171 2023/11/06 6.85UT FUJI -KISO





T20231106160702




BLK: 4,SNR1: 0.43257E-01,SNR2: 0.57659




F20231106160703





BLK: 4,SNR1: 0.43760E-01,SNR2: 2.9355




1915-121 2023/11/06 7.15UT TOYOKAWA-FUJI





T20231106160702




BLK: 3,SNR1: 0.12680 ,SNR2: 0.54647




K20231106160700





BLK: 3,SNR1: 2.4625 ,SNR2: 8.7088




1915-121 2023/11/06 7.15UT TOYOKAWA-KISO








1915-121 2023/11/06 7.15UT FUJI -KISO



T20231106162044





BLK: 3,SNR1: 0.11473 ,SNR2: 1.0740




Frequency (Hz)

F20231106162044




BLK: 3,SNR1:-0.12570 ,SNR2: 2.8311





Frequency (Hz)


1928-142 2023/11/06 7.37UT TOYOKAWA-FUJI



T20231106162044





BLK: 3,SNR1: 0.18960 ,SNR2: 0.66546




Frequency (Hz)

K20231106162041




BLK: 3,SNR1: 2.2552 ,SNR2: 4.5443




Frequency (Hz)


1928-142 2023/11/06 7.37UT TOYOKAWA-KISO





F20231106162044




BLK: 7,SNR1: 0.39745 ,SNR2: 2.2183




K20231106162041



BLK: 7,SNR1: 0.28551 ,SNR2: 3.2086





1928-142 2023/11/06 7.37UT FUJI -KISO







T20231106164511




BLK: 3,SNR1: 0.40671E-01,SNR2: 0.69389




F20231106164512





BLK: 3,SNR1: 0.68815 ,SNR2: 1.5523




1953-077 2023/11/06 7.78UT TOYOKAWA-FUJI





T20231106164511




BLK: 2,SNR1: 0.37974 ,SNR2: 0.88446




K20231106164508





BLK: 2,SNR1: 0.22755 ,SNR2: 4.6609



1953-077 2023/11/06 7.78UT TOYOKAWA-KISO





1953-077 2023/11/06 7.78UT FUJI -KISO

