




T20231108055729





BLK: 4,SNR1:-0.67610E-01,SNR2: 0.63005




Frequency (Hz)

F20231108055730




BLK: 4,SNR1: 0.62159 ,SNR2: 1.8413





Frequency (Hz)


0912-132 2023/11/07 20.99UT TOYOKAWA-FUJI



T20231108055729





BLK: 1,SNR1: 0.18050 ,SNR2: 1.1195




Frequency (Hz)

K20231108055726




BLK: 1,SNR1: 0.66948 ,SNR2: 2.8327





Frequency (Hz)

0912-132 2023/11/07 20.99UT TOYOKAWA-KISO






F20231108055730





BLK: 3,SNR1: 0.37272 ,SNR2: 1.6270




Frequency (Hz)

K20231108055726




BLK: 3,SNR1: 0.94923 ,SNR2: 3.5497





Frequency (Hz)


0912-132 2023/11/07 20.99UT FUJI -KISO



T20231108061920




BLK: 6,SNR1: 4.6100 ,SNR2: 44.328




Frequency (Hz)

3C222 2023/11/07 21.35UT TOYOKAWA-FUJI


F20231108061921





BLK: 6,SNR1:-0.39202E-01,SNR2: 1.5012




Frequency (Hz)



T20231108061920





BLK: 5,SNR1: 51.407 ,SNR2: 348.13




Frequency (Hz)

K20231108061917




BLK: 5,SNR1: 0.39255 ,SNR2: 1.4777




Frequency (Hz)


3C222 2023/11/07 21.35UT TOYOKAWA-KISO



F20231108061921





BLK:11,SNR1:-0.11691E-01,SNR2: 1.2906




Frequency (Hz)

K20231108061917





BLK:11,SNR1: 1.0363 ,SNR2: 3.1847





Frequency (Hz)

3C222 2023/11/07 21.35UT FUJI -KISO







BLK: 7,SNR1: 0.14085 ,SNR2: 2.9159




BLK: 7,SNR1: 6.3157 ,SNR2: 16.685





0941-08 2023/11/07 21.47UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.71888E-01,SNR2: 2.4475




BLK: 4,SNR1: 1.8041 ,SNR2: 6.7089




0941-08 2023/11/07 21.47UT TOYOKAWA-KISO





F20231108062621




BLK:11,SNR1: 7.1366 ,SNR2: 14.624




K20231108062618





BLK:11,SNR1: 1.3905 ,SNR2: 5.7461




0941-08 2023/11/07 21.47UT FUJI -KISO



T20231108063442




BLK: 4,SNR1: 0.43539E-01,SNR2: 2.0989




Frequency (Hz)

3C230 2023/11/07 21.61UT TOYOKAWA-FUJI


F20231108063443



BLK: 4,SNR1: 7.6180 ,SNR2: 14.657




Frequency (Hz)






T20231108063442




BLK: 1,SNR1: 0.31826 ,SNR2: 0.62735




Frequency (Hz)

K20231108063440




BLK: 1,SNR1: 2.5255 ,SNR2: 10.052





Frequency (Hz)


3C230 2023/11/07 21.61UT TOYOKAWA-KISO



F20231108063443





BLK: 7,SNR1: 6.3677 ,SNR2: 9.9005




Frequency (Hz)

3C230 2023/11/07 21.61UT FUJI -KISO


K20231108063440





BLK: 7,SNR1: 0.25059 ,SNR2: 2.2624




Frequency (Hz)



T20231108065042





BLK: 7,SNR1: 0.18906 ,SNR2: 2.2404




Frequency (Hz)

3C237 2023/11/07 21.87UT TOYOKAWA-FUJI


F20231108065043




BLK: 7,SNR1: 0.31964 ,SNR2: 1.3253




Frequency (Hz)



T20231108065042





BLK: 4,SNR1: 0.13748 ,SNR2: 0.94585




Frequency (Hz)

K20231108065040




BLK: 4,SNR1: 2.2120 ,SNR2: 9.0467





Frequency (Hz)


3C237 2023/11/07 21.87UT TOYOKAWA-KISO



F20231108065043





BLK: 6,SNR1: 0.31939 ,SNR2: 0.69081




Frequency (Hz)

3C237 2023/11/07 21.87UT FUJI -KISO


K20231108065040





BLK: 6,SNR1: 0.84549 ,SNR2: 4.5657




Frequency (Hz)





T20231108065659




BLK: 5,SNR1: 0.28408 ,SNR2: 3.2211




F20231108065700





BLK: 5,SNR1: 0.57972 ,SNR2: 1.6661




1011+110 2023/11/07 21.98UT TOYOKAWA-FUJI





T20231108065659




No.Good Data




K20231108065657




No.Good Data




1011+110 2023/11/07 21.98UT TOYOKAWA-KISO



F20231108065700





BLK: 4,SNR1: 0.16706 ,SNR2: 1.4374




Frequency (Hz)

K20231108065657




BLK: 4,SNR1:-0.40917E-01,SNR2: 0.18046





Frequency (Hz)

1011+110 2023/11/07 21.98UT FUJI -KISO







T20231108070440




BLK: 1,SNR1: 0.19159 ,SNR2: 1.8211




F20231108070441





BLK: 1,SNR1: 1.7801 ,SNR2: 11.696




3C241 2023/11/07 22.11UT TOYOKAWA-FUJI



T20231108070440





BLK: 3,SNR1:-0.71907E-01,SNR2: 0.57771E-01





3C241

2023/11/07 22.11UT TOYOKAWA-KISO



K20231108070438




BLK: 3,SNR1: 1.9098 ,SNR2: 7.3909





F20231108070441




BLK: 7,SNR1: 3.7728 ,SNR2: 11.578




K20231108070438





BLK: 7,SNR1: 1.1560 ,SNR2: 3.9330




3C241 2023/11/07 22.11UT FUJI -KISO



T20231108071609




BLK: 3,SNR1: 0.32255 ,SNR2: 0.69237




Frequency (Hz)

F20231108071610




BLK: 3,SNR1: 0.33335 ,SNR2: 1.4354





Frequency (Hz)


1031-11 2023/11/07 22.30UT TOYOKAWA-FUJI



T20231108071609





BLK: 1,SNR1: 0.53483 ,SNR2: 0.90307




Frequency (Hz)

K20231108071607




BLK: 1,SNR1: 5.2717 ,SNR2: 21.014




Frequency (Hz)


1031-11 2023/11/07 22.30UT TOYOKAWA-KISO



F20231108071610





BLK: 4,SNR1: 0.28937 ,SNR2: 1.1013




Frequency (Hz)

K20231108071607




BLK: 4,SNR1: 1.5970 ,SNR2: 6.7640





Frequency (Hz)


1031-11 2023/11/07 22.30UT FUJI -KISO



T20231108072043




BLK: 6,SNR1: 7.3215 ,SNR2: 46.006




Frequency (Hz)

F20231108072044




BLK: 6,SNR1:-0.49003E-01,SNR2: 3.1290





Frequency (Hz)


1035-058 2023/11/07 22.37UT TOYOKAWA-FUJI





T20231108072043




BLK: 3,SNR1: 5.5790 ,SNR2: 60.360




K20231108072041



BLK: 3,SNR1: 2.2320 ,SNR2: 8.4456




1035-058 2023/11/07 22.37UT TOYOKAWA-KISO






F20231108072044




BLK: 6,SNR1: 0.77835 ,SNR2: 2.4966




Frequency (Hz)

K20231108072041




BLK: 6,SNR1: 1.4540 ,SNR2: 7.1616




Frequency (Hz)


1035-058 2023/11/07 22.37UT FUJI -KISO



T20231108072955




BLK: 3,SNR1: 0.36478E-01,SNR2: 0.95703




Frequency (Hz)

F20231108072956




BLK: 3,SNR1: 1.7316 ,SNR2: 4.2877




Frequency (Hz)


1044-008 2023/11/07 22.53UT TOYOKAWA-FUJI



T20231108072955




BLK: 3,SNR1: 0.35117E-01,SNR2: 1.4644




Frequency (Hz)

K20231108072953




BLK: 3,SNR1: 0.11917 ,SNR2: 1.5450





Frequency (Hz)


1044-008 2023/11/07 22.53UT TOYOKAWA-KISO



F20231108072956





BLK: 2,SNR1: 2.0834 ,SNR2: 3.9341




Frequency (Hz)

K20231108072953




BLK: 2,SNR1: 5.8666 ,SNR2: 18.316




Frequency (Hz)


1044-008 2023/11/07 22.53UT FUJI -KISO



T20231108074100





BLK: 4, SNR1: 3.8150 ,SNR2: 9.5144




Frequency (Hz)

1055+01 2023/11/07 22.71UT TOYOKAWA-FUJI


F20231108074101




BLK: 4, SNR1: -0.35360 ,SNR2: 0.99492




Frequency (Hz)



T20231108074100





BLK:10,SNR1: 3.6334 ,SNR2: 8.4057




Frequency (Hz)

1055+01 2023/11/07 22.71UT TOYOKAWA-KISO


K20231108074057





BLK:10,SNR1: 0.23892 ,SNR2: 1.4686




Frequency (Hz)





F20231108074101




BLK: 3,SNR1:-0.13286 ,SNR2: 1.4139




K20231108074057





BLK: 3,SNR1: 0.20416 ,SNR2: 0.62785




1055+01 2023/11/07 22.71UT FWJ -KISO



T20231108075217




BLK: 8,SNR1: 0.12560 ,SNR2: 0.92213





1107+109 2023/11/07 22.90UT TOYOKAWA-FUJI

F20231108075218





BLK: 8,SNR1: 0.53106E-01,SNR2: 0.96759






T20231108075217




BLK: 6,SNR1: 0.22585 ,SNR2: 1.4199





1107+109 2023/11/07 22.90UT TOYOKAWA-KISO



K20231108075215




BLK: 6,SNR1: 4.0355 ,SNR2: 8.2251





F20231108075218




BLK: 7,SNR1: 0.62430 ,SNR2: 2.0894




K20231108075215




BLK: 7,SNR1: 1.9554 ,SNR2: 6.7173




1107+109 2023/11/07 22.90UT FUJI -KISO





T20231108080155




BLK: 4,SNR1: 0.28151 ,SNR2: 1.3479




F20231108080156




BLK: 4,SNR1:-0.25701 ,SNR2: 0.30960




3C255 2023/11/07 23.06UT TOYOKAWA-FUJI




T20231108080155




BLK:16,SNR1: 0.40211 ,SNR2: 2.3508




K20231108080152





BLK:16,SNR1: 0.42521 ,SNR2: 1.4186




3C255 2023/11/07 23.06UT TOYOKAWA-KISO



F20231108080156




BLK: 5,SNR1: 0.23096 ,SNR2: 1.4081





3C255 2023/11/07 23.06UT FUJI -KISO


K20231108080152




BLK: 5,SNR1: 0.55505E-01,SNR2: 0.43356





T20231108082553




BLK: 4,SNR1: 0.15330E-01,SNR2: 0.46658




F20231108082554





BLK: 4,SNR1: 0.38592E-01,SNR2: 2.9608




3C263.1 2023/11/07 23.46UT TOYOKAWA-FUJI



T20231108082553




BLK: 5,SNR1: 4.0572 ,SNR2: 20.805





3C263.1 2023/11/07 23.46UT TOYOKAWA-KISO



K20231108082551




BLK: 5,SNR1: 0.47514 ,SNR2: 5.1158



F20231108082554





BLK: 5,SNR1: 0.56872 ,SNR2: 2.2058




Frequency (Hz)

K20231108082551




BLK: 5,SNR1: 0.64214 ,SNR2: 3.6458





Frequency (Hz)

3C263.1 2023/11/07 23.46UT FUJI -KISO







T20231108083220




BLK: 7,SNR1: 0.10759 ,SNR2: 0.23636




F20231108083221





BLK: 7,SNR1: 0.17474 ,SNR2: 1.9195






3C267 2023/11/07 23.57UT TOYOKAWA-FUJI







BLK: 8, SNR1: 0.16518 , SNR2: 0.66613




BLK: 8, SNR1: 0.24834 , SNR2: 1.7418




3C267 2023/11/07 23.57UT TOYOKAWA-KISO




F20231108083221




BLK:17,SNR1: 0.19319E-01,SNR2: 1.2840




K20231108083218





BLK:17,SNR1: 0.23473 ,SNR2: 1.1478




3C267 2023/11/07 23.57UT FUJI -KISO



T20231108085134





BLK:10,SNR1: 0.15933 ,SNR2: 0.45465




Frequency (Hz)

F20231108085135




BLK:10,SNR1: 2.0269 ,SNR2: 6.3435




Frequency (Hz)


1206+439 2023/11/07 23.89UT TOYOKAWA-FUJI





T20231108085134




BLK: 2, SNR1: 0.13361 , SNR2: 0.50928




K20231108085132







BLK: 2, SNR1: 0.18938 , SNR2: 0.63886








1206+439 2023/11/07 23.89UT TOYOKAWA-KISO






1206+439 2023/11/07 23.89UT FUJI -KISO







3C273 2023/11/08 0.22UT TOYOKAWA-FUJI




T20231108091125




BLK:22,SNR1: 1.0424 ,SNR2: 8.2964




K20231108091123



BLK:22,SNR1: 0.79587 ,SNR2: 3.4435




3C273 2023/11/08 0.22UT TOYOKAWA-KISO






F20231108091126




BLK: 9,SNR1:-0.14183 ,SNR2: 1.1159




Frequency (Hz)

3C273 2023/11/08 0.22UT FUJI -KISO


K20231108091123




BLK: 9,SNR1: 1.0925 ,SNR2: 4.6927





Frequency (Hz)







BLK: 4, SNR1: -0.92401E-03, SNR2: 1.2547




BLK: 4, SNR1: -0.26776, SNR2: 0.71457




3C275 2023/11/08 0.44UT TOYOKAWA-FUJI





T20231108092435




BLK: 7,SNR1: 0.84459E-01,SNR2: 0.71937




K20231108092433




BLK: 7,SNR1: 0.64772 ,SNR2: 3.5309




3C275 2023/11/08 0.44UT TOYOKAWA-KISO





F20231108092436




BLK: 7,SNR1:-0.79811E-01,SNR2: 1.5861




K20231108092433




BLK: 7,SNR1: 0.61681 ,SNR2: 2.5259




3C275 2023/11/08 0.44UT FUJI -KISO




T20231108093824




BLK:16,SNR1: 0.86416 ,SNR2: 6.4364




F20231108093825




BLK:16,SNR1: 0.18106 ,SNR2: 0.91774




3C279 2023/11/08 0.67UT TOYOKAWA-FUJI



T20231108093824





BLK:25,SNR1: 1.1496 ,SNR2: 8.7413




Frequency (Hz)

K20231108093822




BLK:25,SNR1: 0.83857 ,SNR2: 5.5875




Frequency (Hz)


3C279 2023/11/08 0.67UT TOYOKAWA-KISO



F20231108093825





BLK:12,SNR1:-0.33479 ,SNR2: 0.65006




Frequency (Hz)

K20231108093822




BLK:12,SNR1: 0.36455 ,SNR2: 1.2508




Frequency (Hz)


3C279 2023/11/08 0.67UT FUJI -KISO



T20231108095812





BLK: 5,SNR1: 37.308 ,SNR2: 280.89




Frequency (Hz)

F20231108095813




BLK: 5,SNR1: 0.20858 ,SNR2: 1.9383




Frequency (Hz)

1313+453 2023/11/08 1.00UT TOYOKAWA-FUJI






T20231108095812





BLK: 5, SNR1: 43.834 , SNR2: 296.68




Frequency (Hz)

1313+453 2023/11/08 1.00UT TOYOKAWA-KISO


K20231108095810





BLK: 5, SNR1: 0.19852 , SNR2: 0.58361




Frequency (Hz)





F20231108095813




BLK: 4,SNR1: 0.32172E-01,SNR2: 0.70745




K20231108095810





BLK: 4,SNR1: 0.23892 ,SNR2: 0.92811




1313+453 2023/11/08 1.00UT FUJI -KISO




T20231108100818




BLK: 4,SNR1: 0.15909 ,SNR2: 1.6650




F20231108100819





BLK: 4,SNR1:-0.73289E-01,SNR2: 1.7520




1323+32 2023/11/08 1.17UT TOYOKAWA-FUJI



T20231108100818





BLK: 7,SNR1: 0.16235E-01,SNR2: 1.4437





1323+32 2023/11/08 1.17UT TOYOKAWA-KISO


K20231108100816




BLK: 7,SNR1: 0.17989 ,SNR2: 1.8982





F20231108100819




BLK: 5,SNR1: 0.81889E-02,SNR2: 2.6441




K20231108100816




BLK: 5,SNR1: 0.27273 ,SNR2: 3.9262




1323+32 2023/11/08 1.17UT FUJI -KISO



T20231108101309





BLK:12,SNR1: 1.1268 ,SNR2: 2.6670







3C286 2023/11/08 1.25UT TOYOKAWA-FUJI

F20231108101310




BLK:12,SNR1: 0.15383 ,SNR2: 1.1612







3C286 2023/11/08 1.25UT TOYOKAWA-KISO





F20231108101310




BLK: 8,SNR1: 0.79212E-01,SNR2: 1.0788




K20231108101307



BLK: 8,SNR1: 0.42035 ,SNR2: 1.8012





3C286 2023/11/08 1.25UT FUJI -KISO






T20231108102936




BLK: 7,SNR1: 0.32195 ,SNR2: 3.3758




Frequency (Hz)

F20231108102936




BLK: 7,SNR1:-0.11874 ,SNR2: 2.9615





Frequency (Hz)


1345+12 2023/11/08 1.52UT TOYOKAWA-FUJI



T20231108102936





BLK:15,SNR1: 0.49116 ,SNR2: 2.7712





1345+12 2023/11/08 1.52UT TOYOKAWA-KISO


K20231108102934




BLK:15,SNR1: 0.11493 ,SNR2: 0.59441




F20231108102936




BLK: 6,SNR1: 0.30231E-01,SNR2: 5.0340




K20231108102934





BLK: 6,SNR1: 0.27068 ,SNR2: 1.0437




1345+12 2023/11/08 1.52UT FUJI -KISO



T20231108103956





BLK: 7,SNR1: 0.53469 ,SNR2: 6.0397




Frequency (Hz)

1355+01 2023/11/08 1.69UT TOYOKAWA-FUJI


F20231108103957




BLK: 7,SNR1: 0.34882 ,SNR2: 1.5129




Frequency (Hz)



T20231108103956




BLK:19,SNR1: 0.48586 ,SNR2: 1.7339





1355+01 2023/11/08 1.69UT TOYOKAWA-KISO


K20231108103954




BLK:19,SNR1: 0.68098 ,SNR2: 4.0238



F20231108103957





BLK: 4,SNR1: 0.50481 ,SNR2: 1.9630





1355+01 2023/11/08 1.69UT FUJI -KISO



K20231108103954




BLK: 4,SNR1: 3.4790 ,SNR2: 8.1216





T20231108110107




BLK:22,SNR1: 1.8690 ,SNR2: 5.8711




F20231108110108




BLK:22,SNR1: 0.94333 ,SNR2: 4.1241




3C298 2023/11/08 2.05UT TOYOKAWA-FUJI



T20231108110107





BLK:33,SNR1: 1.7767 ,SNR2: 12.127





3C298 2023/11/08 2.05UT TOYOKAWA-KISO

K20231108110105





BLK:33,SNR1: 0.59118 ,SNR2: 3.6825






F20231108110108





BLK:20,SNR1: 4.1271 ,SNR2: 11.411





3C298 2023/11/08 2.05UT FUJI -KISO


K20231108110105




BLK:20,SNR1: 3.9367 ,SNR2: 10.913



T20231108111250




BLK: 8,SNR1: 0.20795 ,SNR2: 2.2114





1428-03 2023/11/08 2.24UT TOYOKAWA-FUJI


F20231108111251




BLK: 8,SNR1: 6.3218 ,SNR2: 12.629





T20231108111250




BLK: 9,SNR1: 0.26494 ,SNR2: 3.0424




K20231108111248




BLK: 9,SNR1: 0.30724 ,SNR2: 1.5600




1428-03 2023/11/08 2.24UT TOYOKAWA-KISO



F20231108111251





BLK:15,SNR1: 3.0540 ,SNR2: 12.658





1428-03 2023/11/08 2.24UT FUJI -KISO



K20231108111248




BLK:15,SNR1: 0.77868 ,SNR2: 2.4221



T20231108111852




BLK: 1,SNR1: 0.19643 ,SNR2: 1.3632




1434+03 2023/11/08 2.34UT TOYOKAWA-FUJI


F20231108111853





BLK: 1,SNR1:-0.11470 ,SNR2: 1.7852




Frequency (Hz)



T20231108111852





BLK: 4,SNR1: 0.91540E-01,SNR2: 1.8817





1434+03 2023/11/08 2.34UT TOYOKAWA-KISO




K20231108111850







BLK: 4,SNR1: 0.39950 ,SNR2: 1.5577




F20231108111853




K20231108111850



T20231108113754




BLK:18,SNR1: 43.216 ,SNR2: 129.05





1453-10 2023/11/08 2.66UT TOYOKAWA-FUJI

F20231108113754




BLK:18,SNR1: 3.8495 ,SNR2: 16.184







T20231108113754




BLK:32,SNR1: 27.085 ,SNR2: 79.664




K20231108113752




BLK:32,SNR1: 1.9552 ,SNR2: 8.3763




1453-10 2023/11/08 2.66UT TOYOKAWA-KISO



F20231108113754




BLK:17,SNR1: 3.8870 ,SNR2: 16.343





1453-10 2023/11/08 2.66UT FUJI -KISO



K20231108113752




BLK:17,SNR1: 1.3503 ,SNR2: 6.2609




T20231108115247




BLK:15,SNR1: 0.16608 ,SNR2: 1.9108




F20231108115248





BLK:15,SNR1: 0.23007 ,SNR2: 3.6828




1508-05 2023/11/08 2.91UT TOYOKAWA-FUJI



T20231108115247




BLK:15,SNR1: 0.27088 ,SNR2: 2.2321





1508-05 2023/11/08 2.91UT TOYOKAWA-KISO


K20231108115244




BLK:15,SNR1: 0.59767 ,SNR2: 2.3498





F20231108115248




BLK:14,SNR1: 0.33343E-01,SNR2: 1.7713




K20231108115244





BLK:14,SNR1: 0.63030 ,SNR2: 2.3202




1508-05 2023/11/08 2.91UT FUJI -KISO




T20231108120147




BLK: 8,SNR1: 0.16527 ,SNR2: 1.1365




F20231108120148




BLK: 8,SNR1: 0.93112E-01,SNR2: 2.2029




3C318 2023/11/08 3.06UT TOYOKAWA-FUJI





T20231108120147




BLK:12,SNR1: 0.14207 ,SNR2: 1.3299




K20231108120144





BLK:12,SNR1: 0.50402 ,SNR2: 2.4124




3C318 2023/11/08 3.06UT TOYOKAWA-KISO



F20231108120148





BLK: 4,SNR1: 0.36651 ,SNR2: 4.1948





3C318 2023/11/08 3.06UT FUJI -KISO

K20231108120144




BLK: 4,SNR1: 0.56296 ,SNR2: 2.3221






T20231108120734




BLK:14,SNR1: 1.1736 ,SNR2: 5.2634




1523+03 2023/11/08 3.15UT TOYOKAWA-FUJI


F20231108120735





BLK:14,SNR1:-0.76639E-02,SNR2: 1.0907




Frequency (Hz)



T20231108120734





BLK:18,SNR1: 1.0999 ,SNR2: 6.1012





1523+03 2023/11/08 3.15UT TOYOKAWA-KISO



K20231108120732







BLK:18,SNR1: 0.33982 ,SNR2: 1.2030







F20231108120735








K20231108120732






1535+139 2023/11/08 3.35UT TOYOKAWA-FUJI







1535+139 2023/11/08 3.35UT TOYOKAWA-KISO



F20231108121915





BLK: 2,SNR1: 0.38888 ,SNR2: 1.3970





1535+139 2023/11/08 3.35UT FUJI -KISO



K20231108121911




BLK: 2,SNR1: 0.57138 ,SNR2: 4.4427




T20231108122937




BLK:11,SNR1: 1.1557 ,SNR2: 4.1224




F20231108122938





BLK:11,SNR1: 0.74362E-01,SNR2: 0.96399




1545-12 2023/11/08 3.52UT TOYOKAWA-FUJI




T20231108122937




BLK:11,SNR1: 0.52529 ,SNR2: 2.7024




K20231108122934



BLK:11,SNR1: 32.294 ,SNR2: 62.017




1545-12 2023/11/08 3.52UT TOYOKAWA-KISO







F20231108122938




BLK: 4,SNR1: 0.30926E-01,SNR2: 2.1926




K20231108122934





BLK: 4,SNR1: 41.078 ,SNR2: 89.048




1545-12 2023/11/08 3.52UT FUJI -KISO




T20231108125041




BLK: 3,SNR1: 0.28570 ,SNR2: 1.0159




F20231108125042




BLK: 3,SNR1: 0.96163 ,SNR2: 5.3099




1607+26 2023/11/08 3.87UT TOYOKAWA-FUJI




T20231108125041




BLK: 2,SNR1: 0.18019 ,SNR2: 0.60859




K20231108125038




BLK: 2,SNR1: 0.81134 ,SNR2: 3.4547




1607+26 2023/11/08 3.87UT TOYOKAWA-KISO





F20231108125042




BLK: 3,SNR1: 0.57408 ,SNR2: 2.8071




K20231108125038





BLK: 3,SNR1: 0.12810 ,SNR2: 0.37006




1607+26 2023/11/08 3.87UT FUJI -KISO




T20231108130544




BLK: 8,SNR1: 0.37966 ,SNR2: 1.4419




F20231108130544





BLK: 8,SNR1: 1.0178 ,SNR2: 5.2510




1621-11 2023/11/08 4.12UT TOYOKAWA-FUJI




T20231108130544




BLK: 4,SNR1: 1.3607 ,SNR2: 3.2425




K20231108130541





BLK: 4,SNR1: 0.29487 ,SNR2: 3.1233




1621-11 2023/11/08 4.12UT TOYOKAWA-KISO





F20231108130544




BLK: 4,SNR1: 0.59029 ,SNR2: 3.1165




K20231108130541




BLK: 4,SNR1: 0.28809 ,SNR2: 1.9164




1621-11 2023/11/08 4.12UT FUJI -KISO




T20231108132218




BLK: 7,SNR1: 0.71111 ,SNR2: 3.8304




F20231108132219



BLK: 7,SNR1: 0.24743 ,SNR2: 1.2209





1638-025 2023/11/08 4.40UT TOYOKAWA-FUJI








T20231108132218




BLK: 5, SNR1: 2.1958 ,SNR2: 13.539




K20231108132215




BLK: 5, SNR1: 0.81172 ,SNR2: 4.7081




1638-025 2023/11/08 4.40UT TOYOKAWA-KISO





F20231108132219




BLK: 3,SNR1: 27.008 ,SNR2: 46.404




K20231108132215





BLK: 3,SNR1: 0.42543 ,SNR2: 2.6778





1638-025 2023/11/08 4.40UT FUJI -KISO




T20231108132912





F20231108132913







1644-106 2023/11/08 4.51UT TOYOKAWA-FUJI





T20231108132912






K20231108132909




F20231108132913





K20231108132909




1644-106 2023/11/08 4.51UT FUJI -KISO





T20231108133433




BLK: 4,SNR1:-0.22359E-01,SNR2: 0.28673




F20231108133434





BLK: 4,SNR1:-0.55077E-01,SNR2: 2.1946




1650+004 2023/11/08 4.60UT TOYOKAWA-FUJI





T20231108133433




BLK: 2,SNR1: 0.17016E-01,SNR2: 1.0380




K20231108133430




BLK: 2,SNR1: 0.62990E-01,SNR2: 0.31480




1650+004 2023/11/08 4.60UT TOYOKAWA-KISO





F20231108133434




BLK: 3, SNR1: 0.14225, SNR2: 1.1383




K20231108133430



BLK: 3, SNR1: 0.15700, SNR2: 1.1455





1650+004 2023/11/08 4.60UT FUJI -KISO








T20231108134005




BLK: 2,SNR1: 0.16887 ,SNR2: 0.32905




F20231108134006





BLK: 2,SNR1: 0.51499 ,SNR2: 2.2624




1656+053 2023/11/08 4.70UT TOYOKAWA-FUJI





T20231108134005




BLK: 2,SNR1:-0.48213E-02,SNR2: 0.13619




K20231108134002





BLK: 2,SNR1: 1.5143 ,SNR2: 12.208




1656+053 2023/11/08 4.70UT TOYOKAWA-KISO





F20231108134006




BLK: 4,SNR1: 0.30659 ,SNR2: 2.5040




K20231108134002





BLK: 4,SNR1: 0.52897 ,SNR2: 4.6179




1656+053 2023/11/08 4.70UT FUJI -KISO




T20231108135635




BLK: 6,SNR1: 0.33714E-01,SNR2: 0.59102




F20231108135636





BLK: 6,SNR1:-0.19170 ,SNR2: 0.79898




1712-033 2023/11/08 4.97UT TOYOKAWA-FUJI





T20231108135635




BLK: 1,SNR1: 0.10521 ,SNR2: 0.49153




K20231108135632




BLK: 1,SNR1: 5.5140 ,SNR2: 21.550




1712-033 2023/11/08 4.97UT TOYOKAWA-KISO





F20231108135636




BLK: 2,SNR1:-0.13275 ,SNR2: 0.0000




K20231108135632







BLK: 2,SNR1: 0.63443 ,SNR2: 2.5363








1712-033 2023/11/08 4.97UT FUJI -KISO






1730-13 2023/11/08 5.27UT TOYOKAWA-FUJI






1730-13 2023/11/08 5.27UT TOYOKAWA-KISO








F20231108141438




BLK: 4,SNR1: 0.10169 ,SNR2: 0.79936




K20231108141434





BLK: 4,SNR1: 0.44955 ,SNR2: 2.1296




1730-13 2023/11/08 5.27UT FUJI -KISO




T20231108143202




BLK: 2,SNR1: 0.73295E-01,SNR2: 0.20005




F20231108143203





BLK: 2,SNR1: 0.69186 ,SNR2: 2.3064




1748+031 2023/11/08 5.56UT TOYOKAWA-FUJI





T20231108143202




BLK: 4,SNR1:-0.10693E-01,SNR2: 0.29845




K20231108143159





BLK: 4,SNR1: 0.54079 ,SNR2: 1.9079




1748+031 2023/11/08 5.56UT TOYOKAWA-KISO





F20231108143203




BLK: 2,SNR1: 0.50746 ,SNR2: 7.6077




K20231108143159





BLK: 2,SNR1: 0.64981 ,SNR2: 3.4166




1748+031 2023/11/08 5.56UT FUJI -KISO




T20231108144255




BLK: 3,SNR1: 0.26820 ,SNR2: 2.6565




F20231108144256





BLK: 3,SNR1: 0.31705 ,SNR2: 1.3015




1759+13 2023/11/08 5.74UT TOYOKAWA-FUJI








1759+13 2023/11/08 5.74UT TOYOKAWA-KISO





F20231108144256




BLK: 5,SNR1:-0.87982E-01,SNR2: 1.0318




K20231108144252





BLK: 5,SNR1: 0.99705E-01,SNR2: 2.6791




1759+13 2023/11/08 5.74UT FUJI -KISO



T20231108150355





BLK: 4,SNR1:-0.21840E-01,SNR2: 0.15276




Frequency (Hz)

F20231108150356




BLK: 4,SNR1: 0.17760 ,SNR2: 2.6969





Frequency (Hz)

1819-096 2023/11/08 6.09UT TOYOKAWA-FUJI








T20231108150355




BLK: 3,SNR1: 0.16452 ,SNR2: 0.43808




K20231108150352







BLK: 3,SNR1: 0.50040 ,SNR2: 4.5222




1819-096 2023/11/08 6.09UT TOYOKAWA-KISO








1819-096 2023/11/08 6.09UT FUJI -KISO



T20231108154135





No. Good Data




Frequency (Hz)

F20231108154135




No. Good Data





Frequency (Hz)


1858+171 2023/11/08 6.72UT TOYOKAWA-FUJI





T20231108154135




BLK: 3,SNR1:-0.97231E-01,SNR2: 0.12555




K20231108154132




BLK: 3,SNR1: 1.7319 ,SNR2: 5.1096




1858+171 2023/11/08 6.72UT TOYOKAWA-KISO





F20231108154135




BLK: 5,SNR1:-0.56338E-01,SNR2: 0.36224




K20231108154132





BLK: 5,SNR1: 0.99067 ,SNR2: 3.8423




1858+171 2023/11/08 6.72UT FUJI -KISO



T20231108155910





No.Good Data




Frequency (Hz)

F20231108155911




No.Good Data





Frequency (Hz)


1915-121 2023/11/08 7.01UT TOYOKAWA-FUJI



T20231108155910





BLK: 2,SNR1:-0.17162 ,SNR2: 0.18445




Frequency (Hz)

K20231108155908




BLK: 2,SNR1: 4.6269 ,SNR2: 18.307





Frequency (Hz)


1915-121 2023/11/08 7.01UT TOYOKAWA-KISO





F20231108155911




BLK: 1,SNR1:-0.14447 ,SNR2: 0.14380E-01




K20231108155908



BLK: 1,SNR1:-0.85370E-02,SNR2: 1.1191





1915-121 2023/11/08 7.01UT FUJI -KISO






T20231108161252




BLK: 2,SNR1:-0.87576E-01,SNR2: 0.34409




Frequency (Hz)

F20231108161253




BLK: 2,SNR1:-0.25828,SNR2: 0.21832





Frequency (Hz)


1928-142 2023/11/08 7.24UT TOYOKAWA-FUJI



T20231108161252





BLK: 2,SNR1: 0.11239 ,SNR2: 1.3920




Frequency (Hz)

K20231108161250




BLK: 2,SNR1: 3.9748 ,SNR2: 14.970




Frequency (Hz)


1928-142 2023/11/08 7.24UT TOYOKAWA-KISO





F20231108161253




BLK: 1,SNR1: 0.46192E-01,SNR2: 1.7201




K20231108161250





BLK: 1,SNR1: 0.65607 ,SNR2: 2.4286




1928-142 2023/11/08 7.24UT FUJI -KISO




T20231108163719




BLK: 6,SNR1: 0.65656E-01,SNR2: 0.97952




F20231108163720





BLK: 6,SNR1: 0.33757 ,SNR2: 2.8278




1953-077 2023/11/08 7.65UT TOYOKAWA-FUJI



T20231108163719





BLK: 2,SNR1: 0.34555 ,SNR2: 1.5045




Frequency (Hz)

K20231108163716








BLK: 2,SNR1: 1.2145 ,SNR2: 4.0158




Frequency (Hz)





1953-077 2023/11/08 7.65UT TOYOKAWA-KISO






1953-077 2023/11/08 7.65UT FUJI -KISO








2012+010 2023/11/08 7.95UT TOYOKAWA-FUJI





T20231108165536




BLK: 2,SNR1: 0.94298E-01,SNR2: 0.31485




K20231108165534





BLK: 2,SNR1: 1.9923 ,SNR2: 10.061



2012+010 2023/11/08 7.95UT TOYOKAWA-KISO







2012+010 2023/11/08 7.95UT FUJI -KISO

