




T20231128055731




BLK: 4,SNR1: 4.3803 ,SNR2: 49.606




Frequency (Hz)

F20231128055732




BLK: 4,SNR1: 0.80720E-01,SNR2: 0.89167





Frequency (Hz)


1031-11 2023/11/27 20.99UT TOYOKAWA-FUJI



T20231128055731




BLK: 6,SNR1: 3.1046 ,SNR2: 24.870




Frequency (Hz)

K20231128055729




BLK: 6,SNR1: 0.12564 ,SNR2: 0.45270




Frequency (Hz)


1031-11 2023/11/27 20.99UT TOYOKAWA-KISO



F20231128055732





BLK: 7,SNR1:-0.17978 ,SNR2: 0.50250




Frequency (Hz)

K20231128055729




BLK: 7,SNR1: 0.28568 ,SNR2: 1.0626





Frequency (Hz)


1031-11 2023/11/27 20.99UT FUJI -KISO



T20231128060205





BLK: 7,SNR1: 0.22528 ,SNR2: 2.3966




Frequency (Hz)

F20231128060206




BLK: 7,SNR1: 0.66950 ,SNR2: 3.0719





Frequency (Hz)


1035-058 2023/11/27 21.06UT TOYOKAWA-FUJI



T20231128060205




BLK: 5, SNR1: 0.40725 ,SNR2: 2.9411




Frequency (Hz)

K20231128060203




BLK: 5, SNR1: 0.25923 ,SNR2: 1.8752





Frequency (Hz)


1035-058 2023/11/27 21.06UT TOYOKAWA-KISO



F20231128060206





BLK: 1,SNR1:-0.25676 ,SNR2: 0.74750




Frequency (Hz)

K20231128060203




BLK: 1,SNR1: 0.58064 ,SNR2: 2.2310





Frequency (Hz)


1035-058 2023/11/27 21.06UT FUJI -KISO



T20231128061117





BLK: 8,SNR1: 13.212 ,SNR2: 78.715




Frequency (Hz)

F20231128061118




BLK: 8,SNR1:-0.17992 ,SNR2: 1.6258




Frequency (Hz)


1044-008 2023/11/27 21.22UT TOYOKAWA-FUJI



T20231128061117





BLK: 6,SNR1: 20.414 ,SNR2: 109.47




Frequency (Hz)

1044-008 2023/11/27 21.22UT TOYOKAWA-KISO


K20231128061115



BLK: 6,SNR1:-0.84086E-01,SNR2: 0.35978





Frequency (Hz)






F20231128061118





BLK: 1,SNR1:-0.25505 ,SNR2: 0.66676




Frequency (Hz)

K20231128061115




BLK: 1,SNR1: 0.41863 ,SNR2: 2.7663




Frequency (Hz)

1044-008 2023/11/27 21.22UT FUJI -KISO




T20231128062222



Time (sec)




BLK: 5,SNR1: 0.61618E-01,SNR2: 0.37207



Frequency (Hz)


F20231128062223



Time (sec)






BLK: 5,SNR1:-0.31067E-01,SNR2: 3.3374






Frequency (Hz)

1055+01 2023/11/27 21.40UT TOYOKAWA-FUJI







BLK: 3, SNR1: 0.14890 , SNR2: 1.2381




BLK: 3, SNR1: 0.76356 , SNR2: 5.1216




1055+01 2023/11/27 21.40UT TOYOKAWA-KISO



F20231128062223




BLK: 5, SNR1: 0.92927 , SNR2: 8.4075




Frequency (Hz)

K20231128062220




BLK: 5, SNR1: 0.14229E-01, SNR2: 0.75841E-01





Frequency (Hz)


1055+01 2023/11/27 21.40UT FUJI -KISO



T20231128063339





BLK: 1,SNR1:-0.83821E-01,SNR2: 1.4849




Frequency (Hz)

F20231128063340




BLK: 1,SNR1: 1.4369 ,SNR2: 3.1680





Frequency (Hz)


1107+109 2023/11/27 21.59UT TOYOKAWA-FUJI



T20231128063339





BLK: 2,SNR1: 0.20645 ,SNR2: 1.3198




Frequency (Hz)

K20231128063337




BLK: 2,SNR1: 0.53611 ,SNR2: 7.8990




Frequency (Hz)


1107+109 2023/11/27 21.59UT TOYOKAWA-KISO




F20231128063340




BLK: 3,SNR1: 2.2209 ,SNR2: 5.0841




K20231128063337





BLK: 3,SNR1: 1.0634 ,SNR2: 4.7759




1107+109 2023/11/27 21.59UT FUJI -KISO



T20231128064317




BLK: 3,SNR1: 0.46848E-01,SNR2: 1.2145




Frequency (Hz)

3C255 2023/11/27 21.75UT TOYOKAWA-FUJI


F20231128064318



BLK: 3,SNR1: 0.63551 ,SNR2: 2.9588





Frequency (Hz)






T20231128064317




BLK: 2,SNR1: 0.98570E-01,SNR2: 0.91904




Frequency (Hz)

3C255 2023/11/27 21.75UT TOYOKAWA-KISO


K20231128064315




BLK: 2,SNR1: 1.1079 ,SNR2: 6.5278




Frequency (Hz)



F20231128064318





BLK: 2,SNR1: 0.14281 ,SNR2: 4.7741




Frequency (Hz)

3C255 2023/11/27 21.75UT FUJI -KISO


K20231128064315





BLK: 2,SNR1: 0.49228E-01,SNR2: 0.78636




Frequency (Hz)



T20231128070715





BLK: 5,SNR1: 3.2799 ,SNR2: 61.364




Frequency (Hz)

3C263.1 2023/11/27 22.15UT TOYOKAWA-FUJI


F20231128070716





BLK: 5,SNR1:-0.21016 ,SNR2: 1.8032




Frequency (Hz)



T20231128070715





BLK: 8,SNR1: 3.4245 ,SNR2: 53.840




Frequency (Hz)

3C263.1 2023/11/27 22.15UT TOYOKAWA-KISO


K20231128070713




BLK: 8,SNR1: 0.26415 ,SNR2: 1.2462




Frequency (Hz)



F20231128070716





BLK: 2,SNR1: 0.33779 ,SNR2: 2.2934




Frequency (Hz)

K20231128070713




BLK: 2,SNR1:-0.13804 ,SNR2: 0.76752





Frequency (Hz)


3C263.1 2023/11/27 22.15UT FUJI -KISO



T20231128071342





BLK: 3,SNR1: 0.31920 ,SNR2: 0.93464




Frequency (Hz)

3C267 2023/11/27 22.28UT TOYOKAWA-FUJI


F20231128071343





BLK: 3,SNR1: 0.19653 ,SNR2: 2.1037




Frequency (Hz)



T20231128071342




BLK: 4,SNR1: 0.26616 ,SNR2: 0.86233




Frequency (Hz)

3C267 2023/11/27 22.26UT TOYOKAWA-KISO


K20231128071340





BLK: 4,SNR1: 0.35142 ,SNR2: 1.5963




Frequency (Hz)



F20231128071343





BLK: 5,SNR1: 0.20593 ,SNR2: 1.6251




Frequency (Hz)

3C267 2023/11/27 22.26UT FUJI -KISO


K20231128071340



BLK: 5,SNR1: 0.39442 ,SNR2: 2.1446





Frequency (Hz)






T20231128075247




BLK: 8,SNR1: 0.25967 ,SNR2: 2.6897




Frequency (Hz)

3C273 2023/11/27 22.91UT TOYOKAWA-FUJI


F20231128075248





BLK: 8,SNR1: 3.3961 ,SNR2: 6.4321




Frequency (Hz)



T20231128075247





BLK: 8,SNR1: 0.46232 ,SNR2: 5.1587




Frequency (Hz)

K20231128075245





BLK: 8,SNR1: 0.54605E-01,SNR2: 0.74667





Frequency (Hz)

3C273 2023/11/27 22.91UT TOYOKAWA-KISO







BLK: 6,SNR1: 0.24823 ,SNR2: 4.3522




BLK: 6,SNR1: -0.73752E-02,SNR2: 0.50110




3C273 2023/11/27 22.91UT FUJI -KISO



T20231128080557




BLK: 8,SNR1: 0.17802 ,SNR2: 2.4174




Frequency (Hz)

3C275 2023/11/27 23.13UT TOYOKAWA-FUJI


F20231128080558





BLK: 8,SNR1:-0.10373 ,SNR2: 1.2820




Frequency (Hz)



T20231128080557





BLK:11,SNR1: 1.0574 ,SNR2: 7.5423




Frequency (Hz)

K20231128080555




BLK:11,SNR1: 0.42686 ,SNR2: 2.9227





Frequency (Hz)


3C275 2023/11/27 23.13UT TOYOKAWA-KISO



F20231128080558





BLK: 5, SNR1: 0.39779 , SNR2: 2.6801




Frequency (Hz)

3C275 2023/11/27 23.13UT FUJI -KISO


K20231128080555





BLK: 5, SNR1: 0.26547 , SNR2: 0.53509




Frequency (Hz)



T20231128081946




BLK: 7,SNR1: 4.2991 ,SNR2: 7.9030





3C279 2023/11/27 23.36UT TOYOKAWA-FUJI



F20231128081947




BLK: 7,SNR1:-0.14237 ,SNR2: 0.74909



T20231128081946




BLK:16,SNR1: 14.681 ,SNR2: 25.711





3C279 2023/11/27 23.36UT TOYOKAWA-KISO

K20231128081944





BLK:16,SNR1: 0.27373E-01,SNR2: 0.77445






F20231128081947





BLK: 2,SNR1:-0.17582 ,SNR2: 0.0000




Frequency (Hz)

3C279 2023/11/27 23.36UT FUJI -KISO


K20231128081944





BLK: 2,SNR1:-0.12073 ,SNR2: 0.61271




Frequency (Hz)



T20231128083934





BLK: 7,SNR1: 15.616 ,SNR2: 211.95




Frequency (Hz)

F20231128083935




BLK: 7,SNR1:-0.38289E-01,SNR2: 1.0776




Frequency (Hz)


1313+453 2023/11/27 23.69UT TOYOKAWA-FUJI




T20231128083934




BLK: 2,SNR1: 53.625 ,SNR2: 278.82




K20231128083931









BLK: 2,SNR1: 0.20832 ,SNR2: 0.50293




1313+453 2023/11/27 23.69UT TOYOKAWA-KISO








1313+453 2023/11/27 23.69UT FUJI -KISO




T20231128084940




BLK:10,SNR1: 0.59723E-01,SNR2: 0.93914




F20231128084941





BLK:10,SNR1: 0.12997 ,SNR2: 2.2211




1323+32 2023/11/27 23.86UT TOYOKAWA-FUJI





T20231128084940




BLK: 5,SNR1: 0.23234 ,SNR2: 0.72593




K20231128084938




BLK: 5,SNR1: 0.57468 ,SNR2: 2.1868




1323+32 2023/11/27 23.86UT TOYOKAWA-KISO





F20231128084941




BLK: 1,SNR1:-0.11803 ,SNR2: 4.0615




K20231128084938




BLK: 1,SNR1: 1.1604 ,SNR2: 5.5020




1323+32 2023/11/27 23.86UT FUJI -KISO



T20231128091058




BLK: 7, SNR1: 0.62957 , SNR2: 9.0636





1345+12 2023/11/28 0.21UT TOYOKAWA-FUJI

F20231128091059




BLK: 7, SNR1: 0.54550 , SNR2: 1.6863







T20231128091058




BLK: 6,SNR1: 0.25946 ,SNR2: 1.5494




K20231128091056




BLK: 6,SNR1: 0.74322 ,SNR2: 5.3791




1345+12 2023/11/28 0.21UT TOYOKAWA-KISO




F20231128091059




BLK: 6,SNR1: 0.74959 ,SNR2: 1.5468




K20231128091056




BLK: 6,SNR1: 0.60013 ,SNR2: 3.1383




1345+12 2023/11/28 0.21UT FUJI -KISO




T20231128092118




BLK: 7,SNR1: 0.13575 ,SNR2: 0.68949




F20231128092119





BLK: 7,SNR1:-0.10347E-01,SNR2: 3.1970




1355+01 2023/11/28 0.38UT TOYOKAWA-FUJI




T20231128092118




BLK: 7,SNR1: 0.11891 ,SNR2: 1.2540




K20231128092116





BLK: 7,SNR1: 0.10343 ,SNR2: 0.49449




1355+01 2023/11/28 0.38UT TOYOKAWA-KISO





F20231128092119




BLK: 6,SNR1: 1.0878 ,SNR2: 4.1365




K20231128092116





BLK: 6,SNR1: 0.89317E-01,SNR2: 1.2326




1355+01 2023/11/28 0.38UT FUJI -KISO




T20231128094229




BLK:22,SNR1: 0.93423 ,SNR2: 11.961




F20231128094230




BLK:22,SNR1:-0.36914E-01,SNR2: 2.1601




3C298 2023/11/28 0.74UT TOYOKAWA-FUJI



T20231128094229




BLK:30,SNR1: 0.98470 ,SNR2: 4.2360





3C298 2023/11/28 0.74UT TOYOKAWA-KISO


K20231128094227




BLK:30,SNR1: 0.27569 ,SNR2: 1.4427



F20231128094230





BLK:14,SNR1: 0.62799E-01,SNR2: 3.8290




Frequency (Hz)

3C298 2023/11/28 0.74UT FUJI -KISO


K20231128094227




BLK:14,SNR1: 0.16642 ,SNR2: 0.85753





Frequency (Hz)









BLK: 2, SNR1: 0.26212 , SNR2: 0.94018




BLK: 2, SNR1: 7.4048 , SNR2: 18.411





1428-03 2023/11/28 0.93UT TOYOKAWA-FUJI







BLK: 4, SNR1: 0.15348 , SNR2: 1.0194





BLK: 4, SNR1: 0.49485 , SNR2: 3.1407




1428-03 2023/11/28 0.93UT TOYOKAWA-KISO





F20231128095413




No.Good Data




K20231128095410




No.Good Data




1428-03 2023/11/28 0.93UT FUJI -KISO



T20231128101916




BLK: 7,SNR1: 0.35618 ,SNR2: 2.9665




Frequency (Hz)

1453-10 2023/11/28 1.35UT TOYOKAWA-FUJI


F20231128101917




BLK: 7,SNR1: 0.33306E-01,SNR2: 4.3463




Frequency (Hz)



T20231128101916





BLK:13,SNR1: 0.29229 ,SNR2: 1.8350





1453-10 2023/11/28 1.35UT TOYOKAWA-KISO



K20231128101914




BLK:13,SNR1: 0.15870 ,SNR2: 2.9488





F20231128101917




BLK: 5,SNR1:-0.16636 ,SNR2: 1.7919




K20231128101914





BLK: 5,SNR1: 0.22968E-01,SNR2: 1.6778




1453-10 2023/11/28 1.35UT FUJI -KISO



T20231128103409




BLK: 1,SNR1: 0.28442 ,SNR2: 1.8363




Frequency (Hz)

F20231128103409




BLK: 1,SNR1:-0.22334 ,SNR2: 0.49554





Frequency (Hz)


1508-05 2023/11/28 1.60UT TOYOKAWA-FUJI



T20231128103409





BLK: 2, SNR1: 0.27531 , SNR2: 1.4147





1508-05 2023/11/28 1.60UT TOYOKAWA-KISO

K20231128103407




BLK: 2, SNR1: 0.91014 , SNR2: 6.4861








F20231128103409




BLK: 4,SNR1: 0.19182E-01,SNR2: 3.9225




K20231128103407




BLK: 4,SNR1: 0.23408 ,SNR2: 3.0091




1508-05 2023/11/28 1.60UT FUJI -KISO




T20231128104309




BLK: 7,SNR1: 0.79985E-01,SNR2: 0.24013




F20231128104310




BLK: 7,SNR1:-0.98987E-01,SNR2: 1.3684




3C318 2023/11/28 1.75UT TOYOKAWA-FUJI





T20231128104309




BLK: 4,SNR1: 0.68061E-01,SNR2: 0.57307




K20231128104307




BLK: 4,SNR1: 1.1166 ,SNR2: 3.7411




3C318 2023/11/28 1.75UT TOYOKAWA-KISO



F20231128104310





BLK: 8, SNR1: 1.6864 , SNR2: 3.3582





3C318 2023/11/28 1.75UT FUJI -KISO



K20231128104307




BLK: 8, SNR1: 0.62261 , SNR2: 3.6972




T20231128104856




BLK: 5,SNR1: 0.24979 ,SNR2: 2.2679




F20231128104857




BLK: 5,SNR1:-0.23753 ,SNR2: 0.59439




1523+03 2023/11/28 1.84UT TOYOKAWA-FUJI



T20231128104856





BLK: 9,SNR1: 0.25671 ,SNR2: 2.5650





1523+03 2023/11/28 1.84UT TOYOKAWA-KISO


K20231128104854




BLK: 9,SNR1: 0.90645E-01,SNR2: 0.50090





F20231128104857




BLK: 3,SNR1:-0.87764E-01,SNR2: 2.3761




K20231128104854





BLK: 3,SNR1: 0.28965 ,SNR2: 0.54065




1523+03 2023/11/28 1.84UT FUJI -KISO



T20231128110036





BLK: 3,SNR1: 0.15274 ,SNR2: 1.6156




Frequency (Hz)

F20231128110037




BLK: 3,SNR1: 0.28772 ,SNR2: 0.59055




Frequency (Hz)

1535+139 2023/11/28 2.04UT TOYOKAWA-FUJI






T20231128110036




BLK: 6,SNR1: 0.65433E-01,SNR2: 1.1980





1535+139 2023/11/28 2.04UT TOYOKAWA-KISO


K20231128110033




BLK: 6,SNR1: 0.14527 ,SNR2: 0.82658




F20231128110037




BLK: 3,SNR1: 0.36721 ,SNR2: 2.2057




K20231128110033




BLK: 3,SNR1: 1.1395 ,SNR2: 6.8099




1535+139 2023/11/28 2.04UT FUJI -KISO



T20231128111059




BLK:11,SNR1: 0.88017 ,SNR2: 5.7015





1545-12 2023/11/28 2.21UT TOYOKAWA-FUJI


F2023112811100




BLK:11,SNR1:-0.21736 ,SNR2: 0.65290E-01



T20231128111059




BLK:19,SNR1: 0.75786 ,SNR2: 5.1456





1545-12 2023/11/28 2.21UT TOYOKAWA-KISO


K20231128111057




BLK:19,SNR1: 13.780 ,SNR2: 34.156




F20231128111100




BLK: 8, SNR1: -0.48494E-01, SNR2: 1.2977




K20231128111057




BLK: 8, SNR1: 12.259, SNR2: 30.146




1545-12 2023/11/28 2.21UT FUJI -KISO





T20231128113203




BLK: 7,SNR1: 0.26680 ,SNR2: 0.86335




F20231128113204




BLK: 7,SNR1:-0.10984 ,SNR2: 0.78497




1607+26 2023/11/28 2.56UT TOYOKAWA-FUJI



T20231128113203





BLK: 5, SNR1: 0.16368 , SNR2: 0.80801





1607+26 2023/11/28 2.56UT TOYOKAWA-KISO



K20231128113201




BLK: 5, SNR1: 0.47114 , SNR2: 2.4129




F20231128113204




BLK: 6,SNR1: 0.27029E-01,SNR2: 2.4625




K20231128113201



BLK: 6,SNR1: 0.46503E-01,SNR2: 0.63965




1607+26 2023/11/28 2.56UT FUJI -KISO







T20231128114706




BLK: 8,SNR1: 0.52065 ,SNR2: 3.4896




F20231128114707







BLK: 8,SNR1:-0.12335 ,SNR2: 1.1940




1621-11 2023/11/28 2.81UT TOYOKAWA-FUJI







1621-11 2023/11/28 2.81UT TOYOKAWA-KISO



F20231128114707




BLK: 3,SNR1:-0.57230E-01,SNR2: 2.8120





1621-11 2023/11/28 2.81UT FUJI -KISO



K20231128114704




BLK: 3,SNR1: 0.64296E-01,SNR2: 0.99218



T20231128120340





BLK:11,SNR1: 3.5473 ,SNR2: 15.267





1638-025 2023/11/28 3.09UT TOYOKAWA-FUJI



F20231128120341




BLK:11,SNR1:-0.13704 ,SNR2: 1.2423



T20231128120340





BLK:12,SNR1: 2.4288 ,SNR2: 6.7341




1638-025 2023/11/28 3.09UT TOYOKAWA-KISO


K20231128120337




BLK:12,SNR1: 0.10731 ,SNR2: 0.51182




Frequency (Hz)



F20231128120341





BLK: 7, SNR1: 0.85245 , SNR2: 1.8022





1638-025 2023/11/28 3.09UT FUJI -KISO



K20231128120337




BLK: 7, SNR1: 0.72165 , SNR2: 3.3301




T20231128121034




BLK: 9,SNR1: 0.50864 ,SNR2: 1.5290




F20231128121035





BLK: 9,SNR1:-0.23276 ,SNR2: 1.4975




1644-106 2023/11/28 3.20UT TOYOKAWA-FUJI




T20231128121034




BLK:22,SNR1: 0.29823 ,SNR2: 1.4867




K20231128121032



BLK:22,SNR1: 0.40041 ,SNR2: 1.7243




1644-106 2023/11/28 3.20UT TOYOKAWA-KISO






F20231128121035





BLK: 8,SNR1:-0.26405 ,SNR2: 1.1897





1644-106 2023/11/28 3.20UT FUJI -KISO



K20231128121032




BLK: 8,SNR1: 0.93590E-01,SNR2: 1.0477





T20231128121555




No. Good Data




F20231128121556





No. Good Data




1650+004 2023/11/28 3.29UT TOYOKAWA-FUJI



T20231128121555





BLK:12,SNR1: 0.29211 ,SNR2: 0.83976




Frequency (Hz)

K20231128121553




BLK:12,SNR1: 0.32183 ,SNR2: 2.3799




Frequency (Hz)


1650+004 2023/11/28 3.29UT TOYOKAWA-KISO



F20231128121556




BLK: 7,SNR1:-0.14980 ,SNR2: 0.86566





1650+004 2023/11/28 3.29UT FUJI -KISO



K20231128121553




BLK: 7,SNR1: 0.91048 ,SNR2: 4.6140




T20231128122127




BLK: 6,SNR1: 0.74539 ,SNR2: 3.1238




F20231128122128





BLK: 6,SNR1: 0.67356 ,SNR2: 6.8590




1656+053 2023/11/28 3.39UT TOYOKAWA-FUJI




T20231128122127




BLK: 8,SNR1: 0.33770 ,SNR2: 1.7575




K20231128122124







BLK: 8,SNR1: 0.62284 ,SNR2: 2.3467




1656+053 2023/11/28 3.39UT TOYOKAWA-KISO







1656+053 2023/11/28 3.99UT FUJI -KISO



T20231128123757




BLK: 6,SNR1: 0.18503 ,SNR2: 1.7086





1712-033 2023/11/28 3.66UT TOYOKAWA-FUJI

F20231128123758




BLK: 6,SNR1:-0.14833 ,SNR2: 0.70233






T20231128123757




BLK:15,SNR1: 0.22572 ,SNR2: 1.6753





1712-033 2023/11/28 3.66UT TOYOKAWA-KISO


K20231128123755




BLK:15,SNR1: 1.4636 ,SNR2: 5.6523




F20231128123758




BLK: 6,SNR1:-0.15574 ,SNR2: 0.57609




K20231128123755





BLK: 6,SNR1: 0.26943E-01,SNR2: 2.0529




1712-033 2023/11/28 3.66UT FUJI -KISO




T20231128125559




BLK:11,SNR1: 0.52704 ,SNR2: 3.4590




F20231128125600





BLK:11,SNR1:-0.21187 ,SNR2: 0.68749




1730-13 2023/11/28 3.96UT TOYOKAWA-FUJI





T20231128125559




BLK:15,SNR1: 0.37506 ,SNR2: 2.9550




K20231128125556




BLK:15,SNR1: 0.44049 ,SNR2: 1.5502




1730-13 2023/11/28 3.96UT TOYOKAWA-KISO



F20231128125600





BLK:10,SNR1: 0.47055E-02,SNR2: 1.0092





1730-13 2023/11/28 3.96UT FUJI -KISO


K20231128125556




BLK:10,SNR1: 0.52416 ,SNR2: 3.4494




T20231128131324




BLK: 2,SNR1: 0.63312E-01,SNR2: 0.68427




F20231128131325




BLK: 2,SNR1: 1.3339 ,SNR2: 2.0467




1748+031 2023/11/28 4.25UT TOYOKAWA-FUJI




T20231128131324




BLK: 3,SNR1:-0.54624E-02,SNR2: 0.63591




K20231128131322




BLK: 3,SNR1: 0.55642E-01,SNR2: 3.1420




1748+031 2023/11/28 4.25UT TOYOKAWA-KISO





F20231128131325




BLK: 4,SNR1: 1.5592 ,SNR2: 3.1812




K20231128131322







BLK: 4,SNR1: 0.28580E-02,SNR2: 0.63267




1748+031 2023/11/28 4.25UT FUJI -KISO












1759+13 2023/11/28 4.43UT TOYOKAWA-FUJI







1759+13 2023/11/28 4.43UT TOYOKAWA-KISO



F20231128132418





BLK:11,SNR1: 3.2426 ,SNR2: 12.094





1759+13 2023/11/28 4.43UT FUJI -KISO



K20231128132415




BLK:11,SNR1: 0.91283 ,SNR2: 4.3289




T20231128134517




BLK: 4,SNR1: 0.28371 ,SNR2: 0.91289




F20231128134518




BLK: 4,SNR1: 0.26725 ,SNR2: 6.2857




1819-096 2023/11/28 4.78UT TOYOKAWA-FUJI





T20231128134517




BLK: 3,SNR1: 0.40128 ,SNR2: 1.8907




K20231128134515




BLK: 3,SNR1: 0.83821 ,SNR2: 6.1048




1819-096 2023/11/28 4.78UT TOYOKAWA-KISO





F20231128134518




BLK:10,SNR1: 0.58185 ,SNR2: 4.8472




K20231128134515





BLK:10,SNR1: 0.11454 ,SNR2: 1.1394




1819-096 2023/11/28 4.78UT FUJI -KISO




T20231128140001




BLK:15,SNR1: 1.2604 ,SNR2: 5.1362




F20231128140002




BLK:15,SNR1: 3.0275 ,SNR2: 12.190




1835+134 2023/11/28 5.03UT TOYOKAWA-FUJI



T20231128140001




BLK: 7,SNR1: 1.9438 ,SNR2: 7.9209





1835+134 2023/11/28 5.03UT TOYOKAWA-KISO

K20231128135958





BLK: 7,SNR1: 5.5600 ,SNR2: 12.193








F20231128140002




BLK:15,SNR1: 9.8460 ,SNR2: 21.497




K20231128135958





BLK:15,SNR1: 4.8312 ,SNR2: 13.145




1835+134 2023/11/28 5.03UT FUJI -KISO




T20231128142257




BLK:16,SNR1: 7.8185 ,SNR2: 17.115




F20231128142258





BLK:16,SNR1: 8.7212 ,SNR2: 18.941




1858+171 2023/11/28 5.41UT TOYOKAWA-FUJI



T20231128142257




BLK:12,SNR1: 8.4834 ,SNR2: 18.537





1858+171 2023/11/28 5.41UT TOYOKAWA-KISO


K20231128142255




BLK:12,SNR1: 9.5045 ,SNR2: 20.402



F20231128142258




BLK:32,SNR1: 14.904 ,SNR2: 23.235





1858+171 2023/11/28 5.41UT FUJI -KISO



K20231128142255




BLK:32,SNR1: 8.1490 ,SNR2: 17.539




T20231128144032




BLK: 8,SNR1: 0.68365 ,SNR2: 2.7433




F20231128144033




BLK: 8,SNR1:-0.85647E-01,SNR2: 1.4491




1915-121 2023/11/28 5.70UT TOYOKAWA-FUJI





T20231128144032




BLK: 6,SNR1: 0.88705 ,SNR2: 3.7648




K20231128144030





BLK: 6,SNR1: 0.62113 ,SNR2: 1.6370




1915-121 2023/11/28 5.70UT TOYOKAWA-KISO





F20231128144033




BLK: 7,SNR1: 0.89398E-01,SNR2: 1.8586




K20231128144030





BLK: 7,SNR1: 3.1122 ,SNR2: 8.8374




1915-121 2023/11/28 5.70UT FUJI -KISO





T20231128145414




BLK: 8,SNR1: 0.86521 ,SNR2: 2.8568




F20231128145415



BLK: 8,SNR1: 7.2069 ,SNR2: 11.708





1928-142 2023/11/28 5.93UT TOYOKAWA-FUJI






T20231128145414





BLK:12,SNR1: 0.70719 ,SNR2: 2.8412





1928-142 2023/11/28 5.93UT TOYOKAWA-KISO


K20231128145412




BLK:12,SNR1: 1.8403 ,SNR2: 4.4012




F20231128145415




BLK:16,SNR1: 11.335 ,SNR2: 21.013




K20231128145412







BLK:16,SNR1: 2.3267 ,SNR2: 3.4866








1928-142 2023/11/28 5.93UT FUJI -KISO






2014+358 2023/11/28 6.68UT TOYOKAWA-FUJI








2014+358 2023/11/28 6.68UT TOYOKAWA-KISO





F20231128153851




BLK: 3,SNR1:-0.41477E-01,SNR2: 1.4189




K20231128153848




BLK: 3,SNR1: 1.3504 ,SNR2: 8.9743




2014+358 2023/11/28 6.68UT FUJI -KISO




T20231128160926




BLK: 1,SNR1: 0.25795 ,SNR2: 2.3691




F20231128160927





BLK: 1,SNR1: 0.28883 ,SNR2: 3.3055




3C422 2023/11/28 7.19UT TOYOKAWA-FUJI





T20231128160926




BLK: 7,SNR1: 0.12819 ,SNR2: 1.5541




K20231128160923




BLK: 7,SNR1: 0.66560 ,SNR2: 2.7364




3C422 2023/11/28 7.19UT TOYOKAWA-KISO





F20231128160927




BLK: 3,SNR1:-0.19497 ,SNR2: 0.62961




K20231128160923



BLK: 3,SNR1: 0.15520 ,SNR2: 0.74311




3C422 2023/11/28 7.19UT FUJI -KISO







T20231128163004




BLK: 6,SNR1: 0.77747E-01,SNR2: 1.3213




F20231128163005





BLK: 6,SNR1: 0.80388 ,SNR2: 1.8973




2105-072 2023/11/28 7.53UT TOYOKAWA-FUJI





T20231128163004




BLK: 5,SNR1: 0.85138E-01,SNR2: 1.4233




K20231128163001




BLK: 5,SNR1: 0.86837 ,SNR2: 3.5153




2105-072 2023/11/28 7.53UT TOYOKAWA-KISO





F20231128163005




BLK: 5,SNR1:-0.2196 ,SNR2: 1.2984




K20231128163001





BLK: 5,SNR1: 2.1956 ,SNR2: 7.7596




2105-072 2023/11/28 7.53UT FUJI -KISO




T20231128164552




BLK: 2,SNR1: 0.17365 ,SNR2: 0.76684




F20231128164553





BLK: 2,SNR1:-0.48976E-01,SNR2: 0.93883




2121-014 2023/11/28 7.79UT TOYOKAWA-FUJI





T20231128164552




BLK: 5,SNR1:-0.14380E-01,SNR2: 0.86094




K20231128164549







BLK: 5,SNR1: 0.56621 ,SNR2: 4.2122



2121-014 2023/11/28 7.79UT TOYOKAWA-KISO





2121-014 2023/11/28 7.79UT FUJI -KISO

