





BLK: 9,SNR1: 19.709 ,SNR2: 70.208





BLK: 9,SNR1: 0.32518 ,SNR2: 1.9292






1031-11 2023/11/28 20.92UT TOYOKAWA-FUJI







BLK: 7, SNR1: 5.1358 , SNR2: 34.735




BLK: 7, SNR1: 7.4441 , SNR2: 14.507




1031-11 2023/11/28 20.92UT TOYOKAWA-KISO



F20231129055336




BLK: 9,SNR1: 0.26768 ,SNR2: 3.7002




Frequency (Hz)

K20231129055333




BLK: 9,SNR1: 3.9263 ,SNR2: 7.9192





Frequency (Hz)


1031-11 2023/11/28 20.92UT FUJI -KISO



T20231129055809





BLK: 6,SNR1: 3.1173 ,SNR2: 16.351




Frequency (Hz)

F20231129055810




BLK: 6,SNR1: 0.96082 ,SNR2: 1.9937





Frequency (Hz)


1035-058 2023/11/28 21.00UT TOYOKAWA-FUJI



T20231129055809




BLK:12,SNR1: 1.7349 ,SNR2: 14.015




Frequency (Hz)

K20231129055807




BLK:12,SNR1: 0.44677 ,SNR2: 5.0096





Frequency (Hz)


1035-058 2023/11/28 21.00UT TOYOKAWA-KISO





F20231129055810




BLK: 4,SNR1:-0.65359E-01,SNR2: 2.9103




K20231129055807





BLK: 4,SNR1: 1.4045 ,SNR2: 8.0900




1035-058 2023/11/28 21.00UT FUJI -KISO





T20231129060721




No.Good Data




F20231129060722




No.Good Data




1044-008 2023/11/28 21.15UT TOYOKAWA-FUJI



T20231129060721




BLK: 4,SNR1: 0.13412 ,SNR2: 1.1962




Frequency (Hz)

K20231129060719




BLK: 4,SNR1: 0.71773 ,SNR2: 3.7670




Frequency (Hz)

1044-008 2023/11/28 21.15UT TOYOKAWA-KISO






F20231129060722




BLK: 5,SNR1: 0.64928 ,SNR2: 2.5924




Frequency (Hz)

K20231129060719




BLK: 5,SNR1: 1.0316 ,SNR2: 3.7216





Frequency (Hz)


1044-008 2023/11/28 21.15UT FUJI -KISO



T20231129061826





No.Good Data




Frequency (Hz)

F20231129061826




No.Good Data




Frequency (Hz)


1055+01 2023/11/28 21.34UT TOYOKAWA-FUJI



T20231129061826





BLK: 4,SNR1: 0.23418 ,SNR2: 1.9974




Frequency (Hz)

K20231129061824




BLK: 4,SNR1: 0.82271E-01,SNR2: 1.4021





Frequency (Hz)


1055+01 2023/11/28 21.34UT TOYOKAWA-KISO



F20231129061826





BLK: 3,SNR1:-0.13333 ,SNR2: 0.12508




Frequency (Hz)

K20231129061824






BLK: 3,SNR1: 0.85009 ,SNR2: 4.4690





Frequency (Hz)

1055+01 2023/11/28 21.34UT FUJI -KISO







BLK: 3,SNR1: 0.35198E-01,SNR2: 1.0326





BLK: 3,SNR1: 0.37398 ,SNR2: 1.5564




1107+109 2023/11/28 21.52UT TOYOKAWA-FUJI



T20231129062943





BLK: 3,SNR1: 0.17057 ,SNR2: 0.67308




Frequency (Hz)

K20231129062941





BLK: 3,SNR1: 1.3649 ,SNR2: 2.5682





Frequency (Hz)

1107+109 2023/11/28 21.52UT TOYOKAWA-KISO







BLK: 2,SNR1: -0.24384 ,SNR2: 0.38805





BLK: 2,SNR1: 0.16942 ,SNR2: 0.74600




1107+109 2023/11/28 21.52UT FUJI -KISO



T20231129063921





BLK: 2,SNR1: 0.20698 ,SNR2: 0.34570




Frequency (Hz)

F20231129063922




BLK: 2,SNR1: 3.9996 ,SNR2: 7.0570





Frequency (Hz)

3C255 2023/11/28 21.68UT TOYOKAWA-FUJI






T20231129063921





BLK: 3,SNR1: 0.33059 ,SNR2: 2.3177




Frequency (Hz)

3C255 2023/11/28 21.68UT TOYOKAWA-KISO


K20231129063919




BLK: 3,SNR1: 7.6788 ,SNR2: 24.157




Frequency (Hz)





F20231129063922




BLK: 3,SNR1:-0.25692 ,SNR2: 0.95629




K20231129063919





BLK: 3,SNR1: 0.15635 ,SNR2: 1.9430




3C255 2023/11/28 21.68UT FUJI -KISO



T20231129070319





BLK: 4,SNR1: 1.2732 ,SNR2: 24.796




Frequency (Hz)

3C263.1 2023/11/28 22.08UT TOYOKAWA-FUJI


F20231129070320





BLK: 4,SNR1: 0.95226E-01,SNR2: 3.6594




Frequency (Hz)



T20231129070319





BLK: 6,SNR1: 1.1300 ,SNR2: 19.607




Frequency (Hz)

3C263.1 2023/11/28 22.08UT TOYOKAWA-KISO


K20231129070317





BLK: 6,SNR1: 1.3702 ,SNR2: 11.778




Frequency (Hz)



F20231129070320





BLK: 2,SNR1: 0.87405E-01,SNR2: 1.5884




Frequency (Hz)

K20231129070317




BLK: 2,SNR1: 18.529 ,SNR2: 32.655




Frequency (Hz)


3C263.1 2023/11/28 22.08UT FUJI -KISO



T20231129070946




BLK: 8,SNR1: 0.14182 ,SNR2: 0.90653




Frequency (Hz)

3C267 2023/11/28 22.19UT TOYOKAWA-FUJI


F20231129070947




BLK: 8,SNR1: 0.78048 ,SNR2: 2.0632




Frequency (Hz)



T20231129070946




BLK: 7,SNR1: 0.53702 ,SNR2: 2.9714




Frequency (Hz)

K20231129070944




BLK: 7,SNR1: 2.5467 ,SNR2: 6.4263





Frequency (Hz)


3C267 2023/11/28 22.19UT TOYOKAWA-KISO



F20231129070947





BLK: 5,SNR1: 0.53387E-01,SNR2: 3.8693




Frequency (Hz)

3C267 2023/11/28 22.19UT FUJI -KISO


K20231129070944



BLK: 5,SNR1: 0.18457 ,SNR2: 1.2126




Frequency (Hz)







T20231129074851




BLK: 7,SNR1: 0.37420 ,SNR2: 3.3887




F20231129074852




BLK: 7,SNR1:-0.47407E-01,SNR2: 2.3116




3C273 2023/11/28 22.84UT TOYOKAWA-FUJI



T20231129074851





BLK:11,SNR1: 0.29467 ,SNR2: 2.9635




Frequency (Hz)

3C273 2023/11/28 22.84UT TOYOKAWA-KISO


K20231129074849





BLK:11,SNR1: 1.9009 ,SNR2: 5.3450




Frequency (Hz)



F20231129074852





BLK: 5,SNR1:-0.30274 ,SNR2: 0.0000




Frequency (Hz)

3C273 2023/11/28 22.84UT FUJI -KISO


K20231129074849





BLK: 5,SNR1: 0.88059 ,SNR2: 3.3019




Frequency (Hz)



T20231129080201




BLK: 9,SNR1: 0.32848 ,SNR2: 1.6940




Frequency (Hz)

3C275 2023/11/28 23.06UT TOYOKAWA-FUJI


F20231129080202





BLK: 9,SNR1:-0.69987E-01,SNR2: 1.3859




Frequency (Hz)



T20231129080201





BLK: 4,SNR1: 1.2011 ,SNR2: 5.2056




Frequency (Hz)

3C275 2023/11/28 23.06UT TOYOKAWA-KISO


K20231129080159





BLK: 4,SNR1: 0.57966 ,SNR2: 2.8563




Frequency (Hz)





F20231129080202




BLK: 2, SNR1: 0.49347 , SNR2: 2.9539




K20231129080159





BLK: 2, SNR1: 0.79505 , SNR2: 9.0358




3C275 2023/11/28 23.06UT FUJI -KISO



T20231129081550




BLK: 7,SNR1: 89.994 ,SNR2: 285.66




Frequency (Hz)

3C279 2023/11/28 23.29UT TOYOKAWA-FUJI


F20231129081551




BLK: 7,SNR1: 1.8293 ,SNR2: 6.7953




Frequency (Hz)




T20231129081550




BLK:17,SNR1: 38.625 ,SNR2: 84.364




K20231129081548



BLK:17,SNR1: 0.35735 ,SNR2: 1.3583




3C279 2023/11/28 23.29UT TOYOKAWA-KISO






F20231129081551





BLK: 6,SNR1: 0.65667 ,SNR2: 2.7296




Frequency (Hz)

K20231129081548




BLK: 6,SNR1: 9.1305 ,SNR2: 17.446




Frequency (Hz)


3C279 2023/11/28 23.29UT FUJI -KISO



T20231129083538




BLK: 5, SNR1: 3.6760 ,SNR2: 27.087





1313+453 2023/11/28 23.62UT TOYOKAWA-FUJI


F20231129083539




BLK: 5, SNR1: -0.15919 ,SNR2: 0.23653




T20231129083538




BLK: 5,SNR1: 9.0853 ,SNR2: 71.263




K20231129083536





BLK: 5,SNR1: 0.89111 ,SNR2: 3.7230




1313+453 2023/11/28 23.62UT TOYOKAWA-KISO



F20231129083539





BLK: 3,SNR1: 0.29757 ,SNR2: 4.0775




Frequency (Hz)

K20231129083536




BLK: 3,SNR1: 1.4875 ,SNR2: 8.5703




Frequency (Hz)


1313+453 2023/11/28 23.62UT FUJI -KISO



T20231129084544





BLK:10,SNR1: 0.21268 ,SNR2: 1.4515




Frequency (Hz)

F20231129084544




BLK:10,SNR1: 0.51094 ,SNR2: 5.4034




Frequency (Hz)


1323+32 2023/11/28 23.79UT TOYOKAWA-FUJI




T20231129084544




BLK: 9,SNR1: 0.11776 ,SNR2: 1.1549




K20231129084542





BLK: 9,SNR1: 5.6062 ,SNR2: 9.9077




1323+32 2023/11/28 23.79UT TOYOKAWA-KISO





F20231129084544




BLK: 7,SNR1: 0.55013 ,SNR2: 5.2516




K20231129084542





BLK: 7,SNR1: 1.7304 ,SNR2: 7.1919




1323+32 2023/11/28 23.79UT FUJI -KISO




T20231129085035




BLK: 9,SNR1: 0.20515 ,SNR2: 1.8652




F20231129085036



BLK: 9,SNR1: 0.24614 ,SNR2: 3.1488





3C286 2023/11/28 23.87UT TOYOKAWA-FUJI






T20231129085035





BLK: 4,SNR1: 0.97309E-01,SNR2: 0.92680




Frequency (Hz)

K20231129085033




BLK: 4,SNR1: 6.3579 ,SNR2: 22.421




Frequency (Hz)


3C286 2023/11/28 23.87UT TOYOKAWA-KISO



F20231129085036




BLK: 7,SNR1: 0.31337 ,SNR2: 4.1844





3C286 2023/11/28 23.87UT FUJI -KISO



K20231129085033




BLK: 7,SNR1: 0.10388 ,SNR2: 0.98673





T20231129090702




BLK: 4,SNR1: 0.67455E-01,SNR2: 2.4924




F20231129090703





BLK: 4,SNR1: 0.94153 ,SNR2: 1.7059




1345+12 2023/11/29 0.15UT TOYOKAWA-FUJI





T20231129090702




BLK: 3,SNR1: 0.33705 ,SNR2: 1.0446




K20231129090700




BLK: 3,SNR1: 0.96087 ,SNR2: 4.2498




1345+12 2023/11/29 0.15UT TOYOKAWA-KISO





F20231129090703




BLK: 5,SNR1: 0.13589 ,SNR2: 3.4579




K20231129090700




BLK: 5,SNR1: 0.39028 ,SNR2: 2.1936




1345+12 2023/11/29 0.15UT FUJI -KISO




T20231129091722




BLK: 3,SNR1: 0.78248E-01,SNR2: 1.9984




F20231129091723





BLK: 3,SNR1: 0.27558 ,SNR2: 1.5813




1355+01 2023/11/29 0.32UT TOYOKAWA-FUJI





T20231129091722




BLK: 4, SNR1: 0.15350 , SNR2: 1.9384




K20231129091720




BLK: 4, SNR1: 3.2829 , SNR2: 14.875




1355+01 2023/11/29 0.32UT TOYOKAWA-KISO





F20231129091723




BLK: 4,SNR1:-0.15014 ,SNR2: 2.0039




K20231129091720



BLK: 4,SNR1: 3.3150 ,SNR2: 15.038




1355+01 2023/11/29 0.32UT FUJI -KISO







T20231129093833




BLK: 9,SNR1: 0.34020 ,SNR2: 3.0807




F20231129093834





BLK: 9,SNR1: 0.17566E-01,SNR2: 1.9388




3C298 2023/11/29 0.67UT TOYOKAWA-FUJI



T20231129093833





BLK: 9,SNR1: 0.27826 ,SNR2: 2.3619




Frequency (Hz)

K20231129093831




BLK: 9,SNR1: 2.1787 ,SNR2: 6.1500




Frequency (Hz)


3C298 2023/11/29 0.67UT TOYOKAWA-KISO



F20231129093834





BLK: 5, SNR1: 0.14561 , SNR2: 3.3590




Frequency (Hz)

K20231129093831




BLK: 5, SNR1: 1.8785 , SNR2: 12.218




Frequency (Hz)


3C298 2023/11/29 0.67UT FUJI -KISO



T20231129095016




BLK: 3,SNR1: 0.42754E-02,SNR2: 0.79714




Frequency (Hz)

F20231129095017




BLK: 3,SNR1:-0.35945 ,SNR2: 0.46842





Frequency (Hz)


1428-03 2023/11/29 0.87UT TOYOKAWA-FUJI





T20231129095016




No. Good Data




K20231129095013





No. Good Data




1428-03 2023/11/29 0.87UT TOYOKAWA-KISO



F20231129095017





BLK: 4, SNR1: 0.19709 , SNR2: 5.0358




Frequency (Hz)

K20231129095013




BLK: 4, SNR1: 2.1651 , SNR2: 8.0978




Frequency (Hz)


1428-03 2023/11/29 0.87UT FUJI -KISO



T20231129101521




BLK:11,SNR1: 0.53747 ,SNR2: 3.0962





1453-10 2023/11/29 1.28UT TOYOKAWA-FUJI


F20231129101522




BLK:11,SNR1:-0.67942E-01,SNR2: 2.0853



T20231129101521





BLK: 8,SNR1: 0.38688 ,SNR2: 3.4146





1453-10 2023/11/29 1.28UT TOYOKAWA-KISO

K20231129101519





BLK: 8,SNR1: 0.89405E-01,SNR2: 0.97926






F20231129101522





BLK: 5, SNR1: -0.16767 , SNR2: 1.2331




Frequency (Hz)

1453-10 2023/11/29 1.28UT FUJI -KISO


K20231129101519





BLK: 5, SNR1: 1.7161 , SNR2: 12.501




Frequency (Hz)





T20231129103013




No.Good Data




F20231129103014





No.Good Data




1508-05 2023/11/29 1.53UT TOYOKAWA-FUJI





T20231129103013




BLK: 1,SNR1: 0.77594 ,SNR2: 0.87619




K20231129103011




BLK: 1,SNR1:-0.12025 ,SNR2: 0.61776




1508-05 2023/11/29 1.53UT TOYOKAWA-KISO





F20231129103014




BLK: 5,SNR1: 0.57071E-01,SNR2: 1.2046




K20231129103011





BLK: 5,SNR1: 0.45371 ,SNR2: 2.6582




1508-05 2023/11/29 1.53UT FUJI -KISO





T20231129103913




No.Good Data




F20231129103914




No.Good Data




3C318 2023/11/29 1.68UT TOYOKAWA-FUJI



T20231129103913





BLK: 4, SNR1: 0.16481 , SNR2: 0.64573





3C318 2023/11/29 1.68UT TOYOKAWA-KISO



K20231129103911




BLK: 4, SNR1: 1.0422 , SNR2: 5.4697



F20231129103914





BLK: 5, SNR1: 0.37081 , SNR2: 4.0036









3C318 2023/11/29 1.68UT FUJI -KISO

K20231129103911




BLK: 5, SNR1: 0.24650 , SNR2: 2.2628







1523+03 2023/11/29 1.78UT TOYOKAWA-FUJI







T20231129104500




BLK:12,SNR1: 0.86595 ,SNR2: 7.7838




K20231129104458




BLK:12,SNR1: 2.9634 ,SNR2: 5.9839




1523+03 2023/11/29 1.78UT TOYOKAWA-KISO





F20231129104500




BLK: 5,SNR1:-0.30507 ,SNR2: 0.51461




K20231129104458





BLK: 5,SNR1: 0.99876 ,SNR2: 2.4619




1523+03 2023/11/29 1.78UT FUJI -KISO



T20231129105640




BLK: 1,SNR1: 0.21918 ,SNR2: 1.2317




Frequency (Hz)

F20231129105640




BLK: 1,SNR1:-0.19956 ,SNR2: 0.66706




Frequency (Hz)


1535+139 2023/11/29 1.97UT TOYOKAWA-FUJI



T20231129105640




BLK: 3,SNR1: 0.10183 ,SNR2: 1.0132





1535+139 2023/11/29 1.97UT TOYOKAWA-KISO


K20231129105638




BLK: 3,SNR1: 2.0687 ,SNR2: 13.040



F20231129105640




BLK: 6,SNR1:-0.19113 ,SNR2: 1.1018





1535+139 2023/11/29 1.97UT FUJI -KISO


K20231129105638




BLK: 6,SNR1: 1.1941 ,SNR2: 6.0004



T20231129110703




BLK:11,SNR1: 1.4223 ,SNR2: 1.9356





1545-12 2023/11/29 2.15UT TOYOKAWA-FUJI


F20231129110704




BLK:11,SNR1:-0.40762E-01,SNR2: 1.0407



T20231129110703





BLK:12,SNR1: 1.4267 ,SNR2: 1.7169





1545-12 2023/11/29 2.15UT TOYOKAWA-KISO


K20231129110701




BLK:12,SNR1: 0.90024 ,SNR2: 1.6662




F20231129110704




BLK: 5,SNR1: 0.82370E-01,SNR2: 1.2512




K20231129110701



BLK: 5,SNR1: 0.22187 ,SNR2: 4.3932




1545-12 2023/11/29 2.15UT FUJI -KISO






T20231129112807





BLK:14,SNR1: 50.666 ,SNR2: 130.25





1607+26 2023/11/29 2.50UT TOYOKAWA-FUJI


F20231129112808




BLK:14,SNR1: 0.63491 ,SNR2: 7.6406



T20231129112807





BLK:12,SNR1: 58.148 ,SNR2: 236.29





1607+26 2023/11/29 2.50UT TOYOKAWA-KISO


K20231129112805




BLK:12,SNR1: 1.2376 ,SNR2: 5.9966



F20231129112808




BLK: 9, SNR1: 0.87765 , SNR2: 10.500




Frequency (Hz)

K20231129112805




BLK: 9, SNR1: 1.2774 , SNR2: 8.8120





Frequency (Hz)


1607+26 2023/11/29 2.50UT FUJI -KISO



T20231129114310




BLK:11,SNR1: 0.34701 ,SNR2: 2.5798





1621-11 2023/11/29 2.75UT TOYOKAWA-FUJI


F20231129114311




BLK:11,SNR1: -0.19657E-01,SNR2: 1.9049



T20231129114310




BLK:11,SNR1: 0.27915 ,SNR2: 2.1815




1621-11 2023/11/29 2.75UT TOYOKAWA-KISO


K20231129114308




BLK:11,SNR1: 11.200 ,SNR2: 18.972




Frequency (Hz)





F20231129114311




BLK:11,SNR1:-0.98554E-02,SNR2: 2.1195




K20231129114308





BLK:11,SNR1: 10.066 ,SNR2: 14.819




1621-11 2023/11/29 2.75UT FUJI -KISO



T20231129115944




BLK:11,SNR1: 0.85010 ,SNR2: 3.8070




1638-025 2023/11/29 3.02UT TOYOKAWA-FUJI


F20231129115945





BLK:11,SNR1:-0.63613E-01,SNR2: 0.85223




Frequency (Hz)



T20231129115944





BLK:14,SNR1: 0.94851 ,SNR2: 4.3091




Frequency (Hz)

K20231129115941




BLK:14,SNR1: 0.38314 ,SNR2: 2.0256





Frequency (Hz)

1638-025 2023/11/29 3.02UT TOYOKAWA-KISO








F20231129115945




BLK: 3,SNR1:-0.19479 ,SNR2: 0.0000




K20231129115941





BLK: 3,SNR1: 0.28053 ,SNR2: 1.4065




1638-025 2023/11/29 3.02UT FUJI -KISO




T20231129120639




BLK: 9,SNR1: 0.43950 ,SNR2: 3.1436




F20231129120640





BLK: 9,SNR1: 0.21160 ,SNR2: 0.92241




1644-106 2023/11/29 3.14UT TOYOKAWA-FUJI



T20231129120639





BLK:11,SNR1: 0.36281 ,SNR2: 3.3513





1644-106 2023/11/29 3.14UT TOYOKAWA-KISO



K20231129120636




BLK:11,SNR1: 1.8124 ,SNR2: 6.0492



F20231129120640





BLK: 5, SNR1: 0.65727 , SNR2: 1.4595





1644-106 2023/11/29 3.14UT FUJI -KISO



K20231129120636




BLK: 5, SNR1: 0.20673 , SNR2: 1.2367



T20231129121159





BLK: 4,SNR1: 0.66660 ,SNR2: 3.9861




Frequency (Hz)

F20231129121200




BLK: 4,SNR1: 0.36898 ,SNR2: 1.3859





Frequency (Hz)


1650+004 2023/11/29 3.23UT TOYOKAWA-FUJI





T20231129121159




BLK:15,SNR1: 2.2842 ,SNR2: 16.269




K20231129121156




BLK:15,SNR1: 3.8328 ,SNR2: 7.9125




1650+004 2023/11/29 3.23UT TOYOKAWA-KISO



F20231129121200




BLK: 7,SNR1: 0.69695 ,SNR2: 2.0683





1650+004 2023/11/29 3.23UT FUJI -KISO


K20231129121156




BLK: 7,SNR1: 5.7574 ,SNR2: 23.352




T20231129121731




BLK: 8,SNR1: 0.84658E-01,SNR2: 0.67739




F20231129121732



BLK: 8,SNR1: 0.26078 ,SNR2: 1.8222




1656+053 2023/11/29 3.32UT TOYOKAWA-FUJI








T20231129121731




BLK: 4,SNR1: 0.42478 ,SNR2: 1.1253




K20231129121728




BLK: 4,SNR1: 0.10085 ,SNR2: 0.96767




1656+053 2023/11/29 3.32UT TOYOKAWA-KISO




F20231129121732




BLK: 6,SNR1: 0.25478 ,SNR2: 4.4915




K20231129121728




BLK: 6,SNR1: 0.99675E-01,SNR2: 0.44542




1656+053 2023/11/29 3.32UT FUJI -KISO




T20231129123401




BLK: 4,SNR1: 0.22653E-01,SNR2: 0.59144




F20231129123402





BLK: 4,SNR1:-0.23583 ,SNR2: 0.49387




1712-033 2023/11/29 3.60UT TOYOKAWA-FUJI




T20231129123401




BLK: 7,SNR1: 0.37909 ,SNR2: 1.7802




K20231129123359




BLK: 7,SNR1: 1.1527 ,SNR2: 3.7655




1712-033 2023/11/29 3.60UT TOYOKAWA-KISO





F20231129123402




BLK: 4,SNR1: 0.13773E-01,SNR2: 0.85740




K20231129123359





BLK: 4,SNR1: 1.1881 ,SNR2: 4.0808




1712-033 2023/11/29 3.60UT FUJI -KISO



T20231129125203




BLK:10,SNR1: 5.1301 ,SNR2: 12.400





1730-13 2023/11/29 3.90UT TOYOKAWA-FUJI



F20231129125204




BLK:10,SNR1: 0.26771 ,SNR2: 1.8845



T20231129125203





BLK:19,SNR1: 3.6769 ,SNR2: 9.3101





1730-13 2023/11/29 3.90UT TOYOKAWA-KISO


K20231129125200




BLK:19,SNR1: 2.7406 ,SNR2: 7.4857



F20231129125204




BLK: 5,SNR1:-0.97605E-01,SNR2: 1.0999





1730-13 2023/11/29 3.90UT FUJI -KISO

K20231129125200





BLK: 5,SNR1: 2.2861 ,SNR2: 6.6588








T20231129130928




BLK: 5,SNR1: 0.66870E-01,SNR2: 0.32258




F20231129130929





BLK: 5,SNR1: 0.18414 ,SNR2: 3.5209




1748+031 2023/11/29 4.19UT TOYOKAWA-FUJI





T20231129130928




No. Good Data




K20231129130925





No. Good Data




1748+031 2023/11/29 4.19UT TOYOKAWA-KISO



F20231129130929





BLK: 4,SNR1: 14.192 ,SNR2: 23.339




Frequency (Hz)

K20231129130925




BLK: 4,SNR1: 6.3561 ,SNR2: 13.048




Frequency (Hz)


1748+031 2023/11/29 4.19UT FUJI -KISO




T20231129132021




BLK: 6,SNR1: 0.27776 ,SNR2: 0.99955




F20231129132022




BLK: 6,SNR1: 1.2022 ,SNR2: 10.227




1759+13 2023/11/29 4.37UT TOYOKAWA-FUJI





T20231129132021




BLK: 7,SNR1: 0.22163 ,SNR2: 0.98961




K20231129132018




BLK: 7,SNR1: 0.78999 ,SNR2: 3.9952




1759+13 2023/11/29 4.37UT TOYOKAWA-KISO





F20231129132022




BLK: 9,SNR1: 0.98633 ,SNR2: 8.7129




K20231129132018





BLK: 9,SNR1: 7.3471 ,SNR2: 13.178




1759+13 2023/11/29 4.37UT FUJI -KISO





T20231129134121




BLK: 7,SNR1: 0.82540E-01,SNR2: 0.40366




F20231129134122




BLK: 7,SNR1: 2.2876 ,SNR2: 9.6941




1819-096 2023/11/29 4.72UT TOYOKAWA-FUJI




T20231129134121




BLK: 7,SNR1: 0.12751 ,SNR2: 0.57408




K20231129134118



BLK: 7,SNR1: 3.5025 ,SNR2: 10.755




1819-096 2023/11/29 4.72UT TOYOKAWA-KISO








F20231129134122




BLK: 7,SNR1: 2.8727 ,SNR2: 11.586




K20231129134118





BLK: 7,SNR1: 2.6599 ,SNR2: 4.6440




1819-096 2023/11/29 4.72UT FUJI -KISO





T20231129134944




BLK:20,SNR1: 7.3799 ,SNR2: 16.118




F20231129134945





BLK:20,SNR1: 9.2834 ,SNR2: 20.314




1829+29 2023/11/29 4.86UT TOYOKAWA-FUJI





T20231129134944




BLK:15,SNR1: 2.7988 ,SNR2: 11.221




K20231129134941





BLK:15,SNR1: 2.6846 ,SNR2: 10.705




1829+29 2023/11/29 4.86UT TOYOKAWA-KISO



F20231129134945





BLK:19,SNR1: 8.1050 ,SNR2: 17.768









1829+29 2023/11/29 4.86UT FUJI -KISO

K20231129134941





BLK:19,SNR1: 2.2983 ,SNR2: 9.2571







1835+134 2023/11/29 4.96UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.18558 ,SNR2: 2.9253





BLK: 3,SNR1: 25.097 ,SNR2: 49.486




1835+134 2023/11/29 4.96UT TOYOKAWA-KISO





F20231129135606




BLK: 9,SNR1: 0.88627 ,SNR2: 8.0561




K20231129135602





BLK: 9,SNR1: 6.4817 ,SNR2: 29.301




1835+134 2023/11/29 4.96UT FUJI -KISO










1858+171 2023/11/29 5.35UT TOYOKAWA-FUJI










1858+171 2023/11/29 5.35UT TOYOKAWA-KISO





F20231129141903




BLK: 5,SNR1: 0.17762 ,SNR2: 2.1808




K20231129141859




BLK: 5,SNR1: 1.2433 ,SNR2: 8.9337




1858+171 2023/11/29 5.35UT FUJI -KISO





T20231129143636




BLK:15,SNR1: 7.6921 ,SNR2: 19.985




F20231129143637




BLK:15,SNR1: 20.191 ,SNR2: 27.320




1915-121 2023/11/29 5.64UT TOYOKAWA-FUJI




T20231129143636




BLK:10,SNR1: 2.5925 ,SNR2: 6.8740




K20231129143633





BLK:10,SNR1: 3.3256 ,SNR2: 13.192




1915-121 2023/11/29 5.64UT TOYOKAWA-KISO





F20231129143637




BLK:22,SNR1: 23.801 ,SNR2: 32.422




K20231129143633





BLK:22,SNR1: 3.3353 ,SNR2: 13.208




1915-121 2023/11/29 5.64UT FUJI -KISO




T20231129145018




BLK: 6,SNR1: 0.19362 ,SNR2: 2.0530




F20231129145019





BLK: 6,SNR1: 0.16398 ,SNR2: 3.4854




1928-142 2023/11/29 5.87UT TOYOKAWA-FUJI





T20231129145018




BLK: 5,SNR1: 0.40877 ,SNR2: 5.6196




K20231129145015




BLK: 5,SNR1: 8.8493 ,SNR2: 27.291




1928-142 2023/11/29 5.87UT TOYOKAWA-KISO





F20231129145019




BLK: 5,SNR1: 7.5835 ,SNR2: 13.014




K20231129145015



BLK: 5,SNR1: 0.36334 ,SNR2: 1.1578





1928-142 2023/11/29 5.87UT FUJI -KISO








T20231129153454




BLK: 3,SNR1:-0.86416E-01,SNR2: 0.16465




F20231129153454





BLK: 3,SNR1: 0.25507 ,SNR2: 3.4764




2014+358 2023/11/29 6.61UT TOYOKAWA-FUJI





T20231129153454




BLK: 3,SNR1: 0.92093E-02,SNR2: 0.25597




K20231129153451





BLK: 3,SNR1: 1.0097 ,SNR2: 4.7981




2014+358 2023/11/29 6.61UT TOYOKAWA-KISO





F20231129153454




BLK: 5,SNR1: 2.0369 ,SNR2: 4.5296




K20231129153451





BLK: 5,SNR1: 1.2182 ,SNR2: 7.6869




2014+358 2023/11/29 6.61UT FUJI -KISO





T20231129160530




BLK: 6,SNR1: 0.23283 ,SNR2: 0.98947




F20231129160531





BLK: 6,SNR1: 0.40926 ,SNR2: 6.4084




3C422 2023/11/29 7.12UT TOYOKAWA-FUJI





T20231129160530




BLK: 4,SNR1: 0.14264 ,SNR2: 0.48022




K20231129160528





BLK: 4,SNR1: 1.5309 ,SNR2: 5.9479




3C422 2023/11/29 7.12UT TOYOKAWA-KISO





F20231129160531




BLK: 6,SNR1: 2.1029 ,SNR2: 6.4567




K20231129160528







BLK: 6,SNR1: 1.7198 ,SNR2: 11.187








3C422 2023/11/29 7.12UT FUJI -KISO






2105-072 2023/11/29 7.46UT TOYOKAWA-FUJI










2105-072 2023/11/29 7.46UT TOYOKAWA-KISO









2105-072 2023/11/29 7.46UT FUJI -KISO




T20231129164156




BLK: 6,SNR1: 0.47320E-01,SNR2: 1.0722




F20231129164157





BLK: 6,SNR1: 7.3219 ,SNR2: 14.720




2121-014 2023/11/29 7.73UT TOYOKAWA-FUJI





T20231129164156




BLK: 6,SNR1: 0.11754 ,SNR2: 1.4529




K20231129164153







BLK: 6,SNR1: 1.3185 ,SNR2: 4.0195



2121-014 2023/11/29 7.73UT TOYOKAWA-KISO





2121-014 2023/11/29 7.73UT FUJI -KISO

