




T20231205061545





BLK: 1,SNR1: 20.642 ,SNR2: 262.81




Frequency (Hz)

3C255 2023/12/04 21.29UT TOYOKAWA-FUJI


F20231205061546





BLK: 1,SNR1: 0.27086 ,SNR2: 4.4717




Frequency (Hz)



T20231205061545





BLK: 4,SNR1: 16.763 ,SNR2: 170.45




Frequency (Hz)

3C255 2023/12/04 21.29UT TOYOKAWA-KISO


K20231205061543




BLK: 4,SNR1: 0.55582 ,SNR2: 2.4054




Frequency (Hz)



F20231205061546




BLK: 3,SNR1:-0.35644 ,SNR2: 0.23017




Frequency (Hz)

3C255 2023/12/04 21.29UT FUJI -KISO


K20231205061543




BLK: 3,SNR1: 1.1515 ,SNR2: 4.5426




Frequency (Hz)



T20231205063527




BLK: 5, SNR1: 0.89103 ,SNR2: 6.1768




Frequency (Hz)

F20231205063528




BLK: 5, SNR1: -0.16329 ,SNR2: 0.59621




Frequency (Hz)


1136-13 2023/12/04 21.62UT TOYOKAWA-FUJI



T20231205063527




BLK: 1, SNR1: 2.5916 , SNR2: 14.783




Frequency (Hz)

K20231205063525




BLK: 1, SNR1: 0.17228 , SNR2: 5.1583





Frequency (Hz)


1136-13 2023/12/04 21.62UT TOYOKAWA-KISO



F20231205063528





BLK: 2,SNR1:-0.30779 ,SNR2: 0.33596




Frequency (Hz)

K20231205063525




BLK: 2,SNR1: 0.23632 ,SNR2: 0.99704





Frequency (Hz)


1136-13 2023/12/04 21.62UT FUJI -KISO



T20231205064610





BLK: 6,SNR1: 0.91806E-01,SNR2: 1.7933




Frequency (Hz)

3C267 2023/12/04 21.80UT TOYOKAWA-FUJI


F20231205064611




BLK: 6,SNR1:-0.10259 ,SNR2: 2.1306




Frequency (Hz)



T20231205064610




BLK: 1,SNR1: 1.4320 ,SNR2: 23.900




Frequency (Hz)

3C267 2023/12/04 21.80UT TOYOKAWA-KISO


K20231205064608



BLK: 1,SNR1: 0.10195 ,SNR2: 0.36208




Frequency (Hz)






F20231205064611




BLK: 5,SNR1: 0.68560 ,SNR2: 1.4597




Frequency (Hz)

3C267 2023/12/04 21.80UT FUJI -KISO


K20231205064608




BLK: 5,SNR1: 0.66830 ,SNR2: 3.5328




Frequency (Hz)




T20231205072515




BLK: 7,SNR1: 0.39333 ,SNR2: 2.1228




F20231205072516




BLK: 7,SNR1: 0.22639E-01,SNR2: 1.9468




3C273 2023/12/04 22.45UT TOYOKAWA-FUJI



T20231205072515





BLK:12,SNR1: 1.0416 ,SNR2: 2.7867




Frequency (Hz)

3C273 2023/12/04 22.45UT TOYOKAWA-KISO


K20231205072513





BLK:12,SNR1: 0.46127 ,SNR2: 1.3887




Frequency (Hz)





F20231205072516




BLK: 3,SNR1:-0.11908E-01,SNR2: 4.2582




K20231205072513





BLK: 3,SNR1:-0.32928E-01,SNR2: 3.1899




3C273 2023/12/04 22.45UT FUJI -KISO



T20231205073826




BLK: 5,SNR1: 0.11195 ,SNR2: 1.1636




Frequency (Hz)

3C275 2023/12/04 22.67UT TOYOKAWA-FUJI


F20231205073827




BLK: 5,SNR1: 0.71864 ,SNR2: 1.7262




Frequency (Hz)



T20231205073826




BLK: 6,SNR1: 0.17265 ,SNR2: 0.56114




Frequency (Hz)

3C275 2023/12/04 22.67UT TOYOKAWA-KISO


K20231205073824





BLK: 6,SNR1: 0.72678 ,SNR2: 1.7623




Frequency (Hz)



F20231205073827





BLK: 6,SNR1: 0.55899 ,SNR2: 3.1787




Frequency (Hz)

3C275 2023/12/04 22.67UT FUJI -KISO


K20231205073824





BLK: 6,SNR1: 0.13813 ,SNR2: 3.0312




Frequency (Hz)



T20231205075215





BLK: 1,SNR1: 0.50488 ,SNR2: 2.2137




Frequency (Hz)

F20231205075216




BLK: 1,SNR1: 3.0520 ,SNR2: 9.7751





Frequency (Hz)

3C279 2023/12/04 22.90UT TOYOKAWA-FUJI






T20231205075215





BLK: 2,SNR1: 0.24318E-01,SNR2: 0.89447




Frequency (Hz)

3C279 2023/12/04 22.90UT TOYOKAWA-KISO


K20231205075213




BLK: 2,SNR1: 0.27314 ,SNR2: 0.79084




Frequency (Hz)



F20231205075216





BLK: 2,SNR1: 2.8100 ,SNR2: 9.0292




Frequency (Hz)

3C279 2023/12/04 22.90UT FUJI -KISO


K20231205075213




BLK: 2,SNR1: 0.25216E-01,SNR2: 0.0000




Frequency (Hz)



T20231205081203




BLK: 8,SNR1: 0.61887 ,SNR2: 2.2405




Frequency (Hz)

F20231205081204




BLK: 8,SNR1: -0.62666E-01,SNR2: 2.4496




Frequency (Hz)


1313+453 2023/12/04 23.23UT TOYOKAWA-FUJI




T20231205081203




BLK: 1,SNR1: 0.88485E-01,SNR2: 1.4219




K20231205081201





BLK: 1,SNR1:-0.23439 ,SNR2: 0.0000




1313+453 2023/12/04 23.23UT TOYOKAWA-KISO



F20231205081204





BLK: 1, SNR1: -0.14606 , SNR2: 1.5059




Frequency (Hz)

K20231205081201




BLK: 1, SNR1: 0.23278 , SNR2: 0.82429





Frequency (Hz)


1313+453 2023/12/04 23.23UT FUJI -KISO



T20231205082209




BLK: 7,SNR1: 0.11452 ,SNR2: 0.96278




Frequency (Hz)

F20231205082210




BLK: 7,SNR1: 0.33003 ,SNR2: 2.7536




Frequency (Hz)


1323+32 2023/12/04 23.40UT TOYOKAWA-FUJI



T20231205082209





BLK: 4,SNR1: 0.10867 ,SNR2: 1.2558




Frequency (Hz)

K20231205082207




BLK: 4,SNR1: 0.27104 ,SNR2: 2.5964




Frequency (Hz)


1323+32 2023/12/04 23.40UT TOYOKAWA-KISO



F20231205082210




BLK: 6,SNR1: 1.0764 ,SNR2: 2.9806




Frequency (Hz)

K20231205082207




BLK: 6,SNR1: 0.46691 ,SNR2: 5.4039




Frequency (Hz)

1323+32 2023/12/04 23.40UT FUJI -KISO






T20231205082659




BLK:17,SNR1: 1.7176 ,SNR2: 7.9858




Frequency (Hz)

3C286 2023/12/04 23.48UT TOYOKAWA-FUJI


F20231205082700




BLK:17,SNR1: 0.87006 ,SNR2: 2.4256




Frequency (Hz)



T20231205082659





BLK:12,SNR1: 1.4897 ,SNR2: 8.0834




Frequency (Hz)

K20231205082657




BLK:12,SNR1: 0.51034E-01,SNR2: 0.89808




Frequency (Hz)


3C286 2023/12/04 23.48UT TOYOKAWA-KISO



F20231205082700




BLK: 3,SNR1: 0.16422 ,SNR2: 1.3785




Frequency (Hz)

3C286 2023/12/04 23.48UT FUJI -KISO


K20231205082657





BLK: 3,SNR1: 0.27825 ,SNR2: 2.8912




Frequency (Hz)



T20231205084326





BLK: 6,SNR1: 1.1993 ,SNR2: 8.3537




Frequency (Hz)

F20231205084327




BLK: 6,SNR1:-0.38235E-01,SNR2: 0.88834




Frequency (Hz)


1345+12 2023/12/04 23.75UT TOYOKAWA-FUJI



T20231205084326




BLK:10,SNR1: 0.84187 ,SNR2: 5.7546




Frequency (Hz)

K20231205084324




BLK:10,SNR1: 0.36489E-01,SNR2: 1.9742




Frequency (Hz)


1345+12 2023/12/04 23.75UT TOYOKAWA-KISO



F20231205084327




BLK: 4,SNR1: 3.8392 ,SNR2: 16.583





1345+12 2023/12/04 23.75UT FUJI -KISO


K20231205084324




BLK: 4,SNR1: 0.61005E-01,SNR2: 0.39302



T20231205085347




BLK: 3,SNR1: 0.94649E-01,SNR2: 2.4086





1355+01 2023/12/04 23.92UT TOYOKAWA-FUJI


F20231205085348




BLK: 3,SNR1:-0.20761E-01,SNR2: 2.5778



T20231205085347




BLK: 6,SNR1: 0.24471 ,SNR2: 1.9750





1355+01 2023/12/04 23.92UT TOYOKAWA-KISO

K20231205085345




BLK: 6,SNR1: 0.29418 ,SNR2: 1.8842







F20231205085348




BLK: 3,SNR1:-0.71672E-01,SNR2: 3.6023




K20231205085345





BLK: 3,SNR1: 0.38078 ,SNR2: 4.5669




1355+01 2023/12/04 23.92UT FWJ -KISO



T20231205091457




BLK:15,SNR1: 6.1133 ,SNR2: 34.716





3C298 2023/12/05 0.28UT TOYOKAWA-FUJI


F20231205091458




BLK:15,SNR1: 0.45942E-01,SNR2: 1.4415



T20231205091457




BLK: 8,SNR1: 1.2375 ,SNR2: 8.3732




Frequency (Hz)

K20231205091455




BLK: 8,SNR1: 0.18087 ,SNR2: 2.3934





Frequency (Hz)


3C298 2023/12/05 0.28UT TOYOKAWA-KISO



F20231205091458





BLK: 4,SNR1: 0.15153E-01,SNR2: 1.2570




Frequency (Hz)

3C298 2023/12/05 0.28UT FUJI -KISO


K20231205091455





BLK: 4,SNR1: 0.27186 ,SNR2: 2.5273




Frequency (Hz)



T20231205092641





BLK: 2,SNR1: 0.43866E-01,SNR2: 0.30720




Frequency (Hz)

1428-03 2023/12/05 0.47UT TOYOKAWA-FUJI


F20231205092642




BLK: 2,SNR1: 15.405 ,SNR2: 43.848




Frequency (Hz)



T20231205092641




BLK: 2,SNR1: 0.73036E-01,SNR2: 0.71603




Frequency (Hz)

K20231205092639




BLK: 2,SNR1: 4.2444 ,SNR2: 8.2349




Frequency (Hz)


1428-03 2023/12/05 0.47UT TOYOKAWA-KISO




F20231205092642




BLK: 3,SNR1: 0.47874E-01,SNR2: 2.6855




K20231205092639




BLK: 3,SNR1: 1.3926 ,SNR2: 7.0064




1428-03 2023/12/05 0.47UT FUJI -KISO



T20231205095145




BLK: 4,SNR1: 0.24612 ,SNR2: 1.1341





1453-10 2023/12/05 0.89UT TOYOKAWA-FUJI

F20231205095146




BLK: 4,SNR1: 0.54482 ,SNR2: 1.4431






T20231205095145




BLK: 4, SNR1: 0.65014 , SNR2: 4.6575





1453-10 2023/12/05 0.89UT TOYOKAWA-KISO



K20231205095143




BLK: 4, SNR1: 0.11653 , SNR2: 1.2073



F20231205095146





BLK: 3,SNR1: 0.14462 ,SNR2: 6.3925




Frequency (Hz)

K20231205095143




BLK: 3,SNR1: 0.67195 ,SNR2: 2.9000





Frequency (Hz)


1453-10 2023/12/05 0.89UT FUJI -KISO



T20231205100638




BLK: 5,SNR1: 0.63108E-01,SNR2: 1.2417




Frequency (Hz)

F20231205100639




BLK: 5,SNR1:-0.50516E-01,SNR2: 1.7685




Frequency (Hz)


1508-05 2023/12/05 1.14UT TOYOKAWA-FUJI



T20231205100638




BLK: 5,SNR1: 0.10609E-01,SNR2: 0.67626





1508-05 2023/12/05 1.14UT TOYOKAWA-KISO



K20231205100636




BLK: 5,SNR1: 0.82360 ,SNR2: 3.5623





F20231205100639




BLK: 4,SNR1:-0.23004 ,SNR2: 0.85536




K20231205100636





BLK: 4,SNR1: 0.81803 ,SNR2: 4.2818




1508-05 2023/12/05 1.14UT FUJI -KISO




T20231205101538




BLK: 7,SNR1: 0.13972 ,SNR2: 1.3773




F20231205101539





BLK: 7,SNR1:-0.22553 ,SNR2: 1.2373




3C318 2023/12/05 1.29UT TOYOKAWA-FUJI





T20231205101538




BLK: 5,SNR1: 0.20274 ,SNR2: 1.3720




K20231205101536




BLK: 5,SNR1: 0.10423 ,SNR2: 3.0837




3C318 2023/12/05 1.29UT TOYOKAWA-KISO



F20231205101539




BLK: 6,SNR1: 0.24400E-01,SNR2: 1.9826




Frequency (Hz)

3C318 2023/12/05 1.29UT FUJI -KISO


K20231205101536



BLK: 6,SNR1: 2.1321 ,SNR2: 12.109





Frequency (Hz)







T20231205102125




BLK: 5, SNR1: 0.25032 , SNR2: 2.3904




F20231205102126





BLK: 5, SNR1: 0.91156 , SNR2: 1.9016




1523+03 2023/12/05 1.39UT TOYOKAWA-FUJI





T20231205102125




BLK: 3,SNR1: 0.95111E-01,SNR2: 1.5533




K20231205102123




BLK: 3,SNR1: 0.16004 ,SNR2: 2.3031




1523+03 2023/12/05 1.39UT TOYOKAWA-KISO



F20231205102126





BLK: 3,SNR1:-0.11896 ,SNR2: 0.49742




Frequency (Hz)

K20231205102123




BLK: 3,SNR1: 1.9576 ,SNR2: 10.370





Frequency (Hz)


1523+03 2023/12/05 1.39UT FUJI -KISO




T20231205103304




BLK: 6,SNR1:-0.75797E-01,SNR2: 0.29998




F20231205103305





BLK: 6,SNR1: 4.2724 ,SNR2: 13.754




1535+139 2023/12/05 1.58UT TOYOKAWA-FUJI



T20231205103304





BLK: 3,SNR1: 0.36093E-01,SNR2: 1.3939




Frequency (Hz)

K20231205103302




BLK: 3,SNR1: 1.9101 ,SNR2: 4.8247




Frequency (Hz)


1535+139 2023/12/05 1.58UT TOYOKAWA-KISO




F20231205103305




BLK: 3,SNR1: 0.14727 ,SNR2: 3.3356




K20231205103302













BLK: 3,SNR1: 0.82336E-01,SNR2: 0.27159



1535+139 2023/12/05 1.58UT FUJI -KISO











F20231205104611




BLK: 4,SNR1: 0.27646 ,SNR2: 2.6500




Frequency (Hz)

1548+05 2023/12/05 1.80UT FUJI -KISO


K20231205104608





BLK: 4,SNR1: 1.4591 ,SNR2: 6.1650




Frequency (Hz)





T20231205110432




BLK: 8,SNR1: 1.1119 ,SNR2: 6.6651




F20231205110433




BLK: 8,SNR1: 0.17943 ,SNR2: 1.3378




1607+26 2023/12/05 2.10UT TOYOKAWA-FUJI



T20231205110432





BLK: 6, SNR1: 3.6169 ,SNR2: 7.7063





1607+26 2023/12/05 2.10UT TOYOKAWA-KISO


K20231205110430




BLK: 6, SNR1: 1.2040 ,SNR2: 5.8767





F20231205110433




BLK: 8, SNR1: 0.35213 , SNR2: 3.3352




K20231205110430




BLK: 8, SNR1: 0.78023 , SNR2: 3.3976




1607+26 2023/12/05 2.10UT FUJI -KISO




T20231205111935




BLK: 6,SNR1: 0.57953 ,SNR2: 1.0201




F20231205111936




BLK: 6,SNR1: 0.50350 ,SNR2: 1.3966




1621-11 2023/12/05 2.35UT TOYOKAWA-FUJI



T20231205111935





BLK: 4, SNR1: 0.24661 , SNR2: 1.4623





1621-11 2023/12/05 2.35UT TOYOKAWA-KISO


K20231205111933




BLK: 4, SNR1: -0.34186E-01, SNR2: 0.31186



F20231205111936





BLK: 6,SNR1: -0.41534E-01,SNR2: 1.1526





1621-11 2023/12/05 2.35UT FUJI -KISO



K20231205111933




BLK: 6,SNR1: 0.74267E-01,SNR2: 2.4071



T20231205113609





BLK:16,SNR1: 3.5903 ,SNR2: 14.113





1638-025 2023/12/05 2.63UT TOYOKAWA-FUJI

F20231205113610





BLK:16,SNR1: 10.460 ,SNR2: 23.129






T20231205113609





BLK:16,SNR1: 3.5896 ,SNR2: 14.111





1638-025 2023/12/05 2.63UT TOYOKAWA-KISO



K20231205113607




BLK:16,SNR1: 14.141 ,SNR2: 30.758





F20231205113610




BLK:27,SNR1: 10.794 ,SNR2: 23.622




K20231205113607




BLK:27,SNR1: 13.715 ,SNR2: 29.834




1638-025 2023/12/05 2.63UT FUJI -KISO



T20231205114303




BLK:15,SNR1: 0.60636 ,SNR2: 2.9373




Frequency (Hz)

F20231205114304




BLK:15,SNR1: 4.9419 ,SNR2: 9.8622




Frequency (Hz)


1644-106 2023/12/05 2.75UT TOYOKAWA-FUJI



T20231205114303




BLK:13,SNR1: 0.93207 ,SNR2: 3.6722





1644-106 2023/12/05 2.75UT TOYOKAWA-KISO


K20231205114301




BLK:13,SNR1: 2.0971 ,SNR2: 5.4530





F20231205114304




BLK:10,SNR1: 1.7558 ,SNR2: 7.9475




K20231205114301





BLK:10,SNR1: 2.4564 ,SNR2: 6.7179




1644-106 2023/12/05 2.75UT FUJI -KISO





T20231205114824




BLK: 8,SNR1: 4.6267 ,SNR2: 28.208




F20231205114825





BLK: 8,SNR1: 11.824 ,SNR2: 18.484




1650+004 2023/12/05 2.83UT TOYOKAWA-FUJI




T20231205114824




BLK: 9,SNR1: 1.9289 ,SNR2: 9.3102




K20231205114822





BLK: 9,SNR1: 0.43948 ,SNR2: 1.6179




1650+004 2023/12/05 2.83UT TOYOKAWA-KISO



F20231205114825




BLK:16,SNR1: 9.9920 ,SNR2: 20.201





1650+004 2023/12/05 2.83UT FUJI -KISO

K20231205114822




BLK:16,SNR1: 0.31846 ,SNR2: 1.3843







T20231205115356




BLK: 9, SNR1: 0.25186 , SNR2: 0.81090




F20231205115357




BLK: 9, SNR1: 3.1234 , SNR2: 8.6778




1656+053 2023/12/05 2.93UT TOYOKAWA-FUJI





T20231205115356




BLK: 5, SNR1: 0.30230 , SNR2: 1.0452




K20231205115354





BLK: 5, SNR1: 3.9971 , SNR2: 12.164




1656+053 2023/12/05 2.93UT TOYOKAWA-KISO





F20231205115357




BLK: 8,SNR1: 5.7228 ,SNR2: 16.743




K20231205115354





BLK: 8,SNR1: 0.63886E-01,SNR2: 2.4337




1656+053 2023/12/05 2.93UT FUJI -KISO



T20231205121026





BLK:15,SNR1: 78.916 ,SNR2: 110.48




Frequency (Hz)

F20231205121027




BLK:15,SNR1: 93.601 ,SNR2: 109.19





Frequency (Hz)


1712-033 2023/12/05 3.20UT TOYOKAWA-FUJI



T20231205121026





BLK:15,SNR1: 78.813 ,SNR2: 110.34




Frequency (Hz)

K20231205121024




BLK:15,SNR1: 73.553 ,SNR2: 85.815




Frequency (Hz)


1712-033 2023/12/05 3.20UT TOYOKAWA-KISO





F20231205121027




BLK:25,SNR1: 65.543 ,SNR2: 81.645




K20231205121024





BLK:25,SNR1: 71.327 ,SNR2: 83.218




1712-033 2023/12/05 3.20UT FUJI -KISO



T20231205122828




BLK:14,SNR1: 0.63586 ,SNR2: 2.5108





1730-13 2023/12/05 3.50UT TOYOKAWA-FUJI



F20231205122829




BLK:14,SNR1: 4.4143 ,SNR2: 12.023





T20231205122828




BLK: 9,SNR1: 0.34103 ,SNR2: 2.5418




K20231205122826



BLK: 9,SNR1: 0.12043 ,SNR2: 1.5050




1730-13 2023/12/05 3.50UT TOYOKAWA-KISO






F20231205122829





BLK: 8,SNR1: 1.8411 ,SNR2: 8.2701





1730-13 2023/12/05 3.50UT FUJI -KISO


K20231205122826




BLK: 8,SNR1: 0.50289 ,SNR2: 1.6916




T20231205124553




BLK:12,SNR1:-0.25861E-02,SNR2: 0.26810




F20231205124554





BLK:12,SNR1: 5.0584 ,SNR2: 11.312




1748+031 2023/12/05 3.79UT TOYOKAWA-FUJI





T20231205124553




No.Good Data




K20231205124550




No.Good Data




1748+031 2023/12/05 3.79UT TOYOKAWA-KISO




F20231205124554




BLK: 9,SNR1: 0.92408 ,SNR2: 5.3620




K20231205124550







BLK: 9,SNR1: 0.12707 ,SNR2: 1.0450





1748+031 2023/12/05 3.79UT FUJI -KISO






1759+13 2023/12/05 3.97UT TOYOKAWA-FUJI








BLK: 6,SNR1: 0.23013 ,SNR2: 2.0978




1759+13 2023/12/05 3.97UT TOYOKAWA-KISO




BLK: 6,SNR1: 3.5632 ,SNR2: 10.456



F20231205125647




BLK:10,SNR1: 7.4272 ,SNR2: 16.414





1759+13 2023/12/05 3.97UT FUJI -KISO



K20231205125643




BLK:10,SNR1: 1.1188 ,SNR2: 2.3819



T20231205131746





BLK: 3,SNR1: 0.18293 ,SNR2: 2.0778





1819-096 2023/12/05 4.32UT TOYOKAWA-FUJI

F20231205131747





BLK: 3,SNR1: 11.932 ,SNR2: 18.709








T20231205131746




BLK: 3,SNR1: 0.31998 ,SNR2: 0.90530




K20231205131743





BLK: 3,SNR1: 13.093 ,SNR2: 26.604




1819-096 2023/12/05 4.32UT TOYOKAWA-KISO



F20231205131747




BLK:11,SNR1: 3.5090 ,SNR2: 13.491




Frequency (Hz)

1819-096 2023/12/05 4.32UT FUJI -KISO


K20231205131743





BLK:11,SNR1: 6.5970 ,SNR2: 10.409




Frequency (Hz)




T20231205132608




BLK:10,SNR1: 0.50766E-01,SNR2: 0.74695




F20231205132609





BLK:10,SNR1: 1.9328 ,SNR2: 7.9493




1829+29 2023/12/05 4.46UT TOYOKAWA-FUJI



T20231205132608




BLK: 2,SNR1: 0.53037E-01,SNR2: 1.5540





1829+29 2023/12/05 4.46UT TOYOKAWA-KISO



K20231205132605




BLK: 2,SNR1: 0.23293 ,SNR2: 1.3540



F20231205132609





BLK: 6,SNR1: 1.2619 ,SNR2: 5.9402





1829+29 2023/12/05 4.46UT FUJI -KISO



K20231205132605




BLK: 6,SNR1: 0.28984 ,SNR2: 1.1503




T20231205133230




BLK: 9,SNR1: 4.3565 ,SNR2: 9.2402




F20231205133231




BLK: 9,SNR1: 7.3886 ,SNR2: 26.235




1835+134 2023/12/05 4.57UT TOYOKAWA-FUJI




T20231205133230




BLK: 6,SNR1: 6.2558 ,SNR2: 13.358




K20231205133227




BLK: 6,SNR1: 166.02 ,SNR2: 244.17




1835+134 2023/12/05 4.57UT TOYOKAWA-KISO



F20231205133231




BLK:10,SNR1: 7.2150 ,SNR2: 25.935





1835+134 2023/12/05 4.57UT FUJI -KISO

K20231205133227





BLK:10,SNR1: 137.62 ,SNR2: 188.74






T20231205135526




BLK: 1,SNR1:-0.65314E-01,SNR2: 1.8604





1858+171 2023/12/05 4.95UT TOYOKAWA-FUJI



F20231205135527




BLK: 1,SNR1: 1.3558 ,SNR2: 5.5838




T20231205135526




BLK: 1,SNR1: 0.48545E-01,SNR2: 0.34513




K20231205135523




BLK: 1,SNR1: 7.7172 ,SNR2: 16.896




1858+171 2023/12/05 4.95UT TOYOKAWA-KISO



F20231205135527





BLK: 5,SNR1:-0.15390 ,SNR2: 1.0143





1858+171 2023/12/05 4.95UT FUJI -KISO


K20231205135523




BLK: 5,SNR1: 0.56376 ,SNR2: 2.7291




T20231205141301




BLK: 7,SNR1: 0.45484 ,SNR2: 2.5103




F20231205141302




BLK: 7,SNR1: 1.0663 ,SNR2: 3.3511




1915-121 2023/12/05 5.25UT TOYOKAWA-FUJI





T20231205141301




BLK: 4,SNR1: 0.69989 ,SNR2: 3.9157




K20231205141258




BLK: 4,SNR1: 16.991 ,SNR2: 32.495




1915-121 2023/12/05 5.25UT TOYOKAWA-KISO





F20231205141302




BLK: 4,SNR1: 1.7128 ,SNR2: 4.2445




K20231205141258




BLK: 4,SNR1: 0.56449 ,SNR2: 2.7518




1915-121 2023/12/05 5.25UT FUJI -KISO




T20231205142642




BLK: 8,SNR1: 0.85157 ,SNR2: 5.7597




F20231205142643




BLK: 8,SNR1:-0.10830 ,SNR2: 1.4466




1928-142 2023/12/05 5.47UT TOYOKAWA-FUJI



T20231205142642





BLK: 8,SNR1: 0.90009 ,SNR2: 3.7598





1928-142 2023/12/05 5.47UT TOYOKAWA-KISO

K20231205142639




BLK: 8,SNR1: 1.8305 ,SNR2: 3.8553








F20231205142643




BLK: 3,SNR1: 0.37507 ,SNR2: 2.7110




K20231205142639





BLK: 3,SNR1: 0.56684E-01,SNR2: 1.9385




1928-142 2023/12/05 5.47UT FUJI -KISO




T20231205151119




BLK: 4,SNR1: 0.53044E-01,SNR2: 0.45845




F20231205151120





BLK: 4,SNR1: 8.7618 ,SNR2: 18.405




2014+358 2023/12/05 6.22UT TOYOKAWA-FUJI





T20231205151119




BLK: 3,SNR1:-0.14868E-01,SNR2: 1.8452




K20231205151116





BLK: 3,SNR1: 11.311 ,SNR2: 32.756




2014+358 2023/12/05 6.22UT TOYOKAWA-KISO





F20231205151120




BLK:10,SNR1: 7.2716 ,SNR2: 15.170




K20231205151116





BLK:10,SNR1: 1.0709 ,SNR2: 6.1389




2014+358 2023/12/05 6.22UT FUJI -KISO




T20231205154155




BLK: 2,SNR1:-0.19991E-01,SNR2: 0.66574




F20231205154156





BLK: 2,SNR1: 0.41820 ,SNR2: 5.2260




3C422 2023/12/05 6.73UT TOYOKAWA-FUJI





T20231205154155




BLK: 2,SNR1:-0.34210E-01,SNR2: 0.36190E-01




K20231205154152








BLK: 2,SNR1: 15.039 ,SNR2: 26.932





3C422 2023/12/05 6.73UT TOYOKAWA-KISO






T20231205160232





BLK: 5,SNR1: 0.11194 ,SNR2: 1.0711




Frequency (Hz)

F20231205160233




BLK: 5,SNR1: 0.13261 ,SNR2: 2.4592





Frequency (Hz)

2105-072 2023/12/05 7.07UT TOYOKAWA-FUJI








T20231205160232




BLK: 3,SNR1: 0.32231 ,SNR2: 1.5507




K20231205160230





BLK: 3,SNR1: 9.0485 ,SNR2: 16.473




2105-072 2023/12/05 7.07UT TOYOKAWA-KISO





F20231205160233




BLK: 2,SNR1: 0.21182 ,SNR2: 1.5230




K20231205160230





BLK: 2,SNR1: 0.90479 ,SNR2: 4.0421




2105-072 2023/12/05 7.07UT FUJI -KISO




T20231205161821




BLK: 4,SNR1: 0.11534 ,SNR2: 0.59742




F20231205161822





BLK: 4,SNR1:-0.61772E-02,SNR2: 2.2345




2121-014 2023/12/05 7.33UT TOYOKAWA-FUJI





T20231205161821




BLK: 4,SNR1: 0.35870E-01,SNR2: 0.67236




K20231205161819




BLK: 4,SNR1: 1.4994 ,SNR2: 7.7163




2121-014 2023/12/05 7.33UT TOYOKAWA-KISO





F20231205161822




BLK: 5,SNR1:-0.18933 ,SNR2: 1.3670




K20231205161819





BLK: 5,SNR1: 1.2509 ,SNR2: 6.6859




2121-014 2023/12/05 7.33UT FUJI -KISO




T20231205164456




BLK: 1,SNR1: 0.72631 ,SNR2: 1.2025




F20231205164457





BLK: 1,SNR1: 3.1340 ,SNR2: 12.135




2147+145 2023/12/05 7.78UT TOYOKAWA-FUJI





T20231205164456




BLK: 3,SNR1:-0.97151E-02,SNR2: 1.7789




K20231205164454




BLK: 3,SNR1: 0.13539 ,SNR2: 1.8404




2147+145 2023/12/05 7.78UT TOYOKAWA-KISO





F20231205164457




BLK: 4,SNR1: 0.57449E-02,SNR2: 1.4529




K20231205164454



BLK: 4,SNR1: 0.14062,SNR2: 0.87234




2147+145 2023/12/05 7.78UT FUJI -KISO








T20231205165400




BLK:27,SNR1: 56.335 ,SNR2: 97.850




F20231205165401




BLK:27,SNR1: 58.601 ,SNR2: 79.351




2156-043 2023/12/05 7.93UT TOYOKAWA-FUJI




T20231205165400




BLK:20,SNR1: 57.926 ,SNR2: 101.47




K20231205165358




BLK:20,SNR1:-0.24751 ,SNR2: 5.1621




2156-043 2023/12/05 7.93UT TOYOKAWA-KISO




F20231205165401




BLK:20,SNR1: 58.634 ,SNR2: 79.397




K20231205165358





BLK:20,SNR1:-0.24741 ,SNR2: 5.1598




2156-043 2023/12/05 7.93UT FUJI -KISO




T20231205170711




BLK: 7,SNR1: 0.14464 ,SNR2: 0.86398




F20231205170712





BLK: 7,SNR1: 0.91231 ,SNR2: 7.5300




2210+016 2023/12/05 8.15UT TOYOKAWA-FUJI





T20231205170711




BLK: 2,SNR1: 0.19375 ,SNR2: 1.6216




K20231205170709




BLK: 2,SNR1: 0.76037E-03,SNR2: 0.57763




2210+016 2023/12/05 8.15UT TOYOKAWA-KISO





F20231205170712




BLK: 7,SNR1: 0.46640 ,SNR2: 3.9873




K20231205170709





BLK: 7,SNR1: 0.23761 ,SNR2: 2.8638




2210+016 2023/12/05 8.15UT FUJI -KISO




T20231205172020




BLK: 2,SNR1: 0.16361 ,SNR2: 0.83762




F20231205172021





BLK: 2,SNR1: 0.28821E-02,SNR2: 2.5831




3C446 2023/12/05 8.37UT TOYOKAWA-FUJI



T20231205172020





BLK: 1,SNR1: 0.36826 ,SNR2: 0.73647




Frequency (Hz)

K20231205172018




BLK: 1,SNR1: 0.35418E-01,SNR2: 1.1669




Frequency (Hz)

3C446 2023/12/05 8.37UT TOYOKAWA-KISO






F20231205172021





BLK: 6,SNR1:-0.22193 ,SNR2: 0.47461





3C446 2023/12/05 8.37UT FUJI -KISO


K20231205172018




BLK: 6,SNR1: 5.5288 ,SNR2: 11.047





T20231205172704




BLK: 5, SNR1: 0.53745E-01, SNR2: 0.48025




F20231205172704





BLK: 5, SNR1: 7.1534, SNR2: 14.355




2229-093 2023/12/05 8.48UT TOYOKAWA-FUJI



T20231205172704





BLK: 2,SNR1: 0.20778E-01,SNR2: 0.51379




Frequency (Hz)

K20231205172702




BLK: 2,SNR1: 0.53236 ,SNR2: 2.8428




Frequency (Hz)


2229-093 2023/12/05 8.48UT TOYOKAWA-KISO





F20231205172704




BLK:10,SNR1: 3.5569 ,SNR2: 8.4709



K20231205172702



BLK:10,SNR1: 0.27899 ,SNR2: 2.9059



2229-093 2023/12/05 8.48UT FUJI -KISO

