




TOYOKAWA 1659-220 2024/03/02(062)06:12:07-06:15:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1704-223 2024/03/02(062)06:17:28-06:20:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1712-033 2024/03/02(062)06:24:24-06:27:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1716+006 2024/03/02(062)06:28:43-06:32:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1721-180 2024/03/02(062)06:33:37-06:37:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1725-069 2024/03/02(062)06:37:15-06:40:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1730-13 2024/03/02(062)06:42:27-06:45:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1748+031 2024/03/02(062)06:59:51-07:03:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1759+13 2024/03/02(062)07:10:45-07:14:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1819-096 2024/03/02(062)07:31:44-07:35:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1830-210 2024/03/02(062)07:43:00-07:46:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1858+171 2024/03/02(062)08:09:25-08:12:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1908-20 2024/03/02(062)08:20:09-08:23:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1915-121 2024/03/02(062)08:27:00-08:30:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1928-142 2024/03/02(062)08:40:41-08:44:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1938-15 2024/03/02(062)08:50:20-08:53:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1942-053 2024/03/02(062)08:54:16-08:57:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2007+502 2024/03/02(062)09:17:34-09:21:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2014+358 2024/03/02(062)09:25:17-09:28:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C422

2024/03/02(062)09:55:53-09:59:19JST


16772+/- 241




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2105-072 2024/03/02(062)10:16:31-10:19:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2131+379 2024/03/02(062)10:42:17-10:45:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2135-209 2024/03/02(062)10:46:35-10:50:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2147+145 2024/03/02(062)10:58:55-11:02:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2156-043 2024/03/02(062)11:07:59-11:11:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2203-18 2024/03/02(062)11:14:47-11:18:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2210+016 2024/03/02(062)11:21:09-11:24:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2218+395 2024/03/02(062)11:28:51-11:32:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C446


2024/03/02(062)11:34:19-11:37:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2229-093 2024/03/02(062)11:41:03-11:44:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2235+511 2024/03/02(062)11:45:36-11:49:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2239+333 2024/03/02(062)11:49:48-11:53:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2243+394 2024/03/02(062)11:54:05-11:57:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C454.3 2024/03/02(062)12:02:19-12:05:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2259+481 2024/03/02(062)12:10:02-12:13:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C456

2024/03/02(062)12:20:50-12:24:16JST

15948+/- 262




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C459

2024/03/02(062)12:24:55-12:28:21JST


12811+/- 620




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2318-16 2024/03/02(062)12:29:23-12:32:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2325+269 2024/03/02(062)12:36:15-12:39:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2344+09 2024/03/02(062)12:54:54-12:58:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2347-02 2024/03/02(062)12:58:40-13:02:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2354+14 2024/03/02(062)13:05:33-13:08:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C2

2024/03/02(062)13:14:36-13:18:02JST


12264+/- 266




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0011+344 2024/03/02(062)13:21:58-13:25:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0019-00 2024/03/02(062)13:30:35-13:34:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C12


2024/03/02(062)13:40:49-13:44:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0038+328 2024/03/02(062)13:49:07-13:52:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0044-056 2024/03/02(062)13:54:51-13:58:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C26

2024/03/02(062)14:02:12-14:05:38JST


12945+/- 100




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0056-00 2024/03/02(062)14:07:11-14:10:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0106+01 2024/03/02(062)14:16:53-14:20:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0115-01 2024/03/02(062)14:26:16-14:29:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0120+405 2024/03/02(062)14:31:37-14:35:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0128+03 2024/03/02(062)14:39:15-14:42:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C48

2024/03/02(062)14:45:49-14:49:15JST


15006+/- 195




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0148+274 2024/03/02(062)14:59:32-15:02:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0155-109 2024/03/02(062)15:05:34-15:09:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0202+15 2024/03/02(062)15:12:41-15:16:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0213+178 2024/03/02(062)15:24:31-15:27:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C67

2024/03/02(062)15:32:13-15:35:39JST

10502+/- 180




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C71

2024/03/02(062)15:50:29-15:53:55JST


11173+/- 59




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0258+350 2024/03/02(062)16:09:43-16:13:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0308+305 2024/03/02(062)16:19:32-16:22:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0320+05 2024/03/02(062)16:31:04-16:34:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0324+119 2024/03/02(062)16:35:09-16:38:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0333+32 2024/03/02(062)16:44:25-16:47:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0347+05 2024/03/02(062)16:57:27-17:00:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0403-132 2024/03/02(062)17:13:02-17:16:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0411+05 2024/03/02(062)17:22:12-17:25:38JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0434-225 2024/03/02(062)17:43:55-17:47:21JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

