





T20240418060835




BLK: 3,SNR1: 0.80351 ,SNR2: 16.984




F20240418060836





BLK: 3,SNR1: 0.46243E-01,SNR2: 3.2493




2003+386 2024/04/17 21.17UT TOYOKAWA-FUJI



T20240418060835




No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

2003+386 2024/04/17 21.17UT TOYOKAWA-KISO



F20240418060836



No.Good Data



KISO





No.Good Data




2003+386 2024/04/17 21.17UT FUJI -KISO





T20240418061249




No.Good Data




FUJI




No.Good Data




2007+502 2024/04/17 21.24UT TOYOKAWA-FUJI




T20240418061249




BLK: 9,SNR1: 41.055 ,SNR2: 189.11




K20240418061248



BLK: 9,SNR1: 0.19602 ,SNR2: 0.99208



2007+502 2024/04/17 21.24UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20240418061248




No.Good Data





Frequency (Hz)

2007+502 2024/04/17 21.24UT FUJI -KISO







BLK: 6,SNR1:-0.44973E-01,SNR2: 0.17873







BLK: 6,SNR1: 0.10497 ,SNR2: 1.0936




2014+358 2024/04/17 21.37UT TOYOKAWA-FUJI






2014+358 2024/04/17 21.37UT TOYOKAWA-KISO






F20240418062033





BLK: 3,SNR1:-0.31816 ,SNR2: 0.11187




Frequency (Hz)

K20240418062031






BLK: 3,SNR1:-0.22353E-01,SNR2: 0.54792





Frequency (Hz)

2014+358 2024/04/17 21.37UT FUJI -KISO







BLK: 4,SNR1: 5.1429 ,SNR2: 66.658





BLK: 4,SNR1: 0.53165 ,SNR2: 1.8659






2022+119 2024/04/17 21.51UT TOYOKAWA-FUJI







BLK: 6,SNR1: 2.2654 ,SNR2: 22.635





BLK: 6,SNR1: 1.2779 ,SNR2: 6.1940




2022+119 2024/04/17 21.51UT TOYOKAWA-KISO



F20240418062840





BLK: 4,SNR1:-0.13770 ,SNR2: 2.0718




Frequency (Hz)

K20240418062838




BLK: 4,SNR1: 2.1255 ,SNR2: 4.0953





Frequency (Hz)


2022+119 2024/04/17 21.51UT FUJI -KISO



T20240418063630





BLK: 2,SNR1: 2.2610 ,SNR2: 28.141




Frequency (Hz)

F20240418063631




BLK: 2,SNR1: 1.1970 ,SNR2: 4.7401





Frequency (Hz)


2029-018 2024/04/17 21.64UT TOYOKAWA-FUJI



T20240418063630





BLK: 6,SNR1: 0.39903 ,SNR2: 3.4342




Frequency (Hz)

K20240418063629




BLK: 6,SNR1: 0.20371 ,SNR2: 1.2127




Frequency (Hz)


2029-018 2024/04/17 21.64UT TOYOKAWA-KISO



F20240418063631





BLK: 5,SNR1: 1.2066 ,SNR2: 4.2211




Frequency (Hz)

K20240418063629




BLK: 5,SNR1: 7.2613 ,SNR2: 13.691





Frequency (Hz)


2029-018 2024/04/17 21.64UT FUJI -KISO



T20240418064046





BLK: 3,SNR1: 0.55546 ,SNR2: 4.7255




Frequency (Hz)

2034-066 2024/04/17 21.71UT TOYOKAWA-FUJI


F20240418064047



BLK: 3,SNR1:-0.21874 ,SNR2: 0.87510





Frequency (Hz)






T20240418064046





BLK: 5,SNR1: 16.661 ,SNR2: 214.29




Frequency (Hz)

K20240418064045




BLK: 5,SNR1: 0.68469E-01,SNR2: 0.67674





Frequency (Hz)


2034-066 2024/04/17 21.71UT TOYOKAWA-KISO



F20240418064047





BLK: 1,SNR1:-0.68472E-01,SNR2: 0.36315




Frequency (Hz)

2034-066 2024/04/17 21.71UT FUJI -KISO


K20240418064045





BLK: 1,SNR1:-0.14223 ,SNR2: 0.74074





Frequency (Hz)




T20240418064515





F20240418064516




2038-013 2024/04/17 21.78UT TOYOKAWA-FUJI





T20240418064515




BLK: 4,SNR1: 2.9171 ,SNR2: 35.121




K20240418064514




BLK: 4,SNR1: 1.0726 ,SNR2: 5.6895




3038-013 2024/04/17 21.78UT TOYOKAWA-KISO



F20240418064516





BLK: 2,SNR1: 1.1709 ,SNR2: 3.3518




Frequency (Hz)

K20240418064514




BLK: 2,SNR1: 0.69968E-01,SNR2: 0.53782





Frequency (Hz)


2038-013 2024/04/17 21.78UT FUJI -KISO



T20240418065108




BLK: 6,SNR1: 0.22731 ,SNR2: 0.61169




Frequency (Hz)

3C422 2024/04/17 21.88UT TOYOKAWA-FUJI


F20240418065109





BLK: 6,SNR1: 1.4030 ,SNR2: 7.2454




Frequency (Hz)



T20240418065108





BLK: 3,SNR1: 0.42788E-01,SNR2: 0.87642




Frequency (Hz)

3C422 2024/04/17 21.88UT TOYOKAWA-KISO


K20240418065107





BLK: 3,SNR1: 0.63350 ,SNR2: 8.9963




Frequency (Hz)



F20240418065109





BLK: 3,SNR1: 5.1592 ,SNR2: 15.040




Frequency (Hz)

3C422 2024/04/17 21.88UT FUJI -KISO


K20240418065107



BLK: 3,SNR1: 0.76062 ,SNR2: 7.6025





Frequency (Hz)






T20240418070304





BLK: 4,SNR1: 5.9494 ,SNR2: 33.294




Frequency (Hz)

2056+028 2024/04/17 22.08UT TOYOKAWA-FUJI


F20240418070304




BLK: 4,SNR1: 1.0156 ,SNR2: 2.3117




Frequency (Hz)





T20240418070304




BLK: 8,SNR1: 21.675 ,SNR2: 158.18




K20240418070303





BLK: 8,SNR1: 1.5480 ,SNR2: 6.0022




2056+028 2024/04/17 22.08UT TOYOKAWA-KISO



F20240418070304





BLK: 4,SNR1: 1.0482 ,SNR2: 2.2941




Frequency (Hz)

K20240418070303




BLK: 4,SNR1: 0.12317 ,SNR2: 1.6243




Frequency (Hz)


2056+028 2024/04/17 22.08UT FUJI -KISO




T20240418071146




BLK: 5,SNR1: 0.89849E-01,SNR2: 0.69600




F20240418071147





BLK: 5,SNR1:-0.10299 ,SNR2: 2.4412




2105-072 2024/04/17 22.22UT TOYOKAWA-FUJI





T20240418071146




BLK: 2,SNR1: 0.51492 ,SNR2: 1.2978




K20240418071145





BLK: 2,SNR1: 0.31048 ,SNR2: 2.9202




2105-072 2024/04/17 22.22UT TOYOKAWA-KISO



F20240418071147





BLK: 4,SNR1:-0.22165 ,SNR2: 0.68915




Frequency (Hz)

K20240418071145




BLK: 4,SNR1: 15.573 ,SNR2: 30.075





Frequency (Hz)


2105-072 2024/04/17 22.22UT FUJI -KISO





T20240418072651




BLK: 3,SNR1:-0.56039E-01,SNR2: 0.56159




F20240418072652




BLK: 3,SNR1: 0.15384 ,SNR2: 1.5200




2120-102 2024/04/17 22.48UT TOYOKAWA-FUJI



T20240418072651





BLK: 5,SNR1: 0.26812E-01,SNR2: 0.55304




Frequency (Hz)

K20240418072650




BLK: 5,SNR1: 0.73501 ,SNR2: 6.7332





Frequency (Hz)

2120-102 2024/04/17 22.48UT TOYOKAWA-KISO







F20240418072652




BLK: 2,SNR1: 0.80040E-01,SNR2: 1.3116




K20240418072650





BLK: 2,SNR1: 0.88489E-01,SNR2: 0.92478




2120-102 2024/04/17 22.48UT FUJI -KISO




T20240418073731




BLK: 1,SNR1: 0.23914 ,SNR2: 0.66267




F20240418073732





BLK: 1,SNR1: 0.17439 ,SNR2: 2.8320




2131+379 2024/04/17 22.65UT TOYOKAWA-FUJI





T20240418073731




BLK: 3, SNR1: 0.33660 , SNR2: 4.1422




K20240418073730




BLK: 3, SNR1: 6.4355 , SNR2: 22.513




2131+379 2024/04/17 22.65UT TOYOKAWA-KISO





F20240418073732




BLK: 6,SNR1:-0.91162E-01,SNR2: 1.4037




K20240418073730




BLK: 6,SNR1: 1.4683 ,SNR2: 6.8456




2131+379 2024/04/17 22.65UT FUJI -KISO



T20240418075409




BLK:11,SNR1: 3.7764 ,SNR2: 9.2499




Frequency (Hz)

2147+145 2024/04/17 22.93UT TOYOKAWA-FUJI


F20240418075409




BLK:11,SNR1: 2.2593 ,SNR2: 9.6208




Frequency (Hz)



T20240418075409




BLK: 8,SNR1: 2.1123 ,SNR2: 9.3879




Frequency (Hz)

K20240418075408




BLK: 8,SNR1: 0.74571 ,SNR2: 3.7066




Frequency (Hz)


2147+145 2024/04/17 22.93UT TOYOKAWA-KISO





F20240418075409




BLK:11,SNR1: 0.17006 ,SNR2: 2.2074




K20240418075408






BLK:11,SNR1: 1.0842 ,SNR2: 3.6284






2147+145 2024/04/17 22.93UT FUJI -KISO




T20240418080313



F20240418080314





2156-043 2024/04/17 23.08UT TOYOKAWA-FUJI






T20240418080313





BLK:12,SNR1: 0.18602 ,SNR2: 1.7129




Frequency (Hz)

K20240418080312




BLK:12,SNR1: 0.33813 ,SNR2: 2.9375




Frequency (Hz)


2156-043 2024/04/17 23.08UT TOYOKAWA-KISO





F20240418080314




BLK: 8,SNR1: 1.7100 ,SNR2: 6.8195




K20240418080312





BLK: 8,SNR1: 1.1311 ,SNR2: 4.8517




2156-043 2024/04/17 23.08UT FUJI -KISO




T20240418081002




BLK: 6,SNR1: 104.16 ,SNR2: 130.51




F20240418081003





BLK: 6,SNR1: 0.13319E-01,SNR2: 1.3920




2203-18 2024/04/17 23.20UT TOYOKAWA-FUJI



T20240418081002





BLK:15,SNR1: 36.053 ,SNR2: 71.172




Frequency (Hz)

K20240418081001




BLK:15,SNR1: 102.28 ,SNR2: 114.73




Frequency (Hz)


2203-18 2024/04/17 23.20UT TOYOKAWA-KISO




F20240418081003




BLK: 2,SNR1:-0.11737 ,SNR2: 0.26790




K20240418081001





BLK: 2,SNR1: 0.18535 ,SNR2: 1.5480




2203-18 2024/04/17 23.20UT FUJI -KISO



T20240418081624




BLK:14,SNR1: 1.7933 ,SNR2: 8.3163




Frequency (Hz)

F20240418081625




BLK:14,SNR1: 3.1845 ,SNR2: 8.2417





Frequency (Hz)


2210+016 2024/04/17 23.30UT TOYOKAWA-FUJI



T20240418081624





BLK:21,SNR1: 8.0643 ,SNR2: 19.066





2210+016 2024/04/17 23.30UT TOYOKAWA-KISO


K20240418081623




BLK:21,SNR1: 22.309 ,SNR2: 32.382





F20240418081625




BLK:12,SNR1: 3.4852 ,SNR2: 9.1240




K20240418081623







BLK:12,SNR1: 12.638 ,SNR2: 36.422




2210+016 2024/04/17 23.30UT FUJI -KISO












2217+128 2024/04/17 23.42UT TOYOKAWA-FUJI







2217+128 2024/04/17 23.42UT TOYOKAWA-KISO





F20240418082348




BLK:11,SNR1: 3.4489 ,SNR2: 8.3844




K20240418082347




BLK:11,SNR1: 0.34974 ,SNR2: 2.4638




2217+128 2024/04/17 23.42UT FUJI -KISO



T20240418082934




BLK:15,SNR1: 2.2222 ,SNR2: 9.9639





3C446 2024/04/17 23.52UT TOYOKAWA-FUJI


F20240418082935




BLK:15,SNR1: 6.5578 ,SNR2: 15.033



T20240418082934





BLK:29,SNR1: 1.5087 ,SNR2: 7.0688





3C446 2024/04/17 23.52UT TOYOKAWA-KISO


K20240418082933




BLK:29,SNR1: 10.081 ,SNR2: 18.753



F20240418082935





BLK:18,SNR1: 6.2472 ,SNR2: 14.167





3C446 2024/04/17 23.52UT FUJI -KISO



K20240418082933




BLK:18,SNR1: 8.0727 ,SNR2: 20.640



T20240418083617




BLK: 9, SNR1: 7.0929 , SNR2: 20.470




2229-093 2024/04/17 23.63UT TOYOKAWA-FUJI


F20240418083617





BLK: 9, SNR1: 0.50149 , SNR2: 3.5907




Frequency (Hz)



T20240418083617





BLK:21,SNR1: 6.8231 ,SNR2: 19.464





2229-093 2024/04/17 23.63UT TOYOKAWA-KISO

K20240418083616




BLK:21,SNR1: 2.4659 ,SNR2: 6.4997








F20240418083617




BLK:15,SNR1: 0.27065 ,SNR2: 3.8047




K20240418083616




BLK:15,SNR1: 2.8405 ,SNR2: 7.3115




2229-093 2024/04/17 23.63UT FUJI -KISO



T20240418084445





BLK: 4,SNR1: 0.35255 ,SNR2: 1.5759




Frequency (Hz)

F20240418084446




BLK: 4,SNR1:-0.10774 ,SNR2: 1.6003





Frequency (Hz)


2238-113 2024/04/17 23.77UT TOYOKAWA-FUJI



T20240418084445





BLK: 9,SNR1: 2.6855 ,SNR2: 12.299




Frequency (Hz)

K20240418084444




BLK: 9,SNR1: 0.50093 ,SNR2: 2.8599





Frequency (Hz)


2238-113 2024/04/17 23.77UT TOYOKAWA-KISO




F20240418084446




BLK: 3,SNR1:-0.30277 ,SNR2: 0.0000




K20240418084444





BLK: 3,SNR1: 0.56512 ,SNR2: 3.2340




2238-113 2024/04/17 23.77UT FUJI -KISO



T20240418090516




BLK: 7,SNR1: 0.19780 ,SNR2: 1.5443




2259+481 2024/04/18 0.12UT TOYOKAWA-FUJI


F20240418090516





BLK: 7,SNR1: 1.1671 ,SNR2: 5.3858




Frequency (Hz)



T20240418090516





BLK:12,SNR1: 0.13388 ,SNR2: 1.0469





2259+481 2024/04/18 0.12UT TOYOKAWA-KISO


K20240418090515




BLK:12,SNR1: 4.0412 ,SNR2: 9.9865





F20240418090516




BLK: 7, SNR1: 1.1830 ,SNR2: 5.5970




K20240418090515




BLK: 7, SNR1: 4.8425 ,SNR2: 10.958




2259+481 2024/04/18 0.12UT FUJI -KISO




T20240418092010




BLK: 7, SNR1: 1.4387 , SNR2: 18.813




F20240418092011



BLK: 7, SNR1: 2.5774 , SNR2: 8.9988




3C459 2024/04/18 0.36UT TOYOKAWA-FUJI






T20240418092010





BLK:17,SNR1: 4.3311 ,SNR2: 37.595




Frequency (Hz)

3C459 2024/04/18 0.36UT TOYOKAWA-KISO


K20240418092009




BLK:17,SNR1: 0.55915 ,SNR2: 2.5431




Frequency (Hz)



F20240418092011




BLK: 9,SNR1: 1.7157 ,SNR2: 11.329





3C459 2024/04/18 0.36UT FUJI -KISO



K20240418092009




BLK: 9,SNR1: 1.2040 ,SNR2: 4.0900



T20240418095355




BLK:10,SNR1: 1.9088 ,SNR2: 17.796





2347-02 2024/04/18 0.93UT TOYOKAWA-FUJI



F20240418095356




BLK:10,SNR1: 0.82293E-03,SNR2: 0.98461



T20240418095355




BLK:14,SNR1: 2.0211 ,SNR2: 24.479




Frequency (Hz)

2347-02 2024/04/18 0.93UT TOYOKAWA-KISO


K20240418095354




BLK:14,SNR1: 0.14267 ,SNR2: 0.88774




Frequency (Hz)



F20240418095356




BLK: 2,SNR1:-0.30281 ,SNR2: 0.0000





2347-02 2024/04/18 0.93UT FUJI -KISO



K20240418095354




BLK: 2,SNR1: 0.51534 ,SNR2: 2.5236



T20240418100048





BLK:12,SNR1: 2.6498 ,SNR2: 11.058




Frequency (Hz)

2354+14 2024/04/18 1.04UT TOYOKAWA-FUJI


F20240418100049




BLK:12,SNR1: 2.3484 ,SNR2: 5.7796




Frequency (Hz)





T20240418100048




BLK:20,SNR1: 2.8084 ,SNR2: 13.132




K20240418100047







BLK:20,SNR1: 2.3150 ,SNR2: 5.7618




2354+14 2024/04/18 1.04UT TOYOKAWA-KISO






2354+14 2024/04/18 1.04UT FUJI -KISO







T20240418100951




BLK:16,SNR1: 1.3013 ,SNR2: 5.6541




F20240418100952




BLK:16,SNR1: 1.2025 ,SNR2: 4.5837




3C2 2024/04/18 1.19UT TOYOKAWA-FUJI



T20240418100951




BLK:26,SNR1: 6.0220 ,SNR2: 13.898





3C2 2024/04/18 1.19UT TOYOKAWA-KISO


K20240418100950




BLK:26,SNR1: 11.374 ,SNR2: 20.166



F20240418100952




BLK:24,SNR1: 0.59846 ,SNR2: 3.1682




Frequency (Hz)

3C2 2024/04/18 1.19UT FUJI -KISO


K20240418100950





BLK:24,SNR1: 6.5427 ,SNR2: 16.070




Frequency (Hz)





T20240418101713




BLK: 4,SNR1: 0.10499 ,SNR2: 1.4044




F20240418101714





BLK: 4,SNR1: 0.35206E-01,SNR2: 1.5819




0011+344 2024/04/18 1.32UT TOYOKAWA-FUJI





T20240418101713




BLK: 4,SNR1: 0.25721 ,SNR2: 0.56434




K20240418101712





BLK: 4,SNR1: 0.35793 ,SNR2: 1.2291




0011+344 2024/04/18 1.32UT TOYOKAWA-KISO



F20240418101714





BLK: 5, SNR1: 0.75737E-01, SNR2: 1.9067




Frequency (Hz)

K20240418101712








BLK: 5, SNR1: 0.27582, SNR2: 1.8419




Frequency (Hz)





0011+344 2024/04/18 1.32UT FUJI -KISO






0019-00 2024/04/18 1.46UT TOYOKAWA-FUJI







0019-00 2024/04/18 1.46UT TOYOKAWA-KISO






F20240418102550




BLK: 8,SNR1: 0.16254E-01,SNR2: 1.2474





0019-00 2024/04/18 1.46UT FUJI -KISO



K20240418102548




BLK: 8,SNR1: 0.44626 ,SNR2: 2.3487



T20240418103604




BLK:12,SNR1: 0.80319 ,SNR2: 4.6286





3C12 2024/04/18 1.63UT TOYOKAWA-FUJI


F20240418103605




BLK:12,SNR1: 1.0177 ,SNR2: 2.5650




T20240418103604




BLK:14,SNR1: 0.89777 ,SNR2: 5.1961




K20240418103603





BLK:14,SNR1: 1.9315 ,SNR2: 8.3994




3C12 2024/04/18 1.63UT TOYOKAWA-KISO



F20240418103605





BLK:15,SNR1: 0.23550 ,SNR2: 2.5849





3C12 2024/04/18 1.63UT FUJI -KISO




K20240418103603





BLK:15,SNR1: 2.4016 ,SNR2: 10.127




T20240418105005





F20240418105006




0044-056 2024/04/18 1.86UT TOYOKAWA-FUJI





T20240418105005




BLK: 6,SNR1: 0.29740 ,SNR2: 2.8245




K20240418105004




BLK: 6,SNR1: 1.1018 ,SNR2: 4.7371




0044-056 2024/04/18 1.86UT TOYOKAWA-KISO



F20240418105006





BLK: 4,SNR1: 1.9573 ,SNR2: 4.7069




Frequency (Hz)

K20240418105004




BLK: 4,SNR1: 0.72827E-01,SNR2: 0.59284





Frequency (Hz)


0044-056 2024/04/18 1.86UT FUJI -KISO



T20240418105727





BLK: 6,SNR1: 0.32495 ,SNR2: 1.9535




Frequency (Hz)

F20240418105728




BLK: 6,SNR1: 0.69566E-01,SNR2: 2.1743




Frequency (Hz)

3C26 2024/04/18 1.99UT TOYOKAWA-FUJI








T20240418105727




BLK:21,SNR1: 0.47263 ,SNR2: 4.5182




K20240418105726





BLK:21,SNR1: 1.9631 ,SNR2: 8.8071




3C26 2024/04/18 1.99UT TOYOKAWA-KISO



F20240418105728




BLK: 9,SNR1:-0.18320E-01,SNR2: 1.1739





3C26 2024/04/18 1.99UT FUJI -KISO



K20240418105726





BLK: 9,SNR1: 2.0415 ,SNR2: 8.7771




T20240418110225





F20240418110226





0056-00 2024/04/18 2.07UT TOYOKAWA-FUJI




T20240418110225





K20240418110224







0056-00 2024/04/18 2.07UT TOYOKAWA-KISO





F20240418110226




K20240418110224




T20240418111207




BLK:12,SNR1: 4.9009 ,SNR2: 24.465




F20240418111207





BLK:12,SNR1: 0.11652 ,SNR2: 1.2307




0106+01 2024/04/18 2.23UT TOYOKAWA-FUJI





T20240418111207




BLK:20,SNR1: 1.3867 ,SNR2: 4.9402




K20240418111206







BLK:20,SNR1: 0.29399 ,SNR2: 2.2341




0106+01 2024/04/18 2.23UT TOYOKAWA-KISO







0106+01 2024/04/18 2.23UT FUJI -KISO







T20240418112130




BLK: 8,SNR1: 0.71583 ,SNR2: 4.7850




F20240418112131




BLK: 8,SNR1: 3.0285 ,SNR2: 11.206




0115-01 2024/04/18 2.39UT TOYOKAWA-FUJI



T20240418112130





BLK:22,SNR1: 25.007 ,SNR2: 50.303





0115-01 2024/04/18 2.39UT TOYOKAWA-KISO



K20240418112129




BLK:22,SNR1: 0.24153 ,SNR2: 0.91898



F20240418112131





BLK: 5,SNR1: 4.4219 ,SNR2: 15.777





0115-01 2024/04/18 2.39UT FUJI -KISO


K20240418112129




BLK: 5,SNR1: 0.50180E-01,SNR2: 0.78092




T20240418113430




BLK:10,SNR1: 1.0381 ,SNR2: 4.4806




F20240418113430




BLK:10,SNR1:-0.17146 ,SNR2: 0.71566




0128+03 2024/04/18 2.60UT TOYOKAWA-FUJI





T20240418113430




BLK:15,SNR1: 0.89362 ,SNR2: 4.6894




K20240418113429




BLK:15,SNR1: 0.20343 ,SNR2: 1.7768




0128+03 2024/04/18 2.60UT TOYOKAWA-KISO





F20240418113430




BLK: 7,SNR1: 0.79097E-01,SNR2: 1.2306




K20240418113429




BLK: 7,SNR1: 0.26755 ,SNR2: 1.5093




0128+03 2024/04/18 2.60UT FUJI -KISO




T20240418114103




BLK:25,SNR1: 8.7562 ,SNR2: 43.104




F20240418114104




BLK:25,SNR1: 0.21878 ,SNR2: 3.8801




3C48 2024/04/18 2.71UT TOYOKAWA-FUJI



T20240418114103





BLK:32,SNR1: 7.8430 ,SNR2: 38.705





3C48 2024/04/18 2.71UT TOYOKAWA-KISO

K20240418114102





BLK:32,SNR1: 2.3515 ,SNR2: 6.2272











F20240418114104




K20240418114102




T20240418120048




BLK: 5,SNR1: 33.446 ,SNR2: 64.154




F20240418120048







BLK: 5,SNR1:-0.15889 ,SNR2: 2.3116




0155-109 2024/04/18 3.04UT TOYOKAWA-FUJI








0155-109 2024/04/18 3.04UT TOYOKAWA-KISO





F20240418120048




BLK:10,SNR1:-0.13871 ,SNR2: 1.9062




K20240418120047





BLK:10,SNR1: 0.49297 ,SNR2: 2.0709




0155-109 2024/04/18 3.04UT FUJI -KISO




T20240418120755




BLK: 8,SNR1: 0.70021 ,SNR2: 3.7292




F20240418120755





BLK: 8,SNR1:-0.32924 ,SNR2: 0.0000




0202+15 2024/04/18 3.16UT TOYOKAWA-FUJI





T20240418120755




BLK:12,SNR1: 0.78798 ,SNR2: 1.9072




K20240418120754




BLK:12,SNR1: 0.40381 ,SNR2: 3.3652




0202+15 2024/04/18 3.16UT TOYOKAWA-KISO



F20240418120755





BLK: 3,SNR1:-0.30618 ,SNR2: 0.0000





0202+15 2024/04/18 3.16UT FUJI -KISO




K20240418120754





BLK: 3,SNR1: 1.8877 ,SNR2: 5.8857




T20240418121946



F20240418121947




0213+178 2024/04/18 3.36UT TOYOKAWA-FUJI








T20240418121946




BLK: 4,SNR1: 0.81833E-01,SNR2: 0.26516E-01




K20240418121945




BLK: 4,SNR1: 2.5019 ,SNR2: 11.700




0213+178 2024/04/18 3.36UT TOYOKAWA-KISO





F20240418121947




BLK: 6,SNR1:-0.13739 ,SNR2: 2.2297




K20240418121945





BLK: 6,SNR1: 2.1156 ,SNR2: 9.9419




0213+178 2024/04/18 3.36UT FUJI -KISO





T20240418122728




BLK:15,SNR1: 0.53477 ,SNR2: 5.7884




F20240418122729






BLK:15,SNR1:-0.53487E-01,SNR2: 1.3909






3C67 2024/04/18 3.49UT TOYOKAWA-FUJI




T20240418122728




K20240418122727




3C67 2024/04/18 3.49UT TOYOKAWA-KISO



F20240418122729




BLK:14,SNR1:-0.82067E-01,SNR2: 0.61556





3C67 2024/04/18 3.49UT FUJI -KISO



K20240418122727




BLK:14,SNR1: 0.65463 ,SNR2: 2.4068



T20240418124543




BLK: 8,SNR1: 1.2590 ,SNR2: 7.5176





3C71 2024/04/18 3.79UT TOYOKAWA-FUJI



F20240418124543




BLK: 8,SNR1:-0.11469 ,SNR2: 0.74093



T20240418124543





BLK:10,SNR1: 1.3548 ,SNR2: 7.3790





3C71 2024/04/18 3.79UT TOYOKAWA-KISO



K20240418124542






BLK:10,SNR1: 0.44439 ,SNR2: 2.6785




F20240418124543



K20240418124542





3C71 2024/04/18 3.79UT FUJI -KISO








T20240418130458




No.Good Data




F20240418130459





No.Good Data




0258+350 2024/04/18 4.11UT TOYOKAWA-FUJI





T20240418130458




BLK: 3,SNR1:-0.17650E-01,SNR2: 0.90758




K20240418130457




BLK: 3,SNR1: 0.91138 ,SNR2: 8.5908




0258+350 2024/04/18 4.11UT TOYOKAWA-KISO





F20240418130459




BLK: 3,SNR1: 0.21071 ,SNR2: 4.2354




K20240418130457




BLK: 3,SNR1: 0.65555 ,SNR2: 8.4365




0258+350 2024/04/18 4.11UT FUJI -KISO





T20240418131447




BLK:11,SNR1: 0.19398 ,SNR2: 3.5709




F20240418131447




BLK:11,SNR1: 1.5373 ,SNR2: 3.9126




0308+305 2024/04/18 4.27UT TOYOKAWA-FUJI





T20240418131447




BLK:16,SNR1: 0.23945 ,SNR2: 3.4457




K20240418131446





BLK:16,SNR1: 0.17651 ,SNR2: 1.1037




0308+305 2024/04/18 4.27UT TOYOKAWA-KISO





F20240418131447




BLK:11,SNR1: 2.0463 ,SNR2: 3.6722




K20240418131446







BLK:11,SNR1: 0.27061 ,SNR2: 1.3550








0308+305 2024/04/18 4.27UT FUJI -KISO






0320+05 2024/04/18 4.47UT TOYOKAWA-FUJI










0320+05 2024/04/18 4.47UT TOYOKAWA-KISO










0320+05 2024/04/18 4.47UT FUJI -KISO







BLK: 4, SNR1: 0.23132E-01, SNR2: 1.6672







BLK: 4, SNR1: 0.15601E-01, SNR2: 0.94748




0333+32 2024/04/18 4.69UT TOYOKAWA-FUJI







0333+32 2024/04/18 4.69UT TOYOKAWA-KISO





F20240418133941




BLK: 6,SNR1: 0.51675E-01,SNR2: 0.64872




K20240418133939




BLK: 6,SNR1: 0.15325 ,SNR2: 0.76129





0333+32 2024/04/18 4.69UT FUJI -KISO







BLK: 5, SNR1: 0.24590 , SNR2: 1.0703





BLK: 5, SNR1: 2.3440 , SNR2: 6.4962




0347+05 2024/04/18 4.91UT TOYOKAWA-FUJI





T20240418135242




BLK: 7,SNR1: 2.4744 ,SNR2: 17.303




K20240418135241





BLK: 7,SNR1: 0.28535 ,SNR2: 1.0668




0347+05 2024/04/18 4.91UT TOYOKAWA-KISO





F20240418135243




BLK: 6,SNR1: 1.1046 ,SNR2: 6.6174




K20240418135241





BLK: 6,SNR1: 0.54338 ,SNR2: 5.2978




0347+05 2024/04/18 4.91UT FUJI -KISO




T20240418140816




BLK: 6,SNR1: 34.100 ,SNR2: 59.372




F20240418140816



BLK: 6,SNR1: 0.89342E-01,SNR2: 1.1930





0403-132 2024/04/18 5.17UT TOYOKAWA-FUJI








T20240418140816




BLK:15,SNR1: 33.911 ,SNR2: 60.584




K20240418140815







BLK:15,SNR1: 4.2809 ,SNR2: 37.205




0403-132 2024/04/18 5.17UT TOYOKAWA-KISO








0403-132 2024/04/18 5.17UT FUJI -KISO





T20240418141727




BLK:12,SNR1: 2.3696 ,SNR2: 8.9768




F20240418141727





BLK:12,SNR1: 0.32579 ,SNR2: 2.2397




0411+05 2024/04/18 5.32UT TOYOKAWA-FUJI





T20240418141727




BLK:10,SNR1: 34.793 ,SNR2: 107.36




K20240418141726





BLK:10,SNR1: 1.4820 ,SNR2: 5.5078




0411+05 2024/04/18 5.32UT TOYOKAWA-KISO



F20240418141727




BLK:15,SNR1: 0.19039 ,SNR2: 2.3342




Frequency (Hz)

K20240418141726




BLK:15,SNR1: 1.1763 ,SNR2: 3.9520




Frequency (Hz)


0411+05 2024/04/18 5.32UT FUJI -KISO





T20240418142820




BLK: 3,SNR1: 54.248 ,SNR2: 166.42




F20240418142820




BLK: 3,SNR1: 0.18436 ,SNR2: 3.5267




0422+178 2024/04/18 5.50UT TOYOKAWA-FUJI



T20240418142820





BLK:10,SNR1: 22.077 ,SNR2: 57.057




Frequency (Hz)

K20240418142819








BLK:10,SNR1: 4.0346 ,SNR2: 9.8359




Frequency (Hz)

0422+178 2024/04/18 5.50UT TOYOKAWA-KISO







0422+178 2024/04/18 5.50UT FUJI -KISO






T20240418143548




BLK:10,SNR1: 1.0192 ,SNR2: 5.5924




Frequency (Hz)

F20240418143549




BLK:10,SNR1:-0.14134 ,SNR2: 0.23520E-01





Frequency (Hz)


3C119 2024/04/18 5.62UT TOYOKAWA-FUJI





T20240418143548




BLK:26,SNR1: 2.0441 ,SNR2: 5.9129




K20240418143547





BLK:26,SNR1: 0.16680 ,SNR2: 1.9227




3C119 2024/04/18 5.62UT TOYOKAWA-KISO



F20240418143549





BLK: 7,SNR1:-0.10778 ,SNR2: 1.0527




Frequency (Hz)

K20240418143547




BLK: 7,SNR1: 0.44844 ,SNR2: 4.0308





Frequency (Hz)


3C119 2024/04/18 5.62UT FUJI -KISO



T20240418152356




BLK:13,SNR1: 0.23113 ,SNR2: 1.7461




Frequency (Hz)

F20240418152356




BLK:13,SNR1: 0.82749E-02,SNR2: 2.4408





Frequency (Hz)


3C138 2024/04/18 6.43UT TOYOKAWA-FUJI



T20240418152356





BLK:16,SNR1: 0.25530 ,SNR2: 1.1447




Frequency (Hz)

K20240418152355




BLK:16,SNR1: 2.5205 ,SNR2: 8.8723




Frequency (Hz)


3C138 2024/04/18 6.43UT TOYOKAWA-KISO





F20240418152356




BLK:19,SNR1: 0.16611 ,SNR2: 3.0127




K20240418152355




BLK:19,SNR1: 3.3251 ,SNR2: 14.152




3C138 2024/04/18 6.43UT FUJI -KISO




T20240418153729




BLK:24,SNR1: 9.0749 ,SNR2: 22.839




F20240418153730




BLK:24,SNR1: 3.9185 ,SNR2: 12.313




0531+194 2024/04/18 6.65UT TOYOKAWA-FUJI




T20240418153729




BLK:31,SNR1: 8.9460 ,SNR2: 22.509




K20240418153728



BLK:31,SNR1: 7.6543 ,SNR2: 19.232





0531+194 2024/04/18 6.65UT TOYOKAWA-KISO







F20240418153730




BLK:26,SNR1: 3.3866 ,SNR2: 10.556




K20240418153728





BLK:26,SNR1: 7.9673 ,SNR2: 20.009




0531+194 2024/04/18 6.65UT FUJI -KISO



T20240418154548




BLK:21,SNR1: 1.1481 ,SNR2: 8.9680




Frequency (Hz)

F20240418154548




BLK:21,SNR1: 0.46105 ,SNR2: 3.1490





Frequency (Hz)


3C147 2024/04/18 6.79UT TOYOKAWA-FUJI





T20240418154548




BLK:24,SNR1: 1.2538 ,SNR2: 8.0266




K20240418154547




BLK:24,SNR1: 0.42309 ,SNR2: 2.3585





3C147 2024/04/18 6.79UT TOYOKAWA-KISO







BLK:14,SNR1: 0.83403 ,SNR2: 3.9133





BLK:14,SNR1: 0.53591 ,SNR2: 3.1804




3C147 2024/04/18 6.79UT FUJI -KISO



T20240418155400




BLK: 3,SNR1: 2.9898 ,SNR2: 13.272




Frequency (Hz)

F20240418155400




BLK: 3,SNR1:-0.13391 ,SNR2: 0.56006





Frequency (Hz)


0548+16 2024/04/18 6.93UT TOYOKAWA-FUJI





T20240418155400




BLK: 7,SNR1: 2.9546 ,SNR2: 13.116




K20240418155359





BLK: 7,SNR1: 0.25783 ,SNR2: 2.0174




0548+16 2024/04/18 6.93UT TOYOKAWA-KISO







0548+16 2024/04/18 6.93UT FUJI -KISO



T20240418155811




BLK:18,SNR1: 6.7689 ,SNR2: 17.243




Frequency (Hz)

F20240418155811




BLK:18,SNR1: 2.4174 ,SNR2: 8.8216




Frequency (Hz)

0552+12 2024/04/18 7.00UT TOYOKAWA-FUJI








T20240418155811




BLK:22,SNR1: 7.7526 ,SNR2: 19.677




K20240418155810




BLK:22,SNR1: 9.7212 ,SNR2: 19.723




0552+12 2024/04/18 7.00UT TOYOKAWA-KISO



F20240418155811





BLK:24,SNR1: 1.0009 ,SNR2: 5.9489




Frequency (Hz)

K20240418155810




BLK:24,SNR1: 9.7321 ,SNR2: 19.747





Frequency (Hz)


0552+12 2024/04/18 7.00UT FUJI -KISO



T20240418160237





BLK:19,SNR1: 7.8924 ,SNR2: 20.015




Frequency (Hz)

F20240418160238




BLK:19,SNR1: 7.6975 ,SNR2: 22.008





Frequency (Hz)


0556+191 2024/04/18 7.07UT TOYOKAWA-FUJI



T20240418160237





BLK:25,SNR1: 8.3692 ,SNR2: 20.977




Frequency (Hz)

K20240418160236




BLK:25,SNR1: 6.1753 ,SNR2: 15.621





Frequency (Hz)


0556+191 2024/04/18 7.07UT TOYOKAWA-KISO



F20240418160238





BLK:21,SNR1: 8.4718 ,SNR2: 21.223




Frequency (Hz)

K20240418160236




BLK:21,SNR1: 7.4985 ,SNR2: 18.932





Frequency (Hz)


0556+191 2024/04/18 7.07UT FUJI -KISO



T20240418160710




No.Good Data




Frequency (Hz)

F20240418160711




No.Good Data





Frequency (Hz)


3C152 2024/04/18 7.15UT TOYOKAWA-FUJI





T20240418160710




BLK: 1,SNR1:-0.95828E-01,SNR2: 0.24932




K20240418160709




BLK: 1,SNR1: 0.39562 ,SNR2: 1.8657




3C152 2024/04/18 7.15UT TOYOKAWA-KISO



F20240418160711





BLK: 4,SNR1:-0.23762 ,SNR2: 0.0000




Frequency (Hz)

K20240418160709




BLK: 4,SNR1: 10.061 ,SNR2: 28.205




Frequency (Hz)

3C152 2024/04/18 7.15UT FUJI -KISO






T20240418162931




BLK:10,SNR1: 7.0796 ,SNR2: 12.752




Frequency (Hz)

F20240418162932




BLK:10,SNR1: 1.0410 ,SNR2: 8.4681




Frequency (Hz)


3C161 2024/04/18 7.52UT TOYOKAWA-FUJI



T20240418162931





BLK:14,SNR1: 3.8459 ,SNR2: 9.5202




Frequency (Hz)

K20240418162930




BLK:14,SNR1: 3.6014 ,SNR2: 7.1971




Frequency (Hz)


3C161 2024/04/18 7.52UT TOYOKAWA-KISO



F20240418162932





BLK: 8,SNR1: 1.5186 ,SNR2: 6.7482




Frequency (Hz)

K20240418162930




BLK: 8,SNR1: 6.1513 ,SNR2: 11.776




Frequency (Hz)


3C161 2024/04/18 7.52UT FUJI -KISO



T20240418165704




BLK:30,SNR1: 12.304 ,SNR2: 21.665




Frequency (Hz)

F20240418165704




BLK:30,SNR1: 2.4328 ,SNR2: 11.051





Frequency (Hz)


0652-130 2024/04/18 7.98UT TOYOKAWA-FUJI



T20240418165704





BLK:32,SNR1: 11.358 ,SNR2: 25.698




Frequency (Hz)

K20240418165703




BLK:32,SNR1: 8.8131 ,SNR2: 21.998




Frequency (Hz)


0652-130 2024/04/18 7.98UT TOYOKAWA-KISO



F20240418165704





BLK:32,SNR1: 2.4307 ,SNR2: 11.029




Frequency (Hz)

K20240418165703






BLK:32,SNR1: 8.8218 ,SNR2: 22.020




Frequency (Hz)



0652-130 2024/04/18 7.98UT FUJI -KISO






0703+138 2024/04/18 8.17UT TOYOKAWA-FUJI







0703+138 2024/04/18 8.17UT TOYOKAWA-KISO






F20240418170842





BLK:10,SNR1:-0.86897E-01,SNR2: 1.7629




Frequency (Hz)

K20240418170840



BLK:10,SNR1: 6.4155 ,SNR2: 15.992



Frequency (Hz)

0703+138 2024/04/18 8.17UT FUJI -KISO

