




TOYOKAWA 2030+517 2024/05/13(134)04:56:51-05:00:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2037+511 2024/05/13(134)05:03:49-05:07:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2045+483 2024/05/13(134)05:12:14-05:15:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2050+364 2024/05/13(134)05:18:14-05:21:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2055+507 2024/05/13(134)05:22:31-05:25:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2104+570 2024/05/13(134)05:30:31-05:33:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2107+288 2024/05/13(134)05:34:47-05:38:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2111+378 2024/05/13(134)05:38:45-05:42:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2114+247 2024/05/13(134)05:42:29-05:45:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2119+435 2024/05/13(134)05:46:34-05:50:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2124+641 2024/05/13(134)05:50:20-05:53:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2127+456 2024/05/13(134)05:54:14-05:57:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2131+379 2024/05/13(134)05:59:12-06:02:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2135+316 2024/05/13(134)06:03:15-06:06:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2139+028 2024/05/13(134)06:07:43-06:11:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2147+145 2024/05/13(134)06:15:50-06:19:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2152+450 2024/05/13(134)06:19:32-06:22:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2156-043 2024/05/13(134)06:24:54-06:28:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2201+315 2024/05/13(134)06:28:34-06:32:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2207+374 2024/05/13(134)06:34:38-06:38:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2217+128 2024/05/13(134)06:45:28-06:48:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C446

2024/05/13(134)06:51:14-06:54:40JST


10302+/- 2112




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2229-093 2024/05/13(134)06:57:58-07:01:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2235+511 2024/05/13(134)07:02:31-07:05:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2238-113 2024/05/13(134)07:06:25-07:09:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2243+394 2024/05/13(134)07:11:00-07:14:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C454.3 2024/05/13(134)07:19:14-07:22:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2259+481 2024/05/13(134)07:26:57-07:30:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C456

2024/05/13(134)07:37:45-07:41:11JST

8796+/- 131




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C459


2024/05/13(134)07:41:50-07:45:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2318-16 2024/05/13(134)07:46:18-07:49:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2325+269 2024/05/13(134)07:53:10-07:56:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2344+09 2024/05/13(134)08:11:49-08:15:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2347-02 2024/05/13(134)08:15:35-08:19:01JST


8857+/- 466




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2354+14 2024/05/13(134)08:22:28-08:25:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C2

2024/05/13(134)08:31:31-08:34:57JST


10933+/- 33




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0011+344 2024/05/13(134)08:38:53-08:42:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0019-00 2024/05/13(134)08:47:30-08:50:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0026+113 2024/05/13(134)08:54:15-08:57:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0038+328 2024/05/13(134)09:06:02-09:09:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0044-056 2024/05/13(134)09:11:46-09:15:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C26

2024/05/13(134)09:19:07-09:22:33JST


9076+/- 179




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0056-00 2024/05/13(134)09:24:06-09:27:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0106+01 2024/05/13(134)09:33:48-09:37:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0116+31 2024/05/13(134)09:44:37-09:48:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0120+405 2024/05/13(134)09:48:32-09:51:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C43

2024/05/13(134)09:55:00-09:58:26JST

9114+/- 296




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C48

2024/05/13(134)10:02:44-10:06:10JST


10832+/- 70




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0148+274 2024/05/13(134)10:16:27-10:19:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0155-109 2024/05/13(134)10:22:29-10:25:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0202+15 2024/05/13(134)10:29:36-10:33:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0213+178 2024/05/13(134)10:41:26-10:44:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C67

2024/05/13(134)10:49:08-10:52:34JST

9829+/- 488




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C71


2024/05/13(134)11:07:24-11:10:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0258+350 2024/05/13(134)11:26:38-11:30:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0308+305 2024/05/13(134)11:36:28-11:39:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0320+05 2024/05/13(134)11:48:00-11:51:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0324+119 2024/05/13(134)11:52:04-11:55:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0333+32 2024/05/13(134)12:01:20-12:04:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0347+05 2024/05/13(134)12:14:22-12:17:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0355+50 2024/05/13(134)12:24:35-12:28:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0403-132 2024/05/13(134)12:29:57-12:33:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0411+05 2024/05/13(134)12:39:07-12:42:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0418+236 2024/05/13(134)12:46:01-12:49:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0422+178 2024/05/13(134)12:50:00-12:53:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C119 2024/05/13(134)12:57:28-13:00:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C138 2024/05/13(134)13:45:36-13:49:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0531+194 2024/05/13(134)13:59:09-14:02:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C147 2024/05/13(134)14:07:29-14:10:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0548+16 2024/05/13(134)14:15:40-14:19:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0552+12 2024/05/13(134)14:19:51-14:23:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0556+191 2024/05/13(134)14:24:18-14:27:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0605-08 2024/05/13(134)14:32:04-14:35:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C158 2024/05/13(134)14:45:57-14:49:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C161 2024/05/13(134)14:51:12-14:54:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0652-130 2024/05/13(134)15:18:45-15:22:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0703+138 2024/05/13(134)15:30:21-15:33:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0713-024 2024/05/13(134)15:39:44-15:43:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0716+022 2024/05/13(134)15:43:24-15:46:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723+10 2024/05/13(134)15:49:56-15:53:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0732+33 2024/05/13(134)16:00:10-16:03:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0741-06 2024/05/13(134)16:08:12-16:11:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0752-200 2024/05/13(134)16:17:57-16:21:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C190 2024/05/13(134)16:25:31-16:28:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0806-103 2024/05/13(134)16:32:37-16:36:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C196 2024/05/13(134)16:37:56-16:41:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0817+183 2024/05/13(134)16:44:40-16:48:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2024/05/13(134)16:49:05-16:52:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0839-071 2024/05/13(134)17:05:51-17:09:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C208 2024/05/13(134)17:16:52-17:20:18JST


10475+/- 42




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216 2024/05/13(134)17:33:33-17:36:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0923+392 2024/05/13(134)17:50:56-17:54:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0931+399 2024/05/13(134)17:58:58-18:02:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0937+391 2024/05/13(134)18:04:53-18:08:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0945+408 2024/05/13(134)18:12:43-18:16:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1004+446 2024/05/13(134)18:31:04-18:34:30JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1031+567 2024/05/13(134)18:58:50-19:02:16JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

