




T20240504054739





BLK: 5,SNR1: 0.14048 ,SNR2: 5.8997




Frequency (Hz)

2045+483 2024/05/03 20.82UT TOYOKAWA-FUJI


F20240504054739





BLK: 5,SNR1:-0.22486 ,SNR2: 1.2765




Frequency (Hz)





T20240504054739




BLK: 4,SNR1: 0.12123 ,SNR2: 2.6813




K20240504054737





BLK: 4,SNR1: 0.14047 ,SNR2: 1.9077




2045+483 2024/05/03 20.82UT TOYOKAWA-KISO



F20240504054739





BLK: 6,SNR1:-0.17552 ,SNR2: 2.1064




Frequency (Hz)

2045+483 2024/05/03 20.82UT FUJI -KISO


K20240504054737




BLK: 6,SNR1: 1.9148 ,SNR2: 12.099




Frequency (Hz)



T20240504061754





BLK: 8,SNR1: 99.145 ,SNR2: 330.23




Frequency (Hz)

F20240504061754




BLK: 8,SNR1: 0.98837 ,SNR2: 5.1953




Frequency (Hz)


2114+247 2024/05/03 21.33UT TOYOKAWA-FUJI



T20240504061754





BLK: 8,SNR1: 53.214 ,SNR2: 372.75




Frequency (Hz)

K20240504061752




BLK: 8,SNR1: 0.49538 ,SNR2: 1.9330





Frequency (Hz)


2114+247 2024/05/03 21.33UT TOYOKAWA-KISO



F20240504061754





BLK: 8,SNR1: 3.3546 ,SNR2: 4.3146




Frequency (Hz)

K20240504061752




BLK: 8,SNR1: 0.34650 ,SNR2: 1.4844





Frequency (Hz)


2114+247 2024/05/03 21.33UT FUJI -KISO



T20240504063437





BLK: 2,SNR1: 3.1521 ,SNR2: 12.205




Frequency (Hz)

2131+379 2024/05/03 21.61UT TOYOKAWA-FUJI


F20240504063438





BLK: 2,SNR1:-0.12686 ,SNR2: 0.58808




Frequency (Hz)



T20240504063437





BLK: 3,SNR1: 5.4971 ,SNR2: 63.671




Frequency (Hz)

K20240504063435




BLK: 3,SNR1:-0.10855 ,SNR2: 0.29227




Frequency (Hz)

2131+379 2024/05/03 21.61UT TOYOKAWA-KISO







F20240504063438




BLK: 5,SNR1: 0.59148E-01,SNR2: 1.0351




K20240504063435





BLK: 5,SNR1: 0.69165 ,SNR2: 2.9747




2131+379 2024/05/03 21.61UT FUJI -KISO



T20240504064308





BLK: 8,SNR1: 34.884 ,SNR2: 110.77




Frequency (Hz)

F20240504064308




BLK: 8,SNR1:-0.22365 ,SNR2: 2.7495





Frequency (Hz)


2139+028 2024/05/03 21.75UT TOYOKAWA-FUJI



T20240504064308





BLK: 5,SNR1: 11.882 ,SNR2: 66.090




Frequency (Hz)

K20240504064306




BLK: 5,SNR1: 0.78383E-01,SNR2: 1.0173




Frequency (Hz)


2139+028 2024/05/03 21.75UT TOYOKAWA-KISO





F20240504064308




BLK: 3,SNR1: 0.57942 ,SNR2: 2.0851




K20240504064308





BLK: 3,SNR1: -0.16326E-01,SNR2: 0.32434




2139+028 2024/05/03 21.75UT FUJI -KISO



T20240504065115





BLK: 5, SNR1: -0.18348E-02, SNR2: 0.88404




Frequency (Hz)

F20240504065116




BLK: 5, SNR1: 1.4199, SNR2: 4.8015





Frequency (Hz)


2147+145 2024/05/03 21.88UT TOYOKAWA-FUJI





T20240504065115




BLK: 5, SNR1: 0.11632 , SNR2: 0.48086




K20240504065112






BLK: 5, SNR1: 0.98307 , SNR2: 2.2763






2147+145 2024/05/03 21.88UT TOYOKAWA-KISO




F20240504065116





K20240504065112




2147+145 2024/05/03 21.88UT FUJI -KISO



T20240504070019




BLK: 7,SNR1: 1.2020 ,SNR2: 13.851




Frequency (Hz)

F20240504070019




BLK: 7,SNR1:-0.20853 ,SNR2: 0.68371




Frequency (Hz)

2156-043 2024/05/03 22.03UT TOYOKAWA-FUJI






T20240504070019





BLK: 8,SNR1: 0.48934 ,SNR2: 4.3496




Frequency (Hz)

K20240504070016




BLK: 8,SNR1: 0.66772 ,SNR2: 2.0329





Frequency (Hz)


2156-043 2024/05/03 22.03UT TOYOKAWA-KISO



F20240504070019





BLK: 9,SNR1:-0.71248E-01,SNR2: 1.7624




Frequency (Hz)

K20240504070016




BLK: 9,SNR1: 2.1288 ,SNR2: 5.9820




Frequency (Hz)


2156-043 2024/05/03 22.03UT FUJI -KISO



T20240504070707





BLK: 5,SNR1: 0.91715E-01,SNR2: 2.0001




Frequency (Hz)

F20240504070707




BLK: 5,SNR1: 0.30812 ,SNR2: 1.0633




Frequency (Hz)


2203-18 2024/05/03 22.15UT TOYOKAWA-FUJI





T20240504070707




BLK: 3,SNR1:-0.38344E-01,SNR2: 1.6108




K20240504070704





BLK: 3,SNR1: 2.7144 ,SNR2: 7.8156




2203-18 2024/05/03 22.15UT TOYOKAWA-KISO



F2024050407070





BLK: 3,SNR1:-0.97276E-01,SNR2: 1.3619




Frequency (Hz)

K20240504070704




BLK: 3,SNR1:-0.50093E-01,SNR2: 1.4732





Frequency (Hz)


2203-18 2024/05/03 22.15UT FUJI -KISO



T20240504071330





BLK:12,SNR1: 0.24340 ,SNR2: 2.1726




Frequency (Hz)

2210+016 2024/05/03 22.25UT TOYOKAWA-FUJI


F20240504071331





BLK:12,SNR1: 1.6452 ,SNR2: 7.7634




Frequency (Hz)





T20240504071330




BLK:11,SNR1: 0.21298 ,SNR2: 2.2305




K20240504071327





BLK:11,SNR1: 0.63614 ,SNR2: 2.6839




2210+016 2024/05/03 22.25UT TOYOKAWA-KISO



F20240504071331





BLK: 7,SNR1:-0.23125 ,SNR2: 1.0692




Frequency (Hz)

K20240504071327




BLK: 7,SNR1: 0.66724 ,SNR2: 4.2046





Frequency (Hz)

2210+016 2024/05/03 22.25UT FUJI -KISO






T20240504072053




BLK: 8,SNR1: 0.94510 ,SNR2: 3.3336




Frequency (Hz)

F20240504072053




BLK: 8,SNR1:-0.21796 ,SNR2: 1.2700





Frequency (Hz)


2217+128 2024/05/03 22.38UT TOYOKAWA-FUJI





T20240504072053




BLK: 4,SNR1: 0.52554E-01,SNR2: 0.53636




K20240504072050




BLK: 4,SNR1: 0.47488 ,SNR2: 2.1725




2217+128 2024/05/03 22.38UT TOYOKAWA-KISO




F20240504072053




BLK: 4,SNR1: 0.35279 ,SNR2: 2.1879




K20240504072050





BLK: 4,SNR1: 0.42129 ,SNR2: 1.6453




2217+128 2024/05/03 22.38UT FUJI -KISO



T20240504072639





BLK: 5,SNR1: 0.65991E-01,SNR2: 1.8033





3C446 2024/05/03 22.47UT TOYOKAWA-FUJI



F20240504072640




BLK: 5,SNR1:-0.15403 ,SNR2: 1.0953





T20240504072639




BLK: 5, SNR1: 0.16616 , SNR2: 1.8533




K20240504072636





BLK: 5, SNR1: 0.89108 , SNR2: 6.3255




3C446 2024/05/03 22.47UT TOYOKAWA-KISO



F20240504072640





BLK: 3,SNR1:-0.37162 ,SNR2: 0.0000




Frequency (Hz)

3C446 2024/05/03 22.47UT FUJI -KISO


K20240504072636





BLK: 3,SNR1: 0.59821 ,SNR2: 6.1421




Frequency (Hz)



T20240504073323





BLK:11,SNR1: 0.44192 ,SNR2: 5.7773




Frequency (Hz)

F20240504073324




BLK:11,SNR1: 0.15245 ,SNR2: 5.4132





Frequency (Hz)


2229-093 2024/05/03 22.58UT TOYOKAWA-FUJI



T20240504073323





BLK: 6,SNR1: 0.98999 ,SNR2: 7.7551




Frequency (Hz)

K20240504073320




BLK: 6,SNR1: 1.8104 ,SNR2: 8.6002




Frequency (Hz)

2229-093 2024/05/03 22.58UT TOYOKAWA-KISO






F20240504073324




BLK: 5,SNR1: 0.42215 ,SNR2: 9.7688




Frequency (Hz)

K20240504073320




BLK: 5,SNR1: 1.6842 ,SNR2: 8.1594





Frequency (Hz)


2229-093 2024/05/03 22.58UT FUJI -KISO



T20240504074150





BLK: 4,SNR1: 3.1480 ,SNR2: 19.788




Frequency (Hz)

F20240504074150




BLK: 4,SNR1:-0.19588 ,SNR2: 2.1087





Frequency (Hz)


2238-113 2024/05/03 22.73UT TOYOKAWA-FUJI



T20240504074150





BLK: 3,SNR1: 1.9780 ,SNR2: 9.3193




Frequency (Hz)

K20240504074147




BLK: 3,SNR1: 1.4739 ,SNR2: 7.1340




Frequency (Hz)


2238-113 2024/05/03 22.73UT TOYOKAWA-KISO





F20240504074150




BLK: 3,SNR1: 0.28420E-01,SNR2: 2.6032




K20240504074147







BLK: 3,SNR1: 0.21999 ,SNR2: 2.7020








2238-113 2024/05/03 22.73UT FUJI -KISO






3C454.3 2024/05/03 22.94UT TOYOKAWA-FUJI







3C454.3 2024/05/03 22.94UT TOYOKAWA-KISO




F20240504075440




BLK: 3,SNR1:-0.43604E-01,SNR2: 2.3884




K20240504075436




BLK: 3,SNR1: 0.35436 ,SNR2: 2.0880




3C454.3 2024/05/03 22.94UT FUJI -KISO




T20240504080222




BLK: 5,SNR1: 0.13508 ,SNR2: 0.62955




F20240504080222



BLK: 5,SNR1:-0.13280 ,SNR2: 2.5400





2259+481 2024/05/03 23.07UT TOYOKAWA-FUJI







T20240504080222




BLK: 3,SNR1: 0.71375E-01,SNR2: 0.91451




K20240504080219




BLK: 3,SNR1: 0.24938E-01,SNR2: 2.0341




2259+481 2024/05/03 23.07UT TOYOKAWA-KISO



F20240504080222





BLK: 4,SNR1:-0.65060E-01,SNR2: 2.3323




Frequency (Hz)

K20240504080219




BLK: 4,SNR1: 0.11946 ,SNR2: 1.1498





Frequency (Hz)


2259+481 2024/05/03 23.07UT FUJI -KISO



T20240504081715





BLK: 9,SNR1: 0.22654 ,SNR2: 1.4149




Frequency (Hz)

3C459 2024/05/03 23.32UT TOYOKAWA-FUJI


F20240504081715





BLK: 9,SNR1:-0.16834 ,SNR2: 1.1228




Frequency (Hz)



T20240504081715





BLK:14,SNR1: 0.12002 ,SNR2: 1.5961





3C459 2024/05/03 23.32UT TOYOKAWA-KISO


K20240504081712




BLK:14,SNR1: 0.32109 ,SNR2: 3.2853



F20240504081715





BLK: 4,SNR1: 0.17485 ,SNR2: 1.8187




Frequency (Hz)

K20240504081712




BLK: 4,SNR1: 0.16574 ,SNR2: 0.94528





Frequency (Hz)


3C459 2024/05/03 23.32UT FUJI -KISO



T20240504085100





BLK: 9,SNR1: 0.64369 ,SNR2: 5.3202





2347-02 2024/05/03 23.88UT TOYOKAWA-FUJI



F20240504085100




BLK: 9,SNR1:-0.16531 ,SNR2: 0.99599



T20240504085100





BLK:13,SNR1: 0.76908 ,SNR2: 4.9268




Frequency (Hz)

2347-02 2024/05/03 23.88UT TOYOKAWA-KISO


K20240504085057




BLK:13,SNR1: 0.54119 ,SNR2: 4.3543




Frequency (Hz)



F20240504085100





BLK: 4,SNR1:-0.13705 ,SNR2: 0.0000





2347-02 2024/05/03 23.88UT FUJI -KISO

K20240504085057




BLK: 4,SNR1: 1.0635 ,SNR2: 8.2710








T20240504090656




BLK:15,SNR1: 1.5805 ,SNR2: 3.7435




F20240504090656




BLK:15,SNR1:-0.70561E-01,SNR2: 2.2569




3C2 2024/05/04 0.14UT TOYOKAWA-FUJI



T20240504090656




BLK:16,SNR1: 1.1125 ,SNR2: 4.3166




Frequency (Hz)

3C2 2024/05/04 0.14UT TOYOKAWA-KISO


K20240504090653





BLK:16,SNR1: 2.4557 ,SNR2: 4.7353




Frequency (Hz)



F20240504090656



BLK:15,SNR1:-0.31281E-01,SNR2: 2.4185





Frequency (Hz)


3C2

2024/05/04 0.14UT FUJI -KISO


K20240504090653





BLK:15,SNR1: 4.5293 ,SNR2: 11.434




Frequency (Hz)




T20240504091418




BLK: 5,SNR1: 0.68045E-01,SNR2: 0.73067




F20240504091418





BLK: 5,SNR1: 1.0282 ,SNR2: 1.9843




0011+344 2024/05/04 0.27UT TOYOKAWA-FUJI





T20240504091418




BLK: 3,SNR1: 0.20371 ,SNR2: 1.0987




K20240504091415




BLK: 3,SNR1: 0.88416E-01,SNR2: 0.77253




0011+344 2024/05/04 0.27UT TOYOKAWA-KISO





F20240504091418




BLK: 5,SNR1: 0.64742E-01,SNR2: 1.2907




K20240504091415




BLK: 5,SNR1: 1.0552 ,SNR2: 4.3335




0011+344 2024/05/04 0.27UT FUJI -KISO




T20240504092255




BLK: 6,SNR1: 0.41371 ,SNR2: 1.7455




F20240504092256





BLK: 6,SNR1: 3.3311 ,SNR2: 15.573




0019-00 2024/05/04 0.41UT TOYOKAWA-FUJI



T20240504092255





BLK: 9,SNR1: 0.23317 ,SNR2: 1.9036





0019-00 2024/05/04 0.41UT TOYOKAWA-KISO

K20240504092252




BLK: 9,SNR1: 1.5143 ,SNR2: 5.4136








F20240504092256




BLK: 5,SNR1:-0.10659 ,SNR2: 3.0538




K20240504092252





BLK: 5,SNR1: 1.9509 ,SNR2: 8.7694




0019-00 2024/05/04 0.41UT FUJI -KISO




T20240504093309




BLK:10,SNR1: 0.38109 ,SNR2: 1.1518




F20240504093309





BLK:10,SNR1: 0.30334 ,SNR2: 3.1874




3C12 2024/05/04 0.58UT TOYOKAWA-FUJI



T20240504093309





BLK:17,SNR1: 0.26531 ,SNR2: 0.87198




Frequency (Hz)

3C12 2024/05/04 0.58UT TOYOKAWA-KISO


K20240504093306




BLK:17,SNR1: 2.3346 ,SNR2: 9.4133




Frequency (Hz)



F20240504093309





BLK:15,SNR1: 0.98172E-01,SNR2: 1.6501




Frequency (Hz)

K20240504093306




BLK:15,SNR1: 1.8038 ,SNR2: 5.7049





Frequency (Hz)


3C12 2024/05/04 0.58UT FUJI -KISO



T20240504094711





BLK: 2,SNR1: 0.32825 ,SNR2: 1.6843




Frequency (Hz)

F20240504094711




BLK: 2,SNR1:-0.32779 ,SNR2: 0.0000




Frequency (Hz)


0044-056 2024/05/04 0.81UT TOYOKAWA-FUJI



T20240504094711




BLK:16,SNR1: 1.5282 ,SNR2: 14.016




Frequency (Hz)

0044-056 2024/05/04 0.81UT TOYOKAWA-KISO


K20240504094708




BLK:16,SNR1: 0.62854 ,SNR2: 2.7637




Frequency (Hz)





F20240504094711




BLK: 6,SNR1:-0.39344 ,SNR2: 0.0000




K20240504094708





BLK: 6,SNR1: 0.56451 ,SNR2: 4.4083




0044-056 2024/05/04 0.81UT FUJI -KISO



T20240504095432




BLK:11,SNR1: 1.5391 ,SNR2: 4.2949





3C26 2024/05/04 0.94UT TOYOKAWA-FUJI

F20240504095432





BLK:11,SNR1: 0.13609 ,SNR2: 3.2465






T20240504095432





BLK:18,SNR1: 3.4853 ,SNR2: 9.4155





3C26 2024/05/04 0.94UT TOYOKAWA-KISO



K20240504095429




BLK:18,SNR1: 5.5340 ,SNR2: 15.326



F20240504095432





BLK:14,SNR1: 0.75321E-01,SNR2: 2.9215




Frequency (Hz)

3C26 2024/05/04 0.94UT FUJI -KISO


K20240504095429





BLK:14,SNR1: 3.6969 ,SNR2: 8.7107




Frequency (Hz)



T20240504095931





BLK:14,SNR1: 2.3525 ,SNR2: 5.9718




Frequency (Hz)

F20240504095932




BLK:14,SNR1:-0.82162E-01,SNR2: 2.0049





Frequency (Hz)


0056-00 2024/05/04 1.02UT TOYOKAWA-FUJI



T20240504095931





BLK:25,SNR1: 2.3289 ,SNR2: 6.1814





0056-00 2024/05/04 1.02UT TOYOKAWA-KISO


K20240504095928




BLK:25,SNR1: 1.6782 ,SNR2: 6.2664





F20240504095932




BLK: 7,SNR1:-0.83050E-02,SNR2: 2.6900




K20240504095928





BLK: 7,SNR1: 3.7866 ,SNR2: 7.3332




0056-00 2024/05/04 1.02UT FUJI -KISO





T20240504100913




BLK: 6,SNR1: 0.37466 ,SNR2: 1.8803




F20240504100913




BLK: 6,SNR1:-0.25055 ,SNR2: 1.7367




0106+01 2024/05/04 1.18UT TOYOKAWA-FUJI





T20240504100913




BLK:14,SNR1: 0.29654 ,SNR2: 2.9860




K20240504100911




BLK:14,SNR1: 0.31199 ,SNR2: 1.2822




0106+01 2024/05/04 1.18UT TOYOKAWA-KISO



F20240504100913




BLK: 5,SNR1:-0.35382 ,SNR2: 0.71427E-03





0106+01 2024/05/04 1.18UT FUJI -KISO

K20240504100911





BLK: 5,SNR1: 0.84106 ,SNR2: 3.9352






T20240504102003




BLK: 9,SNR1: 1.3391 ,SNR2: 3.3684




0116+31 2024/05/04 1.36UT TOYOKAWA-FUJI


F20240504102003





BLK: 9,SNR1:-0.18243 ,SNR2: 1.6057




Frequency (Hz)



T20240504102003




BLK:15,SNR1: 0.84422 ,SNR2: 2.4330





0116+31 2024/05/04 1.36UT TOYOKAWA-KISO



K20240504102000




BLK:15,SNR1: 0.30572 ,SNR2: 2.1991



F20240504102003





BLK: 9,SNR1:-0.17257 ,SNR2: 2.1550




Frequency (Hz)

K20240504102000




BLK: 9,SNR1: 0.38224 ,SNR2: 2.6454




Frequency (Hz)


0116+31 2024/05/04 1.36UT FUJI -KISO





T20240504103025




BLK:10,SNR1: 0.93007 ,SNR2: 9.1123




F20240504103025




BLK:10,SNR1: 0.41139 ,SNR2: 2.5312




3C43 2024/05/04 1.54UT TOYOKAWA-FUJI




T20240504103025




BLK:19,SNR1: 1.3018 ,SNR2: 12.326




K20240504103023





BLK:19,SNR1: 0.19421 ,SNR2: 2.1032




3C43 2024/05/04 1.54UT TOYOKAWA-KISO




F20240504103025




BLK: 6,SNR1: 0.46701 ,SNR2: 2.5918




K20240504103023





BLK: 6,SNR1: -0.33065E-02,SNR2: 1.4378




3C43 2024/05/04 1.54UT FUJI -KISO



T20240504103809





BLK:27,SNR1: 6.7211 ,SNR2: 18.626





3C48 2024/05/04 1.66UT TOYOKAWA-FUJI



F20240504103809




BLK:27,SNR1: 8.2004 ,SNR2: 20.603



T20240504103809





BLK:32,SNR1: 6.7804 ,SNR2: 19.027





3C48 2024/05/04 1.66UT TOYOKAWA-KISO

K20240504103807




BLK:32,SNR1: 9.0362 ,SNR2: 16.094






F20240504103809





BLK:33,SNR1: 8.1612 ,SNR2: 20.504





3C48 2024/05/04 1.66UT FUJI -KISO


K20240504103807




BLK:33,SNR1: 7.0869 ,SNR2: 18.088



T20240504105754





BLK:19,SNR1: 7.7169 ,SNR2: 19.074





0155-109 2024/05/04 1.99UT TOYOKAWA-FUJI



F20240504105754




BLK:19,SNR1: 8.1300 ,SNR2: 20.636



T20240504105754





BLK:19,SNR1: 2.5629 ,SNR2: 12.025




Frequency (Hz)

0155-109 2024/05/04 1.99UT TOYOKAWA-KISO


K20240504105751






BLK:19,SNR1: 8.2015 ,SNR2: 20.821







Frequency (Hz)





F20240504105754




K20240504105751



T20240504110501




BLK:19,SNR1: 17.127 ,SNR2: 40.101





0202+15 2024/05/04 2.11UT TOYOKAWA-FUJI



F20240504110501




BLK:19,SNR1: 4.7256 ,SNR2: 12.969



T20240504110501




BLK:24,SNR1: 16.669 ,SNR2: 39.027




0202+15 2024/05/04 2.11UT TOYOKAWA-KISO


K20240504110459




BLK:24,SNR1: 3.6738 ,SNR2: 16.318




Frequency (Hz)




F20240504110501




BLK:23,SNR1: 5.2086 ,SNR2: 14.080




K20240504110459







BLK:23,SNR1: 8.1155 ,SNR2: 15.467




0202+15 2024/05/04 2.11UT FUJI -KISO










0213+178 2024/05/04 2.31UT TOYOKAWA-FUJI









0213+178 2024/05/04 2.31UT TOYOKAWA-KISO



F20240504111651





BLK:12,SNR1: 0.72341 ,SNR2: 3.0748




Frequency (Hz)

K20240504111648





BLK:12,SNR1: 0.32694 ,SNR2: 1.6053




Frequency (Hz)

0213+178 2024/05/04 2.31UT FUJI -KISO








BLK:27,SNR1: 10.213 ,SNR2: 23.420







3C67 2024/05/04 2.44UT TOYOKAWA-FUJI




BLK:27,SNR1: 5.9612 ,SNR2: 14.764








3C67 2024/05/04 2.44UT TOYOKAWA-KISO



F20240504112434




BLK:34,SNR1: 7.8737 ,SNR2: 13.984





3C67 2024/05/04 2.44UT FUJI -KISO


K20240504112431




BLK:34,SNR1: 5.9629 ,SNR2: 14.999




T20240504114249




BLK:12,SNR1: 0.63368E-01,SNR2: 1.0143




F20240504114249





BLK:12,SNR1:-0.28040 ,SNR2: 1.1679




3C71 2024/05/04 2.74UT TOYOKAWA-FUJI



T20240504114249





BLK:11,SNR1: 0.10454 ,SNR2: 1.2879





3C71 2024/05/04 2.74UT TOYOKAWA-KISO


K20240504114246




BLK:11,SNR1: 0.30221 ,SNR2: 3.0997



F20240504114249





BLK: 4,SNR1:-0.24390 ,SNR2: 1.6394





3C71 2024/05/04 2.74UT FUJI -KISO

K20240504114246





BLK: 4,SNR1: 0.23129 ,SNR2: 2.7370







T20240504120203




BLK:17,SNR1: 1.5264 ,SNR2: 5.6837




F20240504120203





BLK:17,SNR1: 1.2824 ,SNR2: 4.3542




0258+350 2024/05/04 3.06UT TOYOKAWA-FUJI




T20240504120203




BLK:18,SNR1: 1.6390 ,SNR2: 4.4206




K20240504120200




BLK:18,SNR1: 1.1011 ,SNR2: 2.6532




0258+350 2024/05/04 3.06UT TOYOKAWA-KISO



F20240504120203




BLK:15,SNR1: 0.37745 ,SNR2: 3.1432





0258+350 2024/05/04 3.06UT FUJI -KISO



K20240504120200




BLK:15,SNR1: 1.1612 ,SNR2: 3.1885




T20240504121153




BLK:19,SNR1: 2.2816 ,SNR2: 5.7182




F20240504121153




BLK:19,SNR1: 7.9357 ,SNR2: 14.163




0308+305 2024/05/04 3.23UT TOYOKAWA-FUJI




T20240504121153




BLK:25,SNR1: 1.8195 ,SNR2: 4.4258




K20240504121150





BLK:25,SNR1: 7.8575 ,SNR2: 19.459




0308+305 2024/05/04 3.23UT TOYOKAWA-KISO





F20240504121153




BLK:26,SNR1: 7.3923 ,SNR2: 13.204




K20240504121150





BLK:26,SNR1: 7.7987 ,SNR2: 19.314




0308+305 2024/05/04 3.23UT FUJI -KISO





T20240504122325




BLK:16,SNR1: 2.6712 ,SNR2: 11.573




F20240504122326





BLK:16,SNR1: 7.0603 ,SNR2: 17.221




0320+05 2024/05/04 3.42UT TOYOKAWA-FUJI





T20240504122325




BLK:21,SNR1: 4.3279 ,SNR2: 9.4763




K20240504122322



BLK:21,SNR1: 1.9371 ,SNR2: 9.1079




0320+05 2024/05/04 3.42UT TOYOKAWA-KISO







F20240504122326




BLK:25,SNR1: 9.8122 ,SNR2: 23.662




K20240504122322





BLK:25,SNR1: 3.3607 ,SNR2: 12.288




0320+05 2024/05/04 3.42UT FUJI -KISO





T20240504123645




BLK: 4,SNR1: 0.19877 ,SNR2: 1.4380




F20240504123645





BLK: 4,SNR1:-0.18412 ,SNR2: 1.3562




0333+32 2024/05/04 3.64UT TOYOKAWA-FUJI





T20240504123645




BLK: 7,SNR1: 0.33726 ,SNR2: 3.4520




K20240504123642




BLK: 7,SNR1: 0.25480 ,SNR2: 1.5815




0333+32 2024/05/04 3.64UT TOYOKAWA-KISO



F20240504123645





BLK:11,SNR1:-0.98255E-01,SNR2: 2.5802





0333+32 2024/05/04 3.64UT FUJI -KISO



K20240504123642




BLK:11,SNR1: 0.54391 ,SNR2: 3.1344





T20240504124947




BLK: 6,SNR1: 0.76771E-01,SNR2: 1.4353




F20240504124947





BLK: 6,SNR1: 0.23550 ,SNR2: 1.5120




0347+05 2024/05/04 3.86UT TOYOKAWA-FUJI





T20240504124947




BLK:11,SNR1: 0.60525E-01,SNR2: 0.61438




K20240504124944





BLK:11,SNR1: 0.93875 ,SNR2: 4.2837




0347+05 2024/05/04 3.86UT TOYOKAWA-KISO





F20240504124947




BLK: 9,SNR1: 0.21989 ,SNR2: 1.8536




K20240504124944




BLK: 9,SNR1: 0.52651 ,SNR2: 1.8205




0347+05 2024/05/04 3.86UT FUJI -KISO




T20240504130522




BLK:24,SNR1: 6.8202 ,SNR2: 16.826




F20240504130523



BLK:24,SNR1: 4.4223 ,SNR2: 10.604





0403-132 2024/05/04 4.12UT TOYOKAWA-FUJI








T20240504130522




BLK:29,SNR1: 6.4208 ,SNR2: 15.828




K20240504130519




BLK:29,SNR1: 7.5685 ,SNR2: 19.019




0403-132 2024/05/04 4.12UT TOYOKAWA-KISO





F20240504130523




BLK:30,SNR1: 4.1557 ,SNR2: 9.9845




K20240504130519





BLK:30,SNR1: 7.6195 ,SNR2: 19.146




0403-132 2024/05/04 4.12UT FUJI -KISO





T20240504131432




BLK:15,SNR1: 1.1781 ,SNR2: 2.1565




F20240504131432





BLK:15,SNR1: 0.34366 ,SNR2: 4.0028




0411+05 2024/05/04 4.27UT TOYOKAWA-FUJI





T20240504131432




BLK:14,SNR1: 0.46234 ,SNR2: 3.8802




K20240504131429




BLK:14,SNR1: 2.9879 ,SNR2: 11.068




0411+05 2024/05/04 4.27UT TOYOKAWA-KISO




F20240504131432




BLK:10,SNR1: 1.0855 ,SNR2: 2.4588




K20240504131429





BLK:10,SNR1: 2.0720 ,SNR2: 9.3793




0411+05 2024/05/04 4.27UT FUJI -KISO




T20240504132525




BLK: 6,SNR1: 0.18423 ,SNR2: 0.69888




F20240504132526





BLK: 6,SNR1: 0.52372 ,SNR2: 3.4338




0422+178 2024/05/04 4.45UT TOYOKAWA-FUJI





T20240504132525




BLK: 5,SNR1: 0.13144 ,SNR2: 0.84727




K20240504132522




BLK: 5,SNR1: 26.542 ,SNR2: 49.497




0422+178 2024/05/04 4.45UT TOYOKAWA-KISO





F20240504132526




BLK:12,SNR1: 0.59547E-01,SNR2: 1.8300




K20240504132522



BLK:12,SNR1: 1.6264 ,SNR2: 8.2005





0422+178 2024/05/04 4.45UT FUJI -KISO







T20240504133301




BLK: 8,SNR1: 0.56715 ,SNR2: 10.096




F20240504133301




BLK: 8,SNR1: 0.51280 ,SNR2: 1.7915




3C120 2024/05/04 4.58UT TOYOKAWA-FUJI





T20240504133301




BLK: 9,SNR1: 0.28961 ,SNR2: 1.2078




K20240504133258




BLK: 9,SNR1: 0.29015 ,SNR2: 1.4821




3C120 2024/05/04 4.58UT TOYOKAWA-KISO





F20240504133301




BLK:12,SNR1: 0.21537 ,SNR2: 2.6092




K20240504133258





BLK:12,SNR1: 0.10651 ,SNR2: 0.42560




3C120 2024/05/04 4.58UT FUJI -KISO




T20240504142101




BLK:10,SNR1: 0.79863 ,SNR2: 7.1445




F20240504142101





BLK:10,SNR1:-0.94947E-01,SNR2: 1.6544




3C138 2024/05/04 5.38UT TOYOKAWA-FUJI





T20240504142101




BLK:14,SNR1: 0.95199 ,SNR2: 7.1697




K20240504142058




BLK:14,SNR1: 0.54491 ,SNR2: 1.7363




3C138 2024/05/04 5.38UT TOYOKAWA-KISO





F20240504142101




BLK:10,SNR1: 0.57241 ,SNR2: 5.5071




K20240504142058





BLK:10,SNR1: 0.17099 ,SNR2: 0.63041




3C138 2024/05/04 5.38UT FUJI -KISO





T20240504143435




BLK:13,SNR1: 0.90694 ,SNR2: 5.5588




F20240504143435





BLK:13,SNR1: 0.10586 ,SNR2: 1.6633




0531+194 2024/05/04 5.60UT TOYOKAWA-FUJI





T20240504143435




BLK:23,SNR1: 0.84515 ,SNR2: 5.0044




K20240504143433



BLK:23,SNR1: 0.51266 ,SNR2: 2.2303





0531+194 2024/05/04 5.60UT TOYOKAWA-KISO








F20240504143435




BLK:17,SNR1: 0.12228 ,SNR2: 2.6150




K20240504143433




BLK:17,SNR1: 0.62646 ,SNR2: 2.6626




0531+194 2024/05/04 5.60UT FUJI -KISO




T20240504144254




BLK:17,SNR1: 3.8041 ,SNR2: 11.999




F20240504144254




BLK:17,SNR1:-0.26947 ,SNR2: 1.5090




3C147 2024/05/04 5.74UT TOYOKAWA-FUJI





T20240504144254




BLK:24,SNR1: 3.2042 ,SNR2: 12.420




K20240504144252





BLK:24,SNR1: 0.33238 ,SNR2: 2.1530




3C147 2024/05/04 5.74UT TOYOKAWA-KISO





F20240504144254




BLK:17,SNR1:-0.27422 ,SNR2: 1.3267




K20240504144252





BLK:17,SNR1: 0.47869 ,SNR2: 1.3336




3C147 2024/05/04 5.74UT FUJI -KISO



T20240504145106




BLK: 4,SNR1: 0.19684 ,SNR2: 1.1209




Frequency (Hz)

F20240504145106




BLK: 4,SNR1:-0.11269 ,SNR2: 1.4257





Frequency (Hz)


0548+16 2024/05/04 5.88UT TOYOKAWA-FUJI





T20240504145106




BLK: 7,SNR1: 0.62470E-01,SNR2: 0.65286




K20240504145103





BLK: 7,SNR1: 0.26585 ,SNR2: 1.6626




0548+16 2024/05/04 5.88UT TOYOKAWA-KISO



F20240504145106





BLK: 8,SNR1: 2.4760 ,SNR2: 7.4512




Frequency (Hz)

K20240504145103




BLK: 8,SNR1: 0.26934 ,SNR2: 1.2241




Frequency (Hz)


0548+16 2024/05/04 5.88UT FUJI -KISO




T20240504145516




BLK: 4,SNR1: 7.7006 ,SNR2: 54.647




F20240504145516



BLK: 4,SNR1:-0.13342 ,SNR2: 0.78908




0552+12 2024/05/04 5.95UT TOYOKAWA-FUJI








T20240504145516




BLK: 4,SNR1: 0.39925 ,SNR2: 3.6881




K20240504145513





BLK: 4,SNR1: 1.5785 ,SNR2: 6.1584




0552+12 2024/05/04 5.95UT TOYOKAWA-KISO



F20240504145516





No.Good Data




Frequency (Hz)

K20240504145513




No.Good Data





Frequency (Hz)


0552+12 2024/05/04 5.95UT FUJI -KISO



T20240504145943





BLK: 8,SNR1: 0.29004E-01,SNR2: 0.75763




Frequency (Hz)

F20240504145943




BLK: 8,SNR1: 0.10205 ,SNR2: 1.6006





Frequency (Hz)


0556+191 2024/05/04 6.02UT TOYOKAWA-FUJI





T20240504145943




BLK: 8,SNR1: 0.61419E-01,SNR2: 0.86276




K20240504145940





BLK: 8,SNR1: 0.25942 ,SNR2: 2.1531




0556+191 2024/05/04 6.02UT TOYOKAWA-KISO



F20240504145943





BLK:12,SNR1: 0.27510 ,SNR2: 2.0721




Frequency (Hz)

K20240504145940




BLK:12,SNR1: 0.56969 ,SNR2: 2.0692





Frequency (Hz)


0556+191 2024/05/04 6.02UT FUJI -KISO




T20240504150416




BLK: 5,SNR1: 0.17383 ,SNR2: 1.7110




F20240504150416





BLK: 5,SNR1:-0.10833 ,SNR2: 1.8824




3C152 2024/05/04 6.10UT TOYOKAWA-FUJI



T20240504150416





BLK: 3,SNR1: 0.10252 ,SNR2: 0.42504




Frequency (Hz)

K20240504150413




BLK: 3,SNR1: 0.22160 ,SNR2: 1.4730





Frequency (Hz)


3C152 2024/05/04 6.10UT TOYOKAWA-KISO



F20240504150416





BLK: 3,SNR1: 0.75551 ,SNR2: 3.3402




Frequency (Hz)

K20240504150413




BLK: 3,SNR1: 0.13541 ,SNR2: 1.1761





Frequency (Hz)

3C152 2024/05/04 6.10UT FUJI -KISO






T20240504152637




BLK: 8,SNR1: 0.80725 ,SNR2: 6.6597




Frequency (Hz)

F20240504152637




BLK: 8,SNR1:-0.38124 ,SNR2: 0.0000





Frequency (Hz)


3C161 2024/05/04 6.47UT TOYOKAWA-FUJI



T20240504152637




BLK:17,SNR1: 1.1884 ,SNR2: 7.9468




Frequency (Hz)

K20240504152635




BLK:17,SNR1: 0.20234 ,SNR2: 2.6738




Frequency (Hz)


3C161 2024/05/04 6.47UT TOYOKAWA-KISO





F20240504152637




BLK: 7,SNR1:-0.30110 ,SNR2: 1.1383




K20240504152635





BLK: 7,SNR1: 0.68528E-01,SNR2: 1.8981




3C161 2024/05/04 6.47UT FUJI -KISO



T20240504155410




BLK: 4,SNR1: 0.22419 ,SNR2: 1.2465




Frequency (Hz)

F20240504155411




BLK: 4,SNR1: 0.55641 ,SNR2: 2.2472





Frequency (Hz)


0652-130 2024/05/04 6.93UT TOYOKAWA-FUJI





T20240504155410




BLK: 4,SNR1: 0.10373 ,SNR2: 1.0095




K20240504155407







BLK: 4,SNR1: 1.7738 ,SNR2: 14.025




0652-130 2024/05/04 6.93UT TOYOKAWA-KISO








0652-130 2024/05/04 6.93UT FUJI -KISO





T20240504160546




BLK: 9,SNR1: 4.5251 ,SNR2: 17.624




F20240504160546





BLK: 9,SNR1: 0.30026 ,SNR2: 4.1378




0703+138 2024/05/04 7.12UT TOYOKAWA-FUJI





T20240504160546




BLK:12,SNR1: 4.0103 ,SNR2: 12.782




K20240504160543



BLK:12,SNR1: 1.3309 ,SNR2: 6.1669





0703+138 2024/05/04 7.12UT TOYOKAWA-KISO








F20240504160546




BLK: 9,SNR1: 0.13939 ,SNR2: 1.9977




K20240504160543





BLK: 9,SNR1: 0.85544 ,SNR2: 4.3259




0703+138 2024/05/04 7.12UT FUJI -KISO




T20240504161509




BLK: 4,SNR1: 0.13887 ,SNR2: 0.82304




F20240504161510





BLK: 4,SNR1: 3.0060 ,SNR2: 4.3651




0713-024 2024/05/04 7.28UT TOYOKAWA-FUJI





T20240504161509




BLK: 3,SNR1: 0.44808E-01,SNR2: 0.60547




K20240504161506




BLK: 3,SNR1: 0.94451 ,SNR2: 4.0673




0713-024 2024/05/04 7.28UT TOYOKAWA-KISO



F20240504161510





BLK: 5,SNR1:-0.25780 ,SNR2: 0.84625




Frequency (Hz)

K20240504161506




BLK: 5,SNR1: 0.69797E-01,SNR2: 1.6002





Frequency (Hz)


0713-024 2024/05/04 7.28UT FUJI -KISO



T20240504162521





BLK: 6,SNR1: 0.48444 ,SNR2: 3.7047




Frequency (Hz)

F20240504162521




BLK: 6,SNR1: 0.19816E-01,SNR2: 2.4969





Frequency (Hz)


0723+10 2024/05/04 7.45UT TOYOKAWA-FUJI



T20240504162521




BLK: 5,SNR1: 0.77733 ,SNR2: 4.9420




Frequency (Hz)

K20240504162518




BLK: 5,SNR1: 0.77675 ,SNR2: 3.1229





Frequency (Hz)


0723+10 2024/05/04 7.45UT TOYOKAWA-KISO



F20240504162521





BLK: 4,SNR1: 0.14599 ,SNR2: 2.6548




Frequency (Hz)

K20240504162518




BLK: 4,SNR1: 0.60819E-01,SNR2: 0.42942




Frequency (Hz)


0723+10 2024/05/04 7.45UT FUJI -KISO



T20240504163535




BLK: 3,SNR1: 0.36770 ,SNR2: 0.48486




Frequency (Hz)

F20240504163536




BLK: 3,SNR1: 0.55230 ,SNR2: 3.7349





Frequency (Hz)

0732+33 2024/05/04 7.62UT TOYOKAWA-FUJI








T20240504163535




BLK: 3,SNR1: 0.64299E-01,SNR2: 0.41062




K20240504163532





BLK: 3,SNR1: 1.9562 ,SNR2: 8.2241




0732+33 2024/05/04 7.62UT TOYOKAWA-KISO





F20240504163536




BLK: 5,SNR1:-0.83076E-01,SNR2: 1.5808




K20240504163532





BLK: 5,SNR1: 0.50974 ,SNR2: 2.2296




0732+33 2024/05/04 7.62UT FUJI -KISO



T20240504164337




BLK: 6,SNR1: 0.14914 ,SNR2: 3.4017




Frequency (Hz)

F20240504164337




BLK: 6,SNR1:-0.11068 ,SNR2: 2.4087





Frequency (Hz)


0741-06 2024/05/04 7.76UT TOYOKAWA-FUJI



T20240504164337





BLK:14,SNR1: 0.34307 ,SNR2: 2.8721




Frequency (Hz)

K20240504164334




BLK:14,SNR1: 0.52208 ,SNR2: 3.4486




Frequency (Hz)


0741-06 2024/05/04 7.76UT TOYOKAWA-KISO



F20240504164337





BLK: 8,SNR1: 0.78150E-01,SNR2: 2.3466




Frequency (Hz)

K20240504164334




BLK: 8,SNR1: 0.56290 ,SNR2: 3.8489





Frequency (Hz)


0741-06 2024/05/04 7.76UT FUJI -KISO



T20240504170056





BLK: 7,SNR1: 0.41239E-02,SNR2: 0.32420




Frequency (Hz)

F20240504170056




BLK: 7,SNR1:-0.22409 ,SNR2: 1.6310





Frequency (Hz)


3C190 2024/05/04 8.04UT TOYOKAWA-FUJI



T20240504170056





BLK: 4, SNR1: 0.23258 , SNR2: 1.7241




Frequency (Hz)

K20240504170053








BLK: 4, SNR1: 0.73834 , SNR2: 3.7556




Frequency (Hz)

3C190 2024/05/04 8.04UT TOYOKAWA-KISO







3C190 2024/05/04 8.04UT FUJI -KISO






T20240504171321




BLK:11,SNR1: 0.12911 ,SNR2: 1.4948




Frequency (Hz)

F20240504171322




BLK:11,SNR1: 3.1840 ,SNR2: 11.000





Frequency (Hz)


3C196 2024/05/04 8.25UT TOYOKAWA-FUJI



T20240504171321





BLK: 9,SNR1: 0.42390E-01,SNR2: 1.1326




Frequency (Hz)

K20240504171318




BLK: 9,SNR1: 73.331 ,SNR2: 68.921





Frequency (Hz)


3C196 2024/05/04 8.25UT TOYOKAWA-KISO



F20240504171322





BLK: 8,SNR1: 0.21862 ,SNR2: 2.4001




Frequency (Hz)

K20240504171318




BLK: 8,SNR1: 1.0096 ,SNR2: 5.0676





Frequency (Hz)


3C196 2024/05/04 8.25UT FUJI -KISO



T20240504172431





BLK:11,SNR1: 0.60434E-01,SNR2: 1.9318




Frequency (Hz)

F20240504172431




BLK:11,SNR1: 0.32055 ,SNR2: 2.5827




Frequency (Hz)


0821+394 2024/05/04 8.44UT TOYOKAWA-FUJI



T20240504172431





BLK: 8,SNR1: 0.79887E-01,SNR2: 1.2135




Frequency (Hz)

K20240504172428




BLK: 8,SNR1: 96.760 ,SNR2: 91.790





Frequency (Hz)


0821+394 2024/05/04 8.44UT TOYOKAWA-KISO



F20240504172431





BLK: 6,SNR1: 0.75337E-01,SNR2: 1.2846




Frequency (Hz)

K20240504172428




BLK: 6,SNR1: 1.6781 ,SNR2: 9.4834





Frequency (Hz)


0821+394 2024/05/04 8.44UT FUJI -KISO



T20240504174303




BLK: 3,SNR1: 1.4238 ,SNR2: 7.8972




Frequency (Hz)

F20240504174304




BLK: 3,SNR1: 0.44762 ,SNR2: 1.7439





Frequency (Hz)


0840+424 2024/05/04 8.75UT TOYOKAWA-FUJI



T20240504174303





BLK: 6,SNR1: 6.6218 ,SNR2: 39.211




Frequency (Hz)

K20240504174300




BLK: 6,SNR1: 90.338 ,SNR2: 87.748





Frequency (Hz)

0840+424 2024/05/04 8.75UT TOYOKAWA-KISO






F20240504174304





BLK: 4,SNR1:-0.18475 ,SNR2: 1.5127




Frequency (Hz)

K20240504174300



BLK: 4,SNR1: 78.541 ,SNR2: 75.925



Frequency (Hz)

0840+424 2024/05/04 8.75UT FUJI -KISO

