



T20240509055457




BLK: 9,SNR1: 3.4164 ,SNR2: 18.284




Frequency (Hz)

F20240509055457




BLK: 9,SNR1: 2.9882 ,SNR2: 13.178





Frequency (Hz)


2111+301 2024/05/08 20.94UT TOYOKAWA-FUJI



T20240509055457





BLK:11,SNR1: 3.5688 ,SNR2: 42.639




Frequency (Hz)

K20240509055454




BLK:11,SNR1: 4.3368 ,SNR2: 7.8497





Frequency (Hz)


2111+301 2024/05/08 20.94UT TOYOKAWA-KISO



F20240509055457





BLK:17,SNR1: 2.8626 ,SNR2: 12.630




Frequency (Hz)

K20240509055454




BLK:17,SNR1: 3.9032 ,SNR2: 6.9647




Frequency (Hz)


2111+301 2024/05/08 20.94UT FUJI -KISO



T20240509060808




BLK: 3,SNR1: 0.15908 ,SNR2: 1.5584




Frequency (Hz)

F20240509060808




BLK: 3,SNR1: 0.12112 ,SNR2: 1.4209





Frequency (Hz)


2124+349 2024/05/08 21.16UT TOYOKAWA-FUJI



T20240509060808





BLK: 3,SNR1: 0.99350E-01,SNR2: 0.32218




Frequency (Hz)

K20240509060805




BLK: 3,SNR1: 2.6607 ,SNR2: 8.3658





Frequency (Hz)


2124+349 2024/05/08 21.16UT TOYOKAWA-KISO



F20240509060808





BLK: 6,SNR1: 0.49889 ,SNR2: 4.5803




Frequency (Hz)

K20240509060805




BLK: 6,SNR1: 2.4398 ,SNR2: 8.6012





Frequency (Hz)


2124+349 2024/05/08 21.16UT FUJI -KISO



T20240509061457





BLK: 6,SNR1: 0.22619 ,SNR2: 2.5645




Frequency (Hz)

F20240509061457




BLK: 6,SNR1: 0.82881 ,SNR2: 1.9433





Frequency (Hz)


2131+379 2024/05/08 21.28UT TOYOKAWA-FUJI



T20240509061457




BLK: 6,SNR1: 0.34125 ,SNR2: 3.4077




Frequency (Hz)

K20240509061454




BLK: 6,SNR1: 1.5748 ,SNR2: 6.8416





Frequency (Hz)

2131+379 2024/05/08 21.28UT TOYOKAWA-KISO








F20240509061457




BLK:11,SNR1: 0.65528 ,SNR2: 1.8207




K20240509061454





BLK:11,SNR1: 3.2460 ,SNR2: 7.8694




2131+379 2024/05/08 21.28UT FUJI -KISO





T20240509063135




BLK: 4,SNR1: 0.11305 ,SNR2: 0.97122




F20240509063135





BLK: 4,SNR1: 0.32273 ,SNR2: 3.5686




2147+145 2024/05/08 21.55UT TOYOKAWA-FUJI



T20240509063135





BLK: 6,SNR1: 0.84842E-01,SNR2: 0.66124




Frequency (Hz)

K20240509063132




BLK: 6,SNR1: 1.6226 ,SNR2: 5.9003




Frequency (Hz)


2147+145 2024/05/08 21.55UT TOYOKAWA-KISO



F20240509063135





BLK:11,SNR1: 0.29077 ,SNR2: 2.1416




Frequency (Hz)

K20240509063132




BLK:11,SNR1: 0.30675 ,SNR2: 2.6022





Frequency (Hz)


2147+145 2024/05/08 21:55UT FUJI -KISO



T20240509064039





BLK:33,SNR1: 7.6195 ,SNR2: 9.9832




Frequency (Hz)

F20240509064040




BLK:33,SNR1: 2.5210 ,SNR2: 7.8817





Frequency (Hz)


2156-043 2024/05/08 21.71UT TOYOKAWA-FUJI



T20240509064039





BLK:31,SNR1: 4.8708 ,SNR2: 8.6664




Frequency (Hz)

K20240509064036




BLK:31,SNR1: 3.0621 ,SNR2: 4.8698




Frequency (Hz)


2156-043 2024/05/08 21.71UT TOYOKAWA-KISO



F20240509064040





BLK:32,SNR1: 2.5875 ,SNR2: 6.2735




Frequency (Hz)

2156-043 2024/05/08 21.71UT FUJI -KISO


K20240509064036




BLK:32,SNR1: 2.6274 ,SNR2: 5.1369




Frequency (Hz)



T20240509065350




BLK:35,SNR1: 11.908 ,SNR2: 21.618




Frequency (Hz)

F20240509065351




BLK:35,SNR1: 1.5457 ,SNR2: 4.6840




Frequency (Hz)

2210+016 2024/05/08 21.93UT TOYOKAWA-FUJI






T20240509065350





BLK:37,SNR1: 12.207 ,SNR2: 21.963




Frequency (Hz)

K20240509065347




BLK:37,SNR1: 1.9848 ,SNR2: 6.9722





Frequency (Hz)


2210+016 2024/05/08 21.93UT TOYOKAWA-KISO





F20240509065351




BLK:38,SNR1: 1.5160 ,SNR2: 4.1655




K20240509065347




BLK:38,SNR1: 1.9664 ,SNR2: 7.0372




2210+016 2024/05/08 21.93UT FUJI -KISO



T20240509070114




BLK:35,SNR1: 26.147 ,SNR2: 28.382




Frequency (Hz)

F20240509070114




BLK:35,SNR1: 25.514 ,SNR2: 32.779




Frequency (Hz)


2217+128 2024/05/08 22.05UT TOYOKAWA-FUJI



T20240509070114





BLK:37,SNR1: 28.849 ,SNR2: 31.488




Frequency (Hz)

K20240509070111




BLK:37,SNR1: 17.896 ,SNR2: 16.827





Frequency (Hz)


2217+128 2024/05/08 22.05UT TOYOKAWA-KISO



F20240509070114





BLK:38,SNR1: 26.447 ,SNR2: 34.194




Frequency (Hz)

K20240509070111




BLK:38,SNR1: 17.386 ,SNR2: 16.348





Frequency (Hz)


2217+128 2024/05/08 22.05UT FUJI -KISO



T20240509070700





BLK:39,SNR1: 118.59 ,SNR2: 153.34




Frequency (Hz)

3C446 2024/05/08 22.14UT TOYOKAWA-FUJI


F20240509070701





BLK:39,SNR1: 189.50 ,SNR2: 223.65




Frequency (Hz)



T20240509070700





BLK:38,SNR1: 120.73 ,SNR2: 156.11




Frequency (Hz)

3C446 2024/05/08 22.14UT TOYOKAWA-KISO


K20240509070657





BLK:38,SNR1: 67.920 ,SNR2: 72.185




Frequency (Hz)



F20240509070701





BLK:39,SNR1: 189.50 ,SNR2: 223.65




Frequency (Hz)

K20240509070657




BLK:39,SNR1: 60.454 ,SNR2: 65.985





Frequency (Hz)

3C446 2024/05/08 22.14UT FUJI -KISO






T20240509071343





BLK:29,SNR1: 1.5970 ,SNR2: 3.1651




Frequency (Hz)

F20240509071344




BLK:29,SNR1: 3.7287 ,SNR2: 8.2550




Frequency (Hz)


2229-093 2024/05/08 22.26UT TOYOKAWA-FUJI



T20240509071343




BLK:30,SNR1: 1.5369 ,SNR2: 3.0554




Frequency (Hz)

K20240509071340




BLK:30,SNR1: 4.0967 ,SNR2: 10.272





Frequency (Hz)


2229-093 2024/05/08 22.26UT TOYOKAWA-KISO



F20240509071344





BLK:29,SNR1: 2.8384 ,SNR2: 11.088




Frequency (Hz)

K20240509071340




BLK:29,SNR1: 3.7761 ,SNR2: 9.4602





Frequency (Hz)


2229-093 2024/05/08 22.26UT FUJI -KISO



T20240509072211





BLK:18,SNR1: 6.6287 ,SNR2: 19.320




Frequency (Hz)

F20240509072212




BLK:18,SNR1: 0.63839 ,SNR2: 7.2305





Frequency (Hz)


2238-113 2024/05/08 22.40UT TOYOKAWA-FUJI



T20240509072211





BLK:24,SNR1: 6.5470 ,SNR2: 25.110




Frequency (Hz)

K20240509072208




BLK:24,SNR1: 1.9107 ,SNR2: 3.7486





Frequency (Hz)


2238-113 2024/05/08 22.40UT TOYOKAWA-KISO



F20240509072212





BLK:25,SNR1: 1.6760 ,SNR2: 8.0982




Frequency (Hz)

K20240509072208




BLK:25,SNR1: 3.6822 ,SNR2: 7.1158





Frequency (Hz)


2238-113 2024/05/08 22.40UT FUJI -KISO



T20240509073500





BLK:34,SNR1: 2.0907 ,SNR2: 9.3461




Frequency (Hz)

F20240509073501




BLK:34,SNR1: 5.4164 ,SNR2: 9.6233





Frequency (Hz)


3C454.3 2024/05/08 22.61UT TOYOKAWA-FUJI



T20240509073500





BLK:31,SNR1: 2.1620 ,SNR2: 9.6412




Frequency (Hz)

3C454.3 2024/05/08 22.61UT TOYOKAWA-KISO


K20240509073457



BLK:31,SNR1: 7.9104 ,SNR2: 19.647




Frequency (Hz)






F20240509073501




BLK:35,SNR1: 4.8095 ,SNR2: 8.4231




Frequency (Hz)

K20240509073457




BLK:35,SNR1: 7.8752 ,SNR2: 21.949




Frequency (Hz)


3C454.3 2024/05/08 22.61UT FUJI -KISO



T20240509074242





BLK:36,SNR1: 9.4546 ,SNR2: 14.420




Frequency (Hz)

F20240509074243




BLK:36,SNR1: 5.3366 ,SNR2: 11.113




Frequency (Hz)


2259+481 2024/05/08 22.74UT TOYOKAWA-FUJI



T20240509074242




BLK:33,SNR1: 9.4929 ,SNR2: 14.370




Frequency (Hz)

K20240509074239




BLK:33,SNR1: 19.186 ,SNR2: 26.677




Frequency (Hz)


2259+481 2024/05/08 22.74UT TOYOKAWA-KISO




F20240509074243




BLK:33,SNR1: 7.0373 ,SNR2: 12.482




K20240509074239




BLK:33,SNR1: 13.361 ,SNR2: 21.525




2259+481 2024/05/08 22.74UT FUJI -KISO



T20240509075736




BLK:28,SNR1: 14.724 ,SNR2: 22.529





3C459 2024/05/08 22.99UT TOYOKAWA-FUJI


F20240509075736




BLK:28,SNR1: 4.9151 ,SNR2: 8.9097



T20240509075736




BLK:29,SNR1: 16.016 ,SNR2: 30.043





3C459 2024/05/08 22.99UT TOYOKAWA-KISO



K20240509075733




BLK:29,SNR1: 8.5343 ,SNR2: 21.345



F20240509075736





BLK:25,SNR1: 3.9359 ,SNR2: 7.1622




Frequency (Hz)

3C459 2024/05/08 22.99UT FUJI -KISO


K20240509075733





BLK:25,SNR1: 7.4061 ,SNR2: 18.517




Frequency (Hz)



T20240509083121





BLK:31,SNR1: 2.7731 ,SNR2: 13.222




Frequency (Hz)

F20240509083121




BLK:31,SNR1: 7.7153 ,SNR2: 13.699





Frequency (Hz)

2347-02 2024/05/08 23.55UT TOYOKAWA-FUJI






T20240509083121





BLK:32,SNR1: 2.8152 ,SNR2: 13.387




Frequency (Hz)

2347-02 2024/05/08 23.55UT TOYOKAWA-KISO


K20240509083118




BLK:32,SNR1: 7.4990 ,SNR2: 13.368




Frequency (Hz)





F20240509083121




BLK:30,SNR1: 4.9335 ,SNR2: 12.479




K20240509083118




BLK:30,SNR1: 13.581 ,SNR2: 24.014




2347-02 2024/05/08 23.55UT FUJI -KISO





T20240509083814




BLK:28,SNR1: 0.99896 ,SNR2: 1.9808




F20240509083815





BLK:28,SNR1: 5.6664 ,SNR2: 8.0674




2354+14 2024/05/08 23.67UT TOYOKAWA-FUJI



T20240509083814




BLK:20,SNR1: 0.89976 ,SNR2: 2.3154





2354+14 2024/05/08 23.67UT TOYOKAWA-KISO



K20240509083811




BLK:20,SNR1: 7.6236 ,SNR2: 14.634




F20240509083815




BLK:27,SNR1: 4.8326 ,SNR2: 6.7917




K20240509083811





BLK:27,SNR1: 11.333 ,SNR2: 18.558




2354+14 2024/05/08 23.67UT FUJI -KISO



T20240509084717




BLK:16,SNR1: 4.1008 ,SNR2: 9.8012





3C2 2024/05/08 23.82UT TOYOKAWA-FUJI



F20240509084717




BLK:16,SNR1: 2.7146 ,SNR2: 6.8305



T20240509084717




BLK:25,SNR1: 7.9005 ,SNR2: 15.323





3C2 2024/05/08 23.82UT TOYOKAWA-KISO


K20240509084714




BLK:25,SNR1: 8.6794 ,SNR2: 21.293





F20240509084717




BLK:20,SNR1: 3.9786 ,SNR2: 9.8111




K20240509084714



BLK:20,SNR1: 8.5171 ,SNR2: 20.949





3C2 2024/05/08 23.82UT FUJI -KISO






T20240509085404





BLK:30,SNR1: 2.7157 ,SNR2: 13.052





0010+005 2024/05/08 23.93UT TOYOKAWA-FUJI



F20240509085405




BLK:30,SNR1: 2.8451 ,SNR2: 13.541



T20240509085404





BLK:23,SNR1: 2.7184 ,SNR2: 13.063





0010+005 2024/05/08 23.93UT TOYOKAWA-KISO



K20240509085401




BLK:23,SNR1: 8.5473 ,SNR2: 21.664





F20240509085405




BLK:29,SNR1: 2.8817 ,SNR2: 13.687




K20240509085401






BLK:29,SNR1: 8.5150 ,SNR2: 21.572



0010+005 2024/05/08 23.93UT FUJI -KISO






T20240509090315





0019-00 2024/05/09 0.08UT TOYOKAWA-FUJI


F20240509090316



T20240509090315




BLK:19,SNR1: 15.368 ,SNR2: 29.624





0019-00 2024/05/09 0.08UT TOYOKAWA-KISO



K20240509090312




BLK:19,SNR1: 3.9326 ,SNR2: 9.2421




F20240509090316




BLK:27,SNR1: 4.5405 ,SNR2: 9.3173




K20240509090312





BLK:27,SNR1: 3.4195 ,SNR2: 8.1988




0019-00 2024/05/09 08UT FUJI -KISO




T20240509091330




BLK:28,SNR1: 0.77309 ,SNR2: 3.5502




F20240509091331





BLK:28,SNR1: 10.883 ,SNR2: 18.885




3C12 2024/05/09 0.25UT TOYOKAWA-FUJI




T20240509091330




BLK:24,SNR1: 1.2943 ,SNR2: 4.2574




K20240509091327



BLK:24,SNR1: 87.727 ,SNR2: 87.730




3C12 2024/05/09 0.25UT TOYOKAWA-KISO







F20240509091331




BLK:29,SNR1: 13.928 ,SNR2: 23.963




K20240509091327




BLK:29,SNR1: 78.461 ,SNR2: 78.464




3C12 2024/05/09 0.25UT FUJI -KISO





T20240509092731




BLK:12,SNR1: 3.7995 ,SNR2: 9.4604




F20240509092731





BLK:12,SNR1: 0.26916E-01,SNR2: 2.3312




0044-056 2024/05/09 0.49UT TOYOKAWA-FUJI



T20240509092731





BLK:17,SNR1: 4.5315 ,SNR2: 11.252





0044-056 2024/05/09 0.49UT TOYOKAWA-KISO


K20240509092728




BLK:17,SNR1: 2.6754 ,SNR2: 6.6518





F20240509092731




BLK:23,SNR1: 1.2618 ,SNR2: 3.6294




K20240509092728





BLK:23,SNR1: 4.7050 ,SNR2: 11.799




0044-056 2024/05/09 0.49UT FUJI -KISO



T20240509093453





BLK:22,SNR1: 4.1608 ,SNR2: 10.286





3C26 2024/05/09 0.61UT TOYOKAWA-FUJI



F20240509093453




BLK:22,SNR1: 19.178 ,SNR2: 75.807



T20240509093453





BLK:22,SNR1: 4.0614 ,SNR2: 15.328





3C26 2024/05/09 0.61UT TOYOKAWA-KISO


K20240509093450




BLK:22,SNR1: 79.468 ,SNR2: 212.33



F20240509093453





BLK:30,SNR1: 20.616 ,SNR2: 46.107





3C26 2024/05/09 0.61UT FUJI -KISO


K20240509093450




BLK:30,SNR1: 61.258 ,SNR2: 165.84



T20240509093951





BLK:27,SNR1: 0.58772 ,SNR2: 3.0137





0056-00 2024/05/09 0.69UT TOYOKAWA-FUJI

F20240509093952




BLK:27,SNR1: 0.72795 ,SNR2: 2.7548






T20240509093951





BLK:21,SNR1: 0.59592 ,SNR2: 2.9500





0056-00 2024/05/09 0.69UT TOYOKAWA-KISO


K20240509093948




BLK:21,SNR1: 0.94213 ,SNR2: 3.9356





F20240509093952




BLK:25,SNR1: 2.0162 ,SNR2: 2.0683




K20240509093948





BLK:25,SNR1: 2.9808 ,SNR2: 3.6119




0056-00 2024/05/09 0.69UT FUJI -KISO



T20240509094934





BLK: 6,SNR1: 0.45520 ,SNR2: 2.1977





0106+01 2024/05/09 0.85UT TOYOKAWA-FUJI



F20240509094934




BLK: 6,SNR1: 0.11807 ,SNR2: 0.95429




T20240509094934




BLK:13,SNR1: 0.70144 ,SNR2: 1.4936




K20240509094931





BLK:13,SNR1: 0.75070 ,SNR2: 3.4611




0106+01 2024/05/09 0.85UT TOYOKAWA-KISO




F20240509094934




BLK:19,SNR1: 0.66872 ,SNR2: 1.8336




K20240509094931




BLK:19,SNR1: 0.94631 ,SNR2: 2.8466




0106+01 2024/05/09 0.85UT FUJI -KISO




T20240509100023




BLK:18,SNR1: 0.18357 ,SNR2: 1.3778




F20240509100023





BLK:18,SNR1: 0.79394 ,SNR2: 1.3211




0116+31 2024/05/09 1.03UT TOYOKAWA-FUJI





T20240509100023




BLK:18,SNR1: 0.42313 ,SNR2: 1.0117




K20240509100020





BLK:18,SNR1: 0.88370 ,SNR2: 4.8844




0116+31 2024/05/09 1.03UT TOYOKAWA-KISO




F20240509100023




BLK:15,SNR1: 0.31547 ,SNR2: 0.99344




K20240509100020



BLK:15,SNR1: 0.27467 ,SNR2: 2.1101




0116+31 2024/05/09 1.03UT FUJI -KISO






T20240509101046




BLK:19,SNR1: 0.45757 ,SNR2: 3.0014





3C43 2024/05/09 1.21UT TOYOKAWA-FUJI


F20240509101047




BLK:19,SNR1: 0.69155 ,SNR2: 3.1103





T20240509101046




BLK:17,SNR1: 1.5179 ,SNR2: 8.8047




K20240509101044





BLK:17,SNR1: 0.74548 ,SNR2: 3.3236




3C43 2024/05/09 1.21UT TOYOKAWA-KISO



F20240509101047





BLK:22,SNR1: 0.99787 ,SNR2: 4.7425





3C43 2024/05/09 1.21UT FUJI -KISO


K20240509101044




BLK:22,SNR1: 0.68199 ,SNR2: 2.0770



T20240509101830




BLK:36,SNR1: 19.410 ,SNR2: 34.854





3C48 2024/05/09 1.34UT TOYOKAWA-FUJI



F20240509101830




BLK:36,SNR1: 2.8869 ,SNR2: 13.677



T20240509101830





BLK:34,SNR1: 19.409 ,SNR2: 34.853





3C48 2024/05/09 1.34UT TOYOKAWA-KISO



K20240509101828




BLK:34,SNR1: 12.956 ,SNR2: 31.611



F20240509101830





BLK:33,SNR1: 2.8539 ,SNR2: 13.546





3C48 2024/05/09 1.34UT FUJI -KISO


K20240509101828




BLK:33,SNR1: 12.962 ,SNR2: 31.626



T20240509103815




BLK:25,SNR1: 7.0972 ,SNR2: 17.528




0155-109 2024/05/09 1.67UT TOYOKAWA-FUJI


F20240509103815




BLK:25,SNR1: 9.5710 ,SNR2: 16.953




Frequency (Hz)



T20240509103815





BLK:27,SNR1: 7.0437 ,SNR2: 17.388





0155-109 2024/05/09 1.67UT TOYOKAWA-KISO

K20240509103813





BLK:27,SNR1: 8.8088 ,SNR2: 15.650








F20240509103815




BLK:35,SNR1: 8.6720 ,SNR2: 15.368




K20240509103813





BLK:35,SNR1: 8.1483 ,SNR2: 14.487




0155-109 2024/05/09 1.67UT FUJI -KISO



T20240509104521





BLK:21,SNR1: 3.5781 ,SNR2: 11.809




0202+15 2024/05/09 1.78UT TOYOKAWA-FUJI


F20240509104522





BLK:21,SNR1: 61.239 ,SNR2: 65.088




Frequency (Hz)



T20240509104521




BLK:23,SNR1: 4.2101 ,SNR2: 10.846





0202+15 2024/05/09 1.78UT TOYOKAWA-KISO


K20240509104519




BLK:23,SNR1: 0.78319 ,SNR2: 2.5278




F20240509104522




BLK:17,SNR1: 80.912 ,SNR2: 87.834




K20240509104519




BLK:17,SNR1: 0.97145 ,SNR2: 3.1426




0202+15 2024/05/09 1.78UT FUJI -KISO





T20240509105712




BLK:34,SNR1: 118.71 ,SNR2: 117.55




F20240509105712





BLK:34,SNR1: 15.260 ,SNR2: 16.480




0213+178 2024/05/09 1.98UT TOYOKAWA-FUJI




T20240509105712




BLK:34,SNR1: 122.90 ,SNR2: 121.71




K20240509105710




BLK:34,SNR1: 65.344 ,SNR2: 62.873




0213+178 2024/05/09 1.98UT TOYOKAWA-KISO




F20240509105712




BLK:35,SNR1: 15.053 ,SNR2: 16.259




K20240509105710




BLK:35,SNR1: 63.834 ,SNR2: 70.805




0213+178 2024/05/09 1.98UT FUJI -KISO



T20240509110454




BLK:15,SNR1: 1.5704 ,SNR2: 3.1693





3C67 2024/05/09 2.11UT TOYOKAWA-FUJI

F20240509110454




BLK:15,SNR1: 0.19190 ,SNR2: 2.3145






T20240509110454




BLK:31,SNR1: 1.1268 ,SNR2: 2.1716





3C67 2024/05/09 2.11UT TOYOKAWA-KISO



K20240509110451




BLK:31,SNR1: 0.41688 ,SNR2: 1.6305



F20240509110454





BLK:29,SNR1: 0.13137 ,SNR2: 1.5775




Frequency (Hz)

K20240509110451




BLK:29,SNR1: 0.49034 ,SNR2: 1.9763





Frequency (Hz)


3C67 2024/05/09 2.11UT FUJI -KISO



T20240509112309





BLK:30,SNR1: 4.1450 ,SNR2: 7.3864









3C71 2024/05/09 2.41UT TOYOKAWA-FUJI

F20240509112310




BLK:30,SNR1: 6.5829 ,SNR2: 16.128








3C71 2024/05/09 2.41UT TOYOKAWA-KISO



F20240509112310




BLK:31,SNR1: 6.6353 ,SNR2: 16.239





3C71 2024/05/09 2.41UT FUJI -KISO



K20240509112306




BLK:31,SNR1: 3.9864 ,SNR2: 9.7781





T20240509114224




BLK:36,SNR1: 76.933 ,SNR2: 80.088




F20240509114224





BLK:36,SNR1: 7.1733 ,SNR2: 8.7812




0258+350 2024/05/09 2.73UT TOYOKAWA-FUJI




T20240509114224




BLK:37,SNR1: 72.082 ,SNR2: 77.009




K20240509114221





BLK:37,SNR1: 10.709 ,SNR2: 14.120




0258+350 2024/05/09 2.73UT TOYOKAWA-KISO





F20240509114224




BLK:34,SNR1: 6.6243 ,SNR2: 8.1592




K20240509114221



BLK:34,SNR1: 10.514 ,SNR2: 13.865




0258+350 2024/05/09 2.73UT FUJI -KISO







T20240509115213




BLK:34,SNR1: 30.430 ,SNR2: 38.874




F20240509115214




BLK:34,SNR1: 4.7720 ,SNR2: 6.2205




0308+305 2024/05/09 2.90UT TOYOKAWA-FUJI




T20240509115213




BLK:36,SNR1: 33.658 ,SNR2: 37.749




K20240509115210







BLK:36,SNR1: 1.1448 ,SNR2: 5.3108




0308+305 2024/05/09 2.90UT TOYOKAWA-KISO








0308+305 2024/05/09 2.90UT FUJI -KISO





T20240509120345




BLK:30,SNR1: 10.481 ,SNR2: 25.016




F20240509120346







BLK:30,SNR1: 0.62873 ,SNR2: 2.2758




0320+05 2024/05/09 3.09UT TOYOKAWA-FUJI








0320+05 2024/05/09 3.09UT TOYOKAWA-KISO





F20240509120346




BLK:29,SNR1: 0.72158 ,SNR2: 1.9025




K20240509120342





BLK:29,SNR1: 1.4015 ,SNR2: 5.6017




0320+05 2024/05/09 3.09UT FUJI -KISO




T20240509121706




BLK:24,SNR1: 0.13075 ,SNR2: 2.2315




F20240509121706





BLK:24,SNR1: 1.7330 ,SNR2: 2.8708




0333+32 2024/05/09 3.31UT TOYOKAWA-FUJI





T20240509121706




BLK:24,SNR1: 0.11799 ,SNR2: 0.76818




K20240509121703



BLK:24,SNR1: 1.1408 ,SNR2: 4.8028




0333+32 2024/05/09 3.31UT TOYOKAWA-KISO








F20240509121706




BLK:36,SNR1: 1.8238 ,SNR2: 2.9470




K20240509121703





BLK:36,SNR1: 1.1060 ,SNR2: 4.5784




0333+32 2024/05/09 3.31UT FUJI -KISO





T20240509123008




BLK:16,SNR1: 0.43939 ,SNR2: 2.4323




F20240509123008





BLK:16,SNR1: 0.46977 ,SNR2: 1.9754




0347+05 2024/05/09 3.53UT TOYOKAWA-FUJI





T20240509123008




BLK:19,SNR1: 0.24611 ,SNR2: 1.7581




K20240509123005





BLK:19,SNR1: 0.50465 ,SNR2: 2.0082




0347+05 2024/05/09 3.53UT TOYOKAWA-KISO





F20240509123008




BLK:22,SNR1: 0.64179 ,SNR2: 2.9029




K20240509123005






BLK:22,SNR1: 0.40770 ,SNR2: 1.8909





0347+05 2024/05/09 3.53UT FUJI -KISO




T20240509124542




F20240509124542




0403-132 2024/05/09 3.79UT TOYOKAWA-FUJI





T20240509124542




BLK:15,SNR1: 0.93265 ,SNR2: 2.7487




K20240509124539





BLK:15,SNR1: 0.75142 ,SNR2: 3.2574




0403-132 2024/05/09 3.79UT TOYOKAWA-KISO



F20240509124542





BLK:10,SNR1:-0.95808E-01,SNR2: 0.84812




Frequency (Hz)

K20240509124539




BLK:10,SNR1: 0.69742 ,SNR2: 2.4845





Frequency (Hz)


0403-132 2024/05/09 3.79UT FUJI -KISO





T20240509125453




BLK: 8,SNR1: 0.32658 ,SNR2: 1.0516




F20240509125453



BLK: 8,SNR1: 2.8951 ,SNR2: 12.883





0411+05 2024/05/09 3.94UT TOYOKAWA-FUJI








T20240509125453




BLK:14,SNR1: 0.54594E-01,SNR2: 1.8554




K20240509125450





BLK:14,SNR1: 0.81227 ,SNR2: 3.6629




0411+05 2024/05/09 3.94UT TOYOKAWA-KISO





F20240509125453




BLK:16,SNR1: 2.8422 ,SNR2: 12.669




K20240509125450





BLK:16,SNR1: 0.90955 ,SNR2: 4.0084




0411+05 2024/05/09 3.94UT FUJI -KISO





T20240509130546




BLK:33,SNR1: 6.8961 ,SNR2: 9.8618




F20240509130547





BLK:33,SNR1: 190.85 ,SNR2: 215.22




0422+178 2024/05/09 4.12UT TOYOKAWA-FUJI





T20240509130546




BLK:27,SNR1: 5.4882 ,SNR2: 9.7781




K20240509130543





BLK:27,SNR1: 71.297 ,SNR2: 70.804




0422+178 2024/05/09 4.12UT TOYOKAWA-KISO




F20240509130547




BLK:29,SNR1: 181.90 ,SNR2: 184.62




K20240509130543





BLK:29,SNR1: 66.227 ,SNR2: 65.904




0422+178 2024/05/09 4.12UT FUJI -KISO




T20240509131322




BLK:11,SNR1: 0.22408 ,SNR2: 1.1402




F20240509131322





BLK:11,SNR1: 0.72164E-01,SNR2: 0.76687




3C120 2024/05/09 4.25UT TOYOKAWA-FUJI





T20240509131322




BLK:17,SNR1: 0.33546 ,SNR2: 1.1392




K20240509131319




BLK:17,SNR1: 0.27098 ,SNR2: 2.5884




3C120 2024/05/09 4.25UT TOYOKAWA-KISO



F20240509131322





BLK:12,SNR1: 0.56398E-01,SNR2: 1.8957





3C120 2024/05/09 4.25UT FUJI -KISO

K20240509131319





BLK:12,SNR1: 0.49960 ,SNR2: 1.7198







T20240509140122




BLK:17,SNR1: 1.3024 ,SNR2: 4.0932




F20240509140122





BLK:17,SNR1: 0.10947 ,SNR2: 4.7421




3C138 2024/05/09 5.05UT TOYOKAWA-FUJI





T20240509140122




BLK:20,SNR1: 1.3797 ,SNR2: 7.1192




K20240509140119




BLK:20,SNR1: 0.65214 ,SNR2: 2.8196




3C138 2024/05/09 5.05UT TOYOKAWA-KISO



F20240509140122





BLK:10,SNR1: 0.42721 ,SNR2: 10.694





3C138 2024/05/09 5.05UT FUJI -KISO


K20240509140119




BLK:10,SNR1: 0.91346 ,SNR2: 4.0910




T20240509141455




BLK:15,SNR1: 1.0100 ,SNR2: 3.5920




F20240509141456





BLK:15,SNR1: 1.7979 ,SNR2: 6.3667




0531+194 2024/05/09 5.28UT TOYOKAWA-FUJI





T20240509141455




BLK:17,SNR1: 0.74570 ,SNR2: 3.8921




K20240509141453




BLK:17,SNR1: 0.92915 ,SNR2: 3.5895




0531+194 2024/05/09 5.28UT TOYOKAWA-KISO





F20240509141456




BLK:30,SNR1: 3.4688 ,SNR2: 7.1345




K20240509141453





BLK:30,SNR1: 1.1188 ,SNR2: 4.7225




0531+194 2024/05/09 5.28UT FUJI -KISO



T20240509142314





BLK:25,SNR1: 2.5917 ,SNR2: 12.845




Frequency (Hz)

F20240509142314




BLK:25,SNR1: 0.30275 ,SNR2: 3.7568





Frequency (Hz)


3C147 2024/05/09 5.42UT TOYOKAWA-FUJI



T20240509142314





BLK:24,SNR1: 2.6048 ,SNR2: 12.544




Frequency (Hz)

K20240509142312




BLK:24,SNR1: 0.46379 ,SNR2: 4.1723





Frequency (Hz)

3C147 2024/05/09 5.42UT TOYOKAWA-KISO






F20240509142314





BLK:24,SNR1: 0.82065 ,SNR2: 7.5183




Frequency (Hz)

3C147 2024/05/09 5.42UT FUJI -KISO


K20240509142312




BLK:24,SNR1: 0.38398 ,SNR2: 4.2638




Frequency (Hz)




T20240509143126




BLK: 2,SNR1: 0.18883 ,SNR2: 1.1263




F20240509143127




BLK: 2,SNR1: 0.50846E-01,SNR2: 2.4156




0548+16 2024/05/09 5.55UT TOYOKAWA-FUJI





T20240509143126




BLK: 7,SNR1: 0.23944 ,SNR2: 1.0215




K20240509143124





BLK: 7,SNR1: 3.2380 ,SNR2: 7.6576




0548+16 2024/05/09 5.55UT TOYOKAWA-KISO



F20240509143127





BLK: 3,SNR1:-0.12177 ,SNR2: 0.41045




Frequency (Hz)

K20240509143124




BLK: 3,SNR1: 2.8226 ,SNR2: 9.1825





Frequency (Hz)


0548+16 2024/05/09 5.55UT FUJI -KISO





T20240509143537




BLK:11,SNR1: 5.5996 ,SNR2: 21.331




F20240509143538





BLK:11,SNR1:-0.60018E-01,SNR2: 1.4607




0552+12 2024/05/09 5.62UT TOYOKAWA-FUJI





T20240509143537




BLK: 9,SNR1: 12.535 ,SNR2: 53.478




K20240509143535







BLK: 9,SNR1: 2.6047 ,SNR2: 10.687




0552+12 2024/05/09 5.62UT TOYOKAWA-KISO








0552+12 2024/05/09 5.62UT FUJI -KISO




T20240509144004




BLK:14,SNR1: 7.0890 ,SNR2: 50.985




F20240509144004



BLK:14,SNR1: 0.70151 ,SNR2: 8.4677





0556+191 2024/05/09 5.70UT TOYOKAWA-FUJI








T20240509144004




BLK: 8,SNR1: 1.0534 ,SNR2: 6.0963




K20240509144001





BLK: 8,SNR1: 0.97273E-01,SNR2: 1.5261




0556+191 2024/05/09 5.70UT TOYOKAWA-KISO



F20240509144004





BLK:16,SNR1: 0.76098 ,SNR2: 8.2884




Frequency (Hz)

K20240509144001




BLK:16,SNR1: 0.12816 ,SNR2: 1.1569




Frequency (Hz)


0556+191 2024/05/09 5.70UT FUJI -KISO





T20240509144750




BLK: 9,SNR1: 0.16983 ,SNR2: 1.6578




F20240509144750






BLK: 9,SNR1: 1.2279 ,SNR2: 6.4065






0605-08 2024/05/09 5.83UT TOYOKAWA-FUJI




T20240509144750






KISO






0605-08 2024/05/09 5.83UT TOYOKAWA-KISO




F20240509144750




KISO




0605-08 2024/05/09 5.83UT FUJI -KISO





T20240509150657




BLK: 8,SNR1: 1.8833 ,SNR2: 5.2610




F20240509150657




BLK: 8,SNR1: 1.2036 ,SNR2: 3.7234




3C161 2024/05/09 6.14UT TOYOKAWA-FUJI



T20240509150657





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C161 2024/05/09 6.14UT TOYOKAWA-KISO



F20240509150657





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C161 2024/05/09 6.14UT FUJI -KISO







T20240509153431




BLK:12,SNR1: 2.4924 ,SNR2: 7.1079




F20240509153431





BLK:12,SNR1: 2.3674 ,SNR2: 3.7678




0652-130 2024/05/09 6.60UT TOYOKAWA-FUJI





T20240509153431




BLK:12,SNR1: 2.2683 ,SNR2: 6.6695




K20240509153428





BLK:12,SNR1: 0.52795 ,SNR2: 2.5313




0652-130 2024/05/09 6.60UT TOYOKAWA-KISO



F20240509153431





BLK:18,SNR1: 2.3253 ,SNR2: 4.4153




Frequency (Hz)

K20240509153428




BLK:18,SNR1: 0.55846 ,SNR2: 2.6603





Frequency (Hz)


0652-130 2024/05/09 6.60UT FUJI -KISO




T20240509154607




BLK:15,SNR1: 0.32555 ,SNR2: 1.7128




F20240509154608





BLK:15,SNR1: 3.5078 ,SNR2: 6.7441




0703+138 2024/05/09 6.80UT TOYOKAWA-FUJI



T20240509154607





BLK:19,SNR1: 0.30291 ,SNR2: 1.5722




Frequency (Hz)

K20240509154604




BLK:19,SNR1: 1.6240 ,SNR2: 6.0873




Frequency (Hz)


0703+138 2024/05/09 6.80UT TOYOKAWA-KISO




F20240509154608




BLK:25,SNR1: 2.8404 ,SNR2: 5.4819




K20240509154604





BLK:25,SNR1: 1.5353 ,SNR2: 5.8210




0703+138 2024/05/09 6.80UT FUJI -KISO



T20240509155530




BLK:13,SNR1: 1.7944 ,SNR2: 4.7010




Frequency (Hz)

F20240509155530




BLK:13,SNR1: 1.2486 ,SNR2: 2.5610





Frequency (Hz)


0713-024 2024/05/09 6.95UT TOYOKAWA-FUJI



T20240509155530




BLK:12,SNR1: 1.9848 ,SNR2: 5.1128




Frequency (Hz)

K20240509155527




BLK:12,SNR1: 2.5083 ,SNR2: 4.9600





Frequency (Hz)


0713-024 2024/05/09 6.95UT TOYOKAWA-KISO










0713-024 2024/05/09 6.95UT FUJI -KISO



T20240509160541





BLK: 9,SNR1: 0.20999 ,SNR2: 1.0423




Frequency (Hz)

F20240509160542




BLK: 9,SNR1:-0.10901 ,SNR2: 0.64843





Frequency (Hz)


0723+10 2024/05/09 7.12UT TOYOKAWA-FUJI



T20240509160541





BLK: 4,SNR1: 0.36002 ,SNR2: 2.7967




Frequency (Hz)

K20240509160538




BLK: 4,SNR1: 0.19127 ,SNR2: 1.7429





Frequency (Hz)


0723+10 2024/05/09 7.12UT TOYOKAWA-KISO





F20240509160542




BLK: 3,SNR1:-0.81046E-01,SNR2: 1.8355




K20240509160538





BLK: 3,SNR1: 0.13483 ,SNR2: 0.60368




0723+10 2024/05/09 7.12UT FUJI -KISO



T20240509161556




BLK:15,SNR1: 0.54802 ,SNR2: 1.5880




Frequency (Hz)

F20240509161556




BLK:15,SNR1: 0.20642 ,SNR2: 2.4866





Frequency (Hz)


0732+33 2024/05/09 7.29UT TOYOKAWA-FUJI





T20240509161556




BLK:17,SNR1: 0.46096 ,SNR2: 1.6048




K20240509161553




BLK:17,SNR1: 42.522 ,SNR2: 82.250




0732+33 2024/05/09 7.29UT TOYOKAWA-KISO



F20240509161556





BLK:15,SNR1: 0.82790 ,SNR2: 1.6943




Frequency (Hz)

K20240509161553




BLK:15,SNR1: 26.254 ,SNR2: 52.446





Frequency (Hz)


0732+33 2024/05/09 7.29UT FUJI -KISO



T20240509162358




BLK: 5,SNR1: 0.51576 ,SNR2: 4.7481




Frequency (Hz)

F20240509162359




BLK: 5,SNR1: 0.67605E-01,SNR2: 2.3483




Frequency (Hz)

0741-06 2024/05/09 7.43UT TOYOKAWA-FUJI






T20240509162358




BLK:12,SNR1: 0.36956 ,SNR2: 1.8024




Frequency (Hz)

K20240509162355




BLK:12,SNR1: 0.56504 ,SNR2: 4.1606




Frequency (Hz)


0741-06 2024/05/09 7.43UT TOYOKAWA-KISO



F20240509162359





BLK:14,SNR1: 0.35937 ,SNR2: 0.95049




Frequency (Hz)

K20240509162355




BLK:14,SNR1: 0.68945 ,SNR2: 3.3126





Frequency (Hz)


0741-06 2024/05/09 7.43UT FUJI -KISO



T20240509164117




BLK:23,SNR1: 16.815 ,SNR2: 31.844




Frequency (Hz)

F20240509164117




BLK:23,SNR1: 5.4196 ,SNR2: 13.582





Frequency (Hz)


3C190 2024/05/09 7.72UT TOYOKAWA-FUJI



T20240509164117





BLK:26,SNR1: 16.413 ,SNR2: 31.077




Frequency (Hz)

K20240509164114




BLK:26,SNR1: 21.443 ,SNR2: 40.255





Frequency (Hz)


3C190 2024/05/09 7.72UT TOYOKAWA-KISO



F20240509164117





BLK:28,SNR1: 18.260 ,SNR2: 19.932




Frequency (Hz)

K20240509164114




BLK:28,SNR1: 12.959 ,SNR2: 31.652





Frequency (Hz)


3C190 2024/05/09 7.72UT FUJI -KISO



T20240509165341





BLK:27,SNR1: 2.8793 ,SNR2: 13.631




Frequency (Hz)

3C196 2024/05/09 7.92UT TOYOKAWA-FUJI


F20240509165341





BLK:27,SNR1: 18.998 ,SNR2: 34.694




Frequency (Hz)



T20240509165341





BLK:19,SNR1: 2.8956 ,SNR2: 13.704




Frequency (Hz)

K20240509165338




BLK:19,SNR1: 20.864 ,SNR2: 39.150





Frequency (Hz)


3C196 2024/05/09 7.92UT TOYOKAWA-KISO



F20240509165341





BLK:22,SNR1: 19.045 ,SNR2: 34.781




Frequency (Hz)

K20240509165338




BLK:22,SNR1: 20.846 ,SNR2: 39.116





Frequency (Hz)

3C196 2024/05/09 7.92UT FUJI -KISO






T20240509170451





BLK:29,SNR1: 8.4306 ,SNR2: 21.137




Frequency (Hz)

F20240509170452




BLK:29,SNR1: 29.032 ,SNR2: 32.574





Frequency (Hz)


0821+394 2024/05/09 8.11UT TOYOKAWA-FUJI



T20240509170451





BLK:30,SNR1: 8.4166 ,SNR2: 21.102




Frequency (Hz)

K20240509170449




BLK:30,SNR1: 39.166 ,SNR2: 44.439





Frequency (Hz)


0821+394 2024/05/09 8.11UT TOYOKAWA-KISO



F20240509170452





BLK:37,SNR1: 27.264 ,SNR2: 30.591




Frequency (Hz)

K20240509170449




BLK:37,SNR1: 39.021 ,SNR2: 44.274





Frequency (Hz)


0821+394 2024/05/09 8.11UT FUJI -KISO



T20240509174919





BLK:13,SNR1: 0.89978E-01,SNR2: 0.77762




Frequency (Hz)

F20240509174920




BLK:13,SNR1: 0.25742 ,SNR2: 3.8589





Frequency (Hz)


3C216 2024/05/09 8.85UT TOYOKAWA-FUJI



T20240509174919




BLK:17,SNR1: 0.10151 ,SNR2: 0.46859




Frequency (Hz)

K20240509174917






BLK:17,SNR1: 3.3244 ,SNR2: 6.3073



Frequency (Hz)

3C216 2024/05/09 8.85UT TOYOKAWA-KISO





3C216 2024/05/09 8.85UT FUJI -KISO

