




T20240519053041





BLK:15,SNR1: 19.200 ,SNR2: 67.229




Frequency (Hz)

F20240519053043




BLK:15,SNR1: 2.7427 ,SNR2: 6.9776





Frequency (Hz)


2127+456 2024/05/18 20.54UT TOYOKAWA-FUJI



T20240519053041




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

2127+456 2024/05/18 20.54UT TOYOKAWA-KISO




F20240519053043



No.Good Data




KISO





No.Good Data




2127+456 2024/05/18 20.54UT FUJI -KISO



T20240519055558





BLK:17,SNR1: 18.983 ,SNR2: 46.106




Frequency (Hz)

F20240519055600




BLK:17,SNR1: 3.0973 ,SNR2: 7.8841





Frequency (Hz)


2152+450 2024/05/18 20.96UT TOYOKAWA-FUJI





T20240519055558




No.Good Data




KISO





No.Good Data




2152+450 2024/05/18 20.96UT TOYOKAWA-KISO



F20240519055600





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


2152+450 2024/05/18 20.96UT FUJI -KISO



T20240519060326





BLK:10,SNR1: 1.4539 ,SNR2: 15.182




Frequency (Hz)

F20240519060328




BLK:10,SNR1: 0.67587E-01,SNR2: 1.4494





Frequency (Hz)


2159+408 2024/05/18 21.09UT TOYOKAWA-FUJI




T20240519060326




No.Good Data




KISO



No.Good Data





2159+408 2024/05/18 21.09UT TOYOKAWA-KISO








F20240519060328




No.Good Data




KISO





No.Good Data




2159+408 2024/05/18 21.09UT FUJI -KISO



T20240519061104




BLK: 2,SNR1: 0.18002 ,SNR2: 0.33238




Frequency (Hz)

F20240519061106




BLK: 2,SNR1: 0.32616 ,SNR2: 2.1277





Frequency (Hz)


2207+374 2024/05/18 21.21UT TOYOKAWA-FUJI





T20240519061104




No.Good Data




KISO




No.Good Data




2207+374 2024/05/18 21.21UT TOYOKAWA-KISO





F20240519061106




No.Good Data




KISO





No.Good Data




2207+374 2024/05/18 21.21UT FUJI -KISO



T20240519062155





BLK:31,SNR1: 19.488 ,SNR2: 34.978




Frequency (Hz)

F20240519062157




BLK:31,SNR1: 2.9865 ,SNR2: 14.072




Frequency (Hz)


2217+128 2024/05/18 21.39UT TOYOKAWA-FUJI



T20240519062155





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


2217+128 2024/05/18 21.39UT TOYOKAWA-KISO




F20240519062157




No.Good Data




KISO





No.Good Data




2217+128 2024/05/18 21.39UT FUJI -KISO



T20240519064727




BLK: 6,SNR1: 5.9527 ,SNR2: 45.167




Frequency (Hz)

F20240519064729




BLK: 6,SNR1: 0.83202 ,SNR2: 5.1196





Frequency (Hz)

2243+394 2024/05/18 21.82UT TOYOKAWA-FUJI








T20240519064727




No.Good Data




KISO





No.Good Data




2243+394 2024/05/18 21.82UT TOYOKAWA-KISO





F20240519064729




No.Good Data




KISO





No.Good Data




2243+394 2024/05/18 21.82UT FUJI -KISO



T20240519065541





BLK:29,SNR1: 30.024 ,SNR2: 33.889




Frequency (Hz)

F20240519065543




BLK:29,SNR1: 25.742 ,SNR2: 28.877





Frequency (Hz)


3C454.3 2024/05/18 21.96UT TOYOKAWA-FUJI





T20240519065541




No.Good Data




KISO





No.Good Data




3C454.3 2024/05/18 21.96UT TOYOKAWA-KISO



F20240519065543





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C454.3 2024/05/18 21.96UT FUJI -KISO




T20240519070323




BLK: 9,SNR1: 7.0140 ,SNR2: 16.141




F20240519070325





BLK: 9,SNR1: 4.8689 ,SNR2: 16.574




2259+481 2024/05/18 22.08UT TOYOKAWA-FUJI



T20240519070323





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


2259+481 2024/05/18 22.08UT TOYOKAWA-KISO



F20240519070325





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

2259+481 2024/05/18 22.08UT FUJI -KISO






T20240519071817





BLK:22,SNR1: 2.7262 ,SNR2: 12.062




Frequency (Hz)

3C459 2024/05/18 22.33UT TOYOKAWA-FUJI


F20240519071819





BLK:22,SNR1: 4.8241 ,SNR2: 12.246




Frequency (Hz)



T20240519071817





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C459 2024/05/18 22.33UT TOYOKAWA-KISO





F20240519071819




No.Good Data




KISO





No.Good Data




3C459 2024/05/18 22.33UT FUJI -KISO



T20240519075202





BLK:11,SNR1: 0.53794 ,SNR2: 4.5601




Frequency (Hz)

F20240519075204




BLK:11,SNR1: 3.0793 ,SNR2: 9.5837





Frequency (Hz)


2347-02 2024/05/18 22.90UT TOYOKAWA-FUJI



T20240519075202





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


2347-02 2024/05/18 22.90UT TOYOKAWA-KISO



F20240519075204




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


2347-02 2024/05/18 22.90UT FUJI -KISO



T20240519075855




BLK: 5,SNR1: 0.18603 ,SNR2: 0.76593




Frequency (Hz)

2354+14 2024/05/18 23.01UT TOYOKAWA-FUJI


F20240519075857





BLK: 5,SNR1: 1.1744 ,SNR2: 9.1517




Frequency (Hz)



T20240519075855





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

2354+14 2024/05/18 23.01UT TOYOKAWA-KISO








F20240519075857




No.Good Data




KISO





No.Good Data




2354+14 2024/05/18 23.01UT FUJI -KISO



T20240519080758





BLK:10,SNR1: 0.10665 ,SNR2: 1.3503





3C2 2024/05/18 23.16UT TOYOKAWA-FUJI



F20240519080800




BLK:10,SNR1: 1.0425 ,SNR2: 3.1713



T20240519080758





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C2 2024/05/18 23.16UT TOYOKAWA-KISO





F20240519080800




No.Good Data




KISO





No.Good Data




3C2 2024/05/18 23.16UT FUJI -KISO



T20240519081520




BLK: 9,SNR1: 0.17279 ,SNR2: 1.0567




Frequency (Hz)

F20240519081522




BLK: 9,SNR1: 2.8192 ,SNR2: 12.607





Frequency (Hz)


0011+344 2024/05/18 23.28UT TOYOKAWA-FUJI





T20240519081520




No.Good Data




KISO





No.Good Data




0011+344 2024/05/18 23.28UT TOYOKAWA-KISO





F20240519081522




No.Good Data




KISO





No.Good Data




0011+344 2024/05/18 23.28UT FUJI -KISO



T20240519082356




BLK:11,SNR1: 0.43705 ,SNR2: 3.1699





0019-00 2024/05/18 23.43UT TOYOKAWA-FUJI

F20240519082358





BLK:11,SNR1: 0.52266 ,SNR2: 6.0461








T20240519082356




No.Good Data




KISO





No.Good Data




0019-00 2024/05/18 23.43UT TOYOKAWA-KISO





F20240519082358




No.Good Data




KISO





No.Good Data




0019-00 2024/05/18 23.43UT FUJI -KISO



T20240519083411





BLK: 5,SNR1: 0.14424 ,SNR2: 1.6499




Frequency (Hz)

3C12 2024/05/18 23.60UT TOYOKAWA-FUJI


F20240519083413





BLK: 5,SNR1: 0.92759 ,SNR2: 5.4866




Frequency (Hz)





T20240519083411




No.Good Data




KISO





No.Good Data




3C12 2024/05/18 23.60UT TOYOKAWA-KISO





F20240519083413




No.Good Data




KISO






No.Good Data






3C12 2024/05/18 23.60UT FUJI -KISO




T20240519084812





F20240519084814




0044-056 2024/05/18 23.83UT TOYOKAWA-FUJI





T20240519084812




No.Good Data




KISO





No.Good Data




0044-056 2024/05/18 23.83UT TOYOKAWA-KISO





F20240519084814




No.Good Data




KISO



No.Good Data





0044-056 2024/05/18 23.83UT FUJI -KISO








T20240519090032




BLK: 4, SNR1: 0.12115 , SNR2: 1.4880




F20240519090034





BLK: 4, SNR1: 1.9114 , SNR2: 9.0092




0056-00 2024/05/19 0.04UT TOYOKAWA-FUJI



T20240519090032





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0056-00 2024/05/19 0.04UT TOYOKAWA-KISO





F20240519090034




No.Good Data




KISO





No.Good Data




0056-00 2024/05/19 0.04UT FUJI -KISO



T20240519091014





BLK: 7,SNR1: 0.24828 ,SNR2: 1.0003





0106+01 2024/05/19 0.20UT TOYOKAWA-FUJI



F20240519091016




BLK: 7,SNR1: 0.14827 ,SNR2: 3.0060



T20240519091014





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0106+01 2024/05/19 0.20UT TOYOKAWA-KISO





F20240519091016




No.Good Data




KISO




No.Good Data




0106+01 2024/05/19 0.20UT FUJI -KISO



T20240519092104





BLK: 7,SNR1: 0.36232E-01,SNR2: 0.44888





0116+31 2024/05/19 0.38UT TOYOKAWA-FUJI



F20240519092106




BLK: 7,SNR1: 0.42618E-01,SNR2: 5.2078



T20240519092104





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

0116+31 2024/05/19 0.38UT TOYOKAWA-KISO








F20240519092106




No. Good Data




KISO





No. Good Data




0116+31 2024/05/19 0.38UT FUJI -KISO





T20240519093237




BLK: 5,SNR1: 0.45351E-01,SNR2: 0.86437




F20240519093239





BLK: 5,SNR1: 0.37346E-01,SNR2: 2.4634




0128+03 2024/05/19 0.57UT TOYOKAWA-FUJI



T20240519093237





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0128+03 2024/05/19 0.57UT TOYOKAWA-KISO





F20240519093239




No. Good Data




KISO







No. Good Data




0128+03 2024/05/19 0.57UT FUJI -KISO







3C48 2024/05/19 0.68UT TOYOKAWA-FUJI



T20240519093911





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C48 2024/05/19 0.68UT TOYOKAWA-KISO





F20240519093913




No. Good Data




KISO




No. Good Data




3C48 2024/05/19 0.68UT FUJI -KISO




T20240519095856




BLK: 5, SNR1: 0.23243 , SNR2: 1.5709




F20240519095858



BLK: 5, SNR1: 0.86283 , SNR2: 2.2270





0155-109 2024/05/19 1.01UT TOYOKAWA-FUJI






T20240519095856





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0155-109 2024/05/19 1.01UT TOYOKAWA-KISO





F20240519095858




No. Good Data




KISO




No. Good Data




0155-109 2024/05/19 1.01UT FUJI -KISO



T20240519100602




BLK:18,SNR1: 0.44392 ,SNR2: 2.5243





0202+15 2024/05/19 1.13UT TOYOKAWA-FUJI



F20240519100604




BLK:18,SNR1: 0.52134 ,SNR2: 3.0726



T20240519100602





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0202+15 2024/05/19 1.13UT TOYOKAWA-KISO



F20240519100604





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0202+15 2024/05/19 1.13UT FUJI -KISO



T20240519101753




BLK:14,SNR1: 4.1400 ,SNR2: 11.432





0213+178 2024/05/19 1.33UT TOYOKAWA-FUJI



F20240519101755




BLK:14,SNR1: 4.3688 ,SNR2: 12.021



T20240519101753





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0213+178 2024/05/19 1.33UT TOYOKAWA-KISO



F20240519101755





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0213+178 2024/05/19 1.33UT FUJI -KISO






T20240519102535




BLK:18,SNR1: 0.68645 ,SNR2: 7.7461





3C67 2024/05/19 1.45UT TOYOKAWA-FUJI



F20240519102537




BLK:18,SNR1: 0.27921 ,SNR2: 1.3232



T20240519102535





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C67 2024/05/19 1.45UT TOYOKAWA-KISO



F20240519102537





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C67 2024/05/19 1.45UT FUJI -KISO





T20240519104350




BLK: 4, SNR1: 0.17093 , SNR2: 0.72202




F20240519104352





BLK: 4, SNR1: -0.31653 , SNR2: 0.87834




3C71 2024/05/19 1.76UT TOYOKAWA-FUJI



T20240519104350





No.Good Data




Frequency (Hz)

3C71 2024/05/19 1.76UT TOYOKAWA-KISO


KISO





No.Good Data




Frequency (Hz)



F20240519104352





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C71 2024/05/19 1.76UT FUJI -KISO




T20240519110305




BLK: 9,SNR1: 0.19122 ,SNR2: 0.75457




F20240519110307





BLK: 9,SNR1: 0.45225E-01,SNR2: 1.3450




0258+350 2024/05/19 2.08UT TOYOKAWA-FUJI



T20240519110305





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0258+350 2024/05/19 2.08UT TOYOKAWA-KISO








F20240519110307




No.Good Data




KISO




No.Good Data





0258+350 2024/05/19 2.08UT FUJI -KISO







BLK:16,SNR1: 1.1691 ,SNR2: 8.8967





BLK:16,SNR1: 3.0344 ,SNR2: 7.3668




0308+305 2024/05/19 2.24UT TOYOKAWA-FUJI



T20240519111254





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0308+305 2024/05/19 2.24UT TOYOKAWA-KISO



F20240519111256





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0308+305 2024/05/19 2.24UT FUJI -KISO





T20240519112426




BLK:17,SNR1: 3.9234 ,SNR2: 25.798




F20240519112428





BLK:17,SNR1: 0.20458 ,SNR2: 2.3726




0320+05 2024/05/19 2.44UT TOYOKAWA-FUJI



T20240519112426





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0320+05 2024/05/19 2.44UT TOYOKAWA-KISO





F20240519112428




No.Good Data




KISO





No.Good Data




0320+05 2024/05/19 2.44UT FUJI -KISO





T20240519113747




BLK:14,SNR1: 0.20775 ,SNR2: 1.0335




F20240519113749



BLK:14,SNR1: 8.5497 ,SNR2: 20.298





0333+32 2024/05/19 2.66UT TOYOKAWA-FUJI






T20240519113747





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0333+32 2024/05/19 2.66UT TOYOKAWA-KISO



F20240519113749





No.Good Data




Frequency (Hz)

KISO








No.Good Data




Frequency (Hz)

0333+32 2024/05/19 2.66UT FUJI -KISO








0347+05 2024/05/19 2.88UT TOYOKAWA-FUJI



T20240519115049





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0347+05 2024/05/19 2.88UT TOYOKAWA-KISO



F20240519115051





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0347+05 2024/05/19 2.88UT FUJI -KISO




T20240519120623




BLK:12,SNR1: 0.40714 ,SNR2: 5.1948




F20240519120625





BLK:12,SNR1: 0.64132E-02,SNR2: 2.9131




0403-132 2024/05/19 3.13UT TOYOKAWA-FUJI



T20240519120623





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0403-132 2024/05/19 3.13UT TOYOKAWA-KISO



F20240519120625





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0403-132 2024/05/19 3.13UT FUJI -KISO








T20240519121534




BLK:12,SNR1: 0.41977 ,SNR2: 3.0363




F20240519121536





BLK:12,SNR1: 1.2410 ,SNR2: 2.9612




0411+05 2024/05/19 3.29UT TOYOKAWA-FUJI



T20240519121534





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0411+05 2024/05/19 3.29UT TOYOKAWA-KISO



F20240519121536





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0411+05 2024/05/19 3.29UT FUJI -KISO





T20240519122627




BLK:11,SNR1: 0.81758 ,SNR2: 2.1674




F20240519122629





BLK:11,SNR1: 12.334 ,SNR2: 27.640




0422+178 2024/05/19 3.47UT TOYOKAWA-FUJI



T20240519122627





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0422+178 2024/05/19 3.47UT TOYOKAWA-KISO



F20240519122629





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0422+178 2024/05/19 3.47UT FUJI -KISO



T20240519123355





BLK:24,SNR1: 5.1133 ,SNR2: 16.332





3C119 2024/05/19 3.59UT TOYOKAWA-FUJI



F20240519123357




BLK:24,SNR1: 1.7083 ,SNR2: 8.2548



T20240519123355





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C119 2024/05/19 3.59UT TOYOKAWA-KISO






F20240519123357





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C119 2024/05/19 3.59UT FUJI -KISO



T20240519132203





BLK:28,SNR1: 2.8930 ,SNR2: 12.872





3C138 2024/05/19 4.40UT TOYOKAWA-FUJI



F20240519132205




BLK:28,SNR1: 8.0063 ,SNR2: 20.107



T20240519132203





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C138 2024/05/19 4.40UT TOYOKAWA-KISO



F20240519132205





No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)


3C138 2024/05/19 4.40UT FUJI -KISO




T20240519133536




BLK:18,SNR1: 1.2200 ,SNR2: 7.3625




F20240519133538





BLK:18,SNR1: 0.63852 ,SNR2: 3.1164




0531+194 2024/05/19 4.62UT TOYOKAWA-FUJI



T20240519133536





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0531+194 2024/05/19 4.62UT TOYOKAWA-KISO



F20240519133538





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0531+194 2024/05/19 4.62UT FUJI -KISO





T20240519134355




BLK:27,SNR1: 26.280 ,SNR2: 26.543




F20240519134357



BLK:27,SNR1: 36.366 ,SNR2: 41.712





3C147 2024/05/19 4.76UT TOYOKAWA-FUJI






T20240519134355





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C147 2024/05/19 4.76UT TOYOKAWA-KISO




F20240519134357





KISO




3C147 2024/05/19 4.76UT FUJI -KISO





T20240519135207




BLK:23,SNR1: 6.2220 ,SNR2: 15.505




F20240519135209





BLK:23,SNR1: 16.628 ,SNR2: 31.232




0548+16 2024/05/19 4.90UT TOYOKAWA-FUJI



T20240519135207




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0548+16 2024/05/19 4.90UT TOYOKAWA-KISO



F20240519135209





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0548+16 2024/05/19 4.90UT FUJI -KISO




T20240519135618




BLK:21,SNR1: 16.585 ,SNR2: 31.185




F20240519135620





BLK:21,SNR1: 13.452 ,SNR2: 24.815




0552+12 2024/05/19 4.97UT TOYOKAWA-FUJI



T20240519135618





No. Good Data




Frequency (Hz)

KISO




No. Good Data






Frequency (Hz)




0552+12 2024/05/19 4.97UT TOYOKAWA-KISO




F20240519135620



KISO





0552+12 2024/05/19 4.97UT FUJI -KISO







T20240519140045




BLK: 8,SNR1: 1.5775 ,SNR2: 5.3656




F20240519140047





BLK: 8,SNR1: 0.88613 ,SNR2: 2.9800




0556+191 2024/05/19 5.04UT TOYOKAWA-FUJI



T20240519140045





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0556+191 2024/05/19 5.04UT TOYOKAWA-KISO





F20240519140047




No.Good Data




KISO





No.Good Data




0556+191 2024/05/19 5.04UT FUJI -KISO





T20240519140831




BLK: 7,SNR1: 3.3200 ,SNR2: 8.0730




F20240519140833






BLK: 7,SNR1: 1.1537 ,SNR2: 5.9830






0605-08 2024/05/19 5.17UT TOYOKAWA-FUJI




T20240519140831






KISO



0605-08 2024/05/19 5.17UT TOYOKAWA-KISO






F20240519140833




No.Good Data

KISO





No.Good Data


0605-08 2024/05/19 5.17UT FUJI -KISO




T20240519142738




BLK:14,SNR1: 2.6745 ,SNR2: 12.556




F20240519142740





BLK:14,SNR1: 8.2366 ,SNR2: 20.470




3C161 2024/05/19 5.49UT TOYOKAWA-FUJI





T20240519142738




No.Good Data




KISO



No.Good Data





3C161 2024/05/19 5.49UT TOYOKAWA-KISO






F20240519142740





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2024/05/19 5.49UT FUJI -KISO




T20240519145512




BLK: 3,SNR1:-0.21269E-02,SNR2: 0.57085




F20240519145514





BLK: 3,SNR1: 0.73734 ,SNR2: 1.5835




0652-130 2024/05/19 5.95UT TOYOKAWA-FUJI



T20240519145512





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2024/05/19 5.95UT TOYOKAWA-KISO



F20240519145514





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2024/05/19 5.95UT FUJI -KISO





T20240519150648




BLK: 6,SNR1: 0.27268E-01,SNR2: 0.54234




F20240519150650






BLK: 6,SNR1: 0.74335 ,SNR2: 2.9574






0703+138 2024/05/19 6.14UT TOYOKAWA-FUJI




T20240519150648






KISO






0703+138 2024/05/19 6.14UT TOYOKAWA-KISO




F20240519150650





KISO




0703+138 2024/05/19 6.14UT FUJI -KISO



T20240519151611




BLK: 6,SNR1: 1.0738 ,SNR2: 7.0787




Frequency (Hz)

F20240519151613




BLK: 6,SNR1:-0.33424 ,SNR2: 1.5988






Frequency (Hz)

0713-024 2024/05/19 6.30UT TOYOKAWA-FUJI









T20240519151611






KISO






0713-024 2024/05/19 6.30UT TOYOKAWA-KISO




F20240519151613




KISO





0713-024 2024/05/19 6.30UT FUJI -KISO







BLK: 7,SNR1: 1.1260 ,SNR2: 19.866






BLK: 7,SNR1: 0.21078 ,SNR2: 3.9221






0723+10 2024/05/19 6.47UT TOYOKAWA-FUJI




T20240519152622




KISO




0723+10 2024/05/19 6.47UT TOYOKAWA-KISO



F20240519152624





No.Good Data




Frequency (Hz)

KISO








No.Good Data




Frequency (Hz)

0723+10 2024/05/19 6.47UT FUJI -KISO











0732+33 2024/05/19 6.64UT TOYOKAWA-FUJI




T20240519153637





KISO




0732+33 2024/05/19 6.64UT TOYOKAWA-KISO



F20240519153639





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0732+33 2024/05/19 6.64UT FUJI -KISO







T20240519154439




BLK: 7,SNR1: 0.52684 ,SNR2: 4.2797




F20240519154441






BLK: 7,SNR1: 1.5683 ,SNR2: 10.654






0741-06 2024/05/19 6.77UT TOYOKAWA-FUJI




T20240519154439






KISO



0741-06 2024/05/19 6.77UT TOYOKAWA-KISO






F20240519154441




No.Good Data

KISO





No.Good Data


0741-06 2024/05/19 6.77UT FUJI -KISO




T20240519155423




BLK: 8,SNR1:-0.41587E-02,SNR2: 1.0444




F20240519155425






BLK: 8,SNR1: 4.4228 ,SNR2: 13.228






0752-200 2024/05/19 6.93UT TOYOKAWA-FUJI




T20240519155423






KISO






0752-200 2024/05/19 6.93UT TOYOKAWA-KISO




F20240519155425





KISO




0752-200 2024/05/19 6.93UT FUJI -KISO



T20240519160158




BLK: 6,SNR1: 0.14463 ,SNR2: 0.42154




Frequency (Hz)

F20240519160200




BLK: 6,SNR1: 1.6515 ,SNR2: 5.8619






Frequency (Hz)




3C190 2024/05/19 7.06UT TOYOKAWA-FUJI




T20240519160158



KISO






3C190 2024/05/19 7.06UT TOYOKAWA-KISO








F20240519160200




No.Good Data

KISO





No.Good Data


3C190 2024/05/19 7.06UT FUJI -KISO




T20240519161422




BLK:12,SNR1: 0.39486 ,SNR2: 4.0732




F20240519161424






BLK:12,SNR1:-0.21258 ,SNR2: 1.0120






3C196 2024/05/19 7.27UT TOYOKAWA-FUJI




T20240519161422






KISO






3C196 2024/05/19 7.27UT TOYOKAWA-KISO




F20240519161424





KISO




3C196 2024/05/19 7.27UT FUJI -KISO



T20240519162532





BLK: 6,SNR1:-0.13602E-01,SNR2: 0.79247




Frequency (Hz)

F20240519162534




BLK: 6,SNR1: 5.7126 ,SNR2: 25.289





Frequency (Hz)


0821+394 2024/05/19 7.45UT TOYOKAWA-FUJI



T20240519162532





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)

0821+394 2024/05/19 7.45UT TOYOKAWA-KISO






F20240519162534




No.Good Data

KISO





No.Good Data


0821+394 2024/05/19 7.45UT FUJI -KISO



T20240519164218




BLK: 6,SNR1: 1.0982 ,SNR2: 6.9847




Frequency (Hz)

F20240519164220




BLK: 6,SNR1:-0.68758E-01,SNR2: 2.5239





Frequency (Hz)

0839-071 2024/05/19 7.73UT TOYOKAWA-FUJI






T20240519164218





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0839-071 2024/05/19 7.73UT TOYOKAWA-KISO



F20240519164220





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0839-071 2024/05/19 7.73UT FUJI -KISO



T20240519165319





BLK:13,SNR1: 0.62976E-01,SNR2: 0.57907




Frequency (Hz)

F20240519165321




BLK:13,SNR1: 56.616 ,SNR2: 317.31





Frequency (Hz)


3C208 2024/05/19 7.92UT TOYOKAWA-FUJI



T20240519165319





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2024/05/19 7.92UT TOYOKAWA-KISO



F20240519165321





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C208 2024/05/19 7.92UT FUJI -KISO




T20240519171000




BLK: 3,SNR1:-0.71260E-01,SNR2: 0.61035




F20240519171002





BLK: 3,SNR1: 73.290 ,SNR2: 459.51




3C216 2024/05/19 8.19UT TOYOKAWA-FUJI



T20240519171000




No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)

3C216 2024/05/19 8.19UT TOYOKAWA-KISO






F20240519171002




No.Good Data

KISO





No.Good Data

3C216 2024/05/19 8.19UT FUJI -KISO






T20240519173525





BLK: 1,SNR1: 0.12959 ,SNR2: 0.58936




Frequency (Hz)

F20240519173527




BLK: 1,SNR1: 0.57734 ,SNR2: 2.9136





Frequency (Hz)


0931+399 2024/05/19 8.62UT TOYOKAWA-FUJI



T20240519173525





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0931+399 2024/05/19 8.62UT TOYOKAWA-KISO



F20240519173527





No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

0931+399 2024/05/19 8.62UT FUJI -KISO

