



T20240526052827





BLK: 9,SNR1: 0.20712 ,SNR2: 1.6598




Frequency (Hz)

F20240526052829




BLK: 9,SNR1: 0.59642 ,SNR2: 2.4694





Frequency (Hz)


2152+450 2024/05/25 20.50UT TOYOKAWA-FUJI



T20240526052827





BLK: 8,SNR1: 0.64719E-01,SNR2: 0.49426




Frequency (Hz)

K20240526052825




BLK: 8,SNR1: 3.1687 ,SNR2: 3.8156




Frequency (Hz)


2152+450 2024/05/25 20.50UT TOYOKAWA-KISO



F20240526052829




BLK:10,SNR1: 0.72607 ,SNR2: 2.6103




Frequency (Hz)

K20240526052825




BLK:10,SNR1: 0.56952E-01,SNR2: 0.87601





Frequency (Hz)


2152+450 2024/05/25 20.50UT FUJI -KISO





T20240526053653




BLK:13,SNR1: 0.99410 ,SNR2: 8.8084




F20240526053655





BLK:13,SNR1: 3.3408 ,SNR2: 8.0506




2200+420 2024/05/25 20.64UT TOYOKAWA-FUJI





T20240526053653




BLK: 9,SNR1: 2.3965 ,SNR2: 20.324




K20240526053651





BLK: 9,SNR1: 6.8367 ,SNR2: 7.6417




2200+420 2024/05/25 20.64UT TOYOKAWA-KISO



F20240526053655





BLK:24,SNR1: 2.3390 ,SNR2: 10.750





2200+420 2024/05/25 20.64UT FUJI -KISO



K20240526053651




BLK:24,SNR1: 2.1220 ,SNR2: 5.3343




T20240526054333




BLK: 2,SNR1: 0.52137E-01,SNR2: 0.95250




F20240526054335





BLK: 2,SNR1: 0.50545E-01,SNR2: 0.99840




2207+374 2024/05/25 20.75UT TOYOKAWA-FUJI



T20240526054333





BLK: 4, SNR1: 0.16376 , SNR2: 0.50020




Frequency (Hz)

K20240526054331




BLK: 4, SNR1: 0.35946E-01, SNR2: 4.3793





Frequency (Hz)

2207+374 2024/05/25 20.75UT TOYOKAWA-KISO






F20240526054335





BLK: 3,SNR1: 0.15723 ,SNR2: 1.0640




Frequency (Hz)

K20240526054331




BLK: 3,SNR1: 0.20732E-01,SNR2: 1.2974





Frequency (Hz)


2207+374 2024/05/25 20.75UT FUJI -KISO




T20240526060330




No.Good Data




F20240526060332





No.Good Data




2227+444 2024/05/25 21.09UT TOYOKAWA-FUJI



T20240526060330




BLK: 3,SNR1: 0.23798E-01,SNR2: 0.21061




Frequency (Hz)

K20240526060328




BLK: 3,SNR1: 0.22909 ,SNR2: 2.4064




Frequency (Hz)


2227+444 2024/05/25 21.09UT TOYOKAWA-KISO



F20240526060332




BLK: 2,SNR1:-0.19382 ,SNR2: 0.47226





2227+444 2024/05/25 21.09UT FUJI -KISO



K20240526060328




BLK: 2,SNR1: 0.22938 ,SNR2: 1.9616



T20240526061538





BLK: 3,SNR1:-0.61149E-01,SNR2: 0.15022




Frequency (Hz)

F20240526061540




BLK: 3,SNR1: 0.58310E-01,SNR2: 1.0963





Frequency (Hz)


2239+333 2024/05/25 21.29UT TOYOKAWA-FUJI



T20240526061538




BLK: 2,SNR1: 0.24187 ,SNR2: 0.50802




Frequency (Hz)

K20240526061536




BLK: 2,SNR1: 1.8366 ,SNR2: 3.6405




Frequency (Hz)


2239+333 2024/05/25 21.29UT TOYOKAWA-KISO



F20240526061540





BLK: 1,SNR1: 0.18883E-01,SNR2: 0.18372




Frequency (Hz)

K20240526061536




BLK: 1,SNR1: 2.1671 ,SNR2: 18.434




Frequency (Hz)


2239+333 2024/05/25 21.29UT FUJI -KISO



T20240526061956




BLK: 8,SNR1:-0.61218E-02,SNR2: 0.53315




Frequency (Hz)

F20240526061958




BLK: 8,SNR1: 0.60410 ,SNR2: 2.0683





Frequency (Hz)

2243+394 2024/05/25 21.36UT TOYOKAWA-FUJI






T20240526061956





BLK:10,SNR1:-0.26983E-01,SNR2: 0.28619




Frequency (Hz)

K20240526061954




BLK:10,SNR1: 2.4124 ,SNR2: 5.8961





Frequency (Hz)


2243+394 2024/05/25 21.36UT TOYOKAWA-KISO



F20240526061958





BLK:21,SNR1: 0.70336 ,SNR2: 2.6356




Frequency (Hz)

K20240526061954




BLK:21,SNR1: 2.0211 ,SNR2: 3.9742





Frequency (Hz)


2243+394 2024/05/25 21.36UT FUJI -KISO



T20240526062809




BLK: 3,SNR1: 0.11310 ,SNR2: 2.1635




Frequency (Hz)

F20240526062811




BLK: 3,SNR1: 0.75914 ,SNR2: 2.1902




Frequency (Hz)


3C454.3 2024/05/25 21.50UT TOYOKAWA-FUJI



T20240526062809




BLK: 5,SNR1: 0.16231 ,SNR2: 0.87029




Frequency (Hz)

K20240526062807




BLK: 5,SNR1: 1.5505 ,SNR2: 6.5350





Frequency (Hz)


3C454.3 2024/05/25 21.50UT TOYOKAWA-KISO



F20240526062811





BLK: 4,SNR1: 0.60034 ,SNR2: 2.0679




Frequency (Hz)

K20240526062807




BLK: 4,SNR1: 0.47430 ,SNR2: 1.6162





Frequency (Hz)


3C454.3 2024/05/25 21.50UT FUJI -KISO



T20240526063552




BLK: 4,SNR1: 0.49779E-01,SNR2: 0.31004




Frequency (Hz)

F20240526063554




BLK: 4,SNR1: 0.12479 ,SNR2: 0.77565




Frequency (Hz)


2259+481 2024/05/25 21.63UT TOYOKAWA-FUJI



T20240526063552




BLK: 4,SNR1: 0.37970E-01,SNR2: 0.32863




Frequency (Hz)

K20240526063549




BLK: 4,SNR1: 0.45587 ,SNR2: 5.8130





Frequency (Hz)


2259+481 2024/05/25 21.63UT TOYOKAWA-KISO



F20240526063554





BLK: 7,SNR1: 0.26716 ,SNR2: 1.7832




Frequency (Hz)

K20240526063549




BLK: 7,SNR1:-0.37997E-01,SNR2: 0.88383




Frequency (Hz)

2259+481 2024/05/25 21.63UT FUJI -KISO






T20240526065045





BLK:10,SNR1: 1.4033 ,SNR2: 10.329




Frequency (Hz)

F20240526065047





BLK:10,SNR1: 0.18294 ,SNR2: 3.5804





Frequency (Hz)

3C459 2024/05/25 21.87UT TOYOKAWA-FUJI







BLK: 2, SNR1: 4.0105 , SNR2: 76.734





BLK: 2, SNR1: 0.15864 , SNR2: 0.63912




3C459 2024/05/25 21.87UT TOYOKAWA-KISO



F20240526065047





BLK: 5,SNR1: 0.86354 ,SNR2: 2.7272




Frequency (Hz)

K20240526065042




BLK: 5,SNR1: 0.11267 ,SNR2: 0.32714






Frequency (Hz)




3C459 2024/05/25 21.87UT FUJI -KISO




T20240526070206



F20240526070208



2325+269 2024/05/25 22.06UT TOYOKAWA-FUJI



T20240526070206



No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

2325+269 2024/05/25 22.08UT TOYOKAWA-KISO



F20240526070208





No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


2325+269 2024/05/25 22.06UT FUJI -KISO



T20240526072430





BLK: 3,SNR1: 0.30350E-01,SNR2: 1.5370




Frequency (Hz)

F20240526072432




BLK: 3,SNR1: 1.2120 ,SNR2: 4.2001





Frequency (Hz)


2347-02 2024/05/25 22.44UT TOYOKAWA-FUJI



T20240526072430





BLK: 3,SNR1: 0.18609 ,SNR2: 1.1306




Frequency (Hz)

K20240526072427




BLK: 3,SNR1: 0.26595E-01,SNR2: 0.26228





Frequency (Hz)

2347-02 2024/05/25 22.44UT TOYOKAWA-KISO






F20240526072432





BLK: 1,SNR1: 1.9694 ,SNR2: 12.617




Frequency (Hz)

K20240526072427




BLK: 1,SNR1: 0.64579 ,SNR2: 1.3367




Frequency (Hz)


2347-02 2024/05/25 22.44UT FUJI -KISO




T20240526073124




BLK: 1,SNR1: 0.10683E-01,SNR2: 0.51746




F20240526073126





BLK: 1,SNR1: 0.70994E-01,SNR2: 0.64129




2354+14 2024/05/25 22.55UT TOYOKAWA-FUJI





T20240526073124




BLK: 4,SNR1: 0.42338E-01,SNR2: 1.1400




K20240526073121





BLK: 4,SNR1: 0.81465 ,SNR2: 3.8799




2354+14 2024/05/25 22.55UT TOYOKAWA-KISO





F20240526073126




No.Good Data




K20240526073121





No.Good Data




2354+14 2024/05/25 22.55UT FUJI -KISO



T20240526074027



BLK: 8, SNR1: 0.23826 , SNR2: 1.7510





Frequency (Hz)


3C2

2024/05/25 22.70UT TOYOKAWA-FUJI


F20240526074029





BLK: 8, SNR1: 5.2646 , SNR2: 11.521




Frequency (Hz)



T20240526074027



BLK: 5, SNR1: 0.17185 , SNR2: 2.1350





Frequency (Hz)


3C2

2024/05/25 22.70UT TOYOKAWA-KISO


K20240526074024





BLK: 5, SNR1: 0.17254 , SNR2: 1.0959




Frequency (Hz)



F20240526074029



BLK:12,SNR1: 4.0170 ,SNR2: 7.3858





Frequency (Hz)


3C2

2024/05/25 22.70UT FUJI -KISO


K20240526074024




BLK:12,SNR1: 0.14223 ,SNR2: 0.56136





Frequency (Hz)







BLK: 3,SNR1: 0.15027E-01,SNR2: 0.54715



BLK: 3,SNR1: 0.58872E-02,SNR2: 1.6583





0011+344 2024/05/25 22.82UT TOYOKAWA-FUJI








T20240526074748




BLK: 4, SNR1: 0.11699 , SNR2: 0.95978




K20240526074745




BLK: 4, SNR1: 0.53414 , SNR2: 1.4044




0011+344 2024/05/25 22.82UT TOYOKAWA-KISO




F20240526074750




BLK:11,SNR1: 0.44862 ,SNR2: 1.4255




K20240526074745





BLK:11,SNR1: 0.21653 ,SNR2: 1.0208




0011+344 2024/05/25 22.82UT FUJI -KISO



T20240526075625





BLK: 4,SNR1: 0.10224 ,SNR2: 0.48139




Frequency (Hz)

F20240526075627




BLK: 4,SNR1: 0.85830 ,SNR2: 3.1223





Frequency (Hz)


0019-00 2024/05/25 22.97UT TOYOKAWA-FUJI



T20240526075625





BLK: 2,SNR1:-0.78092E-01,SNR2: 0.43542




Frequency (Hz)

K20240526075622




BLK: 2,SNR1: 1.1711 ,SNR2: 3.5204





Frequency (Hz)


0019-00 2024/05/25 22.97UT TOYOKAWA-KISO



F20240526075627




BLK: 5,SNR1:-0.43452E-01,SNR2: 2.2337




Frequency (Hz)

K20240526075622









BLK: 5,SNR1: 0.41530 ,SNR2: 2.8349







Frequency (Hz)


0019-00 2024/05/25 22.97UT FUJI -KISO









3C12 2024/05/25 23.14UT TOYOKAWA-KISO





F20240526080641




BLK: 9,SNR1: 0.39098 ,SNR2: 3.0200




K20240526080636



BLK: 9,SNR1: 0.15822 ,SNR2: 2.0715





3C12 2024/05/25 23.14UT FUJI -KISO






T20240526082041




BLK: 4, SNR1: 2.6402 , SNR2: 28.133





0044-056 2024/05/25 23.37UT TOYOKAWA-FUJI



F20240526082043




BLK: 4, SNR1: 0.22374 , SNR2: 1.5008




T20240526082041




BLK: 3,SNR1:-0.49775E-02,SNR2: 0.96208




K20240526082038





BLK: 3,SNR1: 1.2153 ,SNR2: 5.3081




0044-056 2024/05/25 23.37UT TOYOKAWA-KISO



F20240526082043





BLK: 3,SNR1: 0.15679 ,SNR2: 3.0815




Frequency (Hz)

K20240526082038




BLK: 3,SNR1: 0.64457 ,SNR2: 1.7899





Frequency (Hz)


0044-056 2024/05/25 23.37UT FUJI -KISO



T20240526082802





BLK: 9,SNR1: 0.19346 ,SNR2: 1.7982





3C26 2024/05/25 23.50UT TOYOKAWA-FUJI



F20240526082804




BLK: 9,SNR1: 0.41309 ,SNR2: 5.1706



T20240526082802



BLK:12,SNR1: 0.13775 ,SNR2: 1.5967





Frequency (Hz)


3C26

2024/05/25 23.50UT TOYOKAWA-KISO


K20240526082759





BLK:12,SNR1: 0.55356 ,SNR2: 2.2612




Frequency (Hz)





F20240526082804




BLK:14,SNR1: 0.30498 ,SNR2: 3.8342




K20240526082759





BLK:14,SNR1: 0.42982 ,SNR2: 2.8107




3C26 2024/05/25 23.50UT FUJI -KISO




T20240526083301




BLK: 4,SNR1: 0.19484 ,SNR2: 0.73580




F20240526083303





BLK: 4,SNR1:-0.14495E-01,SNR2: 0.82363




0056-00 2024/05/25 23.58UT TOYOKAWA-FUJI



T20240526083301





BLK: 6, SNR1: 0.10574 , SNR2: 0.92908





0056-00 2024/05/25 23.58UT TOYOKAWA-KISO

K20240526083258





BLK: 6, SNR1: 0.12785 , SNR2: 1.4684








F20240526083303




BLK: 3,SNR1: 0.76707E-01,SNR2: 1.0788




K20240526083258





BLK: 3,SNR1: 1.2618 ,SNR2: 4.9961




0056-00 2024/05/25 23.58UT FUJI -KISO



T20240526084243




BLK: 5,SNR1: 0.28916E-01,SNR2: 1.5673





0106+01 2024/05/25 23.74UT TOYOKAWA-FUJI


F20240526084245




BLK: 5,SNR1: 0.21705 ,SNR2: 7.0030



T20240526084243





BLK: 3,SNR1: 0.98972E-01,SNR2: 1.0370





0106+01 2024/05/25 23.74UT TOYOKAWA-KISO


K20240526084240




BLK: 3,SNR1: 0.19343 ,SNR2: 1.4403





F20240526084245




BLK: 5,SNR1: 0.45148 ,SNR2: 4.5657




K20240526084240





BLK: 5,SNR1: 0.82652 ,SNR2: 3.8732




0106+01 2024/05/25 23.74UT FUJI -KISO



T20240526085333





BLK: 8,SNR1: 0.14097 ,SNR2: 1.8736





0116+31 2024/05/25 23.92UT TOYOKAWA-FUJI



F20240526085335




BLK: 8,SNR1: 0.92617 ,SNR2: 2.7081



T20240526085333





BLK: 7,SNR1: 0.10231 ,SNR2: 2.9879





0116+31 2024/05/25 23.92UT TOYOKAWA-KISO



K20240526085330




BLK: 7,SNR1: 0.14223 ,SNR2: 0.63103





F20240526085335




BLK:10,SNR1: 0.98137 ,SNR2: 4.2473




K20240526085330





BLK:10,SNR1: 0.55032 ,SNR2: 2.5002




0116+31 2024/05/25 23.92UT FUJI -KISO





T20240526090506




BLK: 9,SNR1: 0.24588 ,SNR2: 1.5522




F20240526090508



BLK: 9,SNR1: 0.52300 ,SNR2: 3.2970





0128+03 2024/05/26 0.11UT TOYOKAWA-FUJI






T20240526090506





BLK:12,SNR1: 0.20067 ,SNR2: 0.88204





0128+03 2024/05/26 0.11UT TOYOKAWA-KISO


K20240526090503




BLK:12,SNR1: 0.19553 ,SNR2: 2.8952



F20240526090508





BLK: 7,SNR1: 0.84792 ,SNR2: 5.4069




Frequency (Hz)

K20240526090503








BLK: 7,SNR1: 0.29638 ,SNR2: 1.7141




Frequency (Hz)

0128+03 2024/05/26 0.11UT FUJI -KISO







3C48 2024/05/26 0.22UT TOYOKAWA-FUJI



T20240526091139




BLK:30,SNR1: 4.0792 ,SNR2: 28.680









3C48 2024/05/26 0.22UT TOYOKAWA-KISO

K20240526091136




BLK:30,SNR1: 0.45004 ,SNR2: 2.1960








3C48 2024/05/26 0.22UT FUJI -KISO



T20240526093124




BLK: 8, SNR1: 1.7330 ,SNR2: 8.3077





0155-109 2024/05/26 0.55UT TOYOKAWA-FUJI



F20240526093126




BLK: 8, SNR1: 3.1145 ,SNR2: 11.094



T20240526093124




BLK:14,SNR1: 1.3971 ,SNR2: 6.6008





0155-109 2024/05/26 0.55UT TOYOKAWA-KISO



K20240526093122




BLK:14,SNR1: 1.2534 ,SNR2: 4.2486




F20240526093126




BLK:21,SNR1: 3.3352 ,SNR2: 4.5758




K20240526093122



BLK:21,SNR1: 3.3602 ,SNR2: 4.9286




0155-109 2024/05/26 0.55UT FUJI -KISO






T20240526093831





BLK:12,SNR1: 0.28416 ,SNR2: 3.9338





0202+15 2024/05/26 0.67UT TOYOKAWA-FUJI


F20240526093833




BLK:12,SNR1: 0.26550 ,SNR2: 0.81255





T20240526093831




BLK: 7,SNR1: 0.29850 ,SNR2: 1.7962




K20240526093829




BLK: 7,SNR1: 0.31105 ,SNR2: 2.1300




0202+15 2024/05/26 0.67UT TOYOKAWA-KISO





F20240526093833




BLK: 3,SNR1: 0.82966 ,SNR2: 1.7312




K20240526093829





BLK: 3,SNR1: 0.21343 ,SNR2: 1.1857




0202+15 2024/05/26 0.67UT FUJI -KISO




T20240526095021




BLK: 6,SNR1: 0.18591E-01,SNR2: 0.97152




F20240526095023





BLK: 6,SNR1: 1.1749 ,SNR2: 5.2329




0213+178 2024/05/26 0.87UT TOYOKAWA-FUJI





T20240526095021




BLK: 2,SNR1: 0.96487E-01,SNR2: 0.71665




K20240526095018







BLK: 2,SNR1: 0.31215 ,SNR2: 1.6270




0213+178 2024/05/26 0.87UT TOYOKAWA-KISO








0213+178 2024/05/26 0.87UT FUJI -KISO



T20240526095804




BLK:21,SNR1: 1.4427 ,SNR2: 3.4272





3C67 2024/05/26 1.00UT TOYOKAWA-FUJI



F20240526095806




BLK:21,SNR1: 1.6694 ,SNR2: 4.4596



T20240526095804




BLK:22,SNR1: 2.1195 ,SNR2: 4.9754





3C67 2024/05/26 1.00UT TOYOKAWA-KISO





K20240526095801




BLK:22,SNR1: 2.0644 ,SNR2: 8.2944










3C67 2024/05/26 1.00UT FUJI -KISO



T20240526101619




BLK:15,SNR1: 1.6810 ,SNR2: 6.2905





3C71 2024/05/26 1.30UT TOYOKAWA-FUJI



F20240526101621




BLK:15,SNR1: 5.3017 ,SNR2: 13.007



T20240526101619





BLK:13,SNR1: 1.9822 ,SNR2: 7.6113





3C71 2024/05/26 1.30UT TOYOKAWA-KISO


K20240526101616




BLK:13,SNR1: 10.059 ,SNR2: 17.756



F20240526101621





BLK:19,SNR1: 4.5642 ,SNR2: 11.232





3C71 2024/05/26 1.30UT FUJI -KISO



K20240526101616




BLK:19,SNR1: 8.5052 ,SNR2: 15.013





T20240526103534




BLK: 6,SNR1: 0.46875 ,SNR2: 2.3200




F20240526103536





BLK: 6,SNR1: 0.87836 ,SNR2: 2.2910




0258+350 2024/05/26 1.62UT TOYOKAWA-FUJI





T20240526103534




BLK: 8,SNR1: 0.66225 ,SNR2: 2.7668




K20240526103531





BLK: 8,SNR1: 2.7700 ,SNR2: 9.9664




0258+350 2024/05/26 1.62UT TOYOKAWA-KISO





F20240526103536




BLK: 3,SNR1: 0.35376 ,SNR2: 4.1696




K20240526103531





BLK: 3,SNR1: 0.48864 ,SNR2: 2.2303




0258+350 2024/05/26 1.62UT FUJI -KISO




T20240526104523




BLK:23,SNR1: 3.4449 ,SNR2: 8.1862




F20240526104525



BLK:23,SNR1: 4.7493 ,SNR2: 11.832





0308+305 2024/05/26 1.78UT TOYOKAWA-FUJI






T20240526104523





BLK:23,SNR1: 6.7449 ,SNR2: 19.650





0308+305 2024/05/26 1.78UT TOYOKAWA-KISO


K20240526104520




BLK:23,SNR1: 21.188 ,SNR2: 27.425




F20240526104525




BLK:27,SNR1: 5.2153 ,SNR2: 13.042




K20240526104520




BLK:27,SNR1: 4.0216 ,SNR2: 11.077




0308+305 2024/05/26 1.78UT FUJI -KISO




T20240526105655




BLK:24,SNR1: 1.4933 ,SNR2: 10.867




F20240526105657




BLK:24,SNR1: 0.31031E-01,SNR2: 2.0065




0320+05 2024/05/26 1.98UT TOYOKAWA-FUJI




T20240526105655




BLK:33,SNR1: 1.5483 ,SNR2: 12.954




K20240526105652




BLK:33,SNR1: 0.38843 ,SNR2: 2.5551




0320+05 2024/05/26 1.98UT TOYOKAWA-KISO




F20240526105657




BLK:16,SNR1: 0.50310E-01,SNR2: 1.1034




K20240526105652




BLK:16,SNR1: 0.28622 ,SNR2: 1.3356




0320+05 2024/05/26 1.98UT FUJI -KISO




T20240526111016




BLK:13,SNR1: 0.46255 ,SNR2: 1.8832




F20240526111018




BLK:13,SNR1: 0.20039 ,SNR2: 0.88752




0333+32 2024/05/26 2.20UT TOYOKAWA-FUJI




T20240526111016




BLK: 7,SNR1: 0.61253 ,SNR2: 2.6361




K20240526111013




BLK: 7,SNR1: 0.27536 ,SNR2: 1.2593




0333+32 2024/05/26 2.20UT TOYOKAWA-KISO




F20240526111018




BLK: 7,SNR1: 1.3869 ,SNR2: 1.7866




K20240526111013



BLK: 7,SNR1: 0.29647 ,SNR2: 1.0311





0333+32 2024/05/26 2.20UT FUJI -KISO







T20240526112318




BLK:17,SNR1: 1.8617 ,SNR2: 4.6279




F20240526112320





BLK:17,SNR1: 0.90868 ,SNR2: 2.2643




0347+05 2024/05/26 2.42UT TOYOKAWA-FUJI




T20240526112318




BLK:21,SNR1: 1.6675 ,SNR2: 4.1705




K20240526112315







BLK:21,SNR1: 2.3754 ,SNR2: 7.7963




0347+05 2024/05/26 2.42UT TOYOKAWA-KISO







0347+05 2024/05/26 2.42UT FUJI -KISO





T20240526113852




BLK:30,SNR1: 11.670 ,SNR2: 28.250




F20240526113854




BLK:30,SNR1: 18.883 ,SNR2: 35.099




0403-132 2024/05/26 2.68UT TOYOKAWA-FUJI



T20240526113852





BLK:30,SNR1: 11.653 ,SNR2: 28.209





0403-132 2024/05/26 2.68UT TOYOKAWA-KISO


K20240526113849




BLK:30,SNR1: 14.175 ,SNR2: 25.092



F20240526113854





BLK:34,SNR1: 18.705 ,SNR2: 34.767





0403-132 2024/05/26 2.68UT FUJI -KISO


K20240526113849




BLK:34,SNR1: 14.117 ,SNR2: 24.990





T20240526114803




BLK:21,SNR1: 2.0617 ,SNR2: 7.1508




F20240526114805





BLK:21,SNR1: 17.756 ,SNR2: 32.402




0411+05 2024/05/26 2.83UT TOYOKAWA-FUJI




T20240526114803




BLK:23,SNR1: 1.8512 ,SNR2: 6.8299




K20240526114801



BLK:23,SNR1: 6.0675 ,SNR2: 15.661




0411+05 2024/05/26 2.83UT TOYOKAWA-KISO






F20240526114805





BLK:18,SNR1: 18.654 ,SNR2: 34.348





0411+05 2024/05/26 2.83UT FUJI -KISO



K20240526114801




BLK:18,SNR1: 6.3287 ,SNR2: 16.359



T20240526115856





BLK:21,SNR1: 3.5998 ,SNR2: 6.2375




Frequency (Hz)

F20240526115858




BLK:21,SNR1: 0.85062 ,SNR2: 3.2577





Frequency (Hz)


0422+178 2024/05/26 3.01UT TOYOKAWA-FUJI



T20240526115856





BLK:27,SNR1: 3.1124 ,SNR2: 5.4284





0422+178 2024/05/26 3.01UT TOYOKAWA-KISO



K20240526115854




BLK:27,SNR1: 1.5059 ,SNR2: 5.5712



F20240526115858





BLK:20,SNR1: 0.41708 ,SNR2: 2.9058




Frequency (Hz)

K20240526115854




BLK:20,SNR1: 1.6890 ,SNR2: 6.0920





Frequency (Hz)


0422+178 2024/05/26 3.01UT FUJI -KISO




T20240526120624




BLK:28,SNR1: 4.4072 ,SNR2: 13.773




F20240526120626





BLK:28,SNR1:-0.75478E-02,SNR2: 2.7750




3C119 2024/05/26 3.13UT TOYOKAWA-FUJI





T20240526120624




BLK:36,SNR1: 4.2949 ,SNR2: 9.7942




K20240526120621




BLK:36,SNR1: 0.72725 ,SNR2: 5.8336




3C119 2024/05/26 3.13UT TOYOKAWA-KISO




F20240526120626




BLK:26,SNR1:-0.22714E-01,SNR2: 2.4828




K20240526120621





BLK:26,SNR1: 0.91461 ,SNR2: 4.6445




3C119 2024/05/26 3.13UT FUJI -KISO





T20240526125431




BLK:27,SNR1: 5.7148 ,SNR2: 36.237




F20240526125433



BLK:27,SNR1: 0.11708 ,SNR2: 1.9816





3C138 2024/05/26 3.94UT TOYOKAWA-FUJI








T20240526125431




BLK:32,SNR1: 5.0974 ,SNR2: 33.425




K20240526125428




BLK:32,SNR1: 0.85333 ,SNR2: 3.2182




3C138 2024/05/26 3.94UT TOYOKAWA-KISO



F20240526125433





BLK:30,SNR1: 0.57517E-01,SNR2: 2.8532





3C138 2024/05/26 3.94UT FUJI -KISO



K20240526125428




BLK:30,SNR1: 0.83379 ,SNR2: 3.0030




T20240526130805




BLK:13,SNR1: 1.6957 ,SNR2: 7.3395




F20240526130807




BLK:13,SNR1:-0.13673E-01,SNR2: 0.94199




0531+194 2024/05/26 4.16UT TOYOKAWA-FUJI




T20240526130805




BLK:27,SNR1: 1.7260 ,SNR2: 11.400




K20240526130802




BLK:27,SNR1: 0.46415 ,SNR2: 2.7152




0531+194 2024/05/26 4.16UT TOYOKAWA-KISO




F20240526130807




BLK:14,SNR1:-0.41060E-01,SNR2: 1.1832




K20240526130802




BLK:14,SNR1: 0.30013 ,SNR2: 1.3185




0531+194 2024/05/26 4.16UT FUJI -KISO



T20240526131624




BLK:25,SNR1: 3.8194 ,SNR2: 19.494





3C147 2024/05/26 4.30UT TOYOKAWA-FUJI



F20240526131626




BLK:25,SNR1: 0.72496 ,SNR2: 3.6228




T20240526131624




BLK:32,SNR1: 4.2715 ,SNR2: 15.671




K20240526131622





BLK:32,SNR1: 0.54573 ,SNR2: 3.1894




3C147 2024/05/26 4.30UT TOYOKAWA-KISO




F20240526131626




BLK:22,SNR1: 0.43419 ,SNR2: 3.4829




K20240526131622



BLK:22,SNR1: 0.55675 ,SNR2: 6.2775




3C147 2024/05/26 4.30UT FUJI -KISO







T20240526132436




BLK:19,SNR1: 0.43513 ,SNR2: 3.8982




F20240526132438





BLK:19,SNR1: 0.38998 ,SNR2: 3.4704




0548+16 2024/05/26 4.44UT TOYOKAWA-FUJI





T20240526132436




BLK:19,SNR1: 0.55002 ,SNR2: 5.0944




K20240526132434





BLK:19,SNR1: 0.47166 ,SNR2: 1.4233




0548+16 2024/05/26 4.44UT TOYOKAWA-KISO





F20240526132438




BLK:11,SNR1: 0.72504 ,SNR2: 4.8675




K20240526132434




BLK:11,SNR1: 0.38078 ,SNR2: 2.1305




0548+16 2024/05/26 4.44UT FUJI -KISO





T20240526132846




BLK: 8,SNR1: 2.8223 ,SNR2: 15.752




F20240526132848




BLK: 8,SNR1: 4.7858 ,SNR2: 15.141




0552+12 2024/05/26 4.51UT TOYOKAWA-FUJI





T20240526132846




BLK:12,SNR1: 1.8596 ,SNR2: 8.2478




K20240526132844





BLK:12,SNR1: 0.85159 ,SNR2: 3.5146




0552+12 2024/05/26 4.51UT TOYOKAWA-KISO





F20240526132848




BLK: 6,SNR1: 1.3635 ,SNR2: 4.6530




K20240526132844





BLK: 6,SNR1: 0.44968 ,SNR2: 2.0473




0552+12 2024/05/26 4.51UT FUJI -KISO




T20240526133313




BLK: 9,SNR1: 0.93848E-01,SNR2: 1.0312




F20240526133315





BLK: 9,SNR1: 4.6618 ,SNR2: 15.783




0556+191 2024/05/26 4.58UT TOYOKAWA-FUJI





T20240526133313




BLK:10,SNR1: 0.14576 ,SNR2: 1.1918




K20240526133311



BLK:10,SNR1: 0.50147 ,SNR2: 3.0916





0556+191 2024/05/26 4.58UT TOYOKAWA-KISO








F20240526133315




BLK: 6,SNR1: 8.0211 ,SNR2: 17.160




K20240526133311





BLK: 6,SNR1: 0.66221E-01,SNR2: 1.9029




0556+191 2024/05/26 4.58UT FUJI -KISO





T20240526134059




BLK: 8,SNR1: 10.893 ,SNR2: 26.716




F20240526134101




BLK: 8,SNR1: 11.659 ,SNR2: 31.519




0605-08 2024/05/26 4.71UT TOYOKAWA-FUJI



T20240526134059




BLK:11,SNR1: 6.9363 ,SNR2: 22.344





0605-08 2024/05/26 4.71UT TOYOKAWA-KISO


K20240526134057




BLK:11,SNR1: 1.7034 ,SNR2: 11.750




F20240526134101




BLK: 9,SNR1: 9.7240 ,SNR2: 26.418




K20240526134057





BLK: 9,SNR1: 1.8739 ,SNR2: 9.9276




0605-08 2024/05/26 4.71UT FUJI -KISO




T20240526140007




BLK:13,SNR1: 0.61664 ,SNR2: 5.2654




F20240526140009




BLK:13,SNR1: 4.5910 ,SNR2: 10.240




3C161 2024/05/26 5.03UT TOYOKAWA-FUJI




T20240526140007




BLK:32,SNR1: 0.84473 ,SNR2: 4.3239




K20240526140005





BLK:32,SNR1: 0.40888 ,SNR2: 2.1111




3C161 2024/05/26 5.03UT TOYOKAWA-KISO





F20240526140009




BLK:14,SNR1: 4.0945 ,SNR2: 14.643




K20240526140005




BLK:14,SNR1: 0.77913 ,SNR2: 2.9800




3C161 2024/05/26 5.03UT FUJI -KISO




T20240526142740




BLK: 3,SNR1: 0.30769 ,SNR2: 1.5639




F20240526142742



BLK: 3,SNR1: 0.18153 ,SNR2: 1.5603





0652-130 2024/05/26 5.49UT TOYOKAWA-FUJI








T20240526142740




BLK: 2,SNR1: 0.14447 ,SNR2: 1.9007




K20240526142737





BLK: 2,SNR1:-0.16167 ,SNR2: 0.20350




0652-130 2024/05/26 5.49UT TOYOKAWA-KISO





F20240526142742




BLK: 2,SNR1:-0.76060E-01,SNR2: 0.33753




K20240526142737





BLK: 2,SNR1:-0.37216E-01,SNR2: 0.30672




0652-130 2024/05/26 5.49UT FUJI -KISO





T20240526143916




BLK: 3,SNR1: 0.33787E-01,SNR2: 0.27689




F20240526143918





BLK: 3,SNR1:-0.14286 ,SNR2: 0.0000




0703+138 2024/05/26 5.68UT TOYOKAWA-FUJI



T20240526143916





BLK: 3,SNR1:-0.16674 ,SNR2: 0.0000




Frequency (Hz)

K20240526143913




BLK: 3,SNR1: 0.50611 ,SNR2: 3.2532




Frequency (Hz)


0703+138 2024/05/26 5.68UT TOYOKAWA-KISO





F20240526143918




BLK: 4,SNR1: 0.34676E-01,SNR2: 0.77142




K20240526143913





BLK: 4,SNR1: 1.4328 ,SNR2: 5.2844




0703+138 2024/05/26 5.68UT FUJI -KISO



T20240526144839





BLK: 4,SNR1: 0.54741 ,SNR2: 3.7832




Frequency (Hz)

F20240526144841




BLK: 4,SNR1: 0.21252E-01,SNR2: 1.2611





Frequency (Hz)


0713-024 2024/05/26 5.84UT TOYOKAWA-FUJI



T20240526144839





BLK: 5,SNR1: 0.23360 ,SNR2: 1.9949




Frequency (Hz)

K20240526144837




BLK: 5,SNR1: 0.91202 ,SNR2: 8.5096





Frequency (Hz)


0713-024 2024/05/26 5.84UT TOYOKAWA-KISO



F20240526144841





BLK: 3,SNR1: 0.56158 ,SNR2: 1.9043




Frequency (Hz)

K20240526144837




BLK: 3,SNR1: 0.19620 ,SNR2: 0.99273





Frequency (Hz)

0713-024 2024/05/26 5.84UT FUJI -KISO






T20240526145851





BLK: 4,SNR1: 0.23056 ,SNR2: 1.4365




Frequency (Hz)

F20240526145853




BLK: 4,SNR1: 0.12797 ,SNR2: 0.67833





Frequency (Hz)


0723+10 2024/05/26 6.01UT TOYOKAWA-FUJI



T20240526145851





BLK: 7,SNR1: 0.25779 ,SNR2: 1.1543




Frequency (Hz)

K20240526145849




BLK: 7,SNR1: 0.44174 ,SNR2: 1.9022





Frequency (Hz)


0723+10 2024/05/26 6.01UT TOYOKAWA-KISO





F20240526145853




BLK: 5,SNR1:-0.53347E-01,SNR2: 0.54144




K20240526145849





BLK: 5,SNR1: 0.13714 ,SNR2: 1.0851




0723+10 2024/05/26 6.01UT FUJI -KISO



T20240526150905




BLK: 7,SNR1: 0.10218 ,SNR2: 0.41377




Frequency (Hz)

F20240526150907




BLK: 7,SNR1: 0.12732 ,SNR2: 2.8509





Frequency (Hz)


0732+33 2024/05/26 6.18UT TOYOKAWA-FUJI



T20240526150905





BLK: 5,SNR1: 0.14451 ,SNR2: 0.57401




Frequency (Hz)

K20240526150902




BLK: 5,SNR1: 0.13253 ,SNR2: 1.7985




Frequency (Hz)


0732+33 2024/05/26 6.18UT TOYOKAWA-KISO





F20240526150907




BLK: 3,SNR1: 2.0455 ,SNR2: 8.2243




K20240526150902





BLK: 3,SNR1: 0.75085E-02,SNR2: 0.70832




0732+33 2024/05/26 6.18UT FUJI -KISO



T20240526151708




BLK: 7,SNR1:-0.55588E-01,SNR2: 1.3613




Frequency (Hz)

F20240526151710




BLK: 7,SNR1: 0.57733E-01,SNR2: 1.7572





Frequency (Hz)


0741-06 2024/05/26 6.31UT TOYOKAWA-FUJI



T20240526151708





BLK: 2,SNR1: 0.18718 ,SNR2: 3.0635




Frequency (Hz)

K20240526151705




BLK: 2,SNR1: 1.0218 ,SNR2: 4.1970




Frequency (Hz)

0741-06 2024/05/26 6.31UT TOYOKAWA-KISO







F20240526151710




BLK: 5,SNR1: 0.26644 ,SNR2: 3.7699




K20240526151705




BLK: 5,SNR1: 0.41200 ,SNR2: 1.5174




0741-06 2024/05/26 6.31UT FUJI -KISO



T20240526152652





BLK: 7,SNR1: 0.37576E-01,SNR2: 1.3772




Frequency (Hz)

F20240526152654




BLK: 7,SNR1: 0.57709E-02,SNR2: 0.26342





Frequency (Hz)


0752-200 2024/05/26 6.48UT TOYOKAWA-FUJI





T20240526152652




BLK: 6,SNR1: 0.13168 ,SNR2: 2.2228




K20240526152649





BLK: 6,SNR1: 1.2113 ,SNR2: 7.1389




0752-200 2024/05/26 6.48UT TOYOKAWA-KISO




F20240526152654




BLK: 3,SNR1: 0.85399E-01,SNR2: 0.92125




K20240526152649





BLK: 3,SNR1: 0.35076 ,SNR2: 1.0968




0752-200 2024/05/26 6.48UT FUJI -KISO




T20240526153427




BLK: 7,SNR1: 0.90724E-01,SNR2: 0.51940




F20240526153429





BLK: 7,SNR1: 0.28529 ,SNR2: 1.7196




3C190 2024/05/26 6.60UT TOYOKAWA-FUJI





T20240526153427




BLK:10,SNR1: 0.67743E-01,SNR2: 0.49193




K20240526153424




BLK:10,SNR1: 2.2399 ,SNR2: 10.345




3C190 2024/05/26 6.60UT TOYOKAWA-KISO



F20240526153429




BLK:13,SNR1: 0.14661 ,SNR2: 1.3056




Frequency (Hz)

K20240526153424




BLK:13,SNR1: 2.8269 ,SNR2: 12.569




Frequency (Hz)


3C190 2024/05/26 6.60UT FUJI -KISO



T20240526154651




BLK: 9,SNR1: 0.12355 ,SNR2: 1.0849




Frequency (Hz)

F20240526154653




BLK: 9,SNR1: 0.28858 ,SNR2: 2.1662




Frequency (Hz)

3C196 2024/05/26 6.81UT TOYOKAWA-FUJI







T20240526154651




BLK: 5,SNR1: 0.35985 ,SNR2: 1.0822




K20240526154648




BLK: 5,SNR1: 0.94907E-01,SNR2: 0.46574




3C196 2024/05/26 6.81UT TOYOKAWA-KISO



F20240526154653




BLK: 4,SNR1: 0.99281E-01,SNR2: 0.93568




Frequency (Hz)

K20240526154648




BLK: 4,SNR1: 0.82830,SNR2: 4.2175




Frequency (Hz)


3C196 2024/05/26 6.81UT FUJI -KISO




T20240526155801




BLK: 1,SNR1:-0.99438E-01,SNR2: 0.59237E-01




F20240526155803




BLK: 1,SNR1: 0.27367 ,SNR2: 1.8423




0821+394 2024/05/26 7.00UT TOYOKAWA-FUJI





T20240526155801




BLK: 4,SNR1: 0.50195 ,SNR2: 10.184




K20240526155758




BLK: 4,SNR1: 0.54104 ,SNR2: 2.9571




0821+394 2024/05/26 7.00UT TOYOKAWA-KISO



F20240526155803





BLK: 4, SNR1: 0.47898E-01, SNR2: 1.5964




Frequency (Hz)

K20240526155758




BLK: 4, SNR1: 0.23649, SNR2: 1.2883





Frequency (Hz)


0821+394 2024/05/26 7.00UT FUJI -KISO



T20240526160941





BLK: 8,SNR1: 0.13916 ,SNR2: 1.2098




Frequency (Hz)

F20240526160943






BLK: 8,SNR1:-0.55667E-01,SNR2: 1.1947




Frequency (Hz)

0834-19 2024/05/26 7.19UT TOYOKAWA-FUJI







0834-19 2024/05/26 7.19UT TOYOKAWA-KISO



F20240526160943





BLK: 3,SNR1: 0.33002E-01,SNR2: 1.6436




Frequency (Hz)

K20240526160938




BLK: 3,SNR1:-0.75209E-01,SNR2: 3.3885





Frequency (Hz)

0834-19 2024/05/26 7.19UT FUJI -KISO






T20240526161447





BLK: 2,SNR1: 0.17105 ,SNR2: 0.64920




Frequency (Hz)

F20240526161449




BLK: 2,SNR1:-0.95804E-01,SNR2: 1.3537





Frequency (Hz)


0839-071 2024/05/26 7.27UT TOYOKAWA-FUJI



T20240526161447





BLK: 5,SNR1: 15.468 ,SNR2: 104.25




Frequency (Hz)

K20240526161444




BLK: 5,SNR1: 0.48485 ,SNR2: 2.2331




Frequency (Hz)


0839-071 2024/05/26 7.27UT TOYOKAWA-KISO



F20240526161449





BLK: 4, SNR1: -0.13357 , SNR2: 0.77056




Frequency (Hz)

K20240526161444




BLK: 4, SNR1: 0.65458 , SNR2: 3.0671





Frequency (Hz)


0839-071 2024/05/26 7.27UT FUJI -KISO




T20240526162547




BLK: 4,SNR1: 0.67987E-01,SNR2: 0.43398




F20240526162549





BLK: 4,SNR1:-0.10997 ,SNR2: 0.43122




3C208 2024/05/26 7.46UT TOYOKAWA-FUJI



T20240526162547





BLK: 3,SNR1: 0.58529E-01,SNR2: 0.33682




Frequency (Hz)

K20240526162544




BLK: 3,SNR1: 1.4272 ,SNR2: 6.3060




Frequency (Hz)


3C208 2024/05/26 7.46UT TOYOKAWA-KISO



F20240526162549





BLK: 7,SNR1: 0.64820 ,SNR2: 1.3609




Frequency (Hz)

K20240526162544




BLK: 7,SNR1: 0.94236 ,SNR2: 6.5528





Frequency (Hz)


3C208 2024/05/26 7.46UT FUJI -KISO



T20240526164229





BLK: 1,SNR1: 0.18051 ,SNR2: 0.0000




Frequency (Hz)

F20240526164231




BLK: 1,SNR1: 0.85537 ,SNR2: 4.0102





Frequency (Hz)


3C216 2024/05/26 7.74UT TOYOKAWA-FUJI



T20240526164229




BLK: 1,SNR1: 0.12101 ,SNR2: 0.46082




Frequency (Hz)

K20240526164226




BLK: 1,SNR1: 0.56489E-01,SNR2: 0.17839





Frequency (Hz)

3C216 2024/05/26 7.74UT TOYOKAWA-KISO






F20240526164231




BLK: 2,SNR1: 0.34674 ,SNR2: 4.6177




Frequency (Hz)

K20240526164226






BLK: 2,SNR1: 0.19546 ,SNR2: 0.14898




Frequency (Hz)

3C216 2024/05/26 7.74UT FUJI -KISO








BLK: 4,SNR1: 0.59509 ,SNR2: 5.9895



Frequency (Hz)






BLK: 4,SNR1: 0.53765 ,SNR2: 1.1857




Frequency (Hz)

0926+117 2024/05/26 8.05UT TOYOKAWA-FUJI







0926+117 2024/05/26 8.05UT TOYOKAWA-KISO



F20240526170121





BLK: 4,SNR1: 0.37505 ,SNR2: 1.4794




Frequency (Hz)

K20240526170117





BLK: 4,SNR1: 0.27880 ,SNR2: 1.1253





Frequency (Hz)

0926+117 2024/05/26 8.05UT FUJI -KISO







BLK: 8,SNR1: 2.1385 ,SNR2: 15.520





BLK: 8,SNR1: 0.99600E-01,SNR2: 0.70404




3C225 2024/05/26 8.27UT TOYOKAWA-FUJI







3C225 2024/05/26 8.27UT TOYOKAWA-KISO



F20240526171449





BLK: 5,SNR1: 0.45735 ,SNR2: 1.3650




Frequency (Hz)

K20240526171444




BLK: 5,SNR1: 0.51170 ,SNR2: 2.2381





Frequency (Hz)


3C225 2024/05/26 8.27UT FUJI -KISO



T20240526173833




BLK:10,SNR1: 0.77820 ,SNR2: 2.1574




Frequency (Hz)

F20240526173835




BLK:10,SNR1: 0.24730 ,SNR2: 2.7740





Frequency (Hz)


3C236 2024/05/26 8.67UT TOYOKAWA-FUJI










3C236 2024/05/26 8.67UT TOYOKAWA-KISO



F20240526173835




BLK: 6,SNR1: 0.33698 ,SNR2: 2.0379




Frequency (Hz)

K20240526173831



BLK: 6,SNR1: 1.7919 ,SNR2: 7.0334



Frequency (Hz)

3C236 2024/05/26 8.67UT FUJI -KISO

