




T20240530053857




BLK: 6,SNR1: 0.16128E-01,SNR2: 0.32379




F20240530053859





BLK: 6,SNR1: 0.39723 ,SNR2: 2.1241




2218+395 2024/05/29 20.68UT TOYOKAWA-FUJI



T20240530053857





BLK: 1,SNR1: 0.43907 ,SNR2: 0.75775




Frequency (Hz)

K20240530053855




BLK: 1,SNR1: 1.5362 ,SNR2: 9.8468





Frequency (Hz)


2218+395 2024/05/29 20.68UT TOYOKAWA-KISO



F20240530053859





BLK: 6,SNR1: 0.72502E-01,SNR2: 3.2510




Frequency (Hz)

K20240530053855




BLK: 6,SNR1: 0.44725 ,SNR2: 3.1783





Frequency (Hz)


2218+395 2024/05/29 20.68UT FUJI -KISO



T20240530054746





BLK: 6,SNR1: 1.2652 ,SNR2: 7.7385




Frequency (Hz)

F20240530054748




BLK: 6,SNR1: 0.26939 ,SNR2: 3.2231





Frequency (Hz)


2227+444 2024/05/29 20.82UT TOYOKAWA-FUJI



T20240530054746





BLK: 7,SNR1: 0.28986 ,SNR2: 4.7171




Frequency (Hz)

2227+444 2024/05/29 20.82UT TOYOKAWA-KISO


K20240530054744




BLK: 7,SNR1: 0.94581 ,SNR2: 4.6060




Frequency (Hz)




F20240530054748




BLK: 9,SNR1: 1.0720 ,SNR2: 5.7538




K20240530054744





BLK: 9,SNR1: 0.61260 ,SNR2: 2.8036




2227+444 2024/05/29 20.82UT FUJI -KISO



T20240530055955





BLK:11,SNR1: 5.6269 ,SNR2: 62.936




Frequency (Hz)

F20240530055957




BLK:11,SNR1: 0.44385 ,SNR2: 4.5516





Frequency (Hz)


2239+333 2024/05/29 21.03UT TOYOKAWA-FUJI



T20240530055955





BLK: 9,SNR1: 6.5348 ,SNR2: 24.619




Frequency (Hz)

K20240530055953




BLK: 9,SNR1: 0.33994 ,SNR2: 2.9099




Frequency (Hz)

2239+333 2024/05/29 21.03UT TOYOKAWA-KISO






F20240530055957




BLK:13,SNR1: 0.90313 ,SNR2: 3.2717




Frequency (Hz)

K20240530055953




BLK:13,SNR1: 0.31182 ,SNR2: 1.9457





Frequency (Hz)


2239+333 2024/05/29 21.03UT FUJI -KISO





T20240530060412




No.Good Data




F20240530060414





No.Good Data




2243+394 2024/05/29 21.10UT TOYOKAWA-FUJI





T20240530060412




BLK: 4,SNR1: 0.77059E-01,SNR2: 0.80183




K20240530060410




BLK: 4,SNR1: 0.26284 ,SNR2: 0.86922




2243+394 2024/05/29 21.10UT TOYOKAWA-KISO




F20240530060414




BLK: 6,SNR1:-0.17345 ,SNR2: 1.3012




K20240530060410




BLK: 6,SNR1: 0.86367 ,SNR2: 3.6517




2243+394 2024/05/29 21.10UT FUJI -KISO



T20240530061226




BLK: 9,SNR1: 0.50003 ,SNR2: 2.2307




Frequency (Hz)

F20240530061228




BLK: 9,SNR1: 0.22409 ,SNR2: 1.3753





Frequency (Hz)


3C454.3 2024/05/29 21.24UT TOYOKAWA-FUJI



T20240530061226





BLK:12,SNR1: 0.41425 ,SNR2: 1.7484




Frequency (Hz)

K20240530061224




BLK:12,SNR1: 0.78343 ,SNR2: 3.6932




Frequency (Hz)


3C454.3 2024/05/29 21.24UT TOYOKAWA-KISO



F20240530061228




BLK:11,SNR1: 0.50441 ,SNR2: 2.4460




Frequency (Hz)

K20240530061224




BLK:11,SNR1: 0.61203 ,SNR2: 3.1596





Frequency (Hz)


3C454.3 2024/05/29 21.24UT FUJI -KISO



T20240530062008





BLK: 8,SNR1: 11.938 ,SNR2: 115.28




Frequency (Hz)

2259+481 2024/05/29 21.36UT TOYOKAWA-FUJI


F20240530062010



BLK: 8,SNR1: 2.0432 ,SNR2: 6.8979




Frequency (Hz)






T20240530062008





BLK: 4,SNR1: 12.737 ,SNR2: 214.65




Frequency (Hz)

K20240530062006




BLK: 4,SNR1: 1.1093 ,SNR2: 4.1181




Frequency (Hz)


2259+481 2024/05/29 21.36UT TOYOKAWA-KISO




F20240530062010




BLK:13,SNR1: 0.36031 ,SNR2: 2.6253




K20240530062006






BLK:13,SNR1: 0.58498 ,SNR2: 1.3317






2259+481 2024/05/29 21.36UT FUJI -KISO




T20240530063502




F20240530063504




3C459 2024/05/29 21.61UT TOYOKAWA-FUJI



T20240530063502





BLK:10,SNR1: 47.689 ,SNR2: 182.82




Frequency (Hz)

3C459 2024/05/29 21.61UT TOYOKAWA-KISO


K20240530063500




BLK:10,SNR1: 0.85118 ,SNR2: 3.7786




Frequency (Hz)




F20240530063504




BLK: 4,SNR1: 0.22545 ,SNR2: 1.1065




K20240530063500




BLK: 4,SNR1: 0.62686 ,SNR2: 8.2465




3C459 2024/05/29 21.61UT FUJI -KISO




T20240530064622




BLK: 4,SNR1: 0.66478E-01,SNR2: 0.70328




F20240530064624





BLK: 4,SNR1: 0.35654 ,SNR2: 1.0010




2325+269 2024/05/29 21.80UT TOYOKAWA-FUJI



T20240530064622





BLK: 2,SNR1: 0.30411 ,SNR2: 0.54725




Frequency (Hz)

K20240530064620




BLK: 2,SNR1: 0.80120 ,SNR2: 3.2806





Frequency (Hz)


2325+269 2024/05/29 21.80UT TOYOKAWA-KISO



F20240530064624





BLK: 9,SNR1: 1.6405 ,SNR2: 4.2457




Frequency (Hz)

K20240530064620




BLK: 9,SNR1: 0.80075 ,SNR2: 2.9927




Frequency (Hz)

2325+269 2024/05/29 21.80UT FUJI -KISO






T20240530065504




BLK: 7,SNR1: 1.4165 ,SNR2: 8.1692




Frequency (Hz)

F20240530065506




BLK: 7,SNR1: 1.0107 ,SNR2: 2.7462




Frequency (Hz)


2334+085 2024/05/29 21.95UT TOYOKAWA-FUJI



T20240530065504




BLK: 6,SNR1: 1.6599 ,SNR2: 10.299




Frequency (Hz)

K20240530065502




BLK: 6,SNR1: 0.94064 ,SNR2: 4.4607





Frequency (Hz)


2334+085 2024/05/29 21.95UT TOYOKAWA-KISO



F20240530065506





BLK:20,SNR1: 1.4793 ,SNR2: 2.6236




Frequency (Hz)

K20240530065502




BLK:20,SNR1: 0.73963 ,SNR2: 3.6065





Frequency (Hz)


2334+085 2024/05/29 21.95UT FUJI -KISO



T20240530070847





BLK: 5,SNR1: 0.95146 ,SNR2: 11.958




Frequency (Hz)

F20240530070849




BLK: 5,SNR1: 1.5180 ,SNR2: 3.5261




Frequency (Hz)


2347-02 2024/05/29 22.17UT TOYOKAWA-FUJI



T20240530070847




BLK: 5,SNR1: 1.9181 ,SNR2: 12.425




Frequency (Hz)

K20240530070845




BLK: 5,SNR1: 1.3113 ,SNR2: 4.8691




Frequency (Hz)


2347-02 2024/05/29 22.17UT TOYOKAWA-KISO



F20240530070849




BLK: 3,SNR1: 1.2585 ,SNR2: 4.9948




Frequency (Hz)

K20240530070845




BLK: 3,SNR1: 0.31264 ,SNR2: 1.1769





Frequency (Hz)


2347-02 2024/05/29 22.17UT FUJI -KISO



T20240530071540





BLK: 6,SNR1: 0.20220 ,SNR2: 0.48640




Frequency (Hz)

F20240530071542




BLK: 6,SNR1: 4.4617 ,SNR2: 37.269




Frequency (Hz)


2354+14 2024/05/29 22.29UT TOYOKAWA-FUJI



T20240530071540





BLK: 2,SNR1: 0.29628 ,SNR2: 0.46274




Frequency (Hz)

K20240530071538




BLK: 2,SNR1: 2.1895 ,SNR2: 10.549




Frequency (Hz)

2354+14 2024/05/29 22.29UT TOYOKAWA-KISO







F20240530071542




BLK: 9,SNR1: 2.1267 ,SNR2: 9.8976




K20240530071538





BLK: 9,SNR1: 1.0667 ,SNR2: 5.1252




2354+14 2024/05/29 22.29UT FUJI -KISO





T20240530072443




BLK: 1, SNR1: 0.50836 , SNR2: 1.5530




F20240530072445





BLK: 1, SNR1: -0.23855 , SNR2: 0.16993




3C2 2024/05/29 22.44UT TOYOKAWA-FUJI





T20240530072443




BLK: 2,SNR1:-0.16464E-01,SNR2: 0.53996




K20240530072441





BLK: 2,SNR1: 0.30467 ,SNR2: 1.5889




3C2 2024/05/29 22.44UT TOYOKAWA-KISO





F20240530072445




BLK: 6,SNR1: 0.27298 ,SNR2: 1.2890




K20240530072441




BLK: 6,SNR1: 0.19392 ,SNR2: 1.0943




3C2 2024/05/29 22.44UT FUJI -KISO



T20240530073205




BLK: 4,SNR1: 0.26181 ,SNR2: 1.8983




Frequency (Hz)

F20240530073207




BLK: 4,SNR1: 0.50767E-01,SNR2: 4.1876




Frequency (Hz)


0011+344 2024/05/29 22.56UT TOYOKAWA-FUJI





T20240530073205




BLK: 4,SNR1: 0.10630 ,SNR2: 0.42104




K20240530073203




BLK: 4,SNR1: 1.0402 ,SNR2: 8.4608




0011+344 2024/05/29 22.56UT TOYOKAWA-KISO




F20240530073207




BLK:13,SNR1: 0.27728 ,SNR2: 1.4963




K20240530073203




BLK:13,SNR1: 0.42027 ,SNR2: 4.3014




0011+344 2024/05/29 22.56UT FUJI -KISO



T20240530074041




BLK:11,SNR1: 1.2107 ,SNR2: 5.4612





0019-00 2024/05/29 22.71UT TOYOKAWA-FUJI

F20240530074043




BLK:11,SNR1: 2.6266 ,SNR2: 11.723






T20240530074041




BLK:12,SNR1: 1.7037 ,SNR2: 4.6285





0019-00 2024/05/29 22.71UT TOYOKAWA-KISO


K20240530074039




BLK:12,SNR1: 1.5173 ,SNR2: 5.2572





F20240530074043




BLK:23,SNR1: 2.1121 ,SNR2: 9.4826




K20240530074039





BLK:23,SNR1: 1.1605 ,SNR2: 4.1747




0019-00 2024/05/29 22.71UT FUJI -KISO



T20240530075056





BLK:15,SNR1: 0.32311 ,SNR2: 1.5180




Frequency (Hz)

3C12 2024/05/29 22.88UT TOYOKAWA-FUJI


F20240530075058





BLK:15,SNR1: 3.3713 ,SNR2: 8.8112




Frequency (Hz)



T20240530075056





BLK:17,SNR1: 0.19847 ,SNR2: 1.2033




Frequency (Hz)

K20240530075054




BLK:17,SNR1: 2.1825 ,SNR2: 6.5178




Frequency (Hz)


3C12 2024/05/29 22.88UT TOYOKAWA-KISO



F20240530075058




BLK:23,SNR1: 2.5990 ,SNR2: 7.0843




Frequency (Hz)

3C12 2024/05/29 22.88UT FUJI -KISO


K20240530075054





BLK:23,SNR1: 3.9184 ,SNR2: 9.5198




Frequency (Hz)





T20240530080458




BLK:14,SNR1: 4.0040 ,SNR2: 9.5943




F20240530080500





BLK:14,SNR1: 3.8748 ,SNR2: 10.727




0044-056 2024/05/29 23.11UT TOYOKAWA-FUJI



T20240530080458





BLK:19,SNR1: 3.1520 ,SNR2: 7.3729




Frequency (Hz)

K20240530080456




BLK:19,SNR1: 4.7685 ,SNR2: 11.794




Frequency (Hz)


0044-056 2024/05/29 23.11UT TOYOKAWA-KISO





F20240530080500




BLK:20,SNR1: 2.5924 ,SNR2: 8.9707




K20240530080456



BLK:20,SNR1: 3.9607 ,SNR2: 10.081





0044-056 2024/05/29 23.11UT FUJI -KISO






T20240530081219





BLK: 5, SNR1: 22.264 , SNR2: 42.804




Frequency (Hz)

3C26 2024/05/29 23.23UT TOYOKAWA-FUJI


F20240530081221





BLK: 5, SNR1: 0.12617 , SNR2: 0.90919




Frequency (Hz)



T20240530081219





BLK: 2,SNR1: 0.18239 ,SNR2: 1.3552




Frequency (Hz)

3C26 2024/05/29 23.23UT TOYOKAWA-KISO


K20240530081217




BLK: 2,SNR1: 0.87126E-01,SNR2: 0.43670




Frequency (Hz)



F20240530081221




BLK: 3,SNR1:-0.26821 ,SNR2: 0.41956




Frequency (Hz)

K20240530081217




BLK: 3,SNR1:-0.29556E-01,SNR2: 0.36205





Frequency (Hz)


3C26 2024/05/29 23.23UT FUJI -KISO



T20240530081717




BLK: 5,SNR1:-0.12059E-01,SNR2: 1.0891





0056-00 2024/05/29 23.32UT TOYOKAWA-FUJI



F20240530081719




BLK: 5,SNR1: 0.89527E-01,SNR2: 4.0542



T20240530081717




BLK: 4,SNR1: 0.20475 ,SNR2: 1.9803





0056-00 2024/05/29 23.32UT TOYOKAWA-KISO


K20240530081715




BLK: 4,SNR1: 0.46931 ,SNR2: 6.2446





F20240530081719




BLK: 2,SNR1: 0.26499 ,SNR2: 2.3277




K20240530081715





BLK: 2,SNR1: 1.8723 ,SNR2: 6.6527




0056-00 2024/05/29 23.32UT FUJI -KISO



T20240530082700




BLK:14,SNR1: 1.5474 ,SNR2: 7.4903





0106+01 2024/05/29 23.48UT TOYOKAWA-FUJI



F20240530082702




BLK:14,SNR1: 6.9068 ,SNR2: 17.051



T20240530082700





BLK:12,SNR1: 5.4801 ,SNR2: 16.183





0106+01 2024/05/29 23.48UT TOYOKAWA-KISO

K20240530082658




BLK:12,SNR1: 1.5720 ,SNR2: 3.1907








F20240530082702




BLK:17,SNR1: 6.4389 ,SNR2: 15.937




K20240530082658





BLK:17,SNR1: 3.0151 ,SNR2: 5.9479




0106+01 2024/05/29 23.48UT FUJI -KISO




T20240530083622




BLK:24,SNR1: 2.5019 ,SNR2: 8.5455




F20240530083624




BLK:24,SNR1: 4.5848 ,SNR2: 11.414




0115-01 2024/05/29 23.63UT TOYOKAWA-FUJI



T20240530083622





BLK:25,SNR1: 2.6574 ,SNR2: 8.9074





0115-01 2024/05/29 23.63UT TOYOKAWA-KISO


K20240530083619




BLK:25,SNR1: 6.3834 ,SNR2: 21.927




F20240530083624




BLK:31,SNR1: 4.2714 ,SNR2: 10.770




K20240530083619




BLK:31,SNR1: 5.8876 ,SNR2: 14.933




0115-01 2024/05/29 23.63UT FUJI -KISO



T20240530084922





BLK:13,SNR1: 4.3809 ,SNR2: 10.404





0128+03 2024/05/29 23.85UT TOYOKAWA-FUJI


F20240530084924




BLK:13,SNR1: 5.8892 ,SNR2: 19.804




T20240530084922




BLK:23,SNR1: 3.8002 ,SNR2: 9.1077




K20240530084919




BLK:23,SNR1: 2.8124 ,SNR2: 13.091




0128+03 2024/05/29 23.85UT TOYOKAWA-KISO





F20240530084924




BLK:17,SNR1: 6.0335 ,SNR2: 14.346




K20240530084919




BLK:17,SNR1: 2.8475 ,SNR2: 13.250




0128+03 2024/05/29 23.85UT FUJI -KISO



T20240530091541




BLK:10,SNR1: 0.76211 ,SNR2: 6.5808





0155-109 2024/05/30 0.29UT TOYOKAWA-FUJI

F20240530091543




BLK:10,SNR1: 0.86130E-02,SNR2: 1.1007






T20240530091541




BLK: 3,SNR1: 0.65124 ,SNR2: 7.9316





0155-109 2024/05/30 0.29UT TOYOKAWA-KISO


K20240530091538




BLK: 3,SNR1: 0.19778 ,SNR2: 2.7368



F20240530091543




BLK: 5,SNR1:-0.63456E-01,SNR2: 0.96199





0155-109 2024/05/30 0.29UT FUJI -KISO



K20240530091538




BLK: 5,SNR1: 0.49012E-01,SNR2: 1.9281



T20240530092248





BLK:35,SNR1: 2.5686 ,SNR2: 12.447




0202+15 2024/05/30 0.41UT TOYOKAWA-FUJI


F20240530092250





BLK:35,SNR1: 12.541 ,SNR2: 28.823




Frequency (Hz)



T20240530092248





BLK:35,SNR1: 2.6385 ,SNR2: 12.723





0202+15 2024/05/30 0.41UT TOYOKAWA-KISO



K20240530092245




BLK:35,SNR1: 13.783 ,SNR2: 24.389




F20240530092250




BLK:34,SNR1: 12.543 ,SNR2: 28.829




K20240530092245





BLK:34,SNR1: 13.713 ,SNR2: 24.266




0202+15 2024/05/30 0.41UT FUJI -KISO



T20240530093438





BLK:31,SNR1: 13.703 ,SNR2: 24.298




Frequency (Hz)

0213+178 2024/05/30 0.61UT TOYOKAWA-FUJI


F20240530093440





BLK:31,SNR1: 8.2586 ,SNR2: 20.981




Frequency (Hz)



T20240530093438





BLK:33,SNR1: 13.776 ,SNR2: 24.423




Frequency (Hz)

K20240530093435




BLK:33,SNR1: 10.415 ,SNR2: 25.974





Frequency (Hz)


0213+178 2024/05/30 0.61UT TOYOKAWA-KISO



F20240530093440





BLK:36,SNR1: 7.9110 ,SNR2: 20.085




Frequency (Hz)

K20240530093435




BLK:36,SNR1: 10.399 ,SNR2: 25.935





Frequency (Hz)

0213+178 2024/05/30 0.61UT FUJI -KISO






T20240530094411




BLK:26,SNR1: 8.9074 ,SNR2: 26.268





0223+341 2024/05/30 0.76UT TOYOKAWA-FUJI



F20240530094413




BLK:26,SNR1: 14.253 ,SNR2: 25.124



T20240530094411




BLK:27,SNR1: 8.8272 ,SNR2: 26.039





0223+341 2024/05/30 0.76UT TOYOKAWA-KISO


K20240530094408




BLK:27,SNR1: 8.6737 ,SNR2: 21.753




F20240530094413




BLK:30,SNR1: 14.420 ,SNR2: 25.422




K20240530094408





BLK:30,SNR1: 8.6871 ,SNR2: 21.786




0223+341 2024/05/30 0.76UT FUJI -KISO




T20240530100035




BLK: 3,SNR1: 0.13876 ,SNR2: 0.56301




F20240530100037





BLK: 3,SNR1:-0.41155E-01,SNR2: 1.3090




3C71 2024/05/30 1.04UT TOYOKAWA-FUJI



T20240530100035





BLK: 2,SNR1: 0.65372E-01,SNR2: 0.89400





3C71 2024/05/30 1.04UT TOYOKAWA-KISO



K20240530100032




BLK: 2,SNR1: 2.0074 ,SNR2: 7.7380



F20240530100037





BLK: 3,SNR1: 2.0031 ,SNR2: 5.8757




Frequency (Hz)

K20240530100032




BLK: 3,SNR1: 0.32347 ,SNR2: 0.51688




Frequency (Hz)


3C71 2024/05/30 1.04UT FUJI -KISO



T20240530101950




BLK:16,SNR1: 5.8670 ,SNR2: 10.298




Frequency (Hz)

F20240530101952




BLK:16,SNR1: 1.4223 ,SNR2: 5.0371





Frequency (Hz)


0258+350 2024/05/30 1.36UT TOYOKAWA-FUJI



T20240530101950





BLK:19,SNR1: 5.7195 ,SNR2: 10.036





0258+350 2024/05/30 1.36UT TOYOKAWA-KISO

K20240530101947




BLK:19,SNR1: 1.3331 ,SNR2: 5.4649






F20240530101952





BLK:17,SNR1: 1.3040 ,SNR2: 3.8832




Frequency (Hz)

K20240530101947




BLK:17,SNR1: 0.79601 ,SNR2: 3.2100




Frequency (Hz)


0258+350 2024/05/30 1.36UT FUJI -KISO



T20240530102939





BLK:13,SNR1: 0.68931 ,SNR2: 5.3932




Frequency (Hz)

F20240530102941




BLK:13,SNR1: 0.74245 ,SNR2: 1.8665





Frequency (Hz)


0308+305 2024/05/30 1.52UT TOYOKAWA-FUJI



T20240530102939




BLK:21,SNR1: 0.74862 ,SNR2: 3.3639




Frequency (Hz)

K20240530102936




BLK:21,SNR1: 0.93762 ,SNR2: 4.5736




Frequency (Hz)


0308+305 2024/05/30 1.52UT TOYOKAWA-KISO




F20240530102941




BLK:15,SNR1: 0.88759 ,SNR2: 3.0685




K20240530102936





BLK:15,SNR1: 1.7550 ,SNR2: 6.8827




0308+305 2024/05/30 1.52UT FUJI -KISO




T20240530103759




BLK: 6,SNR1: 0.46135 ,SNR2: 1.9719




F20240530103801





BLK: 6,SNR1: 1.2778 ,SNR2: 3.0309




3C84 2024/05/30 1.66UT TOYOKAWA-FUJI



T20240530103759





BLK:19,SNR1: 1.3176 ,SNR2: 3.7629





3C84 2024/05/30 1.66UT TOYOKAWA-KISO


K20240530103756




BLK:19,SNR1: 0.54825 ,SNR2: 2.6509



F20240530103801




BLK: 7,SNR1: 0.99871 ,SNR2: 3.5907




Frequency (Hz)

3C84 2024/05/30 1.66UT FUJI -KISO


K20240530103756




BLK: 7,SNR1: 0.33345 ,SNR2: 3.0499




Frequency (Hz)





T20240530104516




BLK: 4,SNR1: 0.11672 ,SNR2: 0.83192




F20240530104518



BLK: 4,SNR1: 0.71589 ,SNR2: 2.5643





0324+119 2024/05/30 1.78UT TOYOKAWA-FUJI






T20240530104516





BLK: 7,SNR1: 0.14700 ,SNR2: 0.60640





0324+119 2024/05/30 1.78UT TOYOKAWA-KISO



K20240530104513




BLK: 7,SNR1: 0.21011 ,SNR2: 1.0287




F20240530104518




BLK: 2,SNR1: 0.37253 ,SNR2: 3.8735




K20240530104513





BLK: 2,SNR1: 0.73671 ,SNR2: 3.6017




0324+119 2024/05/30 1.78UT FUJI -KISO



T20240530105432




BLK: 9,SNR1: 6.8679 ,SNR2: 14.541




Frequency (Hz)

F20240530105434




BLK: 9,SNR1:-0.17154 ,SNR2: 2.8186




Frequency (Hz)


0333+32 2024/05/30 1.94UT TOYOKAWA-FUJI



T20240530105432




BLK:10,SNR1: 0.21055 ,SNR2: 0.83854




0333+32 2024/05/30 1.94UT TOYOKAWA-KISO


K20240530105429





BLK:10,SNR1: 3.4610 ,SNR2: 15.000




Frequency (Hz)





F20240530105434




BLK:17,SNR1:-0.56142E-01,SNR2: 1.3558




K20240530105429





BLK:17,SNR1: 3.6475 ,SNR2: 15.453




0333+32 2024/05/30 1.94UT FUJI -KISO





T20240530110734




BLK: 9,SNR1: 0.11247 ,SNR2: 1.9041




F20240530110736





BLK: 9,SNR1: 0.37880 ,SNR2: 1.1261




0347+05 2024/05/30 2.15UT TOYOKAWA-FUJI





T20240530110734




BLK:11,SNR1: 0.57039E-01,SNR2: 1.9518




K20240530110731




BLK:11,SNR1: 20.044 ,SNR2: 52.076




0347+05 2024/05/30 2.15UT TOYOKAWA-KISO





F20240530110736




BLK: 5,SNR1: 0.18654 ,SNR2: 2.9250




K20240530110731



BLK: 5,SNR1: 66.703 ,SNR2: 87.372





0347+05 2024/05/30 2.15UT FUJI -KISO







T20240530112309




BLK: 7,SNR1: 0.12862 ,SNR2: 1.8297




F20240530112311





BLK: 7,SNR1: 1.9055 ,SNR2: 3.1341




0403-132 2024/05/30 2.41UT TOYOKAWA-FUJI





T20240530112309




BLK: 8,SNR1: 0.21520 ,SNR2: 1.3299




K20240530112306




BLK: 8,SNR1: 0.34908 ,SNR2: 1.5942




0403-132 2024/05/30 2.41UT TOYOKAWA-KISO





F20240530112311




BLK: 7,SNR1: 1.5254 ,SNR2: 3.1134




K20240530112306





BLK: 7,SNR1: 0.29751 ,SNR2: 1.2436




0403-132 2024/05/30 2.41UT FUJI -KISO





T20240530113219




BLK:11,SNR1: 0.26089 ,SNR2: 2.6413




F20240530113221





BLK:11,SNR1: 0.14603 ,SNR2: 1.3842




0411+05 2024/05/30 2.57UT TOYOKAWA-FUJI





T20240530113219




BLK:23,SNR1: 0.47266 ,SNR2: 4.1022




K20240530113216




BLK:23,SNR1: 0.13964 ,SNR2: 1.9421




0411+05 2024/05/30 2.57UT TOYOKAWA-KISO




F20240530113221




BLK: 8,SNR1: 0.25658 ,SNR2: 2.1873




K20240530113216





BLK: 8,SNR1: 0.55200 ,SNR2: 3.3711




0411+05 2024/05/30 2.57UT FUJI -KISO





T20240530114312




BLK: 6,SNR1: 0.11249E-01,SNR2: 0.42116




F20240530114314






BLK: 6,SNR1: 3.6195 ,SNR2: 11.931







0422+178 2024/05/30 2.75UT TOYOKAWA-FUJI



T20240530114312




K20240530114309








F20240530114314




BLK:19,SNR1: 8.2249 ,SNR2: 20.878




K20240530114309




BLK:19,SNR1: 0.30471 ,SNR2: 0.97964




0422+178 2024/05/30 2.75UT FUJI -KISO




T20240530115040




BLK:19,SNR1: 2.5185 ,SNR2: 22.192




F20240530115042





BLK:19,SNR1: 0.59359 ,SNR2: 1.8397




3C119 2024/05/30 2.87UT TOYOKAWA-FUJI





T20240530115040




BLK:29,SNR1: 1.9022 ,SNR2: 17.542




K20240530115037




BLK:29,SNR1: 0.45221 ,SNR2: 1.9145




3C119 2024/05/30 2.87UT TOYOKAWA-KISO





F20240530115042




BLK:15,SNR1: 0.54064 ,SNR2: 1.9420




K20240530115037




BLK:15,SNR1: 0.68910 ,SNR2: 2.8608




3C119 2024/05/30 2.87UT FUJI -KISO




T20240530123848




BLK:28,SNR1: 13.730 ,SNR2: 23.241




F20240530123850




BLK:28,SNR1: 0.60105 ,SNR2: 2.7733




3C138 2024/05/30 3.67UT TOYOKAWA-FUJI





T20240530123848




BLK:34,SNR1: 11.229 ,SNR2: 28.139




K20240530123845





BLK:34,SNR1: 2.6033 ,SNR2: 10.842




3C138 2024/05/30 3.67UT TOYOKAWA-KISO



F20240530123850





BLK:33,SNR1: 0.58379 ,SNR2: 2.7546




Frequency (Hz)

K20240530123845




BLK:33,SNR1: 2.6103 ,SNR2: 10.887





Frequency (Hz)


3C138 2024/05/30 3.67UT FUJI -KISO




T20240530125221




BLK:25,SNR1: 9.5995 ,SNR2: 27.948




F20240530125223



BLK:25,SNR1: 0.68682 ,SNR2: 5.2888





0531+194 2024/05/30 3.90UT TOYOKAWA-FUJI






T20240530125221





BLK:29,SNR1: 9.5110 ,SNR2: 27.632





0531+194 2024/05/30 3.90UT TOYOKAWA-KISO


K20240530125219




BLK:29,SNR1: 0.81794 ,SNR2: 4.5032




F20240530125223




BLK:22,SNR1: 0.49777 ,SNR2: 3.4531




K20240530125219




BLK:22,SNR1: 1.0120 ,SNR2: 6.0393




0531+194 2024/05/30 3.90UT FUJI -KISO




T20240530130040




BLK:28,SNR1: 15.181 ,SNR2: 49.673




F20240530130042





BLK:28,SNR1: 0.18764 ,SNR2: 3.4608




3C147 2024/05/30 4.04UT TOYOKAWA-FUJI





T20240530130040




BLK:37,SNR1: 15.044 ,SNR2: 29.919




K20240530130038




BLK:37,SNR1: 1.5775 ,SNR2: 10.473




3C147 2024/05/30 4.04UT TOYOKAWA-KISO



F20240530130042





BLK:31,SNR1: 0.16092 ,SNR2: 4.3728





3C147 2024/05/30 4.04UT FUJI -KISO


K20240530130038




BLK:31,SNR1: 1.4325 ,SNR2: 11.341





T20240530130852




BLK:16,SNR1: 2.5467 ,SNR2: 10.767




F20240530130854





BLK:16,SNR1: 11.360 ,SNR2: 19.345




0548+16 2024/05/30 4.18UT TOYOKAWA-FUJI



T20240530130852





BLK:22,SNR1: 1.6442 ,SNR2: 6.6745




Frequency (Hz)

K20240530130849




BLK:22,SNR1: 3.6391 ,SNR2: 10.780





Frequency (Hz)


0548+16 2024/05/30 4.18UT TOYOKAWA-KISO





F20240530130854




BLK:26,SNR1: 18.403 ,SNR2: 21.776




K20240530130849



BLK:26,SNR1: 12.115 ,SNR2: 18.276




0548+16 2024/05/30 4.18UT FUJI -KISO








T20240530131303




BLK: 8,SNR1: 13.277 ,SNR2: 112.73




F20240530131305




BLK: 8,SNR1: 1.1089 ,SNR2: 3.7010




0552+12 2024/05/30 4.25UT TOYOKAWA-FUJI





T20240530131303




BLK: 9,SNR1: 37.209 ,SNR2: 279.87




K20240530131300





BLK: 9,SNR1: 0.35580 ,SNR2: 1.5789




0552+12 2024/05/30 4.25UT TOYOKAWA-KISO



F20240530131305





BLK: 6,SNR1: 0.36615 ,SNR2: 2.0355




Frequency (Hz)

K20240530131300




BLK: 6,SNR1: 0.25820 ,SNR2: 1.0671





Frequency (Hz)


0552+12 2024/05/30 4.25UT FUJI -KISO





T20240530131730




BLK:10,SNR1: 0.10133 ,SNR2: 1.1441




F20240530131732





BLK:10,SNR1: 4.5768 ,SNR2: 15.723




0556+191 2024/05/30 4.32UT TOYOKAWA-FUJI





T20240530131730




BLK: 4,SNR1: 0.32227E-01,SNR2: 0.53046




K20240530131727





BLK: 4,SNR1: 0.67515 ,SNR2: 7.8731




0556+191 2024/05/30 4.32UT TOYOKAWA-KISO




F20240530131732




BLK: 4,SNR1: 1.0466 ,SNR2: 4.7499




K20240530131727





BLK: 4,SNR1: 1.2775 ,SNR2: 10.176




0556+191 2024/05/30 4.32UT FUJI -KISO




T20240530132516




BLK: 9,SNR1: 0.30849 ,SNR2: 2.5443




F20240530132518





BLK: 9,SNR1: 0.10197 ,SNR2: 4.2856




0605-08 2024/05/30 4.45UT TOYOKAWA-FUJI





T20240530132516




BLK: 1,SNR1: 0.17092 ,SNR2: 1.2924




K20240530132514



BLK: 1,SNR1: 0.24454 ,SNR2: 0.41151




0605-08 2024/05/30 4.45UT TOYOKAWA-KISO








F20240530132518




BLK: 4,SNR1: 0.28251 ,SNR2: 6.4351




K20240530132514





BLK: 4,SNR1:-0.22049E-01,SNR2: 0.36917




0605-08 2024/05/30 4.45UT FUJI -KISO



T20240530134424





BLK:16,SNR1: 0.71686 ,SNR2: 3.6034




Frequency (Hz)

F20240530134426




BLK:16,SNR1:-0.12314E-01,SNR2: 1.5873





Frequency (Hz)


3C161 2024/05/30 4.77UT TOYOKAWA-FUJI




T20240530134424




BLK:26,SNR1: 0.71087 ,SNR2: 6.1937




K20240530134421





BLK:26,SNR1: 0.40379 ,SNR2: 1.2645




3C161 2024/05/30 4.77UT TOYOKAWA-KISO



F20240530134426





BLK:12,SNR1: 0.44329E-01,SNR2: 1.7205




Frequency (Hz)

K20240530134421




BLK:12,SNR1: 0.35571 ,SNR2: 1.0026





Frequency (Hz)


3C161 2024/05/30 4.77UT FUJI -KISO




T20240530141157




BLK: 4,SNR1:-0.66838E-01,SNR2: 0.28673




F20240530141159





BLK: 4,SNR1: 0.58977E-01,SNR2: 4.5445




0652-130 2024/05/30 5.23UT TOYOKAWA-FUJI





T20240530141157




BLK: 4,SNR1: 0.11561 ,SNR2: 0.81929




K20240530141155




BLK: 4,SNR1: 0.55272 ,SNR2: 1.4035




0652-130 2024/05/30 5.23UT TOYOKAWA-KISO



F20240530141159





BLK: 4,SNR1: 0.28612 ,SNR2: 5.4902




Frequency (Hz)

K20240530141155




BLK: 4,SNR1: 0.50064 ,SNR2: 1.9727





Frequency (Hz)


0652-130 2024/05/30 5.23UT FUJI -KISO




T20240530142333




BLK: 9,SNR1: 0.56336E-01,SNR2: 0.87218




F20240530142335



BLK: 9,SNR1: 83.327 ,SNR2: 107.75





0703+138 2024/05/30 5.42UT TOYOKAWA-FUJI








T20240530142333




BLK: 3,SNR1: 0.39849E-01,SNR2: 0.30471




K20240530142330





BLK: 3,SNR1: 0.94379 ,SNR2: 5.6952




0703+138 2024/05/30 5.42UT TOYOKAWA-KISO





F20240530142335




BLK: 4,SNR1: 144.81 ,SNR2: 467.01




K20240530142330





BLK: 4,SNR1:-0.29957E-01,SNR2: 0.88854




0703+138 2024/05/30 5.42UT FUJI -KISO




T20240530143256




BLK: 3,SNR1:-0.15109E-01,SNR2: 1.8488




F20240530143258





BLK: 3,SNR1:-0.52636E-01,SNR2: 0.74605




0713-024 2024/05/30 5.58UT TOYOKAWA-FUJI





T20240530143256




BLK: 3,SNR1: 0.16730 ,SNR2: 0.90745




K20240530143254





BLK: 3,SNR1: 2.5224 ,SNR2: 10.888




0713-024 2024/05/30 5.58UT TOYOKAWA-KISO



F20240530143258





BLK: 4,SNR1:-0.26958E-01,SNR2: 0.68312




Frequency (Hz)

K20240530143254




BLK: 4,SNR1: 1.8730 ,SNR2: 8.4807




Frequency (Hz)


0713-024 2024/05/30 5.58UT FUJI -KISO





T20240530144307




BLK: 4,SNR1: 0.24897 ,SNR2: 0.98812




F20240530144309




BLK: 4,SNR1: 0.38139 ,SNR2: 1.0999




0723+10 2024/05/30 5.75UT TOYOKAWA-FUJI



T20240530144307




BLK: 7,SNR1: 0.15628 ,SNR2: 2.3249




Frequency (Hz)

K20240530144305




BLK: 7,SNR1: 0.29255 ,SNR2: 1.9976





Frequency (Hz)


0723+10 2024/05/30 5.75UT TOYOKAWA-KISO





F20240530144309




BLK: 1,SNR1:-0.39902E-01,SNR2: 0.22543




K20240530144305



BLK: 1,SNR1: 0.35955 ,SNR2: 0.99049





0723+10 2024/05/30 5.75UT FUJI -KISO






T20240530145322




BLK: 9,SNR1: 0.33290 ,SNR2: 1.4878




Frequency (Hz)

F20240530145324




BLK: 9,SNR1: 0.24943 ,SNR2: 1.4524





Frequency (Hz)


0732+33 2024/05/30 5.92UT TOYOKAWA-FUJI





T20240530145322




BLK:15,SNR1: 0.26882 ,SNR2: 1.0697




K20240530145319





BLK:15,SNR1: 0.58323 ,SNR2: 2.2850




0732+33 2024/05/30 5.92UT TOYOKAWA-KISO



F20240530145324





BLK: 7,SNR1: 0.30709 ,SNR2: 5.5392




Frequency (Hz)

K20240530145319




BLK: 7,SNR1: 0.15384 ,SNR2: 1.4300





Frequency (Hz)


0732+33 2024/05/30 5.92UT FUJI -KISO




T20240530150124




BLK: 9,SNR1: 0.29827 ,SNR2: 4.2604




F20240530150126





BLK: 9,SNR1: 0.50145 ,SNR2: 2.0032




0741-06 2024/05/30 6.05UT TOYOKAWA-FUJI





T20240530150124




BLK:14,SNR1: 0.25901 ,SNR2: 2.4302




K20240530150121




BLK:14,SNR1: 0.44318 ,SNR2: 2.5709




0741-06 2024/05/30 6.05UT TOYOKAWA-KISO





F20240530150126




BLK: 6,SNR1: 0.25603 ,SNR2: 1.2957




K20240530150121





BLK: 6,SNR1: 0.67507 ,SNR2: 3.6270




0741-06 2024/05/30 6.05UT FUJI -KISO



T20240530151108





BLK: 8,SNR1: 0.13399 ,SNR2: 1.7964




Frequency (Hz)

F20240530151110




BLK: 8,SNR1:-0.10855 ,SNR2: 0.91119





Frequency (Hz)


0752-200 2024/05/30 6.21UT TOYOKAWA-FUJI





T20240530151108




BLK: 5,SNR1: 0.52428E-01,SNR2: 1.9672




K20240530151105




BLK: 5,SNR1: 0.26426 ,SNR2: 0.72276





0752-200 2024/05/30 6.21UT TOYOKAWA-KISO









BLK: 3,SNR1:-0.91013E-01,SNR2: 1.1122





BLK: 3,SNR1: 0.24822 ,SNR2: 0.81501




0752-200 2024/05/30 6.21UT FUJI -KISO





T20240530151843




BLK: 7,SNR1: 0.87555 ,SNR2: 5.5497




F20240530151845





BLK: 7,SNR1: 0.41860 ,SNR2: 3.6027




3C190 2024/05/30 6.34UT TOYOKAWA-FUJI





T20240530151843




BLK: 3,SNR1: 1.4930 ,SNR2: 20.522




K20240530151841





BLK: 3,SNR1: 1.6846 ,SNR2: 6.8702




3C190 2024/05/30 6.34UT TOYOKAWA-KISO



F20240530151845





BLK: 4,SNR1: 2.0750 ,SNR2: 11.698




Frequency (Hz)

K20240530151841




BLK: 4,SNR1: 0.43399E-01,SNR2: 0.49350





Frequency (Hz)


3C190 2024/05/30 6.34UT FUJI -KISO




T20240530153107




BLK: 5,SNR1: 0.12747 ,SNR2: 2.4264




F20240530153109





BLK: 5,SNR1:-0.59507E-01,SNR2: 0.54583




3C196 2024/05/30 6.55UT TOYOKAWA-FUJI





T20240530153107




BLK:12,SNR1: 0.20651 ,SNR2: 1.6397




K20240530153104




BLK:12,SNR1: 0.12485 ,SNR2: 0.68535




3C196 2024/05/30 6.55UT TOYOKAWA-KISO




F20240530153109




BLK:10,SNR1:-0.81769E-01,SNR2: 0.67594




K20240530153104





BLK:10,SNR1: 0.16837 ,SNR2: 0.81337




3C196 2024/05/30 6.55UT FUJI -KISO



T20240530154217




BLK: 4,SNR1: 0.40048E-01,SNR2: 1.0204




Frequency (Hz)

F20240530154219




BLK: 4,SNR1: 0.25716 ,SNR2: 0.80988





Frequency (Hz)

0821+394 2024/05/30 6.73UT TOYOKAWA-FUJI








T20240530154217




BLK: 5,SNR1: 34.317 ,SNR2: 82.283




K20240530154215





BLK: 5,SNR1: 0.66731 ,SNR2: 3.0033




0821+394 2024/05/30 6.73UT TOYOKAWA-KISO



F20240530154219





BLK: 5,SNR1: 0.99549E-01,SNR2: 1.3482




Frequency (Hz)

K20240530154215








BLK: 5,SNR1: 0.52142 ,SNR2: 1.9185




Frequency (Hz)


0821+394 2024/05/30 6.73UT FUJI -KISO







0834-19 2024/05/30 6.93UT TOYOKAWA-FUJI







BLK:14,SNR1: 2.6526 ,SNR2: 11.838





BLK:14,SNR1: 1.8574 ,SNR2: 3.3535




0834-19 2024/05/30 6.93UT TOYOKAWA-KISO



F20240530155400





BLK:16,SNR1: 2.0512 ,SNR2: 5.0550




Frequency (Hz)

K20240530155355




BLK:16,SNR1: 1.1171 ,SNR2: 4.2147




Frequency (Hz)


0834-19 2024/05/30 6.93UT FUJI -KISO




T20240530155903




BLK: 4,SNR1: 9.7101 ,SNR2: 163.11




F20240530155905




BLK: 4,SNR1:-0.69839E-01,SNR2: 1.1304




0839-071 2024/05/30 7.01UT TOYOKAWA-FUJI



T20240530155903





BLK: 4,SNR1: 2.7093 ,SNR2: 39.038





0839-071 2024/05/30 7.01UT TOYOKAWA-KISO



K20240530155901




BLK: 4,SNR1: 0.95974E-01,SNR2: 0.56801



F20240530155905





BLK: 5,SNR1:-0.18800 ,SNR2: 1.3398




Frequency (Hz)

K20240530155901




BLK: 5,SNR1: 0.21990 ,SNR2: 1.0367





Frequency (Hz)

0839-071 2024/05/30 7.01UT FUJI -KISO






T20240530161004





BLK: 6,SNR1: 0.16147 ,SNR2: 2.2441




Frequency (Hz)

F20240530161006




BLK: 6,SNR1: 0.66184E-01,SNR2: 0.92809





Frequency (Hz)


3C208 2024/05/30 7.20UT TOYOKAWA-FUJI





T20240530161004




BLK:13,SNR1: 0.19127 ,SNR2: 2.5373




K20240530161002





BLK:13,SNR1: 0.10582 ,SNR2: 0.74916




3C208 2024/05/30 7.20UT TOYOKAWA-KISO



F20240530161006





BLK: 9,SNR1: 1.4662 ,SNR2: 6.7913




Frequency (Hz)

K20240530161002






BLK: 9,SNR1: 0.79708 ,SNR2: 5.3500




Frequency (Hz)

3C208 2024/05/30 7.20UT FUJI -KISO








3C216 2024/05/30 7.47UT TOYOKAWA-FUJI



T20240530162645





BLK:19,SNR1: 2.6344 ,SNR2: 11.764




Frequency (Hz)

K20240530162642




BLK:19,SNR1: 6.5860 ,SNR2: 19.030





Frequency (Hz)


3C216 2024/05/30 7.47UT TOYOKAWA-KISO



F20240530162647





BLK:20,SNR1: 2.2473 ,SNR2: 5.7089




Frequency (Hz)

K20240530162642




BLK:20,SNR1: 6.5332 ,SNR2: 18.879





Frequency (Hz)


3C216 2024/05/30 7.47UT FUJI -KISO



T20240530164536





BLK:11,SNR1: 3.4004 ,SNR2: 11.363




Frequency (Hz)

F20240530164538




BLK:11,SNR1: 0.37533 ,SNR2: 1.5007





Frequency (Hz)


0926+117 2024/05/30 7.79UT TOYOKAWA-FUJI




T20240530164536




BLK: 5,SNR1: 3.4871 ,SNR2: 16.322




K20240530164534



BLK: 5,SNR1: 1.4219 ,SNR2: 6.8156




0926+117 2024/05/30 7.79UT TOYOKAWA-KISO






F20240530164538




BLK: 7,SNR1: 0.54331 ,SNR2: 1.9718




Frequency (Hz)

K20240530164534




BLK: 7,SNR1: 1.0412 ,SNR2: 2.9784





Frequency (Hz)


0926+117 2024/05/30 7.79UT FUJI -KISO



T20240530165320





BLK:19,SNR1: 1.4485 ,SNR2: 6.9301




Frequency (Hz)

F20240530165322




BLK:19,SNR1: 5.7369 ,SNR2: 14.434





Frequency (Hz)


3C222 2024/05/30 7.92UT TOYOKAWA-FUJI



T20240530165320





BLK:17,SNR1: 2.8257 ,SNR2: 7.1046




Frequency (Hz)

K20240530165318




BLK:17,SNR1: 2.2069 ,SNR2: 10.879




Frequency (Hz)


3C222 2024/05/30 7.92UT TOYOKAWA-KISO



F20240530165322





BLK:24,SNR1: 6.8929 ,SNR2: 17.260




Frequency (Hz)

K20240530165318




BLK:24,SNR1: 2.3030 ,SNR2: 11.262





Frequency (Hz)


3C222 2024/05/30 7.92UT FUJI -KISO



T20240530175400





BLK: 4,SNR1: 0.17653 ,SNR2: 0.59016




Frequency (Hz)

F20240530175402




BLK: 4,SNR1: 6.6867 ,SNR2: 24.464





Frequency (Hz)


1034+404 2024/05/30 8.93UT TOYOKAWA-FUJI



T20240530175400





BLK: 2,SNR1: 0.17784 ,SNR2: 1.1378




Frequency (Hz)

K20240530175357




BLK: 2,SNR1: 1.3299 ,SNR2: 4.3158




Frequency (Hz)


1034+404 2024/05/30 8.93UT TOYOKAWA-KISO



F20240530175402




BLK: 5, SNR1: 5.5190 , SNR2: 38.300




Frequency (Hz)

K20240530175357



BLK: 5, SNR1: 0.32500 , SNR2: 1.4087



Frequency (Hz)

1034+404 2024/05/30 8.93UT FUJI -KISO

