





T20240531053502




BLK: 5,SNR1: 0.14138 ,SNR2: 1.9723




F20240531053504





BLK: 5,SNR1: 0.88553 ,SNR2: 3.9979




2218+395 2024/05/30 20.61UT TOYOKAWA-FUJI





T20240531053502




BLK: 9,SNR1: 0.79969E-01,SNR2: 0.71452




K20240531053500



BLK: 9,SNR1: 1.0727 ,SNR2: 5.5046




2218+395 2024/05/30 20.61UT TOYOKAWA-KISO






F20240531053504




BLK:11,SNR1: 2.4800 ,SNR2: 4.6952




Frequency (Hz)

K20240531053500




BLK:11,SNR1: 0.32627 ,SNR2: 1.6775






Frequency (Hz)




2218+395 2024/05/30 20.61UT FUJI -KISO




T20240531054350






F20240531054352



2227+444 2024/05/30 20.76UT TOYOKAWA-FUJI






T20240531054350




BLK: 5,SNR1: 10.711 ,SNR2: 145.03


K20240531054348






BLK: 5,SNR1: 0.64161 ,SNR2: 2.8894

2227+444 2024/05/30 20.76UT TOYOKAWA-KISO







BLK: 5,SNR1: 0.15455 ,SNR2: 2.9314





BLK: 5,SNR1: -0.49356E-01,SNR2: 0.55608




2227+444 2024/05/30 20.76UT FUJI -KISO



T20240531055559





BLK: 9,SNR1: 42.595 ,SNR2: 360.03




Frequency (Hz)

F20240531055601




BLK: 9,SNR1: 1.5711 ,SNR2: 3.9006





Frequency (Hz)


2239+333 2024/05/30 20.96UT TOYOKAWA-FUJI



T20240531055559





BLK: 6,SNR1: 70.004 ,SNR2: 507.45




Frequency (Hz)

K20240531055557




BLK: 6,SNR1: 1.0909 ,SNR2: 5.2701





Frequency (Hz)


2239+333 2024/05/30 20.96UT TOYOKAWA-KISO



F20240531055601





BLK:10,SNR1: 0.86537 ,SNR2: 7.4296




Frequency (Hz)

K20240531055557




BLK:10,SNR1: 0.91689 ,SNR2: 3.1872





Frequency (Hz)


2239+333 2024/05/30 20.96UT FUJI -KISO



T20240531060016





BLK: 7,SNR1: 0.14740 ,SNR2: 1.8568




Frequency (Hz)

F20240531060018




BLK: 7,SNR1: 2.8750 ,SNR2: 5.0676




Frequency (Hz)

2243+394 2024/05/30 21.03UT TOYOKAWA-FUJI






T20240531060016





BLK: 7,SNR1: 0.39321E-01,SNR2: 1.6479




Frequency (Hz)

K20240531060014




BLK: 7,SNR1: 0.58274 ,SNR2: 3.3819





Frequency (Hz)


2243+394 2024/05/30 21.03UT TOYOKAWA-KISO



F20240531060018




BLK: 7,SNR1: 2.3489 ,SNR2: 5.7124




Frequency (Hz)

K20240531060014




BLK: 7,SNR1: 0.42264 ,SNR2: 2.0635





Frequency (Hz)


2243+394 2024/05/30 21.03UT FUJI -KISO



T20240531061612





BLK: 4,SNR1: 0.34268 ,SNR2: 1.5209




Frequency (Hz)

F20240531061614




BLK: 4,SNR1: 0.60139 ,SNR2: 3.0691





Frequency (Hz)


2259+481 2024/05/30 21.30UT TOYOKAWA-FUJI



T20240531061612




BLK: 4,SNR1: 0.34777 ,SNR2: 1.8513




Frequency (Hz)

K20240531061609





BLK: 4,SNR1: 0.50833 ,SNR2: 3.0343






Frequency (Hz)

2259+481 2024/05/30 21.30UT TOYOKAWA-KISO







BLK: 2,SNR1:-0.11981 ,SNR2: 0.41627





BLK: 2,SNR1: 0.34548E-01,SNR2: 0.0000




2259+481 2024/05/30 21.30UT FUJI -KISO



T20240531063106





BLK: 5,SNR1: 2.3512 ,SNR2: 22.084




Frequency (Hz)

F20240531063108




BLK: 5,SNR1: 0.13894 ,SNR2: 1.0207





Frequency (Hz)

3C459 2024/05/30 21.55UT TOYOKAWA-FUJI





T20240531063106






Frequency (Hz)

3C459 2024/05/30 21.55UT TOYOKAWA-KISO



K20240531063103




Frequency (Hz)



F20240531063108




BLK:10,SNR1: 0.38888 ,SNR2: 2.7739




Frequency (Hz)

3C459 2024/05/30 21.55UT FUJI -KISO


K20240531063103



BLK:10,SNR1: 0.66084 ,SNR2: 2.4577





Frequency (Hz)








T20240531063557




BLK: 7,SNR1: 0.41343E-01,SNR2: 1.4251




F20240531063559





BLK: 7,SNR1: 0.64699 ,SNR2: 2.8175




2318-001 2024/05/30 21.63UT TOYOKAWA-FUJI





T20240531063557




BLK: 8,SNR1: 0.67877E-01,SNR2: 1.2787




K20240531063555





BLK: 8,SNR1: 0.45303 ,SNR2: 2.0327




2318-001 2024/05/30 21.63UT TOYOKAWA-KISO





F20240531063559




BLK:13,SNR1: 0.96212 ,SNR2: 3.5168




K20240531063555



BLK:13,SNR1: 1.7814 ,SNR2: 6.0451




2318-001 2024/05/30 21.63UT FUJI -KISO






T20240531064226




No.Good Data




Frequency (Hz)

K20240531064224




No.Good Data





Frequency (Hz)


2325+269 2024/05/30 21.74UT TOYOKAWA-KISO



F20240531064228





BLK: 2,SNR1: 0.69307E-01,SNR2: 0.88818




Frequency (Hz)

K20240531064224




BLK: 2,SNR1: 0.73400 ,SNR2: 2.4972





Frequency (Hz)


2325+269 2024/05/30 21.74UT FUJI -KISO




T20240531065108




BLK:11,SNR1: 1.3070 ,SNR2: 12.027




F20240531065110






BLK:11,SNR1: 1.2970 ,SNR2: 5.3737






2334+085 2024/05/30 21.88UT TOYOKAWA-FUJI




T20240531065108



K20240531065106




2334+085 2024/05/30 21.88UT TOYOKAWA-KISO






F20240531065110





BLK:10,SNR1: 0.99941 ,SNR2: 2.3097




Frequency (Hz)

K20240531065106




BLK:10,SNR1: 1.2983 ,SNR2: 4.8019





Frequency (Hz)


2334+085 2024/05/30 21.88UT FUJI -KISO



T20240531070451





BLK:11,SNR1: 0.76757E-01,SNR2: 1.6360




Frequency (Hz)

F20240531070453




BLK:11,SNR1: 0.18050 ,SNR2: 2.5403





Frequency (Hz)


2347-02 2024/05/30 22.11UT TOYOKAWA-FUJI



T20240531070451





BLK:15,SNR1: 0.83309E-01,SNR2: 1.3191




Frequency (Hz)

K20240531070448




BLK:15,SNR1: 1.6556 ,SNR2: 6.3922





Frequency (Hz)


2347-02 2024/05/30 22.11UT TOYOKAWA-KISO



F20240531070453





BLK:19,SNR1: 0.53766 ,SNR2: 3.0062




Frequency (Hz)

K20240531070448




BLK:19,SNR1: 2.1411 ,SNR2: 7.6751





Frequency (Hz)


2347-02 2024/05/30 22.11UT FUJI -KISO



T20240531071144





BLK: 1,SNR1: 0.33008 ,SNR2: 3.9134




Frequency (Hz)

F20240531071146




BLK: 1,SNR1:-0.21547E-01,SNR2: 0.44123




Frequency (Hz)


2354+14 2024/05/30 22.22UT TOYOKAWA-FUJI




T20240531071144




BLK: 2,SNR1:-0.41246E-01,SNR2: 0.52703




K20240531071141





BLK: 2,SNR1: 1.4868 ,SNR2: 10.734




2354+14 2024/05/30 22.22UT TOYOKAWA-KISO



F20240531071146





BLK: 1,SNR1: 0.28611 ,SNR2: 0.34715




Frequency (Hz)

K20240531071141




BLK: 1,SNR1: 1.1817 ,SNR2: 8.8161





Frequency (Hz)


2354+14 2024/05/30 22.22UT FUJI -KISO





T20240531072047




BLK: 7,SNR1: 0.64239E-03,SNR2: 1.3404




F20240531072049



BLK: 7,SNR1: 1.6316 ,SNR2: 4.3887




3C2 2024/05/30 22.37UT TOYOKAWA-FUJI







T20240531072047




BLK: 9,SNR1: 0.42517E-01,SNR2: 1.1563




K20240531072044




BLK: 9,SNR1: 0.86843 ,SNR2: 3.7066




3C2 2024/05/30 22.37UT TOYOKAWA-KISO



F20240531072049



BLK: 8,SNR1: 0.91445 ,SNR2: 4.6257




Frequency (Hz)


3C2

2024/05/30 22.37UT FUJI -KISO


K20240531072044





BLK: 8,SNR1: 0.59455 ,SNR2: 4.7195




Frequency (Hz)





T20240531072809




BLK:10,SNR1: 0.14539 ,SNR2: 1.5527




F20240531072811





BLK:10,SNR1: 22.579 ,SNR2: 41.211




0011+344 2024/05/30 22.50UT TOYOKAWA-FUJI



T20240531072809





BLK:10,SNR1: 0.16505 ,SNR2: 1.4785




Frequency (Hz)

K20240531072806




BLK:10,SNR1: 8.4481 ,SNR2: 20.079





Frequency (Hz)


0011+344 2024/05/30 22.50UT TOYOKAWA-KISO



F20240531072811





BLK:19,SNR1: 22.129 ,SNR2: 40.383




Frequency (Hz)

K20240531072806




BLK:19,SNR1: 2.8914 ,SNR2: 12.839





Frequency (Hz)


0011+344 2024/05/30 22.50UT FUJI -KISO



T20240531073646




BLK:15,SNR1: 0.13710 ,SNR2: 1.3072




Frequency (Hz)

0019-00 2024/05/30 22.64UT TOYOKAWA-FUJI


F20240531073648





BLK:15,SNR1: 0.15068 ,SNR2: 1.1123




Frequency (Hz)



T20240531073646




BLK:11,SNR1: 0.13164 ,SNR2: 1.2286





0019-00 2024/05/30 22.64UT TOYOKAWA-KISO



K20240531073643




BLK:11,SNR1: 0.25621 ,SNR2: 3.0708




F20240531073648




BLK:15,SNR1:-0.70904E-01,SNR2: 1.5974




K20240531073643



BLK:15,SNR1: 0.27888 ,SNR2: 2.9722





0019-00 2024/05/30 22.64UT FUJI -KISO






T20240531074700




BLK: 8,SNR1: 0.10266 ,SNR2: 0.73036




Frequency (Hz)

3C12 2024/05/30 22.81UT TOYOKAWA-FUJI


F20240531074702





BLK: 8,SNR1: 0.10766 ,SNR2: 1.7638




Frequency (Hz)





T20240531074700




BLK: 5,SNR1: 0.60606E-01,SNR2: 1.5366




K20240531074657




BLK: 5,SNR1: 0.61034 ,SNR2: 1.9385




3C12 2024/05/30 22.81UT TOYOKAWA-KISO





F20240531074702




BLK: 3,SNR1:-0.16755 ,SNR2: 0.61934




K20240531074657




BLK: 3,SNR1: 0.57637E-02,SNR2: 0.32534




3C12 2024/05/30 22.81UT FUJI -KISO





T20240531080102




BLK:12,SNR1: 1.5072 ,SNR2: 4.2185




F20240531080104




BLK:12,SNR1: 3.6644 ,SNR2: 9.5898




0044-056 2024/05/30 23.05UT TOYOKAWA-FUJI



T20240531080102





BLK:14,SNR1: 2.6079 ,SNR2: 4.9597




Frequency (Hz)

K20240531080059




BLK:14,SNR1: 2.8151 ,SNR2: 9.9743





Frequency (Hz)


0044-056 2024/05/30 23.05UT TOYOKAWA-KISO





F20240531080104




BLK:15,SNR1: 3.3631 ,SNR2: 8.6733




K20240531080059





BLK:15,SNR1: 3.4416 ,SNR2: 6.6491




0044-056 2024/05/30 23.05UT FUJI -KISO



T20240531080823




BLK: 6,SNR1: 0.93997E-01,SNR2: 1.6411





3C26 2024/05/30 23.17UT TOYOKAWA-FUJI



F20240531080825




BLK: 6,SNR1: 0.15946 ,SNR2: 3.3715



T20240531080823





BLK: 7,SNR1: 0.27870 ,SNR2: 3.2319





3C26 2024/05/30 23.17UT TOYOKAWA-KISO

K20240531080820





BLK: 7,SNR1: 1.2941 ,SNR2: 4.5376






F20240531080825





BLK: 3,SNR1: 0.87933E-01,SNR2: 3.4059




Frequency (Hz)

3C26 2024/05/30 23.17UT FUJI -KISO


K20240531080820




BLK: 3,SNR1: 1.0934 ,SNR2: 4.9999




Frequency (Hz)



T20240531081322





BLK:24,SNR1: 6.0659 ,SNR2: 11.671





0056-00 2024/05/30 23.25UT TOYOKAWA-FUJI


F20240531081324




BLK:24,SNR1: 9.4200 ,SNR2: 22.750



T20240531081322





BLK:29,SNR1: 6.0485 ,SNR2: 11.625




Frequency (Hz)

K20240531081319




BLK:29,SNR1: 8.1399 ,SNR2: 19.815





Frequency (Hz)


0056-00 2024/05/30 23.25UT TOYOKAWA-KISO





F20240531081324




BLK:31,SNR1: 9.3339 ,SNR2: 22.545




K20240531081319





BLK:31,SNR1: 13.067 ,SNR2: 23.661




0056-00 2024/05/30 23.25UT FUJI -KISO





T20240531082304




BLK: 4, SNR1: 0.26253 , SNR2: 1.3668




F20240531082306





BLK: 4, SNR1: 2.5385 , SNR2: 6.3729




0106+01 2024/05/30 23.41UT TOYOKAWA-FUJI



T20240531082304





BLK: 3,SNR1: 0.11830E-01,SNR2: 0.60701





0106+01 2024/05/30 23.41UT TOYOKAWA-KISO


K20240531082301




BLK: 3,SNR1: 1.4611 ,SNR2: 4.4224





F20240531082306




BLK: 2,SNR1: 0.83409E-02,SNR2: 1.8794




K20240531082301





BLK: 2,SNR1:-0.13935 ,SNR2: 1.1954




0106+01 2024/05/30 23.41UT FUJI -KISO



T20240531083227





BLK: 9,SNR1: 0.22965 ,SNR2: 1.3500




0115-01 2024/05/30 23.57UT TOYOKAWA-FUJI


F20240531083229



BLK: 9,SNR1: 0.93325 ,SNR2: 1.6134





Frequency (Hz)






T20240531083227





BLK:12,SNR1: 0.19378 ,SNR2: 1.0486





0115-01 2024/05/30 23.57UT TOYOKAWA-KISO


K20240531083224




BLK:12,SNR1: 2.0300 ,SNR2: 6.4354




F20240531083229




BLK:20,SNR1: 0.62371 ,SNR2: 2.3380




K20240531083224





BLK:20,SNR1: 3.0845 ,SNR2: 6.1109




0115-01 2024/05/30 23.57UT FUJI -KISO



T20240531084526





BLK:28,SNR1: 2.8968 ,SNR2: 13.728





0128+03 2024/05/30 23.79UT TOYOKAWA-FUJI



F20240531084528




BLK:28,SNR1: 5.4691 ,SNR2: 15.205



T20240531084526





BLK:32,SNR1: 2.8894 ,SNR2: 13.695





0128+03 2024/05/30 23.79UT TOYOKAWA-KISO


K20240531084523




BLK:32,SNR1: 4.1812 ,SNR2: 9.8753



F20240531084528





BLK:29,SNR1: 5.4547 ,SNR2: 15.355





0128+03 2024/05/30 23.79UT FUJI -KISO


K20240531084523




BLK:29,SNR1: 4.0605 ,SNR2: 9.5957



T20240531085200




BLK:26,SNR1: 1.8906 ,SNR2: 18.425





3C48 2024/05/30 23.89UT TOYOKAWA-FUJI



F20240531085200




BLK:26,SNR1: 0.38533 ,SNR2: 1.7393



T20240531085200




BLK:28,SNR1: 2.1254 ,SNR2: 15.153





3C48 2024/05/30 23.89UT TOYOKAWA-KISO


K20240531085157




BLK:28,SNR1: 0.48823 ,SNR2: 3.8082



F20240531085202




BLK:28,SNR1: 0.39495 ,SNR2: 2.3489





3C48 2024/05/30 23.89UT FUJI -KISO

K20240531085157





BLK:28,SNR1: 0.41931 ,SNR2: 1.8918






T20240531091145





BLK:29,SNR1: 13.549 ,SNR2: 24.436





0155-109 2024/05/31 0.22UT TOYOKAWA-FUJI



F20240531091147




BLK:29,SNR1: 12.193 ,SNR2: 29.815



T20240531091145





BLK:30,SNR1: 13.537 ,SNR2: 24.414





0155-109 2024/05/31 0.22UT TOYOKAWA-KISO


K20240531091142




BLK:30,SNR1: 9.5453 ,SNR2: 23.873



F20240531091147





BLK:26,SNR1: 12.422 ,SNR2: 30.366





0155-109 2024/05/31 0.22UT FUJI -KISO



K20240531091142




BLK:26,SNR1: 9.5482 ,SNR2: 23.883



T20240531091852




BLK:14,SNR1: 6.1826 ,SNR2: 15.575





0202+15 2024/05/31 0.34UT TOYOKAWA-FUJI


F20240531091854




BLK:14,SNR1: 5.0282 ,SNR2: 12.228



T20240531091852




BLK:19,SNR1: 5.4084 ,SNR2: 13.660





0202+15 2024/05/31 0.34UT TOYOKAWA-KISO


K20240531091849




BLK:19,SNR1: 6.4097 ,SNR2: 15.719





F20240531091854




BLK:29,SNR1: 4.3726 ,SNR2: 9.9580




K20240531091849







BLK:29,SNR1: 7.3448 ,SNR2: 14.102




0202+15 2024/05/31 0.34UT FUJI -KISO








0213+178 2024/05/31 0.54UT TOYOKAWA-FUJI





T20240531093042




BLK:22,SNR1: 4.1386 ,SNR2: 10.311




K20240531093039



BLK:22,SNR1: 2.7634 ,SNR2: 13.215





0213+178 2024/05/31 0.54UT TOYOKAWA-KISO








F20240531093044




BLK:18,SNR1: 7.8653 ,SNR2: 25.146




K20240531093039







BLK:18,SNR1: 2.7640 ,SNR2: 13.217








0213+178 2024/05/31 0.54UT FUJI -KISO






0223+341 2024/05/31 0.70UT TOYOKAWA-FUJI








0223+341 2024/05/31 0.70UT TOYOKAWA-KISO





F20240531094017




BLK: 7,SNR1: 0.85422 ,SNR2: 2.8509




K20240531094012




BLK: 7,SNR1: 0.35435 ,SNR2: 1.3970




0223+341 2024/05/31 0.70UT FUJI -KISO



T20240531095639





BLK:26,SNR1: 9.6670 ,SNR2: 23.410





3C71 2024/05/31 0.97UT TOYOKAWA-FUJI



F20240531095641




BLK:26,SNR1: 18.791 ,SNR2: 33.701



T20240531095639





BLK:28,SNR1: 2.9133 ,SNR2: 12.898





3C71 2024/05/31 0.97UT TOYOKAWA-KISO



K20240531095637




BLK:28,SNR1: 3.0095 ,SNR2: 13.949



F20240531095641





BLK:27,SNR1: 17.991 ,SNR2: 32.003




Frequency (Hz)

3C71 2024/05/31 0.97UT FUJI -KISO


K20240531095637





BLK:27,SNR1: 3.0123 ,SNR2: 13.961




Frequency (Hz)




T20240531101554




BLK:17,SNR1: 1.3277 ,SNR2: 3.8877




F20240531101556



BLK:17,SNR1: 1.1402 ,SNR2: 2.9635





0258+350 2024/05/31 1.29UT TOYOKAWA-FUJI






T20240531101554





BLK:21,SNR1: 2.8548 ,SNR2: 12.682





0258+350 2024/05/31 1.29UT TOYOKAWA-KISO


K20240531101552




BLK:21,SNR1: 0.56087 ,SNR2: 2.2619





F20240531101556




BLK:16,SNR1: 0.66869 ,SNR2: 3.2204




K20240531101552




BLK:16,SNR1: 1.1694 ,SNR2: 3.9969




0258+350 2024/05/31 1.29UT FUJI -KISO



T20240531102543





BLK:15,SNR1: 0.40444 ,SNR2: 2.8855




Frequency (Hz)

F20240531102545




BLK:15,SNR1: 0.14607 ,SNR2: 2.3037




Frequency (Hz)


0308+305 2024/05/31 1.46UT TOYOKAWA-FUJI



T20240531102543





BLK:15,SNR1: 0.36079 ,SNR2: 3.4337




Frequency (Hz)

K20240531102541




BLK:15,SNR1: 0.47974 ,SNR2: 2.3630




Frequency (Hz)


0308+305 2024/05/31 1.46UT TOYOKAWA-KISO





F20240531102545




BLK:15,SNR1: 0.51468 ,SNR2: 1.3846




K20240531102541





BLK:15,SNR1: 1.8374 ,SNR2: 7.0043




0308+305 2024/05/31 1.46UT FUJI -KISO



T20240531103403




BLK: 6,SNR1: 0.60158 ,SNR2: 4.5900





3C84 2024/05/31 1.60UT TOYOKAWA-FUJI



F20240531103405




BLK: 6,SNR1: 0.43026E-01,SNR2: 0.82699



T20240531103403




BLK:17,SNR1: 0.49203 ,SNR2: 2.5831





3C84 2024/05/31 1.60UT TOYOKAWA-KISO


K20240531103401




BLK:17,SNR1: 0.72652 ,SNR2: 3.0099



F20240531103405





BLK:11,SNR1: 0.62417 ,SNR2: 1.7480





3C84 2024/05/31 1.60UT FUJI -KISO

K20240531103401





BLK:11,SNR1: 0.50780 ,SNR2: 2.4319








T20240531104120




BLK: 3,SNR1: 0.10804 ,SNR2: 2.4147




F20240531104122





BLK: 3,SNR1: 0.23671 ,SNR2: 1.3242




0324+119 2024/05/31 1.72UT TOYOKAWA-FUJI





T20240531104120




BLK: 7,SNR1: 0.33615 ,SNR2: 0.98502




K20240531104118





BLK: 7,SNR1: 0.57822 ,SNR2: 6.4081




0324+119 2024/05/31 1.72UT TOYOKAWA-KISO





F20240531104122




BLK: 6,SNR1: 0.81198 ,SNR2: 5.5968




K20240531104118





BLK: 6,SNR1: 1.0496 ,SNR2: 2.7008




0324+119 2024/05/31 1.72UT FUJI -KISO





T20240531105036




BLK: 7,SNR1: 0.13163 ,SNR2: 1.7895




F20240531105038





BLK: 7,SNR1: 0.34701 ,SNR2: 1.0496




0333+32 2024/05/31 1.87UT TOYOKAWA-FUJI





T20240531105036




BLK:10,SNR1: 0.20834 ,SNR2: 1.5972




K20240531105034




BLK:10,SNR1: 0.40372 ,SNR2: 2.0902




0333+32 2024/05/31 1.87UT TOYOKAWA-KISO




F20240531105038




BLK:15,SNR1: 0.13143 ,SNR2: 1.7673




K20240531105034





BLK:15,SNR1: 0.23920 ,SNR2: 2.1846




0333+32 2024/05/31 1.87UT FUJI -KISO





T20240531110338




BLK: 7,SNR1: 0.78801E-01,SNR2: 0.65798




F20240531110340




BLK: 7,SNR1: 0.47019 ,SNR2: 1.3937




0347+05 2024/05/31 2.09UT TOYOKAWA-FUJI




T20240531110338




BLK:16,SNR1: 0.17292 ,SNR2: 0.66567




K20240531110335



BLK:16,SNR1: 0.30370 ,SNR2: 2.0337




0347+05 2024/05/31 2.09UT TOYOKAWA-KISO







F20240531110340




BLK: 4,SNR1: 0.16579 ,SNR2: 0.71835




K20240531110335





BLK: 4,SNR1: 0.71772 ,SNR2: 2.5247




0347+05 2024/05/31 2.09UT FUJI -KISO




T20240531111913




BLK: 8,SNR1: 0.17041 ,SNR2: 3.4833




F20240531111915





BLK: 8,SNR1: 0.81150E-01,SNR2: 1.0669




0403-132 2024/05/31 2.35UT TOYOKAWA-FUJI



T20240531111913





BLK:14,SNR1: 0.38850 ,SNR2: 4.0705




Frequency (Hz)

K20240531111910




BLK:14,SNR1: 0.20451 ,SNR2: 1.1083




Frequency (Hz)


0403-132 2024/05/31 2.35UT TOYOKAWA-KISO




F20240531111915




BLK: 5,SNR1: 0.17440 ,SNR2: 1.7135




K20240531111910





BLK: 5,SNR1: 0.34260 ,SNR2: 2.0889




0403-132 2024/05/31 2.35UT FUJI -KISO





T20240531112823




BLK: 5,SNR1: 0.20398 ,SNR2: 1.9886




F20240531112825





BLK: 5,SNR1: 0.22533 ,SNR2: 1.0987




0411+05 2024/05/31 2.50UT TOYOKAWA-FUJI





T20240531112823




BLK:13,SNR1: 0.26829 ,SNR2: 2.2944




K20240531112821




BLK:13,SNR1: 0.29047E-01,SNR2: 0.30546




0411+05 2024/05/31 2.50UT TOYOKAWA-KISO





F20240531112825




BLK: 8,SNR1: 0.28501 ,SNR2: 0.95011




K20240531112821







BLK: 8,SNR1: 0.14206 ,SNR2: 1.5968




0411+05 2024/05/31 2.50UT FUJI -KISO










0422+178 2024/05/31 2.68UT TOYOKAWA-FUJI










0422+178 2024/05/31 2.68UT TOYOKAWA-KISO



F20240531113918




BLK: 6,SNR1: 0.99597 ,SNR2: 5.1406




Frequency (Hz)

K20240531113913




BLK: 6,SNR1: 0.59078 ,SNR2: 2.3227





Frequency (Hz)


0422+178 2024/05/31 2.68UT FUJI -KISO





T20240531114644




BLK:28,SNR1: 4.5042 ,SNR2: 11.451




F20240531114646





BLK:28,SNR1: 2.2426 ,SNR2: 10.548




3C119 2024/05/31 2.81UT TOYOKAWA-FUJI





T20240531114644




BLK:32,SNR1: 4.7990 ,SNR2: 9.9959




K20240531114642





BLK:32,SNR1: 1.2077 ,SNR2: 6.4674




3C119 2024/05/31 2.81UT TOYOKAWA-KISO



F20240531114646




BLK:25,SNR1: 2.2929 ,SNR2: 10.767





3C119 2024/05/31 2.81UT FUJI -KISO


K20240531114642




BLK:25,SNR1: 1.3097 ,SNR2: 6.7643




T20240531123452




BLK:24,SNR1: 19.417 ,SNR2: 71.664




F20240531123454





BLK:24,SNR1:-0.14937E-01,SNR2: 2.2077




3C138 2024/05/31 3.61UT TOYOKAWA-FUJI




T20240531123452




BLK:26,SNR1: 20.176 ,SNR2: 36.856




K20240531123449





BLK:26,SNR1: 2.9571 ,SNR2: 15.169




3C138 2024/05/31 3.61UT TOYOKAWA-KISO



F20240531123454





BLK:34,SNR1: 0.19585 ,SNR2: 3.0877





3C138 2024/05/31 3.61UT FUJI -KISO

K20240531123449





BLK:34,SNR1: 3.0719 ,SNR2: 14.934







T20240531124825




BLK:21,SNR1: 7.2313 ,SNR2: 54.357




F20240531124827





BLK:21,SNR1: 0.26985 ,SNR2: 2.7508




0531+194 2024/05/31 3.84UT TOYOKAWA-FUJI



T20240531124825





BLK:27,SNR1: 6.5678 ,SNR2: 44.345







0531+194 2024/05/31 3.84UT TOYOKAWA-KISO

K20240531124822




BLK:27,SNR1: 4.7746 ,SNR2: 13.620








0531+194 2024/05/31 3.84UT FUJI -KISO





T20240531125644




BLK:32,SNR1: 8.9820 ,SNR2: 60.933




F20240531125646





BLK:32,SNR1: 0.16328 ,SNR2: 3.9985




3C147 2024/05/31 3.97UT TOYOKAWA-FUJI





T20240531125644




BLK:37,SNR1: 8.8171 ,SNR2: 57.758




K20240531125641




BLK:37,SNR1: 1.6085 ,SNR2: 6.6109




3C147 2024/05/31 3.97UT TOYOKAWA-KISO





F20240531125646




BLK:27,SNR1: 0.30073 ,SNR2: 2.5590




K20240531125641





BLK:27,SNR1: 1.6389 ,SNR2: 7.0980




3C147 2024/05/31 3.97UT FUJI -KISO




T20240531130456




BLK: 8,SNR1: 0.68701 ,SNR2: 6.0279




F20240531130458





BLK: 8,SNR1: 0.94643E-02,SNR2: 2.0072




0548+16 2024/05/31 4.11UT TOYOKAWA-FUJI





T20240531130456




BLK:16,SNR1: 0.48701 ,SNR2: 3.0664




K20240531130454



BLK:16,SNR1: 0.10051 ,SNR2: 1.5407





0548+16 2024/05/31 4.11UT TOYOKAWA-KISO






F20240531130458





BLK: 4,SNR1: 1.1103 ,SNR2: 2.1906




Frequency (Hz)

K20240531130454




BLK: 4,SNR1: 0.71533E-01,SNR2: 0.69275





Frequency (Hz)


0548+16 2024/05/31 4.11UT FUJI -KISO





T20240531130907




BLK:13,SNR1: 1.7124 ,SNR2: 11.719




F20240531130909





BLK:13,SNR1: 0.10357 ,SNR2: 0.66669




0552+12 2024/05/31 4.18UT TOYOKAWA-FUJI





T20240531130907




BLK:19,SNR1: 0.69572 ,SNR2: 4.7532




K20240531130905





BLK:19,SNR1: 0.11438 ,SNR2: 0.41842




0552+12 2024/05/31 4.18UT TOYOKAWA-KISO





F20240531130909




BLK: 5,SNR1: 0.34007 ,SNR2: 0.79180




K20240531130905







BLK: 5,SNR1: 0.17430 ,SNR2: 0.88599





0552+12 2024/05/31 4.18UT FUJI -KISO







0556+191 2024/05/31 4.25UT TOYOKAWA-FUJI







BLK:20,SNR1: 3.6231 ,SNR2: 15.268




BLK:20,SNR1: 3.8787 ,SNR2: 16.361




0556+191 2024/05/31 4.25UT TOYOKAWA-KISO





F20240531131336




BLK:21,SNR1: 1.6182 ,SNR2: 7.6475




K20240531131331





BLK:21,SNR1: 3.8805 ,SNR2: 16.365




0556+191 2024/05/31 4.25UT FUJI -KISO




T20240531132120




BLK: 2,SNR1: 0.11932 ,SNR2: 0.69332




F20240531132122



BLK: 2,SNR1: 3.4902 ,SNR2: 10.724





0605-08 2024/05/31 4.38UT TOYOKAWA-FUJI








T20240531132120




BLK: 2,SNR1: 0.26314 ,SNR2: 5.7031




K20240531132118




BLK: 2,SNR1: 0.39469 ,SNR2: 0.60221




0605-08 2024/05/31 4.38UT TOYOKAWA-KISO




F20240531132122




BLK: 5,SNR1: 0.77935E-02,SNR2: 3.1299




K20240531132118





BLK: 5,SNR1: 0.92488 ,SNR2: 4.1761




0605-08 2024/05/31 4.38UT FUJI -KISO




T20240531134028




BLK:13,SNR1: 3.4627 ,SNR2: 14.509




F20240531134030





BLK:13,SNR1:-0.64926E-02,SNR2: 1.1567




3C161 2024/05/31 4.70UT TOYOKAWA-FUJI





T20240531134028




BLK:30,SNR1: 2.6077 ,SNR2: 11.246




K20240531134025





BLK:30,SNR1: 3.6192 ,SNR2: 10.026




3C161 2024/05/31 4.70UT TOYOKAWA-KISO



F20240531134030





BLK:13,SNR1:-0.57743E-01,SNR2: 1.0698




Frequency (Hz)

K20240531134025




BLK:13,SNR1: 6.9230 ,SNR2: 12.773





Frequency (Hz)


3C161 2024/05/31 4.70UT FUJI -KISO



T20240531140801




BLK: 2,SNR1: 0.27818 ,SNR2: 0.91251




Frequency (Hz)

F20240531140803




BLK: 2,SNR1:-0.22239E-01,SNR2: 1.1851





Frequency (Hz)


0652-130 2024/05/31 5.16UT TOYOKAWA-FUJI





T20240531140801




BLK: 2,SNR1: 0.11640E-01,SNR2: 0.35452




K20240531140759




BLK: 2,SNR1: 0.56697 ,SNR2: 2.2047




0652-130 2024/05/31 5.16UT TOYOKAWA-KISO





F20240531140803




BLK: 6,SNR1:-0.10143 ,SNR2: 0.46413




K20240531140759



BLK: 6,SNR1: 1.7235 ,SNR2: 7.5746





0652-130 2024/05/31 5.16UT FUJI -KISO






T20240531141937





BLK: 7,SNR1: 0.27626 ,SNR2: 1.4753




Frequency (Hz)

F20240531141939




BLK: 7,SNR1:-0.87474E-01,SNR2: 1.7170





Frequency (Hz)


0703+138 2024/05/31 5.36UT TOYOKAWA-FUJI





T20240531141937




BLK: 5,SNR1: 0.90859E-01,SNR2: 0.32821




K20240531141935





BLK: 5,SNR1: 1.4636 ,SNR2: 7.6522




0703+138 2024/05/31 5.36UT TOYOKAWA-KISO





F20240531141939




No.Good Data




K20240531141935





No.Good Data




0703+138 2024/05/31 5.36UT FUJI -KISO



T20240531142900




BLK: 4,SNR1: 0.21745 ,SNR2: 0.64891




Frequency (Hz)

F20240531142902




BLK: 4,SNR1:-0.79859E-01,SNR2: 1.1655




Frequency (Hz)


0713-024 2024/05/31 5.51UT TOYOKAWA-FUJI





T20240531142900




BLK: 4,SNR1: 0.12864 ,SNR2: 1.4760




K20240531142858




BLK: 4,SNR1: 1.1554 ,SNR2: 8.9421




0713-024 2024/05/31 5.51UT TOYOKAWA-KISO





F20240531142902




BLK: 5,SNR1:-0.34846 ,SNR2: 0.78456




K20240531142858





BLK: 5,SNR1: 0.95653 ,SNR2: 4.1850




0713-024 2024/05/31 5.51UT FUJI -KISO





T20240531143911




BLK: 3,SNR1: 0.72417E-01,SNR2: 1.8203




F20240531143913





BLK: 3,SNR1:-0.31650E-01,SNR2: 1.2759




0723+10 2024/05/31 5.68UT TOYOKAWA-FUJI





T20240531143911




BLK: 6,SNR1: 0.18259 ,SNR2: 0.75840




K20240531143909



BLK: 6,SNR1: 0.63386 ,SNR2: 4.1969





0723+10 2024/05/31 5.68UT TOYOKAWA-KISO






F20240531143913





BLK: 3,SNR1:-0.18060E-01,SNR2: 1.4195




Frequency (Hz)

K20240531143909




BLK: 3,SNR1: 0.59840 ,SNR2: 3.1752





Frequency (Hz)


0723+10 2024/05/31 5.68UT FUJI -KISO




T20240531144926




BLK: 1,SNR1:-0.20366E-01,SNR2: 0.28822E-01




F20240531144928





BLK: 1,SNR1: 4.2145 ,SNR2: 7.2010




0732+33 2024/05/31 5.85UT TOYOKAWA-FUJI





T20240531144926




BLK: 4,SNR1: 0.63754E-01,SNR2: 0.34064




K20240531144923





BLK: 4,SNR1: 0.43871,SNR2: 1.3123




0732+33 2024/05/31 5.85UT TOYOKAWA-KISO



F20240531144928




BLK: 4,SNR1: 0.26057 ,SNR2: 2.3346




Frequency (Hz)

K20240531144923




BLK: 4,SNR1: 0.26866 ,SNR2: 1.5525





Frequency (Hz)


0732+33 2024/05/31 5.85UT FUJI -KISO



T20240531145728





BLK: 8,SNR1: 0.30336 ,SNR2: 3.2087




Frequency (Hz)

F20240531145730




BLK: 8,SNR1: 0.14768 ,SNR2: 1.0841





Frequency (Hz)


0741-06 2024/05/31 5.99UT TOYOKAWA-FUJI



T20240531145728





BLK:12,SNR1: 0.26115 ,SNR2: 2.8085




Frequency (Hz)

K20240531145725




BLK:12,SNR1: 0.32985 ,SNR2: 2.2565





Frequency (Hz)


0741-06 2024/05/31 5.99UT TOYOKAWA-KISO



F20240531145730





BLK: 7,SNR1: 0.55261 ,SNR2: 1.5759




Frequency (Hz)

K20240531145725




BLK: 7,SNR1: 0.36570 ,SNR2: 2.4123





Frequency (Hz)


0741-06 2024/05/31 5.99UT FUJI -KISO




T20240531150713




BLK: 4,SNR1: 0.17559E-01,SNR2: 1.8957




F20240531150715



BLK: 4,SNR1:-0.17961,SNR2: 0.32170





0752-200 2024/05/31 6.15UT TOYOKAWA-FUJI






T20240531150713





BLK: 5,SNR1: 1.7622 ,SNR2: 8.4917




Frequency (Hz)

K20240531150711




BLK: 5,SNR1: 0.16677 ,SNR2: 0.81930





Frequency (Hz)


0752-200 2024/05/31 6.15UT TOYOKAWA-KISO





F20240531150715




BLK: 3,SNR1:-0.19394 ,SNR2: 2.0308




K20240531150711





BLK: 3,SNR1: 0.36887 ,SNR2: 2.7779




0752-200 2024/05/31 6.15UT FUJI -KISO




T20240531151447




BLK: 2,SNR1: 0.56920E-01,SNR2: 0.44605




F20240531151449





BLK: 2,SNR1: 0.35973 ,SNR2: 1.5996




3C190 2024/05/31 6.27UT TOYOKAWA-FUJI





T20240531151447




BLK: 4,SNR1: 0.42920 ,SNR2: 8.4702




K20240531151444




BLK: 4,SNR1: 0.83607 ,SNR2: 7.7422




3C190 2024/05/31 6.27UT TOYOKAWA-KISO



F20240531151449





BLK: 3,SNR1: 0.57563 ,SNR2: 2.1518




Frequency (Hz)

K20240531151444




BLK: 3,SNR1:-0.45765E-01,SNR2: 0.84994





Frequency (Hz)


3C190 2024/05/31 6.27UT FUJI -KISO



T20240531152712




BLK: 8,SNR1: 0.16669 ,SNR2: 1.7652




Frequency (Hz)

F20240531152714




BLK: 8,SNR1: 0.26134E-01,SNR2: 2.0219




Frequency (Hz)


3C196 2024/05/31 6.48UT TOYOKAWA-FUJI



T20240531152712





BLK:11,SNR1: 0.34493 ,SNR2: 1.7891




Frequency (Hz)

K20240531152710




BLK:11,SNR1: 0.38553 ,SNR2: 1.5927





Frequency (Hz)


3C196 2024/05/31 6.48UT TOYOKAWA-KISO



F20240531152714





BLK:11,SNR1: 0.84075E-01,SNR2: 1.1091




Frequency (Hz)

K20240531152710




BLK:11,SNR1: 0.33105 ,SNR2: 1.1280





Frequency (Hz)

3C196 2024/05/31 6.48UT FUJI -KISO








T20240531153821




BLK: 6,SNR1: 0.15601 ,SNR2: 0.53563




F20240531153823





BLK: 6,SNR1: 0.70617E-01,SNR2: 0.96077




0821+394 2024/05/31 6.67UT TOYOKAWA-FUJI




T20240531153821




BLK: 3,SNR1: 0.34190E-01,SNR2: 0.61186




K20240531153819





BLK: 3,SNR1: 0.93911 ,SNR2: 2.3748




0821+394 2024/05/31 6.67UT TOYOKAWA-KISO



F20240531153823





BLK: 5,SNR1: 0.19425 ,SNR2: 1.6601




Frequency (Hz)

K20240531153819




BLK: 5,SNR1: 0.92091 ,SNR2: 3.1186





Frequency (Hz)


0821+394 2024/05/31 6.67UT FUJI -KISO





T20240531155002




BLK: 4,SNR1: 0.65917E-01,SNR2: 1.3595




F20240531155004





BLK: 4,SNR1: 0.24657 ,SNR2: 1.6669




0834-19 2024/05/31 6.86UT TOYOKAWA-FUJI




T20240531155002




BLK: 6,SNR1:-0.10515E-01,SNR2: 1.2743




K20240531154959





BLK: 6,SNR1: 1.0030 ,SNR2: 3.7702




0834-19 2024/05/31 6.86UT TOYOKAWA-KISO



F20240531155004





BLK: 5,SNR1: 1.2667 ,SNR2: 3.1272




Frequency (Hz)

K20240531154959




BLK: 5,SNR1: 0.96661 ,SNR2: 4.3068




Frequency (Hz)


0834-19 2024/05/31 6.86UT FUJI -KISO



T20240531155507




BLK:18,SNR1: 3.3093 ,SNR2: 6.4943




Frequency (Hz)

0839-071 2024/05/31 6.95UT TOYOKAWA-FUJI


F20240531155509





BLK:18,SNR1: 6.2073 ,SNR2: 14.907




Frequency (Hz)



T20240531155507





BLK:20,SNR1: 5.3684 ,SNR2: 10.510




Frequency (Hz)

K20240531155504




BLK:20,SNR1: 6.5622 ,SNR2: 16.445




Frequency (Hz)

0839-071 2024/05/31 6.95UT TOYOKAWA-KISO






F20240531155509





BLK:23,SNR1: 6.6165 ,SNR2: 15.839




Frequency (Hz)

K20240531155504




BLK:23,SNR1: 7.0615 ,SNR2: 17.479





Frequency (Hz)


0839-071 2024/05/31 6.95UT FUJI -KISO



T20240531160608





BLK:26,SNR1: 7.2814 ,SNR2: 18.212




Frequency (Hz)

F20240531160610




BLK:26,SNR1: 7.0597 ,SNR2: 12.495





Frequency (Hz)


3C208 2024/05/31 7.13UT TOYOKAWA-FUJI



T20240531160608





BLK:33,SNR1: 7.0700 ,SNR2: 17.486




Frequency (Hz)

K20240531160605





BLK:33,SNR1: 11.402 ,SNR2: 27.009





Frequency (Hz)

3C208 2024/05/31 7.13UT TOYOKAWA-KISO







BLK:31,SNR1: 7.7003 ,SNR2: 19.090




BLK:31,SNR1: 11.546 ,SNR2: 27.353




3C208 2024/05/31 7.13UT FUJI -KISO



T20240531162249





BLK: 6,SNR1: 0.15748 ,SNR2: 0.72368




Frequency (Hz)

F20240531162251




BLK: 6,SNR1: 0.80000E-01,SNR2: 1.2469





Frequency (Hz)


3C216 2024/05/31 7.41UT TOYOKAWA-FUJI



T20240531162249





BLK:15,SNR1: 0.68483E-01,SNR2: 1.8156




Frequency (Hz)

K20240531162247




BLK:15,SNR1: 0.45375 ,SNR2: 2.0736





Frequency (Hz)


3C216 2024/05/31 7.41UT TOYOKAWA-KISO



F20240531162251





BLK: 8,SNR1: 0.91089 ,SNR2: 5.3977




Frequency (Hz)

K20240531162247




BLK: 8,SNR1: 0.57513 ,SNR2: 3.1787




Frequency (Hz)


3C216 2024/05/31 7.41UT FUJI -KISO



T20240531164140





BLK:21,SNR1: 6.0898 ,SNR2: 14.665




Frequency (Hz)

F20240531164142




BLK:21,SNR1: 4.2236 ,SNR2: 10.348




Frequency (Hz)

0926+117 2024/05/31 7.72UT TOYOKAWA-FUJI






T20240531164140





BLK:18,SNR1: 6.5727 ,SNR2: 15.663




Frequency (Hz)

K20240531164138




BLK:18,SNR1: 7.8916 ,SNR2: 19.821





Frequency (Hz)


0926+117 2024/05/31 7.72UT TOYOKAWA-KISO



F20240531164142





BLK:25,SNR1: 3.8748 ,SNR2: 9.7104




Frequency (Hz)

K20240531164138




BLK:25,SNR1: 7.7822 ,SNR2: 19.546





Frequency (Hz)


0926+117 2024/05/31 7.72UT FUJI -KISO



T20240531164924





BLK:25,SNR1: 8.9166 ,SNR2: 22.342




Frequency (Hz)

F20240531164926




BLK:25,SNR1: 8.7358 ,SNR2: 21.889





Frequency (Hz)


3C222 2024/05/31 7.85UT TOYOKAWA-FUJI



T20240531164924





BLK:29,SNR1: 8.8446 ,SNR2: 22.161




Frequency (Hz)

3C222 2024/05/31 7.85UT TOYOKAWA-KISO


K20240531164921




BLK:29,SNR1: 8.7197 ,SNR2: 21.836




Frequency (Hz)



F20240531164926




BLK:31,SNR1: 8.6606 ,SNR2: 21.863




Frequency (Hz)

K20240531164921




BLK:31,SNR1: 6.7953 ,SNR2: 20.476





Frequency (Hz)


3C222 2024/05/31 7.85UT FUJI -KISO



T20240531175004




BLK:14,SNR1: 0.21631 ,SNR2: 1.5091




Frequency (Hz)

F20240531175006




BLK:14,SNR1: 0.44972 ,SNR2: 2.1139




Frequency (Hz)


1034+404 2024/05/31 8.86UT TOYOKAWA-FUJI





T20240531175004




BLK:14,SNR1: 2.8498 ,SNR2: 13.228




K20240531175001




BLK:14,SNR1: 2.8271 ,SNR2: 4.2333




1034+404 2024/05/31 8.86UT TOYOKAWA-KISO



F20240531175006





BLK:14,SNR1: 0.31986 ,SNR2: 1.4737




Frequency (Hz)

K20240531175001



BLK:14,SNR1: 1.8066 ,SNR2: 6.2397



Frequency (Hz)

1034+404 2024/05/31 8.86UT FWJ -KISO

