





BLK: 4,SNR1: 1.1763 ,SNR2: 27.152





BLK: 4,SNR1: 0.53664E-01,SNR2: 0.52463




2227+444 2024/06/02 20.56UT TOYOKAWA-FUJI



T20240603053202





BLK: 2,SNR1: 29.380 ,SNR2: 298.76




Frequency (Hz)

2227+444 2024/06/02 20.56UT TOYOKAWA-KISO


K20240603053159





BLK: 2,SNR1: 0.34051 ,SNR2: 0.60532




Frequency (Hz)



F20240603053204





BLK: 2, SNR1: 0.40919 , SNR2: 6.2371




Frequency (Hz)

K20240603053159




BLK: 2, SNR1: 0.44864 , SNR2: 5.6831





Frequency (Hz)


2227+444 2024/06/02 20.56UT FUJI -KISO



T20240603054411





BLK: 5, SNR1: 0.10844 , SNR2: 0.45803




Frequency (Hz)

F20240603054413




BLK: 5, SNR1: 1.2493 , SNR2: 3.1490





Frequency (Hz)


2239+333 2024/06/02 20.76UT TOYOKAWA-FUJI



T20240603054411





BLK: 1,SNR1: 0.25107 ,SNR2: 0.24559




Frequency (Hz)

K20240603054408




BLK: 1,SNR1: 0.94035 ,SNR2: 3.0795





Frequency (Hz)


2239+333 2024/06/02 20.76UT TOYOKAWA-KISO



F20240603054413





BLK:21,SNR1: 4.1194 ,SNR2: 10.215




Frequency (Hz)

K20240603054408




BLK:21,SNR1: 3.0029 ,SNR2: 13.244




Frequency (Hz)


2239+333 2024/06/02 20.76UT FUJI -KISO




T20240603054828




BLK: 3,SNR1: 0.24556E-01,SNR2: 0.79496




F20240603054830




BLK: 3,SNR1: 0.47114 ,SNR2: 2.1899




2243+394 2024/06/02 20.84UT TOYOKAWA-FUJI




T20240603054828




BLK: 7,SNR1: 0.43931 ,SNR2: 4.8131




K20240603054825




BLK: 7,SNR1: 0.53762 ,SNR2: 3.5912





2243+394 2024/06/02 20.84UT TOYOKAWA-KISO









BLK:13,SNR1: 0.21326 ,SNR2: 1.4069





BLK:13,SNR1: 0.63644 ,SNR2: 2.6420




2243+394 2024/06/02 20.84UT FUJI -KISO



T20240603060425





BLK: 7,SNR1: 4.6487 ,SNR2: 19.740




Frequency (Hz)

F20240603060427




BLK: 7,SNR1:-0.44879E-01,SNR2: 1.9100





Frequency (Hz)


2259+481 2024/06/02 21.10UT TOYOKAWA-FUJI



T20240603060425





BLK: 4,SNR1: 8.0840 ,SNR2: 60.821




Frequency (Hz)

K20240603060422




BLK: 4,SNR1: 0.93893E-01,SNR2: 1.1843




Frequency (Hz)


2259+481 2024/06/02 21.10UT TOYOKAWA-KISO



F20240603060427




BLK: 5,SNR1:-0.46578E-01,SNR2: 1.4944




Frequency (Hz)

2259+481 2024/06/02 21.10UT FUJI -KISO


K20240603060422





BLK: 5,SNR1: 0.23927 ,SNR2: 2.0054




Frequency (Hz)



T20240603063039




BLK:12,SNR1: 0.50284 ,SNR2: 3.0121




Frequency (Hz)

F20240603063041




BLK:12,SNR1: 3.7210 ,SNR2: 9.1479





Frequency (Hz)


2325+269 2024/06/02 21.54UT TOYOKAWA-FUJI



T20240603063039





BLK:14,SNR1: 0.47573 ,SNR2: 2.3700




Frequency (Hz)

2325+269 2024/06/02 21.54UT TOYOKAWA-KISO


K20240603063036





BLK:14,SNR1: 8.3923 ,SNR2: 20.435




Frequency (Hz)



F20240603063041





BLK:23,SNR1: 2.5810 ,SNR2: 7.0529




Frequency (Hz)

K20240603063036




BLK:23,SNR1: 7.2873 ,SNR2: 17.744





Frequency (Hz)


2325+269 2024/06/02 21.54UT FUJI -KISO



T20240603063921





BLK: 4,SNR1: 2.9004 ,SNR2: 22.627




Frequency (Hz)

F20240603063923




BLK: 4,SNR1: 0.61511 ,SNR2: 3.5643




Frequency (Hz)

2334+085 2024/06/02 21.68UT TOYOKAWA-FUJI






T20240603063921





BLK: 6,SNR1: 12.942 ,SNR2: 104.76




Frequency (Hz)

K20240603063918




BLK: 6,SNR1: 1.4443 ,SNR2: 4.8269





Frequency (Hz)


2334+085 2024/06/02 21.68UT TOYOKAWA-KISO



F20240603063923





BLK:10,SNR1: 0.98195 ,SNR2: 2.9901




Frequency (Hz)

K20240603063918




BLK:10,SNR1: 0.81662 ,SNR2: 1.6502





Frequency (Hz)

2334+085 2024/06/02 21.68UT FUJI -KISO






T20240603065303




2347-02 2024/06/02 21.91UT TOYOKAWA-FUJI


F20240603065305



T20240603065303




BLK:24,SNR1: 3.8137 ,SNR2: 16.390




Frequency (Hz)

K20240603065300




BLK:24,SNR1: 4.0959 ,SNR2: 10.150




Frequency (Hz)


2347-02 2024/06/02 21.91UT TOYOKAWA-KISO



F20240603065305




BLK:18,SNR1: 4.7102 ,SNR2: 11.214




Frequency (Hz)

K20240603065300




BLK:18,SNR1: 4.9552 ,SNR2: 12.099





Frequency (Hz)


2347-02 2024/06/02 21.91UT FUJI -KISO



T20240603065957





BLK: 3,SNR1: 0.55999 ,SNR2: 2.9179




Frequency (Hz)

F20240603065959




BLK: 3,SNR1: 0.14489 ,SNR2: 1.5189





Frequency (Hz)


2354+14 2024/06/02 22.03UT TOYOKAWA-FUJI





T20240603065957




BLK: 8,SNR1: 0.25649 ,SNR2: 2.8214




K20240603065954




BLK: 8,SNR1: 5.6963 ,SNR2: 15.638




2354+14 2024/06/02 22.03UT TOYOKAWA-KISO



F20240603065959




BLK: 4,SNR1: 0.10499 ,SNR2: 1.9892




Frequency (Hz)

K20240603065954




BLK: 4,SNR1: 6.7805 ,SNR2: 18.292





Frequency (Hz)

2354+14 2024/06/02 22.03UT FUJI -KISO






T20240603070859



BLK:14,SNR1: 1.2696 ,SNR2: 5.1845




Frequency (Hz)


3C2

2024/06/02 22.18UT TOYOKAWA-FUJI


F20240603070901





BLK:14,SNR1: 5.2420 ,SNR2: 12.946




Frequency (Hz)



T20240603070859





BLK:16,SNR1: 0.99842 ,SNR2: 4.6493





3C2

2024/06/02 22.18UT TOYOKAWA-KISO



K20240603070856




BLK:16,SNR1: 1.8797 ,SNR2: 7.0950





F20240603070901




BLK:14,SNR1: 4.8145 ,SNR2: 12.087




K20240603070856





BLK:14,SNR1: 2.5023 ,SNR2: 4.8704




3C2 2024/06/02 22.18UT FUJI -KISO



T20240603071621




BLK: 4,SNR1: 0.83673E-01,SNR2: 0.34564




Frequency (Hz)

F20240603071623




BLK: 4,SNR1: 0.15785 ,SNR2: 1.6463





Frequency (Hz)


0011+344 2024/06/02 22.30UT TOYOKAWA-FUJI



T20240603071621





BLK: 4,SNR1:-0.46286E-01,SNR2: 0.18567




Frequency (Hz)

K20240603071618




BLK: 4,SNR1: 0.36158 ,SNR2: 5.5993





Frequency (Hz)


0011+344 2024/06/02 22.30UT TOYOKAWA-KISO



F20240603071623





BLK: 4,SNR1: 0.49736 ,SNR2: 6.7432




Frequency (Hz)

K20240603071618




BLK: 4,SNR1: 0.21518 ,SNR2: 0.91991





Frequency (Hz)


0011+344 2024/06/02 22.30UT FUJI -KISO



T20240603072458





BLK:17,SNR1: 2.1479 ,SNR2: 5.8284




Frequency (Hz)

F20240603072500




BLK:17,SNR1: 2.9731 ,SNR2: 6.6747




Frequency (Hz)


0019-00 2024/06/02 22.44UT TOYOKAWA-FUJI




T20240603072458




BLK:16,SNR1: 1.9263 ,SNR2: 5.2863




K20240603072455



BLK:16,SNR1: 6.7056 ,SNR2: 16.589




0019-00 2024/06/02 22.44UT TOYOKAWA-KISO






F20240603072500





BLK:21,SNR1: 2.3880 ,SNR2: 5.9112




Frequency (Hz)

K20240603072455




BLK:21,SNR1: 6.0930 ,SNR2: 15.104




Frequency (Hz)


0019-00 2024/06/02 22.44UT FUJI -KISO




T20240603073512




BLK: 8,SNR1: 3.5195 ,SNR2: 6.5440




F20240603073514




BLK: 8,SNR1: 1.2926 ,SNR2: 3.0749




3C12 2024/06/02 22.61UT TOYOKAWA-FUJI




T20240603073512




BLK:12,SNR1: 1.4918 ,SNR2: 6.4021




K20240603073509




BLK:12,SNR1: 2.8151 ,SNR2: 7.4035




3C12 2024/06/02 22.61UT TOYOKAWA-KISO




F20240603073514




BLK:11,SNR1: 1.5871 ,SNR2: 4.9052




K20240603073509





BLK:11,SNR1: 3.7223 ,SNR2: 9.5755




3C12 2024/06/02 22.61UT FUJI -KISO



T20240603074914





BLK:25,SNR1: 11.301 ,SNR2: 27.701




Frequency (Hz)

F20240603074916




BLK:25,SNR1: 11.519 ,SNR2: 21.852





Frequency (Hz)


0044-056 2024/06/02 22.85UT TOYOKAWA-FUJI



T20240603074914





BLK:27,SNR1: 19.270 ,SNR2: 35.519




Frequency (Hz)

K20240603074911




BLK:27,SNR1: 13.360 ,SNR2: 32.582





Frequency (Hz)


0044-056 2024/06/02 22.85UT TOYOKAWA-KISO



F20240603074916





BLK:33,SNR1: 16.235 ,SNR2: 27.746




Frequency (Hz)

K20240603074911




BLK:33,SNR1: 13.386 ,SNR2: 32.643




Frequency (Hz)


0044-056 2024/06/02 22.85UT FUJI -KISO



T20240603075635



BLK: 2,SNR1: 0.34140 ,SNR2: 1.3044




Frequency (Hz)


3C26

2024/06/02 22.97UT TOYOKAWA-FUJI


F20240603075637



BLK: 2,SNR1: 0.58552E-01,SNR2: 0.90968





Frequency (Hz)






T20240603075635





BLK: 9,SNR1: 0.22835 ,SNR2: 0.90745





3C26 2024/06/02 22.97UT TOYOKAWA-KISO


K20240603075633




BLK: 9,SNR1: 0.42266 ,SNR2: 2.2185



F20240603075637




BLK: 3,SNR1: 0.72923 ,SNR2: 10.194




Frequency (Hz)

3C26 2024/06/02 22.97UT FUJI -KISO


K20240603075633





BLK: 3,SNR1: 1.4332 ,SNR2: 4.6973




Frequency (Hz)



T20240603080134





BLK:36,SNR1: 19.290 ,SNR2: 35.887




Frequency (Hz)

0056-00 2024/06/02 23.05UT TOYOKAWA-FUJI


F20240603080136





BLK:36,SNR1: 19.486 ,SNR2: 36.184




Frequency (Hz)



T20240603080134





BLK:37,SNR1: 19.286 ,SNR2: 35.880




Frequency (Hz)

0056-00 2024/06/02 23.05UT TOYOKAWA-KISO


K20240603080132





BLK:37,SNR1: 10.066 ,SNR2: 25.105




Frequency (Hz)





F20240603080136




BLK:38,SNR1: 19.021 ,SNR2: 35.331




K20240603080132





BLK:38,SNR1: 9.9582 ,SNR2: 24.845




0056-00 2024/06/02 23.05UT FUJI -KISO



T20240603081116




BLK:23,SNR1: 41.641 ,SNR2: 56.772





0106+01 2024/06/02 23.22UT TOYOKAWA-FUJI



F20240603081116




BLK:23,SNR1: 4.1359 ,SNR2: 10.295



T20240603081116





BLK:26,SNR1: 45.928 ,SNR2: 61.744





0106+01 2024/06/02 23.22UT TOYOKAWA-KISO


K20240603081113




BLK:26,SNR1: 12.209 ,SNR2: 21.932




F20240603081118




BLK:23,SNR1: 4.1201 ,SNR2: 10.242




K20240603081113



BLK:23,SNR1: 12.287 ,SNR2: 21.892





0106+01 2024/06/02 23.22UT FUJI -KISO






T20240603082039




BLK: 8,SNR1: 1.5100 ,SNR2: 3.8347





0115-01 2024/06/02 23.37UT TOYOKAWA-FUJI



F20240603082041




BLK: 8,SNR1: 0.77825 ,SNR2: 6.4636



T20240603082039





BLK:11,SNR1: 3.3561 ,SNR2: 8.2405





0115-01 2024/06/02 23.37UT TOYOKAWA-KISO



K20240603082037




BLK:11,SNR1: 1.8585 ,SNR2: 3.7619





F20240603082041




BLK:12,SNR1: 0.52070 ,SNR2: 4.6868




K20240603082037





BLK:12,SNR1: 1.2339 ,SNR2: 4.5612




0115-01 2024/06/02 23.37UT FUJI -KISO





T20240603083338




BLK:12,SNR1: 0.80920 ,SNR2: 4.1124




F20240603083340





BLK:12,SNR1: 2.3237 ,SNR2: 7.3059




0128+03 2024/06/02 23.59UT TOYOKAWA-FUJI



T20240603083338





BLK:18,SNR1: 1.0596 ,SNR2: 3.8978





0128+03 2024/06/02 23.59UT TOYOKAWA-KISO


K20240603083335




BLK:18,SNR1: 1.5049 ,SNR2: 3.1724




F20240603083340




BLK: 8,SNR1: 3.0020 ,SNR2: 9.1902




K20240603083335




BLK: 8,SNR1: 2.6626 ,SNR2: 5.2670




0128+03 2024/06/02 23.59UT FUJI -KISO



T20240603084012




BLK:17,SNR1: 2.4605 ,SNR2: 5.5940





3C48 2024/06/02 23.70UT TOYOKAWA-FUJI



F20240603084014




BLK:17,SNR1: 1.5875 ,SNR2: 4.0278



T20240603084012





BLK:29,SNR1: 2.0102 ,SNR2: 4.2654





3C48 2024/06/02 23.70UT TOYOKAWA-KISO

K20240603084009




BLK:29,SNR1: 0.46823 ,SNR2: 2.2200






F20240603084014





BLK:16,SNR1: 1.4574 ,SNR2: 6.1284





3C48 2024/06/02 23.70UT FUJI -KISO


K20240603084009




BLK:16,SNR1: 0.45612 ,SNR2: 2.6473





T20240603090704




BLK: 9,SNR1: 1.6931 ,SNR2: 5.9172




F20240603090706




BLK: 9,SNR1:-0.39959 ,SNR2: 0.37890




0202+15 2024/06/03 0.15UT TOYOKAWA-FUJI



T20240603090704





BLK:13,SNR1: 0.82448 ,SNR2: 4.1160





0202+15 2024/06/03 0.15UT TOYOKAWA-KISO


K20240603090701




BLK:13,SNR1: 0.52666 ,SNR2: 3.5648





F20240603090706




BLK: 8,SNR1: 1.2528 ,SNR2: 3.0914




K20240603090701





BLK: 8,SNR1: 0.97768 ,SNR2: 3.4789




0202+15 2024/06/03 0.15UT FUJI -KISO




T20240603091854




BLK:10,SNR1: 1.5113 ,SNR2: 3.9516




F20240603091856





BLK:10,SNR1: 0.55567 ,SNR2: 2.7956




0213+178 2024/06/03 0.34UT TOYOKAWA-FUJI




T20240603091854




BLK:14,SNR1: 1.3731 ,SNR2: 3.4931




K20240603091851




BLK:14,SNR1: 0.62255 ,SNR2: 2.7588




0213+178 2024/06/03 0.34UT TOYOKAWA-KISO



F20240603091856




BLK: 8,SNR1: 0.90170 ,SNR2: 2.9552




Frequency (Hz)

K20240603091851




BLK: 8,SNR1: 0.54580 ,SNR2: 2.5787





Frequency (Hz)


0213+178 2024/06/03 0.34UT FUJI -KISO





T20240603092828




BLK: 4,SNR1: 0.11994 ,SNR2: 0.36762




F20240603092830



BLK: 4,SNR1: 0.84557 ,SNR2: 2.7763





0223+341 2024/06/03 0.50UT TOYOKAWA-FUJI








T20240603092828




BLK: 6,SNR1: 0.47408E-01,SNR2: 0.26242




K20240603092825





BLK: 6,SNR1: 0.33835 ,SNR2: 1.8193




0223+341 2024/06/03 0.50UT TOYOKAWA-KISO





F20240603092830




BLK: 6,SNR1: 0.54520 ,SNR2: 1.8018




K20240603092825





BLK: 6,SNR1: 0.19682 ,SNR2: 1.0316




0223+341 2024/06/03 0.50UT FUJI -KISO





T20240603094452




BLK: 2,SNR1: 36.774 ,SNR2: 59.355




F20240603094454





BLK: 2,SNR1:-0.17324 ,SNR2: 0.0000




3C71 2024/06/03 0.78UT TOYOKAWA-FUJI



T20240603094452




BLK:10,SNR1: 3.1020 ,SNR2: 16.902




Frequency (Hz)

3C71 2024/06/03 0.78UT TOYOKAWA-KISO


K20240603094449





BLK:10,SNR1: 0.81545 ,SNR2: 3.0052




Frequency (Hz)





F20240603094454




BLK: 5,SNR1:-0.49669E-01,SNR2: 2.1000




K20240603094449





BLK: 5,SNR1: 1.0952 ,SNR2: 3.7316




3C71 2024/06/03 0.78UT FUJI -KISO





T20240603100406




BLK: 4,SNR1:-0.18882E-01,SNR2: 0.57710




F20240603100408





BLK: 4,SNR1: 0.38127 ,SNR2: 2.5377




0258+350 2024/06/03 1.10UT TOYOKAWA-FUJI





T20240603100406




BLK: 5,SNR1: 0.47574E-01,SNR2: 0.94029




K20240603100403




BLK: 5,SNR1: 0.24020 ,SNR2: 2.9402




0258+350 2024/06/03 1.10UT TOYOKAWA-KISO




F20240603100408




BLK: 5,SNR1: 0.57837 ,SNR2: 2.3282




K20240603100403



BLK: 5,SNR1: 0.34163 ,SNR2: 1.5993





0258+350 2024/06/03 1.10UT FUJI -KISO








T20240603101356




BLK: 6,SNR1: 0.20558 ,SNR2: 3.0649




F20240603101358





BLK: 6,SNR1:-0.52189E-02,SNR2: 1.2811




0308+305 2024/06/03 1.26UT TOYOKAWA-FUJI





T20240603101356




BLK:12,SNR1: 0.36398 ,SNR2: 3.1461




K20240603101353




BLK:12,SNR1: 0.66941E-01,SNR2: 0.72262




0308+305 2024/06/03 1.26UT TOYOKAWA-KISO





F20240603101358




BLK: 5,SNR1: 0.32039E-01,SNR2: 1.5920




K20240603101353





BLK: 5,SNR1: 0.23782 ,SNR2: 1.9906




0308+305 2024/06/03 1.26UT FUJI -KISO



T20240603102216




BLK:12,SNR1: 0.55542 ,SNR2: 1.3412





3C84 2024/06/03 1.40UT TOYOKAWA-FUJI


F20240603102218




BLK:12,SNR1: 0.81768 ,SNR2: 4.8978



T20240603102216




BLK:20,SNR1: 0.40438 ,SNR2: 1.3421





3C84 2024/06/03 1.40UT TOYOKAWA-KISO



K20240603102213




BLK:20,SNR1: 0.33848 ,SNR2: 2.0470



F20240603102218




BLK: 5,SNR1: 1.4329 ,SNR2: 5.4417




Frequency (Hz)

3C84 2024/06/03 1.40UT FUJI -KISO


K20240603102213





BLK: 5,SNR1: 1.0717 ,SNR2: 5.6057




Frequency (Hz)





T20240603102932




BLK: 1,SNR1: 0.95283E-01,SNR2: 3.7735




F20240603102934





BLK: 1,SNR1: 0.36578 ,SNR2: 1.4228




0324+119 2024/06/03 1.52UT TOYOKAWA-FUJI





T20240603102932




BLK: 6,SNR1: 0.54469E-01,SNR2: 1.6604




K20240603102929



BLK: 6,SNR1: 1.0476 ,SNR2: 5.3495




0324+119 2024/06/03 1.52UT TOYOKAWA-KISO








F20240603102934




No.Good Data




K20240603102929





No.Good Data




0324+119 2024/06/03 1.52UT FUJI -KISO




T20240603103849




BLK: 4,SNR1: 0.81992E-01,SNR2: 0.48979




F20240603103851





BLK: 4,SNR1:-0.10381 ,SNR2: 1.0609




0333+32 2024/06/03 1.68UT TOYOKAWA-FUJI



T20240603103849





BLK:13,SNR1: 0.51108E-01,SNR2: 1.4719





0333+32 2024/06/03 1.68UT TOYOKAWA-KISO



K20240603103847




BLK:13,SNR1: 2.9498 ,SNR2: 11.371



F20240603103851




BLK: 6,SNR1: 0.51702 ,SNR2: 3.3781




Frequency (Hz)

K20240603103847




BLK: 6,SNR1: 0.15166 ,SNR2: 1.0110





Frequency (Hz)


0333+32 2024/06/03 1.68UT FUJI -KISO



T20240603105150




BLK:11,SNR1: 0.11528 ,SNR2: 0.95711





0347+05 2024/06/03 1.89UT TOYOKAWA-FUJI



F20240603105152




BLK:11,SNR1: 2.0677 ,SNR2: 8.7070





T20240603105150




BLK: 8,SNR1: 0.57865E-01,SNR2: 1.0318




K20240603105147





BLK: 8,SNR1: 1.7309 ,SNR2: 4.9244




0347+05 2024/06/03 1.89UT TOYOKAWA-KISO



F20240603105152





BLK: 8,SNR1: 2.0475 ,SNR2: 8.7283





0347+05 2024/06/03 1.89UT FUJI -KISO



K20240603105147




BLK: 8,SNR1: 1.6496 ,SNR2: 7.3808




T20240603110725




BLK:11,SNR1: 0.12416 ,SNR2: 1.7215




F20240603110727



BLK:11,SNR1: 0.10017 ,SNR2: 1.1630





0403-132 2024/06/03 2.15UT TOYOKAWA-FUJI







T20240603110725




BLK:11,SNR1: 0.94734 ,SNR2: 4.8243




K20240603110722




BLK:11,SNR1: 0.89497 ,SNR2: 4.3449




0403-132 2024/06/03 2.15UT TOYOKAWA-KISO




F20240603110727




BLK: 8,SNR1: 0.26641E-01,SNR2: 0.87998




K20240603110722




BLK: 8,SNR1: 1.0505 ,SNR2: 5.1013




0403-132 2024/06/03 2.15UT FUJI -KISO





T20240603111635




BLK: 9,SNR1: 0.17156 ,SNR2: 1.1450




F20240603111637





BLK: 9,SNR1: 0.33832 ,SNR2: 1.1677




0411+05 2024/06/03 2.30UT TOYOKAWA-FUJI



T20240603111635





BLK:10,SNR1: 0.17421 ,SNR2: 1.3941





0411+05 2024/06/03 2.30UT TOYOKAWA-KISO



K20240603111632




BLK:10,SNR1: 0.76911E-01,SNR2: 0.45415





F20240603111637




BLK: 4,SNR1: 0.22667 ,SNR2: 1.1555




K20240603111632





BLK: 4,SNR1: 0.11621 ,SNR2: 1.4927




0411+05 2024/06/03 2.30UT FUJI -KISO




T20240603112728




BLK: 7,SNR1: 0.18405 ,SNR2: 1.5635




F20240603112730





BLK: 7,SNR1: 0.42330 ,SNR2: 1.5358




0422+178 2024/06/03 2.49UT TOYOKAWA-FUJI





T20240603112728




BLK: 7,SNR1: 0.18683E-01,SNR2: 1.1279




K20240603112726




BLK: 7,SNR1: 0.80502 ,SNR2: 3.0889




0422+178 2024/06/03 2.49UT TOYOKAWA-KISO





F20240603112730




BLK: 8,SNR1: 0.41473 ,SNR2: 3.3572




K20240603112726



BLK: 8,SNR1: 0.66863 ,SNR2: 5.4017





0422+178 2024/06/03 2.49UT FUJI -KISO








T20240603113457




BLK:29,SNR1: 8.7414 ,SNR2: 23.680




F20240603113459





BLK:29,SNR1: 1.3168 ,SNR2: 5.8945




3C119 2024/06/03 2.61UT TOYOKAWA-FUJI




T20240603113457




BLK:30,SNR1: 8.8513 ,SNR2: 24.282




K20240603113454





BLK:30,SNR1: 7.9696 ,SNR2: 21.618




3C119 2024/06/03 2.61UT TOYOKAWA-KISO




F20240603113459




BLK:32,SNR1: 2.6347 ,SNR2: 8.2312




K20240603113454





BLK:32,SNR1: 8.0751 ,SNR2: 21.919




3C119 2024/06/03 2.61UT FUJI -KISO




T20240603122304




BLK:28,SNR1: 24.100 ,SNR2: 88.888




F20240603122306




BLK:28,SNR1: 1.0171 ,SNR2: 4.9591




3C138 2024/06/03 3.41UT TOYOKAWA-FUJI





T20240603122304




BLK:29,SNR1: 23.116 ,SNR2: 97.672




K20240603122301




BLK:29,SNR1: 3.5003 ,SNR2: 13.171




3C138 2024/06/03 3.41UT TOYOKAWA-KISO



F20240603122306





BLK:31,SNR1: 0.97429 ,SNR2: 4.8881





3C138 2024/06/03 3.41UT FUJI -KISO



K20240603122301




BLK:31,SNR1: 10.847 ,SNR2: 13.427





T20240603123638




BLK:19,SNR1: 4.8594 ,SNR2: 21.142




F20240603123640




BLK:19,SNR1: 0.62967 ,SNR2: 2.9041




0531+194 2024/06/03 3.64UT TOYOKAWA-FUJI





T20240603123638




BLK:23,SNR1: 4.2378 ,SNR2: 18.144




K20240603123636







BLK:23,SNR1: 56.240 ,SNR2: 67.204




0531+194 2024/06/03 3.64UT TOYOKAWA-KISO










0531+194 2024/06/03 3.64UT FUJI -KISO




T20240603124457




BLK:32,SNR1: 18.489 ,SNR2: 72.232




F20240603124459





BLK:32,SNR1: 0.23144 ,SNR2: 4.8690




3C147 2024/06/03 3.78UT TOYOKAWA-FUJI



T20240603124457





BLK:35,SNR1: 17.081 ,SNR2: 66.760





3C147 2024/06/03 3.78UT TOYOKAWA-KISO


K20240603124454




BLK:35,SNR1: 2.1295 ,SNR2: 10.575





F20240603124459




BLK:31,SNR1: 0.24177 ,SNR2: 6.2728




K20240603124454





BLK:31,SNR1: 2.2221 ,SNR2: 11.628




3C147 2024/06/03 3.78UT FUJI -KISO




T20240603125309




BLK: 6,SNR1: 5.2691 ,SNR2: 20.867




F20240603125311





BLK: 6,SNR1: 2.3601 ,SNR2: 10.732




0548+16 2024/06/03 3.91UT TOYOKAWA-FUJI




T20240603125309




BLK: 9,SNR1: 2.0820 ,SNR2: 6.7728




K20240603125307





BLK: 9,SNR1: 5.0349 ,SNR2: 17.434




0548+16 2024/06/03 3.91UT TOYOKAWA-KISO





F20240603125311




BLK:12,SNR1: 0.21049 ,SNR2: 2.1148




K20240603125307





BLK:12,SNR1: 3.3596 ,SNR2: 12.856




0548+16 2024/06/03 3.91UT FUJI -KISO





T20240603125719




BLK: 9,SNR1: 12.225 ,SNR2: 99.161




F20240603125721



BLK: 9,SNR1: 0.33670 ,SNR2: 3.2800





0552+12 2024/06/03 3.98UT TOYOKAWA-FUJI








T20240603125719




BLK:14,SNR1: 8.8408 ,SNR2: 33.894




K20240603125717





BLK:14,SNR1: 1.2405 ,SNR2: 8.4232




0552+12 2024/06/03 3.98UT TOYOKAWA-KISO





F20240603125721




BLK: 9,SNR1: 1.2772 ,SNR2: 6.7163




K20240603125717





BLK: 9,SNR1: 1.9610 ,SNR2: 8.1082




0552+12 2024/06/03 3.98UT FUJI -KISO




T20240603130146




BLK:12,SNR1: 0.30213 ,SNR2: 2.6165




F20240603130148





BLK:12,SNR1: 0.51641 ,SNR2: 2.3003




0556+191 2024/06/03 4.06UT TOYOKAWA-FUJI





T20240603130146




BLK: 8,SNR1: 0.35098 ,SNR2: 2.4588




K20240603130144




BLK: 8,SNR1: 0.19402 ,SNR2: 2.2513




0556+191 2024/06/03 4.06UT TOYOKAWA-KISO





F20240603130148




BLK: 5,SNR1: 0.45235 ,SNR2: 1.8684




K20240603130144




BLK: 5,SNR1: 0.35074 ,SNR2: 1.2339




0556+191 2024/06/03 4.06UT FUJI -KISO




T20240603130932




BLK: 4,SNR1: 0.57948 ,SNR2: 6.6426




F20240603130934




BLK: 4,SNR1: 0.33458 ,SNR2: 1.4929




0605-08 2024/06/03 4.19UT TOYOKAWA-FUJI





T20240603130932




BLK: 4,SNR1: 0.77055 ,SNR2: 9.1782




K20240603130929





BLK: 4,SNR1: 0.79399 ,SNR2: 5.9143




0605-08 2024/06/03 4.19UT TOYOKAWA-KISO





F20240603130934




No.Good Data




K20240603130929



No.Good Data





0605-08 2024/06/03 4.19UT FUJI -KISO







T20240603132840




BLK:13,SNR1: 0.67428 ,SNR2: 3.9438




F20240603132842




BLK:13,SNR1:-0.93595E-02,SNR2: 1.7437




3C161 2024/06/03 4.51UT TOYOKAWA-FUJI





T20240603132840




BLK:27,SNR1: 0.55901 ,SNR2: 4.3639




K20240603132838





BLK:27,SNR1: 0.28614 ,SNR2: 1.1085




3C161 2024/06/03 4.51UT TOYOKAWA-KISO



F20240603132842





BLK: 8,SNR1:-0.20596E-01,SNR2: 1.7785




Frequency (Hz)

3C161 2024/06/03 4.51UT FUJI -KISO


K20240603132838





BLK: 8,SNR1: 0.27025 ,SNR2: 1.3855




Frequency (Hz)




T20240603135613




BLK: 7,SNR1: 0.60231E-01,SNR2: 0.45581




F20240603135615





BLK: 7,SNR1:-0.42221E-01,SNR2: 1.3319




0652-130 2024/06/03 4.97UT TOYOKAWA-FUJI





T20240603135613




BLK: 4,SNR1: 0.11512 ,SNR2: 0.66670




K20240603135610




BLK: 4,SNR1:-0.23750E-01,SNR2: 0.50178




0652-130 2024/06/03 4.97UT TOYOKAWA-KISO





F20240603135615




BLK: 5,SNR1: 0.10316 ,SNR2: 0.68388




K20240603135610





BLK: 5,SNR1: 0.48509 ,SNR2: 3.1515




0652-130 2024/06/03 4.97UT FUJI -KISO





T20240603140749




BLK: 4,SNR1: 0.95842E-01,SNR2: 1.1575




F20240603140751





BLK: 4,SNR1: 0.62022E-02,SNR2: 1.7243




0703+138 2024/06/03 5.16UT TOYOKAWA-FUJI





T20240603140749




BLK:13,SNR1: 0.10441 ,SNR2: 1.0533




K20240603140746



BLK:13,SNR1: 1.3188 ,SNR2: 7.9674





0703+138 2024/06/03 5.16UT TOYOKAWA-KISO








F20240603140751




BLK:11,SNR1: 0.16075E-01,SNR2: 0.50816




K20240603140746




BLK:11,SNR1: 1.4324 ,SNR2: 6.1692




0703+138 2024/06/03 5.16UT FUJI -KISO



T20240603141712





BLK:11,SNR1: 0.41550 ,SNR2: 3.3080




Frequency (Hz)

F20240603141714




BLK:11,SNR1:-0.87912E-01,SNR2: 1.0770





Frequency (Hz)


0713-024 2024/06/03 5.31UT TOYOKAWA-FUJI





T20240603141712




BLK:12,SNR1: 0.16291 ,SNR2: 1.2248




K20240603141709




BLK:12,SNR1: 1.3854 ,SNR2: 6.0120




0713-024 2024/06/03 5.31UT TOYOKAWA-KISO



F20240603141714





BLK:13,SNR1:-0.16445 ,SNR2: 0.97242




Frequency (Hz)

K20240603141709




BLK:13,SNR1: 1.0590 ,SNR2: 4.3378





Frequency (Hz)


0713-024 2024/06/03 5.31UT FUJI -KISO





T20240603142724




BLK: 3,SNR1: 0.22581 ,SNR2: 2.2845




F20240603142726





BLK: 3,SNR1:-0.59437E-01,SNR2: 0.91206




0723+10 2024/06/03 5.48UT TOYOKAWA-FUJI





T20240603142724




BLK: 3,SNR1:-0.14601E-01,SNR2: 0.50366




K20240603142721





BLK: 3,SNR1: 0.39936 ,SNR2: 1.3109




0723+10 2024/06/03 5.48UT TOYOKAWA-KISO





F20240603142726




BLK: 3,SNR1:-0.70381E-01,SNR2: 2.2599




K20240603142721





BLK: 3,SNR1: 0.60052 ,SNR2: 1.1716




0723+10 2024/06/03 5.48UT FUJI -KISO





T20240603143738




BLK: 4,SNR1: 0.11743 ,SNR2: 0.76894




F20240603143740



BLK: 4,SNR1: 4.2329 ,SNR2: 4.4056





0732+33 2024/06/03 5.66UT TOYOKAWA-FUJI






T20240603143738





BLK: 7,SNR1: 0.25000 ,SNR2: 0.44473




Frequency (Hz)

K20240603143735




BLK: 7,SNR1: 0.15434 ,SNR2: 1.9254





Frequency (Hz)


0732+33 2024/06/03 5.66UT TOYOKAWA-KISO





F20240603143740




BLK:11,SNR1: 3.7291 ,SNR2: 3.8796




K20240603143735





BLK:11,SNR1: 1.3150 ,SNR2: 6.1147




0732+33 2024/06/03 5.66UT FUJI -KISO



T20240603144540





BLK:19,SNR1: 0.44908 ,SNR2: 1.3786




Frequency (Hz)

F20240603144542




BLK:19,SNR1: 1.2046 ,SNR2: 4.3057





Frequency (Hz)


0741-06 2024/06/03 5.79UT TOYOKAWA-FUJI





T20240603144540




BLK:26,SNR1: 0.49384 ,SNR2: 1.5008




K20240603144537





BLK:26,SNR1: 5.2521 ,SNR2: 15.272




0741-06 2024/06/03 5.79UT TOYOKAWA-KISO





F20240603144542




BLK:23,SNR1: 2.3374 ,SNR2: 5.6866




K20240603144537





BLK:23,SNR1: 5.6251 ,SNR2: 16.105




0741-06 2024/06/03 5.79UT FUJI -KISO





T20240603145525




BLK:19,SNR1: 5.7234 ,SNR2: 14.286




F20240603145527





BLK:19,SNR1: 2.0813 ,SNR2: 10.713




0752-200 2024/06/03 5.95UT TOYOKAWA-FUJI





T20240603145525




BLK:29,SNR1: 6.0635 ,SNR2: 15.111




K20240603145522





BLK:29,SNR1: 2.8649 ,SNR2: 12.771




0752-200 2024/06/03 5.95UT TOYOKAWA-KISO





F20240603145527




BLK:22,SNR1: 2.0016 ,SNR2: 6.7693




K20240603145522



BLK:22,SNR1: 2.8820 ,SNR2: 12.837





0752-200 2024/06/03 5.95UT FUJI -KISO






T20240603150259





BLK: 3,SNR1: 0.12812 ,SNR2: 0.52550




Frequency (Hz)

F20240603150301




BLK: 3,SNR1: 0.14156 ,SNR2: 0.34399





Frequency (Hz)


3C190 2024/06/03 6.08UT TOYOKAWA-FUJI





T20240603150259




BLK: 8,SNR1: 0.90114E-01,SNR2: 0.68816




K20240603150256





BLK: 8,SNR1: 0.40469 ,SNR2: 2.4020




3C190 2024/06/03 6.08UT TOYOKAWA-KISO





F20240603150301




BLK:12,SNR1: 0.35444E-01,SNR2: 0.66725




K20240603150256





BLK:12,SNR1: 0.70611 ,SNR2: 3.2231




3C190 2024/06/03 6.08UT FUJI -KISO





T20240603151524




BLK: 8,SNR1: 0.27334 ,SNR2: 1.0904




F20240603151526





BLK: 8,SNR1: 0.58502 ,SNR2: 1.3418




3C196 2024/06/03 6.28UT TOYOKAWA-FUJI





T20240603151524




BLK: 8,SNR1: 0.19047 ,SNR2: 0.98134




K20240603151521





BLK: 8,SNR1: 0.59312 ,SNR2: 3.9038




3C196 2024/06/03 6.28UT TOYOKAWA-KISO





F20240603151526




BLK: 5,SNR1: 1.7067 ,SNR2: 2.2802




K20240603151521





BLK: 5,SNR1:-0.11860E-01,SNR2: 0.66718




3C196 2024/06/03 6.28UT FUJI -KISO





T20240603152634




BLK: 5,SNR1: 1.7314 ,SNR2: 7.5413




F20240603152636




BLK: 5,SNR1: 0.58238 ,SNR2: 2.1909





0821+394 2024/06/03 6.47UT TOYOKAWA-FUJI







BLK:12,SNR1: 0.92468 ,SNR2: 4.4408




BLK:12,SNR1: 0.82800 ,SNR2: 3.4888





0821+394 2024/06/03 6.47UT TOYOKAWA-KISO









BLK:13,SNR1: 11.044 ,SNR2: 14.750





BLK:13,SNR1: 0.62262 ,SNR2: 2.8946




0821+394 2024/06/03 6.47UT FUJI -KISO



T20240603153814




BLK:14,SNR1: 0.53056 ,SNR2: 3.2897




Frequency (Hz)

F20240603153816




BLK:14,SNR1: 3.5157 ,SNR2: 4.2811





Frequency (Hz)


0834-19 2024/06/03 6.67UT TOYOKAWA-FUJI



T20240603153814





BLK:19,SNR1: 0.41484 ,SNR2: 4.3136




Frequency (Hz)

K20240603153811




BLK:19,SNR1: 13.816 ,SNR2: 32.211




Frequency (Hz)


0834-19 2024/06/03 6.67UT TOYOKAWA-KISO



F20240603153816





BLK:19,SNR1: 1.1168 ,SNR2: 4.7756




Frequency (Hz)

K20240603153811




BLK:19,SNR1: 13.651 ,SNR2: 31.804





Frequency (Hz)


0834-19 2024/06/03 6.67UT FUJI -KISO




T20240603154319




BLK:21,SNR1: 9.0359 ,SNR2: 22.625




F20240603154321





BLK:21,SNR1: 8.1606 ,SNR2: 20.522




0839-071 2024/06/03 6.75UT TOYOKAWA-FUJI




T20240603154319




BLK:21,SNR1: 9.0308 ,SNR2: 22.612




K20240603154316





BLK:21,SNR1: 15.487 ,SNR2: 27.347




0839-071 2024/06/03 6.75UT TOYOKAWA-KISO



F20240603154321





BLK:18,SNR1: 8.1394 ,SNR2: 20.469




Frequency (Hz)

K20240603154316




BLK:18,SNR1: 8.8645 ,SNR2: 22.196





Frequency (Hz)


0839-071 2024/06/03 6.75UT FUJI -KISO




T20240603155420




BLK:25,SNR1: 7.7670 ,SNR2: 19.565




F20240603155422



BLK:25,SNR1: 6.6845 ,SNR2: 16.917





3C208 2024/06/03 6.93UT TOYOKAWA-FUJI






T20240603155420




BLK:34,SNR1: 7.7826 ,SNR2: 19.602





3C208 2024/06/03 6.93UT TOYOKAWA-KISO



K20240603155417




BLK:34,SNR1: 7.2652 ,SNR2: 21.140



F20240603155422





BLK:28,SNR1: 6.6066 ,SNR2: 16.727




Frequency (Hz)

K20240603155417




BLK:28,SNR1: 7.2682 ,SNR2: 21.150





Frequency (Hz)


3C208 2024/06/03 6.93UT FUJI -KISO



T20240603161101





BLK:10,SNR1: 0.11641 ,SNR2: 0.64553




Frequency (Hz)

F20240603161103




BLK:10,SNR1: 9.4296 ,SNR2: 16.248





Frequency (Hz)


3C216 2024/06/03 7.21UT TOYOKAWA-FUJI



T20240603161101





BLK: 1,SNR1: 0.16887 ,SNR2: 1.4490




Frequency (Hz)

K20240603161058




BLK: 1,SNR1: 0.50867 ,SNR2: 1.1875





Frequency (Hz)


3C216 2024/06/03 7.21UT TOYOKAWA-KISO



F20240603161103




BLK: 6,SNR1: 3.2974 ,SNR2: 5.2835




Frequency (Hz)

K20240603161058




BLK: 6,SNR1: 0.13711 ,SNR2: 0.42118





Frequency (Hz)


3C216 2024/06/03 7.21UT FUJI -KISO



T20240603162313




BLK: 7,SNR1: 0.14388 ,SNR2: 1.6301




Frequency (Hz)

0919-142 2024/06/03 7.42UT TOYOKAWA-FUJI


F20240603162315





BLK: 7,SNR1: 1.8899 ,SNR2: 3.8395




Frequency (Hz)



T20240603162313





BLK: 9,SNR1: 0.19202 ,SNR2: 1.1612




Frequency (Hz)

K20240603162310





BLK: 9,SNR1: 0.31015 ,SNR2: 3.0418





Frequency (Hz)

0919-142 2024/06/03 7.42UT TOYOKAWA-KISO







BLK: 5, SNR1: 1.1462 , SNR2: 4.5216



BLK: 5, SNR1: 0.35414 , SNR2: 3.6139





0919-142 2024/06/03 7.42UT FUJI -KISO






T20240603162952





BLK:24,SNR1: 4.1607 ,SNR2: 12.545




Frequency (Hz)

F20240603162954




BLK:24,SNR1: 2.8801 ,SNR2: 7.2503





Frequency (Hz)


0926+117 2024/06/03 7.53UT TOYOKAWA-FUJI





T20240603162952




BLK:10,SNR1: 9.0662 ,SNR2: 27.232




K20240603162949





BLK:10,SNR1: 6.9426 ,SNR2: 19.612




0926+117 2024/06/03 7.53UT TOYOKAWA-KISO



F20240603162954





BLK:22,SNR1: 3.6006 ,SNR2: 6.5622




Frequency (Hz)

K20240603162949




BLK:22,SNR1: 6.3361 ,SNR2: 14.651





Frequency (Hz)


0926+117 2024/06/03 7.53UT FUJI -KISO



T20240603163737





BLK:16,SNR1: 0.34716 ,SNR2: 1.8397




Frequency (Hz)

F20240603163739




BLK:16,SNR1: 1.4527 ,SNR2: 4.2824




Frequency (Hz)


3C222 2024/06/03 7.66UT TOYOKAWA-FUJI



T20240603163737





BLK:15,SNR1: 0.55415 ,SNR2: 4.1846




Frequency (Hz)

K20240603163734




BLK:15,SNR1: 1.1523 ,SNR2: 2.3584





Frequency (Hz)


3C222 2024/06/03 7.66UT TOYOKAWA-KISO



F20240603163739





BLK:20,SNR1: 1.4533 ,SNR2: 4.2844




Frequency (Hz)

K20240603163734




BLK:20,SNR1: 5.7991 ,SNR2: 13.666





Frequency (Hz)


3C222 2024/06/03 7.66UT FUJI -KISO



T20240603165259





BLK:10,SNR1: 0.16574 ,SNR2: 0.92801




Frequency (Hz)

F20240603165301




BLK:10,SNR1: 12.012 ,SNR2: 17.973





Frequency (Hz)


3C230 2024/06/03 7.91UT TOYOKAWA-FUJI



T20240603165259





BLK:21,SNR1: 0.20532 ,SNR2: 1.6678




Frequency (Hz)

K20240603165256




BLK:21,SNR1: 1.2916 ,SNR2: 5.1924





Frequency (Hz)

3C230 2024/06/03 7.91UT TOYOKAWA-KISO






F20240603165301





BLK:22,SNR1: 12.030 ,SNR2: 18.006




Frequency (Hz)

K20240603165256




BLK:22,SNR1: 1.1007 ,SNR2: 4.5014





Frequency (Hz)


3C230 2024/06/03 7.91UT FUJI -KISO



T20240603170859





BLK: 6,SNR1: 0.44312 ,SNR2: 5.5161




Frequency (Hz)

F20240603170901




BLK: 6,SNR1:-0.56064E-01,SNR2: 0.48133





Frequency (Hz)


3C237 2024/06/03 8.18UT TOYOKAWA-FUJI



T20240603170859





BLK:10,SNR1: 0.21529 ,SNR2: 1.4454




Frequency (Hz)

K20240603170856




BLK:10,SNR1: 0.54907 ,SNR2: 2.3309





Frequency (Hz)


3C237 2024/06/03 8.18UT TOYOKAWA-KISO



F20240603170901





BLK: 3,SNR1: 0.24817 ,SNR2: 1.8984




Frequency (Hz)

K20240603170856




BLK: 3,SNR1: 0.37999 ,SNR2: 2.9418





Frequency (Hz)


3C237 2024/06/03 8.18UT FUJI -KISO



T20240603171515





BLK: 5,SNR1: 0.15776E-01,SNR2: 0.96269




Frequency (Hz)

F20240603171517




BLK: 5,SNR1: 2.4080 ,SNR2: 8.0494





Frequency (Hz)


1011+110 2024/06/03 8.28UT TOYOKAWA-FUJI



T20240603171515





BLK: 6,SNR1: 0.18809 ,SNR2: 2.4328




Frequency (Hz)

K20240603171513




BLK: 6,SNR1: 1.2821 ,SNR2: 5.2345




Frequency (Hz)


1011+110 2024/06/03 8.28UT TOYOKAWA-KISO



F20240603171517





BLK:13,SNR1: 2.3341 ,SNR2: 5.7295




Frequency (Hz)

K20240603171513




BLK:13,SNR1: 1.0993 ,SNR2: 4.5970





Frequency (Hz)


1011+110 2024/06/03 8.28UT FWJ -KISO



T20240603172256




BLK: 8,SNR1: 0.50534 ,SNR2: 2.1539




Frequency (Hz)

F20240603172258




BLK: 8,SNR1: 1.2030 ,SNR2: 9.3482





Frequency (Hz)

3C241 2024/06/03 8.41UT TOYOKAWA-FUJI






T20240603172256





BLK:13,SNR1: 0.22431 ,SNR2: 1.9190




Frequency (Hz)

K20240603172254




BLK:13,SNR1: 9.7100 ,SNR2: 21.862




Frequency (Hz)


3C241 2024/06/03 8.41UT TOYOKAWA-KISO



F20240603172258





BLK:21,SNR1: 2.3027 ,SNR2: 6.4966




Frequency (Hz)

K20240603172254




BLK:21,SNR1: 8.9394 ,SNR2: 20.120





Frequency (Hz)


3C241 2024/06/03 8.41UT FUJI -KISO



T20240603173816




BLK: 2,SNR1: 0.20724 ,SNR2: 0.76837




Frequency (Hz)

F20240603173818




BLK: 2,SNR1: 0.27619 ,SNR2: 1.6683





Frequency (Hz)


1034+404 2024/06/03 8.67UT TOYOKAWA-FUJI



T20240603173816





BLK: 4,SNR1: 0.88188E-01,SNR2: 0.79002




Frequency (Hz)

K20240603173813




BLK: 4,SNR1: 0.51866 ,SNR2: 4.0302




Frequency (Hz)


1034+404 2024/06/03 8.67UT TOYOKAWA-KISO



F20240603173818





BLK: 7,SNR1: 0.42194 ,SNR2: 1.0149




Frequency (Hz)

K20240603173813



BLK: 7,SNR1: 0.39047 ,SNR2: 2.6401



Frequency (Hz)

1034+404 2024/06/03 8.67UT FUJI -KISO

