




T20240610053231





BLK:27,SNR1: 8.6995 ,SNR2: 16.234




Frequency (Hz)

F20240610053233




BLK:27,SNR1: 7.7819 ,SNR2: 20.147





Frequency (Hz)


2255+416 2024/06/09 20.57UT TOYOKAWA-FUJI



T20240610053231





BLK:30,SNR1: 8.7033 ,SNR2: 16.241




Frequency (Hz)

K20240610053228




BLK:30,SNR1: 8.7771 ,SNR2: 21.977





Frequency (Hz)


2255+416 2024/06/09 20.57UT TOYOKAWA-KISO



F20240610053233





BLK:31,SNR1: 7.7825 ,SNR2: 20.148




Frequency (Hz)

K20240610053228








BLK:31,SNR1: 8.5378 ,SNR2: 21.605




Frequency (Hz)





2255+416 2024/06/09 20.57UT FUJI -KISO






2259+481 2024/06/09 20.64UT TOYOKAWA-FUJI







2259+481 2024/06/09 20.64UT TOYOKAWA-KISO




F20240610053655




BLK:12,SNR1: 0.59293 ,SNR2: 2.6361




K20240610053650





BLK:12,SNR1: 0.96217 ,SNR2: 4.5806




2259+481 2024/06/09 20.64UT FUJI -KISO



T20240610054855




BLK: 7,SNR1:-0.16668E-01,SNR2: 2.3969




Frequency (Hz)

F20240610054857




BLK: 7,SNR1: 0.96228 ,SNR2: 2.9054





Frequency (Hz)


2311+469 2024/06/09 20.84UT TOYOKAWA-FUJI



T20240610054855





BLK: 2,SNR1: 0.10364 ,SNR2: 5.3428




Frequency (Hz)

K20240610054853




BLK: 2,SNR1: 0.82194E-02,SNR2: 0.23304









Frequency (Hz)


2311+469 2024/06/09 20.84UT TOYOKAWA-KISO










2311+469 2024/06/09 20.84UT FUJI -KISO



T20240610060307





BLK: 3,SNR1: 0.35424E-01,SNR2: 0.32797




Frequency (Hz)

F20240610060309




BLK: 3,SNR1: 0.10567 ,SNR2: 1.8979




Frequency (Hz)


2325+269 2024/06/09 21.08UT TOYOKAWA-FUJI



T20240610060307



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


2325+269 2024/06/09 21.08UT TOYOKAWA-KISO




F20240610060309




No.Good Data




KISO





No.Good Data




2325+269 2024/06/09 21.08UT FUJI -KISO



T20240610063225





BLK: 8,SNR1: 0.43416 ,SNR2: 3.7952




Frequency (Hz)

2354+14 2024/06/09 21.57UT TOYOKAWA-FUJI


F20240610063227





BLK: 8,SNR1: 0.57852 ,SNR2: 2.3579






Frequency (Hz)







BLK:14,SNR1: 0.31302 ,SNR2: 2.1101





BLK:14,SNR1: 1.0702 ,SNR2: 3.6743




2354+14 2024/06/09 21.57UT TOYOKAWA-KISO



F20240610063227





BLK: 6,SNR1: 0.69210 ,SNR2: 3.2357




Frequency (Hz)

K20240610063222




BLK: 6,SNR1: 1.9411 ,SNR2: 6.6941





Frequency (Hz)


2354+14 2024/06/09 21.57UT FUJI -KISO



T20240610064128



BLK:11,SNR1: 0.10373 ,SNR2: 1.4100





Frequency (Hz)


3C2

2024/06/09 21.72UT TOYOKAWA-FUJI


F20240610064130



BLK:11,SNR1: 0.98029 ,SNR2: 3.6570





Frequency (Hz)






T20240610064128



BLK:16,SNR1: 2.9736 ,SNR2: 13.148





Frequency (Hz)


3C2

2024/06/09 21.72UT TOYOKAWA-KISO


K20240610064125





BLK:16,SNR1: 1.4513 ,SNR2: 2.9082




Frequency (Hz)



F20240610064130



BLK:12,SNR1: 0.86982 ,SNR2: 2.6691





Frequency (Hz)


3C2

2024/06/09 21.72UT FUJI -KISO


K20240610064125





BLK:12,SNR1: 0.71416 ,SNR2: 3.0708




Frequency (Hz)



T20240610064850





BLK: 3,SNR1:-0.71276E-01,SNR2: 0.52739




Frequency (Hz)

F20240610064852




BLK: 3,SNR1: 0.80149E-01,SNR2: 1.5463




Frequency (Hz)


0011+344 2024/06/09 21.84UT TOYOKAWA-FUJI





T20240610064850




No.Good Data




K20240610064847





No.Good Data




0011+344 2024/06/09 21.84UT TOYOKAWA-KISO



F20240610064852




BLK: 4,SNR1: 0.77770 ,SNR2: 7.8087




Frequency (Hz)

K20240610064847




BLK: 4,SNR1: 0.83294E-01,SNR2: 2.1778





Frequency (Hz)


0011+344 2024/06/09 21.84UT FUJI -KISO



T20240610065727





BLK: 5,SNR1: 0.79107E-01,SNR2: 0.80706




Frequency (Hz)

F20240610065729




BLK: 5,SNR1: 0.23724 ,SNR2: 2.4137





Frequency (Hz)


0019-00 2024/06/09 21.99UT TOYOKAWA-FUJI



T20240610065727





BLK:10,SNR1: 0.53711E-01,SNR2: 0.89404




Frequency (Hz)

K20240610065725




BLK:10,SNR1: 1.0044 ,SNR2: 2.9816





Frequency (Hz)


0019-00 2024/06/09 21.99UT TOYOKAWA-KISO



F20240610065729





BLK: 8,SNR1: 0.17180 ,SNR2: 2.5780




Frequency (Hz)

K20240610065725




BLK: 8,SNR1: 1.1831 ,SNR2: 4.7680





Frequency (Hz)

0019-00 2024/06/09 21.99UT FUJI -KISO






T20240610070741





BLK: 4,SNR1: 0.43448 ,SNR2: 7.4607




Frequency (Hz)

3C12 2024/06/09 22.16UT TOYOKAWA-FUJI


F20240610070743





BLK: 4,SNR1: 0.10385 ,SNR2: 2.7193




Frequency (Hz)



T20240610070741





BLK: 2,SNR1: 0.26978 ,SNR2: 0.56994




Frequency (Hz)

3C12 2024/06/09 22.16UT TOYOKAWA-KISO


K20240610070738





BLK: 2,SNR1: 0.26387 ,SNR2: 1.1122




Frequency (Hz)



F20240610070743





No.Good Data




Frequency (Hz)

3C12 2024/06/09 22.16UT FUJI -KISO


K20240610070738





No.Good Data




Frequency (Hz)



T20240610071559




BLK: 2,SNR1:-0.61677E-01,SNR2: 0.28267




Frequency (Hz)

F20240610071601




BLK: 2,SNR1:-0.23060 ,SNR2: 0.64606





Frequency (Hz)


0038+328 2024/06/09 22.29UT TOYOKAWA-FUJI



T20240610071559




BLK: 2,SNR1: 0.20737 ,SNR2: 0.62965




Frequency (Hz)

K20240610071556




BLK: 2,SNR1:-0.57177E-01,SNR2: 0.26054





Frequency (Hz)


0038+328 2024/06/09 22.29UT TOYOKAWA-KISO



F20240610071601





BLK: 6,SNR1: 0.76498 ,SNR2: 2.5791




Frequency (Hz)

K20240610071556




BLK: 6,SNR1: 0.46458E-01,SNR2: 2.0132





Frequency (Hz)


0038+328 2024/06/09 22.29UT FUJI -KISO



T20240610072904




BLK: 2,SNR1: 0.73567E-02,SNR2: 1.3431





3C26 2024/06/09 22.51UT TOYOKAWA-FUJI



F20240610072906




BLK: 2,SNR1: 1.5333 ,SNR2: 12.814



T20240610072904



BLK: 3,SNR1: 0.19973 ,SNR2: 0.73612





Frequency (Hz)


3C26

2024/06/09 22.51UT TOYOKAWA-KISO


K20240610072901



BLK: 3,SNR1: 0.33274 ,SNR2: 3.6053





Frequency (Hz)






F20240610072906





BLK: 2,SNR1: 1.8771 ,SNR2: 17.136




Frequency (Hz)

3C26 2024/06/09 22.51UT FUJI -KISO


K20240610072901





BLK: 2,SNR1: 0.42571 ,SNR2: 1.6330




Frequency (Hz)



T20240610073403




BLK: 5,SNR1: 0.21536 ,SNR2: 1.5048




Frequency (Hz)

F20240610073405




BLK: 5,SNR1: 1.7565 ,SNR2: 5.1891




Frequency (Hz)


0056-00 2024/06/09 22.60UT TOYOKAWA-FUJI



T20240610073403





BLK: 3,SNR1: 0.51240E-01,SNR2: 1.0796





0056-00 2024/06/09 22.60UT TOYOKAWA-KISO



K20240610073400




BLK: 3,SNR1: 0.11226 ,SNR2: 3.0358



F20240610073405





BLK: 5,SNR1:-0.14133 ,SNR2: 1.7817




Frequency (Hz)

K20240610073400




BLK: 5,SNR1: 0.43512 ,SNR2: 1.9072





Frequency (Hz)


0056-00 2024/06/09 22.60UT FUJI -KISO



T20240610074345




BLK: 3,SNR1: 0.16421 ,SNR2: 0.66963




Frequency (Hz)

F20240610074347




BLK: 3,SNR1: 2.1815 ,SNR2: 8.8396




Frequency (Hz)


0106+01 2024/06/09 22.76UT TOYOKAWA-FUJI




T20240610074345




BLK: 7,SNR1: 0.12276 ,SNR2: 1.4694




K20240610074342





BLK: 7,SNR1: 0.35900 ,SNR2: 3.2926




0106+01 2024/06/09 22.76UT TOYOKAWA-KISO



F20240610074347





BLK: 4,SNR1:-0.10893 ,SNR2: 0.50740




Frequency (Hz)

K20240610074342




BLK: 4,SNR1: 0.36749E-01,SNR2: 0.83041




Frequency (Hz)


0106+01 2024/06/09 22.76UT FUJI -KISO



T20240610075308




BLK: 5,SNR1: 0.80053E-01,SNR2: 0.57150





0115-01 2024/06/09 22.91UT TOYOKAWA-FUJI

F20240610075310




BLK: 5,SNR1: 5.7504 ,SNR2: 21.774






T20240610075308




BLK: 4,SNR1: 0.77373E-01,SNR2: 1.1306





0115-01 2024/06/09 22.91UT TOYOKAWA-KISO



K20240610075305




BLK: 4,SNR1: 0.45162 ,SNR2: 6.4660



F20240610075310





BLK: 6,SNR1: 1.3996 ,SNR2: 8.4010




Frequency (Hz)

K20240610075305




BLK: 6,SNR1: 0.69649E-01,SNR2: 0.50544




Frequency (Hz)


0115-01 2024/06/09 22.91UT FUJI -KISO




T20240610080607




BLK: 6,SNR1: 0.21028 ,SNR2: 1.7827




F20240610080609





BLK: 6,SNR1: 0.32171 ,SNR2: 1.5569




0128+03 2024/06/09 23.13UT TOYOKAWA-FUJI



T20240610080607





BLK: 8,SNR1: 0.11829 ,SNR2: 1.6560





0128+03 2024/06/09 23.13UT TOYOKAWA-KISO



K20240610080605




BLK: 8,SNR1: 0.37490 ,SNR2: 3.8125



F20240610080609





BLK: 3,SNR1: 0.16224 ,SNR2: 4.7950




Frequency (Hz)

0128+03 2024/06/09 23.13UT FUJI -KISO


K20240610080605




BLK: 3,SNR1:-0.15411E-01,SNR2: 1.3793




Frequency (Hz)



T20240610081241



BLK:30,SNR1: 7.6445 ,SNR2: 49.852





Frequency (Hz)


3C48

2024/06/09 23.24UT TOYOKAWA-FUJI


F20240610081243




BLK:30,SNR1: 0.37506 ,SNR2: 3.1223




Frequency (Hz)



T20240610081241




BLK:33,SNR1: 7.6365 ,SNR2: 24.999




Frequency (Hz)

3C48 2024/06/09 23.24UT TOYOKAWA-KISO


K20240610081239




BLK:33,SNR1: 1.2330 ,SNR2: 3.5427




Frequency (Hz)



F20240610081243





BLK:31,SNR1: 0.34827 ,SNR2: 5.1345




Frequency (Hz)

3C48 2024/06/09 23.24UT FUJI -KISO


K20240610081239



BLK:31,SNR1: 1.3466 ,SNR2: 8.3731





Frequency (Hz)






T20240610083226





BLK: 4,SNR1: 1.1281 ,SNR2: 5.1965





0155-109 2024/06/09 23.57UT TOYOKAWA-FUJI



F20240610083228




BLK: 4,SNR1: 0.10350 ,SNR2: 3.7427



T20240610083226





BLK:10,SNR1: 1.9232 ,SNR2: 20.675





0155-109 2024/06/09 23.57UT TOYOKAWA-KISO


K20240610083223




BLK:10,SNR1: 0.30290 ,SNR2: 2.4802



F20240610083228





BLK: 3,SNR1: 0.23211 ,SNR2: 2.7444




Frequency (Hz)

K20240610083223




BLK: 3,SNR1: 0.86208E-01,SNR2: 1.2990




Frequency (Hz)


0155-109 2024/06/09 23.57UT FUJI -KISO



T20240610083933




BLK:10,SNR1: 0.47643 ,SNR2: 5.3770





0202+15 2024/06/09 23.69UT TOYOKAWA-FUJI


F20240610083935




BLK:10,SNR1: 0.15618E-01,SNR2: 1.3814



T20240610083933





BLK:15,SNR1: 0.38872 ,SNR2: 3.1382





0202+15 2024/06/09 23.69UT TOYOKAWA-KISO


K20240610083930




BLK:15,SNR1: 0.49920 ,SNR2: 1.7555




F20240610083935




BLK: 2,SNR1: 0.45581 ,SNR2: 2.4860




K20240610083930




BLK: 2,SNR1: 0.58703E-01,SNR2: 0.24867




0202+15 2024/06/09 23.69UT FUJI -KISO



T20240610085123




BLK: 4,SNR1:-0.14213 ,SNR2: 0.64490





0213+178 2024/06/09 23.88UT TOYOKAWA-FUJI



F20240610085125




BLK: 4,SNR1: 0.88879 ,SNR2: 7.2696





T20240610085123




BLK: 8,SNR1: 0.16144 ,SNR2: 0.75893




K20240610085120



BLK: 8,SNR1: 0.98052 ,SNR2: 4.4972





0213+178 2024/06/09 23.88UT TOYOKAWA-KISO








F20240610085125




BLK:10,SNR1: 0.10819 ,SNR2: 1.3098




K20240610085120





BLK:10,SNR1: 0.89365 ,SNR2: 3.6012




0213+178 2024/06/09 23.88UT FUJI -KISO



T20240610091720





BLK:13,SNR1: 3.9457 ,SNR2: 16.578





3C71 2024/06/10 0.32UT TOYOKAWA-FUJI


F20240610091722




BLK:13,SNR1: 3.8642 ,SNR2: 16.280



T20240610091720





BLK:13,SNR1: 3.9454 ,SNR2: 16.580





3C71 2024/06/10 0.32UT TOYOKAWA-KISO



K20240610091717




BLK:13,SNR1: 12.677 ,SNR2: 24.004



F20240610091722





BLK:22,SNR1: 3.8443 ,SNR2: 16.200




Frequency (Hz)

3C71 2024/06/10 0.32UT FUJI -KISO


K20240610091717





BLK:22,SNR1: 3.8525 ,SNR2: 10.016




Frequency (Hz)





T20240610093635




BLK: 6,SNR1: 0.12958 ,SNR2: 0.65929




F20240610093637





BLK: 6,SNR1: 0.13140 ,SNR2: 1.5311




0258+350 2024/06/10 0.64UT TOYOKAWA-FUJI





T20240610093635




BLK: 4,SNR1: 0.34955E-02,SNR2: 1.2482




K20240610093632




BLK: 4,SNR1: 0.10253 ,SNR2: 0.62645




0258+350 2024/06/10 0.64UT TOYOKAWA-KISO





F20240610093637




BLK: 9,SNR1: 0.78226 ,SNR2: 6.1555




K20240610093632





BLK: 9,SNR1: 0.51663 ,SNR2: 2.6750




0258+350 2024/06/10 0.64UT FUJI -KISO





T20240610094624




BLK: 6,SNR1:-0.42003E-01,SNR2: 0.67949




F20240610094626



BLK: 6,SNR1: 13.746 ,SNR2: 26.224





0308+305 2024/06/10 0.80UT TOYOKAWA-FUJI








T20240610094624




BLK:10,SNR1: 0.12590 ,SNR2: 0.69190




K20240610094621




BLK:10,SNR1: 0.93829E-01,SNR2: 1.3757




0308+305 2024/06/10 0.80UT TOYOKAWA-KISO



F20240610094626





BLK:13,SNR1: 5.7641 ,SNR2: 11.058





0308+305 2024/06/10 0.80UT FUJI -KISO



K20240610094621




BLK:13,SNR1: 0.11887 ,SNR2: 0.68515



T20240610095444





BLK: 9,SNR1: 0.15985 ,SNR2: 3.3044




Frequency (Hz)

3C84 2024/06/10 0.94UT TOYOKAWA-FUJI


F20240610095446





BLK: 9,SNR1:-0.20073 ,SNR2: 1.7329




Frequency (Hz)



T20240610095444





BLK:18,SNR1: 0.25993 ,SNR2: 1.3043





3C84 2024/06/10 0.94UT TOYOKAWA-KISO



K20240610095441




BLK:18,SNR1: 0.21408 ,SNR2: 1.2629



F20240610095446





BLK: 2,SNR1:-0.82410E-01,SNR2: 3.9395





3C84 2024/06/10 0.94UT FUJI -KISO



K20240610095441




BLK: 2,SNR1: 0.47117 ,SNR2: 5.0471



T20240610100201





BLK: 2,SNR1: 0.88468E-01,SNR2: 1.2447





0324+119 2024/06/10 1.06UT TOYOKAWA-FUJI


F20240610100203




BLK: 2,SNR1: 0.66888E-01,SNR2: 4.7807



T20240610100201





BLK: 2,SNR1:-0.23790E-01,SNR2: 0.92553




Frequency (Hz)

0324+119 2024/06/10 1.06UT TOYOKAWA-KISO


K20240610100158




BLK: 2,SNR1: 1.2306 ,SNR2: 5.0732




Frequency (Hz)




F20240610100203




BLK: 3,SNR1: 0.21446 ,SNR2: 2.2104




K20240610100158



BLK: 3,SNR1:-0.12253E-01,SNR2: 0.36364





0324+119 2024/06/10 1.06UT FUJI -KISO






T20240610101117





BLK: 6,SNR1: 0.12088 ,SNR2: 0.92816





0333+32 2024/06/10 1.22UT TOYOKAWA-FUJI



F20240610101119




BLK: 6,SNR1: 0.49192 ,SNR2: 1.8417



T20240610101117





BLK:10,SNR1: 0.15085 ,SNR2: 1.2124




0333+32 2024/06/10 1.22UT TOYOKAWA-KISO


K20240610101114




BLK:10,SNR1: 1.3517 ,SNR2: 6.1774




Frequency (Hz)




F20240610101119




BLK: 9,SNR1: 0.53957 ,SNR2: 1.7280




K20240610101114





BLK: 9,SNR1: 0.68094 ,SNR2: 3.0549




0333+32 2024/06/10 1.22UT FUJI -KISO



T20240610102419





BLK: 5,SNR1: 0.52077E-01,SNR2: 0.75105




0347+05 2024/06/10 1.43UT TOYOKAWA-FUJI


F20240610102421





BLK: 5,SNR1: 14.329 ,SNR2: 36.016




Frequency (Hz)



T20240610102419





BLK: 2,SNR1: 0.17332 ,SNR2: 2.2665




0347+05 2024/06/10 1.43UT TOYOKAWA-KISO


K20240610102416




BLK: 2,SNR1: 1.6496 ,SNR2: 6.5138




Frequency (Hz)



F20240610102421




BLK: 5,SNR1: 0.49183E-01,SNR2: 1.1087





0347+05 2024/06/10 1.43UT FUJI -KISO


K20240610102416




BLK: 5,SNR1: 0.38057 ,SNR2: 2.0517



T20240610103954




BLK:11,SNR1: 1.7191 ,SNR2: 6.8354





0403-132 2024/06/10 1.69UT TOYOKAWA-FUJI


F20240610103956




BLK:11,SNR1:-0.30411 ,SNR2: 0.54027





T20240610103954




BLK:24,SNR1: 1.0594 ,SNR2: 10.114




K20240610103951



BLK:24,SNR1: 0.69320 ,SNR2: 2.7708




0403-132 2024/06/10 1.69UT TOYOKAWA-KISO








F20240610103956




BLK:10,SNR1:-0.27779 ,SNR2: 0.82616




K20240610103951




BLK:10,SNR1: 0.58116 ,SNR2: 2.5719




0403-132 2024/06/10 1.69UT FUJI -KISO



T20240610104904




BLK: 6,SNR1: 0.48268 ,SNR2: 3.2578





0411+05 2024/06/10 1.85UT TOYOKAWA-FUJI


F20240610104906




BLK: 6,SNR1: 0.64692 ,SNR2: 2.1329



T20240610104904




BLK: 9,SNR1: 11.874 ,SNR2: 35.834





0411+05 2024/06/10 1.85UT TOYOKAWA-KISO



K20240610104901




BLK: 9,SNR1: 0.29101 ,SNR2: 0.96678





F20240610104906




BLK: 6,SNR1: 0.59292 ,SNR2: 3.6706




K20240610104901





BLK: 6,SNR1: 0.78310 ,SNR2: 2.6526




0411+05 2024/06/10 1.85UT FUJI -KISO



T20240610105558





BLK:27,SNR1: 4.6328 ,SNR2: 24.101




Frequency (Hz)

F20240610105600




BLK:27,SNR1: 5.0048 ,SNR2: 12.165





Frequency (Hz)


0418+236 2024/06/10 1.96UT TOYOKAWA-FUJI





T20240610105558




BLK:38,SNR1: 4.6839 ,SNR2: 23.845




K20240610105555




BLK:38,SNR1: 11.521 ,SNR2: 19.016




0418+236 2024/06/10 1.96UT TOYOKAWA-KISO




F20240610105600




BLK:27,SNR1: 7.1801 ,SNR2: 17.429




K20240610105555





BLK:27,SNR1: 11.177 ,SNR2: 18.754




0418+236 2024/06/10 1.96UT FUJI -KISO



T20240610110725




BLK:20,SNR1: 3.8939 ,SNR2: 34.161





3C119 2024/06/10 2.15UT TOYOKAWA-FUJI

F20240610110727





BLK:20,SNR1: 0.87979 ,SNR2: 4.5720








T20240610110725




BLK:31,SNR1: 4.0917 ,SNR2: 29.431




K20240610110722





BLK:31,SNR1: 0.59174 ,SNR2: 4.2971




3C119 2024/06/10 2.15UT TOYOKAWA-KISO



F20240610110727




BLK:25,SNR1: 0.46556 ,SNR2: 2.8943




Frequency (Hz)

K20240610110722




BLK:25,SNR1: 0.79249 ,SNR2: 2.7075




Frequency (Hz)


3C119 2024/06/10 2.15UT FUJI -KISO




T20240610115533




BLK:19,SNR1: 5.9539 ,SNR2: 17.429




F20240610115535




BLK:19,SNR1: 0.33696 ,SNR2: 2.5867




3C138 2024/06/10 2.95UT TOYOKAWA-FUJI



T20240610115533




BLK:29,SNR1: 5.0013 ,SNR2: 16.499





3C138 2024/06/10 2.95UT TOYOKAWA-KISO


K20240610115530




BLK:29,SNR1: 1.7809 ,SNR2: 6.8682



F20240610115535





BLK:22,SNR1: 0.35494 ,SNR2: 2.5291




Frequency (Hz)

3C138 2024/06/10 2.95UT FUJI -KISO


K20240610115530




BLK:22,SNR1: 2.1843 ,SNR2: 9.1051




Frequency (Hz)




T20240610120906




BLK:17,SNR1: 1.1569 ,SNR2: 3.2145




F20240610120908




BLK:17,SNR1: 0.48491E-01,SNR2: 2.2105




0531+194 2024/06/10 3.18UT TOYOKAWA-FUJI





T20240610120906




BLK:20,SNR1: 1.2526 ,SNR2: 7.6023




K20240610120903




BLK:20,SNR1: 0.82269 ,SNR2: 4.3210




0531+194 2024/06/10 3.18UT TOYOKAWA-KISO




F20240610120908




BLK:15,SNR1: 0.94028E-01,SNR2: 1.9720




K20240610120903



BLK:15,SNR1: 1.1511 ,SNR2: 4.4601




0531+194 2024/06/10 3.18UT FUJI -KISO







T20240610121725




BLK:30,SNR1: 28.077 ,SNR2: 72.159




F20240610121727




BLK:30,SNR1: 1.3649 ,SNR2: 3.4171




3C147 2024/06/10 3.32UT TOYOKAWA-FUJI




T20240610121725




BLK:36,SNR1: 26.168 ,SNR2: 67.248




K20240610121723





BLK:36,SNR1: 4.1032 ,SNR2: 15.012




3C147 2024/06/10 3.32UT TOYOKAWA-KISO



F20240610121727





BLK:34,SNR1: 1.2448 ,SNR2: 4.4748





3C147 2024/06/10 3.32UT FUJI -KISO


K20240610121723




BLK:34,SNR1: 4.0656 ,SNR2: 14.904



T20240610122537




BLK:21,SNR1: 3.0256 ,SNR2: 13.705





0548+16 2024/06/10 3.46UT TOYOKAWA-FUJI


F20240610122539




BLK:21,SNR1: 2.0261 ,SNR2: 7.6207



T20240610122537




BLK:22,SNR1: 3.0196 ,SNR2: 13.678





0548+16 2024/06/10 3.46UT TOYOKAWA-KISO



K20240610122534




BLK:22,SNR1: 1.8824 ,SNR2: 7.2084





F20240610122539




BLK:21,SNR1: 3.7986 ,SNR2: 9.5837




K20240610122534





BLK:21,SNR1: 1.9977 ,SNR2: 7.8405




0548+16 2024/06/10 3.46UT FUJI -KISO



T20240610122948




BLK:19,SNR1: 2.8248 ,SNR2: 13.415




0552+12 2024/06/10 3.52UT TOYOKAWA-FUJI


F20240610122950





BLK:19,SNR1: 8.6363 ,SNR2: 15.337




Frequency (Hz)



T20240610122948





BLK:26,SNR1: 2.8365 ,SNR2: 13.450





0552+12 2024/06/10 3.52UT TOYOKAWA-KISO

K20240610122945




BLK:26,SNR1: 71.738 ,SNR2: 72.099








F20240610122950




BLK:23,SNR1: 7.1565 ,SNR2: 17.587




K20240610122945




BLK:23,SNR1: 29.109 ,SNR2: 52.587




0552+12 2024/06/10 3.52UT FUJI -KISO




T20240610123415




BLK:20,SNR1: 0.40074 ,SNR2: 1.7886




F20240610123417





BLK:20,SNR1: 1.8560 ,SNR2: 9.0230




0556+191 2024/06/10 3.60UT TOYOKAWA-FUJI



T20240610123415





BLK:19,SNR1: 0.47636 ,SNR2: 4.2680





0556+191 2024/06/10 3.60UT TOYOKAWA-KISO



K20240610123412




BLK:19,SNR1: 0.57101 ,SNR2: 2.5090



F20240610123417





BLK:20,SNR1: 1.2250 ,SNR2: 7.8892




Frequency (Hz)

K20240610123412




BLK:20,SNR1: 0.23775 ,SNR2: 1.4185





Frequency (Hz)


0556+191 2024/06/10 3.60UT FUJI -KISO



T20240610124201




BLK:11,SNR1: 0.62336 ,SNR2: 2.4596




Frequency (Hz)

F20240610124203




BLK:11,SNR1: 0.34754 ,SNR2: 3.3389





Frequency (Hz)


0605-08 2024/06/10 3.73UT TOYOKAWA-FUJI





T20240610124201




BLK: 8,SNR1: 0.43308 ,SNR2: 4.8071




K20240610124158





BLK: 8,SNR1: 1.7016 ,SNR2: 5.7637




0605-08 2024/06/10 3.73UT TOYOKAWA-KISO



F20240610124203





BLK:13,SNR1: 0.88473 ,SNR2: 3.2219




Frequency (Hz)

K20240610124158








BLK:13,SNR1: 1.9036 ,SNR2: 3.7930




Frequency (Hz)

0605-08 2024/06/10 3.73UT FUJI -KISO







3C161 2024/06/10 4.05UT TOYOKAWA-FUJI






T20240610130109





BLK:30,SNR1: 5.2587 ,SNR2: 9.9114






3C161 2024/06/10 4.05UT TOYOKAWA-KISO

K20240610130106





BLK:30,SNR1: 2.9404 ,SNR2: 13.911







BLK:37,SNR1: 11.677 ,SNR2: 20.725





BLK:37,SNR1: 2.7795 ,SNR2: 13.271




3C161 2024/06/10 4.05UT FUJI -KISO





T20240610132842




BLK:11,SNR1: 0.42051 ,SNR2: 2.1061




F20240610132844





BLK:11,SNR1: 0.61397 ,SNR2: 1.7202




0652-130 2024/06/10 4.51UT TOYOKAWA-FUJI





T20240610132842




BLK: 9,SNR1: 0.59919 ,SNR2: 4.8276




K20240610132839





BLK: 9,SNR1: 0.87433 ,SNR2: 3.9793




0652-130 2024/06/10 4.51UT TOYOKAWA-KISO





F20240610132844




BLK: 8,SNR1: 0.56212 ,SNR2: 1.8666




K20240610132839





BLK: 8,SNR1: 0.87362 ,SNR2: 3.7657




0652-130 2024/06/10 4.51UT FUJI -KISO





T20240610134018




BLK: 3,SNR1:-0.30579E-01,SNR2: 0.71067




F20240610134020





BLK: 3,SNR1: 0.11537 ,SNR2: 1.4011




0703+138 2024/06/10 4.70UT TOYOKAWA-FUJI





T20240610134018




BLK: 3,SNR1: 0.27006E-02,SNR2: 0.43991




K20240610134015





BLK: 3,SNR1: 2.8727 ,SNR2: 12.854




0703+138 2024/06/10 4.70UT TOYOKAWA-KISO





F20240610134020




BLK: 5,SNR1: 0.21911 ,SNR2: 0.91242




K20240610134015



BLK: 5,SNR1: 0.20491 ,SNR2: 1.8042





0703+138 2024/06/10 4.70UT FUJI -KISO







T20240610134941




BLK: 6,SNR1: 0.20020 ,SNR2: 0.56547




F20240610134943





BLK: 6,SNR1: 1.1104 ,SNR2: 8.4414




0713-024 2024/06/10 4.86UT TOYOKAWA-FUJI





T20240610134941




BLK: 8,SNR1: 0.30371 ,SNR2: 1.3015




K20240610134938





BLK: 8,SNR1: 4.4466 ,SNR2: 11.480




0713-024 2024/06/10 4.86UT TOYOKAWA-KISO





F20240610134943




BLK: 7,SNR1: 1.2161 ,SNR2: 8.9992




K20240610134938





BLK: 7,SNR1: 2.5277 ,SNR2: 6.6402




0713-024 2024/06/10 4.86UT FUJI -KISO





T20240610135952




BLK:17,SNR1: 2.0229 ,SNR2: 9.6767




F20240610135954





BLK:17,SNR1: 2.9884 ,SNR2: 5.3963




0723+10 2024/06/10 5.03UT TOYOKAWA-FUJI



T20240610135952





BLK:12,SNR1: 2.1850 ,SNR2: 10.278




Frequency (Hz)

K20240610135949




BLK:12,SNR1: 7.5166 ,SNR2: 21.511





Frequency (Hz)


0723+10 2024/06/10 5.03UT TOYOKAWA-KISO





F20240610135954




BLK:19,SNR1: 7.2674 ,SNR2: 20.958




K20240610135949





BLK:19,SNR1: 7.3825 ,SNR2: 21.126




0723+10 2024/06/10 5.03UT FUJI -KISO




T20240610141007




BLK:17,SNR1: 0.79130 ,SNR2: 2.8903




F20240610141009





BLK:17,SNR1: 3.3519 ,SNR2: 8.2381




0732+33 2024/06/10 5.20UT TOYOKAWA-FUJI




T20240610141007




BLK:26,SNR1: 0.69594 ,SNR2: 2.4182




K20240610141005



BLK:26,SNR1: 2.8139 ,SNR2: 9.9054




0732+33 2024/06/10 5.20UT TOYOKAWA-KISO







F20240610141009




BLK:24,SNR1: 2.7176 ,SNR2: 6.8519




K20240610141005





BLK:24,SNR1: 2.7217 ,SNR2: 9.8328




0732+33 2024/06/10 5.20UT FUJI -KISO



T20240610141809





BLK: 7,SNR1: 0.28479 ,SNR2: 2.8342




Frequency (Hz)

F20240610141811




BLK: 7,SNR1: 0.14434 ,SNR2: 1.0700





Frequency (Hz)


0741-06 2024/06/10 5.33UT TOYOKAWA-FUJI





T20240610141809




BLK:18,SNR1: 0.22388 ,SNR2: 1.6772




K20240610141806




BLK:18,SNR1: 0.80225 ,SNR2: 3.1187




0741-06 2024/06/10 5.33UT TOYOKAWA-KISO



F20240610141811





BLK:10,SNR1: 0.33657 ,SNR2: 2.6659




Frequency (Hz)

K20240610141806




BLK:10,SNR1: 2.0389 ,SNR2: 7.6499





Frequency (Hz)


0741-06 2024/06/10 5.33UT FUJI -KISO



T20240610142754





BLK: 6,SNR1: 0.13010 ,SNR2: 1.7869




Frequency (Hz)

F20240610142756




BLK: 6,SNR1:-0.61169E-01,SNR2: 0.95163





Frequency (Hz)


0752-200 2024/06/10 5.49UT TOYOKAWA-FUJI



T20240610142754





BLK: 4,SNR1: 0.24039 ,SNR2: 2.7570




Frequency (Hz)

K20240610142751




BLK: 4,SNR1:-0.50375E-02,SNR2: 0.44027





Frequency (Hz)


0752-200 2024/06/10 5.49UT TOYOKAWA-KISO





F20240610142756




BLK: 3,SNR1: 0.60778 ,SNR2: 1.7777




K20240610142751





BLK: 3,SNR1: 0.19374E-02,SNR2: 0.25885




0752-200 2024/06/10 5.49UT FUJI -KISO



T20240610143528





BLK: 3,SNR1: 0.32575E-01,SNR2: 1.3989




Frequency (Hz)

F20240610143530




BLK: 3,SNR1: 0.18230 ,SNR2: 3.1885





Frequency (Hz)

3C190 2024/06/10 5.62UT TOYOKAWA-FUJI








T20240610143528




BLK: 5,SNR1: 0.25185E-01,SNR2: 1.8766




K20240610143525




BLK: 5,SNR1: 0.82946 ,SNR2: 4.3094




3C190 2024/06/10 5.62UT TOYOKAWA-KISO





F20240610143530




BLK:12,SNR1: 0.62567 ,SNR2: 1.3262




K20240610143525





BLK:12,SNR1: 0.70638 ,SNR2: 2.7196




3C190 2024/06/10 5.62UT FUJI -KISO





T20240610144753




BLK: 7,SNR1: 0.91579E-01,SNR2: 0.86146




F20240610144755





BLK: 7,SNR1: 0.48191 ,SNR2: 1.2745




3C196 2024/06/10 5.83UT TOYOKAWA-FUJI



T20240610144753





BLK:11,SNR1: 0.20370 ,SNR2: 4.7797




Frequency (Hz)

K20240610144750




BLK:11,SNR1: 0.41572 ,SNR2: 1.2540





Frequency (Hz)


3C196 2024/06/10 5.83UT TOYOKAWA-KISO





F20240610144755




BLK: 2,SNR1:-0.29021E-01,SNR2: 0.97737




K20240610144750





BLK: 2,SNR1: 0.98589 ,SNR2: 3.5029




3C196 2024/06/10 5.83UT FUJI -KISO



T20240610145902





BLK: 2,SNR1: 4.5066 ,SNR2: 28.423




Frequency (Hz)

F20240610145904




BLK: 2,SNR1: 0.48476 ,SNR2: 1.8604





Frequency (Hz)


0821+394 2024/06/10 6.01UT TOYOKAWA-FUJI



T20240610145902





BLK: 6,SNR1: 1.2227 ,SNR2: 12.193




Frequency (Hz)

K20240610145859




BLK: 6,SNR1: 0.54689 ,SNR2: 2.8968





Frequency (Hz)


0821+394 2024/06/10 6.01UT TOYOKAWA-KISO



F20240610145904




BLK: 4,SNR1: 1.0461 ,SNR2: 2.6708




Frequency (Hz)

K20240610145859




BLK: 4,SNR1: 0.58486 ,SNR2: 2.9238





Frequency (Hz)

0821+394 2024/06/10 6.01UT FUJI -KISO








T20240610151043




BLK: 7,SNR1: 0.97177E-01,SNR2: 2.0290




F20240610151045





BLK: 7,SNR1: 0.26276 ,SNR2: 1.6645




0834-19 2024/06/10 6.21UT TOYOKAWA-FUJI





T20240610151043




BLK: 8,SNR1: 0.21602 ,SNR2: 2.8436




K20240610151040





BLK: 8,SNR1: 0.10436 ,SNR2: 1.3035




0834-19 2024/06/10 6.21UT TOYOKAWA-KISO





F20240610151045




BLK: 2,SNR1: 0.36573 ,SNR2: 0.88828




K20240610151040





BLK: 2,SNR1: 0.10639 ,SNR2: 0.76520




0834-19 2024/06/10 6.21UT FUJI -KISO



T20240610151548




BLK: 9,SNR1: 2.0028 ,SNR2: 7.0774




Frequency (Hz)

F20240610151550




BLK: 9,SNR1: 1.1011 ,SNR2: 2.0035





Frequency (Hz)


0839-071 2024/06/10 6.29UT TOYOKAWA-FUJI



T20240610151548





BLK: 9,SNR1: 5.2232 ,SNR2: 18.046




Frequency (Hz)

K20240610151545








BLK: 9,SNR1: 0.65463 ,SNR2: 2.8629




Frequency (Hz)

0839-071 2024/06/10 6.29UT TOYOKAWA-KISO








0839-071 2024/06/10 6.29UT FUJI -KISO





T20240610152649




BLK: 5,SNR1: 0.12314 ,SNR2: 0.80464




F20240610152651





BLK: 5,SNR1: 0.25084 ,SNR2: 3.4444




3C208 2024/06/10 6.48UT TOYOKAWA-FUJI





T20240610152649




BLK: 7,SNR1: 0.13393 ,SNR2: 0.81419




K20240610152646



BLK: 7,SNR1: 0.59042 ,SNR2: 2.6577




3C208 2024/06/10 6.48UT TOYOKAWA-KISO






F20240610152651





BLK: 6,SNR1: 0.47562 ,SNR2: 4.1236




Frequency (Hz)

K20240610152646




BLK: 6,SNR1: 0.47015 ,SNR2: 3.2367





Frequency (Hz)


3C208 2024/06/10 6.48UT FUJI -KISO



T20240610154330




BLK: 3,SNR1: 0.11857 ,SNR2: 0.59705




Frequency (Hz)

F20240610154332






BLK: 3,SNR1: 0.59428 ,SNR2: 2.3264




Frequency (Hz)

3C216 2024/06/10 6.75UT TOYOKAWA-FUJI







3C216 2024/06/10 6.75UT TOYOKAWA-KISO



F20240610154332





BLK: 6,SNR1: 0.11032 ,SNR2: 1.3465




Frequency (Hz)

K20240610154327




BLK: 6,SNR1: 1.0702 ,SNR2: 4.4824





Frequency (Hz)


3C216 2024/06/10 6.75UT FUJI -KISO





T20240610155542




BLK:10,SNR1: 1.0742 ,SNR2: 4.8070




F20240610155544





BLK:10,SNR1: 2.5448 ,SNR2: 10.958




0919-142 2024/06/10 6.96UT TOYOKAWA-FUJI





T20240610155542




BLK:11,SNR1: 0.99062 ,SNR2: 4.5657




K20240610155539





BLK:11,SNR1: 3.6114 ,SNR2: 10.626




0919-142 2024/06/10 6.96UT TOYOKAWA-KISO



F20240610155544




BLK:14,SNR1: 5.5976 ,SNR2: 10.306




Frequency (Hz)

K20240610155539




BLK:14,SNR1: 3.2594 ,SNR2: 9.5505





Frequency (Hz)


0919-142 2024/06/10 6.96UT FUJI -KISO




T20240610160221




BLK: 2,SNR1:-0.10730 ,SNR2: 1.3114




F20240610160223



BLK: 2,SNR1: 0.22351 ,SNR2: 1.6121





0926+117 2024/06/10 7.07UT TOYOKAWA-FUJI








T20240610160221




BLK: 2,SNR1:-0.54036E-01,SNR2: 0.68463




K20240610160218




BLK: 2,SNR1: 1.1197 ,SNR2: 2.4765




0926+117 2024/06/10 7.07UT TOYOKAWA-KISO



F20240610160223





BLK: 6,SNR1: 0.29033 ,SNR2: 1.0086




Frequency (Hz)

K20240610160218




BLK: 6,SNR1: 0.51313 ,SNR2: 2.1232





Frequency (Hz)


0926+117 2024/06/10 7.07UT FUJI -KISO



T20240610161005





BLK: 2,SNR1:-0.54472E-01,SNR2: 0.68833




Frequency (Hz)

F20240610161007




BLK: 2,SNR1: 0.88527E-01,SNR2: 3.7028





Frequency (Hz)


3C222 2024/06/10 7.20UT TOYOKAWA-FUJI



T20240610161005





BLK: 8,SNR1: 0.17579 ,SNR2: 1.9468




Frequency (Hz)

K20240610161002




BLK: 8,SNR1: 0.18968 ,SNR2: 1.8191




Frequency (Hz)


3C222 2024/06/10 7.20UT TOYOKAWA-KISO




F20240610161007




BLK: 1,SNR1:-0.22166 ,SNR2: 2.1029




K20240610161002





BLK: 1,SNR1:-0.11497 ,SNR2: 0.23035




3C222 2024/06/10 7.20UT FUJI -KISO



T20240610161705




BLK: 4,SNR1: 0.49453E-01,SNR2: 2.8127




Frequency (Hz)

F20240610161707




BLK: 4,SNR1: 0.34857 ,SNR2: 2.9378





Frequency (Hz)


0941-08 2024/06/10 7.31UT TOYOKAWA-FUJI





T20240610161705




BLK: 3,SNR1: 0.14565 ,SNR2: 2.6829




K20240610161702




BLK: 3,SNR1: 0.73137 ,SNR2: 2.7698




0941-08 2024/06/10 7.31UT TOYOKAWA-KISO



F20240610161707





BLK: 2, SNR1: 0.64143 , SNR2: 1.8475




Frequency (Hz)

K20240610161702




BLK: 2, SNR1: 0.20130 , SNR2: 2.0624





Frequency (Hz)

0941-08 2024/06/10 7.31UT FUJI -KISO








T20240610162527




BLK: 6,SNR1: 0.82365E-01,SNR2: 0.90313




F20240610162529





BLK: 6,SNR1: 0.61162E-01,SNR2: 1.5059




3C230 2024/06/10 7.45UT TOYOKAWA-FUJI



T20240610162527





BLK:18,SNR1: 2.5349 ,SNR2: 11.182




Frequency (Hz)

3C230 2024/06/10 7.45UT TOYOKAWA-KISO


K20240610162524




BLK:18,SNR1: 3.4624 ,SNR2: 15.049




Frequency (Hz)



F20240610162529





BLK:20,SNR1: 0.17904 ,SNR2: 2.3668




Frequency (Hz)

K20240610162524




BLK:20,SNR1: 3.2918 ,SNR2: 14.292





Frequency (Hz)


3C230 2024/06/10 7.45UT FUJI -KISO



T20240610164128





BLK: 2,SNR1: 0.15639 ,SNR2: 0.70007




Frequency (Hz)

F20240610164130




BLK: 2,SNR1: 0.16884 ,SNR2: 0.56333





Frequency (Hz)


3C237 2024/06/10 7.72UT TOYOKAWA-FUJI



T20240610164128





BLK: 5,SNR1: 3.6795 ,SNR2: 10.493




Frequency (Hz)

K20240610164125




BLK: 5,SNR1: 0.52446E-01,SNR2: 0.99226





Frequency (Hz)


3C237 2024/06/10 7.72UT TOYOKAWA-KISO



F20240610164130





BLK: 1,SNR1: 0.21523 ,SNR2: 2.0591




Frequency (Hz)

K20240610164125




BLK: 1,SNR1: 0.13436 ,SNR2: 0.0000





Frequency (Hz)


3C237 2024/06/10 7.72UT FUJI -KISO



T20240610164744





BLK:10,SNR1: 0.22077 ,SNR2: 0.89619




Frequency (Hz)

F20240610164746




BLK:10,SNR1: 0.87913 ,SNR2: 2.5012





Frequency (Hz)


1011+110 2024/06/10 7.82UT TOYOKAWA-FUJI



T20240610164744





BLK: 8,SNR1: 0.85808E-01,SNR2: 0.94261




Frequency (Hz)

K20240610164741




BLK: 8,SNR1: 2.3982 ,SNR2: 10.458





Frequency (Hz)

1011+110 2024/06/10 7.82UT TOYOKAWA-KISO






F20240610164746





BLK:20,SNR1: 0.77164 ,SNR2: 2.9787




Frequency (Hz)

K20240610164741




BLK:20,SNR1: 2.5009 ,SNR2: 10.913




Frequency (Hz)


1011+110 2024/06/10 7.82UT FUJI -KISO



T20240610165525




BLK: 2,SNR1: 0.12992 ,SNR2: 1.0146




Frequency (Hz)

F20240610165527






BLK: 2,SNR1: 0.42890 ,SNR2: 2.2134




Frequency (Hz)

3C241 2024/06/10 7.95UT TOYOKAWA-FUJI







3C241 2024/06/10 7.95UT TOYOKAWA-KISO



F20240610165527





BLK: 3,SNR1: 0.83260 ,SNR2: 3.9329




Frequency (Hz)

K20240610165522




BLK: 3,SNR1: 0.23524 ,SNR2: 0.74741




Frequency (Hz)


3C241 2024/06/10 7.95UT FUJI -KISO



T20240610182104





BLK: 2,SNR1: 0.30903 ,SNR2: 0.60649




Frequency (Hz)

F20240610182106




BLK: 2,SNR1: 0.20495 ,SNR2: 2.0054




Frequency (Hz)


1145+485 2024/06/10 9.38UT TOYOKAWA-FUJI



T20240610182104





No.Good Data




Frequency (Hz)

K20240610182101




No.Good Data





Frequency (Hz)


1145+485 2024/06/10 9.38UT TOYOKAWA-KISO



F20240610182106





BLK: 7,SNR1: 0.96256 ,SNR2: 4.4044




Frequency (Hz)

K20240610182101



BLK: 7,SNR1: 0.32116 ,SNR2: 1.0332



Frequency (Hz)

1145+485 2024/06/10 9.38UT FUJI -KISO

