



T20240614052110




BLK: 8,SNR1: 12.579 ,SNR2: 34.599




Frequency (Hz)

F20240614052112




BLK: 8,SNR1: 0.69499 ,SNR2: 5.4458





Frequency (Hz)



2259+481 2024/06/13 20.38UT TOYOKAWA-FUJI




T20240614052110





K20240614052108




2259+481 2024/06/13 20.38UT TOYOKAWA-KISO



F20240614052112





BLK: 8,SNR1: 1.2930 ,SNR2: 8.8891




Frequency (Hz)

K20240614052108




BLK: 8,SNR1: 0.27546 ,SNR2: 1.9051




Frequency (Hz)


2259+481 2024/06/13 20.38UT FUJI -KISO





T20240614053713




BLK: 1, SNR1: 0.23068 ,SNR2: 1.8279




F20240614053715




BLK: 1, SNR1: 2.5544 ,SNR2: 10.623




2315+396 2024/06/13 20.65UT TOYOKAWA-FUJI



T20240614053713





BLK: 2, SNR1: 0.20924 , SNR2: 0.54514




Frequency (Hz)

K20240614053710




BLK: 2, SNR1: 1.1045 , SNR2: 5.5634





Frequency (Hz)


2315+396 2024/06/13 20.65UT TOYOKAWA-KISO



F20240614053715





BLK: 7,SNR1: 1.1080 ,SNR2: 2.8672




Frequency (Hz)

K20240614053710




BLK: 7,SNR1: 0.25165 ,SNR2: 3.3208




Frequency (Hz)


2315+396 2024/06/13 20.65UT FUJI -KISO



T20240614061642




BLK: 3,SNR1: 0.64973E-01,SNR2: 0.40718




Frequency (Hz)

F20240614061644




BLK: 3,SNR1: 0.20236 ,SNR2: 3.0321





Frequency (Hz)


2354+14 2024/06/13 21.31UT TOYOKAWA-FUJI



T20240614061642





No.Good Data




Frequency (Hz)

K20240614061639




No.Good Data





Frequency (Hz)

2354+14 2024/06/13 21.31UT TOYOKAWA-KISO






F20240614061644





BLK: 4,SNR1: 0.11679 ,SNR2: 0.58956




Frequency (Hz)

K20240614061639




BLK: 4,SNR1: 0.19202 ,SNR2: 1.4887




Frequency (Hz)


2354+14 2024/06/13 21.31UT FUJI -KISO



T20240614063306




BLK: 1,SNR1: 0.15472 ,SNR2: 1.2772




Frequency (Hz)

F20240614063308




BLK: 1,SNR1: 0.14072E-01,SNR2: 1.8544




Frequency (Hz)


0011+344 2024/06/13 21.58UT TOYOKAWA-FUJI





T20240614063306




No.Good Data




K20240614063303




No.Good Data




0011+344 2024/06/13 21.58UT TOYOKAWA-KISO



F20240614063308





BLK: 4,SNR1: 0.46277 ,SNR2: 4.3338




Frequency (Hz)

K20240614063303




BLK: 4,SNR1: 0.15746E-01,SNR2: 0.33023





Frequency (Hz)


0011+344 2024/06/13 21.58UT FUJI -KISO



T20240614064143




BLK: 2,SNR1: 0.15595 ,SNR2: 0.73078




Frequency (Hz)

F20240614064145




BLK: 2,SNR1:-0.10410 ,SNR2: 0.68699




Frequency (Hz)


0019-00 2024/06/13 21.72UT TOYOKAWA-FUJI



T20240614064143





BLK: 2,SNR1:-0.35648E-01,SNR2: 0.77062




Frequency (Hz)

K20240614064141




BLK: 2,SNR1: 1.4106 ,SNR2: 6.9108





Frequency (Hz)


0019-00 2024/06/13 21.72UT TOYOKAWA-KISO





F20240614064145




No.Good Data




K20240614064141





No.Good Data




0019-00 2024/06/13 21.72UT FUJI -KISO



T20240614065157





BLK: 2,SNR1: 0.29278 ,SNR2: 0.47632




Frequency (Hz)

3C12 2024/06/13 21.89UT TOYOKAWA-FUJI


F20240614065159



BLK: 2,SNR1: 0.91545E-01,SNR2: 2.7891




Frequency (Hz)






T20240614065157





BLK: 2,SNR1: 0.10312E-01,SNR2: 0.79089E-01




Frequency (Hz)

K20240614065155




BLK: 2,SNR1: 0.81167 ,SNR2: 7.4774





Frequency (Hz)


3C12 2024/06/13 21.89UT TOYOKAWA-KISO



F20240614065159





BLK: 3,SNR1: 0.11414 ,SNR2: 1.9737




Frequency (Hz)

3C12 2024/06/13 21.89UT FUJI -KISO


K20240614065155





BLK: 3,SNR1: 0.56024 ,SNR2: 5.8940




Frequency (Hz)



T20240614070015




BLK: 3,SNR1: 0.18331 ,SNR2: 0.55471




Frequency (Hz)

F20240614070017




BLK: 3,SNR1: 0.85147E-01,SNR2: 2.7427




Frequency (Hz)


0038+328 2024/06/13 22.03UT TOYOKAWA-FUJI



T20240614070015




BLK: 3,SNR1: 0.30913E-01,SNR2: 0.42331




Frequency (Hz)

K20240614070012




BLK: 3,SNR1: 0.46568 ,SNR2: 4.2277





Frequency (Hz)


0038+328 2024/06/13 22.03UT TOYOKAWA-KISO



F20240614070017





BLK: 3,SNR1: 0.79157E-01,SNR2: 2.5269




Frequency (Hz)

K20240614070012




BLK: 3,SNR1: 0.56882 ,SNR2: 1.6063





Frequency (Hz)


0038+328 2024/06/13 22.03UT FUJI -KISO



T20240614071320



BLK: 6,SNR1: 0.11831 ,SNR2: 1.3696





Frequency (Hz)


3C26

2024/06/13 22.25UT TOYOKAWA-FUJI


F20240614071322





BLK: 6,SNR1:-0.12820 ,SNR2: 0.75258




Frequency (Hz)



T20240614071320



BLK:10,SNR1: 0.15446 ,SNR2: 1.3449





Frequency (Hz)


3C26

2024/06/13 22.25UT TOYOKAWA-KISO


K20240614071317





BLK:10,SNR1: 1.2285 ,SNR2: 6.5571




Frequency (Hz)



F20240614071322





BLK: 5,SNR1: 1.7275 ,SNR2: 3.5395




Frequency (Hz)

3C26 2024/06/13 22.25UT FUJI -KISO


K20240614071317



BLK: 5,SNR1: 0.69679 ,SNR2: 3.1897





Frequency (Hz)






T20240614071819




BLK: 1,SNR1: 0.46757 ,SNR2: 1.2425




Frequency (Hz)

F20240614071821




BLK: 1,SNR1:-0.12252 ,SNR2: 0.66696





Frequency (Hz)


0056-00 2024/06/13 22.33UT TOYOKAWA-FUJI



T20240614071819





BLK: 6,SNR1: 0.11977 ,SNR2: 1.9603




Frequency (Hz)

K20240614071816




BLK: 6,SNR1: 0.14340 ,SNR2: 1.2413





Frequency (Hz)


0056-00 2024/06/13 22.33UT TOYOKAWA-KISO



F20240614071821





No.Good Data




Frequency (Hz)

K20240614071816




No.Good Data




Frequency (Hz)


0056-00 2024/06/13 22.33UT FUJI -KISO





T20240614072801




BLK: 4,SNR1:-0.54086E-01,SNR2: 0.27812




F20240614072803





BLK: 4,SNR1: 0.16274 ,SNR2: 1.9139




0106+01 2024/06/13 22.50UT TOYOKAWA-FUJI



T20240614072801





BLK: 7,SNR1: 0.91285E-01,SNR2: 0.63670




Frequency (Hz)

K20240614072758




BLK: 7,SNR1: 0.71790 ,SNR2: 3.3598





Frequency (Hz)


0106+01 2024/06/13 22.50UT TOYOKAWA-KISO



F20240614072803





BLK: 4,SNR1:-0.28873 ,SNR2: 0.74935E-02




Frequency (Hz)

K20240614072758




BLK: 4,SNR1:-0.98757E-02,SNR2: 1.3797





Frequency (Hz)


0106+01 2024/06/13 22.50UT FUJI -KISO





T20240614073724




No.Good Data




F20240614073726





No.Good Data




0115-01 2024/06/13 22.65UT TOYOKAWA-FUJI



T20240614073724





BLK: 1,SNR1: 0.37086 ,SNR2: 12.404




Frequency (Hz)

0115-01 2024/06/13 22.65UT TOYOKAWA-KISO


K20240614073721



BLK: 1,SNR1: 0.34289 ,SNR2: 1.6992





Frequency (Hz)






F20240614073726





BLK: 4,SNR1:-0.97897E-01,SNR2: 0.79908




Frequency (Hz)

K20240614073721




BLK: 4,SNR1: 0.92545 ,SNR2: 4.0198





Frequency (Hz)


0115-01 2024/06/13 22.65UT FWJ -KISO



T20240614075023




BLK: 2,SNR1: 0.98382E-01,SNR2: 1.0439




Frequency (Hz)

F20240614075025




BLK: 2,SNR1: 0.37049 ,SNR2: 1.2509




Frequency (Hz)


0128+03 2024/06/13 22.87UT TOYOKAWA-FUJI



T20240614075023




BLK: 6,SNR1: 0.24661 ,SNR2: 1.9471




Frequency (Hz)

K20240614075020




BLK: 6,SNR1: 1.0528 ,SNR2: 4.0528




Frequency (Hz)


0128+03 2024/06/13 22.87UT TOYOKAWA-KISO



F20240614075025





BLK: 5,SNR1: 1.2918 ,SNR2: 6.7238




Frequency (Hz)

K20240614075020




BLK: 5,SNR1: 0.19028 ,SNR2: 1.8406





Frequency (Hz)


0128+03 2024/06/13 22.87UT FUJI -KISO



T20240614075657




BLK:28,SNR1: 4.0226 ,SNR2: 17.665





3C48 2024/06/13 22.98UT TOYOKAWA-FUJI


F20240614075659




BLK:28,SNR1: 0.22111 ,SNR2: 1.2918



T20240614075657



BLK:33,SNR1: 3.7475 ,SNR2: 17.083





Frequency (Hz)


3C48

2024/06/13 22.98UT TOYOKAWA-KISO


K20240614075654




BLK:33,SNR1: 0.96683 ,SNR2: 5.9365




Frequency (Hz)



F20240614075659



BLK:27,SNR1: 0.21317 ,SNR2: 1.2296





Frequency (Hz)


3C48

2024/06/13 22.98UT FUJI -KISO


K20240614075654





BLK:27,SNR1: 1.0389 ,SNR2: 6.7213




Frequency (Hz)




T20240614081642




BLK: 5,SNR1: 0.14936 ,SNR2: 1.7450




F20240614081644



BLK: 5,SNR1:-0.79621E-01,SNR2: 1.2970




0155-109 2024/06/13 23.31UT TOYOKAWA-FUJI






T20240614081642




BLK: 2,SNR1: 0.35508 ,SNR2: 3.4204





0155-109 2024/06/13 23.31UT TOYOKAWA-KISO



K20240614081639




BLK: 2,SNR1: 0.13186 ,SNR2: 0.73298



F20240614081644





BLK: 3,SNR1:-0.12011 ,SNR2: 0.52062




Frequency (Hz)

K20240614081639




BLK: 3,SNR1: 0.39873 ,SNR2: 1.9560





Frequency (Hz)


0155-109 2024/06/13 23.31UT FUJI -KISO



T20240614082349




BLK: 8,SNR1: 0.12838 ,SNR2: 2.1591





0202+15 2024/06/13 23.43UT TOYOKAWA-FUJI


F20240614082351




BLK: 8,SNR1:-0.63796E-01,SNR2: 1.0410



T20240614082349





BLK: 7,SNR1: 0.22710 ,SNR2: 0.82061




Frequency (Hz)

K20240614082346




BLK: 7,SNR1: 0.33534 ,SNR2: 2.4872





Frequency (Hz)


0202+15 2024/06/13 23.43UT TOYOKAWA-KISO



F20240614082351




BLK: 4,SNR1:-0.90830E-01,SNR2: 1.7454




Frequency (Hz)

K20240614082346




BLK: 4,SNR1: 0.19395 ,SNR2: 2.4158





Frequency (Hz)


0202+15 2024/06/13 23.43UT FUJI -KISO




T20240614083539




BLK: 2,SNR1: 0.47263 ,SNR2: 1.1045




F20240614083541





BLK: 2,SNR1:-0.49151E-03,SNR2: 0.59873




0213+178 2024/06/13 23.62UT TOYOKAWA-FUJI



T20240614083539





BLK: 4,SNR1: 1.9820 ,SNR2: 2.2057





0213+178 2024/06/13 23.62UT TOYOKAWA-KISO


K20240614083536




BLK: 4,SNR1: 2.0532 ,SNR2: 9.8382





F20240614083541




BLK:10,SNR1: 0.55555 ,SNR2: 2.9436




K20240614083536



BLK:10,SNR1: 1.5810 ,SNR2: 7.4661




0213+178 2024/06/13 23.62UT FUJI -KISO






T20240614084322




BLK: 6,SNR1: 0.39047 ,SNR2: 3.6040





3C67 2024/06/13 23.75UT TOYOKAWA-FUJI



F20240614084324




BLK: 6,SNR1: 0.23659 ,SNR2: 2.2018





T20240614084322




BLK: 4,SNR1: 0.10994 ,SNR2: 2.5244




K20240614084319




BLK: 4,SNR1: 0.34955 ,SNR2: 1.6219




3C67 2024/06/13 23.75UT TOYOKAWA-KISO



F20240614084324





BLK:10,SNR1: 0.73294 ,SNR2: 2.6486




Frequency (Hz)

3C67 2024/06/13 23.75UT FUJI -KISO


K20240614084319




BLK:10,SNR1: 0.43667 ,SNR2: 1.7544




Frequency (Hz)



T20240614085403




BLK: 2,SNR1: 0.24063 ,SNR2: 0.56428





0232-042 2024/06/13 23.93UT TOYOKAWA-FUJI


F20240614085405




BLK: 2,SNR1: 1.5497 ,SNR2: 2.5173





T20240614085403




BLK: 5,SNR1: 0.10786 ,SNR2: 1.0394




K20240614085400




BLK: 5,SNR1: 0.48895 ,SNR2: 2.5681




0232-042 2024/06/13 23.93UT TOYOKAWA-KISO




F20240614085405




BLK: 3,SNR1: 0.13250E-01,SNR2: 0.75578




K20240614085400




BLK: 3,SNR1: 0.22183 ,SNR2: 1.4919




0232-042 2024/06/13 23.93UT FUJI -KISO



T20240614090137




BLK: 6, SNR1: 0.24887 , SNR2: 0.89150




Frequency (Hz)

3C71 2024/06/14 0.06UT TOYOKAWA-FUJI


F20240614090139




BLK: 6, SNR1: 0.11725 , SNR2: 1.5655




Frequency (Hz)



T20240614090137





BLK:17,SNR1: 0.33212 ,SNR2: 1.8996




Frequency (Hz)

3C71 2024/06/14 0.06UT TOYOKAWA-KISO


K20240614090134



BLK:17,SNR1: 2.2419 ,SNR2: 7.4512




Frequency (Hz)







F20240614090139




BLK: 8,SNR1: 0.13124 ,SNR2: 1.2853




K20240614090134





BLK: 8,SNR1: 3.0491 ,SNR2: 9.2811




3C71 2024/06/14 0.06UT FUJI -KISO



T20240614092052





BLK: 3,SNR1: 1.4808 ,SNR2: 3.7706




Frequency (Hz)

F20240614092054




BLK: 3,SNR1: 19.574 ,SNR2: 91.416





Frequency (Hz)


0258+350 2024/06/14 0.38UT TOYOKAWA-FUJI



T20240614092052





BLK: 1,SNR1: 0.10550 ,SNR2: 0.70889




Frequency (Hz)

K20240614092049




BLK: 1,SNR1: 0.13202 ,SNR2: 0.59430




Frequency (Hz)


0258+350 2024/06/14 0.38UT TOYOKAWA-KISO





F20240614092054




BLK: 3,SNR1: 16.524 ,SNR2: 75.680




K20240614092049





BLK: 3,SNR1: 0.67022 ,SNR2: 4.8489




0258+350 2024/06/14 0.38UT FUJI -KISO





T20240614093041




BLK: 3,SNR1: 0.23290 ,SNR2: 0.55983




F20240614093043





BLK: 3,SNR1: 3.5188 ,SNR2: 9.0518




0308+305 2024/06/14 0.54UT TOYOKAWA-FUJI



T20240614093041





BLK: 4,SNR1: 0.77329E-01,SNR2: 1.1327





0308+305 2024/06/14 0.54UT TOYOKAWA-KISO


K20240614093038




BLK: 4,SNR1: 3.7522 ,SNR2: 16.201



F20240614093043




BLK: 7,SNR1: 1.9992 ,SNR2: 4.4670





0308+305 2024/06/14 0.54UT FUJI -KISO



K20240614093038




BLK: 7,SNR1: 3.4133 ,SNR2: 14.823





T20240614093901




BLK: 5,SNR1: 0.24000 ,SNR2: 1.4408




F20240614093903



BLK: 5,SNR1:-0.13018E-01,SNR2: 4.2336





3C84 2024/06/14 0.68UT TOYOKAWA-FUJI








T20240614093901




BLK:15,SNR1: 0.15843 ,SNR2: 1.2357




K20240614093858




BLK:15,SNR1: 0.29283 ,SNR2: 1.3551




3C84 2024/06/14 0.68UT TOYOKAWA-KISO



F20240614093903





BLK: 5,SNR1: 0.76702E-01,SNR2: 2.0284




Frequency (Hz)

3C84 2024/06/14 0.68UT FUJI -KISO


K20240614093858





BLK: 5,SNR1: 0.37100 ,SNR2: 1.2475




Frequency (Hz)





T20240614094617




BLK: 1,SNR1: 0.67796E-01,SNR2: 0.31624




F20240614094619





BLK: 1,SNR1: 0.64672E-01,SNR2: 0.59308




0324+119 2024/06/14 0.80UT TOYOKAWA-FUJI



T20240614094617





BLK: 3,SNR1: 0.12072 ,SNR2: 0.31211





0324+119 2024/06/14 0.80UT TOYOKAWA-KISO



K20240614094614




BLK: 3,SNR1: 0.61340 ,SNR2: 3.1850




F20240614094619




BLK: 6,SNR1: 0.91390E-01,SNR2: 1.4781




K20240614094614





BLK: 6,SNR1: 0.14204 ,SNR2: 1.4404




0324+119 2024/06/14 0.80UT FUJI -KISO




T20240614095534




BLK: 3,SNR1: 0.20358E-01,SNR2: 0.36039




F20240614095536




BLK: 3,SNR1: 0.60159 ,SNR2: 2.8510




0333+32 2024/06/14 0.95UT TOYOKAWA-FUJI



T20240614095534




BLK: 4,SNR1: 0.50158E-01,SNR2: 0.39634




Frequency (Hz)

0333+32 2024/06/14 0.95UT TOYOKAWA-KISO


K20240614095531




BLK: 4,SNR1: 0.62323 ,SNR2: 2.6005




Frequency (Hz)





F20240614095536




BLK: 6,SNR1: 0.52196 ,SNR2: 2.5026




K20240614095531



BLK: 6,SNR1: 1.0894 ,SNR2: 4.4229





0333+32 2024/06/14 0.95UT FUJI -KISO






T20240614100835




BLK: 6,SNR1: 0.29650 ,SNR2: 4.4173





0347+05 2024/06/14 1.17UT TOYOKAWA-FUJI



F20240614100837




BLK: 6,SNR1: 1.0996 ,SNR2: 4.8040





T20240614100835




BLK: 5,SNR1: 0.33382 ,SNR2: 1.3596




K20240614100832




BLK: 5,SNR1: 0.29429 ,SNR2: 0.74201




0347+05 2024/06/14 1.17UT TOYOKAWA-KISO




F20240614100837




BLK: 4,SNR1: 1.9303 ,SNR2: 5.2943




K20240614100832





BLK: 4,SNR1: 0.19211 ,SNR2: 0.96835




0347+05 2024/06/14 1.17UT FUJI -KISO




T20240614102410




BLK: 9,SNR1: 0.22192 ,SNR2: 2.1411




F20240614102412




BLK: 9,SNR1: 1.1149 ,SNR2: 2.8529




0403-132 2024/06/14 1.43UT TOYOKAWA-FUJI





T20240614102410




BLK:13,SNR1: 0.40418 ,SNR2: 2.8008




K20240614102407




BLK:13,SNR1: 1.4794 ,SNR2: 6.0529




0403-132 2024/06/14 1.43UT TOYOKAWA-KISO





F20240614102412




BLK: 9,SNR1: 2.5615 ,SNR2: 8.2277




K20240614102407





BLK: 9,SNR1: 1.9300 ,SNR2: 7.5907




0403-132 2024/06/14 1.43UT FUJI -KISO




T20240614103321




BLK:14,SNR1: 0.50071 ,SNR2: 2.4372




F20240614103323





BLK:14,SNR1: 0.48178 ,SNR2: 1.9947




0411+05 2024/06/14 1.58UT TOYOKAWA-FUJI





T20240614103321




BLK:21,SNR1: 0.48027 ,SNR2: 2.2136




K20240614103318



BLK:21,SNR1: 0.66121 ,SNR2: 2.6553




0411+05 2024/06/14 1.58UT TOYOKAWA-KISO






F20240614103323





BLK:14,SNR1: 1.6577 ,SNR2: 4.8803




Frequency (Hz)

K20240614103318




BLK:14,SNR1: 0.96753 ,SNR2: 4.1537





Frequency (Hz)


0411+05 2024/06/14 1.58UT FUJI -KISO





T20240614104015




BLK: 8,SNR1: 0.99501E-01,SNR2: 0.53190




F20240614104017





BLK: 8,SNR1: 3.5026 ,SNR2: 11.910




0418+236 2024/06/14 1.70UT TOYOKAWA-FUJI





T20240614104015




BLK:10,SNR1: 0.11296 ,SNR2: 0.80079




K20240614104012




BLK:10,SNR1: 1.5509 ,SNR2: 7.4344




0418+236 2024/06/14 1.70UT TOYOKAWA-KISO




F20240614104017




BLK:23,SNR1: 5.2398 ,SNR2: 14.193




K20240614104012





BLK:23,SNR1: 1.4285 ,SNR2: 6.2124




0418+236 2024/06/14 1.70UT FUJI -KISO




T20240614105142




BLK:12,SNR1: 3.2441 ,SNR2: 23.004




F20240614105144





BLK:12,SNR1: 1.3914 ,SNR2: 6.8467




3C119 2024/06/14 1.89UT TOYOKAWA-FUJI





T20240614105142




BLK:23,SNR1: 2.8423 ,SNR2: 16.786




K20240614105139





BLK:23,SNR1: 0.54615 ,SNR2: 2.1331




3C119 2024/06/14 1.89UT TOYOKAWA-KISO



F20240614105144




BLK:17,SNR1: 0.97603 ,SNR2: 5.2387




Frequency (Hz)

K20240614105139




BLK:17,SNR1: 0.59957 ,SNR2: 2.3739





Frequency (Hz)


3C119 2024/06/14 1.89UT FUJI -KISO



T20240614113949





BLK:24,SNR1: 13.682 ,SNR2: 24.255




3C138 2024/06/14 2.69UT TOYOKAWA-FUJI


F20240614113951



BLK:24,SNR1: 9.8809 ,SNR2: 24.659





Frequency (Hz)






T20240614113949





BLK:26,SNR1: 13.665 ,SNR2: 24.226




3C138 2024/06/14 2.69UT TOYOKAWA-KISO


K20240614113946





BLK:26,SNR1: 2.6961 ,SNR2: 12.941




Frequency (Hz)



F20240614113951





BLK:32,SNR1: 2.7919 ,SNR2: 13.323





3C138 2024/06/14 2.69UT FUJI -KISO



K20240614113946




BLK:32,SNR1: 2.6761 ,SNR2: 12.868



T20240614115323




BLK:18,SNR1: 2.7338 ,SNR2: 13.084





0531+194 2024/06/14 2.92UT TOYOKAWA-FUJI



F20240614115325




BLK:18,SNR1: 5.3891 ,SNR2: 15.312





T20240614115323




BLK:29,SNR1: 8.5681 ,SNR2: 21.494




K20240614115320




BLK:29,SNR1: 8.9918 ,SNR2: 16.777




0531+194 2024/06/14 2.92UT TOYOKAWA-KISO



F20240614115325




BLK:24,SNR1: 5.4237 ,SNR2: 15.405





0531+194 2024/06/14 2.92UT FUJI -KISO



K20240614115320




BLK:24,SNR1: 8.9017 ,SNR2: 16.613



T20240614120142





BLK:30,SNR1: 3.1541 ,SNR2: 14.515





3C147 2024/06/14 3.06UT TOYOKAWA-FUJI



F20240614120144




BLK:30,SNR1: 6.7011 ,SNR2: 18.666





T20240614120142




BLK:30,SNR1: 3.1434 ,SNR2: 14.474




K20240614120139







BLK:30,SNR1: 8.5263 ,SNR2: 21.390




3C147 2024/06/14 3.06UT TOYOKAWA-KISO






3C147 2024/06/14 3.06UT FUJI -KISO







T20240614120954




BLK:13,SNR1: 11.778 ,SNR2: 32.655




F20240614120956





BLK:13,SNR1: 0.56524E-01,SNR2: 2.1466




0548+16 2024/06/14 3.19UT TOYOKAWA-FUJI




T20240614120954




BLK:21,SNR1: 9.2503 ,SNR2: 24.039




K20240614120951




BLK:21,SNR1: 0.41421 ,SNR2: 2.4202




0548+16 2024/06/14 3.19UT TOYOKAWA-KISO




F20240614120956




BLK:14,SNR1: 0.46264 ,SNR2: 1.3634




K20240614120951




BLK:14,SNR1: 0.77665 ,SNR2: 3.0709




0548+16 2024/06/14 3.19UT FUJI -KISO



T20240614121404





BLK:18,SNR1: 2.6066 ,SNR2: 12.297





0552+12 2024/06/14 3.26UT TOYOKAWA-FUJI


F20240614121406




BLK:18,SNR1: 2.8324 ,SNR2: 13.277



T20240614121404




BLK:25,SNR1: 8.5406 ,SNR2: 21.137





0552+12 2024/06/14 3.26UT TOYOKAWA-KISO



K20240614121401




BLK:25,SNR1: 8.0159 ,SNR2: 20.821





F20240614121406




BLK:25,SNR1: 2.8805 ,SNR2: 13.462




K20240614121401




BLK:25,SNR1: 8.0398 ,SNR2: 20.887




0552+12 2024/06/14 3.26UT FUJI -KISO




T20240614121831




BLK:15,SNR1: 0.85184 ,SNR2: 3.2064




F20240614121833





BLK:15,SNR1: 1.7050 ,SNR2: 5.4211




0556+191 2024/06/14 3.34UT TOYOKAWA-FUJI





T20240614121831




BLK:22,SNR1: 0.89401 ,SNR2: 3.2805




K20240614121828



BLK:22,SNR1: 0.30042 ,SNR2: 2.0609




0556+191 2024/06/14 3.34UT TOYOKAWA-KISO








F20240614121833




BLK:13,SNR1: 1.8459 ,SNR2: 5.9229




K20240614121828





BLK:13,SNR1: 0.52646 ,SNR2: 2.2456




0556+191 2024/06/14 3.34UT FUJI -KISO





T20240614122617




BLK:25,SNR1: 3.1788 ,SNR2: 8.1397




F20240614122619





BLK:25,SNR1: 5.3262 ,SNR2: 12.250




0605-08 2024/06/14 3.47UT TOYOKAWA-FUJI





T20240614122617




BLK:24,SNR1: 3.0235 ,SNR2: 8.8040




K20240614122615





BLK:24,SNR1: 7.8424 ,SNR2: 19.303




0605-08 2024/06/14 3.47UT TOYOKAWA-KISO





F20240614122619




BLK:25,SNR1: 5.7567 ,SNR2: 13.365




K20240614122615




BLK:25,SNR1: 8.2620 ,SNR2: 14.763




0605-08 2024/06/14 3.47UT FUJI -KISO




T20240614124525




BLK:19,SNR1: 1.1599 ,SNR2: 4.7454




F20240614124527




BLK:19,SNR1: 0.12135 ,SNR2: 1.7484




3C161 2024/06/14 3.79UT TOYOKAWA-FUJI



T20240614124525





BLK:28,SNR1: 0.99376 ,SNR2: 7.9950





3C161 2024/06/14 3.79UT TOYOKAWA-KISO


K20240614124522




BLK:28,SNR1: 0.34441 ,SNR2: 1.3155



F20240614124527





BLK:18,SNR1: 0.19269 ,SNR2: 2.0132





3C161 2024/06/14 3.79UT FUJI -KISO



K20240614124522




BLK:18,SNR1: 0.63279 ,SNR2: 2.3810




T20240614131258




BLK:11,SNR1: 0.67256 ,SNR2: 2.0533




F20240614131300



BLK:11,SNR1: 2.6522 ,SNR2: 11.979





0652-130 2024/06/14 4.24UT TOYOKAWA-FUJI








T20240614131258




BLK: 9,SNR1: 0.29257 ,SNR2: 2.3345




K20240614131256




BLK: 9,SNR1: 8.5264 ,SNR2: 21.408




0652-130 2024/06/14 4.24UT TOYOKAWA-KISO





F20240614131300




BLK:14,SNR1: 3.0569 ,SNR2: 13.426




K20240614131256





BLK:14,SNR1: 7.5965 ,SNR2: 19.302




0652-130 2024/06/14 4.24UT FUJI -KISO





T20240614132434




BLK: 3,SNR1:-0.37421E-01,SNR2: 0.75541




F20240614132436





BLK: 3,SNR1: 0.85736 ,SNR2: 2.8334




0703+138 2024/06/14 4.44UT TOYOKAWA-FUJI





T20240614132434




BLK: 7,SNR1: 0.35406E-01,SNR2: 0.34729




K20240614132432





BLK: 7,SNR1: 0.94719 ,SNR2: 4.4127




0703+138 2024/06/14 4.44UT TOYOKAWA-KISO





F20240614132436




BLK: 9,SNR1: 0.22286 ,SNR2: 0.90249




K20240614132432





BLK: 9,SNR1: 0.49936 ,SNR2: 2.6014




0703+138 2024/06/14 4.44UT FUJI -KISO





T20240614133357




BLK: 6,SNR1: 0.15963 ,SNR2: 0.83559




F20240614133359





BLK: 6,SNR1: 2.8818 ,SNR2: 12.796




0713-024 2024/06/14 4.59UT TOYOKAWA-FUJI





T20240614133357




BLK:13,SNR1: 0.10311 ,SNR2: 0.81794




K20240614133354





BLK:13,SNR1: 1.5413 ,SNR2: 6.8063




0713-024 2024/06/14 4.59UT TOYOKAWA-KISO





F20240614133359




BLK:14,SNR1: 2.5691 ,SNR2: 11.687




K20240614133354



BLK:14,SNR1: 1.1158 ,SNR2: 5.2433




0713-024 2024/06/14 4.59UT FUJI -KISO








T20240614134409




BLK: 4,SNR1: 0.29757E-01,SNR2: 0.56114




F20240614134411




BLK: 4,SNR1: 0.90247E-02,SNR2: 1.2590




0723+10 2024/06/14 4.76UT TOYOKAWA-FUJI





T20240614134409




BLK: 6,SNR1:-0.59761E-01,SNR2: 0.75234




K20240614134406





BLK: 6,SNR1: 0.78309 ,SNR2: 3.0579




0723+10 2024/06/14 4.76UT TOYOKAWA-KISO





F20240614134411




BLK:11,SNR1: 0.64590 ,SNR2: 1.9051




K20240614134406





BLK:11,SNR1: 1.1640 ,SNR2: 4.5403




0723+10 2024/06/14 4.76UT FUJI -KISO




T20240614135423




BLK: 8,SNR1: 4.7098 ,SNR2: 23.273




F20240614135425




BLK: 8,SNR1: 0.33534 ,SNR2: 1.8887




0732+33 2024/06/14 4.93UT TOYOKAWA-FUJI




T20240614135423




BLK:14,SNR1: 0.35358E-01,SNR2: 1.6952




K20240614135420




BLK:14,SNR1: 0.54488 ,SNR2: 2.2667




0732+33 2024/06/14 4.93UT TOYOKAWA-KISO





F20240614135425




BLK:15,SNR1: 0.17684 ,SNR2: 1.8523




K20240614135420





BLK:15,SNR1: 1.7072 ,SNR2: 6.6884




0732+33 2024/06/14 4.93UT FUJI -KISO




T20240614140225




BLK: 5,SNR1: 0.64598 ,SNR2: 3.9088




F20240614140227





BLK: 5,SNR1: 0.11333 ,SNR2: 2.1183




0741-06 2024/06/14 5.07UT TOYOKAWA-FUJI





T20240614140225




BLK: 9,SNR1: 0.61486 ,SNR2: 4.5074




K20240614140223



BLK: 9,SNR1: 0.19092 ,SNR2: 0.96921





0741-06 2024/06/14 5.07UT TOYOKAWA-KISO








F20240614140227




BLK: 2,SNR1: 0.41595 ,SNR2: 4.5408




K20240614140223




BLK: 2,SNR1: 0.23893 ,SNR2: 1.5111




0741-06 2024/06/14 5.07UT FUJI -KISO





T20240614141210




BLK: 4,SNR1: 0.23184E-01,SNR2: 0.91929




F20240614141212




BLK: 4,SNR1: 0.15203 ,SNR2: 1.6428




0752-200 2024/06/14 5.23UT TOYOKAWA-FUJI





T20240614141210




BLK: 3,SNR1:-0.84804E-01,SNR2: 0.81392




K20240614141207





BLK: 3,SNR1: 0.34129 ,SNR2: 1.5102




0752-200 2024/06/14 5.23UT TOYOKAWA-KISO





F20240614141212




BLK: 3,SNR1: 0.64754 ,SNR2: 6.1846




K20240614141207





BLK: 3,SNR1: 0.15941 ,SNR2: 1.1586




0752-200 2024/06/14 5.23UT FUJI -KISO





T20240614141945




BLK: 8,SNR1: 0.77696 ,SNR2: 6.1692




F20240614141947





BLK: 8,SNR1: 0.38153 ,SNR2: 2.1327




3C190 2024/06/14 5.36UT TOYOKAWA-FUJI





T20240614141945




BLK:12,SNR1: 1.0484 ,SNR2: 4.8753




K20240614141942





BLK:12,SNR1: 22.263 ,SNR2: 27.190




3C190 2024/06/14 5.36UT TOYOKAWA-KISO





F20240614141947




BLK:18,SNR1: 1.4591 ,SNR2: 3.8827




K20240614141942





BLK:18,SNR1: 9.9437 ,SNR2: 11.760




3C190 2024/06/14 5.36UT FUJI -KISO




T20240614143209




BLK:13,SNR1: 0.84579 ,SNR2: 2.7796




F20240614143211



BLK:13,SNR1: 0.13343 ,SNR2: 1.0447





3C196 2024/06/14 5.56UT TOYOKAWA-FUJI






T20240614143209





BLK:25,SNR1: 0.96014 ,SNR2: 1.6321




Frequency (Hz)

K20240614143207




BLK:25,SNR1: 5.3143 ,SNR2: 7.1918




Frequency (Hz)


3C196 2024/06/14 5.56UT TOYOKAWA-KISO



F20240614143211




BLK:10,SNR1: 0.79548E-01,SNR2: 1.2225




Frequency (Hz)

K20240614143207




BLK:10,SNR1: 9.3344 ,SNR2: 8.7878





Frequency (Hz)


3C196 2024/06/14 5.56UT FUJI -KISO





T20240614144319




BLK:10,SNR1: 0.52931 ,SNR2: 2.2784




F20240614144321





BLK:10,SNR1: 0.48150 ,SNR2: 1.9511




0821+394 2024/06/14 5.75UT TOYOKAWA-FUJI





T20240614144319




BLK:14,SNR1: 0.43629 ,SNR2: 2.0328




K20240614144316





BLK:14,SNR1: 0.58750 ,SNR2: 4.4116




0821+394 2024/06/14 5.75UT TOYOKAWA-KISO





F20240614144321




BLK:16,SNR1: 45.889 ,SNR2: 102.53




K20240614144316





BLK:16,SNR1: 35.077 ,SNR2: 57.004




0821+394 2024/06/14 5.75UT FUJI -KISO



T20240614145459





BLK:13,SNR1: 0.58742 ,SNR2: 3.0955




Frequency (Hz)

F20240614145501




BLK:13,SNR1: 1.2650 ,SNR2: 3.1416




Frequency (Hz)


0834-19 2024/06/14 5.94UT TOYOKAWA-FUJI





T20240614145459




BLK:18,SNR1: 0.25451 ,SNR2: 1.9876




K20240614145456





BLK:18,SNR1: 1.5517 ,SNR2: 1.4742




0834-19 2024/06/14 5.94UT TOYOKAWA-KISO



F20240614145501





BLK:15,SNR1: 4.3320 ,SNR2: 6.4630




Frequency (Hz)

K20240614145456




BLK:15,SNR1: 2.4811 ,SNR2: 2.3036





Frequency (Hz)

0834-19 2024/06/14 5.94UT FUJI -KISO






T20240614150004




BLK: 7,SNR1: 1.4442 ,SNR2: 4.3762




Frequency (Hz)

F20240614150006




BLK: 7,SNR1: 0.14394 ,SNR2: 3.0770




Frequency (Hz)


0839-071 2024/06/14 6.03UT TOYOKAWA-FUJI



T20240614150004





BLK:14,SNR1: 1.3174 ,SNR2: 2.6744




Frequency (Hz)

K20240614150001




BLK:14,SNR1: 1.4306 ,SNR2: 3.3291




Frequency (Hz)


0839-071 2024/06/14 6.03UT TOYOKAWA-KISO



F20240614150006





BLK: 5,SNR1: 0.55226 ,SNR2: 4.5013




Frequency (Hz)

K20240614150001




BLK: 5,SNR1:-0.10762 ,SNR2: 0.95802





Frequency (Hz)


0839-071 2024/06/14 6.03UT FUJI -KISO




T20240614151105




BLK: 4,SNR1: 0.15869 ,SNR2: 2.5292




F20240614151107





BLK: 4,SNR1: 1.0312 ,SNR2: 4.0118




3C208 2024/06/14 6.21UT TOYOKAWA-FUJI





T20240614151105




BLK: 3,SNR1: 0.48406E-01,SNR2: 0.66507




K20240614151103




BLK: 3,SNR1: 1.6265 ,SNR2: 7.1386




3C208 2024/06/14 6.21UT TOYOKAWA-KISO



F20240614151107





BLK:11,SNR1: 3.1094 ,SNR2: 14.152




Frequency (Hz)

K20240614151103




BLK:11,SNR1: 0.31572 ,SNR2: 3.7113





Frequency (Hz)


3C208 2024/06/14 6.21UT FUJI -KISO



T20240614152746





BLK: 5,SNR1: 0.31945 ,SNR2: 0.73959




Frequency (Hz)

F20240614152748




BLK: 5,SNR1: 3.6474 ,SNR2: 9.2478





Frequency (Hz)


3C216 2024/06/14 6.49UT TOYOKAWA-FUJI



T20240614152746





BLK: 9,SNR1: 0.31381E-01,SNR2: 1.3259




Frequency (Hz)

K20240614152744




BLK: 9,SNR1: 0.13426 ,SNR2: 2.3993




Frequency (Hz)

3C216 2024/06/14 6.49UT TOYOKAWA-KISO








F20240614152748




BLK:11,SNR1: 4.3354 ,SNR2: 10.987




K20240614152744





BLK:11,SNR1: 3.9988 ,SNR2: 16.797




3C216 2024/06/14 6.49UT FUJI -KISO



T20240614153958




BLK:13,SNR1: 0.21349 ,SNR2: 0.72746




Frequency (Hz)

F20240614154000




BLK:13,SNR1: 2.9201 ,SNR2: 13.064





Frequency (Hz)


0919-142 2024/06/14 6.69UT TOYOKAWA-FUJI



T20240614153958





BLK:21,SNR1: 1.7449 ,SNR2: 7.6480




Frequency (Hz)

K20240614153956




BLK:21,SNR1: 3.8145 ,SNR2: 4.4841




Frequency (Hz)


0919-142 2024/06/14 6.69UT TOYOKAWA-KISO





F20240614154000




BLK:15,SNR1: 2.6796 ,SNR2: 11.812




K20240614153956





BLK:15,SNR1: 3.9776 ,SNR2: 3.5806




0919-142 2024/06/14 6.69UT FUJI -KISO



T20240614154637





BLK: 8,SNR1: 0.23262E-01,SNR2: 0.28679




Frequency (Hz)

F20240614154639




BLK: 8,SNR1: 2.3045 ,SNR2: 11.445




Frequency (Hz)


0926+117 2024/06/14 6.81UT TOYOKAWA-FUJI



T20240614154637





BLK: 4,SNR1:-0.68797E-01,SNR2: 0.53408




Frequency (Hz)

K20240614154635




BLK: 4,SNR1: 5.4741 ,SNR2: 4.9151





Frequency (Hz)


0926+117 2024/06/14 6.81UT TOYOKAWA-KISO



F20240614154639





BLK: 9,SNR1: 5.9783 ,SNR2: 9.0070




Frequency (Hz)

K20240614154635




BLK: 9,SNR1: 0.10491 ,SNR2: 1.0734





Frequency (Hz)


0926+117 2024/06/14 6.81UT FUJI -KISO



T20240614155422




BLK: 7,SNR1: 0.28089 ,SNR2: 1.2963




Frequency (Hz)

F20240614155424




BLK: 7,SNR1: 0.22091 ,SNR2: 2.8085





Frequency (Hz)

3C222 2024/06/14 6.93UT TOYOKAWA-FUJI








T20240614155422




BLK:16,SNR1: 0.13841 ,SNR2: 0.79724




K20240614155419




BLK:16,SNR1: 3.0585 ,SNR2: 3.5482




3C222 2024/06/14 6.93UT TOYOKAWA-KISO



F20240614155424





BLK: 4,SNR1: 5.7649 ,SNR2: 11.331




Frequency (Hz)

K20240614155419




BLK: 4,SNR1: 1.0257 ,SNR2: 5.0833





Frequency (Hz)


3C222 2024/06/14 6.93UT FUJI -KISO



T20240614160122




BLK: 4,SNR1: 0.12722 ,SNR2: 0.49774




Frequency (Hz)

F20240614160124




BLK: 4,SNR1:-0.13237E-01,SNR2: 1.6611





Frequency (Hz)


0941-08 2024/06/14 7.05UT TOYOKAWA-FUJI





T20240614160122




BLK: 3,SNR1: 0.21063 ,SNR2: 0.75426




K20240614160120




BLK: 3,SNR1: 0.43362 ,SNR2: 3.2574




0941-08 2024/06/14 7.05UT TOYOKAWA-KISO



F20240614160124





BLK:10,SNR1: 0.10470E-01,SNR2: 1.7102




Frequency (Hz)

K20240614160120




BLK:10,SNR1: 0.49326E-01,SNR2: 1.3111





Frequency (Hz)


0941-08 2024/06/14 7.05UT FUJI -KISO




T20240614160944




BLK: 9,SNR1: 3.5344 ,SNR2: 15.341




F20240614160946





BLK: 9,SNR1: 7.2070 ,SNR2: 13.451




3C230 2024/06/14 7.19UT TOYOKAWA-FUJI





T20240614160944




BLK:19,SNR1: 3.5565 ,SNR2: 15.701




K20240614160942




BLK:19,SNR1: 3.7318 ,SNR2: 11.164




3C230 2024/06/14 7.19UT TOYOKAWA-KISO



F20240614160946





BLK:12,SNR1: 8.9261 ,SNR2: 16.469




Frequency (Hz)

K20240614160942




BLK:12,SNR1: 23.101 ,SNR2: 27.194





Frequency (Hz)

3C230 2024/06/14 7.19UT FUJI -KISO






T20240614162544





BLK:10,SNR1: 0.81736 ,SNR2: 3.9166




Frequency (Hz)

F20240614162546




BLK:10,SNR1: 0.20941 ,SNR2: 1.0574





Frequency (Hz)


3C237 2024/06/14 7.46UT TOYOKAWA-FUJI



T20240614162544




BLK:10,SNR1: 0.75412 ,SNR2: 3.7908




Frequency (Hz)

K20240614162542




BLK:10,SNR1: 0.42707 ,SNR2: 2.0468





Frequency (Hz)


3C237 2024/06/14 7.46UT TOYOKAWA-KISO



F20240614162546





BLK:16,SNR1: 0.61583 ,SNR2: 2.0810




Frequency (Hz)

K20240614162542




BLK:16,SNR1: 0.59252 ,SNR2: 2.6197





Frequency (Hz)


3C237 2024/06/14 7.46UT FUJI -KISO



T20240614163201





BLK: 8,SNR1: 8.3539 ,SNR2: 79.932




Frequency (Hz)

F20240614163203




BLK: 8,SNR1: 10.705 ,SNR2: 17.253





Frequency (Hz)


1011+110 2024/06/14 7.56UT TOYOKAWA-FUJI



T20240614163201




BLK: 5,SNR1: 0.40641E-01,SNR2: 0.27662




Frequency (Hz)

K20240614163159




BLK: 5,SNR1: 0.48308 ,SNR2: 5.3919





Frequency (Hz)


1011+110 2024/06/14 7.56UT TOYOKAWA-KISO



F20240614163203





BLK:11,SNR1: 9.9371 ,SNR2: 14.306




Frequency (Hz)

K20240614163159




BLK:11,SNR1: 0.25474 ,SNR2: 0.73733





Frequency (Hz)


1011+110 2024/06/14 7.56UT FUJI -KISO



T20240614163942





BLK: 5,SNR1: 0.14551 ,SNR2: 0.60248




Frequency (Hz)

F20240614163944




BLK: 5,SNR1: 5.5010 ,SNR2: 26.188





Frequency (Hz)


3C241 2024/06/14 7.69UT TOYOKAWA-FUJI



T20240614163942





BLK: 9,SNR1: 0.99874E-01,SNR2: 0.44136




Frequency (Hz)

K20240614163939




BLK: 9,SNR1: 0.12151 ,SNR2: 1.0307





Frequency (Hz)

3C241 2024/06/14 7.69UT TOYOKAWA-KISO






F20240614163944




BLK: 9,SNR1: 6.1869 ,SNR2: 33.695




Frequency (Hz)

K20240614163939




BLK: 9,SNR1: 0.84836E-01,SNR2: 0.82879





Frequency (Hz)


3C241 2024/06/14 7.69UT FUJI -KISO



T20240614175104





BLK: 4,SNR1: 0.89553E-01,SNR2: 0.91109




Frequency (Hz)

F20240614175106




BLK: 4,SNR1: 0.38798 ,SNR2: 5.1238





Frequency (Hz)


1130+335 2024/06/14 8.88UT TOYOKAWA-FUJI



T20240614175104





BLK: 6,SNR1:-0.53822E-02,SNR2: 0.99729




Frequency (Hz)

K20240614175101






BLK: 6,SNR1: 1.7115 ,SNR2: 4.5914



Frequency (Hz)

1130+335 2024/06/14 8.88UT TOYOKAWA-KISO





1130+335 2024/06/14 8.88UT FUJI -KISO

