



T20240620054809




BLK: 1,SNR1: 0.32107E-03,SNR2: 0.59034




Frequency (Hz)

F20240620054811




BLK: 1,SNR1:-0.13145 ,SNR2: 0.43387





Frequency (Hz)


2349+327 2024/06/19 20.83UT TOYOKAWA-FUJI



T20240620054809





BLK: 3,SNR1: 0.93072E-01,SNR2: 0.45113




Frequency (Hz)

K20240620054806




BLK: 3,SNR1: 0.94673 ,SNR2: 5.1970





Frequency (Hz)


2349+327 2024/06/19 20.83UT TOYOKAWA-KISO



F20240620054811





BLK: 3,SNR1: 0.18711E-01,SNR2: 2.8335




Frequency (Hz)

K20240620054806




BLK: 3,SNR1: 1.0221 ,SNR2: 4.0671





Frequency (Hz)


2349+327 2024/06/19 20.83UT FUJI -KISO



T20240620060143




BLK: 3,SNR1: 0.48002 ,SNR2: 10.386




Frequency (Hz)

F20240620060145




BLK: 3,SNR1:-0.16391 ,SNR2: 1.1160





Frequency (Hz)


0003+313 2024/06/19 21.06UT TOYOKAWA-FUJI



T20240620060143





BLK: 5,SNR1: 0.37053 ,SNR2: 2.0625




Frequency (Hz)

K20240620060141




BLK: 5,SNR1: 0.29729 ,SNR2: 1.7986





Frequency (Hz)


0003+313 2024/06/19 21.06UT TOYOKAWA-KISO



F20240620060145





BLK: 4,SNR1:-0.14544 ,SNR2: 1.9957




Frequency (Hz)

K20240620060141




BLK: 4,SNR1: 1.3013 ,SNR2: 8.1326




Frequency (Hz)


0003+313 2024/06/19 21.06UT FUJI -KISO



T20240620060931




BLK:12,SNR1: 2.7502 ,SNR2: 7.6616




Frequency (Hz)

F20240620060933




BLK:12,SNR1: 1.4590 ,SNR2: 6.4778





Frequency (Hz)


0011+344 2024/06/19 21.19UT TOYOKAWA-FUJI





T20240620060931




BLK:13,SNR1: 2.7934 ,SNR2: 11.987




K20240620060929



BLK:13,SNR1: 4.1054 ,SNR2: 17.223





0011+344 2024/06/19 21.19UT TOYOKAWA-KISO






F20240620060933





BLK:15,SNR1: 1.4073 ,SNR2: 6.0698




Frequency (Hz)

K20240620060929




BLK:15,SNR1: 4.1051 ,SNR2: 17.222




Frequency (Hz)


0011+344 2024/06/19 21.19UT FUJI -KISO



T20240620062256




BLK: 2,SNR1: 0.44385 ,SNR2: 1.4973




Frequency (Hz)

F20240620062258




BLK: 2,SNR1:-0.84059E-01,SNR2: 0.69599




Frequency (Hz)


0024+125 2024/06/19 21.41UT TOYOKAWA-FUJI



T20240620062256





BLK: 4,SNR1: 4.8001 ,SNR2: 52.156




Frequency (Hz)

0024+125 2024/06/19 21.41UT TOYOKAWA-KISO


K20240620062254





BLK: 4,SNR1: 0.12059 ,SNR2: 3.5346




Frequency (Hz)



F20240620062258





BLK: 5,SNR1: 0.71129E-02,SNR2: 0.58897




Frequency (Hz)

K20240620062254




BLK: 5,SNR1: 0.98116E-01,SNR2: 2.5257





Frequency (Hz)


0024+125 2024/06/19 21.41UT FUJI -KISO



T20240620062822




BLK: 1,SNR1:-0.15955 ,SNR2: 0.17818




Frequency (Hz)

3C12 2024/06/19 21.50UT TOYOKAWA-FUJI


F20240620062824




BLK: 1,SNR1:-0.13878 ,SNR2: 1.7496




Frequency (Hz)



T20240620062822





BLK: 5,SNR1: 0.77804E-02,SNR2: 1.1312




Frequency (Hz)

3C12 2024/06/19 21.50UT TOYOKAWA-KISO


K20240620062820




BLK: 5,SNR1: 0.73187 ,SNR2: 2.4374




Frequency (Hz)



F20240620062824





BLK: 6,SNR1: 0.50147E-01,SNR2: 1.3064




Frequency (Hz)

3C12 2024/06/19 21.50UT FUJI -KISO


K20240620062820




BLK: 6,SNR1: 0.11868 ,SNR2: 1.9609





Frequency (Hz)







BLK: 5,SNR1: 1.1491 ,SNR2: 4.8630




BLK: 5,SNR1: 9.6015 ,SNR2: 16.715





0038+328 2024/06/19 21.64UT TOYOKAWA-FUJI









BLK: 8,SNR1: 0.58091 ,SNR2: 2.2277





BLK: 8,SNR1: 23.187 ,SNR2: 28.421




0038+328 2024/06/19 21.64UT TOYOKAWA-KISO





F20240620063642




BLK:12,SNR1: 16.532 ,SNR2: 20.346




K20240620063638







BLK:12,SNR1: 28.458 ,SNR2: 27.566








0038+328 2024/06/19 21.64UT FUJI -KISO






3C26 2024/06/19 21.86UT TOYOKAWA-FUJI







3C26 2024/06/19 21.86UT TOYOKAWA-KISO





F20240620064947




BLK: 1,SNR1:-0.26503 ,SNR2: 0.72428




K20240620064943





BLK: 1,SNR1: 0.11351 ,SNR2: 2.6369




3C26 2024/06/19 21.86UT FUJI -KISO



T20240620065444





No.Good Data




Frequency (Hz)

F20240620065446




No.Good Data





Frequency (Hz)


0056-00 2024/06/19 21.94UT TOYOKAWA-FUJI



T20240620065444





BLK: 6,SNR1: 0.45748E-01,SNR2: 0.30098





0056-00 2024/06/19 21.94UT TOYOKAWA-KISO



K20240620065442




BLK: 6,SNR1: 0.23310 ,SNR2: 3.0454



F20240620065446





BLK: 6,SNR1:-0.32547 ,SNR2: 0.89079E-02




Frequency (Hz)

K20240620065442




BLK: 6,SNR1: 0.38106 ,SNR2: 2.1938





Frequency (Hz)

0056-00 2024/06/19 21.94UT FUJI -KISO







T20240620070426




BLK: 4,SNR1: 0.64646E-01,SNR2: 0.89899




F20240620070428





BLK: 4,SNR1: 0.37799E-01,SNR2: 1.0453




0106+01 2024/06/19 22.10UT TOYOKAWA-FUJI



T20240620070426





BLK: 2,SNR1:-0.47891E-01,SNR2: 1.2255




Frequency (Hz)

0106+01 2024/06/19 22.10UT TOYOKAWA-KISO


K20240620070424





BLK: 2,SNR1: 1.5148 ,SNR2: 8.3268




Frequency (Hz)



F20240620070428





BLK: 3,SNR1:-0.25285 ,SNR2: 0.25461E-01




Frequency (Hz)

0106+01 2024/06/19 22.10UT FUJI -KISO


K20240620070424





BLK: 3,SNR1: 0.63210E-01,SNR2: 0.71618




Frequency (Hz)



T20240620071349





BLK: 4,SNR1: 0.12950 ,SNR2: 1.0720




Frequency (Hz)

F20240620071351




BLK: 4,SNR1:-0.20512 ,SNR2: 0.52596





Frequency (Hz)


0115-01 2024/06/19 22.26UT TOYOKAWA-FUJI



T20240620071349





BLK: 4,SNR1: 4.2106 ,SNR2: 11.836




Frequency (Hz)

0115-01 2024/06/19 22.28UT TOYOKAWA-KISO


K20240620071347





BLK: 4,SNR1: 0.80910 ,SNR2: 3.9482




Frequency (Hz)





F20240620071351




BLK: 3,SNR1:-0.97581E-01,SNR2: 0.0000




K20240620071347





BLK: 3,SNR1: 1.0713 ,SNR2: 5.0768




0115-01 2024/06/19 22.26UT FUJI -KISO



T20240620072648





BLK: 6,SNR1: 0.25621 ,SNR2: 2.1059




Frequency (Hz)

F20240620072650




BLK: 6,SNR1: 0.39386E-02,SNR2: 1.4252





Frequency (Hz)


0128+03 2024/06/19 22.47UT TOYOKAWA-FUJI



T20240620072648





BLK: 5,SNR1: 0.14734 ,SNR2: 1.8514




Frequency (Hz)

K20240620072646




BLK: 5,SNR1: 0.41583 ,SNR2: 2.2584




Frequency (Hz)

0128+03 2024/06/19 22.47UT TOYOKAWA-KISO






F20240620072650




BLK: 5,SNR1: 0.10576E-01,SNR2: 2.1612




Frequency (Hz)

K20240620072646




BLK: 5,SNR1: 0.50930 ,SNR2: 2.4526





Frequency (Hz)


0128+03 2024/06/19 22.47UT FUJI -KISO



T20240620073322




BLK:16,SNR1: 0.57844 ,SNR2: 6.9872




Frequency (Hz)

3C48 2024/06/19 22.58UT TOYOKAWA-FUJI


F20240620073324





BLK:16,SNR1: 2.8390 ,SNR2: 11.808




Frequency (Hz)



T20240620073322




BLK:22,SNR1: 0.61452 ,SNR2: 8.0335





3C48 2024/06/19 22.58UT TOYOKAWA-KISO


K20240620073320




BLK:22,SNR1: 2.6522 ,SNR2: 11.457



F20240620073324




BLK:10,SNR1: 3.0352 ,SNR2: 12.737




Frequency (Hz)

3C48 2024/06/19 22.58UT FUJI -KISO


K20240620073320





BLK:10,SNR1: 0.72851 ,SNR2: 3.8334




Frequency (Hz)



T20240620075307





BLK:11,SNR1: 2.4407 ,SNR2: 5.7406




Frequency (Hz)

F20240620075309




BLK:11,SNR1: 0.35989 ,SNR2: 2.2658




Frequency (Hz)


0155-109 2024/06/19 22.91UT TOYOKAWA-FUJI



T20240620075307




BLK:11,SNR1: 3.3633 ,SNR2: 11.435




Frequency (Hz)

K20240620075304




BLK:11,SNR1: 0.79710 ,SNR2: 3.3476





Frequency (Hz)


0155-109 2024/06/19 22.91UT TOYOKAWA-KISO



F20240620075309





BLK: 9,SNR1: 0.12329 ,SNR2: 1.3368




Frequency (Hz)

K20240620075304




BLK: 9,SNR1: 0.49589 ,SNR2: 1.8954





Frequency (Hz)


0155-109 2024/06/19 22.91UT FUJI -KISO



T20240620080014




BLK: 5,SNR1: 0.54119 ,SNR2: 4.3839




Frequency (Hz)

0202+15 2024/06/19 23.03UT TOYOKAWA-FUJI


F20240620080016



BLK: 5,SNR1: 0.74667 ,SNR2: 2.5940





Frequency (Hz)






T20240620080014





BLK:14,SNR1: 0.51239 ,SNR2: 3.6281





0202+15 2024/06/19 23.03UT TOYOKAWA-KISO


K20240620080011




BLK:14,SNR1: 0.40610 ,SNR2: 2.3461





F20240620080016




BLK: 9,SNR1: 0.50207 ,SNR2: 2.0061




K20240620080011





BLK: 9,SNR1: 4.0715 ,SNR2: 17.076




0202+15 2024/06/19 23.03UT FUJI -KISO




T20240620081204




BLK: 4,SNR1: 0.12742 ,SNR2: 0.65322




F20240620081206





BLK: 4,SNR1: 0.58832 ,SNR2: 6.9807




0213+178 2024/06/19 23.23UT TOYOKAWA-FUJI





T20240620081204




BLK: 3,SNR1: 0.12528E-01,SNR2: 0.57222




K20240620081202




BLK: 3,SNR1: 0.38119 ,SNR2: 1.1558




0213+178 2024/06/19 23.23UT TOYOKAWA-KISO




F20240620081206




BLK: 5,SNR1: 0.47102 ,SNR2: 1.3917




K20240620081202





BLK: 5,SNR1: 0.55563 ,SNR2: 2.1841




0213+178 2024/06/19 23.23UT FUJI -KISO



T20240620081946




BLK: 8,SNR1: 0.97612E-01,SNR2: 1.4050





3C67 2024/06/19 23.36UT TOYOKAWA-FUJI


F20240620081948




BLK: 8,SNR1: 0.88653 ,SNR2: 2.4957



T20240620081946





BLK: 5,SNR1: 0.18270E-01,SNR2: 2.1602





3C67 2024/06/19 23.36UT TOYOKAWA-KISO


K20240620081944




BLK: 5,SNR1: 0.24119 ,SNR2: 3.7873



F20240620081948



BLK: 8,SNR1: 1.3199 ,SNR2: 3.4695





Frequency (Hz)


3C67

2024/06/19 23.36UT FUJI -KISO


K20240620081944







BLK: 8,SNR1: 0.15591 ,SNR2: 0.67516




Frequency (Hz)









3C71 2024/06/19 23.66UT TOYOKAWA-FUJI



T20240620083801




BLK:21,SNR1: 3.8626 ,SNR2: 11.136





3C71 2024/06/19 23.66UT TOYOKAWA-KISO


K20240620083758




BLK:21,SNR1: 3.0234 ,SNR2: 5.9730



F20240620083803





BLK:19,SNR1: 2.1981 ,SNR2: 10.560





3C71 2024/06/19 23.66UT FUJI -KISO



K20240620083758




BLK:19,SNR1: 3.4536 ,SNR2: 6.7914



T20240620085413





BLK: 3,SNR1: 0.16497 ,SNR2: 0.98454




Frequency (Hz)

F20240620085415




BLK: 3,SNR1: 0.27612 ,SNR2: 1.8924





Frequency (Hz)


0255+460 2024/06/19 23.93UT TOYOKAWA-FUJI





T20240620085413




BLK: 3,SNR1: 0.25210 ,SNR2: 0.84805




K20240620085410




BLK: 3,SNR1: 1.0130 ,SNR2: 5.2894




0255+460 2024/06/19 23.93UT TOYOKAWA-KISO





F20240620085415




BLK: 6,SNR1: 0.86075E-01,SNR2: 1.0662




K20240620085410




BLK: 6,SNR1: 0.35186 ,SNR2: 1.1927




0255+460 2024/06/19 23.93UT FUJI -KISO




T20240620090705




BLK:23,SNR1: 2.0264 ,SNR2: 7.1800




F20240620090707




BLK:23,SNR1: 0.28233E-01,SNR2: 2.0799




0308+305 2024/06/20 0.15UT TOYOKAWA-FUJI





T20240620090705




BLK:28,SNR1: 1.7653 ,SNR2: 6.4316




K20240620090703



BLK:28,SNR1: 1.3816 ,SNR2: 5.5052




0308+305 2024/06/20 0.15UT TOYOKAWA-KISO







F20240620090707




BLK:18,SNR1: 0.18847E-01,SNR2: 1.9758




K20240620090703





BLK:18,SNR1: 2.5143 ,SNR2: 8.2579




0308+305 2024/06/20 0.15UT FUJI -KISO




T20240620091525




BLK: 8,SNR1: 0.17826 ,SNR2: 3.3557




F20240620091527




BLK: 8,SNR1: 0.86333E-01,SNR2: 1.8020




3C84 2024/06/20 0.29UT TOYOKAWA-FUJI



T20240620091525





BLK:13,SNR1: 0.18035 ,SNR2: 1.1030





3C84 2024/06/20 0.29UT TOYOKAWA-KISO


K20240620091522




BLK:13,SNR1: 0.59379 ,SNR2: 2.4164



F20240620091527




BLK: 5, SNR1: 0.32680 , SNR2: 3.1505





3C84 2024/06/20 0.29UT FUJI -KISO



K20240620091522




BLK: 5, SNR1: 0.44915 , SNR2: 2.0291



T20240620092242




BLK:36,SNR1: 8.7866 ,SNR2: 22.024




0324+119 2024/06/20 0.41UT TOYOKAWA-FUJI


F20240620092244





BLK:36,SNR1: 7.5101 ,SNR2: 18.842




Frequency (Hz)



T20240620092242





BLK:32,SNR1: 8.7935 ,SNR2: 22.041





0324+119 2024/06/20 0.41UT TOYOKAWA-KISO



K20240620092239




BLK:32,SNR1: 2.5178 ,SNR2: 12.242



F20240620092244





BLK:36,SNR1: 7.5178 ,SNR2: 19.079




Frequency (Hz)

K20240620092239




BLK:36,SNR1: 2.5160 ,SNR2: 12.234




Frequency (Hz)


0324+119 2024/06/20 0.41UT FUJI -KISO



T20240620093158





BLK:12,SNR1: 2.5774 ,SNR2: 12.409





0333+32 2024/06/20 0.56UT TOYOKAWA-FUJI

F20240620093200




BLK:12,SNR1: 6.7406 ,SNR2: 16.988






T20240620093158





BLK:17,SNR1: 2.5903 ,SNR2: 12.386





0333+32 2024/06/20 0.56UT TOYOKAWA-KISO



K20240620093155




BLK:17,SNR1: 20.275 ,SNR2: 53.579





F20240620093200




BLK:18,SNR1: 6.6319 ,SNR2: 16.666




K20240620093155





BLK:18,SNR1: 28.266 ,SNR2: 51.100




0333+32 2024/06/20 0.56UT FUJI -KISO



T20240620094500





BLK:30,SNR1: 8.8986 ,SNR2: 22.270





0347+05 2024/06/20 0.78UT TOYOKAWA-FUJI



F20240620094502




BLK:30,SNR1: 19.935 ,SNR2: 22.500



T20240620094500





BLK:35,SNR1: 8.7503 ,SNR2: 21.907





0347+05 2024/06/20 0.78UT TOYOKAWA-KISO



K20240620094457




BLK:35,SNR1: 9.0529 ,SNR2: 22.652



F20240620094502





BLK:30,SNR1: 19.880 ,SNR2: 22.438





0347+05 2024/06/20 0.78UT FUJI -KISO



K20240620094457




BLK:30,SNR1: 9.1852 ,SNR2: 22.981




T20240620100035




BLK: 8,SNR1: 0.20149 ,SNR2: 1.8751




F20240620100037





BLK: 8,SNR1: 1.2167 ,SNR2: 4.3270




0403-132 2024/06/20 1.04UT TOYOKAWA-FUJI



T20240620100035




BLK:10,SNR1: 0.17365 ,SNR2: 0.97178





0403-132 2024/06/20 1.04UT TOYOKAWA-KISO


K20240620100032




BLK:10,SNR1: 0.48198 ,SNR2: 1.8361





F20240620100037




BLK: 9,SNR1: 6.6865 ,SNR2: 19.543




K20240620100032



BLK: 9,SNR1: 0.53211 ,SNR2: 1.6692





0403-132 2024/06/20 1.04UT FUJI -KISO






T20240620100945





BLK:14,SNR1: 2.9168 ,SNR2: 13.586





0411+05 2024/06/20 1.19UT TOYOKAWA-FUJI



F20240620100947




BLK:14,SNR1: 6.1677 ,SNR2: 15.467



T20240620100945





BLK:13,SNR1: 2.9172 ,SNR2: 13.589





0411+05 2024/06/20 1.19UT TOYOKAWA-KISO



K20240620100942




BLK:13,SNR1: 8.4223 ,SNR2: 21.098




F20240620100947




BLK:18,SNR1: 4.8903 ,SNR2: 12.570




K20240620100942




BLK:18,SNR1: 8.4298 ,SNR2: 21.124




0411+05 2024/06/20 1.19UT FUJI -KISO




T20240620101639




BLK:17,SNR1: 70.113 ,SNR2: 279.55




F20240620101641




BLK:17,SNR1: 58.650 ,SNR2: 93.816




0418+236 2024/06/20 1.31UT TOYOKAWA-FUJI





T20240620101639




BLK:19,SNR1: 67.221 ,SNR2: 278.82




K20240620101636




BLK:19,SNR1: 64.603 ,SNR2: 84.083




0418+236 2024/06/20 1.31UT TOYOKAWA-KISO





F20240620101641




BLK:19,SNR1: 55.695 ,SNR2: 100.12




K20240620101636




BLK:19,SNR1: 17.113 ,SNR2: 52.898




0418+236 2024/06/20 1.31UT FUJI -KISO




T20240620102806




BLK:20,SNR1: 5.5839 ,SNR2: 46.913




F20240620102808




BLK:20,SNR1: 0.85252 ,SNR2: 1.9356




3C119 2024/06/20 1.50UT TOYOKAWA-FUJI





T20240620102806




BLK:32,SNR1: 5.3962 ,SNR2: 44.203




K20240620102803



BLK:32,SNR1: 1.1644 ,SNR2: 4.4962





3C119 2024/06/20 1.50UT TOYOKAWA-KISO








F20240620102808




BLK:29,SNR1: 0.85321 ,SNR2: 2.4851




K20240620102803





BLK:29,SNR1: 1.3176 ,SNR2: 5.0323




3C119 2024/06/20 1.50UT FUJI -KISO




T20240620111614




BLK:26,SNR1: 17.435 ,SNR2: 64.435




F20240620111616





BLK:26,SNR1: 2.6374 ,SNR2: 6.1600




3C138 2024/06/20 2.30UT TOYOKAWA-FUJI



T20240620111614




BLK:24,SNR1: 15.035 ,SNR2: 56.561





3C138 2024/06/20 2.30UT TOYOKAWA-KISO


K20240620111611




BLK:24,SNR1: 1.5641 ,SNR2: 6.4707




F20240620111616




BLK:28,SNR1: 2.4404 ,SNR2: 5.9019




K20240620111611





BLK:28,SNR1: 1.6162 ,SNR2: 6.7559




3C138 2024/06/20 2.30UT FUJI -KISO




T20240620112947




BLK:18,SNR1: 1.6281 ,SNR2: 8.7647




F20240620112949





BLK:18,SNR1: 0.19949 ,SNR2: 2.0505




0531+194 2024/06/20 2.52UT TOYOKAWA-FUJI





T20240620112947




BLK:23,SNR1: 1.5965 ,SNR2: 8.0479




K20240620112944




BLK:23,SNR1: 0.54154 ,SNR2: 1.7178




0531+194 2024/06/20 2.52UT TOYOKAWA-KISO



F20240620112949





BLK:19,SNR1: 0.42774 ,SNR2: 3.4646





0531+194 2024/06/20 2.52UT FUJI -KISO



K20240620112944




BLK:19,SNR1: 0.45387 ,SNR2: 2.0094




T20240620113806




BLK:28,SNR1: 24.815 ,SNR2: 96.819




F20240620113808



BLK:28,SNR1: 0.68362 ,SNR2: 6.1432





3C147 2024/06/20 2.66UT TOYOKAWA-FUJI








T20240620113806




BLK:37,SNR1: 23.558 ,SNR2: 90.170




K20240620113803




BLK:37,SNR1: 3.1903 ,SNR2: 12.431




3C147 2024/06/20 2.66UT TOYOKAWA-KISO





F20240620113808




BLK:34,SNR1: 0.69984 ,SNR2: 5.9246




K20240620113803





BLK:34,SNR1: 3.5644 ,SNR2: 7.1069




3C147 2024/06/20 2.66UT FUJI -KISO



T20240620114618





BLK:18,SNR1: 7.1941 ,SNR2: 15.904





0548+16 2024/06/20 2.80UT TOYOKAWA-FUJI


F20240620114620




BLK:18,SNR1: 0.33980 ,SNR2: 1.3883



T20240620114618




BLK:30,SNR1: 6.9159 ,SNR2: 12.335





0548+16 2024/06/20 2.80UT TOYOKAWA-KISO



K20240620114615




BLK:30,SNR1: 0.66799 ,SNR2: 2.6881



F20240620114620





BLK:13,SNR1: 0.77954 ,SNR2: 2.8448




Frequency (Hz)

K20240620114615




BLK:13,SNR1: 0.82812 ,SNR2: 3.7766




Frequency (Hz)


0548+16 2024/06/20 2.80UT FUJI -KISO




T20240620115029




BLK:30,SNR1: 186.80 ,SNR2: 316.01




F20240620115031




BLK:30,SNR1: 87.762 ,SNR2: 129.11




0552+12 2024/06/20 2.87UT TOYOKAWA-FUJI




T20240620115029




BLK:35,SNR1: 166.27 ,SNR2: 288.47




K20240620115026




BLK:35,SNR1: 11.037 ,SNR2: 41.143




0552+12 2024/06/20 2.87UT TOYOKAWA-KISO





F20240620115031




BLK:33,SNR1: 79.419 ,SNR2: 118.56




K20240620115026



BLK:33,SNR1: 11.439 ,SNR2: 41.898





0552+12 2024/06/20 2.87UT FUJI -KISO








T20240620115456




BLK:30,SNR1: 11.763 ,SNR2: 28.788




F20240620115458





BLK:30,SNR1: 1.1702 ,SNR2: 4.9450




0556+191 2024/06/20 2.94UT TOYOKAWA-FUJI



T20240620115456




BLK:25,SNR1: 13.225 ,SNR2: 32.361





0556+191 2024/06/20 2.94UT TOYOKAWA-KISO



K20240620115453




BLK:25,SNR1: 1.6001 ,SNR2: 6.7657





F20240620115458




BLK:18,SNR1: 1.9000 ,SNR2: 5.2097




K20240620115453




BLK:18,SNR1: 2.1219 ,SNR2: 10.159




0556+191 2024/06/20 2.94UT FUJI -KISO




T20240620115928




BLK:21,SNR1: 2.8628 ,SNR2: 10.943




F20240620115930





BLK:21,SNR1: 1.5058 ,SNR2: 2.5165




3C152 2024/06/20 3.02UT TOYOKAWA-FUJI



T20240620115928





BLK:17,SNR1: 2.2301 ,SNR2: 8.1512





3C152 2024/06/20 3.02UT TOYOKAWA-KISO



K20240620115925




BLK:17,SNR1: 23.128 ,SNR2: 20.662



F20240620115930





BLK:27,SNR1: 3.4513 ,SNR2: 8.3904





3C152 2024/06/20 3.02UT FUJI -KISO


K20240620115925




BLK:27,SNR1: 22.744 ,SNR2: 20.317





T20240620122150




BLK:24,SNR1: 3.0162 ,SNR2: 29.301




F20240620122152




BLK:24,SNR1: 0.23261 ,SNR2: 3.5368




3C161 2024/06/20 3.39UT TOYOKAWA-FUJI



T20240620122150





BLK:31,SNR1: 3.1829 ,SNR2: 26.085





3C161 2024/06/20 3.39UT TOYOKAWA-KISO

K20240620122147





BLK:31,SNR1: 0.79018 ,SNR2: 3.0946






F20240620122152




BLK:25,SNR1: 0.42449 ,SNR2: 4.3973




Frequency (Hz)

3C161 2024/06/20 3.39UT FUJI -KISO


K20240620122147




BLK:25,SNR1: 0.93780 ,SNR2: 3.6804




Frequency (Hz)



T20240620124923




BLK:11,SNR1: 38.119 ,SNR2: 61.047





0652-130 2024/06/20 3.85UT TOYOKAWA-FUJI



F20240620124925




BLK:11,SNR1: 0.83264 ,SNR2: 2.3814



T20240620124923





BLK:12,SNR1: 32.961 ,SNR2: 53.176




Frequency (Hz)

0652-130 2024/06/20 3.85UT TOYOKAWA-KISO


K20240620124920




BLK:12,SNR1: 0.69538 ,SNR2: 3.6299




Frequency (Hz)





F20240620124925




BLK: 9,SNR1: 0.63835 ,SNR2: 1.9749




K20240620124920





BLK: 9,SNR1: 0.79048 ,SNR2: 3.6222




0652-130 2024/06/20 3.85UT FUJI -KISO





T20240620130059




BLK: 6,SNR1: 0.30660 ,SNR2: 1.8195




F20240620130101





BLK: 6,SNR1: 0.21750 ,SNR2: 0.77822




0703+138 2024/06/20 4.04UT TOYOKAWA-FUJI





T20240620130059




BLK: 4,SNR1: 0.27478 ,SNR2: 2.0365




K20240620130057





BLK: 4,SNR1: 1.2899 ,SNR2: 6.3865




0703+138 2024/06/20 4.04UT TOYOKAWA-KISO





F20240620130101




BLK: 4,SNR1: 0.29870 ,SNR2: 2.3351




K20240620130057





BLK: 4,SNR1: 0.18333 ,SNR2: 2.9534




0703+138 2024/06/20 4.04UT FUJI -KISO





T20240620131022




BLK: 3,SNR1: 0.77662E-01,SNR2: 1.0775




F20240620131024



BLK: 3,SNR1: 0.47236E-01,SNR2: 1.2618





0713-024 2024/06/20 4.20UT TOYOKAWA-FUJI








T20240620131022




BLK: 9,SNR1: 0.31790E-01,SNR2: 1.1654




K20240620131019





BLK: 9,SNR1: 0.81421 ,SNR2: 3.4475




0713-024 2024/06/20 4.20UT TOYOKAWA-KISO





F20240620131024




BLK: 5,SNR1: 0.19557 ,SNR2: 1.7200




K20240620131019





BLK: 5,SNR1: 7.5904 ,SNR2: 13.046




0713-024 2024/06/20 4.20UT FUJI -KISO





T20240620132033




BLK:15,SNR1: 3.3211 ,SNR2: 14.435




F20240620132035





BLK:15,SNR1: 13.078 ,SNR2: 25.763




0723+10 2024/06/20 4.37UT TOYOKAWA-FUJI





T20240620132033




BLK:18,SNR1: 3.1920 ,SNR2: 13.900




K20240620132031





BLK:18,SNR1: 4.1138 ,SNR2: 11.388




0723+10 2024/06/20 4.37UT TOYOKAWA-KISO



F20240620132035





BLK:29,SNR1: 12.419 ,SNR2: 24.461





0723+10 2024/06/20 4.37UT FUJI -KISO



K20240620132031




BLK:29,SNR1: 4.1141 ,SNR2: 11.384




T20240620133048




BLK:10,SNR1: 0.25169 ,SNR2: 0.95529




F20240620133050





BLK:10,SNR1: 0.80079 ,SNR2: 6.1090




0732+33 2024/06/20 4.54UT TOYOKAWA-FUJI





T20240620133048




BLK:14,SNR1: 0.25692 ,SNR2: 1.0482




K20240620133046




BLK:14,SNR1: 0.86260 ,SNR2: 6.1358




0732+33 2024/06/20 4.54UT TOYOKAWA-KISO





F20240620133050




BLK: 4,SNR1: 1.3292 ,SNR2: 4.1463




K20240620133046



BLK: 4,SNR1: 6.6236 ,SNR2: 26.897




0732+33 2024/06/20 4.54UT FUJI -KISO







T20240620133850




BLK:12,SNR1: 0.41785 ,SNR2: 2.9234




F20240620133852




BLK:12,SNR1: 1.7102 ,SNR2: 3.8676




0741-06 2024/06/20 4.68UT TOYOKAWA-FUJI




T20240620133850




BLK:20,SNR1: 0.40716 ,SNR2: 2.7408




K20240620133847




BLK:20,SNR1: 0.42719 ,SNR2: 1.7901




0741-06 2024/06/20 4.68UT TOYOKAWA-KISO





F20240620133852




BLK:11,SNR1: 1.7288 ,SNR2: 4.3121




K20240620133847





BLK:11,SNR1: 0.19603 ,SNR2: 0.73391




0741-06 2024/06/20 4.68UT FUJI -KISO





T20240620134835




BLK:14,SNR1: 10.429 ,SNR2: 12.798




F20240620134837







BLK:14,SNR1: 2.3271 ,SNR2: 6.1586




0752-200 2024/06/20 4.84UT TOYOKAWA-FUJI







0752-200 2024/06/20 4.84UT TOYOKAWA-KISO



F20240620134837





BLK:21,SNR1: 2.2540 ,SNR2: 5.9361





0752-200 2024/06/20 4.84UT FUJI -KISO



K20240620134832




BLK:21,SNR1: 4.1606 ,SNR2: 17.467





T20240620135609




BLK:11,SNR1: 0.23728 ,SNR2: 0.70666




F20240620135611





BLK:11,SNR1: 0.55365 ,SNR2: 2.4688




3C190 2024/06/20 4.96UT TOYOKAWA-FUJI





T20240620135609




BLK: 6,SNR1: 0.19368 ,SNR2: 0.66521




K20240620135607



BLK: 6,SNR1: 0.40975 ,SNR2: 3.2262




3C190 2024/06/20 4.96UT TOYOKAWA-KISO








F20240620135611




BLK: 5,SNR1: 0.77861 ,SNR2: 3.0278




K20240620135607





BLK: 5,SNR1: 0.41921 ,SNR2: 2.2831




3C190 2024/06/20 4.96UT FUJI -KISO



T20240620140834





BLK: 8,SNR1: 0.44742 ,SNR2: 2.6347




Frequency (Hz)

F20240620140836




BLK: 8,SNR1: 0.64750E-01,SNR2: 0.90229





Frequency (Hz)


3C196 2024/06/20 5.17UT TOYOKAWA-FUJI



T20240620140834





BLK: 7,SNR1: 0.22066 ,SNR2: 1.3753




Frequency (Hz)

K20240620140831




BLK: 7,SNR1: 0.89386 ,SNR2: 3.6393




Frequency (Hz)


3C196 2024/06/20 5.17UT TOYOKAWA-KISO




F20240620140836




BLK: 7,SNR1: 0.36977 ,SNR2: 1.7072




K20240620140831





BLK: 7,SNR1: 0.20429 ,SNR2: 0.53815




3C196 2024/06/20 5.17UT FUJI -KISO




T20240620141943




BLK:15,SNR1: 0.27802 ,SNR2: 1.0516




F20240620141945





BLK:15,SNR1: 0.27068 ,SNR2: 1.1801




0821+394 2024/06/20 5.36UT TOYOKAWA-FUJI





T20240620141943




BLK:10,SNR1: 0.38952 ,SNR2: 1.0506




K20240620141941




BLK:10,SNR1: 0.36122 ,SNR2: 1.1036




0821+394 2024/06/20 5.36UT TOYOKAWA-KISO





F20240620141945




BLK: 9,SNR1: 0.13218 ,SNR2: 1.0346




K20240620141941





BLK: 9,SNR1: 0.37720 ,SNR2: 2.1300




0821+394 2024/06/20 5.36UT FUJI -KISO





T20240620143124




BLK: 7,SNR1: 0.61247 ,SNR2: 6.3886




F20240620143126



BLK: 7,SNR1: 0.35834 ,SNR2: 2.4975





0834-19 2024/06/20 5.55UT TOYOKAWA-FUJI








T20240620143124




BLK:15,SNR1: 0.30160 ,SNR2: 3.1852




K20240620143121





BLK:15,SNR1: 0.47126 ,SNR2: 2.5223




0834-19 2024/06/20 5.55UT TOYOKAWA-KISO





F20240620143126




BLK: 7,SNR1: 0.52106 ,SNR2: 1.7802




K20240620143121




BLK: 7,SNR1: 0.16568 ,SNR2: 1.0398




0834-19 2024/06/20 5.55UT FUJI -KISO




T20240620143629




BLK: 8,SNR1: 2.7443 ,SNR2: 10.627




F20240620143631





BLK: 8,SNR1: 0.10279 ,SNR2: 2.1407




0839-071 2024/06/20 5.64UT TOYOKAWA-FUJI





T20240620143629




BLK:12,SNR1: 4.5095 ,SNR2: 31.333




K20240620143626




BLK:12,SNR1: 2.5195 ,SNR2: 10.513




0839-071 2024/06/20 5.64UT TOYOKAWA-KISO



F20240620143631





BLK:11,SNR1:-0.76972E-01,SNR2: 0.70206




Frequency (Hz)

K20240620143626




BLK:11,SNR1: 2.4194 ,SNR2: 10.459





Frequency (Hz)


0839-071 2024/06/20 5.64UT FUJI -KISO




T20240620144730




BLK: 4,SNR1: 0.58841 ,SNR2: 1.4623




F20240620144732





BLK: 4,SNR1: 1.0098 ,SNR2: 3.3973




3C208 2024/06/20 5.82UT TOYOKAWA-FUJI





T20240620144730




BLK: 6,SNR1: 0.16485 ,SNR2: 0.47398




K20240620144728





BLK: 6,SNR1: 1.1382 ,SNR2: 5.2332




3C208 2024/06/20 5.82UT TOYOKAWA-KISO





F20240620144732




BLK: 5,SNR1: 0.21221 ,SNR2: 1.4498




K20240620144728



BLK: 5,SNR1: 0.25885E-02,SNR2: 0.40499





3C208 2024/06/20 5.82UT FUJI -KISO







T20240620150411




BLK: 9,SNR1: 0.10506 ,SNR2: 0.57918




F20240620150413





BLK: 9,SNR1: 1.3487 ,SNR2: 5.0179




3C216 2024/06/20 6.10UT TOYOKAWA-FUJI




T20240620150411




BLK: 8,SNR1: 0.21153 ,SNR2: 2.0517




K20240620150408




BLK: 8,SNR1: 0.63063 ,SNR2: 3.2179




3C216 2024/06/20 6.10UT TOYOKAWA-KISO



F20240620150413





BLK:14,SNR1: 1.2660 ,SNR2: 2.3473




Frequency (Hz)

K20240620150408




BLK:14,SNR1: 0.53610 ,SNR2: 2.3902





Frequency (Hz)


3C216 2024/06/20 6.10UT FUJI -KISO




T20240620151623




BLK:18,SNR1: 1.1550 ,SNR2: 2.1674




F20240620151625





BLK:18,SNR1: 1.9645 ,SNR2: 4.6686




0919-142 2024/06/20 6.30UT TOYOKAWA-FUJI





T20240620151623




BLK:13,SNR1: 2.3648 ,SNR2: 5.5471




K20240620151621




BLK:13,SNR1: 0.44420 ,SNR2: 1.9260




0919-142 2024/06/20 6.30UT TOYOKAWA-KISO



F20240620151625





BLK: 9,SNR1: 2.5739 ,SNR2: 6.4513




Frequency (Hz)

K20240620151621




BLK: 9,SNR1: 0.85913 ,SNR2: 3.8038





Frequency (Hz)


0919-142 2024/06/20 6.30UT FUJI -KISO





T20240620152302




BLK:21,SNR1: 0.61457 ,SNR2: 2.1572




F20240620152304





BLK:21,SNR1: 2.8534 ,SNR2: 12.711




0926+117 2024/06/20 6.41UT TOYOKAWA-FUJI





T20240620152302




BLK:13,SNR1: 1.3323 ,SNR2: 4.7081




K20240620152259



BLK:13,SNR1: 8.4706 ,SNR2: 21.220





0926+117 2024/06/20 6.41UT TOYOKAWA-KISO








F20240620152304




BLK:24,SNR1: 2.8744 ,SNR2: 12.796




K20240620152259





BLK:24,SNR1: 2.8994 ,SNR2: 13.739




0926+117 2024/06/20 6.41UT FUJI -KISO




T20240620153046




BLK: 6,SNR1: 0.10588 ,SNR2: 0.49620




F20240620153048





BLK: 6,SNR1: 3.3036 ,SNR2: 14.090




3C222 2024/06/20 6.54UT TOYOKAWA-FUJI




T20240620153046




BLK:11,SNR1: 0.17053 ,SNR2: 0.74192




K20240620153043




BLK:11,SNR1: 1.0134 ,SNR2: 5.4250




3C222 2024/06/20 6.54UT TOYOKAWA-KISO



F20240620153048





BLK: 8,SNR1: 2.8658 ,SNR2: 12.346




Frequency (Hz)

K20240620153043




BLK: 8,SNR1: 1.1408 ,SNR2: 5.3734





Frequency (Hz)


3C222 2024/06/20 6.54UT FUJI -KISO



T20240620153746




BLK:19,SNR1: 0.71791 ,SNR2: 3.1830




Frequency (Hz)

F20240620153748




BLK:19,SNR1: 4.2318 ,SNR2: 10.431





Frequency (Hz)


0941-08 2024/06/20 6.66UT TOYOKAWA-FUJI



T20240620153746




BLK:22,SNR1: 0.70945 ,SNR2: 2.8097




Frequency (Hz)

K20240620153743




BLK:22,SNR1: 6.3025 ,SNR2: 15.592




Frequency (Hz)


0941-08 2024/06/20 6.66UT TOYOKAWA-KISO



F20240620153748




BLK:22,SNR1: 4.2846 ,SNR2: 10.524




Frequency (Hz)

K20240620153743




BLK:22,SNR1: 9.4382 ,SNR2: 16.719





Frequency (Hz)


0941-08 2024/06/20 6.66UT FUJI -KISO





T20240620154608




BLK:22,SNR1: 8.4414 ,SNR2: 21.028




F20240620154610



BLK:22,SNR1: 17.058 ,SNR2: 23.651





3C230 2024/06/20 6.80UT TOYOKAWA-FUJI






T20240620154608





BLK:28,SNR1: 8.0154 ,SNR2: 19.964




Frequency (Hz)

K20240620154605




BLK:28,SNR1: 8.1614 ,SNR2: 14.609





Frequency (Hz)


3C230 2024/06/20 6.80UT TOYOKAWA-KISO



F20240620154610





BLK:26,SNR1: 17.010 ,SNR2: 23.584




Frequency (Hz)

K20240620154605




BLK:26,SNR1: 8.2566 ,SNR2: 14.779





Frequency (Hz)


3C230 2024/06/20 6.80UT FUJI -KISO



T20240620160209





BLK:19,SNR1: 0.76425 ,SNR2: 2.9315




Frequency (Hz)

F20240620160211




BLK:19,SNR1: 4.1864 ,SNR2: 10.260





Frequency (Hz)


3C237 2024/06/20 7.06UT TOYOKAWA-FUJI



T20240620160209





BLK:18,SNR1: 0.78376 ,SNR2: 2.0066




Frequency (Hz)

K20240620160207




BLK:18,SNR1: 2.1626 ,SNR2: 8.5775





Frequency (Hz)


3C237 2024/06/20 7.06UT TOYOKAWA-KISO



F20240620160211





BLK:19,SNR1: 3.6227 ,SNR2: 8.8998




Frequency (Hz)

K20240620160207




BLK:19,SNR1: 2.0540 ,SNR2: 8.1415





Frequency (Hz)


3C237 2024/06/20 7.06UT FUJI -KISO



T20240620160825




BLK:21,SNR1: 2.4473 ,SNR2: 11.739




Frequency (Hz)

F20240620160827




BLK:21,SNR1: 10.666 ,SNR2: 18.868





Frequency (Hz)


1011+110 2024/06/20 7.17UT TOYOKAWA-FUJI



T20240620160825





BLK:23,SNR1: 2.7017 ,SNR2: 12.707




Frequency (Hz)

K20240620160822




BLK:23,SNR1: 8.5485 ,SNR2: 21.464




Frequency (Hz)


1011+110 2024/06/20 7.17UT TOYOKAWA-KISO



F20240620160827





BLK:26,SNR1: 10.387 ,SNR2: 18.370




Frequency (Hz)

K20240620160822




BLK:26,SNR1: 8.5034 ,SNR2: 21.352





Frequency (Hz)

1011+110 2024/06/20 7.17UT FUJI -KISO






T20240620161606





BLK: 6,SNR1: 0.17049 ,SNR2: 1.7854




Frequency (Hz)

F20240620161608




BLK: 6,SNR1: 0.28631 ,SNR2: 2.9325





Frequency (Hz)


3C241 2024/06/20 7.30UT TOYOKAWA-FUJI



T20240620161606





BLK: 3,SNR1: 0.10171 ,SNR2: 2.1330




Frequency (Hz)

K20240620161603




BLK: 3,SNR1: 0.84811 ,SNR2: 3.3751




Frequency (Hz)


3C241 2024/06/20 7.30UT TOYOKAWA-KISO



F20240620161608





BLK: 6,SNR1: 0.22779 ,SNR2: 2.5457




Frequency (Hz)

K20240620161603




BLK: 6,SNR1: 0.89325E-01,SNR2: 0.91701





Frequency (Hz)


3C241 2024/06/20 7.30UT FUJI -KISO



T20240620162735





BLK:11,SNR1: 0.20619 ,SNR2: 1.7478




Frequency (Hz)

F20240620162737




BLK:11,SNR1: 0.54064 ,SNR2: 4.5081




Frequency (Hz)


1031-11 2024/06/20 7.49UT TOYOKAWA-FUJI



T20240620162735





BLK:10,SNR1: 0.20796 ,SNR2: 1.1195




Frequency (Hz)

K20240620162733








BLK:10,SNR1: 0.71059 ,SNR2: 3.8233




Frequency (Hz)

1031-11 2024/06/20 7.49UT TOYOKAWA-KISO







1031-11 2024/06/20 7.49UT FUJI -KISO



T20240620163209




BLK:24,SNR1: 12.546 ,SNR2: 22.040




Frequency (Hz)

F20240620163211




BLK:24,SNR1: 7.2933 ,SNR2: 18.197




Frequency (Hz)


1035-058 2024/06/20 7.56UT TOYOKAWA-FUJI



T20240620163209





BLK:25,SNR1: 7.2465 ,SNR2: 19.531




Frequency (Hz)

K20240620163207




BLK:25,SNR1: 2.8371 ,SNR2: 13.253





Frequency (Hz)

1035-058 2024/06/20 7.56UT TOYOKAWA-KISO






F20240620163211





BLK:22,SNR1: 7.6540 ,SNR2: 19.078




Frequency (Hz)

K20240620163207




BLK:22,SNR1: 2.8683 ,SNR2: 13.373





Frequency (Hz)


1035-058 2024/06/20 7.56UT FUJI -KISO



T20240620164122




BLK:21,SNR1: 2.2501 ,SNR2: 4.3929




Frequency (Hz)

F20240620164124




BLK:21,SNR1: 1.0829 ,SNR2: 5.2209





Frequency (Hz)


1044-008 2024/06/20 7.72UT TOYOKAWA-FUJI



T20240620164122





BLK:32,SNR1: 1.4366 ,SNR2: 5.5684




Frequency (Hz)

K20240620164120




BLK:32,SNR1: 7.1259 ,SNR2: 17.917




Frequency (Hz)


1044-008 2024/06/20 7.72UT TOYOKAWA-KISO



F20240620164124




BLK:23,SNR1: 1.0551 ,SNR2: 5.2523




Frequency (Hz)

K20240620164120





BLK:23,SNR1: 2.4067 ,SNR2: 11.736





Frequency (Hz)

1044-008 2024/06/20 7.72UT FUJI -KISO







BLK:16,SNR1: 2.8674 ,SNR2: 12.860







BLK:16,SNR1: 1.2949 ,SNR2: 11.131




1055+01 2024/06/20 7.90UT TOYOKAWA-FUJI







1055+01 2024/06/20 7.90UT TOYOKAWA-KISO



F20240620165228




BLK:16,SNR1: 1.2575 ,SNR2: 9.8575




Frequency (Hz)

K20240620165224





BLK:16,SNR1: 1.5517 ,SNR2: 5.9989





Frequency (Hz)

1055+01 2024/06/20 7.90UT FUJI -KISO







BLK:23,SNR1: 7.0766 ,SNR2: 12.033



BLK:23,SNR1: 6.7594 ,SNR2: 19.223





1107+109 2024/06/20 8.09UT TOYOKAWA-FUJI






T20240620170344





BLK:26,SNR1: 4.1498 ,SNR2: 10.596




Frequency (Hz)

K20240620170341





BLK:26,SNR1: 7.2839 ,SNR2: 21.271





Frequency (Hz)

1107+109 2024/06/20 8.09UT TOYOKAWA-KISO







BLK:24,SNR1: 6.8199 ,SNR2: 19.384





BLK:24,SNR1: 7.3270 ,SNR2: 21.397




1107+109 2024/06/20 8.09UT Fuji -KISO



T20240620172728




BLK:27,SNR1: 2.7163 ,SNR2: 12.175




Frequency (Hz)

F20240620172730




BLK:27,SNR1: 6.0807 ,SNR2: 15.080





Frequency (Hz)


1130+335 2024/06/20 8.49UT TOYOKAWA-FUJI



T20240620172728




BLK:30,SNR1: 2.7197 ,SNR2: 12.188




Frequency (Hz)

K20240620172725




BLK:30,SNR1: 3.6228 ,SNR2: 9.3609





Frequency (Hz)


1130+335 2024/06/20 8.49UT TOYOKAWA-KISO



F20240620172730




BLK:29,SNR1: 5.7929 ,SNR2: 14.374




Frequency (Hz)

K20240620172725




BLK:29,SNR1: 3.5887 ,SNR2: 9.3845




Frequency (Hz)


1130+335 2024/06/20 8.49UT FUJI -KISO



T20240620180300




BLK:23,SNR1: 1.6949 ,SNR2: 5.7904




Frequency (Hz)

F20240620180302




BLK:23,SNR1: 5.1354 ,SNR2: 12.737




Frequency (Hz)


1206+439 2024/06/20 9.08UT TOYOKAWA-FUJI



T20240620180300





BLK:19,SNR1: 1.7537 ,SNR2: 6.2269




Frequency (Hz)

K20240620180257




BLK:19,SNR1: 2.7812 ,SNR2: 12.957





Frequency (Hz)


1206+439 2024/06/20 9.08UT TOYOKAWA-KISO



F20240620180302





BLK:28,SNR1: 4.7893 ,SNR2: 11.862




Frequency (Hz)

K20240620180257



BLK:28,SNR1: 2.7249 ,SNR2: 12.685



Frequency (Hz)

1206+439 2024/06/20 9.08UT FUJI -KISO

