




T20240622052239




BLK: 7,SNR1: 3.2144 ,SNR2: 14.034




Frequency (Hz)

F20240622052241




BLK: 7,SNR1: 2.0130 ,SNR2: 8.3552





Frequency (Hz)


2332+489 2024/06/21 20.41UT TOYOKAWA-FUJI



T20240622052239





BLK:10,SNR1: 4.1869 ,SNR2: 17.557




Frequency (Hz)

K20240622052237




BLK:10,SNR1: 4.0348 ,SNR2: 16.968




Frequency (Hz)

2332+489 2024/06/21 20.41UT TOYOKAWA-KISO







F20240622052241




BLK:16,SNR1: 2.9561 ,SNR2: 5.8806




K20240622052237





BLK:16,SNR1: 3.9570 ,SNR2: 16.653




2332+489 2024/06/21 20.41UT FUJI -KISO





T20240622054631




No.Good Data




F20240622054633





No.Good Data




2356+437 2024/06/21 20.80UT TOYOKAWA-FUJI



T20240622054631





BLK: 2,SNR1: 0.44236E-01,SNR2: 0.42527




Frequency (Hz)

K20240622054628




BLK: 2,SNR1:-0.74182E-01,SNR2: 0.0000





Frequency (Hz)


2356+437 2024/06/21 20.80UT TOYOKAWA-KISO



F20240622054633





BLK: 1,SNR1: 0.77115E-01,SNR2: 1.4628




Frequency (Hz)

K20240622054628




BLK: 1,SNR1: 0.32583 ,SNR2: 1.3821




Frequency (Hz)


2356+437 2024/06/21 20.80UT FUJI -KISO



T20240622060139




BLK: 2,SNR1: 0.33644 ,SNR2: 0.54910




Frequency (Hz)

F20240622060141




BLK: 2,SNR1:-0.76018E-01,SNR2: 1.8208




Frequency (Hz)


0011+344 2024/06/21 21.06UT TOYOKAWA-FUJI



T20240622060139




BLK: 3,SNR1:-0.42205E-01,SNR2: 0.17647




Frequency (Hz)

K20240622060137




BLK: 3,SNR1: 0.50695 ,SNR2: 2.5074




Frequency (Hz)


0011+344 2024/06/21 21.06UT TOYOKAWA-KISO



F20240622060141




BLK: 1,SNR1: 1.7586 ,SNR2: 6.7377




Frequency (Hz)

K20240622060137




BLK: 1,SNR1:-0.11102 ,SNR2: 0.52825





Frequency (Hz)


0011+344 2024/06/21 21.06UT FUJI -KISO



T20240622060914





BLK: 4,SNR1: 29.767 ,SNR2: 201.46




Frequency (Hz)

F20240622060916




BLK: 4,SNR1: 0.24424 ,SNR2: 1.1598





Frequency (Hz)

0018+241 2024/06/21 21.18UT TOYOKAWA-FUJI






T20240622060914





BLK: 9,SNR1: 32.519 ,SNR2: 143.45




Frequency (Hz)

K20240622060912




BLK: 9,SNR1: 0.29328 ,SNR2: 1.1162





Frequency (Hz)


0018+241 2024/06/21 21.18UT TOYOKAWA-KISO



F20240622060916





BLK: 2,SNR1: 0.72079 ,SNR2: 1.9809




Frequency (Hz)

K20240622060912




BLK: 2,SNR1:-0.92518E-01,SNR2: 0.23808





Frequency (Hz)


0018+241 2024/06/21 21.18UT FUJI -KISO



T20240622062030





BLK: 7,SNR1: 1.0822 ,SNR2: 5.1432




Frequency (Hz)

3C12 2024/06/21 21.37UT TOYOKAWA-FUJI


F20240622062032




BLK: 7,SNR1: 0.48857 ,SNR2: 2.4314




Frequency (Hz)



T20240622062030





BLK:10,SNR1: 3.7602 ,SNR2: 14.951




Frequency (Hz)

3C12 2024/06/21 21.37UT TOYOKAWA-KISO


K20240622062028





BLK:10,SNR1:-0.31705 ,SNR2: 0.34345




Frequency (Hz)



F20240622062032





BLK: 7,SNR1: 0.42776 ,SNR2: 2.1153




Frequency (Hz)

3C12 2024/06/21 21.37UT FUJI -KISO


K20240622062028





BLK: 7,SNR1: 0.10937 ,SNR2: 2.1543




Frequency (Hz)



T20240622062848




BLK: 2,SNR1: 0.13895 ,SNR2: 0.71582




Frequency (Hz)

F20240622062850




BLK: 2,SNR1:-0.24210 ,SNR2: 0.27052




Frequency (Hz)


0038+328 2024/06/21 21.51UT TOYOKAWA-FUJI



T20240622062848




BLK: 3,SNR1: 0.37101E-01,SNR2: 0.35913




Frequency (Hz)

K20240622062845




BLK: 3,SNR1: 0.82386E-01,SNR2: 2.4290





Frequency (Hz)


0038+328 2024/06/21 21.51UT TOYOKAWA-KISO



F20240622062850




BLK: 4,SNR1: 0.22379 ,SNR2: 3.9812




Frequency (Hz)

K20240622062845




BLK: 4,SNR1: -0.99476E-01,SNR2: 0.45987





Frequency (Hz)

0038+328 2024/06/21 21.51UT FUJI -KISO






T20240622064652





BLK: 1,SNR1:-0.18032E-01,SNR2: 0.24055




Frequency (Hz)

0056-00 2024/06/21 21.81UT TOYOKAWA-FUJI


F20240622064654





BLK: 1,SNR1: 1.0131 ,SNR2: 4.0416




Frequency (Hz)



T20240622064652





BLK: 1,SNR1: 0.41558 ,SNR2: 0.86788




Frequency (Hz)

K20240622064649




BLK: 1,SNR1: 3.2398 ,SNR2: 7.7247




Frequency (Hz)


0056-00 2024/06/21 21.81UT TOYOKAWA-KISO



F20240622064654





BLK: 2,SNR1: 1.3573 ,SNR2: 2.6141




Frequency (Hz)

K20240622064649




BLK: 2,SNR1: 1.2237 ,SNR2: 5.1689





Frequency (Hz)


0056-00 2024/06/21 21.81UT FUJI -KISO



T20240622065634





BLK: 5,SNR1: 2.8070 ,SNR2: 12.493





0106+01 2024/06/21 21.97UT TOYOKAWA-FUJI



F20240622065636




BLK: 5,SNR1: 0.13258 ,SNR2: 3.4434



T20240622065634





BLK: 6,SNR1: 2.6818 ,SNR2: 11.987





0106+01 2024/06/21 21.97UT TOYOKAWA-KISO


K20240622065631




BLK: 6,SNR1: 1.0514 ,SNR2: 2.7644



F20240622065636




BLK: 3,SNR1:-0.97870E-01,SNR2: 0.35765E-01




Frequency (Hz)

K20240622065631




BLK: 3,SNR1: 0.12915 ,SNR2: 0.83978





Frequency (Hz)


0106+01 2024/06/21 21.97UT FUJI -KISO



T20240622070557





BLK: 5,SNR1: 0.43586 ,SNR2: 2.2945




Frequency (Hz)

F20240622070559




BLK: 5,SNR1: 0.99679E-01,SNR2: 2.1257





Frequency (Hz)


0115-01 2024/06/21 22.13UT TOYOKAWA-FUJI



T20240622070557





BLK:14,SNR1: 0.43586 ,SNR2: 1.9466




Frequency (Hz)

K20240622070554




BLK:14,SNR1: 0.97912 ,SNR2: 3.5420





Frequency (Hz)

0115-01 2024/06/21 22.13UT TOYOKAWA-KISO








F20240622070559




BLK: 3,SNR1: 1.4117 ,SNR2: 3.6253




K20240622070554





BLK: 3,SNR1: 0.88478 ,SNR2: 3.1323




0115-01 2024/06/21 22.13UT FUJI -KISO



T20240622071856




BLK: 4,SNR1: 0.74789 ,SNR2: 3.2309




Frequency (Hz)

F20240622071858




BLK: 4,SNR1: 0.85841E-01,SNR2: 1.0976





Frequency (Hz)


0128+03 2024/06/21 22.34UT TOYOKAWA-FUJI



T20240622071856




BLK: 8,SNR1: 1.5987 ,SNR2: 7.4020




Frequency (Hz)

K20240622071853




BLK: 8,SNR1: 0.73128 ,SNR2: 5.1074





Frequency (Hz)


0128+03 2024/06/21 22.34UT TOYOKAWA-KISO



F20240622071858




BLK: 5,SNR1: 0.14977 ,SNR2: 1.5735




Frequency (Hz)

K20240622071853




BLK: 5,SNR1: 0.56930 ,SNR2: 2.3940




Frequency (Hz)


0128+03 2024/06/21 22.34UT FUJI -KISO



T20240622072530




BLK:18,SNR1: 0.76115 ,SNR2: 5.8897




Frequency (Hz)

3C48 2024/06/21 22.45UT TOYOKAWA-FUJI


F20240622072532




BLK:18,SNR1: 0.18226 ,SNR2: 2.5184




Frequency (Hz)



T20240622072530




BLK:21,SNR1: 0.78616 ,SNR2: 9.0467





3C48 2024/06/21 22.45UT TOYOKAWA-KISO


K20240622072527




BLK:21,SNR1: 0.57410 ,SNR2: 1.9223



F20240622072532



BLK: 9,SNR1: 0.35247 ,SNR2: 2.2429




Frequency (Hz)


3C48

2024/06/21 22.45UT FUJI -KISO


K20240622072527





BLK: 9,SNR1: 4.6838 ,SNR2: 11.774




Frequency (Hz)



T20240622074515




BLK: 3,SNR1: 0.72816E-01,SNR2: 4.8777




Frequency (Hz)

F20240622074517




BLK: 3,SNR1: 0.16040E-01,SNR2: 0.81330





Frequency (Hz)

0155-109 2024/06/21 22.78UT TOYOKAWA-FUJI






T20240622074515





BLK: 3,SNR1: 0.51189E-01,SNR2: 1.0631




Frequency (Hz)

K20240622074512




BLK: 3,SNR1: 0.55595 ,SNR2: 2.9631





Frequency (Hz)


0155-109 2024/06/21 22.78UT TOYOKAWA-KISO



F20240622074517





BLK: 3,SNR1:-0.17879 ,SNR2: 1.5789




Frequency (Hz)

K20240622074512




BLK: 3,SNR1: 0.42798 ,SNR2: 2.4579





Frequency (Hz)


0155-109 2024/06/21 22.78UT FUJI -KISO



T20240622075222





BLK:18,SNR1: 3.0813 ,SNR2: 13.581




Frequency (Hz)

0202+15 2024/06/21 22.90UT TOYOKAWA-FUJI


F20240622075224





BLK:18,SNR1: 1.3711 ,SNR2: 6.6516




Frequency (Hz)



T20240622075222





BLK:19,SNR1: 3.0773 ,SNR2: 13.566




Frequency (Hz)

0202+15 2024/06/21 22.90UT TOYOKAWA-KISO


K20240622075219





BLK:19,SNR1: 4.3581 ,SNR2: 14.276




Frequency (Hz)



F20240622075224





BLK:20,SNR1: 1.4913 ,SNR2: 7.1512




Frequency (Hz)

K20240622075219




BLK:20,SNR1: 4.2203 ,SNR2: 11.082





Frequency (Hz)


0202+15 2024/06/21 22.90UT FUJI -KISO



T20240622080412





BLK:11,SNR1: 2.7349 ,SNR2: 12.882





0213+178 2024/06/21 23.10UT TOYOKAWA-FUJI



F20240622080414




BLK:11,SNR1: 2.8761 ,SNR2: 6.9994



T20240622080412





BLK:14,SNR1: 2.7046 ,SNR2: 12.763





0213+178 2024/06/21 23.10UT TOYOKAWA-KISO



K20240622080409




BLK:14,SNR1: 2.9092 ,SNR2: 7.4372





F20240622080414




BLK:19,SNR1: 6.6070 ,SNR2: 18.910




K20240622080409



BLK:19,SNR1: 5.9679 ,SNR2: 17.316





0213+178 2024/06/21 23.10UT FUJI -KISO






T20240622081154





BLK:17,SNR1: 2.9869 ,SNR2: 13.873





3C67 2024/06/21 23.23UT TOYOKAWA-FUJI



F20240622081156




BLK:17,SNR1: 4.7636 ,SNR2: 11.210



T20240622081154





BLK:23,SNR1: 2.9852 ,SNR2: 13.866




Frequency (Hz)

3C67 2024/06/21 23.23UT TOYOKAWA-KISO


K20240622081151




BLK:23,SNR1: 2.6315 ,SNR2: 12.681




Frequency (Hz)



F20240622081156





BLK:15,SNR1: 5.1503 ,SNR2: 12.110





3C67 2024/06/21 23.23UT FUJI -KISO



K20240622081151




BLK:15,SNR1: 2.6379 ,SNR2: 12.712



T20240622083010



BLK: 5,SNR1:-0.16131E-01,SNR2: 0.27738





Frequency (Hz)


3C71

2024/06/21 23.53UT TOYOKAWA-FUJI


F20240622083012





BLK: 5,SNR1:-0.11883 ,SNR2: 1.1960




Frequency (Hz)



T20240622083010





BLK: 6,SNR1: 0.24646E-01,SNR2: 0.32296





3C71 2024/06/21 23.53UT TOYOKAWA-KISO


K20240622083007




BLK: 6,SNR1: 0.61473 ,SNR2: 4.3714



F20240622083012



BLK: 2,SNR1:-0.35395E-01,SNR2: 0.62567





Frequency (Hz)


3C71

2024/06/21 23.53UT FUJI -KISO


K20240622083007





BLK: 2,SNR1: 0.24549 ,SNR2: 1.9599




Frequency (Hz)



T20240622084924





BLK:19,SNR1: 1.5213 ,SNR2: 4.4182





0258+350 2024/06/21 23.85UT TOYOKAWA-FUJI



F20240622084926




BLK:19,SNR1: 3.3513 ,SNR2: 15.263





T20240622084924




BLK:21,SNR1: 1.4504 ,SNR2: 4.1963




K20240622084921



BLK:21,SNR1: 7.6196 ,SNR2: 19.153





0258+350 2024/06/21 23.85UT TOYOKAWA-KISO








F20240622084926




BLK:20,SNR1: 3.4963 ,SNR2: 15.821




K20240622084921





BLK:20,SNR1: 7.8038 ,SNR2: 19.611




0258+350 2024/06/21 23.85UT FUJI -KISO



T20240622090734





BLK:15,SNR1: 2.5045 ,SNR2: 7.6664





3C84 2024/06/22 0.15UT TOYOKAWA-FUJI



F20240622090736




BLK:15,SNR1: 1.9099 ,SNR2: 9.2177



T20240622090734




BLK:20,SNR1: 2.5284 ,SNR2: 8.1857





3C84 2024/06/22 0.15UT TOYOKAWA-KISO


K20240622090731




BLK:20,SNR1: 10.143 ,SNR2: 17.973




F20240622090736




BLK:23,SNR1: 1.5587 ,SNR2: 7.7002




K20240622090731




BLK:23,SNR1: 9.4929 ,SNR2: 16.831




3C84 2024/06/22 0.15UT FUJI -KISO





T20240622091450




BLK: 6,SNR1: 0.48224E-01,SNR2: 2.1660




F20240622091452





BLK: 6,SNR1: 0.43298 ,SNR2: 1.7156




0324+119 2024/06/22 0.28UT TOYOKAWA-FUJI



T20240622091450





BLK: 2,SNR1: 0.27461 ,SNR2: 1.6497




Frequency (Hz)

0324+119 2024/06/22 0.28UT TOYOKAWA-KISO


K20240622091447





BLK: 2,SNR1: 0.35810 ,SNR2: 1.3660




Frequency (Hz)





F20240622091452




BLK: 4,SNR1: 0.42437 ,SNR2: 1.8088




K20240622091447





BLK: 4,SNR1: 1.4779 ,SNR2: 6.2305




0324+119 2024/06/22 0.28UT FUJI -KISO



T20240622092406




BLK: 4,SNR1: 0.70678E-01,SNR2: 0.55453





0333+32 2024/06/22 0.43UT TOYOKAWA-FUJI

F20240622092408





BLK: 4,SNR1: 0.68005 ,SNR2: 3.9999






T20240622092406





BLK: 9,SNR1:-0.16590E-01,SNR2: 0.47738




0333+32 2024/06/22 0.43UT TOYOKAWA-KISO


K20240622092403





BLK: 9,SNR1: 1.2126 ,SNR2: 4.9396




Frequency (Hz)





F20240622092408




BLK:20,SNR1: 1.1974 ,SNR2: 3.7066




K20240622092403





BLK:20,SNR1: 11.492 ,SNR2: 18.069




0333+32 2024/06/22 0.43UT FUJI -KISO



T20240622093708




BLK: 2,SNR1:-0.45882E-02,SNR2: 0.87402




Frequency (Hz)

0347+05 2024/06/22 0.65UT TOYOKAWA-FUJI


F20240622093710





BLK: 2,SNR1: 0.31257 ,SNR2: 2.2030




Frequency (Hz)



T20240622093708





BLK: 2,SNR1:-0.16022 ,SNR2: 0.54566




Frequency (Hz)

0347+05 2024/06/22 0.65UT TOYOKAWA-KISO


K20240622093705




BLK: 2,SNR1:-0.67747E-02,SNR2: 0.34201




Frequency (Hz)




F20240622093710




BLK: 5,SNR1: 0.46634 ,SNR2: 2.7897




K20240622093705




BLK: 5,SNR1: 0.17001 ,SNR2: 0.54258




0347+05 2024/06/22 0.65UT FUJI -KISO





T20240622095243




BLK:18,SNR1: 0.44499 ,SNR2: 2.0146




F20240622095245





BLK:18,SNR1: 0.83911 ,SNR2: 2.1569




0403-132 2024/06/22 0.91UT TOYOKAWA-FUJI



T20240622095243





BLK:25,SNR1: 0.43684 ,SNR2: 1.8410





0403-132 2024/06/22 0.91UT TOYOKAWA-KISO


K20240622095240




BLK:25,SNR1: 1.9294 ,SNR2: 8.3477





F20240622095245




BLK:21,SNR1: 1.4523 ,SNR2: 3.5626




K20240622095240



BLK:21,SNR1: 2.3999 ,SNR2: 10.146





0403-132 2024/06/22 0.91UT FUJI -KISO








T20240622100153




BLK: 4,SNR1: 0.56745E-01,SNR2: 0.52777




F20240622100155





BLK: 4,SNR1: 0.45993 ,SNR2: 1.9063




0411+05 2024/06/22 1.06UT TOYOKAWA-FUJI



T20240622100153





BLK: 3,SNR1: 0.19069E-01,SNR2: 0.42133




0411+05 2024/06/22 1.06UT TOYOKAWA-KISO


K20240622100150




BLK: 3,SNR1: 2.0991 ,SNR2: 13.268




Frequency (Hz)




F20240622100155




BLK: 2,SNR1:-0.15971E-01,SNR2: 2.9621




K20240622100150




BLK: 2,SNR1: 0.71692E-01,SNR2: 1.0004




0411+05 2024/06/22 1.06UT FUJI -KISO




T20240622100847




BLK:11,SNR1: 0.57291 ,SNR2: 2.5414




F20240622100849





BLK:11,SNR1: 4.5716 ,SNR2: 12.194




0418+236 2024/06/22 1.17UT TOYOKAWA-FUJI



T20240622100847





BLK: 9,SNR1: 1.0465 ,SNR2: 2.8430









0418+236 2024/06/22 1.17UT TOYOKAWA-KISO

K20240622100844




BLK: 9,SNR1: 8.6630 ,SNR2: 16.959







0418+236 2024/06/22 1.17UT FUJI -KISO



T20240622102015




BLK:14,SNR1: 5.2014 ,SNR2: 17.461





3C119 2024/06/22 1.37UT TOYOKAWA-FUJI


F20240622102017




BLK:14,SNR1: 1.2925 ,SNR2: 4.4950




T20240622102015




BLK:16,SNR1: 4.5709 ,SNR2: 16.150




K20240622102012



BLK:16,SNR1: 1.5162 ,SNR2: 5.9007





3C119 2024/06/22 1.37UT TOYOKAWA-KISO






F20240622102017




BLK:26,SNR1: 0.99115 ,SNR2: 3.4982




Frequency (Hz)

3C119 2024/06/22 1.37UT FUJI -KISO


K20240622102012




BLK:26,SNR1: 1.4401 ,SNR2: 5.5343




Frequency (Hz)



T20240622110822




BLK:27,SNR1: 12.831 ,SNR2: 96.438





3C138 2024/06/22 2.17UT TOYOKAWA-FUJI


F20240622110824




BLK:27,SNR1: 0.76834 ,SNR2: 4.1400



T20240622110822




BLK:30,SNR1: 12.138 ,SNR2: 46.556





3C138 2024/06/22 2.17UT TOYOKAWA-KISO



K20240622110820




BLK:30,SNR1: 1.6036 ,SNR2: 6.4225



F20240622110824





BLK:22,SNR1: 0.60047 ,SNR2: 5.3731





3C138 2024/06/22 2.17UT FUJI -KISO


K20240622110820




BLK:22,SNR1: 1.4470 ,SNR2: 5.7642




T20240622112155




BLK:18,SNR1: 3.8953 ,SNR2: 13.181




F20240622112157




BLK:18,SNR1: 1.4582 ,SNR2: 4.7048




0531+194 2024/06/22 2.39UT TOYOKAWA-FUJI





T20240622112155




BLK:26,SNR1: 3.2401 ,SNR2: 21.993




K20240622112153




BLK:26,SNR1: 0.87498 ,SNR2: 3.4812




0531+194 2024/06/22 2.39UT TOYOKAWA-KISO



F20240622112157





BLK:16,SNR1: 0.99826 ,SNR2: 3.6762





0531+194 2024/06/22 2.39UT FUJI -KISO


K20240622112153




BLK:16,SNR1: 0.94500 ,SNR2: 3.8484




T20240622113015




BLK:31,SNR1: 19.211 ,SNR2: 114.89




F20240622113017



BLK:31,SNR1: 0.72008 ,SNR2: 4.4036




3C147 2024/06/22 2.53UT TOYOKAWA-FUJI







T20240622113015




BLK:39,SNR1: 18.549 ,SNR2: 110.90




K20240622113013




BLK:39,SNR1: 2.3189 ,SNR2: 6.8042




3C147 2024/06/22 2.53UT TOYOKAWA-KISO



F20240622113017





BLK:30,SNR1: 0.76784 ,SNR2: 5.2266




Frequency (Hz)

3C147 2024/06/22 2.53UT FUJI -KISO


K20240622113013




BLK:30,SNR1: 2.5164 ,SNR2: 13.053




Frequency (Hz)



T20240622113826





BLK:13,SNR1: 0.86758 ,SNR2: 6.1291





0548+16 2024/06/22 2.67UT TOYOKAWA-FUJI


F20240622113828




BLK:13,SNR1: 1.3381 ,SNR2: 2.7074



T20240622113826





BLK:17,SNR1: 1.1506 ,SNR2: 5.7960





0548+16 2024/06/22 2.67UT TOYOKAWA-KISO


K20240622113823




BLK:17,SNR1: 5.2783 ,SNR2: 20.198



F20240622113828





BLK: 8,SNR1:-0.17856 ,SNR2: 1.8560





0548+16 2024/06/22 2.67UT FUJI -KISO


K20240622113823




BLK: 8,SNR1: 5.4192 ,SNR2: 20.727




T20240622114237




BLK:12,SNR1: 3.9585 ,SNR2: 15.336




F20240622114239





BLK:12,SNR1: 2.7465 ,SNR2: 8.6887




0552+12 2024/06/22 2.74UT TOYOKAWA-FUJI



T20240622114237





BLK:18,SNR1: 4.6487 ,SNR2: 13.120





0552+12 2024/06/22 2.74UT TOYOKAWA-KISO



K20240622114234




BLK:18,SNR1: 0.62067 ,SNR2: 3.6154





F20240622114239




BLK:12,SNR1: 4.6057 ,SNR2: 7.2479




K20240622114234



BLK:12,SNR1: 0.28765 ,SNR2: 1.1406





0552+12 2024/06/22 2.74UT FUJI -KISO








T20240622114704




BLK:18,SNR1: 9.0315 ,SNR2: 25.461




F20240622114706





BLK:18,SNR1: 48.461 ,SNR2: 77.500




0556+191 2024/06/22 2.81UT TOYOKAWA-FUJI



T20240622114704





BLK:27,SNR1: 7.1392 ,SNR2: 21.022









0556+191 2024/06/22 2.81UT TOYOKAWA-KISO

K20240622114701




BLK:27,SNR1: 0.90040 ,SNR2: 3.3874







0556+191 2024/06/22 2.81UT FUJI -KISO





T20240622115137




BLK: 3,SNR1: 0.41418 ,SNR2: 3.5612




F20240622115139




BLK: 3,SNR1: 0.18732E+14,SNR2: 0.18108E+14




3C152 2024/06/22 2.89UT TOYOKAWA-FUJI




T20240622115137




BLK:15,SNR1: 0.71443 ,SNR2: 2.1101




K20240622115134




BLK:15,SNR1: 13.285 ,SNR2: 53.043




3C152 2024/06/22 2.89UT TOYOKAWA-KISO





F20240622115139




BLK:12,SNR1: 0.18732E+14,SNR2: 0.18108E+14




K20240622115134





BLK:12,SNR1: 15.768 ,SNR2: 62.812




3C152 2024/06/22 2.89UT FUJI -KISO



T20240622121358




BLK:18,SNR1: 3.4069 ,SNR2: 30.280





3C161 2024/06/22 3.26UT TOYOKAWA-FUJI



F20240622121400




BLK:18,SNR1: 0.27197 ,SNR2: 1.5605





T20240622121358




BLK:36,SNR1: 2.9611 ,SNR2: 25.414




K20240622121355



BLK:36,SNR1: 0.70892 ,SNR2: 2.9889





3C161 2024/06/22 3.26UT TOYOKAWA-KISO






F20240622121400





BLK:22,SNR1: 0.24612 ,SNR2: 1.7252




Frequency (Hz)

3C161 2024/06/22 3.26UT FUJI -KISO


K20240622121355





BLK:22,SNR1: 0.62379 ,SNR2: 2.5166




Frequency (Hz)




T20240622124131




BLK: 5,SNR1: 0.26148 ,SNR2: 1.0992




F20240622124133





BLK: 5,SNR1: 0.15821 ,SNR2: 0.68067




0652-130 2024/06/22 3.72UT TOYOKAWA-FUJI





T20240622124131




BLK:10,SNR1: 0.10721 ,SNR2: 0.50119




K20240622124128




BLK:10,SNR1: 0.46442 ,SNR2: 2.6506




0652-130 2024/06/22 3.72UT TOYOKAWA-KISO



F20240622124133




BLK: 3,SNR1:-0.12163 ,SNR2: 1.0690





0652-130 2024/06/22 3.72UT FUJI -KISO


K20240622124128




BLK: 3,SNR1: 0.13192E-01,SNR2: 1.2032




T20240622125307




BLK: 7,SNR1: 0.18629 ,SNR2: 0.74176




F20240622125309





BLK: 7,SNR1: 0.45138 ,SNR2: 3.0292




0703+138 2024/06/22 3.91UT TOYOKAWA-FUJI





T20240622125307




BLK: 7,SNR1: 0.11864 ,SNR2: 0.69668




K20240622125304




BLK: 7,SNR1: 1.2605 ,SNR2: 6.1504




0703+138 2024/06/22 3.91UT TOYOKAWA-KISO





F20240622125309




BLK: 5,SNR1: 0.85375E-01,SNR2: 1.7998




K20240622125304





BLK: 5,SNR1: 1.8909 ,SNR2: 5.4778




0703+138 2024/06/22 3.91UT FUJI -KISO





T20240622130230




BLK: 5,SNR1: 3.6742 ,SNR2: 11.064




F20240622130232



BLK: 5,SNR1:-0.20146 ,SNR2: 0.0000





0713-024 2024/06/22 4.07UT TOYOKAWA-FUJI








T20240622130230




BLK:14,SNR1: 1.4110 ,SNR2: 4.3454




K20240622130227




BLK:14,SNR1: 0.45123 ,SNR2: 2.1655




0713-024 2024/06/22 4.07UT TOYOKAWA-KISO





F20240622130232




BLK: 6,SNR1: 2.4247 ,SNR2: 8.1256




K20240622130227





BLK: 6,SNR1: 23.197 ,SNR2: 20.653




0713-024 2024/06/22 4.07UT FUJI -KISO





T20240622131242




BLK:19,SNR1: 0.55823 ,SNR2: 2.2066




F20240622131244




BLK:19,SNR1: 0.72507E-01,SNR2: 0.49128




0723+10 2024/06/22 4.24UT TOYOKAWA-FUJI




T20240622131242




BLK:26,SNR1: 0.69085 ,SNR2: 5.4580




K20240622131240





BLK:26,SNR1: 0.34393 ,SNR2: 1.4714




0723+10 2024/06/22 4.24UT TOYOKAWA-KISO





F20240622131244




BLK:14,SNR1: 0.11825 ,SNR2: 0.64710




K20240622131240





BLK:14,SNR1: 0.22249 ,SNR2: 0.92177




0723+10 2024/06/22 4.24UT FUJI -KISO





T20240622132256




BLK:12,SNR1: 0.25184 ,SNR2: 0.80358




F20240622132258





BLK:12,SNR1: 0.55830 ,SNR2: 3.5723




0732+33 2024/06/22 4.41UT TOYOKAWA-FUJI





T20240622132256




BLK:17,SNR1: 0.24153 ,SNR2: 1.2298




K20240622132254





BLK:17,SNR1: 0.66478 ,SNR2: 2.6509




0732+33 2024/06/22 4.41UT TOYOKAWA-KISO



F20240622132258





BLK:11,SNR1: 0.51724 ,SNR2: 3.3763




Frequency (Hz)

K20240622132254




BLK:11,SNR1: 1.0541 ,SNR2: 6.3743




Frequency (Hz)

0732+33 2024/06/22 4.41UT FUJI -KISO







T20240622133058




BLK:17,SNR1: 1.0697 ,SNR2: 9.7978




F20240622133100




BLK:17,SNR1: 0.46363 ,SNR2: 1.4715




0741-06 2024/06/22 4.54UT TOYOKAWA-FUJI





T20240622133058




BLK:23,SNR1: 1.0487 ,SNR2: 8.5080




K20240622133055




BLK:23,SNR1: 0.64826 ,SNR2: 2.5689




0741-06 2024/06/22 4.54UT TOYOKAWA-KISO





F20240622133100




BLK:18,SNR1: 0.16406 ,SNR2: 1.3581




K20240622133055





BLK:18,SNR1: 1.0500 ,SNR2: 4.3299




0741-06 2024/06/22 4.54UT FUJI -KISO





T20240622134043




BLK:12,SNR1: 0.82998E-01,SNR2: 2.3549




F20240622134045





BLK:12,SNR1: 0.21097 ,SNR2: 1.2716




0752-200 2024/06/22 4.71UT TOYOKAWA-FUJI





T20240622134043




BLK:11,SNR1: 0.26103 ,SNR2: 1.6748




K20240622134041




BLK:11,SNR1: 4.6943 ,SNR2: 12.270




0752-200 2024/06/22 4.71UT TOYOKAWA-KISO





F20240622134045




BLK: 8,SNR1: 0.36769 ,SNR2: 1.2278




K20240622134041





BLK: 8,SNR1: 5.4985 ,SNR2: 14.333




0752-200 2024/06/22 4.71UT FUJI -KISO





T20240622134817




BLK:11,SNR1: 0.10819 ,SNR2: 0.92310




F20240622134819





BLK:11,SNR1: 0.38158 ,SNR2: 1.7362




3C190 2024/06/22 4.83UT TOYOKAWA-FUJI





T20240622134817




BLK: 8,SNR1: 0.28115 ,SNR2: 7.0121




K20240622134815



BLK: 8,SNR1: 0.19508 ,SNR2: 3.2848





3C190 2024/06/22 4.83UT TOYOKAWA-KISO








F20240622134819




BLK: 7,SNR1: 0.21473 ,SNR2: 1.0177




K20240622134815





BLK: 7,SNR1: 0.94386 ,SNR2: 3.6010




3C190 2024/06/22 4.83UT FUJI -KISO





T20240622140042




BLK:11,SNR1: 0.47702 ,SNR2: 1.8559




F20240622140044





BLK:11,SNR1: 0.58050E-01,SNR2: 1.5755




3C196 2024/06/22 5.04UT TOYOKAWA-FUJI



T20240622140042




BLK:12,SNR1: 0.34152 ,SNR2: 4.8293




Frequency (Hz)

K20240622140039




BLK:12,SNR1: 0.37355 ,SNR2: 0.91545





Frequency (Hz)


3C196 2024/06/22 5.04UT TOYOKAWA-KISO



F20240622140044





BLK: 7,SNR1: 0.21095 ,SNR2: 1.2941




Frequency (Hz)

K20240622140039




BLK: 7,SNR1: 0.43749 ,SNR2: 2.2531





Frequency (Hz)


3C196 2024/06/22 5.04UT FUJI -KISO





T20240622141152




BLK: 5,SNR1: 0.24644 ,SNR2: 1.2379




F20240622141154





BLK: 5,SNR1: 0.68107 ,SNR2: 1.8898




0821+394 2024/06/22 5.23UT TOYOKAWA-FUJI





T20240622141152




BLK: 5,SNR1: 0.28472 ,SNR2: 2.0932




K20240622141149





BLK: 5,SNR1: 0.76845 ,SNR2: 3.1388




0821+394 2024/06/22 5.23UT TOYOKAWA-KISO



F20240622141154





BLK: 8,SNR1: 0.39824 ,SNR2: 1.5993




Frequency (Hz)

K20240622141149




BLK: 8,SNR1: 0.56141 ,SNR2: 2.1443





Frequency (Hz)


0821+394 2024/06/22 5.23UT FUJI -KISO





T20240622142332




BLK:11,SNR1: 0.87453E-01,SNR2: 2.0608




F20240622142334



BLK:11,SNR1: 0.25386 ,SNR2: 2.3432





0834-19 2024/06/22 5.42UT TOYOKAWA-FUJI








T20240622142332




BLK:14,SNR1: 0.10260 ,SNR2: 2.0693




K20240622142329




BLK:14,SNR1: 0.21501 ,SNR2: 1.7052




0834-19 2024/06/22 5.42UT TOYOKAWA-KISO





F20240622142334




BLK: 9,SNR1: 0.52964 ,SNR2: 2.6499




K20240622142329





BLK: 9,SNR1: 0.49691 ,SNR2: 1.5401




0834-19 2024/06/22 5.42UT FUJI -KISO



T20240622142837





BLK:11,SNR1: 1.7634 ,SNR2: 15.092




Frequency (Hz)

F20240622142839




BLK:11,SNR1: 2.9360 ,SNR2: 7.2395





Frequency (Hz)


0839-071 2024/06/22 5.51UT TOYOKAWA-FUJI





T20240622142837




BLK:13,SNR1: 2.8390 ,SNR2: 13.529




K20240622142834




BLK:13,SNR1: 6.3512 ,SNR2: 15.864




0839-071 2024/06/22 5.51UT TOYOKAWA-KISO





F20240622142839




BLK:16,SNR1: 3.7386 ,SNR2: 8.5047




K20240622142834





BLK:16,SNR1: 6.1713 ,SNR2: 15.746




0839-071 2024/06/22 5.51UT FUJI -KISO





T20240622143938




BLK:11,SNR1: 0.30072 ,SNR2: 1.4344




F20240622143940





BLK:11,SNR1: 5.5287 ,SNR2: 13.811




3C208 2024/06/22 5.69UT TOYOKAWA-FUJI





T20240622143938




BLK:21,SNR1: 0.46968 ,SNR2: 2.2375




K20240622143936





BLK:21,SNR1: 1.8097 ,SNR2: 8.4287




3C208 2024/06/22 5.69UT TOYOKAWA-KISO



F20240622143940





BLK:18,SNR1: 9.8477 ,SNR2: 13.723





3C208 2024/06/22 5.69UT FUJI -KISO

K20240622143936





BLK:18,SNR1: 4.5075 ,SNR2: 11.249







T20240622145619




BLK: 6,SNR1: 0.74479E-02,SNR2: 1.0176




F20240622145621





BLK: 6,SNR1:-0.72218E-01,SNR2: 1.1236




3C216 2024/06/22 5.97UT TOYOKAWA-FUJI





T20240622145619




BLK: 6,SNR1: 0.87818E-01,SNR2: 0.65294




K20240622145616





BLK: 6,SNR1: 1.1971 ,SNR2: 5.0784




3C216 2024/06/22 5.97UT TOYOKAWA-KISO



F20240622145621





BLK: 5,SNR1: 0.16997 ,SNR2: 0.80722




Frequency (Hz)

K20240622145616




BLK: 5,SNR1: 1.1008 ,SNR2: 5.3919





Frequency (Hz)


3C216 2024/06/22 5.97UT FUJI -KISO



T20240622150831





BLK:11,SNR1: 0.35322 ,SNR2: 1.7976




Frequency (Hz)

F20240622150833




BLK:11,SNR1: 1.4165 ,SNR2: 5.0398





Frequency (Hz)


0919-142 2024/06/22 6.17UT TOYOKAWA-FUJI



T20240622150831





BLK:10,SNR1: 0.33660 ,SNR2: 1.8429




Frequency (Hz)

K20240622150828




BLK:10,SNR1: 3.2447 ,SNR2: 6.2981





Frequency (Hz)


0919-142 2024/06/22 6.17UT TOYOKAWA-KISO



F20240622150833





BLK:11,SNR1: 1.0591 ,SNR2: 3.3037




Frequency (Hz)

K20240622150828




BLK:11,SNR1: 1.0042 ,SNR2: 3.9451





Frequency (Hz)


0919-142 2024/06/22 6.17UT FUJI -KISO





T20240622151510




BLK:16,SNR1: 3.3544 ,SNR2: 8.2032




F20240622151512





BLK:16,SNR1: 9.1703 ,SNR2: 16.302




0926+117 2024/06/22 6.28UT TOYOKAWA-FUJI





T20240622151510




BLK:16,SNR1: 3.2640 ,SNR2: 8.0323




K20240622151508



BLK:16,SNR1: 6.8871 ,SNR2: 19.884





0926+117 2024/06/22 6.28UT TOYOKAWA-KISO








F20240622151512




BLK:21,SNR1: 8.5689 ,SNR2: 15.250




K20240622151508





BLK:21,SNR1: 6.6577 ,SNR2: 19.227




0926+117 2024/06/22 6.28UT FUJI -KISO





T20240622152255




BLK:20,SNR1: 2.8718 ,SNR2: 13.665




F20240622152257





BLK:20,SNR1: 19.354 ,SNR2: 21.609




3C222 2024/06/22 6.41UT TOYOKAWA-FUJI





T20240622152255




BLK:26,SNR1: 2.8579 ,SNR2: 13.612




K20240622152253





BLK:26,SNR1: 7.2995 ,SNR2: 21.582




3C222 2024/06/22 6.41 UT TOYOKAWA-KISO





F20240622152257




BLK:26,SNR1: 19.888 ,SNR2: 22.205




K20240622152253





BLK:26,SNR1: 7.2069 ,SNR2: 21.185




3C222 2024/06/22 6.41UT FUJI -KISO



T20240622152955




BLK: 6,SNR1: 0.50266 ,SNR2: 8.4635




Frequency (Hz)

F20240622152957




BLK: 6,SNR1: 0.56148E-01,SNR2: 0.89451





Frequency (Hz)


0941-08 2024/06/22 6.53UT TOYOKAWA-FUJI





T20240622152955




BLK: 7,SNR1: 0.16687 ,SNR2: 1.3891




K20240622152952




BLK: 7,SNR1: 0.19308 ,SNR2: 2.6464




0941-08 2024/06/22 6.53UT TOYOKAWA-KISO




F20240622152957




BLK: 7,SNR1:-0.23397E-01,SNR2: 0.75803




K20240622152952





BLK: 7,SNR1: 0.30674 ,SNR2: 1.3777




0941-08 2024/06/22 6.53UT FUJI -KISO



T20240622153816




BLK:14,SNR1: 2.3014 ,SNR2: 4.6074




Frequency (Hz)

F20240622153818




BLK:14,SNR1: 7.5831 ,SNR2: 14.203





Frequency (Hz)

3C230 2024/06/22 6.67UT TOYOKAWA-FUJI






T20240622153816





BLK:17,SNR1: 0.90411 ,SNR2: 4.8713




Frequency (Hz)

K20240622153814




BLK:17,SNR1: 7.4814 ,SNR2: 22.143




Frequency (Hz)


3C230 2024/06/22 6.67UT TOYOKAWA-KISO



F20240622153818





BLK:14,SNR1: 7.5033 ,SNR2: 20.463




Frequency (Hz)

K20240622153814




BLK:14,SNR1: 7.4905 ,SNR2: 22.170




Frequency (Hz)


3C230 2024/06/22 6.67UT FUJI -KISO



T20240622155417





BLK:20,SNR1: 0.87254 ,SNR2: 4.1349




Frequency (Hz)

F20240622155419




BLK:20,SNR1: 0.25133 ,SNR2: 3.1887




Frequency (Hz)


3C237 2024/06/22 6.93UT TOYOKAWA-FUJI



T20240622155417




BLK:25,SNR1: 0.77836 ,SNR2: 3.6591




Frequency (Hz)

K20240622155414




BLK:25,SNR1: 0.85841 ,SNR2: 3.4852





Frequency (Hz)


3C237 2024/06/22 6.93UT TOYOKAWA-KISO



F20240622155419




BLK:23,SNR1: 0.28900 ,SNR2: 2.0339




Frequency (Hz)

K20240622155414




BLK:23,SNR1: 0.83241 ,SNR2: 3.2350





Frequency (Hz)


3C237 2024/06/22 6.93UT FUJI -KISO



T20240622160033





BLK: 8,SNR1: 0.60468 ,SNR2: 2.5423




Frequency (Hz)

F20240622160035




BLK: 8,SNR1: 1.5705 ,SNR2: 7.5156





Frequency (Hz)


1011+110 2024/06/22 7.04UT TOYOKAWA-FUJI



T20240622160033





BLK:12,SNR1: 0.42878 ,SNR2: 1.9076




Frequency (Hz)

K20240622160031




BLK:12,SNR1: 1.1206 ,SNR2: 4.2432





Frequency (Hz)


1011+110 2024/06/22 7.04UT TOYOKAWA-KISO



F20240622160035





BLK:13,SNR1: 2.2591 ,SNR2: 5.6870




Frequency (Hz)

K20240622160031




BLK:13,SNR1: 0.71537 ,SNR2: 2.4944





Frequency (Hz)

1011+110 2024/06/22 7.04UT FUJI -KISO






T20240622160814




BLK:25,SNR1: 2.9173 ,SNR2: 13.603




Frequency (Hz)

3C241 2024/06/22 7.17UT TOYOKAWA-FUJI


F20240622160816





BLK:25,SNR1: 4.1630 ,SNR2: 11.195




Frequency (Hz)



T20240622160814





BLK:31,SNR1: 2.9102 ,SNR2: 13.574




Frequency (Hz)

3C241 2024/06/22 7.17UT TOYOKAWA-KISO


K20240622160811




BLK:31,SNR1: 8.4474 ,SNR2: 21.213




Frequency (Hz)



F20240622160816




BLK:30,SNR1: 5.0243 ,SNR2: 8.9937




Frequency (Hz)

K20240622160811




BLK:30,SNR1: 8.3799 ,SNR2: 21.048





Frequency (Hz)


3C241 2024/06/22 7.17UT FUJI -KISO





T20240622161944




BLK:31,SNR1: 8.1948 ,SNR2: 23.838




F20240622161946





BLK:31,SNR1: 8.1202 ,SNR2: 20.571




1031-11 2024/06/22 7.36UT TOYOKAWA-FUJI





T20240622161944




BLK:37,SNR1: 8.2041 ,SNR2: 23.867




K20240622161942





BLK:37,SNR1: 9.8498 ,SNR2: 24.789




1031-11 2024/06/22 7.36UT TOYOKAWA-KISO



F20240622161946





BLK:34,SNR1: 8.1091 ,SNR2: 20.542




Frequency (Hz)

K20240622161942




BLK:34,SNR1: 9.8519 ,SNR2: 24.795





Frequency (Hz)


1031-11 2024/06/22 7.36UT FUJI -KISO



T20240622162417




BLK: 7,SNR1: 8.5253 ,SNR2: 60.036




Frequency (Hz)

F20240622162419




BLK: 7,SNR1:-0.75148E-01,SNR2: 2.0626





Frequency (Hz)


1035-058 2024/06/22 7.43UT TOYOKAWA-FUJI





T20240622162417




BLK: 6,SNR1: 24.864 ,SNR2: 81.362




K20240622162414



BLK: 6,SNR1: 0.29863 ,SNR2: 1.3392




1035-058 2024/06/22 7.43UT TOYOKAWA-KISO






F20240622162419





BLK: 4,SNR1: 1.3140 ,SNR2: 7.2606




Frequency (Hz)

K20240622162414




BLK: 4,SNR1: 1.0884 ,SNR2: 5.0779





Frequency (Hz)


1035-058 2024/06/22 7.43UT FUJI -KISO



T20240622163330




BLK:10,SNR1: 6.2626 ,SNR2: 15.785




Frequency (Hz)

F20240622163332




BLK:10,SNR1: 0.63210E-01,SNR2: 1.9079




Frequency (Hz)


1044-008 2024/06/22 7.59UT TOYOKAWA-FUJI



T20240622163330




BLK:21,SNR1: 6.7897 ,SNR2: 16.710




Frequency (Hz)

K20240622163327




BLK:21,SNR1: 2.6576 ,SNR2: 5.2355





Frequency (Hz)


1044-008 2024/06/22 7.59UT TOYOKAWA-KISO



F20240622163332





BLK: 8,SNR1: 0.17879 ,SNR2: 2.4880




Frequency (Hz)

K20240622163327




BLK: 8,SNR1: 2.9497 ,SNR2: 10.769





Frequency (Hz)


1044-008 2024/06/22 7.59UT FUJI -KISO



T20240622164434




BLK: 8,SNR1: 0.67605 ,SNR2: 3.1707




Frequency (Hz)

F20240622164436




BLK: 8,SNR1:-0.71335E-01,SNR2: 1.1918





Frequency (Hz)


1055+01 2024/06/22 7.77UT TOYOKAWA-FUJI



T20240622164434





BLK:21,SNR1: 0.45203 ,SNR2: 2.2576




Frequency (Hz)

K20240622164431




BLK:21,SNR1: 6.9480 ,SNR2: 16.583





Frequency (Hz)


1055+01 2024/06/22 7.77UT TOYOKAWA-KISO



F20240622164436





BLK:13,SNR1:-0.12886 ,SNR2: 0.75836




Frequency (Hz)

K20240622164431




BLK:13,SNR1: 2.6664 ,SNR2: 12.164




Frequency (Hz)


1055+01 2024/06/22 7.77UT FUJI -KISO



T20240622165552





BLK:12,SNR1: 1.0928 ,SNR2: 5.4783




Frequency (Hz)

F20240622165554




BLK:12,SNR1: 1.3452 ,SNR2: 4.8126





Frequency (Hz)

1107+109 2024/06/22 7.96UT TOYOKAWA-FUJI






T20240622165552





BLK:11,SNR1: 1.2039 ,SNR2: 3.7980




Frequency (Hz)

K20240622165549




BLK:11,SNR1: 1.5950 ,SNR2: 11.804





Frequency (Hz)


1107+109 2024/06/22 7.96UT TOYOKAWA-KISO



F20240622165554




BLK:16,SNR1: 1.0230 ,SNR2: 3.5508




Frequency (Hz)

K20240622165549




BLK:16,SNR1: 1.2452 ,SNR2: 6.6772





Frequency (Hz)


1107+109 2024/06/22 7.96UT FUJI -KISO



T20240622172927




BLK:12,SNR1: 0.65158 ,SNR2: 1.3100




Frequency (Hz)

F20240622172929




BLK:12,SNR1: 2.5306 ,SNR2: 6.2046





Frequency (Hz)


3C263.1 2024/06/22 8.52UT TOYOKAWA-FUJI



T20240622172927





BLK:10,SNR1: 0.41554 ,SNR2: 1.7864




Frequency (Hz)

K20240622172925




BLK:10,SNR1: 17.146 ,SNR2: 26.365




Frequency (Hz)


3C263.1 2024/06/22 8.52UT TOYOKAWA-KISO



F20240622172929





BLK:13,SNR1: 2.7663 ,SNR2: 6.7603




Frequency (Hz)

K20240622172925




BLK:13,SNR1: 2.2595 ,SNR2: 5.8202





Frequency (Hz)


3C263.1 2024/06/22 8.52UT FUJI -KISO



T20240622175508





BLK: 6,SNR1: 0.12805E-02,SNR2: 0.54450




Frequency (Hz)

F20240622175510




BLK: 6,SNR1:-0.13654E-01,SNR2: 0.99724





Frequency (Hz)


1206+439 2024/06/22 8.95UT TOYOKAWA-FUJI



T20240622175508





BLK: 1,SNR1: 0.89125E-01,SNR2: 0.51203




Frequency (Hz)

K20240622175505




BLK: 1,SNR1: 0.33279 ,SNR2: 0.51902





Frequency (Hz)


1206+439 2024/06/22 8.95UT TOYOKAWA-KISO



F20240622175510





BLK: 3,SNR1: 0.14414E-01,SNR2: 1.2429




Frequency (Hz)

K20240622175505




BLK: 3,SNR1: 0.31312 ,SNR2: 1.6653





Frequency (Hz)

1206+439 2024/06/22 8.95UT Fuji -KISO






T20240622181019





BLK:30,SNR1: 9.2479 ,SNR2: 23.109




Frequency (Hz)

F20240622181021




BLK:30,SNR1: 2.8546 ,SNR2: 13.589





Frequency (Hz)


1222+423 2024/06/22 9.20UT TOYOKAWA-FUJI



T20240622181019





BLK:34,SNR1: 7.1348 ,SNR2: 20.944




Frequency (Hz)

K20240622181017




BLK:34,SNR1: 7.0708 ,SNR2: 20.502





Frequency (Hz)


1222+423 2024/06/22 9.20UT TOYOKAWA-KISO



F20240622181021





BLK:36,SNR1: 2.8505 ,SNR2: 13.571




Frequency (Hz)

K20240622181017



BLK:36,SNR1: 7.6041 ,SNR2: 19.307



Frequency (Hz)

1222+423 2024/06/22 9.20UT FUJI -KISO

