




T20240625053443





BLK: 4,SNR1: 0.30055 ,SNR2: 1.8859




Frequency (Hz)

F20240625053445




BLK: 4,SNR1: 0.30253 ,SNR2: 3.1010





Frequency (Hz)


2356+437 2024/06/24 20.61UT TOYOKAWA-FUJI



T20240625053443





BLK: 5,SNR1: 0.71174E-01,SNR2: 0.84874




Frequency (Hz)

2356+437 2024/06/24 20.61UT TOYOKAWA-KISO


K20240625053440



BLK: 5,SNR1: 3.1146 ,SNR2: 13.817





Frequency (Hz)






F20240625053445





BLK: 6,SNR1: 0.10322 ,SNR2: 1.2876




Frequency (Hz)

K20240625053440




BLK: 6,SNR1: 3.0838 ,SNR2: 13.694




Frequency (Hz)


2356+437 2024/06/24 20.61UT FUJI -KISO



T20240625054951




BLK: 3,SNR1: 0.15144 ,SNR2: 0.27673




Frequency (Hz)

F20240625054953




BLK: 3,SNR1: 1.1912 ,SNR2: 6.8793




Frequency (Hz)


0011+344 2024/06/24 20.86UT TOYOKAWA-FUJI



T20240625054951





BLK: 4,SNR1: 0.60829E-01,SNR2: 0.79654




Frequency (Hz)

K20240625054948




BLK: 4,SNR1: 0.15929 ,SNR2: 0.29671





Frequency (Hz)


0011+344 2024/06/24 20.86UT TOYOKAWA-KISO



F20240625054953





BLK: 4,SNR1: 0.28170 ,SNR2: 4.7524




Frequency (Hz)

K20240625054948




BLK: 4,SNR1: 0.24002 ,SNR2: 1.4663





Frequency (Hz)


0011+344 2024/06/24 20.86UT FUJI -KISO



T20240625061700





BLK: 7,SNR1: 1.3942 ,SNR2: 4.9310




Frequency (Hz)

F20240625061702




BLK: 7,SNR1: 0.14376 ,SNR2: 0.59713





Frequency (Hz)


0038+328 2024/06/24 21.31UT TOYOKAWA-FUJI



T20240625061700





BLK: 7,SNR1: 37.688 ,SNR2: 141.74




Frequency (Hz)

K20240625061657




BLK: 7,SNR1: 0.12526 ,SNR2: 0.70191





Frequency (Hz)


0038+328 2024/06/24 21.31UT TOYOKAWA-KISO



F20240625061702





BLK: 9,SNR1: 0.26837 ,SNR2: 1.5711




Frequency (Hz)

K20240625061657




BLK: 9,SNR1: 1.3617 ,SNR2: 6.7145





Frequency (Hz)


0038+328 2024/06/24 21.31UT FUJI -KISO



T20240625063848





BLK: 6,SNR1: 2.3953 ,SNR2: 11.329




Frequency (Hz)

F20240625063850




BLK: 6,SNR1: 0.66487 ,SNR2: 3.0277





Frequency (Hz)

0100+146 2024/06/24 21.67UT TOYOKAWA-FUJI






T20240625063848





BLK: 9,SNR1: 2.2830 ,SNR2: 10.708




Frequency (Hz)

K20240625063845




BLK: 9,SNR1: 4.8675 ,SNR2: 12.010





Frequency (Hz)


0100+146 2024/06/24 21.67UT TOYOKAWA-KISO



F20240625063850





BLK: 7,SNR1: 0.59345 ,SNR2: 2.7704




Frequency (Hz)

K20240625063845




BLK: 7,SNR1: 2.4262 ,SNR2: 10.623





Frequency (Hz)


0100+146 2024/06/24 21.67UT FUJI -KISO



T20240625064446





BLK: 7,SNR1: 0.24843 ,SNR2: 2.7390




Frequency (Hz)

F20240625064448




BLK: 7,SNR1: 2.4355 ,SNR2: 5.5701





Frequency (Hz)


0106+01 2024/06/24 21.77UT TOYOKAWA-FUJI



T20240625064446





BLK: 7,SNR1: 0.48092 ,SNR2: 2.0579




Frequency (Hz)

K20240625064443




BLK: 7,SNR1: 0.66228 ,SNR2: 6.0928




Frequency (Hz)


0106+01 2024/06/24 21.77UT TOYOKAWA-KISO





F20240625064448




BLK:10,SNR1: 0.67776 ,SNR2: 4.0525




K20240625064443




BLK:10,SNR1: 0.88917 ,SNR2: 6.5253




0106+01 2024/06/24 21.77UT FUJI -KISO



T20240625065409




BLK:16,SNR1: 3.5421 ,SNR2: 6.6360




Frequency (Hz)

F20240625065411




BLK:16,SNR1: 7.8669 ,SNR2: 19.774




Frequency (Hz)


0115-01 2024/06/24 21.93UT TOYOKAWA-FUJI



T20240625065409




BLK:20,SNR1: 1.5270 ,SNR2: 3.0081




Frequency (Hz)

K20240625065406




BLK:20,SNR1: 8.2079 ,SNR2: 20.845





Frequency (Hz)


0115-01 2024/06/24 21.93UT TOYOKAWA-KISO



F20240625065411





BLK:16,SNR1: 2.6588 ,SNR2: 12.527




Frequency (Hz)

0115-01 2024/06/24 21.93UT FUJI -KISO


K20240625065406



BLK:16,SNR1: 8.2399 ,SNR2: 20.926




Frequency (Hz)






T20240625070709




BLK:14,SNR1: 3.8495 ,SNR2: 9.6673




Frequency (Hz)

F20240625070711




BLK:14,SNR1: 5.7925 ,SNR2: 10.389




Frequency (Hz)


0128+03 2024/06/24 22.15UT TOYOKAWA-FUJI



T20240625070709




BLK:11,SNR1: 4.2800 ,SNR2: 10.643




Frequency (Hz)

K20240625070706




BLK:11,SNR1: 11.345 ,SNR2: 20.240





Frequency (Hz)


0128+03 2024/06/24 22.15UT TOYOKAWA-KISO



F20240625070711




BLK:18,SNR1: 5.5789 ,SNR2: 9.9630




Frequency (Hz)

K20240625070706




BLK:18,SNR1: 9.7863 ,SNR2: 17.482





Frequency (Hz)


0128+03 2024/06/24 22.15UT FUJI -KISO



T20240625071342





BLK:23,SNR1: 8.1940 ,SNR2: 20.620




Frequency (Hz)

3C48 2024/06/24 22.26UT TOYOKAWA-FUJI


F20240625071344





BLK:23,SNR1: 4.7364 ,SNR2: 11.192




Frequency (Hz)



T20240625071342





BLK:22,SNR1: 8.2092 ,SNR2: 20.656




Frequency (Hz)

3C48 2024/06/24 22.26UT TOYOKAWA-KISO


K20240625071339





BLK:22,SNR1: 2.7186 ,SNR2: 13.070




Frequency (Hz)



F20240625071344



BLK:19,SNR1: 5.4090 ,SNR2: 9.8804





Frequency (Hz)


3C48

2024/06/24 22.26UT FUJI -KISO


K20240625071339





BLK:19,SNR1: 2.7136 ,SNR2: 13.051




Frequency (Hz)



T20240625073327





BLK:11,SNR1: 0.27491 ,SNR2: 2.4550




Frequency (Hz)

F20240625073329




BLK:11,SNR1: 0.11091 ,SNR2: 1.2612




Frequency (Hz)


0155-109 2024/06/24 22.59UT TOYOKAWA-FUJI



T20240625073327





BLK:11,SNR1: 0.10325 ,SNR2: 1.3922




Frequency (Hz)

K20240625073324




BLK:11,SNR1: 0.52628 ,SNR2: 4.1327




Frequency (Hz)

0155-109 2024/06/24 22.59UT TOYOKAWA-KISO







F20240625073329




BLK: 5,SNR1: 0.32765 ,SNR2: 0.79515




K20240625073324





BLK: 5,SNR1: 0.43187 ,SNR2: 6.1731




0155-109 2024/06/24 22.59UT FUJI -KISO



T20240625074034





BLK: 7,SNR1: 3.0559 ,SNR2: 8.3759




Frequency (Hz)

F20240625074036




BLK: 7,SNR1: 8.9377 ,SNR2: 15.856





Frequency (Hz)


0202+15 2024/06/24 22.70UT TOYOKAWA-FUJI



T20240625074034




BLK:11,SNR1: 2.3536 ,SNR2: 6.2796




Frequency (Hz)

K20240625074031




BLK:11,SNR1: 5.2985 ,SNR2: 13.898





Frequency (Hz)


0202+15 2024/06/24 22.70UT TOYOKAWA-KISO



F20240625074036





BLK:19,SNR1: 5.1083 ,SNR2: 13.031




Frequency (Hz)

K20240625074031




BLK:19,SNR1: 4.3356 ,SNR2: 11.969




Frequency (Hz)


0202+15 2024/06/24 22.70UT FUJI -KISO



T20240625075224




BLK: 8,SNR1: 0.30043E-01,SNR2: 0.15447




Frequency (Hz)

F20240625075226




BLK: 8,SNR1: 1.0689 ,SNR2: 6.1313





Frequency (Hz)


0213+178 2024/06/24 22.90UT TOYOKAWA-FUJI





T20240625075224




BLK: 5,SNR1: 0.42754E-01,SNR2: 0.16669




K20240625075222





BLK: 5,SNR1: 1.2081 ,SNR2: 4.7806




0213+178 2024/06/24 22.90UT TOYOKAWA-KISO



F20240625075226





BLK:12,SNR1: 1.2009 ,SNR2: 6.4295




Frequency (Hz)

K20240625075222




BLK:12,SNR1: 0.55073 ,SNR2: 2.2242





Frequency (Hz)


0213+178 2024/06/24 22.90UT FUJI -KISO



T20240625080007




BLK:23,SNR1: 7.7115 ,SNR2: 19.401




Frequency (Hz)

3C67 2024/06/24 23.03UT TOYOKAWA-FUJI


F20240625080009



BLK:23,SNR1: 5.8848 ,SNR2: 14.600





Frequency (Hz)








T20240625080007




No.Good Data




KISO





No.Good Data




3C67 2024/06/24 23.03UT TOYOKAWA-KISO





F20240625080009




No.Good Data




KISO





No.Good Data




3C67 2024/06/24 23.03UT FUJI -KISO



T20240625081822





BLK: 2,SNR1:-0.19632 ,SNR2: 0.38620




Frequency (Hz)

F20240625081824




BLK: 2,SNR1: 0.38232 ,SNR2: 2.0471





Frequency (Hz)


3C71 2024/06/24 23.33UT TOYOKAWA-FUJI





T20240625081822




No.Good Data




KISO





No.Good Data




3C71 2024/06/24 23.33UT TOYOKAWA-KISO





F20240625081824




No.Good Data




KISO





No.Good Data




3C71 2024/06/24 23.33UT FUJI -KISO



T20240625083737





BLK:10,SNR1: 0.25034 ,SNR2: 3.3363




Frequency (Hz)

F20240625083739




BLK:10,SNR1: 196.10 ,SNR2: 297.05





Frequency (Hz)


0258+350 2024/06/24 23.66UT TOYOKAWA-FUJI





T20240625083737




BLK:11,SNR1: 0.37906 ,SNR2: 1.3032




K20240625083734





BLK:11,SNR1: 19.045 ,SNR2: 32.890




0258+350 2024/06/24 23.66UT TOYOKAWA-KISO





F20240625083739




BLK:24,SNR1: 165.35 ,SNR2: 250.48




K20240625083734



BLK:24,SNR1: 18.350 ,SNR2: 31.692





0258+350 2024/06/24 23.66UT FUJI -KISO






T20240625084726





BLK:10,SNR1: 5.4597 ,SNR2: 13.267




Frequency (Hz)

F20240625084728




BLK:10,SNR1: 5.9397 ,SNR2: 14.651




Frequency (Hz)


0308+305 2024/06/24 23.82UT TOYOKAWA-FUJI



T20240625084726





BLK:14,SNR1: 4.6834 ,SNR2: 11.312




Frequency (Hz)

K20240625084723




BLK:14,SNR1: 7.3976 ,SNR2: 16.867





Frequency (Hz)


0308+305 2024/06/24 23.82UT TOYOKAWA-KISO



F20240625084728




BLK:23,SNR1: 3.5514 ,SNR2: 8.8833




Frequency (Hz)

K20240625084723




BLK:23,SNR1: 6.0726 ,SNR2: 11.809





Frequency (Hz)


0308+305 2024/06/24 23.82UT FUJI -KISO




T20240625085412




BLK: 2,SNR1:-0.92679E-01,SNR2: 0.18522




F20240625085414





BLK: 2,SNR1: 1.8972 ,SNR2: 7.7964




0315+045 2024/06/24 23.93UT TOYOKAWA-FUJI




T20240625085412




BLK: 6,SNR1: 2.8649 ,SNR2: 8.2211




K20240625085409





BLK: 6,SNR1: 1.2958 ,SNR2: 8.5664




0315+045 2024/06/24 23.93UT TOYOKAWA-KISO





F20240625085414




No. Good Data




K20240625085409





No. Good Data




0315+045 2024/06/24 23.93UT FUJI -KISO





T20240625091219




BLK: 4,SNR1: 0.52990E-01,SNR2: 0.66224




F20240625091221





BLK: 4,SNR1: 0.64078 ,SNR2: 3.4926




0333+32 2024/06/25 0.23UT TOYOKAWA-FUJI





T20240625091219




BLK:10,SNR1: 0.11756 ,SNR2: 0.46597




K20240625091216



BLK:10,SNR1: 2.7595 ,SNR2: 6.8788





0333+32 2024/06/25 0.23UT TOYOKAWA-KISO








F20240625091221




BLK:17,SNR1: 0.38837 ,SNR2: 3.1447




K20240625091216




BLK:17,SNR1: 2.7422 ,SNR2: 9.6967




0333+32 2024/06/25 0.23UT FUJI -KISO



T20240625092521





BLK: 3,SNR1: 0.71965E-01,SNR2: 0.24303





0347+05 2024/06/25 0.45UT TOYOKAWA-FUJI


F20240625092523




BLK: 3,SNR1: 0.91726 ,SNR2: 5.7796



T20240625092521





BLK: 4,SNR1:-0.44287E-02,SNR2: 1.5819





0347+05 2024/06/25 0.45UT TOYOKAWA-KISO



K20240625092518




BLK: 4,SNR1: 0.57110 ,SNR2: 2.5183



F20240625092523





BLK: 3,SNR1: 0.94261E-01,SNR2: 0.93188




Frequency (Hz)

K20240625092518




BLK: 3,SNR1: 1.7089 ,SNR2: 10.856





Frequency (Hz)


0347+05 2024/06/25 045UT FUJI -KISO



T20240625094055





BLK: 6,SNR1: 0.28387 ,SNR2: 1.7534




Frequency (Hz)

F20240625094057




BLK: 6,SNR1: 0.57091 ,SNR2: 2.2474





Frequency (Hz)


0403-132 2024/06/25 0.71UT TOYOKAWA-FUJI




T20240625094055




BLK: 9,SNR1: 0.17602 ,SNR2: 2.0270




K20240625094052




BLK: 9,SNR1: 2.7231 ,SNR2: 9.8544




0403-132 2024/06/25 0.71UT TOYOKAWA-KISO





F20240625094057




BLK:16,SNR1: 0.67220 ,SNR2: 2.5058




K20240625094052





BLK:16,SNR1: 2.4658 ,SNR2: 9.2041




0403-132 2024/06/25 0.71UT FUJI -KISO





T20240625095006




BLK: 7,SNR1: 0.18289 ,SNR2: 1.1621




F20240625095008



BLK: 7,SNR1: 1.2871 ,SNR2: 7.2579





0411+05 2024/06/25 0.86UT TOYOKAWA-FUJI






T20240625095006





BLK: 6,SNR1: 0.14370 ,SNR2: 0.86809





0411+05 2024/06/25 0.86UT TOYOKAWA-KISO



K20240625095003




BLK: 6,SNR1: 0.11159 ,SNR2: 1.0812





F20240625095008




BLK: 5,SNR1: 0.77848 ,SNR2: 2.7802




K20240625095003





BLK: 5,SNR1: 0.24359 ,SNR2: 0.30145




0411+05 2024/06/25 0.86UT FUJI -KISO





T20240625095700




BLK:10,SNR1: 0.23847E-01,SNR2: 0.78243




F20240625095702





BLK:10,SNR1: 2.0775 ,SNR2: 11.313




0418+236 2024/06/25 0.98UT TOYOKAWA-FUJI



T20240625095700




BLK:10,SNR1: 0.28087E-01,SNR2: 0.27257





0418+236 2024/06/25 0.98UT TOYOKAWA-KISO



K20240625095657




BLK:10,SNR1: 2.8111 ,SNR2: 11.144





F20240625095702




BLK:24,SNR1: 1.6513 ,SNR2: 7.8132




K20240625095657





BLK:24,SNR1: 2.0860 ,SNR2: 8.3771




0418+236 2024/06/25 0.98UT FUJI -KISO



T20240625100827




BLK:20,SNR1: 2.8309 ,SNR2: 17.734




Frequency (Hz)

3C119 2024/06/25 1.17UT TOYOKAWA-FUJI


F20240625100829





BLK:20,SNR1: 0.59295E-01,SNR2: 1.7121




Frequency (Hz)




T20240625100827




BLK:18,SNR1: 2.1556 ,SNR2: 13.665




K20240625100824




BLK:18,SNR1: 0.56763 ,SNR2: 2.6341




3C119 2024/06/25 1.17UT TOYOKAWA-KISO





F20240625100829




BLK:19,SNR1: 0.10055 ,SNR2: 2.1243




K20240625100824



BLK:19,SNR1: 0.74707 ,SNR2: 3.1951




3C119 2024/06/25 1.17UT FUJI -KISO







T20240625105634




BLK:32,SNR1: 22.079 ,SNR2: 81.469




F20240625105636




BLK:32,SNR1: 0.43852 ,SNR2: 4.6530




3C138 2024/06/25 1.97UT TOYOKAWA-FUJI



T20240625105634




BLK:29,SNR1: 20.711 ,SNR2: 76.471





3C138 2024/06/25 1.97UT TOYOKAWA-KISO



K20240625105631




BLK:29,SNR1: 2.2741 ,SNR2: 9.6971



F20240625105636




BLK:29,SNR1: 0.51187 ,SNR2: 5.2590




Frequency (Hz)

3C138 2024/06/25 1.97UT FUJI -KISO


K20240625105631




BLK:29,SNR1: 2.5367 ,SNR2: 10.696




Frequency (Hz)



T20240625111008





BLK:22,SNR1: 10.270 ,SNR2: 31.548





0531+194 2024/06/25 2.20UT TOYOKAWA-FUJI


F20240625111010




BLK:22,SNR1: 0.69492 ,SNR2: 4.5308



T20240625111008





BLK:29,SNR1: 8.1644 ,SNR2: 31.946





0531+194 2024/06/25 2.20UT TOYOKAWA-KISO



K20240625111005




BLK:29,SNR1: 1.4540 ,SNR2: 13.615



F20240625111010





BLK:17,SNR1: 0.44616 ,SNR2: 2.6383




Frequency (Hz)

K20240625111005




BLK:17,SNR1: 1.5847 ,SNR2: 16.372




Frequency (Hz)


0531+194 2024/06/25 2.20UT FUJI -KISO




T20240625111827




BLK:20,SNR1: 15.629 ,SNR2: 79.302




F20240625111829




BLK:20,SNR1: 0.30353 ,SNR2: 2.7493




3C147 2024/06/25 2.34UT TOYOKAWA-FUJI





T20240625111827




BLK:32,SNR1: 15.817 ,SNR2: 36.592




K20240625111824



BLK:32,SNR1: 3.6016 ,SNR2: 15.111




3C147 2024/06/25 2.34UT TOYOKAWA-KISO






F20240625111829





BLK:25,SNR1: 0.20205 ,SNR2: 2.5994





3C147 2024/06/25 2.34UT FUJI -KISO



K20240625111824




BLK:25,SNR1: 1.7545 ,SNR2: 8.1098



T20240625112639




BLK:21,SNR1: 2.9574 ,SNR2: 14.925




Frequency (Hz)

0548+16 2024/06/25 2.47UT TOYOKAWA-FUJI


F20240625112641





BLK:21,SNR1: 0.21772 ,SNR2: 0.90195




Frequency (Hz)



T20240625112639




BLK:25,SNR1: 3.4332 ,SNR2: 16.817




Frequency (Hz)

K20240625112636




BLK:25,SNR1: 0.74226 ,SNR2: 4.3292




Frequency (Hz)


0548+16 2024/06/25 2.47UT TOYOKAWA-KISO




F20240625112641




BLK:12,SNR1: 0.20608 ,SNR2: 0.84083




K20240625112636




BLK:12,SNR1: 0.87290 ,SNR2: 2.6233




0548+16 2024/06/25 2.47UT FUJI -KISO



T20240625113049





BLK:18,SNR1: 3.7107 ,SNR2: 19.364




0552+12 2024/06/25 2.54UT TOYOKAWA-FUJI


F20240625113051





BLK:18,SNR1: 0.12997 ,SNR2: 1.2714




Frequency (Hz)



T20240625113049





BLK:18,SNR1: 2.7306 ,SNR2: 8.4963





0552+12 2024/06/25 2.54UT TOYOKAWA-KISO


K20240625113046




BLK:18,SNR1: 0.91812 ,SNR2: 4.5481





F20240625113051




BLK: 7,SNR1: 0.20019 ,SNR2: 0.65259




K20240625113046





BLK: 7,SNR1: 2.0897 ,SNR2: 6.2715




0552+12 2024/06/25 2.54UT FUJI -KISO



T20240625113516





BLK:12,SNR1: 7.2969 ,SNR2: 26.346





0556+191 2024/06/25 2.62UT TOYOKAWA-FUJI

F20240625113518




BLK:12,SNR1: 0.13955 ,SNR2: 0.81290








T20240625113516




BLK:15,SNR1: 8.4139 ,SNR2: 29.435




K20240625113513




BLK:15,SNR1: 0.62606 ,SNR2: 3.6552




0556+191 2024/06/25 2.62UT TOYOKAWA-KISO




F20240625113518




BLK: 5,SNR1: 0.50488 ,SNR2: 5.2533




K20240625113513




BLK: 5,SNR1: 0.25034 ,SNR2: 0.94298




0556+191 2024/06/25 2.62UT FUJI -KISO




T20240625113949




BLK:15,SNR1: 1.5249 ,SNR2: 6.9185




F20240625113951





BLK:15,SNR1: 0.54300 ,SNR2: 4.4167




3C152 2024/06/25 2.69UT TOYOKAWA-FUJI




T20240625113949




BLK:17,SNR1: 1.3232 ,SNR2: 4.1890




K20240625113946





BLK:17,SNR1: 0.53738 ,SNR2: 3.5015




3C152 2024/06/25 2.69UT TOYOKAWA-KISO





F20240625113951




BLK:11,SNR1: 0.67059 ,SNR2: 6.3904




K20240625113946




BLK:11,SNR1: 0.48286 ,SNR2: 3.3739




3C152 2024/06/25 2.69UT FUJI -KISO




T20240625120210




BLK:16,SNR1: 1.0977 ,SNR2: 5.3678




F20240625120212




BLK:16,SNR1: 0.11518 ,SNR2: 1.3189




3C161 2024/06/25 3.06UT TOYOKAWA-FUJI





T20240625120210




BLK:28,SNR1: 1.3993 ,SNR2: 9.9261




K20240625120207





BLK:28,SNR1: 0.48232 ,SNR2: 2.9299




3C161 2024/06/25 3.06UT TOYOKAWA-KISO



F20240625120212





BLK:21,SNR1: 0.28492 ,SNR2: 2.8851




Frequency (Hz)

K20240625120207




BLK:21,SNR1: 0.44648 ,SNR2: 3.6846





Frequency (Hz)

3C161 2024/06/25 3.06UT FUJI -KISO







T20240625122943




BLK: 2,SNR1: 0.23727 ,SNR2: 0.96759




F20240625122945





BLK: 2,SNR1: 0.38333 ,SNR2: 0.90144




0652-130 2024/06/25 3.52UT TOYOKAWA-FUJI





T20240625122943




BLK: 2,SNR1: 0.66717E-01,SNR2: 1.2438




K20240625122940




BLK: 2,SNR1: 0.85746 ,SNR2: 4.2073




0652-130 2024/06/25 3.52UT TOYOKAWA-KISO



F20240625122945





BLK: 3,SNR1: 0.99377E-01,SNR2: 2.3448





0652-130 2024/06/25 3.52UT FUJI -KISO



K20240625122940




BLK: 3,SNR1: 1.5901 ,SNR2: 7.5009





T20240625124119




BLK: 6,SNR1: 2.0547 ,SNR2: 11.494




F20240625124121





BLK: 6,SNR1: 1.2722 ,SNR2: 3.8954




0703+138 2024/06/25 3.72UT TOYOKAWA-FUJI





T20240625124119




BLK: 9,SNR1: 0.24552 ,SNR2: 1.4410




K20240625124116





BLK: 9,SNR1: 1.6074 ,SNR2: 6.5103




0703+138 2024/06/25 3.72UT TOYOKAWA-KISO





F20240625124121




BLK:13,SNR1: 0.46598 ,SNR2: 1.7945




K20240625124116





BLK:13,SNR1: 1.3862 ,SNR2: 5.6436




0703+138 2024/06/25 3.72UT FUJI -KISO




T20240625125042




BLK: 5,SNR1: 0.20876 ,SNR2: 2.6539




F20240625125044





BLK: 5,SNR1:-0.71567E-01,SNR2: 1.8246




0713-024 2024/06/25 3.87UT TOYOKAWA-FUJI




T20240625125042




BLK:13,SNR1: 0.16319 ,SNR2: 1.1527




K20240625125039



BLK:13,SNR1: 0.19822 ,SNR2: 2.6157




0713-024 2024/06/25 3.87UT TOYOKAWA-KISO







F20240625125044




BLK: 3,SNR1: 2.0912 ,SNR2: 11.009




K20240625125039




BLK: 3,SNR1: 0.11046E-01,SNR2: 0.29269




0713-024 2024/06/25 3.87UT FUJI -KISO





T20240625130054




BLK:14,SNR1: 1.3570 ,SNR2: 6.5984




F20240625130056




BLK:14,SNR1: 0.12629 ,SNR2: 0.46225




0723+10 2024/06/25 4.04UT TOYOKAWA-FUJI





T20240625130054




BLK:26,SNR1: 1.3256 ,SNR2: 5.6437




K20240625130051




BLK:26,SNR1: 0.25436 ,SNR2: 1.4084




0723+10 2024/06/25 4.04UT TOYOKAWA-KISO





F20240625130056




BLK: 8,SNR1: 0.20977 ,SNR2: 0.71695




K20240625130051




BLK: 8,SNR1: 0.84727 ,SNR2: 5.7373




0723+10 2024/06/25 4.04UT FUJI -KISO




T20240625131108




BLK:14,SNR1: 0.48075 ,SNR2: 1.7338




F20240625131110




BLK:14,SNR1: 0.27196 ,SNR2: 1.2069




0732+33 2024/06/25 4.21UT TOYOKAWA-FUJI




T20240625131108




BLK:16,SNR1: 0.34264 ,SNR2: 1.3587




K20240625131105




BLK:16,SNR1: 3.6880 ,SNR2: 11.946




0732+33 2024/06/25 4.21UT TOYOKAWA-KISO



F20240625131110





BLK: 4,SNR1: 0.84514 ,SNR2: 2.4934




Frequency (Hz)

K20240625131105




BLK: 4,SNR1: 8.4103 ,SNR2: 33.969





Frequency (Hz)


0732+33 2024/06/25 4.21UT FUJI -KISO




T20240625131910




BLK:14,SNR1: 0.66765 ,SNR2: 5.4597




F20240625131912



BLK:14,SNR1: 0.48450E-01,SNR2: 0.85611




0741-06 2024/06/25 4.35UT TOYOKAWA-FUJI








T20240625131910




BLK:23,SNR1: 0.49862 ,SNR2: 4.8617




K20240625131907





BLK:23,SNR1: 0.59236 ,SNR2: 1.8524




0741-06 2024/06/25 4.35UT TOYOKAWA-KISO





F20240625131912




BLK: 7,SNR1:-0.22611E-02,SNR2: 0.62113




K20240625131907




BLK: 7,SNR1: 0.12150 ,SNR2: 0.91024




0741-06 2024/06/25 4.35UT FUJI -KISO





T20240625132855




BLK:15,SNR1: 9.0412 ,SNR2: 16.365




F20240625132857





BLK:15,SNR1: 3.6034 ,SNR2: 8.6512




0752-200 2024/06/25 4.51UT TOYOKAWA-FUJI




T20240625132855




BLK:18,SNR1: 5.3182 ,SNR2: 12.845




K20240625132852





BLK:18,SNR1: 6.5175 ,SNR2: 12.789




0752-200 2024/06/25 4.51UT TOYOKAWA-KISO




F20240625132857




BLK:21,SNR1: 2.0404 ,SNR2: 5.3768




K20240625132852





BLK:21,SNR1: 5.0967 ,SNR2: 10.048




0752-200 2024/06/25 4.51UT FUJI -KISO





T20240625133630




BLK: 5,SNR1: 0.24691 ,SNR2: 1.2034




F20240625133632





BLK: 5,SNR1: 0.58435 ,SNR2: 0.90279




3C190 2024/06/25 4.64UT TOYOKAWA-FUJI





T20240625133630




BLK: 9,SNR1: 0.18012 ,SNR2: 1.5717




K20240625133627




BLK: 9,SNR1: 1.0677 ,SNR2: 3.6378




3C190 2024/06/25 4.64UT TOYOKAWA-KISO



F20240625133632





BLK: 8,SNR1: 0.48707 ,SNR2: 1.1715





3C190 2024/06/25 4.64UT FUJI -KISO

K20240625133627





BLK: 8,SNR1: 0.21838 ,SNR2: 1.1985







T20240625134854




BLK:10,SNR1: 0.50995 ,SNR2: 1.6203




F20240625134856





BLK:10,SNR1: 0.28090 ,SNR2: 1.1420




3C196 2024/06/25 4.84UT TOYOKAWA-FUJI





T20240625134854




BLK:15,SNR1: 0.54842 ,SNR2: 1.9080




K20240625134852




BLK:15,SNR1: 0.59732 ,SNR2: 2.9529




3C196 2024/06/25 4.84UT TOYOKAWA-KISO



F20240625134856




BLK:12,SNR1: 0.73402 ,SNR2: 1.9569





3C196 2024/06/25 4.84UT FUJI -KISO


K20240625134852




BLK:12,SNR1: 1.1419 ,SNR2: 4.5729




T20240625140004




BLK: 9,SNR1: 0.21109 ,SNR2: 1.4468




F20240625140006




BLK: 9,SNR1: 0.40207 ,SNR2: 2.0980




0821+394 2024/06/25 5.03UT TOYOKAWA-FUJI





T20240625140004




BLK:14,SNR1: 0.21148 ,SNR2: 1.9355




K20240625140001




BLK:14,SNR1: 0.90920 ,SNR2: 3.6100




0821+394 2024/06/25 5.03UT TOYOKAWA-KISO





F20240625140006




BLK:16,SNR1: 0.80757 ,SNR2: 2.0591




K20240625140001





BLK:16,SNR1: 1.2372 ,SNR2: 4.8470




0821+394 2024/06/25 5.03UT FUJI -KISO





T20240625141144




BLK: 6,SNR1: 0.40929 ,SNR2: 2.1791




F20240625141146





BLK: 6,SNR1: 2.6040 ,SNR2: 5.1214




0834-19 2024/06/25 5.22UT TOYOKAWA-FUJI





T20240625141144




BLK:16,SNR1: 0.15117 ,SNR2: 2.1001




K20240625141141



BLK:16,SNR1: 4.7607 ,SNR2: 12.333





0834-19 2024/06/25 5.22UT TOYOKAWA-KISO








F20240625141146




BLK:19,SNR1: 2.5256 ,SNR2: 6.1966




K20240625141141





BLK:19,SNR1: 4.9290 ,SNR2: 12.523




0834-19 2024/06/25 5.22UT FUJI -KISO





T20240625141649




BLK:21,SNR1: 4.4441 ,SNR2: 8.7672




F20240625141651





BLK:21,SNR1: 5.1630 ,SNR2: 13.018




0839-071 2024/06/25 5.31UT TOYOKAWA-FUJI




T20240625141649




BLK:13,SNR1: 4.1285 ,SNR2: 14.613




K20240625141646





BLK:13,SNR1: 6.5833 ,SNR2: 12.896




0839-071 2024/06/25 5.31UT TOYOKAWA-KISO




F20240625141651




BLK:25,SNR1: 6.0421 ,SNR2: 15.020




K20240625141646





BLK:25,SNR1: 6.7478 ,SNR2: 13.188




0839-071 2024/06/25 5.31UT FUJI -KISO





T20240625142750




BLK:23,SNR1: 11.290 ,SNR2: 26.246




F20240625142752





BLK:23,SNR1: 8.7225 ,SNR2: 21.855




3C208 2024/06/25 5.49UT TOYOKAWA-FUJI





T20240625142750




BLK:22,SNR1: 16.889 ,SNR2: 29.707




K20240625142748





BLK:22,SNR1: 7.9634 ,SNR2: 20.173




3C208 2024/06/25 5.49UT TOYOKAWA-KISO



F20240625142752





BLK:25,SNR1: 2.4522 ,SNR2: 11.999




Frequency (Hz)

K20240625142748




BLK:25,SNR1: 2.9868 ,SNR2: 13.893





Frequency (Hz)


3C208 2024/06/25 5.49UT FUJI -KISO



T20240625144432





BLK:11,SNR1: 0.26031 ,SNR2: 1.5297




Frequency (Hz)

F20240625144434




BLK:11,SNR1: 0.97847 ,SNR2: 2.9069





Frequency (Hz)

3C216 2024/06/25 5.77UT TOYOKAWA-FUJI






T20240625144432





BLK: 9,SNR1: 0.22599 ,SNR2: 1.2597




Frequency (Hz)

K20240625144429




BLK: 9,SNR1: 0.55591 ,SNR2: 2.3302





Frequency (Hz)


3C216 2024/06/25 5.77UT TOYOKAWA-KISO



F20240625144434





BLK:14,SNR1: 0.80609 ,SNR2: 2.9249




Frequency (Hz)

K20240625144429




BLK:14,SNR1: 0.20982 ,SNR2: 1.1645





Frequency (Hz)


3C216 2024/06/25 5.77UT FUJI -KISO




T20240625145643




BLK:10,SNR1: 2.9075 ,SNR2: 12.924




F20240625145645





BLK:10,SNR1: 0.36884 ,SNR2: 3.4779




0919-142 2024/06/25 5.97UT TOYOKAWA-FUJI





T20240625145643




BLK:11,SNR1: 2.9073 ,SNR2: 12.923




K20240625145640




BLK:11,SNR1: 0.32419 ,SNR2: 1.7992




0919-142 2024/06/25 5.97UT TOYOKAWA-KISO





F20240625145645




BLK:10,SNR1: 1.0851 ,SNR2: 5.6783




K20240625145640





BLK:10,SNR1: 0.56236 ,SNR2: 3.1074




0919-142 2024/06/25 5.97UT FUJI -KISO





T20240625150322




BLK: 2,SNR1: 0.12856 ,SNR2: 0.50881




F20240625150324





BLK: 2,SNR1: 0.82811 ,SNR2: 4.9924




0926+117 2024/06/25 6.08UT TOYOKAWA-FUJI





T20240625150322




BLK: 2,SNR1: 0.23954E-01,SNR2: 0.45020




K20240625150319





BLK: 2,SNR1:-0.12675E-01,SNR2: 1.2496




0926+117 2024/06/25 6.08UT TOYOKAWA-KISO





F20240625150324




BLK: 1,SNR1:-0.33846E-01,SNR2: 0.97276




K20240625150319



BLK: 1,SNR1:-0.50293E-01,SNR2: 1.2295




0926+117 2024/06/25 6.08UT FUJI -KISO








T20240625151107




BLK:25,SNR1: 5.6431 ,SNR2: 15.919




F20240625151109




BLK:25,SNR1: 6.2487 ,SNR2: 15.902




3C222 2024/06/25 6.21UT TOYOKAWA-FUJI





T20240625151107




BLK:31,SNR1: 5.7888 ,SNR2: 16.535




K20240625151105





BLK:31,SNR1: 2.7988 ,SNR2: 13.355




3C222 2024/06/25 6.21UT TOYOKAWA-KISO





F20240625151109




BLK:30,SNR1: 6.0938 ,SNR2: 15.509




K20240625151105





BLK:30,SNR1: 2.7492 ,SNR2: 13.159




3C222 2024/06/25 6.21UT FUJI -KISO



T20240625151807




BLK:13,SNR1: 0.96026 ,SNR2: 3.7688




Frequency (Hz)

F20240625151809




BLK:13,SNR1: 0.22600 ,SNR2: 2.7084





Frequency (Hz)


0941-08 2024/06/25 6.33UT TOYOKAWA-FUJI





T20240625151807




BLK:17,SNR1: 1.1517 ,SNR2: 2.8164




K20240625151804




BLK:17,SNR1: 3.1070 ,SNR2: 11.639




0941-08 2024/06/25 6.33UT TOYOKAWA-KISO



F20240625151809




BLK:14,SNR1: 0.29709 ,SNR2: 3.4901




Frequency (Hz)

K20240625151804




BLK:14,SNR1: 8.3620 ,SNR2: 19.736





Frequency (Hz)


0941-08 2024/06/25 6.33UT FUJI -KISO



T20240625152629




BLK: 2,SNR1: 0.28024 ,SNR2: 4.1732




Frequency (Hz)

F20240625152631




BLK: 2,SNR1:-0.42090E-01,SNR2: 1.2279





Frequency (Hz)


3C230 2024/06/25 6.47UT TOYOKAWA-FUJI





T20240625152629




BLK: 7,SNR1: 0.19933 ,SNR2: 2.2891




K20240625152626



BLK: 7,SNR1: 0.56278 ,SNR2: 1.8943




3C230 2024/06/25 6.47UT TOYOKAWA-KISO






F20240625152631





BLK: 3,SNR1: 0.21579 ,SNR2: 1.5080




Frequency (Hz)

K20240625152626




BLK: 3,SNR1: 0.42516 ,SNR2: 0.69452





Frequency (Hz)


3C230 2024/06/25 6.47UT FUJI -KISO





T20240625154229




BLK:32,SNR1: 9.9546 ,SNR2: 23.401




F20240625154231





BLK:32,SNR1: 13.026 ,SNR2: 31.381




3C237 2024/06/25 6.74UT TOYOKAWA-FUJI



T20240625154229





BLK:33,SNR1: 9.9506 ,SNR2: 23.391




Frequency (Hz)

K20240625154226




BLK:33,SNR1: 13.099 ,SNR2: 31.571





Frequency (Hz)


3C237 2024/06/25 6.74UT TOYOKAWA-KISO



F20240625154231





BLK:36,SNR1: 12.851 ,SNR2: 30.969




Frequency (Hz)

K20240625154226




BLK:36,SNR1: 13.021 ,SNR2: 31.380





Frequency (Hz)


3C237 2024/06/25 6.74UT FUJI -KISO



T20240625154846





BLK: 5,SNR1:-0.38217E-01,SNR2: 0.50390




Frequency (Hz)

F20240625154848




BLK: 5,SNR1: 0.38835 ,SNR2: 3.6348





Frequency (Hz)


1011+110 2024/06/25 6.84UT TOYOKAWA-FUJI



T20240625154846





BLK: 5,SNR1: 0.88877 ,SNR2: 4.0923




Frequency (Hz)

K20240625154844




BLK: 5,SNR1: 0.34831 ,SNR2: 1.0115





Frequency (Hz)


1011+110 2024/06/25 6.84UT TOYOKAWA-KISO




F20240625154848




BLK: 4,SNR1:-0.26982E-01,SNR2: 0.37447




K20240625154844





BLK: 4,SNR1: 0.63583 ,SNR2: 2.5219




1011+110 2024/06/25 6.84UT FUJI -KISO



T20240625155627





BLK:23,SNR1: 6.1809 ,SNR2: 11.034




Frequency (Hz)

F20240625155629




BLK:23,SNR1: 3.0486 ,SNR2: 14.098





Frequency (Hz)

3C241 2024/06/25 6.97UT TOYOKAWA-FUJI






T20240625155627





BLK:21,SNR1: 6.5318 ,SNR2: 11.555




Frequency (Hz)

K20240625155624




BLK:21,SNR1: 13.378 ,SNR2: 32.619





Frequency (Hz)


3C241 2024/06/25 6.97UT TOYOKAWA-KISO



F20240625155629





BLK:23,SNR1: 3.0115 ,SNR2: 13.952





3C241 2024/06/25 6.97UT FUJI -KISO



K20240625155624




BLK:23,SNR1: 13.264 ,SNR2: 32.345



T20240625160756





BLK:31,SNR1: 6.9986 ,SNR2: 16.650




Frequency (Hz)

F20240625160758




BLK:31,SNR1: 14.288 ,SNR2: 26.589





Frequency (Hz)


1031-11 2024/06/25 7.16UT TOYOKAWA-FUJI





T20240625160756




BLK:28,SNR1: 7.2652 ,SNR2: 17.274




K20240625160753





BLK:28,SNR1: 10.909 ,SNR2: 21.111




1031-11 2024/06/25 7.16UT TOYOKAWA-KISO



F20240625160758





BLK:25,SNR1: 16.114 ,SNR2: 29.961




Frequency (Hz)

K20240625160753




BLK:25,SNR1: 11.494 ,SNR2: 22.276





Frequency (Hz)


1031-11 2024/06/25 7.16UT FUJI -KISO



T20240625161229





BLK: 4,SNR1: 0.94906 ,SNR2: 2.7744




Frequency (Hz)

F20240625161231




BLK: 4,SNR1: 0.19138 ,SNR2: 1.4241





Frequency (Hz)


1035-058 2024/06/25 7.24UT TOYOKAWA-FUJI



T20240625161229





BLK:12,SNR1: 7.7181 ,SNR2: 31.935




Frequency (Hz)

K20240625161226




BLK:12,SNR1: 1.7790 ,SNR2: 6.7255





Frequency (Hz)


1035-058 2024/06/25 7.24UT TOYOKAWA-KISO



F20240625161231





BLK: 9,SNR1: 0.14240 ,SNR2: 1.8140




Frequency (Hz)

K20240625161226




BLK: 9,SNR1: 1.1028 ,SNR2: 5.5645





Frequency (Hz)

1035-058 2024/06/25 7.24UT FUJI -KISO







T20240625162142




BLK: 5,SNR1: 0.94190E-01,SNR2: 0.52357




F20240625162144





BLK: 5,SNR1: 1.3066 ,SNR2: 10.566




1044-008 2024/06/25 7.39UT TOYOKAWA-FUJI



T20240625162142





BLK: 4,SNR1: 0.49236E-01,SNR2: 0.96557




Frequency (Hz)

K20240625162139




BLK: 4,SNR1: 0.41646 ,SNR2: 2.3455




Frequency (Hz)


1044-008 2024/06/25 7.39UT TOYOKAWA-KISO



F20240625162144





BLK: 7,SNR1: 0.36181 ,SNR2: 4.2110




Frequency (Hz)

K20240625162139




BLK: 7,SNR1: 1.0661 ,SNR2: 5.3151





Frequency (Hz)


1044-008 2024/06/25 7.39UT FUJI -KISO



T20240625163247




BLK: 9,SNR1: 0.48949 ,SNR2: 1.2663




Frequency (Hz)

F20240625163249




BLK: 9,SNR1: 6.3600 ,SNR2: 11.430





Frequency (Hz)


1055+01 2024/06/25 7.57UT TOYOKAWA-FUJI



T20240625163247




BLK: 8,SNR1: 0.66740 ,SNR2: 3.0428




Frequency (Hz)

K20240625163244




BLK: 8,SNR1: 2.8908 ,SNR2: 10.525




Frequency (Hz)


1055+01 2024/06/25 7.57UT TOYOKAWA-KISO




F20240625163249




BLK:14,SNR1: 1.7212 ,SNR2: 8.1241




K20240625163244





BLK:14,SNR1: 1.7423 ,SNR2: 6.8023




1055+01 2024/06/25 7.57UT FUJI -KISO



T20240625164404





BLK:10,SNR1: 0.83818 ,SNR2: 2.1957




Frequency (Hz)

F20240625164406




BLK:10,SNR1: 4.9416 ,SNR2: 12.283





Frequency (Hz)


1107+109 2024/06/25 7.76UT TOYOKAWA-FUJI



T20240625164404





BLK:11,SNR1: 0.71002 ,SNR2: 1.8788




Frequency (Hz)

K20240625164401




BLK:11,SNR1: 4.4030 ,SNR2: 11.682





Frequency (Hz)

1107+109 2024/06/25 7.76UT TOYOKAWA-KISO






F20240625164406





BLK:18,SNR1: 7.8659 ,SNR2: 18.674




Frequency (Hz)

K20240625164401




BLK:18,SNR1: 5.0736 ,SNR2: 12.904





Frequency (Hz)


1107+109 2024/06/25 7.76UT FUJI -KISO



T20240625165341





BLK: 4,SNR1: 0.25486 ,SNR2: 1.4495




Frequency (Hz)

F20240625165343




BLK: 4,SNR1:-0.16889 ,SNR2: 1.3360





Frequency (Hz)


3C255 2024/06/25 7.92UT TOYOKAWA-FUJI



T20240625165341





BLK: 5,SNR1: 0.30824 ,SNR2: 1.9115




Frequency (Hz)

K20240625165338




BLK: 5,SNR1: 0.69666 ,SNR2: 6.6147





Frequency (Hz)


3C255 2024/06/25 7.92UT TOYOKAWA-KISO



F20240625165343





BLK: 3,SNR1:-0.13417 ,SNR2: 0.93825




Frequency (Hz)

K20240625165338




BLK: 3,SNR1: 0.19887 ,SNR2: 0.40130





Frequency (Hz)


3C255 2024/06/25 7.92UT FUJI -KISO



T20240625171740





BLK: 4,SNR1: 0.28248 ,SNR2: 2.2256




Frequency (Hz)

F20240625171742




BLK: 4,SNR1: 0.30103 ,SNR2: 1.3297





Frequency (Hz)


3C263.1 2024/06/25 8.32UT TOYOKAWA-FUJI



T20240625171740





BLK: 6,SNR1: 0.27559 ,SNR2: 2.8352




Frequency (Hz)

K20240625171737




BLK: 6,SNR1: 0.58175 ,SNR2: 1.7793





Frequency (Hz)


3C263.1 2024/06/25 8.32UT TOYOKAWA-KISO



F20240625171742





BLK:10,SNR1: 3.0234 ,SNR2: 4.9009




Frequency (Hz)

K20240625171737




BLK:10,SNR1: 0.94256 ,SNR2: 3.4388





Frequency (Hz)


3C263.1 2024/06/25 8.32UT FUJI -KISO



T20240625174321





BLK: 3,SNR1: 0.60472E-01,SNR2: 0.94137




Frequency (Hz)

F20240625174323




BLK: 3,SNR1:-0.32941E-01,SNR2: 1.2889





Frequency (Hz)

1206+439 2024/06/25 8.75UT TOYOKAWA-FUJI






T20240625174321





BLK: 5,SNR1: 0.65563E-01,SNR2: 0.85437




Frequency (Hz)

K20240625174318




BLK: 5,SNR1: 0.97552 ,SNR2: 3.5010





Frequency (Hz)


1206+439 2024/06/25 8.75UT TOYOKAWA-KISO



F20240625174323




BLK: 5, SNR1: 0.18105 , SNR2: 2.5281




Frequency (Hz)

K20240625174318



BLK: 5, SNR1: 1.2038 , SNR2: 4.0274



Frequency (Hz)

1206+439 2024/06/25 8.75UT FUJI -KISO

